


ORIGINAL  
FILE COPY 42



**Florida  
Power**  
CORPORATION

**BEFORE THE  
FLORIDA PUBLIC SERVICE COMMISSION**

**DOCKET No. 970261-EI**

**In Re: Review of Nuclear Outage  
at Florida Power Corporation's  
Crystal River Unit No. 3**

**DIRECT TESTIMONY  
AND EXHIBITS OF  
PERCY M. BEARD, JR.**

**For Filing April 14, 1997**  
DOCUMENT NUMBER-DATE  
03749 APR 14 5  
FPSC-RECORDS/REPORTING

CONFIDENTIAL  
7-15-00

**FLORIDA POWER CORPORATION  
DOCKET NO. 970261-EI**

**DIRECT TESTIMONY OF  
PERCY M. BEARD, JR.**

1 **I. BACKGROUND**

2 **Q. WHAT IS YOUR NAME, ADDRESS, AND OCCUPATION?**

3 **A.** My name is Percy M. Beard, Jr. I live at 1630B Royal Palm Drive South,  
4 Gulfport, Florida 33707. I am retired from Florida Power Corporation  
5 ("Florida Power" or "the Company").  
6

7 **Q. WHAT WAS YOUR POSITION AT FPC?**

8 **A.** I served as Senior Vice President, Nuclear Operations for Florida Power in  
9 charge of the Company's nuclear program and management of the Crystal  
10 River Unit 3 nuclear power plant ("CR-3") from December 1989 through  
11 my retirement on March 3, 1997. As Senior Vice President, Nuclear  
12 Operations, I was responsible for overall management of CR-3 and for  
13 assuring, in particular, that all CR-3 activities, including engineering,  
14 licensing, operations, and maintenance were performed in accordance with  
15 the Facility Operating License issued by the NRC.  
16

17 **Q. WHAT IS YOUR EDUCATION, EXPERIENCE, AND TRAINING?**

18 **A.** I received my Bachelor of Science Degree in Marine/Electrical Engineering  
19 from the U.S. Naval Academy in 1958 and my Doctorate Degree in  
20 Nuclear Physics from Duke University in 1964. I served in the U.S. Navy

1 from 1958 through 1981, holding a number of posts, including the  
2 command of two nuclear submarines.

3 In 1981, I joined the Institute of Nuclear Power Operations  
4 (sometimes referred to as "INPO"). The Institute of Nuclear Power  
5 Operations was formed in 1980 to promote a standard of excellence  
6 throughout the commercial nuclear power industry. Between 1981 and  
7 1989, I served at the Institute as an Evaluation Team Manager, Director  
8 and Vice President of the Evaluation and Assistance Group, and Vice  
9 President of Government Relations. As Vice President of Government  
10 Relations, I managed INPO's relationships with the U.S. Nuclear  
11 Regulatory Commission ("NRC"), the U.S. Department of Energy, and  
12 various industry organizations, including the Nuclear Management and  
13 Resource Council (now called the "Nuclear Energy Institute"), the Nuclear  
14 Power Oversight Committee, the Edison Electric Institute, and the Electric  
15 Power Research Institute.

16  
17 **II. PURPOSE AND SUMMARY OF TESTIMONY**

18 **Q. WHAT IS THE PURPOSE OF YOUR TESTIMONY?**

19 **A.** I describe in my testimony the overall operating performance and safe  
20 condition of CR-3 during the years of my tenure leading to the current  
21 outage. I also describe a modification that was made during the 1996  
22 refueling outage that provides the immediate background to the current  
23 outage, the lube oil pipe failure that precipitated the current outage, and  
24 my decision at the beginning of October 1996 to extend the outage in  
25 order to permit CR-3 to restore compliance with the conditions of its

1 operating license. Finally, I explain why it was reasonably necessary to  
2 incur the costs associated with the current outage.

3  
4 **Q. WOULD YOU PLEASE SUMMARIZE YOUR TESTIMONY?**

5 A. Yes. Over the years, Florida Power has endeavored to avoid extended  
6 outages. Since I joined the Company in 1989, the productivity of the  
7 plant climbed continually until we commenced this outage in 1996. The  
8 plant's capacity factor rose steadily from 53% in 1989 to approximately  
9 100% in 1995. The plant's performance in 1995 placed CR-3 among the  
10 top-performing nuclear plants in the world. During the same years, CR-3  
11 enjoyed a steadily declining cost of producing electricity. In 1989, it cost  
12 \$40.44 per megawatt hour to produce electricity at CR-3; by 1995, the  
13 cost was \$17.96. Florida Power's ratepayers have enjoyed the benefits  
14 of this superior performance over those years.

15 Florida Power has always operated CR-3 in a safe manner. We  
16 continually monitor our safety systems and have succeeded in maintaining  
17 our objective over the years in ensuring the availability of emergency  
18 equipment and systems. We have consistently observed the safety limits  
19 established for the protection of our employees, the public, and the  
20 environment.

21 The Company initiated the current outage in order to repair a ruptured  
22 lube oil pipe in the main turbine. The pipe was not observable while the  
23 plant was operating and so it's failure was not foreseen. The pipe failed  
24 due to stress caused by vibration in the operation of the turbine coupled

1 with latent impurities in the pipe material. We had to shut down the plant  
2 to identify the problem with certainty and to make the necessary repairs.

3 I was compelled to make the decision to place CR-3 in an extended  
4 shutdown because we determined by the beginning of October 1996 that  
5 we needed to restore compliance with the plant's operating license and  
6 that this would require a thorough investigation of alternatives and  
7 sufficient time to make any necessary modifications to the plant's  
8 Engineered Safeguards system. The modifications we are making grow  
9 out of a series of regulatory requirements prompted by the accident at  
10 Three Mile Island. On account of these requirements, plants that had been  
11 designed and constructed previously had to retrofit their Engineered  
12 Safeguards system to meet hypothetical emergency situations that the  
13 plants had not been designed to meet.

14 Over the years, Florida Power has made a number of modifications  
15 to CR-3's control systems and procedures and less extensive  
16 modifications to the plant's hardware in order to meet applicable licensing  
17 requirements. The Company has maintained the plant in safe operating  
18 condition while avoiding the need to make extensive modifications  
19 requiring lengthy outages.

20 During the refueling outage that commenced in February 1996, CR-3  
21 engineers added more accurate instrumentation to the meters that plant  
22 operators use to manage load on the plant's Emergency Diesel Generators.  
23 In the course of analyzing this modification, our engineers detected a  
24 potential problem arising out of a modification that had been made years  
25 earlier, in 1987, to reduce load on the generators. In 1987, the Company



1 had configured the plant's Emergency Feedwater system so that both of  
2 the plant's Emergency Feedwater pumps would be actuated at the same  
3 time. Because one of the pumps was driven by steam, the actuation of  
4 this pump reduced the hydraulic load on the other, electric-powered pump,  
5 and thus reduced the electrical load that the electric-powered pump  
6 imposed on one of the Emergency Diesel Generators.

7 During the 1996 refueling outage, CR-3 engineers became concerned  
8 based on calculations that they made at that time that simultaneous  
9 operation of both Emergency Feedwater pumps -- in a situation involving  
10 the loss of the battery that powers the valves to the steam-driven pump -  
11 - might cause an excessive flow of feedwater through the pumps  
12 potentially leading to pump failure. Up until that time, this hypothetical  
13 contingency had not been recognized by the Company, the Architect  
14 Engineer (Gilbert Commonwealth, Inc. now Parsons Power) or the nuclear  
15 steam supply vendor (Babcock & Wilcox now Framatome Technologies,  
16 Inc.). In order to remedy the problem, CR-3 engineers determined to  
17 "reverse" the 1987 modification linking the two pumps together.

18 They were able to do this based on the fact that the Emergency  
19 Diesel Generators had been upgraded after the 1987 modification and  
20 based on information from the manufacturer of the diesels -- Coltec  
21 Industries -- that the diesels could handle the load of the electric-powered  
22 pump acting alone. Based on this modification, we were able to restart  
23 the plant in May 1996.

24 In continuing to analyze the Engineered Safeguards system of the  
25 plant, however, both Florida Power and the NRC came to question

1        whether the May 1996 modification departed from the documented bases  
2        of the plant's Technical Specifications, which are conditions of the  
3        operating license. Florida Power and the NRC further determined that the  
4        modification gave rise to other concerns about the adequacy of the  
5        Emergency Feedwater system. On October 4, 1997, after consulting with  
6        CR-3 engineers, I concluded that we had to take steps to restore  
7        compliance with the plant's operating license, and that significant time  
8        would be required to complete our investigation and to make any  
9        necessary modifications.

10        Even if we had acquired this insight sooner, the same kind of outage  
11        would have been required. Because the problem involves complying with  
12        the conditions of our license, once we identified the problem we had to  
13        shut down the plant in 72 hours, or keep the plant shut down (if it was  
14        already out of service), until the problem could be redressed. Further, the  
15        modifications that we must make can only be made while the plant is shut  
16        down. In addition, we could not have done the extensive work associated  
17        with these modifications during any prior outage. Accordingly, this kind  
18        of outage was unavoidable.

19        The Company will benefit from making these modifications at this  
20        time because the Company will be able to learn from the trial and error of  
21        certain other plants similar to CR-3 that have attempted similar  
22        modifications, picking and choosing those solutions that seem best suited  
23        to CR-3 and that have proved successful at other nuclear plants.  
24  
25

1 **III. DESCRIPTION OF PLANT PERFORMANCE**

2 **Q. PLEASE DESCRIBE GENERALLY CR-3's PERFORMANCE FROM THE TIME**  
3 **YOU ASSUMED YOUR RESPONSIBILITIES AS SENIOR VICE PRESIDENT,**  
4 **NUCLEAR OPERATIONS, UNTIL THE REFUELING OUTAGE THAT**  
5 **COMMENCED IN FEBRUARY 1996.**

6 **A.** Overall, the plant performed very well during that period of time. Its  
7 productivity increased continually from 1989, when I started at Florida  
8 Power, through the end of 1995. A good indicator of a power plant's  
9 productivity is its capacity factor. The capacity factor is a comparison of  
10 a power plant's actual production with its potential production; thus, it  
11 represents a measure of how close the plant has come to achieving its full  
12 productive potential. I have attached as exhibits to my testimony three  
13 tables -- PMB Ex. 1 -- which demonstrate that CR-3's capacity factor rose  
14 steadily from 1989 through 1995, culminating in performance that placed  
15 CR-3 among the top-performing nuclear plants in the entire world.

16 Specifically, in 1989, at the end of its first decade of operation, CR-  
17 3's lifetime capacity factor was approximately 53%. As of that time, CR-  
18 3 was ranked 78th out of 107 nuclear units in terms of net capacity  
19 factor. Between 1991 and 1993, CR-3 rose to 41st out of 107 units, and  
20 between 1993 and 1995, CR-3 ranked 5th out of 108 units. Comparing  
21 the period 1990-1992 to 1993-1995, CR-3 increased its capacity factor  
22 by more than twenty percentage points. See PMB Ex. 2. In 1995, CR-3  
23 had a capacity factor of approximately 100%, which was the best  
24 capacity factor of all nuclear plants in the country and ranked 5th in the  
25 world. Because nuclear fuel is relatively less expensive than alternative



1 sources of fuel, CR-3's exceptional operation during this period of time  
2 directly benefited Florida Power ratepayers.

3 This benefit may be seen more clearly when consideration is given  
4 to CR-3's declining costs associated with operations, maintenance, and  
5 fuel. Specifically, in 1989, it cost \$40.44 per megawatt hour to produce  
6 electricity at CR-3. We consistently reduced that cost through 1995. In  
7 1990, we were able to reduce our cost per megawatt hour by more than  
8 25%, to \$30.20. By 1995, we had reduced CR-3's cost per megawatt  
9 hour to \$17.96 -- nearly a 60% decrease since 1989. As a result, CR-3  
10 was able to supply efficient, reliable, and economical energy to Florida  
11 Power's ratepayers.

12  
13 **Q. WAS CR-3 SAFE DURING THE TIME THAT YOU SERVED AS SENIOR**  
14 **VICE PRESIDENT, NUCLEAR OPERATIONS?**

15 **A.** Yes, it was. I placed top priority on the public health and safety during  
16 my leadership of the plant, and I would not have allowed the plant to  
17 operate if I did not have complete confidence in its safety. We monitored  
18 the safety systems and equipment at CR-3 continuously to ensure that  
19 they met rigorous standards of availability. We succeeded in meeting our  
20 performance indicator targets confirming that the plant's Engineered  
21 Safeguards equipment and systems remained in-service and available to  
22 respond to emergencies. We continuously monitored and confirmed the  
23 reliability of safety equipment to start and function when actuated.

24 The plant ran well during my tenure and experienced very few  
25 "Scrams," or automatic precautionary shut downs. We had a relatively

1 moderate maintenance backlog and succeeded in keeping the plant in  
2 sound material condition. CR-3 consistently observed radiological safety  
3 limits established to protect employees, the public, and the environment.  
4

5 **Q. ENTERING 1996, DID YOU BELIEVE THAT CR-3 MET ALL CONDITIONS**  
6 **OF ITS LICENSE AND COMPLIED WITH ALL APPLICABLE DESIGN**  
7 **REQUIREMENTS?**

8 **A. Yes.**  
9

10 **III. SUMMARY OF MODIFICATIONS MADE TO THE CR-3 ENGINEERED**  
11 **SAFEGUARDS SYSTEM DURING THE 1996 REFUEL OUTAGE**  
12

13 **Q. DID FLORIDA POWER DETERMINE IN THE COURSE OF THE 1996**  
14 **REFUELING OUTAGE THAT IT WAS NECESSARY TO MODIFY CR-3's**  
15 **ENGINEERED SAFEGUARDS SYSTEM IN ORDER TO RESTORE**  
16 **COMPLIANCE WITH APPLICABLE DESIGN REQUIREMENTS?**

17 **A. Yes, we did.**  
18

19 **Q. DID THE COMPANY MODIFY ITS ENGINEERED SAFEGUARDS SYSTEM**  
20 **DURING THE FEBRUARY 1996 REFUELING OUTAGE?**

21 **A. Yes, it did.**  
22

23 **Q. PLEASE EXPLAIN WHEN, HOW, AND WHY THE COMPANY MADE THESE**  
24 **MODIFICATIONS.**

1 A. At the end of March 1996, we upgraded the kilowatt meters that are  
2 relied upon by operators in applying loads to the Emergency Diesel  
3 Generators in the event of an emergency condition requiring the use of the  
4 generators. Our engineers had developed a concern that the existing  
5 meters lacked reliability at load levels over 200 kW. In the course of  
6 analyzing Emergency Diesel Generator loading issues relating to that  
7 modification, the engineers examined the assumption that load would be  
8 reduced by the concurrent operation of the (electric-powered) "A"  
9 Emergency Feedwater pump and the (steam-powered) "B" Emergency  
10 Feedwater pump.

11 As Mr. Paul McKee explains in his testimony at greater length, in  
12 order to reduce the load that we would place on the "A" Emergency Diesel  
13 Generator during a loss of coolant accident and a concurrent loss of offsite  
14 power, the Company modified the Engineered Safeguards system in 1987.  
15 The 1987 modification made the "B" Emergency Feedwater pump actuate  
16 by opening a valve to the "B" pump, called "ASV-204," anytime the "A"  
17 Emergency Feedwater pump was started. Because the "B" pump is steam  
18 driven, the Company reasoned that the "B" pump would reduce the  
19 burden on the electric-powered "A" pump, in turn reducing the load on the  
20 "A" Emergency Diesel Generator.

21 In re-examining Emergency Diesel Generator loading issues in March  
22 1996, during the most recent refueling outage, CR-3 personnel focused on  
23 the plant's reliance on the concurrent operation of the two feedwater  
24 pumps and observed that it was possible that the "B" Emergency  
25 Feedwater pump might not be available to provide controlled back-up to

1 the "A" Emergency Feedwater pump if a failure occurred in the battery  
2 used to power valves on equipment on the "B" side of the Engineered  
3 Safeguards system. The valves that control the flow of feedwater through  
4 the "B" Emergency Feedwater pump are normally wide open and require  
5 power to close. If the battery used to power those valves were to fail, the  
6 "B" pump would operate only at its maximum capacity (i.e., with its  
7 control valves wide open). This would afford plant operators less control  
8 over the operation of the "B" Emergency Feedwater pump in a small break  
9 loss of coolant accident.

10 Further, at that time, CR-3 engineers became concerned that the flow  
11 of feedwater through the Emergency Feedwater pumps in the situation  
12 just described might result in the loss of sufficient Net Positive Suction  
13 Head ("NPSH") needed to maintain the operability of the pumps.

14 To address this concern, CR-3 engineers from Operations, Licensing,  
15 Electrical and Mechanical Design Engineering, and Emergency Operating  
16 Procedures determined that it would be appropriate to modify the  
17 Engineered Safeguards system so that actuation of the "A" Emergency  
18 Feedwater pump would not automatically actuate the "B" Emergency  
19 Feedwater pump, thus "reversing" the 1987 modification. This decision  
20 was based on several considerations. Since the time of the 1987  
21 modification, the Company had upgraded the Emergency Diesel Generators  
22 by adding 150 kW of capacity to them. Also, we had gained greater  
23 confidence in our ability to measure load and capacity. During the 1980s  
24 Florida Power had based loading determinations on generic information  
25 concerning the capacity and performance characteristics of the model

1 Emergency Diesel Generators used at CR-3. By 1996, however, we had  
2 been provided by the manufacturer of these generators -- Coltec Industries  
3 -- precise performance curves for the particular Emergency Diesel  
4 Generators actually in use at CR-3. Based on this information, our  
5 engineers believed that it was not necessary to maintain the linkage  
6 established by the 1987 modification between the "A" and "B" Emergency  
7 Feedwater pumps.

8 CR-3 personnel knew that the Emergency Diesel Generators had been  
9 assigned ratings by Coltec indicating that the diesels were made to  
10 operate continuously at a maximum of 3500 kW for 30 minutes. CR-3  
11 personnel also knew that calculations showed that, if the "A" Emergency  
12 Diesel Generator were required to operate the "A" Emergency Feedwater  
13 pump without back-up from the "B" pump, load might be expected to  
14 spike up to 3700 kW for up to a few seconds at a time. (This knowledge  
15 was based on recent state-of-the-art calculations.) But the load was not  
16 expected to exceed 3500 kW on a continuous basis. The Electrical  
17 Design Engineering Department obtained assurance from Coltec that the  
18 Emergency Diesel Generators could in fact handle the transient spikes that  
19 might result if we would be required to operate the "A" Emergency  
20 Feedwater pump during a loss of coolant accident without concurrent  
21 operation of the "B" Emergency Feedwater pump. Accordingly, the  
22 decision was made to approve the modification terminating the automatic  
23 actuation of the "B" Emergency Feedwater pump upon initiation of the "A"  
24 Emergency Feedwater pump. The modification was completed in May

1 1996. With the completion of this modification, we were able to restart  
2 CR-3 on May 17, 1996.

3  
4 **IV. THE CAUSE OF THE SEPTEMBER 2, 1996 OUTAGE**

5 **Q. WHY DID FLORIDA POWER SHUT DOWN CR-3 ON SEPTEMBER 2, 1996?**

6 **A.** The immediate cause of this shutdown was a rupture of a lube oil pipe in  
7 the main turbine.

8  
9 **Q. PLEASE EXPLAIN THE CIRCUMSTANCES OF THE LUBE OIL PIPE**  
10 **RUPTURE.**

11 **A.** Plant operators detected a loss of lube oil pressure in the main turbine on  
12 August 30, 1996, which caused an automatic start of the electric back-up  
13 bearing oil pump. We commenced an immediate investigation of the  
14 problem and contacted the system vendor, Westinghouse, for guidance.  
15 Westinghouse suspected that a valve was partially blocked. CR-3  
16 engineers took steps to adjust the valve to correct the problem.

17 Plant operators monitored the lube oil pressure, and oil pressure  
18 continued to fall. On September 2, plant operators detected a substantial  
19 drop in the main turbine lube oil reservoir level over the prior 24 hour  
20 period. Based upon this problem and the continued loss of lube oil  
21 pressure, we decided to take CR-3 off line.

22 On September 3, our engineers opened several lube oil tank access  
23 ports and detected a long pipe crack. Upon further inspection of the  
24 system, the engineers identified a four and a half foot crack in a lube oil  
25 pipe just inside the top of the tank. In addition, the flange bolts at one



1 end of this pipe had loosened and much of the gasket had blown out. The  
2 crack and the condition of the gasket permitted lube oil to leak out of the  
3 pipe, explaining the loss of pressure. Our engineers concluded that the  
4 crack and the loosening of the flange bolts had been caused by vibration  
5 over a period of time that occurs during the operation of the equipment.  
6

7 **Q. BASED ON THE INFORMATION AVAILABLE TO THE COMPANY PRIOR TO**  
8 **THE RUPTURE OF THIS PIPE, DID THE COMPANY ANTICIPATE THAT**  
9 **THIS MIGHT OCCUR?**

10 **A.** No. The pipe had long been in use, and we had not experienced any  
11 problem like this before. The pipe was naturally subject to vibration during  
12 the normal operation of the plant. During operation of the plant, the pipe  
13 is not observable. We were unaware of the inclusions in the pipe material  
14 and of the loosening of the flange bolts since they are both within the oil  
15 reservoir. Finally, to our knowledge, there have been no industry advice  
16 letters or similar failures at other nuclear units.  
17

18 **Q. WHAT STEPS DID THE COMPANY TAKE TO REPAIR THE PIPE?**

19 **A.** After shutting the plant down, we continued to investigate the problem,  
20 and we commenced repair work. By September 14, we had completed  
21 the repairs, cleaned the tank, and refilled it with oil. The lube oil system  
22 was restored to service by September 14. Ordinarily, we would have  
23 been able to bring CR-3 back on line within about a week of that date, in  
24 order to allow for final inspections and verifications and the restart of the  
25 unit.

1 V. THE CAUSE OF THE CURRENT EXTENDED OUTAGE

2 Q. WHY DID THE COMPANY KEEP THE PLANT OUT OF SERVICE AFTER  
3 COMPLETION OF THE REPAIR TO THE LUBE OIL PIPE?

4 A. I decided to keep the plant shut down after we determined that the  
5 Engineered Safeguards system did not comply with CR-3 licensing  
6 requirements. We came to this conclusion in the following manner.

7 After every refueling outage, we re-test our Emergency Diesel  
8 Generators. In addition, we provide additional information to the NRC  
9 regarding any modification to safety-related equipment. Thus, following  
10 the restart of CR-3 in May 1996 both CR-3 personnel and NRC inspectors  
11 were conducting an ongoing review of Emergency Diesel Generator  
12 loading issues.

13 Further, the NRC conducted its intensive Integrated Performance  
14 Assessment Process ("IPAP") inspection of CR-3 in June and July 1996.  
15 This in-depth inspection included a Safety System Functional Inspection  
16 ("SSFI") of the decay heat removal function (the process of cooling the  
17 core) and supporting systems. In the course of this inspection,  
18 representatives of the NRC and the CR-3 plant discussed issues  
19 concerning the loading of the Emergency Diesel Generators, which had  
20 been addressed by the modification completed before the restart in May.  
21 The NRC was aware that Florida Power had determined that in the  
22 hypothetical circumstances -- namely, a loss of coolant accident, a loss of  
23 offsite power, and a loss of the "B" battery -- that the load placed on the  
24 "A" Emergency Diesel Generator would spike above 3500 kW for a few  
25 seconds. Florida Power engineers and the NRC inspectors agreed that the

1 "A" Emergency Diesel Generator had the technical capability of carrying  
2 the load that might be placed upon it in this situation.

3 In September 1996, however, after CR-3 was shut down due to the  
4 lube oil pipe rupture, NRC inspectors raised a concern that operating on  
5 the assumption that the "A" Emergency Diesel Generator could handle  
6 that load in those hypothetical circumstances may raise an "Unreviewed  
7 Safety Question" or "USQ." As Mr. McKee explains at greater length in  
8 his testimony, an Unreviewed Safety Question arises whenever a licensee  
9 has made a modification that results in an affirmative answer to any of the  
10 following three questions: (1) could the modification increase the  
11 probability of occurrence or consequences of a malfunction of equipment  
12 important to safety previously evaluated in the Final Safety Analysis  
13 Report? (2) could the modification create a possibility for an accident or  
14 malfunction of a different type than any evaluated previously in the Final  
15 Safety Analysis Report? or (3) will the modification cause a reduction in  
16 the margin of safety as defined in the basis for any of the plant's  
17 Technical Specifications? The NRC concluded that the May 1996  
18 modification negating automatic actuation of the "B" Emergency  
19 Feedwater pump upon start-up of the "A" Emergency Feedwater pump  
20 presented an Unreviewed Safety Question. This was so because the NRC  
21 concluded that CR-3's Technical Specifications contemplated that the "A"  
22 Emergency Diesel Generator would not be expected to operate at a level  
23 above 3500 kW at its maximum 30-minute rating, even on a transient  
24 basis.

1           The NRC further determined that the documented bases of CR-3's  
2           Technical Specifications required that the "A" Emergency Diesel Generator  
3           be capable of handling a load of 3100 kW in a worst case scenario where  
4           all equipment that may be automatically loaded would be required to  
5           operate in an emergency. CR-3 engineers had calculated that the load  
6           that would actually be placed on the "A" generator at CR-3 in that  
7           situation would total 3159 kW. Finally, the NRC expressed concern that  
8           the bases of CR-3's Technical Specifications stated that the single largest  
9           load from any piece of equipment that might be placed on the Emergency  
10          Diesel Generators was 616 kW, attributable to a High Pressure Injection  
11          pump. Florida Power's testing revealed that the Makeup Pump &  
12          Purification Pump actually imposed the largest load of 690.9 kW on the  
13          Emergency Diesel Generators.

14          CR-3's Technical Specifications prescribe how the Emergency Diesel  
15          Generators must perform and how they must be tested. The Technical  
16          Specifications themselves do not prohibit, for example, loading the  
17          Emergency Diesel Generators above 3500 kW. The Technical  
18          Specifications contain a section called "bases," however, which provide  
19          the explanation for the actual Technical Specifications. The "bases"  
20          portion of CR-3's Technical Specifications set forth the ratings for the  
21          generators in the course of explaining the testing procedures.

22          The NRC's conclusion that the modification made in May 1996  
23          presented Unreviewed Safety Questions was not based on that portion of  
24          CR-3's Technical Specifications that prescribes the actual performance and  
25          testing criteria for the Emergency Diesel Generators, but on that portion

1 that provides the explanation or "bases" for the Technical Specifications  
2 themselves. In fact, Florida Power had actually tested the Emergency  
3 Diesel Generators taking into account the actual loads that might be  
4 imposed during a small break loss of coolant accident and determined that  
5 the generators met the performance criteria of the Technical Specifications  
6 and that the generators were capable of performing their safety function  
7 for all design basis accidents. Thus, although the intent of the Technical  
8 Specifications had been met, the NRC concluded, and we agreed, that  
9 there had been a departure from the documented "bases" of the Technical  
10 Specifications.

11 Before this problem was resolved, the NRC further inquired at the end  
12 of September 1996, whether an Unreviewed Safety Question existed in  
13 connection with CR-3's Emergency Feedwater system. Our engineers  
14 initially disagreed with the NRC's interpretation of the circumstances and  
15 responded that no such question existed, but we agreed to study the  
16 matter. In analyzing this issue, we ultimately concluded that in reversing  
17 the 1987 ASV-204 modification, we had inadvertently reduced the  
18 reliability of the "B" Emergency Feedwater pump to assist in a loss of  
19 coolant accident in certain hypothetical emergency situations and thus  
20 had, indeed, created an Unreviewed Safety Question.

21 This was due in part to the fact that, in 1990, the Company had  
22 modified its Engineered Safeguards system to cause the "A" Emergency  
23 Feedwater pump to turn off automatically (or "trip" off) whenever the "A"  
24 Low Pressure Injection pump was started, based on information from  
25 Framatome Technologies Inc. that both pumps would not be needed

1 simultaneously to combat a loss of coolant accident. This modification  
2 provided the benefit of reducing load on the "A" Emergency Diesel  
3 Generator in certain hypothetical emergency situations. Due to the 1987  
4 ASV-204 modification, the "B" Emergency Feedwater pump would have  
5 been actuated when the "A" pump was turned on. The "B" pump would  
6 thus be available to supply feedwater between the set point where the  
7 Low Pressure Injection pump would be turned on (and the "A" Emergency  
8 Feedwater concurrently turned off) -- at 500 pounds per square inch of  
9 Reactor Coolant System pressure -- and the time that the Low Pressure  
10 Injection pump would actually start to supply water to cool the core -- at  
11 approximately 185 pounds per square inch. As a result of the reversal of  
12 the 1987 modification, however, a theoretical possibility existed that the  
13 "A" pump might be tripped off and the "B" pump would be needed but  
14 would no longer be actuated automatically with the initiation of the "A"  
15 pump. This resulted in reliance on operator action to initiate an  
16 Emergency Feedwater pump, thus arguably increasing the severity of an  
17 accident or malfunction.

18 Because the resulting configuration differed from Technical  
19 Specifications that the NRC had previously reviewed and approved, the  
20 modification created an Unreviewed Safety Question. Upon examination  
21 of this issue, we concluded that we had no apparent means to resolve the  
22 concerns about the Engineered Safeguards system without making  
23 significant hardware modifications to the plant.

24 In the circumstances confronting us, we were required under the  
25 conditions of our license to restore compliance within 72 hours or to keep



1 the plant shut down. (If the plant had been operating, we would have had  
2 72 hours to rectify non-compliance with our license, or we would have  
3 had to shut the plant down). See PMB Ex. 3 (Technical Specifications  
4 limiting conditions). Confronted with these facts, I concluded on October  
5 4, 1996 that we could not restart the plant. Accordingly, I directed that  
6 the plant remain shut down until we could complete a thorough  
7 investigation and implement modifications that would be effective to  
8 restore compliance with the conditions of CR-3's operating license.  
9

10 **Q. WHAT MODIFICATIONS IS THE COMPANY MAKING TO MEET THE**  
11 **CONDITIONS OF ITS LICENSE?**

12 **A.** The principal modifications are (1) upgrading the Emergency Diesel  
13 Generators by adding 150 kW of long-term capacity to each and (2)  
14 installing cavitating venturis in the Emergency Feedwater pumps to  
15 regulate feedwater flow. Given that the plant would be out of service for  
16 an extended period of time to accomplish this work, we undertook to  
17 make additional modifications that we believe are necessary to maintain  
18 design margins in CR-3's Engineered Safeguards system and that will not  
19 lengthen the outage. We had planned to perform some of these  
20 modifications during future refueling outages, but it will be more  
21 economical and more effective to perform this work now while the  
22 Engineered Safeguards system can be examined and enhanced as an  
23 integrated whole.  
24

1 Q. HAS THE COMPANY RULED OUT THE POSSIBILITY OF COMPLYING  
2 WITH ITS LICENSE BY MAKING LESS EXTENSIVE MODIFICATIONS?

3 A. Yes. In fact, the Company has been striving ever since regulatory  
4 requirements were changed after the Three Mile Island accident to avoid  
5 making more extensive modifications to retrofit the plant. We exhausted  
6 all practicable alternatives and were left with no reasonable choice but to  
7 commence the modifications now underway.

8  
9 Q. WHY DIDN'T FLORIDA POWER ANTICIPATE THE NEED FOR SIGNIFICANT  
10 MODIFICATIONS TO ITS ENGINEERED SAFEGUARDS SYSTEM AND  
11 IMPLEMENT THESE GRADUALLY BEFORE NOW?

12 A. The Company believed that the modifications that it was making all along  
13 would be adequate to enable CR-3 to meet the conditions of its license.  
14 The modifications that Mr. McKee describes and that I have described  
15 were not designed or implemented as temporary fixes, but as the best  
16 practicable, permanent alternatives to meeting applicable safety  
17 requirements. When it appears possible to meet operating and regulatory  
18 requirements with existing equipment, or by means of modifications that  
19 do not require extensive shutdowns, it is preferable to pursue that  
20 approach. The Company believed that it had the capability to resolve  
21 applicable regulatory requirements with its existing equipment and thus  
22 felt an obligation to do so.

23 It must be recognized that the situation that we faced in September  
24 and October 1996 was not like running out of gas. We had no gauge that  
25 told us this was coming. Rather, what happened was that we suddenly

1       came to recognize that a hypothetical set of circumstances could be  
2       supposed to exist where CR-3 would be operating outside its Technical  
3       Specifications. We arrived at this determination as the result of improved  
4       instrumentation, improved information about the characteristics of our  
5       equipment, improved knowledge about the operation of the plant, and  
6       sheer analytical insight. Until then, neither plant personnel, the designers  
7       of the plant, nor the manufacturers of its equipment spotted this issue.

8             It is often possible -- particularly with the benefit of hindsight -- to  
9       conjure up a "better" solution that costs more and that will require an  
10      extensive shutdown to implement, but it is difficult or impossible to know  
11      in advance whether these solutions will truly prove better for the ratepayer  
12      and the public at large. Until we commenced the current outage and  
13      determined that we had to implement the modifications now in progress,  
14      we believed that it would be ill-advised to undertake the extensive  
15      modifications that we now believe are necessary. We believed that we  
16      had other, superior and more cost-effective means available to cope with  
17      hypothetical design basis accidents. The Company has tried painstakingly  
18      over the years to meet its licensing requirements and to protect the  
19      ratepayer against unreasonable costs. We could not conclude that an  
20      outage like this one was cost-justified until, as I have described, we  
21      concluded in October 1996 that we simply had no choice.

22  
23   **Q. IF THE COMPANY HAD CONCLUDED PRIOR TO OCTOBER 1996 THAT**  
24   **THESE MODIFICATIONS WERE NECESSARY, WOULD THE SAME KIND**  
25   **OF OUTAGE BEEN REQUIRED?**

1 A. Yes. If one supposes that Florida Power had concluded at any time prior  
2 to October 1996 that it would be necessary to make the modifications  
3 now in progress, one must also suppose that Florida Power knew why  
4 these modifications would be necessary: namely, that these modifications  
5 are needed to maintain CR-3s compliance with the conditions of its  
6 license. If the Company had this recognition earlier, the Company would  
7 have had to shut down the plant within 72 hours, under the terms of its  
8 license, to implement these modifications. This would have required the  
9 same kind of outage as the one we have now.

10  
11 Q. WHY WASN'T FLORIDA POWER ALERTED TO THE NEED FOR THESE  
12 MODIFICATIONS BY THE FACT THAT CERTAIN OTHER UTILITIES WERE  
13 MAKING SOME SIMILAR MODIFICATIONS?

14 A. Although there are many similarities among nuclear plants -- at least those  
15 whose reactors were designed by Babcock & Wilcox -- there are also  
16 important differences. Each plant must tailor solutions to its own  
17 particular configuration and needs. Until now, Florida Power had believed  
18 that the most practicable and desirable manner to ensure that its  
19 Emergency Feedwater system could meet the requirements of a safety-  
20 related system was to implement electrical control solutions (including, for  
21 example, the installation of the Emergency Feedwater Initiation and  
22 Control system that Mr. McKee describes) rather than extensive hardware  
23 modifications that require an extended outage to carry out. In fact, during  
24 the time that Florida Power was charting this course, other plants were  
25 having difficulty with hardware modifications.

1 Q. WILL FLORIDA POWER BENEFIT FROM THE FACT THAT OTHER  
2 UTILITIES HAVE MADE SIMILAR MODIFICATIONS?

3 A. Yes. For example, the Davis Besse, Three Mile Island, and Rancho Seco  
4 plants (all B&W plants) have installed cavitating venturis to avoid  
5 cavitation in their Emergency Feedwater pumps. Florida Power is now  
6 able to use state-of-the-art design in making this modification. By  
7 contrast, when Arkansas Power first installed cavitating venturis (in its  
8 High Pressure Injection system), the devices created excessive vibration  
9 and resulting secondary damage, forcing Arkansas Power to modify the  
10 devices. The Baltimore Gas & Electric Company has made upgrades to the  
11 Emergency Diesel Generators in its Calvert Cliffs nuclear unit similar to the  
12 modifications that we are making to CR-3's Emergency Diesel Generators.

13 Because the Engineered Safeguards system is an integrated system,  
14 the Company is making modifications at this time to the Low Pressure  
15 Injection system and the High Pressure Injection system. Three Mile Island  
16 has made similar modifications to its Low Pressure Injection system, and  
17 Oconee, Three Mile Island, and Arkansas Power have made similar  
18 modifications to their High Pressure Injection systems. Florida Power will  
19 benefit from lessons learned in each of these installations.

20 Of course, no two plants are exactly alike, and Florida Power must  
21 engineer the implementation of these modifications for the particular  
22 configuration of CR-3. Nonetheless, the conceptual design work has been  
23 verified through operational experience, and the NRC is comfortable with  
24 these solutions to the various engineering issues they are designed to  
25 address. Florida Power is consulting with the engineers of other Babcock

1 & Wilcox nuclear units concerning the ongoing modifications at CR-3. As  
2 a result, the Company will be able to make these modifications as  
3 efficiently and effectively as anyone else in the industry.  
4

5 **Q. COULD THE WORK THAT THE COMPANY IS DOING NOW HAVE BEEN**  
6 **COMPLETED DURING A PRIOR OUTAGE?**

7 **A.** No. The work now underway is extensive and all consuming. Likewise,  
8 during all prior outages during my years at the Company, the Company  
9 was fully occupied tending to other important matters. The Company  
10 could not have accomplished extensive modifications of the kind now  
11 being made without lengthening any prior outage by the number of days  
12 being consumed in this outage. There is simply no practicable way that  
13 this shutdown -- or one just like it -- could have been avoided, given the  
14 fact that Florida Power is retrofitting equipment that was not part of the  
15 original design for the plant and given the Company's reason for doing it.  
16

17 **Q. WAS IT REASONABLY NECESSARY FOR FLORIDA POWER TO INCUR**  
18 **THE COSTS OF THIS EXTENDED OUTAGE?**

19 **A.** Yes. For all the reasons I have given, these costs were not reasonably  
20 avoidable.  
21

22 **Q. DOES THIS CONCLUDE YOUR DIRECT TESTIMONY?**

23 **A.** Yes.  
24



**EXHIBITS TO THE TESTIMONY OF  
PERCY M. BEARD, JR.**

---

**EXHIBIT No. \_\_\_\_ (PMB-1)**

**TABLE I**

**1989-91 SINGLE-UNIT RANKINGS**

**1991-93 SINGLE-UNIT RANKINGS**

**1993-95 SINGLE-UNIT RANKINGS**

---

TABLE I  
1989-91 SINGLE-UNIT RANKINGS BY DER NET CAPACITY FACTOR

Rank	Unit	MWe	Utility	Vendor	A-E	Factor
1.	Prince Island-1	330	NBP	W	Fluor	87.83
2.	Prince Island-2	330	NBP	W	Fluor	87.38
3.	Callaway	1171	UEC	W	Babcock	85.58
4.	San Onofre-3	1888	SCS	CE	Babcock	84.97
5.	Comanche-3	885	Duke	SAW	Babcock*	84.88
6.	Three Mile Island-1	829	OPSW	SAW	GE	84.88
7.	Forty-1	885	EDS	W	Babcock*	84.17
8.	Point Beach-3	497	Watts	W	Babcock	83.98
9.	Vermont Yankee	334	VTAPC	GE	Fluor	83.89
10.	St. Louis-2	885	FP&L	CE	Fluor	83.88
11.	Comanche-2	885	Duke	SAW	Babcock*	83.88
12.	Point Beach-1	497	Watts	W	Babcock	83.82
13.	North Anna-2	885	VFC	W	SAW	83.68
14.	New York	885	NYAPC	CE	SAW	83.68
15.	Duke Canyon-1	1088	PG&E	W	(utility)	83.68
16.	Vogtle-1	1101	EDS	W	Babcock*	83.58
17.	Duke Canyon-2	1119	PG&E	W	(utility)	83.54
18.	Olan	498	HO&R	W	GE	83.18
19.	Windsor-3	1104	Energy	CE	Fluor	83.18
20.	Forty-2	885	EDS	W	Babcock*	83.18
21.	Sequoyah	885	WVS	W	Fluor	83.18
22.	Susquehanna-1	1088	FP&L	CE	Babcock	83.08
23.	Comanche-1	885	Duke	SAW	Babcock*	79.87
24.	St. Louis-1	885	FP&L	CE	Fluor	79.88
25.	Hope Creek	1087	PE&S	GE	Babcock	79.88
26.	Susquehanna-2	1088	FP&L	CE	Babcock	79.78
27.	Sequoyah-1	1108	TVA	W	(utility)	79.37
28.	ANQ-1	912	Energy	CE	Babcock	79.11
29.	Lafayette-1	1078	CEC	CE	S&I	79.11
30.	Wolf Creek	1138	WCHOC	W	S&I	79.14
31.	Humb-2	784	EDS	CE	Babcock	79.08
32.	Humb-1	784	CP&L	W	Fluor	79.08
33.	Lafayette-2	1078	CEC	CE	S&I	79.11
34.	McGuire-2	1189	Duke	W	(utility)	79.18
35.	Bynum-1	1128	CEC	W	S&I	79.28
36.	Missouri	885	NBP	CE	Babcock	79.64
37.	Humb-1	784	EDS	CE	Babcock*	79.68
38.	Sequoyah-2	1108	TVA	W	(utility)	79.78
39.	Grand Chino-2	788	Energy	CE	S&I	79.88
40.	Grand Gulf	1708	Energy	CE	Babcock	79.88
41.	Aspid	885	HLAP	CE	Babcock	79.28
42.	Duck-Linn	988	Comstar	SAW	Babcock	79.77
43.	North Anna-1	887	VFC	W	SAW	79.88
44.	Coeper	778	NPPD	CE	S&I	71.88
45.	Fort Calhoun	488	TPD	CE	GE	71.84
46.	Edison-2	1118	PG&E	W	(utility)	71.88
47.	Summer	885	SC&G	W	Other	71.88
48.	Summer Valley-2	885	Dayman	W	SAW	79.88
49.	Bynum-2	1128	CEC	W	S&I	79.83
50.	Canby-1	1148	Duke	W	(utility)	79.78
51.	Coal-1	1088	NBP	W	(utility)	79.58
52.	Big Rock Point	72	Common	CE	Babcock	79.61
53.	Sequoyah-3	788	VFC	W	SAW	79.18
54.	Hope Creek	1087	EDS	CE	SAW	83.37
55.	San Onofre-2	1878	SCS	CE	Babcock	81.88
56.	Linn-1	1088	PG&E	CE	Babcock	82.47
57.	Indian Point-3	988	NYPA	W	UE&C	82.21
58.	Coal-2	1088	NBP	W	(utility)	82.87
59.	Sequoyah-1	1108	CEC	W	S&I	87.89
60.	Yonkers	118	Y&C	W	SAW	87.88
61.	Clayton-2	1148	EDS	W	(utility)	87.19
62.	Forty-1	1181	Comstar	CE	Other	85.48
63.	Millstone-1	688	NU	CE	Fluor	85.31
64.	Fort Point	885	NYPA	CE	SAW	85.91
65.	Fort-2	1088	Duke	CE	(utility)	84.41
66.	Edison-1	1118	PG&E	W	(utility)	84.41
67.	Grand Chino-1	788	CEC	CE	S&I	84.77
68.	ANQ-2	885	Energy	SAW	Babcock	82.84
69.	McGuire-1	1189	Duke	W	(utility)	82.47
70.	Summer Valley-1	885	Dayman	W	SAW	82.38
71.	Millstone-2	688	NU	CE	(utility)	81.88
72.	Dresden-2	784	CEC	CE	S&I	81.47
73.	Sequoyah-3	1108	CEC	W	S&I	82.74
74.	Millstone-3	1184	NU	W	SAW	82.88
75.	Sequoyah-4	885	CP&L	CE	UE&C	82.78
76.	South Texas-1	1281	HLAP	W	Babcock	82.28
77.	Rollins-2	788	CP&L	W	Fluor	82.14
78.	Crystal River-1	885	FC	SAW	Other	87.79
79.	Palo Verde-1	1378	APC	CE	Babcock	87.38
80.	Edison-3	1088	CEC	W	S&I	86.41
81.	Dresden-1	784	CEC	CE	S&I	81.54
82.	Oyster Creek	688	OP&N	CE	S&I/GE	81.47
83.	Peak Shinnecock	1088	PG&E	CE	Babcock	81.38
84.	WAPA-2	1188	WVPS	CE	S&I	81.66
85.	Palo Verde-2	1378	APC	CE	Babcock	81.38
86.	Sequoyah-4	885	CP&L	CE	UE&C	81.84
87.	Indian Point-2	988	Comstar	W	UE&C	84.77
88.	Plym	885	Duke	CE	Babcock	81.47
89.	Pittsford	885	Common	CE	Babcock	84.41
90.	Three Mile Island-2	1079	Watts	CE	SAW	81.88
91.	Sequoyah-4	788	VFC	W	SAW	81.77
92.	Indian Point	885	NU	W	SAW	81.88
93.	Chamber	885	FC	CE	S&I	81.88
94.	Edison-4	1088	CEC	W	S&I	81.11
95.	Palo Verde-3	1378	APC	CE	Babcock	87.42
96.	Peak Shinnecock	1088	PG&E	CE	Babcock	81.84
97.	Tulley Point-3	688	FP&L	W	Babcock	81.37
98.	Tulley	1128	Fortner	W	Babcock	84.88
99.	San Onofre-1	1888	SCS	W	Babcock	81.54
100.	Tulley Point-4	688	FP&L	W	Babcock	80.91
101.	Chamber Creek-1	885	PG&E	CE	Babcock	81.72
102.	New Mills Point-1	688	Watts	CE	(utility)	81.11
103.	Chamber Creek-2	885	PG&E	CE	Babcock	81.88
104.	Dresden Point-1	1079	TVA	CE	(utility)	13.43
105.	Summer Point-1	1088	TVA	CE	(utility)	0.88
106.	Summer Point-2	1088	TVA	CE	(utility)	0.88

NOTE: The power ratings shown are effective as of the end of 1991. If the rating changed in the previous three years, the capacity factor is calculated with an appropriate weighting factor. Some of the capacity factor figures shown are given as equal to other units, but the only tie is for last place, because neither Browns Ferry-1 nor Browns Ferry-2 generated any electricity during 1989-91. Fort-2, at 84.4131, is listed ahead of Edison-1, at 84.4130.

\*Assistant-engineering responsibility is considered to be shared by Babcock and the utility.

TABLE I  
1991-93 SINGLE-UNIT RANKINGS BY DER NET CAPACITY FACTOR

Rank	Unit	Factor	MWe	Utility	Vendor	A-E
1.	Surry-1	87.05	788	VPC	W	SAW
2.	Vogtle-1	86.99	1151	Southern	W	Bechtel*
3.	Vogtle-2	86.47	1151	Southern	W	Bechtel*
4.	Three Mile Island-1	86.18	819	OPUN	SAW	Gilbert
5.	Callaway	85.92	1171	UEC	W	Bechtel
6.	Point Beach-2	85.66	497	Wepac	W	Bechtel
7.	Palmer Island-1	85.05	230	NEP	W	Floor
8.	North Anna-2	84.81	907	VPC	W	SAW
9.	Oconee	84.66	470	EG&E	W	Gilbert
10.	Point Beach-1	84.41	497	Wepac	W	Bechtel
11.	Oconee-2	84.12	806	Duke	SAW	Bechtel*
12.	St. Lucie-1	84.12	820	FP&L	C-E	Ebasco
13.	Diablo Canyon-2	84.09	1119	PG&E	W	(utility)
14.	Diablo Canyon-1	83.44	1085	PG&E	W	(utility)
15.	Limerick-1	83.27	1055	FESCO	GE	Bechtel
16.	Limerick-2	83.23	1055	FESCO	GE	Bechtel
17.	Manitou	83.09	545	NEP	GE	Bechtel
18.	Vermont Yankee	82.99	514	VYAPC	GE	Ebasco
19.	Hops Creek	82.91	1067	PE&O	GE	Bechtel
20.	Waterford-2	82.77	1184	Energy	C-E	Ebasco
21.	ANO-1	82.71	820	Energy	SAW	Bechtel
22.	Parley-1	82.55	829	Southern	W	Bechtel*
23.	Davis-Besse	82.15	906	Comstar	SAW	Bechtel
24.	Palmer Island-2	82.08	530	NEP	W	Floor
25.	Catawba-2	82.04	1145	Duke	W	(utility)
26.	Susquehanna-2	81.66	1050	FP&L	GE	Bechtel
27.	Kewaunee	81.23	235	WPS	W	Floor
28.	Oconee-1	80.72	884	Duke	SAW	Bechtel*
29.	St. Lucie-2	80.66	820	FP&L	C-E	Ebasco
30.	Summer	80.09	900	EG&E	W	Gilbert
31.	Beaver Valley-2	80.07	826	Duquesne	W	SAW
32.	Parley-2	79.71	829	Southern	W	Bechtel*
33.	San Onofre-2	79.69	1090	SC&E	C-E	Bechtel
34.	Harris	79.65	900	CP&L	W	Ebasco
35.	Byron-2	79.34	1120	CECo	W	S&L
36.	Oconee-3	79.07	806	Duke	SAW	Bechtel*
37.	ANO-2	79.06	912	Energy	C-E	Bechtel
38.	San Onofre-1	78.80	1070	SC&E	C-E	Bechtel
39.	Sandwich	78.58	1148	NU	W	UE&C
40.	Cook-1	78.47	1020	HL&P	W	(utility)
41.	Crystal River-2	77.89	825	FPC	SAW	Gilbert
42.	Hatch-1	77.46	776	Southern	GE	Bechtel
43.	Byron-1	76.89	1120	CECo	W	S&L
44.	Braidwood-2	76.55	1120	CECo	W	S&L
45.	Grand Gulf	76.43	1250	Energy	GE	Bechtel
46.	Maine Yankee	76.45	870	MYAPC	C-E	SAW
47.	Arnold	76.43	538	HL&P	GE	Bechtel
48.	Calvert Cliffs-1	76.10	840	EG&E	C-E	Bechtel
49.	Palo Verde-2	75.72	1270	APS	C-E	Bechtel
50.	Ferns-2	75.28	1114	Dowd	GE	(utility)
51.	McGuire-2	74.43	1180	Duke	W	(utility)
52.	Maddux Neck	73.97	583	NU	W	SAW
53.	Susquehanna-1	73.90	1050	FP&L	GE	Bechtel
54.	Pilgrim	73.59	881	Bechtel	GE	Bechtel
55.	Wolf Creek	73.29	1170	WVOC	W	Bechtel
56.	Lafayette-1	72.22	1078	CECo	GE	S&L
57.	Surry-2	72.14	788	VPC	W	SAW
58.	Crocker	71.85	778	NFFD	GE	S&R
59.	Lafayette-2	71.72	1078	CECo	GE	S&L
60.	Palo Verde-1	71.68	1270	APS	C-E	Bechtel
61.	Oyster Creek	71.00	690	OPUN	GE	S&R/GE
62.	Hatch-2	70.85	784	Southern	GE	Bechtel*
63.	Robinson-2	70.80	700	CP&L	W	Ebasco
64.	Port Calhoun	70.69	478	OPFD	C-E	O&H
65.	Ernstwood-1	70.67	1120	CECo	W	S&L
66.	Catawba-1	70.65	1145	Duke	W	(utility)
67.	Palo Verde-3	70.33	1270	APS	C-E	Bechtel
68.	North Anna-1	69.91	907	VPC	W	SAW
69.	Climax	68.71	933	IPC	GE	S&L
70.	Calvert Cliffs-2	68.39	840	EG&E	C-E	Bechtel
71.	Nine Mile Point-1	68.30	613	NH&O	GE	(utility)
72.	Indian Point-2	68.14	906	ComEd	W	UE&C
73.	Nine Mile Point-2	68.07	1062	NH&O	GE	SAW
74.	Peash Bottom-2	68.00	1065	FESCO	GE	Bechtel
75.	Peash Bottom-1	68.01	1065	FESCO	GE	Bechtel
76.	Beaver Valley-1	68.24	826	Duquesne	W	SAW
77.	Catawba Peak-1	64.23	1180	TU	W	O&H
78.	Ferry-1	64.23	1191	Comstar	GE	Gilbert
79.	Browns Ferry-2	63.99	1065	TVA	GE	(utility)
80.	McGuire-1	63.94	1180	Duke	W	(utility)
81.	Big Rock Point	62.79	72	Comstar	GE	Bechtel
82.	Palisades	62.74	805	Comstar	C-E	Bechtel
83.	Sagoyah-2	61.77	1148	TVA	W	(utility)
84.	Ound Cliffs-1	61.40	789	CECo	GE	S&L
85.	Millstone-1	61.28	880	NU	GE	Ebasco
86.	Salmon-1	61.27	1115	PE&O	W	(utility)
87.	Salmon-2	61.10	1115	PE&O	W	(utility)
88.	Cook-2	59.75	1020	HL&P	W	(utility)
89.	River Bend	59.74	934	GEU	GE	SAW
90.	Ound Cliffs-2	59.33	789	CECo	GE	S&L
91.	WNP-2	58.60	1120	WPPSS	GE	S&R
92.	Zion-2	57.72	1040	CECo	W	S&L
93.	Turkey Point-2	57.00	893	FP&L	W	Bechtel
94.	Millstone-2	56.57	870	NU	C-E	Bechtel
95.	Zion-1	56.27	1040	CECo	W	S&L
96.	Sagoyah-1	55.85	1148	TVA	W	(utility)
97.	Turkey Point-4	55.55	893	FP&L	W	Bechtel
98.	South Texas-2	55.48	1231	HL&P	W	Bechtel
99.	Millstone-3	52.34	1154	NU	W	S&L
100.	Indian Point-3	52.21	965	NYPA	W	UE&C
101.	Dresden-2	50.74	794	CECo	GE	S&L
102.	Dresden-1	48.86	794	CECo	GE	S&L
103.	South Texas-1	48.99	1231	HL&P	W	Bechtel
104.	Brunswick-2	41.10	821	CP&L	GE	UE&C
105.	PligPatrik	37.83	814	NYPA	GE	SAW
106.	Brunswick-1	27.78	821	CP&L	GE	UE&C
107.	Browns Ferry-1	0.00	1065	TVA	GE	(utility)
108.	Browns Ferry-2	0.00	1065	TVA	GE	(utility)

The figures above, and elsewhere in this article, are rounded off for convenience. The only actual tie is for 107th place. Oconee-2 (84.12143) is indeed ahead of St. Lucie-1 (84.12126). Some plants' power ratings changed during the three-year period; the figures shown here are the ratings at the end of 1993, but the figures were computed with weighted averages on plants for which ratings changed.

\*Architect-engineering responsibility is considered to be shared by Bechtel and the utility.



TABLE I  
1993-95 SINGLE-UNIT RANKINGS BY DER NET CAPACITY FACTOR

Rank	Unit	Factor	MW's	Utility	Vendor	A-E	Rank	Unit	Factor	MW's	Utility	Vendor	A-E
1.	Prairie Island-1	90.55	530	NSP	W	Floor	51.	McGuire-2	79.17	1180	Duke	W	(utility)
2.	Vogtle-1	89.96	1169	Southern	GE	Bechtel*	52.	Clinon	79.12	933	IPC	GE	S&L
3.	Limerick-1	89.27	1055	FBCO	GE	Bechtel	53.	Catawba-2	79.04	1145	Duke	W	(utility)
4.	Vogtle-2	89.16	1169	Southern	W	Bechtel*	54.	Oyster Creek	78.95	650	OPUN	GE	B&R/GE
5.	Crystal River-3	88.81	825	FPC	B&W	Gilbert	55.	Surry-2	78.81	788	VPC	W	S&W
6.	Prairie Island-2	88.07	530	NSP	W	Floor	56.	Millstone-3	78.75	1154	NU	W	S&L
7.	Point Beach-1	88.05	497	Wepco	W	Bechtel	57.	Calvert Cliffs-2	78.63	845	BO&E	C-E	Bechtel
8.	Three Mile Island-1	88.00	819	OPUN	B&W	Gilbert	58.	St. Lucie-1	78.48	830	PP&L	C-E	Ebasco
9.	Monocello	87.80	545	NSP	GE	Bechtel	59.	Arnold	78.37	538	HL&P	GE	Bechtel
10.	Turkey Point-3	86.76	693	PP&L	W	Bechtel	60.	Seabrook	78.33	1148	NU	W	UE&C
11.	Catawba-1	86.67	1145	Duke	W	(utility)	61.	Palo Verde-1	77.77	1249	APS	C-E	Bechtel
12.	Callaway	86.60	1171	UEC	W	Bechtel	62.	Grand Gulf	77.72	1250	Emergy	GE	Bechtel
13.	Limerick-2	86.57	1115	FBCO	GE	Bechtel	63.	Palo Verde-3	77.07	1253	APS	C-E	Bechtel
14.	ANO-1	86.39	850	Emergy	B&W	Bechtel	64.	Braidwood-1	77.05	1120	ComEd	W	S&L
15.	Wolf Creek	86.16	1170	WCNOC	W	Bechtel	65.	Summer	76.54	900	SCE&G	W	Gilbert
16.	Peach Bottom-2	86.15	1119	FBCO	GE	Bechtel	66.	Robinson-2	76.04	700	CP&L	W	Ebasco
17.	Byron-2	85.99	1120	ComEd	W	S&L	67.	Susquehanna-1	75.40	1100	PP&L	GE	Bechtel
18.	Calvert Cliffs-1	85.81	845	BO&E	C-E	Bechtel	68.	Millstone-1	74.47	660	NU	GE	Ebasco
19.	Farley-1	85.71	829	Southern	W	Bechtel*	69.	Hatch-2	74.37	784	Southern	GE	Bechtel*
20.	Waterford-3	85.60	1104	Emergy	C-E	Ebasco	70.	Cook-1	74.30	1020	DMP	W	(utility)
21.	North Anna-1	85.28	907	VFC	W	S&W	71.	Byron-1	74.22	1120	ComEd	W	S&L
22.	Ginna	85.11	470	BO&E	W	Gilbert	72.	Pilgrim	73.49	655	Boston	GE	Bechtel
23.	Vermont Yankee	85.04	522	VYAPC	GE	Ebasco	73.	River Bend	73.48	936	GSU	GE	S&W
24.	Davis-Besse	84.58	906	Consolid	B&W	Bechtel	74.	Haddam Neck	73.16	582	NU	W	S&W
25.	Turkey Point-4	84.54	693	PP&L	W	Bechtel	75.	DeSalle-1	72.33	1078	ComEd	GE	S&L
26.	Fort Calhoun	84.27	478	OPPD	C-E	G&H	76.	St. Lucie-2	71.51	830	PP&L	C-E	Ebasco
27.	Nine Mile Point-1	84.27	613	NMCo	GE	(utility)	77.	Big Rock Point	71.49	72	Consumers	GE	Bechtel
28.	Point Beach-2	84.05	497	Wepco	W	Bechtel	78.	DeSalle-2	71.44	1078	ComEd	GE	S&L
29.	Oconee-3	83.88	886	Duke	B&W	Bechtel*	79.	Indian Point-2	71.16	986	ComEd	W	UE&C
30.	San Onofre-3	83.83	1080	SCE	C-E	Bechtel	80.	WNP-2	70.01	1153	WPPSS	GE	B&R
31.	Kewaunee	83.58	535	WPS	W	Floor	81.	Beaver Valley-1	69.73	835	Duquesne	W	S&W
32.	Diablo Canyon-1	83.55	1086	PG&E	W	(utility)	82.	Brunswick-2	69.53	821	CP&L	GE	UE&C
33.	San Onofre-2	83.34	1070	SCE	C-E	Bechtel	83.	Cook-2	68.73	1090	DMP	W	(utility)
34.	Diablo Canyon-2	83.33	1119	PG&E	W	(utility)	84.	McGuire-1	68.53	1180	Duke	W	(utility)
35.	Beaver Valley-2	83.16	836	Duquesne	W	S&W	85.	Elgin	67.84	816	NYP&A	GE	S&W
36.	Oconee-2	83.13	886	Duke	B&W	Bechtel*	86.	Zion-1	64.53	1040	ComEd	W	S&L
37.	Hatch-1	83.00	776	Southern	GE	Bechtel	87.	Zion-2	63.54	1040	ComEd	W	S&L
38.	North Anna-2	82.85	907	VFC	W	S&W	88.	Palo Verde-2	63.58	1249	APS	C-E	Bechtel
39.	Harris	82.66	900	CP&L	W	Ebasco	89.	Palladas	61.05	805	Consumers	C-E	Bechtel
40.	Susquehanna-2	82.61	1100	PP&L	GE	Bechtel	90.	Quad Cities-1	60.76	789	ComEd	GE	S&L
41.	ANO-2	82.41	912	Emergy	C-E	Bechtel	91.	Surry-1	56.48	1191	Consolid	GE	Gilbert
42.	Hope Creek	82.08	1067	PSE&G	GE	Bechtel	92.	Saprophy-2	55.64	1148	TVA	W	(utility)
43.	Oconee-1	81.45	886	Duke	B&W	Bechtel*	93.	South Texas-1	55.42	1251	HL&P	W	Bechtel
44.	Surry-1	81.41	788	VPC	W	S&W	94.	Millstone-2	55.41	870	NU	C-E	Bechtel
45.	Comanche Peak-1	80.49	1150	TU	W	G&H	95.	Maine Yankee	54.98	870	MYAPC	C-E	S&W
46.	Nine Mile Point-2	80.48	1143	NMCo	GE	S&W	96.	Brunswick-1	54.36	821	CP&L	GE	UE&C
47.	Farley-2	80.21	829	Southern	W	Bechtel	97.	South Texas-2	50.51	1251	HL&P	W	Bechtel
48.	Braidwood-2	79.91	1120	ComEd	W	S&L	98.	Cooper	49.34	778	NPPD	GE	B&R
49.	Browns Ferry-2	79.74	1065	TVA	GE	(utility)	99.	Salem-1	48.23	1115	PSE&G	W	(utility)
50.	Peach Bottom-3	79.56	1119	FBCO	GE	Bechtel	100.	Druden-3	48.20	794	ComEd	GE	S&L
							101.	Saprophy-1	46.94	1148	TVA	W	(utility)
							102.	Quad Cities-2	46.41	789	ComEd	GE	S&L
							103.	Fermi-2	45.75	1116	Detroit	GE	(utility)
							104.	Salem-2	44.89	1115	PSE&G	W	(utility)
							105.	Druden-2	43.07	794	ComEd	GE	S&L
							106.	Indian Point-3	10.50	965	NYP&A	W	UE&C
							107.	Browns Ferry-1	2.73	1065	TVA	GE	(utility)
							108.	Browns Ferry-3	0.00	1065	TVA	GE	(utility)

These figures, and others in this article, are rounded off. There are no actual ties: Fort Calhoun, in 26th place, has a factor of 84.274923, edging out Nine Mile Point-1's 84.272138. Some units' power ratings changed during the three-year period; the ratings shown here are those in effect at the end of 1995, but the factors were computed with weighted averages in cases where ratings changed.

\* Architect-engineering responsibility is considered to be shared by Bechtel and the utility.

**EXHIBITS TO THE TESTIMONY OF  
PERCY M. BEARD, JR.**

---

**EXHIBIT No. \_\_\_ (PMB-2)**

**TABLE II  
CAPACITY FACTOR CHANGE 1993-95 vs. 1990-92**

---

TABLE II  
CAPACITY FACTOR CHANGE, 1993-94 VS. 1990-91

Rank Unit	Factor Change, percentage points	Rank Unit	Factor Change, percentage points	Rank Unit	Factor Change, percentage points
1. Turkey Point-3	+42.35	37. Vogtle-2	+7.83	71. Palo Verde-3	+0.62
2. Calvert Cliffs-1	+36.66	38. Bridgwood-1	+7.83	72. Perry-2	+0.43
3. Browns Ferry-2	+36.58	39. Beaver Valley-2	+7.25	73. Surry-2	+0.41
4. Nine Mile Point-1	+35.33	40. McGuire-1	+7.11	74. Vermont Yankee	+0.28
5. Calvert Cliffs-2	+32.62	41. Bridgwood-2	+6.92	75. Monticello	+0.22
6. Turkey Point-4	+30.68	42. Vogtle-1	+6.38	76. Diablo Canyon-2	+0.02
7. FitzPatrick	+30.67	43. San Onofre-3	+6.22	77. Browns Ferry-1	+0.00
8. Brunswick-2	+28.09	44. McGuire-2	+5.85	78. North Anna-2	-0.92
9. Nine Mile Point-2	+25.15	45. Point Beach	+5.71	79. Oconee-2	-1.15
10. Peach Bottom-2	+23.92	46. Prairie Island	+5.57	80. Point Beach-2	-1.22
11. Millstone-3	+20.66	47. Brunswick-1	+5.37	81. Byron-1	-1.23
12. Crystal River-3	+20.15	48. Indian Point	+5.35	82. St. Louis-1	-1.34
13. Clinton	+19.71	49. Oconee-1	+5.20	83. LaSalle-2	-1.48
14. Fort Calhoun	+19.03	50. Three Mile Island	+4.89	84. Quad Cities-1	-2.05
15. Cook-2	+18.67	51. Westford-3	+4.66	85. Susquehanna-1	-2.99
16. Catawba-1	+18.58	52. Three Mile Island	+4.66	86. Dresden-3	-3.35
17. Zion-1	+17.67	53. Three Mile Island	+4.66	87. Summer	-3.56
18. Limerick-1	+17.26	54. ANO-2	+4.25	88. Hatch-2	-3.89
19. Haddam Neck	+16.08	55. Millstone-2	+4.11	89. Beaver Valley-1	-3.89
20. WNP-2	+15.87	56. Millstone-1	+4.11	90. DeSalle-1	-4.96
21. Zion-2	+15.69	57. Browns Ferry	+3.75	91. South Texas-1	-6.78
22. Palo Verde-1	+14.46	58. Clinch	+3.75	92. Dresden-2	-10.77
23. Millstone-1	+14.22	59. Grand Gulf	+3.75	93. Palo Verde-2	-11.09
24. Wolf Creek	+13.95	60. San Onofre-2	+3.64	94. St. Louis-2	-11.25
25. ANO-1	+12.64	61. Browns Ferry	+3.64	95. Shimo-1	-13.35
26. River Bend	+12.38	62. Clinch	+3.64	96. Salem-2	-15.75
27. Byron-2	+12.09	63. Clinch	+3.64	97. Perry-1	-16.09
28. Davis-Besse	+10.49	64. Haddam Neck	+3.64	98. Maine Yankee	-18.45
29. Oyster Creek	+10.05	65. Perry-1	+3.64	99. Quad Cities-2	-21.89
30. Robinson-2	+10.00	66. Diablo Canyon	+3.64	100. South Texas-2	-22.41
31. Hatch-1	+9.85	67. Susquehanna-2	+3.64	101. Sequoyah-2	-23.07
32. Prairie Island-1	+9.43	68. Oconee-1	+3.64	102. Flaming	-23.94
33. North Anna-1	+8.92	69. Palisades	+0.83	103. Sequoyah-1	-27.41
34. Peach Bottom-3	+8.80	70. Glina	+0.84	104. Cooper	-29.64
35. Big Rock Point	+8.72			105. Indian Point-3	-36.84



**EXHIBITS TO THE TESTIMONY OF  
PERCY M. BEARD, JR.**

---

**EXHIBIT No. \_\_\_\_ (PMB-3)  
IMPROVED TECHNICAL SPECIFICATION OF CR-3's  
LICENSE, SECTIONS 3.0.4, 3.5.2, 3.7.5 AND 3.8.1**

---

3.0 LIMITING CONDITION FOR OPERATION (LCO) APPLICABILITY

---

LCO 3.0.1 LCOs shall be met during the MODES or other specified conditions in the Applicability, except as provided in LCO 3.0.2.

---

LCO 3.0.2 Upon discovery of a failure to meet an LCO, the Required Actions of the associated Conditions shall be met, except as provided in LCO 3.0.5 and 3.0.6.

If the LCO is met or is no longer applicable prior to expiration of the specified Completion Time(s), completion of the Required Action(s) is not required, unless otherwise stated.

---

LCO 3.0.3 When an LCO is not met, except as provided in the associated ACTIONS, and an associated ACTION is not met or provided, the unit shall be placed in a MODE or other specified condition in which the Specification is not applicable. Action shall be initiated within 1 hour to place the unit, as applicable, in:

- a. MODE 3 within 7 hours;
- b. MODE 4 within 13 hours; and
- c. MODE 5 within 37 hours.

Exceptions to this Specification are stated in the individual Specifications.

Where corrective measures are completed that permit operation in accordance with the LCO or ACTIONS, completion of the actions required by LCO 3.0.3 is not required.

LCO 3.0.3 is only applicable in MODES 1, 2, 3, and 4.

---

LCO 3.0.4 When an LCO is not met, entry into a MODE or other specified condition in the Applicability shall not be made except when the associated ACTIONS to be entered permit continued

(continued)

---

3.0 LCO APPLICABILITY

---

LCO 3.0.4  
(continued) operation in the MODE or other specified condition in the Applicability for an unlimited period of time. This Specification shall not prevent changes in MODES or other specified conditions in the Applicability that are required to comply with ACTIONS.

Exceptions to this Specification are stated in the individual Specifications. These exceptions allow entry into MODES or other specified conditions in the Applicability when the associated ACTIONS to be entered allow unit operation in the MODE or other specified condition in the Applicability only for a limited period of time.

---

LCO 3.0.5 Equipment removed from service or declared inoperable to comply with ACTIONS may be returned to service under administrative control solely to perform testing required to demonstrate its OPERABILITY, the OPERABILITY of other equipment, or variables to be within limits. This is an exception to LCO 3.0.2 for the system returned to service under administrative control to perform the required testing.

---

LCO 3.0.6 When a supported system LCO is not met solely due to a support system LCO not being met, the Conditions and Required Actions associated with this supported system are not required to be entered. Only the support system Specification ACTIONS are required to be entered. This is an exception to LCO 3.0.2 for the supported system. In this event, additional evaluations and limitations may be required in accordance with Specification 5.6.2.16, "Safety Function Determination Program." If a loss of safety function is determined to exist by this program, the appropriate Conditions and Required Actions of the Specification in which the loss of safety function exists are required to be entered.

(continued)

---

3.5 EMERGENCY CORE COOLING SYSTEMS (ECCS)

3.5.2 ECCS—Operating

LCO 3.5.2 Two ECCS trains shall be OPERABLE.

APPLICABILITY: MODES 1, 2, and 3.

ACTIONS

CONDITION	REQUIRED ACTION	COMPLETION TIME
<p>A. One or more trains inoperable.</p> <p><u>AND</u></p> <p>At least 100% of the ECCS flow equivalent to a single OPERABLE ECCS train available.</p>	<p>A.1 Restor. train(s) to OPERABLE status.</p>	<p>72 hours</p>
<p>B. Required Action and associated Completion Time not met.</p>	<p>B.1 Be in MODE 3.</p> <p><u>AND</u></p> <p>B.2 Be in MODE 4.</p>	<p>6 hours</p> <p>12 hours</p>

3.7 PLANT SYSTEMS

3.7.5 Emergency Feedwater (EFW) System

LCO 3.7.5 Two EFW trains shall be OPERABLE.

-----NOTE-----  
 Only one EFW train, which includes a motor driven pump, is required to be OPERABLE in MODE 3 with steam generator pressure < 200 psig.  
 -----

APPLICABILITY: MODES 1, 2, and 3.

ACTIONS

CONDITION	REQUIRED ACTION	COMPLETION TIME
A. One steam supply to the turbine driven EFW pump inoperable.	A.1 Restore steam supply to OPERABLE status.	7 days <u>AND</u> 10 days from discovery of failure to meet the LCO
B. One EFW train inoperable for reasons other than Condition A.	B.1 Restore EFW train to OPERABLE status.	72 hours <u>AND</u> 10 days from discovery of failure to meet the LCO

(continued)

ACTIONS (continued)

CONDITION	REQUIRED ACTION	COMPLETION TIME
C. Required Action and associated Completion Time of Condition A or B not met.	C.1 Be in MODE 3. <u>AND</u> C.2 Be in MODE 4.	6 hours  12 hours
D. Two EFW trains inoperable.	- D.1 Initiate action to restore one EFW train to OPERABLE status.	Immediately



3.8 ELECTRICAL POWER SYSTEMS

3.8.1 AC Sources—Operating

- LCO 3.8.1 The following AC electrical power sources shall be OPERABLE:
- a. Two qualified circuits between the offsite transmission network and the onsite Class 1E AC Electrical Power Distribution System; and
  - b. Two emergency diesel generators (EDGs) each capable of supplying one train of the onsite Class 1E AC Electrical Power Distribution System.

APPLICABILITY: MODES 1, 2, 3, and 4.

ACTIONS

CONDITION	REQUIRED ACTION	COMPLETION TIME
A. One required offsite circuit inoperable.	A.1 Perform SR 3.8.1.1 for OPERABLE required offsite circuit.	1 hour <u>AND</u> Once per 8 hours thereafter
	<u>AND</u> A.2 Declare required feature(s), with no offsite power available, inoperable when its redundant required feature(s) are inoperable.	24 hours from discovery of no offsite power to one train concurrent with inoperability of redundant required feature(s)
	<u>AND</u>	(continued)

ACTIONS

CONDITION	REQUIRED ACTION	COMPLETION TIME
A. (continued)	<p>A.3 Restore required offsite circuit to OPERABLE status.</p>	<p>72 hours <u>AND</u> 6 days from discovery of failure to meet LCO</p>
B. One EDG inoperable.	<p>B.1 Perform SR 3.8.1.1 for OPERABLE offsite circuit(s).</p> <p><u>AND</u></p> <p>B.2 Declare required feature(s), supported by the inoperable EDG, inoperable when its redundant required feature(s) are inoperable.</p> <p><u>AND</u></p> <p>B.3.1 Determine OPERABLE EDG is not inoperable due to common cause failure.</p> <p><u>OR</u></p> <p>B.3.2 Perform SR 3.8.1.2 for OPERABLE EDG.</p> <p><u>AND</u></p>	<p>1 hour <u>AND</u> Once per 8 hours thereafter</p> <p>4 hours from discovery of Condition B concurrent with inoperability of redundant required feature(s)</p> <p>24 hours</p> <p>24 hours</p> <p>(continued)</p>

ACTIONS

CONDITION	REQUIRED ACTION	COMPLETION TIME
B. (continued)	B.4 Restore EDG to OPERABLE status.	72 hours <u>AND</u> 6 days from discovery of failure to meet LCO
C. Two required offsite circuits inoperable.	C.1 Declare required feature(s) inoperable when its redundant required feature(s) are inoperable.  <u>AND</u> C.2 Restore one required offsite circuit to OPERABLE status.	12 hours from discovery of Condition C concurrent with inoperability of redundant required feature(s)  24 hours

(continued)

ACTIONS (continued)

CONDITION	REQUIRED ACTION	COMPLETION TIME
<p>D. One required offsite circuit inoperable.</p> <p><u>AND</u></p> <p>One EDG inoperable.</p>	<p>-----NOTE----- Enter applicable Conditions and Required Actions of LCO 3.8.9, "Distribution Systems—Operating," when Condition D is entered with no AC power source to one train. -----</p> <p>D.1 Restore required offsite circuit to OPERABLE status.</p> <p><u>OR</u></p> <p>D.2 Restore EDG to OPERABLE status.</p>	<p>12 hours</p> <p>12 hours</p>
<p>E. Two EDGs inoperable.</p>	<p>E.1 Restore one EDG to OPERABLE status.</p>	<p>2 hours</p>
<p>F. Required Action and associated Completion Time of Condition A, B, C, D, or E not met.</p>	<p>F.1 Be in MODE 3.</p> <p><u>AND</u></p> <p>F.2 Be in MODE 5.</p>	<p>12 hours</p> <p>36 hours</p>
<p>G. Three or more required AC sources inoperable.</p>	<p>G.1 Enter LCO 3.0.3.</p>	<p>Immediately</p>