

**BEFORE THE FLORIDA
PUBLIC SERVICE COMMISSION**

**DOCKET NO. 060038-EI
FLORIDA POWER & LIGHT COMPANY**

**IN RE: FLORIDA POWER & LIGHT COMPANY'S PETITION FOR
ISSUANCE OF A STORM RECOVERY FINANCING ORDER**

APRIL 10, 2006

REBUTTAL TESTIMONY & EXHIBITS OF:

BARBARA A. JAINDL

DOCUMENT NUMBER-DATE

03208 APR 10 8

FPSC-COMMISSION CLERK

1 **BEFORE THE FLORIDA PUBLIC SERVICE COMMISSION**

2 **FLORIDA POWER & LIGHT COMPANY**

3 **REBUTTAL TESTIMONY OF BARBARA JAINDL**

4 **DOCKET NO. 060038-EI**

5 **APRIL 10, 2006**

6

7 **Q. Please state your name and business address.**

8 A. My name is Barbara Jaindl. My business address is 700 Universe Boulevard,
9 Juno Beach, Florida 33408-0420.

10 **Q. Did you previously submit direct testimony in this proceeding?**

11 A. No.

12 **Q. By whom are you employed and what is your position?**

13 A. I am employed by Florida Power & Light Company (FPL) as Director of
14 Transmission.

15 **Q. Please describe your duties and responsibilities in that position.**

16 A. For the past six years I have been responsible for the siting, design,
17 engineering, and construction of the transmission system. I recently assumed
18 the additional responsibility of maintenance and restoration of the
19 transmission lines.

20 **Q. Please describe your educational background and professional
21 experience.**

22 A. I have a Bachelor of Civil Engineering degree from Georgia Institute of
23 Technology and a Bachelor of Science in Electrical Engineering from

1 University of Miami. I have worked for FPL since 1976 in a variety of
2 positions involving transmission and substation. I have been supervisor of
3 civil/structural engineering, manager of design and standards, director of
4 substations, director of transmission and director of transmission projects. I
5 am a registered Professional Engineer in both Civil and Electrical Engineering
6 in the state of Florida.

7 **Q. What is the purpose of your rebuttal testimony?**

8 A. The purpose of my testimony is to address transmission issues raised by OPC
9 witness Byerley and provide details that support the reasonableness and
10 prudence of FPL's inspection, maintenance and replacement programs for
11 transmission facilities, especially with regard to the actions FPL took on the
12 Conservation-Corbett 500 kV line, the Alva-Corbett 230 kV line, and the 69
13 kV line on the Herbert Hoover dike of Lake Okeechobee. I will also address
14 the reasonableness of FPL's substation landscaping storm repair costs, which
15 are the subject of Staff Audit Finding No. 2 sponsored by Staff witness
16 Welch.

17

18 **CONSERVATION-CORBETT 500 KV LINE**

19 **Q. On page 3 of his testimony, Mr. Byerley claims that failure of the**
20 **Conservation-Corbett 500 kV transmission line is partly the result of**
21 **poor construction management practices. Please describe the**
22 **Conservation-Corbett 500 kV transmission line, its design and**

1 **construction specifications, and the construction quality assessment and**
2 **quality control.**

3 A. The Conservation-Corbett 500 kV line was energized in 1996. Twenty-eight
4 of the 57 miles of this line are in the South Florida Water Management
5 District Conservation areas. To minimize environmental impacts in the
6 conservation area, significant portions of the line were designed to allow
7 construction without building access roads.

8
9 Design considerations for roadless construction included structures that were
10 designed to reduce weight so that the majority of structures could be installed
11 with a helicopter. Overall, although the line design differed in some respects
12 from previous designs, it was built to all applicable industry standards and
13 guidelines including: National Electrical Safety Code (NESC) for clearance,
14 loading and strength requirements including extreme wind; EPRI (Electric
15 Power Research Institute) Transmission Line Reference Book (1982) for
16 phase spacing; NESC/OSHA (Occupational Safety & Health Administration)
17 requirements for safe minimum approach distance; ASCE (American Society
18 of Civil Engineers) 74 "Guideline for Electrical Transmission Line Structure
19 Loadings"; and ASCE 72 "Design of Steel Transmission Pole Structures" for
20 the H-frame designs.

21
22 The construction specifications for the structures on the Conservation-Corbett
23 500 kV line included both FPL standard and job specific requirements for

1 structure erection. Although FPL developed the design criteria and
2 participated in the design optimization, the structure design, fabrication and
3 erection details for the new Conservation-Corbett 500 kV structures were
4 developed by Thomas and Betts (T&B), and the T&B drawings were included
5 as part of the construction specifications. These drawings showed assembly
6 and erection requirements, including nut tightening specifications, which
7 referenced the 9th edition of American Institute of Steel Construction (AISC)
8 as the basis for these specifications. Specifically, the drawings called for the
9 “turn of the nut” method, which requires that the nut be rotated a specified
10 amount past snug. The specifications for the Conservation-Corbett 500 kV
11 structures were consistent with the T&B erection drawings used on previous
12 FPL 500 kV lines.

13
14 The industry standard practice for weathering steel connections, both at the
15 time of construction and today, is for the patina (the change in an object’s
16 surface due to oxidation) associated with the weathering steel to secure the
17 nuts on all bolted connections. FPL’s use of this locking mechanism on more
18 than 1,000 miles of weathering steel 500 kV structures has proven to be
19 effective, even under hurricane winds.

20
21 FPL’s construction inspection for this line, as for previous 500 kV lines, was
22 consistent with industry practices for oversight and acceptance of foundations
23 and anchors, structure assembly and erection, and conductor/overhead ground

1 wire (OHGW) sag and tensioning. FPL utilized experienced FPL construction
2 supervisors to oversee the Conservation-Corbett 500 kV line construction.

3 **Q. On page 7 of Mr. Byerley's testimony, he states that the Rural Utility**
4 **Service (RUS) requires use of locknuts on bolted connections to prevent**
5 **loosening by vibration. Is that bulletin pertinent to weathering steel**
6 **transmission structures?**

7 A. No. Rural Utilities Service (RUS) bulletin 1724e-200 section 15.4.1, is titled
8 "Structure Related Hardware for Wood Structures." In contrast, Section 15.5
9 applies to concrete and steel structures. That section goes on to explain that
10 hardware used on wood construction may be appropriate for steel structures
11 but could differ because wood can shrink or swell with age and weather over
12 time.

13
14 I also should note that even Section 15.5 would not directly apply to the
15 Conservation-Corbett structures, because it is for galvanized steel hardware
16 and does not address weathering steel. In the case of weathering steel,
17 the industry standard practice for connections is for the patina associated with
18 the weathering steel to secure the nuts on all bolted connections, not locknuts.

19 **Q. Mr. Byerley refers to loose and missing brace bolts on the Conservation-**
20 **Corbett towers. How did FPL first discover that there were loose and**
21 **missing bolts on the Conservation-Corbett transmission line and what**
22 **was determined to be the cause?**

1 A. FPL became aware of the loose/missing bolt issue in early 1998 as the result
2 of an outage investigation and follow-up inspections for an insulator failure.
3 During these inspections, FPL observed excessive vibration on the conductors
4 and also noted that some of the structure bolts appeared loose and that two
5 were missing.

6
7 The root cause of the loose/missing bolts was determined to be excessive
8 conductor vibration. The vibration caused some of the nuts on the bolt to
9 loosen from the snug tight specifications before the weathering steel patina
10 could “lock” them in place. The excessive conductor vibration was confirmed
11 by field measurements in a 1998 study that FPL performed jointly with the
12 Georgia Institute of Technology’s National Electric Energy Testing Research
13 and Application Center (NEETRAC) and Dulmison Products (provider of the
14 original wire-type spacer dampening system).

15 **Q. On page 6 of his testimony, Mr. Byerley states that “FPL did not take**
16 **adequate measures to remedy the situation”. Do you agree?**

17 A. No. In early 1998, the bolt status was inventoried for each structure in the
18 accessible area, and FPL took immediate action to replace missing bolts. The
19 NEETRAC study was done to measure the line vibration. After determining
20 that there was excessive conductor vibration and it was causing the bolts to
21 loosen, FPL took action in late 1998 to tighten the loose bolts in addition to
22 changing out corona rings and adding dampers to reduce the vibration. The
23 addition of these dampers reduced the conductor vibration to within industry

1 standard limits. After a follow-up conductor condition analysis was complete,
2 FPL installed additional vibration damping upgrades on the entire line in
3 1999.

4 **Q. On page 8 of his testimony, Mr. Byerley asserts that the 1998 inspection**
5 **results should have been entered into FPL's Asset Management System.**
6 **Do you agree?**

7 A. No. FPL's asset management system was developed at the component level
8 for items such as poles, cross-arms, insulators, conductor, OHGW, etc. It did
9 not have in 1998, and does not have today, the capability to record assets
10 down to the bolt level. Keep in mind that FPL has had no history of loose or
11 missing bolt problems on transmission structures such as those used on the
12 Conservation –Corbett 500 kV line and we reasonably believed the 1998-99
13 experience to be a vibration-induced anomaly that had been fully resolved by
14 the additional vibration dampers. Mr. Byerley's criticism is made only with
15 the benefit of 20/20 hindsight.

16 **Q. If the information was not entered into the asset management system,**
17 **how do you know the bolts were replaced or tightened?**

18 A. We confirmed that action was taken as planned by comparing bolt status post
19 Wilma with the original 1998 inspection results. This comparison revealed
20 that, of the 105 structures inspected in both 1998 and 2005, loose or missing
21 bolts were found at 31 locations in 1998 and 23 locations post-Wilma, with
22 only 15 locations common to both inspections. Thus, a little less than half of
23 the structures that had loose or missing bolts in 1998 also had them in 2005.

1 We concluded from this comparison that the bolts were tightened as specified
2 in 1998. Otherwise we would have found loose or missing bolts at all of the
3 original 31 locations at the time of the 2005 inspection.

4 **Q. On Page 11 of his testimony, Mr. Byerley states “clearly, the crews did**
5 **not follow the recommendation in the November 1998 FPL staff report to**
6 **peen the crossbrace bolt threads”. Why was this not done?**

7 A. At the top of the same page 11, Mr. Byerley summarized the
8 recommendations at the time: “if a nut is frozen, leave it alone”. This is the
9 criteria that the crews used to determine if the threads needed to be peened.
10 Clearly in hindsight this was not adequate and threads on all brace bolts are
11 now being peened post-Wilma.

12 **Q. On page 10 of his testimony, Mr. Byerley cites a statement from the “1998**
13 **Analytical Techniques, 500 kV Structure Fastener Problem” that refers**
14 **to the loosening of structure bolts as an “independent problem.” He**
15 **concludes from this statement that the bolts “should have been addressed**
16 **separately and effectively.” Do you agree?**

17 A. No. By “independent problem,” the author of the study simply meant that the
18 loose and missing bolts were another problem, in addition to insulator
19 damage, both of which were caused by excessive conductor vibration. FPL
20 knew at the time that conductor vibration, and not independent structural
21 vibration, was the culprit because the NEETRAC measurements performed in
22 March 1998 looked at vibration on both the conductors and structures.
23 NEETRAC concluded from those measurements that the vibration of the

1 conductor was excessive whereas the structural vibration was within the
2 expected range.

3 **Q. If FPL already knew the root cause of the loose bolts in 1998, then what**
4 **was the purpose of the “1998 Analytical Techniques, 500 kV Structure**
5 **Fastener Problem” that is attached to Mr. Byerley’s testimony as Exhibit**
6 **JSB-6?**

7 A. This 1998 study was a statistical analysis to determine if the “new”, lighter,
8 straight-leg H-frame structure was more prone to loose bolts from conductor
9 induced vibration than the “old”, slanted-leg H-frame structure. Both types of
10 structures are used on the Conservation-Corbett line, and both had
11 experienced loose bolts but in different proportions. In the conclusions of this
12 study (see pages 22-23 of Exhibit JSB-6) the author relates the loose bolts to
13 vibration and recommends the same solutions for the bolt issue without regard
14 to the structure type.

15 **Q. On page 3 of his testimony, Mr. Byerley claims that damages during**
16 **hurricane Wilma were exacerbated by inadequate inspection practices.**
17 **What are FPL’s normal inspection standards pertaining to the**
18 **Conservation-Corbett 500 kV transmission line?**

19 A. As part of its transmission system inspection, FPL schedules and conducts
20 detailed inspections on its 500 kV transmission structures on a 10% sample
21 population every 4 years.

22 **Q. Why is the practice of inspecting a 10% random sample of the 500 kV**
23 **steel structures appropriate?**

1 A. Sampling along with routine visual inspections and special assessments gives
2 FPL a good view of the overall condition of the steel structures on a 500 kV
3 line. The focus of the 10 % sampling is on a detailed inspection of the
4 structures. Depending upon the results from the sample population, additional
5 detailed inspections are scheduled accordingly.

6

7 The inspection for the other line components such as wire, insulator, and
8 conductor are normally done with special assessments (in addition to
9 sampling) based upon identified problems with age, manufacturer or
10 environment.

11 **Q. On page 8 of his testimony, Mr. Byerley states that, after the bolt issues**
12 **were found "... the line should have been completely inspected frequently**
13 **until the problem was resolved satisfactorily." Was this done?**

14 A. Yes. FPL conducted follow up special assessments on the Conservation-
15 Corbett 500 kV line post 1998 in addition to the 10% sample inspections.

16 **Q. Describe the additional inspections that occurred on the Conservation-**
17 **Corbett 500 kV line after the loose bolt issue was found.**

18 A. FPL increased the frequency of inspection on the Conservation-Corbett line
19 after the repairs in 1998/1999. Follow-up helicopter inspections on the line
20 were performed in 2001 and 2003 to ensure that there was no evidence of a
21 continuing vibration problem, which included an inspection of the bolts. All
22 the line insulators were thermovisioned in 2003, and the condition of the
23 structures was confirmed visually as part of that inspection. All these

1 inspections were in addition to the regularly scheduled climbing inspections
2 that were conducted on 10% of the structures in 2002 and the routine ground
3 patrols.

4

5 These additional inspections, well beyond the 10% standard inspection, were
6 well suited to identifying any loose or missing bolts.

7 **Q. Did FPL discover loose or missing bolts subsequent to 1998?**

8 A. One missing bolt was reported in 2002 as the result of a routine ground patrol.
9 None were reported from any of the other inspections.

10 **Q. What was determined to be the cause of the missing bolt that was**
11 **discovered in 2002?**

12 A. No specific cause was identified. However, as no other missing or loose bolts
13 were reported from the other inspections, FPL reasonably concluded that the
14 single missing bolt was an anomaly.

15 **Q. What does FPL now believe is the reason that the Conservation-Corbett**
16 **line experienced the additional loose and missing bolts that were**
17 **identified after Hurricane Wilma?**

18 A. FPL has carefully evaluated the design, construction, maintenance and
19 inspections of the Conservation-Corbett line. We have found nothing that
20 definitively caused the loose and missing bolts. At this point, it appears
21 possible that the loose and missing bolts may have resulted from subtle and
22 unanticipated interactions of components in the line, perhaps exacerbated by
23 the extraordinary loads imposed by hurricane-force winds. Because of this

1 uncertainty, we are taking all reasonably feasible measures to prevent
2 recurrence.

3 **Q. Please describe the corrective measures FPL is taking.?**

4 A. FPL is inspecting every structure bolt (crossbrace, foundation, crossarm, etc)
5 on the Conservation-Corbett 500 kV line, tightening them to a connection-
6 specific specification where necessary, and peening the exposed threads on all
7 cross brace and cross arm bolts to provide additional locking security beyond
8 the natural patina. Follow up inspections on the bolts are scheduled to be
9 completed prior to the start of hurricane season.

10

11 Additionally a detailed helicopter and ground inspection is being done on the
12 entire 500 kV system and is almost complete. No missing or loose bolts have
13 been identified on any other of FPL's 500 kV transmission lines. FPL is not
14 charging the cost of any of these measures as part of the storm recovery.

15

16 Due to physical damage, the conductor damping system for the entire line was
17 replaced post Wilma. The damping system was designed by a damper
18 manufacturer based upon line sag and tension characteristics. In order to
19 ensure the conductor vibration issue is effectively addressed with this new
20 system, FPL has installed conductor vibration monitors on the line. Data will
21 be reviewed over the next several months to ensure the system is working as
22 designed. The repair of this damage is part of storm recovery.

23

1 **Q. Was the foundation failure on the Conservation-Corbett 500 kV line the**
2 **result of insufficient quality specifications and inspection, as Mr. Byerley**
3 **suggests?**

4 A. No. The job specifications for cast-in-place foundations spelled out
5 comprehensive quality control and inspection criteria for the acceptance of
6 each foundation including: dimension checks, concrete checks, and concrete
7 placement surveillance with emphasis on ensuring a clean hole and continuous
8 pour. Although the contractor was responsible for inspecting and approving
9 work to ensure compliance with FPL drawings and specifications, FPL had
10 experienced construction supervisors doing surveillance inspections to ensure
11 foundations were being constructed to specifications. FPL's actions were
12 consistent with good industry practice to ensure that the foundations met the
13 specifications by specifying the quality requirements, requiring quality checks
14 on each foundations and doing surveillance inspection while the foundations
15 were being installed.

16
17 As a result of the foundation failure discovered after Hurricane Wilma, FPL
18 has visually inspected and "sounded" all the foundations and, where
19 warranted, is following up with core borings. FPL is not seeking to recover
20 the costs for this testing as part of the storm recovery.

21
22
23

1 **ALVA-CORBETT 230 KV LINE**

2 **Q. Please respond to Mr. Byerley's observations on the deterioration of the**
3 **wood structures on Alva-Corbett line and his assertion that they**
4 **contributed to the failure that occurred in Hurricane Wilma.**

5 A. I disagree with Mr. Byerley's conclusion that the failed transmission
6 structures on the Alva-Corbett 230 kV transmission line were a result of
7 deterioration. In May 2005, the most recent climbing inspection was
8 completed on the Alva-Corbett 230 kV line. During this inspection, no
9 problems were reported on the six (6) transmission poles that required
10 replacement as a result of hurricane Wilma.

11 **Q. What comments do you have in respect to the two deteriorated poles**
12 **referenced to by Mr. Byerley.**

13 A. We know from our hurricane forensics that none of the six structures that
14 failed on the Alva-Corbett line from hurricane Wilma was the result of
15 deterioration. Mr. Byerley's Exhibit JSB-2, photo 54 does not illustrate
16 transmission structure damage from hurricane Wilma but rather a stub that
17 was abandoned in place after damage from hurricane Frances (September
18 2004).

19
20 Similarly, Exhibit JSB-2, photo 51 simply shows a deteriorated pole on the
21 ground. The work site Mr. Byerley visited on the Alva-Corbett line is
22 currently under construction. I cannot conclude whether this particular

1 photograph was even from the Alva-Corbett 230 kV transmission line or the
2 timeframe from which it existed.

3 **Q. Please respond to Mr. Byerley's conclusion that FPL made an economic**
4 **decision to replace a portion of Alva-Corbett line that was leaning/**
5 **deteriorated rather than repair it.**

6 A. FPL indeed made economic decisions following the 2004 storm season
7 regarding the most cost-effective way to maintain the Alva-Corbett 230 kV
8 transmission line, and rightly so. FPL is currently rebuilding a portion of the
9 Alva-Corbett 230 kV transmission line as part of a planned system expansion
10 project. Knowing the rebuild project was forthcoming, FPL made an
11 economic decision after the 2004 storm season to temporarily brace 10 miles
12 of poles that were leaning as a result of Hurricane Frances in order to
13 minimize the cost to storm recovery. Since this particular rebuild project is
14 not storm related, the charges are not included in FPL's petition.

15 **Q. Please respond to the statements on page 15 of Mr. Byerley's testimony**
16 **that the leaning structures also indicate a potential for foundation failure**
17 **in a future storm.**

18 A. As discussed above, this portion of the line will be rebuilt prior to the 2006
19 storm season.

20

21 **OTHER TRANSMISSION LINE FAILURES**

22 **Q. On page 17 of his testimony, Mr. Byerley addresses the failure of a**
23 **number of other transmission structures. Please describe the ove rall**

1 **performance of the transmission system during the 2005 hurricane**
2 **season.**

3 A. There were 100 transmission structure failures as a result of Hurricane Wilma:
4 30 were on the Conservation-Corbett 500 kV line, which also caused five
5 wood H-frame structures to fail on the Alva-Corbett line; 46 were single pole
6 unguyed wood (or wood equiv) on three 69 kV line sections located on berms
7 in the vicinity of Lake Okeechobee which I will discuss below; and there were
8 19 random structure failures. Thus, out of 64,000 transmission structures in
9 the FPL system, only about 0.16% failed, which is very good performance in
10 the face of Wilma's strong winds.

11 **Q. On page 17, Mr. Byerley states that the failure of other 69 kV**
12 **transmission structures in western Palm Beach County could have been**
13 **avoided if they had been relocated prior to 2005. What structures is he**
14 **referring to?**

15 A. There are three 69 kV lines in the vicinity of Lake Okeechobee that are
16 installed on raised berms and that experienced failures in 2005. One was a
17 line that also failed in 2004 and had been partially relocated and rebuilt.

18 **Q. Mr. Byerley states that since the replaced and relocated poles performed**
19 **well during Wilma, that FPL should have taken some action on the**
20 **remaining poles to mitigate future damage. Please describe these**
21 **transmission structures and FPL's efforts to relocate the line after the**
22 **2004 hurricanes.**

1 A. The line that failed in 2004 was a 69 kV line that was constructed of single
2 unguyed wood poles located on the Herbert Hoover dike and dated back to
3 approximately 1963. It experienced failures as a result of hurricanes in both
4 2004 and 2005. The primary cause for these structure failures was the older
5 design standard and the high winds associated with the “coastal” effect of
6 Lake Okeechobee and the topographic speed-up effect associated with the
7 surrounding earth berm.

8
9 After the 2004 storm season, FPL relocated the portion (approximately 5.8
10 miles) of this transmission line section north of Canal Point that was
11 previously located along the Herbert Hoover Dike. It was relocated
12 approximately 300 feet east of the Herbert Hoover Dike and was rebuilt with
13 round spun concrete poles and polymer post insulators consistent with FPL’s
14 current design standard. FPL was able to quickly relocate and rebuild the
15 structures in this area because of limited commercial and residential
16 development along this portion of the transmission line. None of the
17 structures along this rebuilt portion of the transmission line required
18 replacement after Hurricane Wilma.

19
20 The southern portion of this transmission line south of Canal Point was also
21 located along the Herbert Hoover Dike. Relocation of this southern line
22 section was problematic, as it would either have significant community impact
23 by routing through residential and commercial areas or would require a

1 routing study and significant right of way acquisition to avoid the developed
2 areas. After the 2004 hurricane season, in order to ensure reliable service to
3 the area, this southern portion of the transmission line was rebuilt on the dike
4 with wood poles while an alternative route, permitting, right-of-way
5 acquisition and community outreach could properly be evaluated and
6 completed. The temporary rebuild of this line section could not be done to
7 current standards, because the poles could not be set as deep into the dike
8 surrounding Lake Okeechobee as would normally be FPL's practice. The
9 rebuilt section on the dike failed as a result of Hurricane Wilma. FPL is
10 aggressively pursuing relocation of this line section and anticipates
11 completion by mid 2006.

12 **Q. Would it have been possible for FPL to relocate all of the transmission**
13 **structures on the Herbert Hoover Dike prior to the 2005 hurricane**
14 **season?**

15 **A.** No. It was not possible to identify a new line route, conduct community
16 outreach, and acquire necessary permits and easements for the southern part of
17 the line prior to the 2005 hurricane season.

18

19 **SUBSTATION LANDSCAPING**

20 **Q. On page 4 and 5 of her testimony, Ms. Welch discusses the amount of**
21 **costs related to substation landscaping that the company should remove**
22 **from the storm reserve account if the Commission were to decide that**
23 **these costs should not be recovered. Is landscaping required at FPL**

1 **substations and is FPL required to replace or restore landscaping**
2 **damaged by hurricanes?**

3 A. Yes. Landscaping installed at substations is in response to local development
4 orders or code requirements. The landscaping shown on approved landscape
5 plans must be planted and then maintained by FPL; otherwise the site would
6 be in violation of the approved development order, which would result in code
7 enforcement action by the local jurisdiction. The effect of not
8 restoring/replacing landscaping would be to create the potential for “Notices
9 of Violation” (NOV’s) and/or monetary fines imposed by local jurisdictions.

10

11 **Q. Please summarize your testimony.**

12 A. FPL’s actions with regard to the design, construction, maintenance and
13 inspection of the transmission system, specifically including the facilities that
14 Mr. Byerley takes issue with, were all consistent with applicable standards
15 and codes and represent good utility practice. Mr. Byerley’s testimony raises
16 no valid points to the contrary.

17

18 The repair of substation landscaping is required to meet conditions of the
19 original site plan approval.

20 **Q. Does this conclude your rebuttal testimony?**

21 A. Yes.