



Matthew R. Bernier
ASSOCIATE GENERAL COUNSEL

March 1, 2021

VIA ELECTRONIC FILING

Adam J. Teitzman, Commission Clerk
Florida Public Service Commission
2540 Shumard Oak Boulevard
Tallahassee, Florida 32399-0850

Re: *2020 Annual Service Reliability Report; Undocketed*

Dear Mr. Teitzman:

Please find enclosed for electronic filing on behalf of Duke Energy Florida, LLC ("DEF"), its 2020 Annual Service Reliability Report. DEF also provided two (2) hard copies and two (2) CDs of its Annual Service Reliability Report to the Division of Engineering. Due to the implementation of Rule 25-6.030, F.A.C., the storm-hardening activities were excluded from this year's Reliability Report filing, and that the information will be filed by June 1, 2021 instead.

Additionally, on January 1, 2020, DEF re-organized its Zone boundaries to provide increased operational leadership at the local level to provide higher levels of customer service and ownership by balancing customer count between DEF's four Zones. This organizational change resulted in the Seven Springs and Zephyrhills Operation Centers moving to the North Coastal Zone. The metrics provided in the 2020 Annual Service Reliability Report reflect this organizational change.

Thank you for your assistance in this matter. Please feel free to call me at (850) 521-1428 should you have any questions concerning this filing.

Respectfully,

s/ Matthew R. Bernier

Matthew R. Bernier

MRB/cmw
Enclosures

cc: Tom Ballinger, Director, Division of Engineering



2020 Annual Service Reliability Report

March 1, 2021

Table of Contents

| | |
|-------------------------------------------------------------------------------------------|-----------|
| 2020 DEF Customer Count by Region | 2 |
| Overall Reliability Performance – 2020 (Unadjusted) (Rule 25-6.0455, F.A.C.) | 3 |
| Generation Events – Adjustments | 10 |
| Transmission Events – Adjustments | 12 |
| Extreme Weather – Exclusions | 13 |
| Other Distribution – Adjustments | 15 |
| 2020 Adjusted Reliability..... | 16 |
| Distribution Substations | 26 |
| Supplemental Distribution Information | 30 |
| Reliability-Related Customer Complaints | 37 |
| Wood Pole Inspection Program..... | 38 |
| CCA Sampling Report | 40 |



2020 Year End Customers Served by Region

| Zone/Regions | 3 Char OP | Op Center | Cust Served | Date |
|---------------|-----------|----------------|------------------|------------|
| NORTH CENTRAL | APK | APOPKA | 106,014 | 12/31/2020 |
| | DEL | DELAND | 87,353 | 12/31/2020 |
| | JAM | JAMESTOWN | 143,062 | 12/31/2020 |
| | LNG | LONGWOOD | 93,467 | 12/31/2020 |
| | | | 429,896 | |
| NORTH COASTAL | INV | INVERNESS | 78,974 | 12/31/2020 |
| | MON | MONTICELLO | 56,897 | 12/31/2020 |
| | OCA | OCALA | 82,174 | 12/31/2020 |
| | SEV | SEVEN SPRINGS | 199,584 | 12/31/2020 |
| | ZEP | ZEPHYRHILLS | 27,692 | 12/31/2020 |
| | | | 445,321 | |
| SOUTH CENTRAL | BNV | BUENA VISTA | 130,430 | 12/31/2020 |
| | CLR | CLERMONT | 38,971 | 12/31/2020 |
| | HIL | HIGHLANDS | 57,538 | 12/31/2020 |
| | LKW | LAKE WALES | 121,845 | 12/31/2020 |
| | SEO | SE ORLANDO | 97,451 | 12/31/2020 |
| | WGN | WINTER GARDEN | 86,132 | 12/31/2020 |
| | | | 532,367 | |
| SOUTH COASTAL | CLW | CLEARWATER | 149,674 | 12/31/2020 |
| | STP | ST. PETERSBURG | 183,488 | 12/31/2020 |
| | WAL | WALSINGHAM | 157,790 | 12/31/2020 |
| | | | 490,952 | |
| SYSTEM | | | 1,898,536 | |

OVERALL RELIABILITY PERFORMANCE – 2020 (Rule 25-6.0455, F.A.C.)

a. Discuss overall performance absent adjustments

In 2020, Duke Energy Florida, LLC (DEF) experienced 6 different tornados as well as Tropical Storm Eta. Prior to beginning of storm season (June 1) DEF’s service territory was impacted by three (3) tornados, two (2) on January 4th, resulting in 0.11 SAIDI minutes and 0.01 SAIDI minutes, respectively, as well as one (1) on April 20th resulting in 0.34 SAIDI minutes. Once storm season started, the tornadic activity continued with one (1) tornado on June 6th resulting in 0.21 SAIDI minutes and one (1) on August 18th resulting in 1.79 SAIDI minutes. From November 11th to November 12th, DEF experienced impacts of Tropical Storm Eta which accounted for 16.88 SAIDI minutes. After the storm season concluded, there was one (1) final tornado that occurred in DEF’s service territory on December 16th resulting in 1.65 SAIDI minutes.

| <i>Year</i> | <i>2015</i> | <i>2016</i> | <i>2017</i> | <i>2018</i> | <i>2019</i> | <i>2020</i> |
|-------------------------------|-------------|--------------|---------------|--------------|-------------|-------------|
| <i>Weather Excluded SAIDI</i> | <i>1.1</i> | <i>266.9</i> | <i>2469.0</i> | <i>105.4</i> | <i>3.2</i> | <i>21.0</i> |

2020 saw a drop in Weather Excluded SAIDI compared to the previous 5-year average. This is a result of the decrease in intensity and number of named storms that made landfall, reducing DEF’s unadjusted SAIDI by 442% compared to the prior 5-year average. This large reduction is a result of the large SAIDI in 2016, 2017 and 2018 from the large storms that made impacted DEF’s service territory, including Hurricanes Matthew, Irma and Michael. DEF continues to improve its reliability by concentrating on its Grid Investment Plan as well as through its pole replacement, cable replacement and beginning in 2021, the Storm Protection Plan.

| <i>Year</i> | <i>2015</i> | <i>2016</i> | <i>2017</i> | <i>2018</i> | <i>2019</i> | <i>2020</i> |
|-----------------------|-------------|--------------|---------------|--------------|--------------|--------------|
| <i>Reported SAIDI</i> | <i>98.6</i> | <i>370.7</i> | <i>2572.9</i> | <i>226.3</i> | <i>111.3</i> | <i>124.8</i> |

b. Describe the level of detailed reliability data the Company tracks.

DEF tracks detailed reliability information in various databases. This detailed data is recorded per event which includes affected device, time of day, length of outage, cause of outage, number of customers affected and other pertinent information.

c. Describe Company efforts to increase critical review of detailed reliability data.

In 2020, DEF continued to utilize the IEEE method for internal business goal reporting due to integrated business practices. DEF uses the IEEE Methodology (2.5 Beta) for calculating the reliability indices. This is also the way DEF measures reliability for incentive goals. DEF will continue tracking PSC indices which are reported at year end. The IEEE Method is the industry standard for Reliability measurement and comparison.

DEF continued the practice of auditing outage data to ensure accuracy and using Outage Management System Reconciliation (OMSR) as a platform which allows outage data to be captured in greater detail.

In 2020, DEF conducted analysis and reviewed reliability data that met certain operational thresholds in order to reduce the number of outages and momentary interruptions. From 2019 to 2020, DEF had a 29% decrease in the number of MAIFIE events.

d. Describe the process used by your company to identify and select the level of detailed reliability data.

Customer feedback, benchmarking with other utilities, input from the Florida Public Service Commission (FPSC), performance of assets, and trends are all considered when identifying the level of detailed reliability data.

e. Discuss adjustments.

- i. Generation events – see pages 10-11
- ii. Transmission events – see page 12
- iii. Extreme weather – see pages 13-14
- iv. Other Distribution events – see page 15

f. Discuss adjusted performance.

For the 2020 adjusted performance results, please see pages 16-24.

**FLORIDA PUBLIC SERVICE COMMISSION
ANNUAL DISTRIBUTION SERVICE RELIABILITY REPORT – ACTUAL**

PART I

| CAUSES OF OUTAGE EVENTS – ACTUAL (Absent Adjustments) | | | | |
|------------------------------------------------------------------------------|-------------------------------------------|-----------------------------------------|---------------------------------------|--------------------------------------------------|
| Utility Name: <u>Duke Energy Florida, LLC</u> | | | Year: 2020 | |
| Cause (a) | Customer Minutes Of Interruption | Number of Outage Events(N) (b) | Average Duration (L-Bar) (c) | Average Restoration Time (CAIDI) (d) |
| 1. Animals | 5,181,970 | 3,884 | 82.3 | 68.8 |
| 2. Vegetation | 55,483,993 | 9,548 | 173.0 | 120.3 |
| 3. Lightning | 3,243,352 | 1,002 | 158.4 | 98.4 |
| 4. Other Weather | 59,483,297 | 6,554 | 226.6 | 159.2 |
| 5. Vehicle | 14,340,034 | 510 | 245.6 | 111.6 |
| 6. Defective Equipment | 40,916,020 | 12,022 | 148.6 | 84.8 |
| 7. Unknown | 1,300,066 | 556 | 87.7 | 69.0 |
| | | | | |
| | | | | |
| | | | | |
| Subtotal | 179,948,732 | 34,076 | 163.6 | 114.4 |
| All Other Causes *See Attached | 56,938,969 | 16,443 | 142.2 | 54.2 |
| System Totals | 236,887,701 | 50,519 | 156.7 | 90.3 |
| | | | | |

PSC/ECR 102 (8/06)
Incorporated by reference in Rule 25-6.0455, F.A.C.

CAUSES OF OUTAGE EVENTS – ACTUAL ([Absent Adjustments](#))

Utility Name: Duke Energy Florida, LLC

Year: **2020**

| Cause (a) | Customer Minutes Of Interruption | Number of Outage Events(N) (b) | Average Duration (L-Bar) (c) | Average Restoration Time (CAIDI) (d) |
|-------------------------------------|-------------------------------------------|-----------------------------------------|---------------------------------------|--------------------------------------------------|
| U/G Primary Cable | 13,026,685 | 1,228 | 298.1 | 103.0 |
| Emergency Shutdown-PGN | 10,747,603 | 2,905 | 79.0 | 32.4 |
| Line Maintenance | 7,449,152 | 6,123 | 126.6 | 130.8 |
| Transmission-Storm | 3,108,346 | 12 | 750.5 | 174.8 |
| Right-Of-Way | 2,067,759 | 59 | 56.9 | 22.3 |
| Human Error-Public | 2,043,539 | 345 | 154.1 | 77.1 |
| U/G Secondary/Service | 1,780,708 | 3,573 | 185.8 | 232.3 |
| Substation-Human Error-PGN | 1,745,784 | 15 | 117.6 | 73.9 |
| Dig-In | 1,672,160 | 238 | 194.3 | 59.6 |
| Transmission-Insulator Failure | 1,638,862 | 33 | 52.2 | 51.0 |
| Substation-Breaker Failure | 1,348,488 | 21 | 54.6 | 39.6 |
| Substation-Animal | 1,070,029 | 24 | 35.1 | 20.0 |
| Substation-Defective Equipment | 1,026,197 | 14 | 231.9 | 54.9 |
| Substation-Unknown | 1,012,401 | 25 | 56.5 | 29.8 |
| Human Error-PGN Contractor | 870,119 | 222 | 90.5 | 54.0 |
| Foreign Material in Line | 670,755 | 65 | 118.8 | 147.1 |
| Relay-Relay Problem | 635,277 | 6 | 51.2 | 52.7 |
| Transmission-Tree-Nonprevent | 504,850 | 4 | 59.6 | 52.3 |
| Overload | 494,640 | 122 | 120.3 | 95.6 |
| Substation-Lightning | 474,255 | 5 | 79.5 | 46.4 |
| Substation-Bushing-Failure | 383,095 | 4 | 79.0 | 61.6 |
| Substation-Switch Failure | 323,928 | 2 | 124.0 | 87.4 |
| Relay-Wiring Error | 289,814 | 8 | 23.5 | 23.8 |
| Equipment Misapplication | 282,306 | 25 | 127.9 | 490.1 |
| Human Error-PGN | 234,192 | 355 | 71.5 | 25.0 |
| Miscellaneous | 232,704 | 626 | 89.5 | 97.5 |
| Transmission-Switch Error- PGN | 219,227 | 9 | 13.9 | 16.7 |
| Relay-Auto Reclose Cutout Sw | 192,808 | 1 | 77.0 | 77.0 |
| Substation-Potential Transformer | 190,224 | 4 | 63.5 | 49.5 |

PART II

THREE PERCENT FEEDER LIST - ACTUAL (UNADJUSTED)

Utility Name: Duke Energy Florida, LLC Year: 2020

| Primary Circuit Id. No. or Name (a) | Sub-station Origin (b) | Location (c) | Number of Customers | | | | | Outage Events "N" (i) | Avg Duration "L-Bar" (j) | CAIDI (k) | Listed Last Year? (l) | No. of Years in the Last 5 (m) | Corrective Action Completion Date (n) |
|-------------------------------------|------------------------|----------------|---------------------|----------------|----------------|-----------|-----------|-----------------------|--------------------------|-----------|-----------------------|--------------------------------|---------------------------------------|
| | | | Residential (d) | Commercial (e) | Industrial (f) | Other (g) | Total (h) | | | | | | |
| X121 | GATEWAY | WALSINGHAM | 98 | 517 | 46 | 26 | 687 | 8 | 172.6 | 55.1 | N | 1 | 6/30/21 |
| K1772 | CROOKED LAKE | LAKE WALES | 689 | 142 | 1 | 62 | 894 | 8 | 123.7 | 58.7 | N | 1 | 6/30/21 |
| A34 | REDDICK | OCALA | 1,490 | 259 | - | 61 | 1,810 | 7 | 153.3 | 127.2 | N | - | 12/31/21 |
| X151 | MAXIMO | ST. PETERSBURG | 2,157 | 125 | - | 91 | 2,373 | 6 | 198.5 | 35.1 | N | - | 12/31/21 |
| K1066 | LAKE PLACID | HIGHLANDS | 1,012 | 334 | 5 | 98 | 1,449 | 6 | 110.8 | 56.4 | Y | 1 | 6/30/21 |
| K1590 | FISHEATING CREEK | HIGHLANDS | 2,387 | 120 | - | 66 | 2,573 | 6 | 107.7 | 64.2 | Y | 1 | 6/30/21 |
| K1825 | NORTHRIDGE | LAKE WALES | 111 | 93 | - | 14 | 218 | 6 | 119.8 | 64.6 | N | - | 12/31/21 |
| A379 | OBRLEN | MONTECELLO | 553 | 150 | 1 | 64 | 768 | 6 | 197.2 | 219.0 | N | 1 | 6/30/21 |
| W1105 | DELAND EAST | DELAND | 1,281 | 65 | - | 96 | 1,442 | 5 | 286.8 | 129.8 | N | - | 12/31/21 |
| M3 | ZELLWOOD | APOPKA | 1,151 | 221 | 9 | 13 | 1,394 | 5 | 117.5 | 82.1 | Y | 2 | 6/30/21 |
| M445 | BAY RIDGE | APOPKA | 632 | 137 | 1 | 24 | 794 | 5 | 128.0 | 56.6 | N | 2 | 6/30/21 |
| X141 | MAXIMO | ST. PETERSBURG | 2,059 | 139 | - | 103 | 2,301 | 5 | 195.0 | 96.2 | Y | 1 | 6/30/21 |
| A36 | REDDICK | OCALA | 901 | 242 | - | 61 | 1,204 | 5 | 184.8 | 112.3 | N | - | 6/30/21 |
| K1885 | LAKE OF THE HILLS | LAKE WALES | 1,109 | 76 | 1 | - | 1,186 | 5 | 113.6 | 38.7 | N | 2 | 6/30/21 |
| A45 | GEORGIA PACIFIC | MONTECELLO | 990 | 246 | - | 113 | 1,349 | 5 | 145.9 | 101.3 | N | - | 12/31/21 |
| K3205 | PEMBROKE | HIGHLANDS | 1 | 17 | - | 2 | 20 | 5 | 289.9 | 316.0 | Y | 2 | 6/30/21 |
| K866 | WEST LAKE WALES | LAKE WALES | 845 | 191 | 3 | 48 | 1,087 | 4 | 125.0 | 100.2 | N | - | 6/30/21 |
| W0496 | CENTRAL PARK | SE ORLANDO | 66 | 198 | 6 | 5 | 275 | 4 | 116.1 | 47.2 | N | - | 12/31/21 |
| N195 | JENNINGS | MONTECELLO | 380 | 80 | 1 | 33 | 494 | 4 | 182.5 | 133.0 | N | 1 | 6/30/21 |
| K975 | BONNET CREEK | BUENA VISTA | 256 | 86 | - | 32 | 374 | 4 | 59.7 | 44.5 | Y | 3 | 6/30/21 |
| W0502 | MAGNOLIA RANCH | SE ORLANDO | 2,377 | 73 | 2 | - | 2,452 | 4 | 131.7 | 58.2 | N | - | 6/30/21 |
| K861 | SHINGLE CREEK | BUENA VISTA | 1,209 | 162 | 1 | 48 | 1,420 | 4 | 213.0 | 80.0 | N | - | 12/31/21 |
| X113 | GATEWAY | WALSINGHAM | 2,065 | 163 | - | 37 | 2,265 | 4 | 221.5 | 58.3 | N | - | 6/30/21 |
| X97 | BAYWAY | ST. PETERSBURG | 1,500 | 169 | 1 | 86 | 1,756 | 4 | 132.2 | 29.3 | N | - | 12/31/21 |
| W0202 | MONASTERY | DELAND | 1,285 | 105 | - | 54 | 1,444 | 4 | 152.2 | 65.3 | N | - | 12/31/21 |
| N332 | ST MARKS WEST | MONTECELLO | 979 | 96 | - | 69 | 1,144 | 4 | 139.2 | 133.7 | Y | 3 | 6/30/21 |
| X63 | DISSTON | WALSINGHAM | 2,544 | 216 | 2 | 52 | 2,814 | 4 | 183.7 | 157.4 | N | - | 12/31/21 |
| N36 | CRAWFORDVILLE | MONTECELLO | 1,109 | 111 | - | 28 | 1,248 | 4 | 120.8 | 70.2 | N | 1 | 6/30/21 |
| X37 | THIRTY SECOND STREET | ST. PETERSBURG | 2,337 | 119 | - | 56 | 2,512 | 4 | 142.9 | 76.1 | N | - | 12/31/21 |
| N68 | MONTECELLO | MONTECELLO | 217 | 89 | - | 12 | 318 | 4 | 143.8 | 52.0 | N | 2 | 6/30/21 |
| W0372 | ORANGE CITY | DELAND | 1,822 | 59 | 2 | - | 1,883 | 4 | 120.7 | 106.5 | N | - | 12/31/21 |
| C855 | ZEPHYRHILLS | ZEPHYRHILLS | 2,894 | 179 | 12 | 146 | 3,231 | 4 | 150.6 | 54.7 | N | - | 12/31/21 |
| K2247 | HEMPLE | WINTER GARDEN | 716 | 56 | - | 4 | 776 | 4 | 200.0 | 88.6 | N | - | 12/31/21 |
| A90 | TRENTON | MONTECELLO | 921 | 204 | 3 | 68 | 1,196 | 4 | 139.8 | 98.2 | N | 2 | 6/30/21 |
| J141 | CROSS BAYOU | WALSINGHAM | 779 | 333 | 43 | 57 | 1,212 | 4 | 182.0 | 88.6 | N | - | 12/31/21 |
| C103 | DUNEDIN | CLEARWATER | 2,836 | 199 | - | 111 | 3,146 | 4 | 169.2 | 99.8 | N | - | 12/31/21 |
| A196 | ARCHER | MONTECELLO | 332 | 101 | - | 66 | 499 | 4 | 157.2 | 140.1 | N | 1 | 6/30/21 |
| A46 | CROSS CITY INDUSTRIAL | MONTECELLO | 333 | 126 | 2 | 28 | 489 | 4 | 140.7 | 74.0 | Y | 1 | 6/30/21 |
| A96 | BROOKSVILLE | INVERNESS | 1,221 | 331 | 9 | 77 | 1,638 | 4 | 156.2 | 109.6 | N | - | 12/31/21 |
| C906 | EAST CLEARWATER | CLEARWATER | 2,115 | 210 | - | 69 | 2,394 | 4 | 186.4 | 61.9 | N | - | 12/31/21 |
| W0809 | DELAND | DELAND | 629 | 219 | 4 | 48 | 900 | 3 | 142.4 | 51.4 | N | - | 12/31/21 |
| K232 | LAKE BRYAN | BUENA VISTA | 1,036 | 63 | 0 | 11 | 1,110 | 3 | 298.0 | 79.4 | N | - | 12/31/21 |

LBAR AND CAIDI Includes all devices.

PSC/ECR 102 (8/06)

Incorporated by reference in Rule 25-6.0455, F.A.C.

PART III

| SYSTEM RELIABILITY INDICES – ACTUAL (ABSENT ADJUSTMENTS) | | | | | |
|----------------------------------------------------------|--------------|--------------|-------------|------------|--------------|
| Utility Name: Duke Energy Florida, LLC Year: 2020 | | | | | |
| District or Service Area (a) | SAIDI (b) | CAIDI (c) | SAIFI (d) | MAIFle (e) | CEMI5 (f) |
| North Coastal | 153.5 | 99.0 | 1.6 | 6.6 | 2.74% |
| Inverness | 217.5 | 123.3 | 1.76 | 7.3 | 5.14% |
| Monticello | 245.9 | 103.4 | 2.38 | 6.4 | 6.41% |
| Ocala | 186.6 | 96.3 | 1.94 | 6.8 | 5.33% |
| Seven Springs | 100.1 | 89.2 | 1.12 | 6.4 | 0.06% |
| Zephyrhills | 67.3 | 56.9 | 1.18 | 5.6 | 0.00% |
| South Coastal | 160.8 | 101.3 | 1.59 | 6.4 | 1.29% |
| Clearwater | 151.0 | 96.4 | 1.57 | 6.6 | 0.66% |
| St. Petersburg | 153.1 | 91.5 | 1.67 | 5.8 | 2.44% |
| Walsingham | 178.9 | 118.7 | 1.51 | 6.9 | 0.55% |
| North Central | 106.0 | 92.4 | 1.15 | 3.2 | 0.58% |
| Apopka | 94.9 | 94.8 | 1.00 | 6.9 | 0.54% |
| Deland | 162.2 | 111.1 | 1.46 | 2.9 | 1.77% |
| Jamestown | 75.9 | 69.4 | 1.09 | 0.2 | 0.11% |
| Longwood | 112.4 | 101.8 | 1.10 | 3.8 | 0.24% |
| South Central | 82.7 | 66.7 | 1.24 | 5.7 | 1.57% |
| Buena Vista | 45.5 | 72.3 | 0.63 | 4.2 | 0.00% |
| Clermont | 74.1 | 70.9 | 1.04 | 3.8 | 0.15% |
| SE Orlando | 92.4 | 72.7 | 1.27 | 9.1 | 5.33% |
| Highlands | 113.4 | 63.6 | 1.78 | 7.7 | 2.66% |
| Lake Wales | 78.5 | 58.2 | 1.35 | 1.9 | 0.45% |
| Winter Garden | 117.5 | 69.1 | 1.70 | 8.7 | 2.08% |
| System | 124.8 | 90.3 | 1.38 | 5.5 | 1.55% |

GENERATION EVENTS – ADJUSTMENTS (Rule 25-6.0455, F.A.C.)

- a. Discuss each generation event that resulted in customer outages.**

There were no events to report for 2020.

- b. Address whether the event was localized or system-wide.**

N/A

- c. Describe the Company’s efforts to avoid or minimize any similar events in the future in terms of the level of costs incurred and outage duration.**

N/A

- d. Provide the 2020 service reliability data for each generation outage event that is excluded from your Company’s 2020 Annual Distribution Reliability Report pursuant to Rule 25-6.0455.**

| | |
|------------------|-----|
| Generation Event | N/A |
| C | N/A |
| CMI | N/A |
| CI | N/A |
| SAIDI | N/A |
| SAIFI | N/A |

Please see Form 103 below.

PART I

| <u>CAUSES OF OUTAGE EVENTS – ADJUSTED</u> | | | |
|-------------------------------------------|-----------------------------------------|---------------------------------------|--------------------------------------------------|
| Utility Name: Duke Energy Florida, LLC | | | Year: 2020 |
| Cause (a) | Number of Outage Events(N) (b) | Average Duration (L-Bar) (c) | Average Restoration Time (CAIDI) (d) |
| Generation | N/A | N/A | N/A |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| System Totals: | N/A | N/A | N/A |

PSC/ECR 103 (8/06)
 Incorporated by reference in Rule 25-6.0455, F.A.C.

TRANSMISSION EVENTS – ADJUSTMENTS (Rule 25-6.0455, F.A.C.)

a. Discuss each transmission event that resulted in customer outages.

See Attachment A – “DEF Transmission Outages 2020 - Major Events Excluded.”

b. Address whether the event was localized or system-wide.

See Attachment A – “DEF Transmission Outages 2020 - Major Events Excluded.”

c. Describe the Company’s efforts to avoid or minimize any similar events in the future in terms of the level of costs incurred and outage duration.

Outages are reviewed and investigated by local transmission maintenance staff. The results from these investigations are looked at from a system-perspective by DEF’s Transmission Department Asset Management Group to determine if the failure is isolated or similar failures are occurring on another part of the system. When similar failures are noted on the system, further investigation is performed to determine if a solution should be implemented system-wide to remedy the problem. If a project is required, it is submitted for prioritization against other projects.

d. Provide the 2020 service reliability data for each transmission outage event that is excluded from your Company’s 2020 Annual Distribution Reliability Report pursuant to Rule 25-6.0455.

There were no events outside of Extreme Weather that resulted in CMI in 2020 per Rule 25-6.0455. This information is reflected in Attachment B – “DEF Transmission Outages 2020 - Major Events Only.”

EXTREME WEATHER - EXCLUSIONS (Rule 25-6.0455, F.A.C.)

- a. Include in the discussion, the type of weather event, strength (wind speeds/surge-flood levels), locations affected, source of meteorological information and the performance of overhead and underground systems.

Distribution

| Dates | Type of Weather Event | Strength (Wind Speeds/surge-flood levels) | Locations affected | Source of Metrological Information | Performance of Overhead and Underground Systems |
|-------------------------------------------|-----------------------|-------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------|------------------------------------------------------------|
| 14/2020 - 11:00 AM to 11:59 AM | Tornado | Unknown Wind Speed | Deland | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |
| 14/2020 - 11:00 PM to 11:59 PM | Tornado | Unknown Wind Speed | Lake Wales | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |
| 4/20/2020 - 9:00 AM to 10:59 AM | Tornado | Unknown Wind Speed | Inverness | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |
| 6/6/2020 - 7:00 PM to 7:59 PM | Tornado | Unknown Wind Speed | SE Orlando | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |
| 8/18/2020 - 3:00 PM to 4:59 PM | Tornado | Unknown Wind Speed | Deland | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |
| 11/11/2020 3:00 PM to 11/12/2020 11:59 AM | Tropical Storm Eta | 39 to 73 mph | Clearwater Inverness Monticello Ocala Seven Springs St. Petersburg Walsingham Zephyrhills | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |
| 12/16/2020 3:00 PM to 4:59 PM | Tornado | Unknown Wind Speed | Clearwater Seven Springs Walsingham | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |

Transmission

There were four major Extreme Weather events resulting in CMI that were excluded in 2020. This information is reflected in Attachment B – “DEF Transmission Outages 2020 - Major Events Only.”

- b. Describe the Company’s efforts to avoid or minimize in terms of costs incurred and outage duration any similar events in the future (Example: Reference specific storm hardening activity).

Distribution

These efforts are addressed in “DEF’s 2019-2021 Storm Hardening Plan” that was filed on March 1, 2019 (Attachment J).

Transmission

These efforts are addressed in “DEF’s 2019-2021 Storm Hardening Plan” that was filed on March 1, 2019 (Attachment J).

- c. If the method of deriving the weather exclusion is different from the method used for 2015, please explain the changes and provide the CMI and CI for 2020 using the prior method.

For Distribution & Transmission – The same exclusion method has been used for years 2015 through 2020.

- d. Provide the 2020 service reliability data for each transmission outage event that is excluded from your Company’s 2020 Annual Distribution Reliability Report pursuant to Rule 25-6.0455.

Distribution

| Dates | Overhead vs. Underground | C | CMI | CI | Duration | L-Bar | N |
|-------------------------------------------|--------------------------|---------|------------|--------|----------|---------|-----|
| 1/4/2020 - 11:00 AM to 11:59 AM | OH | 87,353 | 206,775 | 1,140 | 3,307 | 472.4 | 7 |
| | UG | | - | - | - | - | - |
| 1/4/2020 - 11:00 PM to 11:59 PM | OH | 121,845 | 11,200 | 50 | 224 | 224.2 | 1 |
| | UG | | - | - | - | - | - |
| 4/20/2020 - 9:00 AM to 10:59 AM | OH | 78,974 | 654,652 | 2,129 | 11,009 | 379.6 | 29 |
| | UG | | - | - | - | - | - |
| 6/6/2020 - 7:00 PM to 7:59 PM | OH | 97,451 | 395,301 | 1,663 | 4,927 | 1,231.7 | 4 |
| | UG | | - | - | - | - | - |
| 8/18/2020 - 3:00 PM to 4:59 PM | OH | 87,353 | 3,391,430 | 7,602 | 54,901 | 963.2 | 57 |
| | UG | | 237 | 1 | 237 | 237.1 | 1 |
| 11/11/2020 3:00 PM to 11/12/2020 11:59 PM | OH | 936,273 | 30,198,251 | 98,851 | 630,687 | 733.4 | 860 |
| | UG | | 1,841,540 | 2,562 | 64,857 | 600.5 | 108 |
| 12/16/2020 3:00 PM to 4:59 PM | OH | 507,048 | 3,100,576 | 12,948 | 10,307 | 572.6 | 18 |
| | UG | | 41,047 | 358 | 924 | 307.9 | 3 |

Transmission

There were four major Extreme Weather events resulting in CMI that were excluded in 2020. This information is reflected in Attachment B – “DEF Transmission Outages 2020 - Major Events Only.”

OTHER DISTRIBUTION – ADJUSTMENTS (Rule 25-6.0455, F.A.C.)

- a. Discuss the causation of each type of distribution event that resulted in customer complaints.**

Since DEF has not taken “other” causations as exclusions for any events in 2020, DEF has no information to report in this section.

- b. Describe the Company’s efforts to avoid or minimize any similar events in the future in terms of the level of costs incurred and outage duration.**

Since DEF has not taken “other” causations as exclusions for any events in 2020, DEF has no information to report in this section.

- c. Provide the 2020 service reliability data for each distribution outage event that is excluded from your Company’s 2021 Annual Distribution Reliability Report pursuant to Rule 25-6.0455.**

- i. A table
- ii. Electronic file
- iii. Causation, Date, CMI, CI Total Repair Cost, etc.

Since DEF has not taken “other” causations as exclusions for any events in 2020, DEF has no information to report in this section.

2020 ADJUSTED RELIABILITY (Rule 25-6.0455, F.A.C.)

DEF’s 2020 annual adjusted SAIDI was 87.9, a 3% decrease from SAIDI observed in 2019 following an 8% decrease from 2018. The primary driver for 2020 was caused by weather-related outages.

There were 8 days in 2020 that totaled more than 1 SAIDI minute each. All of the 8 days had weather-related outages as the driving factor with more than 60% of the outages for each day being weather-related. These 8 days were February 6th (4.68 SAIDI), February 7th (1.04 SAIDI), April 24th (1.60 SAIDI), May 18th (1.17 SAIDI), May 22nd (1.19 SAIDI), August 9th (1.59 SAIDI), August 30th (1.14 SAIDI) and December 24th (2.16 SAIDI).

In 2020, DEF had more impact from tornados compared to the previous 5 years, with 6 tornados touching down as well as the impact of Tropical Storm Eta. DEF had a reduction in SAIDI compared to 2018 and 2019 and continues to see a decline of SAIFI, MAIFIe, and CEMI5 over the last 5 years. This is part DEF’s efforts to focus on minimizing outages through investing in the grid with the Grid Investment Plan.

| <i>Year</i> | <i>2015</i> | <i>2016</i> | <i>2017</i> | <i>2018</i> | <i>2019</i> | <i>2020</i> |
|-----------------------|-------------|-------------|-------------|-------------|-------------|-------------|
| <i>Adjusted SAIDI</i> | <i>79.7</i> | <i>85.0</i> | <i>82.7</i> | <i>98.5</i> | <i>90.5</i> | <i>87.9</i> |

| <i>Year</i> | <i>2015</i> | <i>2016</i> | <i>2017</i> | <i>2018</i> | <i>2019</i> | <i>2020</i> |
|-----------------------|-------------|-------------|-------------|-------------|-------------|-------------|
| <i>Adjusted SAIFI</i> | <i>0.98</i> | <i>0.98</i> | <i>0.92</i> | <i>1.01</i> | <i>0.97</i> | <i>0.94</i> |

a. Causes of outages events – see attached forms.

i. 5-yr patterns/trends in outage causation for each of the top 10 causes of outage events, including the frequency, duration, restoration time, cost incurred to restore service, remediation programs and costs.

- See Attachment D – “2020 Adjusted Reliability (5 yr. Trend by Cause Code)” Spreadsheet for 2016 – 2020.

ii. The process used to identify and select the actions to improve the performance in each of the top 10 causes of outages.

DEF prioritizes the reliability improvement action plan by balancing historical and current year performance. System devices are evaluated based on the number of interruptions, customers interrupted (CI) and customer minutes of interruption (CMI). In addition, current year performance is monitored monthly to identify emergent and seasonal issues including load balancing for cold weather and the need for foot patrols of devices experiencing multiple interruptions.

iii. 2020 activities and financial projection levels addressing each of the 10 causes of service outage.

- See Attachment E – “2021 Program Budget” Spreadsheet.

b. Three percent Feeder list

Identify whether any feeders appear on the 3% listing more than once within a consecutive 5-year period and any actions implemented to improve feeder performance.

Feeder K1772:

- DEF Infrared scanned main feeder K1772 in 2018. No hotspots were found. DEF will continue to scan main feeder of K1772 in June/July 2021.
- K1772 experienced 5 feeder level outages in 2020. Two were caused by vehicle accident, 1 was caused by lightning and 2 were caused by failed equipment. One of the failed equipment outages was caused by a recloser that failed and the other was caused by a failed connection to an overhead switch.
- DEF completed backbone trimming in 2019. K1772 is planned to have the backbone trimmed in 2021.
- Operations techs will continue to analyze feeder and perform an in-depth patrol to identify operational issues and initiate mitigation actions.

Feeder A36:

- DEF Infrared scanned main feeder A36 in 2017. DEF will continue to scan main feeder of A36 in June/July 2021.
- A36 experienced 4 feeder level outages in 2020. One outage was caused by nonpreventable tree damage, 1 was caused by a wire that came down during a storm, 1 was caused by a connector failure and 1 was caused by a vehicle accident.
- DEF completed backbone tree trimming in 2020.
- A36 was part of a Self-Optimizing Grid Team that deployed in early 2021.
- Operations techs will continue to analyze feeder and perform an in-depth patrol to identify operational issues and initiate mitigation actions.

Feeder X141:

- DEF Infrared scanned main feeder X141 in 2020. DEF will continue to scan main feeder of A36 in June/July 2021.
- X141 experienced 3 feeder level outages in 2020. Two outages were caused by connector failures and 1 by a failed underground cable on an overhead to underground pole.
- DEF completed backbone tree trimming in 2020.

- Operations techs will continue to analyze feeder and perform an in-depth patrol to identify operational issues and initiate mitigation actions.

Feeder M33:

- DEF Infrared scanned main feeder M33 in 2020. No hotspots were found. DEF will continue to scan main feeder of M33 in June/July 2021.
- M33 experienced 3 feeder level outages in 2020. All 3 outages were caused by connector failures.
- DEF completed backbone tree trimming in 2020.
- DEF completed transformer retrofit on feeder M33 in 2020.
- M33 is planned to be part of a new Self Optimizing Grid Team deploying in 2021.
- Operations techs will continue to analyze feeder and perform an in-depth patrol to identify operational issues and initiate mitigation actions.

Feeder A186:

- DEF Infrared scanned main feeder A186 in 2020. DEF will continue to scan main feeder of M33 in June/July 2021.
- A186 experienced 3 feeder level outages in 2020. All 3 outages were caused by nonpreventable tree damage.
- DEF completed backbone trimming in 2019. A186 is planned to have the backbone trimmed in 2021.
- Operations techs will continue to analyze feeder and perform an in-depth patrol to identify operational issues and initiate mitigation actions.

Feeder A195:

- DEF Infrared scanned main feeder A195 in 2017. DEF will continue to scan main feeder of A195 in June/July 2021.
- A195 experienced 3 feeder level outages in 2020. Two of the outages were caused by afternoon thunderstorms and 1 was caused by nonpreventable tree damage.
- DEF completed backbone trimming in 2019. A195 is planned to have the backbone trimmed in 2021.
- Operations techs will continue to analyze feeder and perform an in-depth patrol to identify operational issues and initiate mitigation actions.

i. The process used to identify and select the actions to improve the performance of feeders in the 3% feeder list, if any

DEF prioritizes the reliability improvement action plan for 3% Feeder List by balancing historical and current year performance. Feeders are evaluated based on the number of interruptions, interruption cause code, customers interrupted (CI), and customer minutes of interruption (CMI). In addition, current year performance is monitored monthly to identify emergent and

seasonal issues including load balancing for cold weather and the need for foot patrols of feeders experiencing multiple interruptions.

ii. 2020 activities and financial projection levels directed at improving feeder performance

Feeders are prioritized for maintenance and replacement work based on several criteria including CMI, number of interruptions, interruption cause code and CEMI repeat outage performance. This process results in a work plan targeted at feeders and devices having the greatest impact on reliability indices and customer satisfaction. This process has resulted in consistent and sustained reliability performance.

The 3% feeder list is based solely on number of feeder interruptions and does not take into consideration any of the additional criteria above. While all feeders on the 3% list are patrolled for corrective action, the possibility exists that they could appear on the list more than once due to their relative impact on system reliability indices.

For the 2021 budget levels, please see Attachment E – “2021 Program Budget” Spreadsheet.

c. Regional Reliability Indices – see attached forms.

i. 5-Yr. patterns/trends in each region’s reliability for each index and on any overall basis.

- See Attachment F – “2020 Adjusted Reliability (5 yr. Summary by Region)” Spreadsheet.

ii. The process used to identify and select actions to improve the regional reliability trends.

- Regional reliability trends are tracked to ensure alignment with the system level goals they support. Specific device level improvements are measured and prioritized at a system level to ensure maximum benefit for resources expended.

iii. Discuss any 2021 projected activities and financial projection levels directed at improving regional reliability performance.

- See Attachment E – “2021 Program Budget” Spreadsheet. Regional reliability trends are tracked to ensure alignment with the system level goals they support. Specific device level improvements are measured and prioritized at a system level to ensure maximum benefit for resources expended.
- DEF is currently installing Self-Optimizing Grid Teams as a continuation and upgrade of its Self-Healing Teams. This upgraded system segments the distribution grid to minimize the number of customers affected by a

fault. The SCADA communication between the devices and the DEF Distribution Control Center (DCC), allows automatic remote sectionalization to further reduce the number and duration of the outages. DEF currently has 126 teams installed, which involves 424 circuits and 812,612 customers. In 2021, DEF will continue the install Self-Optimizing Grid Teams across its service territory.

- DEF will continue the Targeted Underground (TUG) Program in 2021 as part of the Grid Investment Plan. The purpose of this program is to target areas that are exposed to tree and debris related outages in the area of exposure by converting heavily vegetated neighborhoods prone to power outages from overhead to underground construction to decrease outages, reduce momentary interruptions, improve major storm restoration time, improve customer satisfaction and reduce costs. DEF continued the Targeted Undergrounding (TUG) Program in 2020 completing a total of 36.7 miles of overhead facilities converted to underground facilities.
- In 2020, DEF conducted analysis and reviewed reliability data that meet certain operational thresholds in order to reduce the number of outages and momentary interruptions. From 2019 to 2020, DEF had a 29% reduction in MAIFIE, and the 5-year trend in MAIFIE is downward.
- DEF will continue the implementation of the Transformer Retrofit Program as part of the Grid Investment Plan. This targets the mitigation of outages caused by CSP (Completely Self-Protected) transformers. CSP transformers with no external protection have been a frequent cause of upstream fuse outages. Adding the external fuse to these transformers would limit the number of customers impacted by transformer or service level issues. This outage mitigation will be accomplished by adding external fused cutouts, replacing bare copper wires with covered copper and adding animal mitigation to these locations. The retrofitting of CSP transformers is being done in lieu of replacement as a cost-effective method of outage reduction for DEF customers in these locations.
- DEF will continue the implementation of the Deteriorated Conductor Program in 2021 as part of the Grid Investment Plan. The Deteriorated Conductor Program focuses on replacing small overhead copper conductor with aluminum conductor. Copper conductor on the grid is older, and by replacing it with new aluminum conductor will improve the overall reliability.
- DEF has begun its Storm Protection Plan in 2021 beginning with the Feeder Hardening Program in distribution. The Feeder Hardening program will enable the feeder backbone to better withstand extreme weather events by upgrading the feeder backbone to meet NESC 250C Extreme wind load standard. This includes strengthening structures, updating basic insulation level to current standards, updating conductor to current standards, relocating difficult to access facilities, replacing oil filled equipment as appropriate and will incorporate the Company's pole inspection and replacement activities.

**FLORIDA PUBLIC SERVICE COMMISSION
ANNUAL DISTRIBUTION SERVICE RELIABILITY REPORT –
ADJUSTED
Top Ten Outage Causes: Form PSC/ECR 102-1(a) (8/06) and Form
PSC/ECR 102-1(b) (8/06)**

PART I

| <u>CAUSES OF OUTAGE EVENTS – ADJUSTED</u> | | | | |
|-------------------------------------------|-------------------------------------------|-----------------------------------------|---------------------------------------|-----------------------------------------------|
| Utility Name: Duke Energy Florida, LLC | | | Year: 2020 | |
| Cause** (a) | Customer Minutes Of Interruption | Number of Outage Events(N) (b) | Average Duration (L-Bar) (c) | Average Restoration Time (CAIDI) (d) |
| 1.) Animals | 5,180,230 | 3,882 | 82.1 | 68.8 |
| 2.) Vegetation | 48,462,663 | 9,291 | 160.3 | 110.9 |
| 3.) Lightning | 3,182,721 | 994 | 157.0 | 97.4 |
| 4.) Other Weather | 32,057,368 | 5,826 | 159.3 | 109.7 |
| 5.) Vehicle | 14,331,534 | 509 | 245.1 | 111.6 |
| 6.) Defective Equipment | 39,395,329 | 11,973 | 146.4 | 82.4 |
| 7.) Unknown | 1,300,066 | 556 | 87.7 | 69.0 |
| | | | | |
| | | | | |
| Subtotal | 143,909,911 | 33,031 | 145.9 | 98.4 |
| All Other Causes *See attached | 22,946,834 | 7,170 | 181.0 | 71.4 |
| | | | | |
| System Totals: | 166,856,745 | 40,201 | 152.1 | 93.5 |

PSC/ECR 103 (8/06)
Incorporated by reference in Rule 25-6.0455, F.A.C.

CAUSES OF OUTAGE EVENTS – ADJUSTED

Utility Name: Duke Energy Florida, LLC

Year: **2020**

| All Other Causes | Customer Minutes Of Interruption | Number of Outage Events(N) (b) | Average Duration (L-Bar) (c) | Average Restoration Time (CAIDI) (d) |
|----------------------------|-------------------------------------------|-----------------------------------------|---------------------------------------|-----------------------------------------------|
| Cause (a) | | | | |
| U/G Primary Cable | 12,995,548 | 1,226 | 297.7 | 102.7 |
| Right-Of-Way | 2,067,759 | 59 | 56.9 | 22.3 |
| Human Error-Public | 2,043,539 | 345 | 154.1 | 77.1 |
| U/G Secondary/Service | 1,778,686 | 3,570 | 185.6 | 232.1 |
| Dig-In | 1,672,160 | 238 | 194.3 | 59.6 |
| Human Error-PGN Contractor | 870,119 | 222 | 90.5 | 54.0 |
| Overload | 494,640 | 122 | 120.3 | 95.6 |
| Foreign Material In Line | 427,380 | 64 | 110.5 | 102.1 |
| Human Error-PGN | 234,192 | 355 | 71.5 | 25.0 |
| Miscellaneous | 205,011 | 621 | 86.4 | 88.0 |
| O/H Secondary Cable | 90,873 | 249 | 143.4 | 151.2 |
| Improper Installation | 36,005 | 35 | 114.9 | 18.4 |
| Construction Equipment | 17,422 | 17 | 122.7 | 68.6 |
| Equipment Misapplication | 8,886 | 24 | 110.0 | 103.3 |
| Vandalism | 4,614 | 23 | 82.2 | 76.9 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| All Other Causes | 22,946,834 | 7,170 | 181.0 | 71.4 |

PART II

| THREE PERCENT FEEDER LIST – ADJUSTED | | | | | | | | | | | | | | |
|----------------------------------------------------|--------------------------|----------------|--------------------|-------------------|-------------------|--------------|--------------|-----|-------------------------|---------------------------------------|--------------|------------------------------|--------------------------------------------|---------------------------------------------------|
| Utility Name: DUKE ENERGY FLORIDA, LLC. Year: 2020 | | | | | | | | | | | | | | |
| PRIMARY CIRCUIT ID. NO. OR NAME | SUBSTATION ORIGIN | LOCATION | CUSTOMERS | | | | | | OUTAGE EVENTS "N" | AVERAGE DURATION "L-Bar" (j) | CAIDI (k) | LISTED LAST YEAR ? (l) | NO. OF YEARS IN THE LAST 5 (m) | CORRECTIVE ACTION COMPLETION DATE (n) |
| | | | RESIDENTIAL (d) | COMMERCIAL (e) | INDUSTRIAL (f) | OTHER (g) | TOTAL (h) | | | | | | | |
| (a) | (b) | (c) | (d) | (e) | (f) | (g) | (h) | (i) | (j) | (k) | (l) | (m) | (n) | |
| K121 | GATEWAY | WALSINGHAM | 98 | 517 | 46 | 26 | 687 | 7 | 178.5 | 51.1 | N | - | 6/30/21 | |
| A34 | REDDICK | OCALA | 1,490 | 259 | - | 61 | 1,810 | 6 | 165.2 | 127.8 | N | - | 12/31/21 | |
| K1825 | NORTHBRIDGE | LAKE WALES | 111 | 93 | - | 14 | 218 | 5 | 119.4 | 72.5 | N | - | 12/31/21 | |
| M445 | BAY RIDGE | APOPKA | 632 | 137 | 1 | 24 | 794 | 5 | 131.2 | 56.2 | N | 1 | 6/30/21 | |
| K1560 | FISHEATING CREEK | HIGHLANDS | 2,387 | 120 | - | 66 | 2,573 | 5 | 111.7 | 61.7 | Y | 1 | 6/30/21 | |
| K1772 | CROOKED LAKE | LAKE WALES | 689 | 142 | 1 | 62 | 894 | 5 | 126.7 | 81.0 | N | 2 | 6/30/21 | |
| W0502 | MAGNOLIA RANCH | SE ORLANDO | 2,377 | 73 | 2 | - | 2,452 | 4 | 130.5 | 58.1 | N | 1 | 6/30/21 | |
| K1066 | LAKE PLACID | HIGHLANDS | 1,012 | 334 | 5 | 98 | 1,449 | 4 | 111.6 | 58.5 | N | - | 6/30/21 | |
| C906 | EAST CLEARWATER | CLEARWATER | 2,115 | 210 | - | 69 | 2,394 | 4 | 171.0 | 78.3 | N | - | 12/31/21 | |
| A36 | REDDICK | OCALA | 901 | 242 | - | 61 | 1,204 | 4 | 185.7 | 111.5 | N | 2 | 6/30/21 | |
| W0202 | MONASTERY | DELAND | 1,285 | 105 | - | 54 | 1,444 | 4 | 158.5 | 65.3 | N | - | 12/31/21 | |
| K63 | DISSTON | WALSINGHAM | 2,544 | 216 | 2 | 52 | 2,814 | 4 | 163.0 | 84.0 | N | - | 12/31/21 | |
| W1105 | DELAND EAST | DELAND | 1,281 | 65 | - | 96 | 1,442 | 4 | 155.3 | 91.6 | N | - | 12/31/21 | |
| A379 | O'BRIEN | MONTICELLO | 553 | 150 | 1 | 64 | 768 | 4 | 213.7 | 259.9 | N | 1 | 6/30/21 | |
| K151 | MAXIMO | ST. PETERSBURG | 2,157 | 125 | - | 91 | 2,373 | 4 | 177.7 | 46.7 | N | - | 12/31/21 | |
| A96 | BROOKSVILLE | INVERNESS | 1,221 | 331 | 9 | 77 | 1,638 | 4 | 136.9 | 111.4 | N | - | 12/31/21 | |
| N195 | JENNINGS | MONTICELLO | 380 | 80 | 1 | 33 | 494 | 4 | 198.7 | 134.8 | N | 1 | 6/30/21 | |
| K866 | WEST LAKE WALES | LAKE WALES | 845 | 191 | 3 | 48 | 1,087 | 4 | 124.1 | 101.2 | N | 1 | 6/30/21 | |
| K141 | MAXIMO | ST. PETERSBURG | 2,059 | 139 | - | 103 | 2,301 | 3 | 139.2 | 64.2 | Y | 2 | 6/30/21 | |
| N36 | CRAWFORDVILLE | MONTICELLO | 1,109 | 111 | - | 28 | 1,248 | 3 | 128.0 | 88.2 | N | 1 | 6/30/21 | |
| M33 | ZELLWOOD | APOPKA | 1,151 | 221 | 9 | 13 | 1,394 | 3 | 156.6 | 75.1 | Y | 2 | 6/30/21 | |
| A45 | GEORGIA PACIFIC | MONTICELLO | 990 | 246 | - | 113 | 1,349 | 3 | 150.5 | 127.6 | N | - | 12/31/21 | |
| W0496 | CENTRAL PARK | SE ORLANDO | 66 | 198 | 6 | 5 | 275 | 3 | 119.1 | 59.5 | N | - | 12/31/21 | |
| A46 | CROSS CITY INDUSTRIAL | MONTICELLO | 333 | 126 | 2 | 28 | 489 | 3 | 146.7 | 79.7 | Y | 1 | 6/30/21 | |
| K861 | SHINGLE CREEK | BUENA VISTA | 1,209 | 162 | 1 | 48 | 1,420 | 3 | 228.4 | 108.2 | N | - | 12/31/21 | |
| A88 | FLORAL CITY | INVERNESS | 449 | 80 | - | 20 | 549 | 3 | 153.5 | 127.5 | Y | 1 | 6/30/21 | |
| N1 | MADISON | MONTICELLO | 978 | 137 | - | 53 | 1,168 | 3 | 170.0 | 127.1 | N | - | 12/31/21 | |
| A90 | TRENTON | MONTICELLO | 921 | 204 | 3 | 68 | 1,196 | 3 | 154.1 | 123.2 | N | 1 | 6/30/21 | |
| W0028 | CASSELBERRY | JAMESTOWN | 1,142 | 126 | 1 | 31 | 1,300 | 3 | 154.8 | 105.6 | N | - | 12/31/21 | |
| C103 | DUNEDIN | CLEARWATER | 2,836 | 199 | - | 111 | 3,146 | 3 | 160.8 | 108.9 | N | - | 12/31/21 | |
| K113 | GATEWAY | WALSINGHAM | 2,065 | 163 | - | 37 | 2,265 | 3 | 233.5 | 59.1 | N | 1 | 6/30/21 | |
| C4322 | ODESSA | SEVEN SPRNGS | 1,975 | 124 | - | - | 2,099 | 3 | 133.5 | 51.8 | N | - | 12/31/21 | |
| K37 | THIRTY SECOND STREET | ST. PETERSBURG | 2,337 | 119 | - | 56 | 2,512 | 3 | 128.7 | 68.8 | N | - | 12/31/21 | |
| C903 | EAST CLEARWATER | CLEARWATER | 481 | 99 | 2 | 32 | 614 | 3 | 132.1 | 87.6 | N | - | 12/31/21 | |
| K232 | LAKE BRYAN | BUENA VISTA | 1,036 | 63 | - | 11 | 1,110 | 3 | 298.0 | 79.4 | N | - | 12/31/21 | |
| A186 | GE ALACHUA | MONTICELLO | 442 | 81 | 3 | 38 | 564 | 3 | 271.7 | 158.4 | Y | 2 | 6/30/21 | |
| M82 | MAITLAND | LONGWOOD | 511 | 80 | 1 | 35 | 627 | 3 | 322.7 | 201.1 | N | - | 12/31/21 | |
| K1104 | REEDY LAKE | BUENA VISTA | 2,448 | 130 | 1 | - | 2,579 | 3 | 143.1 | 73.9 | N | - | 12/31/21 | |
| N332 | ST MARKS WEST | MONTICELLO | 979 | 96 | - | 69 | 1,144 | 3 | 148.2 | 135.8 | N | 1 | 6/30/21 | |
| K1296 | SUN N LAKES | HIGHLANDS | 1,959 | 188 | - | 92 | 2,239 | 3 | 112.8 | 109.9 | N | - | 12/31/21 | |
| N68 | MONTICELLO | MONTICELLO | 217 | 89 | - | 12 | 318 | 3 | 142.7 | 48.9 | N | 1 | 6/30/21 | |
| A195 | ARCHER | MONTICELLO | 366 | 65 | 0 | 32 | 463 | 3 | 208.00 | 188.60 | N | 2 | 6/30/21 | |

LBAR AND CAIDI Includes all devices.

PART III

| SYSTEM RELIABILITY INDICES – ADJUSTED | | | | | |
|---------------------------------------------------|--------------|--------------|-------------|------------|--------------|
| Utility Name: Duke Energy Florida, LLC Year: 2020 | | | | | |
| District or Service Area (a) | SAIDI (b) | CAIDI (c) | SAIFI (d) | MAIFle (e) | CEMI5 (f) |
| North Coastal | 117.2 | 101.9 | 1.15 | 6.4 | 2.32% |
| Inverness | 168.0 | 123.4 | 1.36 | 7.2 | 4.12% |
| Monticello | 224.4 | 117.1 | 1.92 | 6.4 | 5.42% |
| Ocala | 164.6 | 101.3 | 1.63 | 6.7 | 4.81% |
| Seven Springs | 58.1 | 81.0 | 0.72 | 6.1 | 0.03% |
| Zephyrhills | 37.0 | 54.3 | 0.68 | 5.2 | 0.00% |
| South Coastal | 82.6 | 96.1 | 0.86 | 6.0 | 0.37% |
| Clearwater | 75.8 | 94.6 | 0.80 | 6.0 | 0.28% |
| St. Petersburg | 94.5 | 92.9 | 1.02 | 5.5 | 0.46% |
| Walsingham | 75.3 | 102.8 | 0.73 | 6.6 | 0.36% |
| North Central | 85.2 | 101.5 | 0.84 | 3.1 | 0.42% |
| Apopka | 85.3 | 101.7 | 0.84 | 6.8 | 0.34% |
| Deland | 108.8 | 98.3 | 1.11 | 2.7 | 1.27% |
| Jamestown | 64.1 | 91.9 | 0.70 | 0.2 | 0.11% |
| Longwood | 95.3 | 118.0 | 0.81 | 3.8 | 0.21% |
| South Central | 70.4 | 76.7 | 0.92 | 5.7 | 1.17% |
| Buena Vista | 40.9 | 75.2 | 0.54 | 4.2 | 0.00% |
| Clermont | 62.3 | 98.3 | 0.63 | 3.8 | 0.00% |
| SE Orlando | 78.3 | 77.3 | 1.01 | 9.1 | 5.34% |
| Highlands | 96.6 | 70.4 | 1.37 | 7.7 | 1.43% |
| Lake Wales | 64.7 | 69.4 | 0.93 | 1.9 | 0.32% |
| Winter Garden | 100.5 | 84.6 | 1.19 | 8.7 | 1.43% |
| SYSTEM | 87.9 | 93.5 | 0.94 | 5.4 | 1.06% |

FEEDER SPECIFIC DATA – Expanded to include OH/UG details

Provide the following information for each feeder circuit in service during 2020. If any data is not available, explain whether the Company has any plans to begin tracking such data and if not, why.

For (A) thru (Y) – See Attachment G – a CD containing Excel File – “2020 Feeder Specific Data.”

For (Z) – See Attachment G – “2020 Summer Feeder Peaks.”

| | |
|--------------------------------------------------------------------------|-------------------------|
| (A) Feeder ID | <i>See Attachment G</i> |
| (B) Sub-Region in which the feeder is located | <i>See Attachment G</i> |
| (C) Number of overhead lateral lines | <i>See Attachment G</i> |
| (D) Number of overhead lateral miles | <i>See Attachment G</i> |
| (E) Number of Customers served on OH lateral lines | <i>See Attachment G</i> |
| (F) CMI for overhead lateral lines | <i>See Attachment G</i> |
| (G) CI for overhead lateral lines | <i>See Attachment G</i> |
| (H) Number of underground lateral lines | <i>See Attachment G</i> |
| (I) Number of underground lateral miles | <i>See Attachment G</i> |
| (J) Number of customers served on UG lateral lines | <i>See Attachment G</i> |
| (K) CMI for underground lateral lines | <i>See Attachment G</i> |
| (L) CI for underground lateral lines | <i>See Attachment G</i> |
| (M) Number of automatic line sectionalizing devices on the lateral lines | <i>See Attachment G</i> |
| (N) Number of automatic line sectionalizing devices on the feeder | <i>See Attachment G</i> |
| (O) Whether the feeder circuit is looped | <i>See Attachment G</i> |
| (P) Total length of the feeder circuit | <i>See Attachment G</i> |
| (Q) Length of underground portion of the feeder circuit | <i>See Attachment G</i> |
| (R) Number of customers served by underground feeders | <i>See Attachment G</i> |
| (S) CMI for underground feeders | <i>See Attachment G</i> |
| (T) CI for underground feeders | <i>See Attachment G</i> |
| (U) Length of overhead portion of the feeder circuit | <i>See Attachment G</i> |
| (V) Number of customers served by overhead feeders | <i>See Attachment G</i> |
| (W) CMI for overhead feeders | <i>See Attachment G</i> |
| (X) CI for overhead feeders | <i>See Attachment G</i> |
| (Y) Load growth since December 31, 2009 | <i>See Attachment G</i> |
| (Z) Peak load recorded through December 31, 2009 | <i>See Attachment G</i> |
| (AA) Vegetation Management-number of overhead lateral lines-miles | <i>See Attachment G</i> |

DISTRIBUTION SUBSTATION (Rule 25-6.0455, F.A.C.)

a. Describe the five-year patterns/trends in reliability performance of distribution substations.

The five-year patterns/trends in reliability performance of distribution substations is best described by the performance indices. These indices are used for calculating system reliability:

- SAIDI – System Average Interruption Duration Index (minutes/customer). SAIDI reflects the average number of minutes a customer was without power system-wide. It is determined by dividing the sum of customer-minutes of interruption by the average number of customers served during a period.
- CAIDI – Customer Average Interruption Duration Index (minutes/customer). CAIDI is the average customer-minutes of interruption per customer interruption. It approximates the average length of time required to complete service restoration. It is determined by dividing the sum of all customer-minutes of interruption durations by the number of customer interruptions during a period. CAIDI measures how long it takes DEF to restore service after an interruption.
- SAIFI – System Average Interruption Frequency Index. SAIFI is the average number of interruptions per customer per a certain period. It is determined by dividing the total number of customer interruptions by the average number of customers served during a period.
- OHMY – Outages per Hundred Miles per Year. OHMY measures the number of forced transmission line events, momentary AND sustained, that are incurred per hundred circuit miles per year. This measure is often grouped by voltage class.

The following charts will show the trending for these Reliability Indices:

| Section | Grid SAIDI | SECI SAIDI | Retail SAIDI |
|----------------|-------------------|-------------------|---------------------|
| North | 1.88 | 7.01 | 2.0 |
| Central | 1.31 | 0.08 | 1.4 |
| Coastal | 3.01 | 0.59 | 3.1 |
| Florida | 6.1 | 7.68 | 6.6 |

Table 1: 2020 DEF SAIDI Reliability Indices

In 2020, Grid SAIDI decreased from 2019 and SECI (Seminole Electric Cooperatives, Inc.). SAIDI also decreased from 2019. SECI represents its electric cooperative members in Florida.




Fig.1: DEF SAIDI Trending (2016 - 2020)

| Grid KPIs | 2016 | 2017 | 2018 | 2019 | 2020 |
|-----------------------|--------|--------|--------|--------|--------|
| Customers (Thousands) | 445.65 | 533.33 | 440.34 | 429.79 | 432.19 |
| CMI (Millions) | 18.9 | 21.7 | 20.85 | 25.04 | 17.83 |
| SAIDI | 8.18 | 9.3 | 6.5 | 8.3 | 6.1 |
| CAIDI | 39.68 | 40.69 | 43.33 | 58.26 | 41.39 |
| SAIFI | 0.21 | 0.22 | 0.19 | 0.14 | 0.15 |
| FSO | N/A | N/A | N/A | N/A | N/A |
| FOHMY | 9.07 | 9.75 | 9.92 | 8.12 | 8.74 |

Table 2: DEF Statistics (2016 - 2020)




Fig.2: DEF Key Performance Indicators Trending (2016 - 2020)




Fig.3: DEF Customers Minute Interruption Trending (2016 - 2020)

DEF CMI Per Month (2016 - 2020)




Fig.4: DEF CMI per month (2016 - 2020)

a. Describe Company efforts to track the reliability of distribution substations.

DEF’s in-house database, Transmission Outage Management System (TOMS), is used to keep track and record all the events that occur every day. It maintains all the indices mentioned above.

b. Describe the process used by your Company to identify and select the actions to promote substation reliability.

To identify and promote substation reliability, DEF uses different methods, such as monthly substation inspections, predictive and preventive maintenance, infra-red analysis and numerous diagnostics tests. Once a problem is identified, DEF’s work management tool is used to track the efforts to correct it.

c. Provide the number of distribution substations inspected during normal operations (non-storm related) for 2007 through 2020.

DEF has inspected each of its current 513 substations.

SUPPLEMENTAL DISTRIBUTION INFORMATION

The next six pages contain the following information:

CMI / CI by Operation Center for 2020 (Unadjusted/Adjusted) 31

CEMI5 by Operation Center for 2020 (Unadjusted) 32

CEMI5 by Operation Center for 2020 (Adjusted) 33

MAIFIE by Operation Center for 2020 (Unadjusted) 34

MAIFIE by Operation Center for 2020 (Adjusted) 35

SAIDI by Operation Center for 2020 (Unadjusted/Adjusted) 36



2020

| | Unadjusted Data | | Adjusted Data | |
|----------------------|--------------------|------------------|--------------------|------------------|
| | CMI | CI | CMI | CI |
| NORTH CENTRAL | 45,584,898 | 493,212 | 36,630,654 | 360,827 |
| APOPKA | 10,056,057 | 106,056 | 9,044,285 | 88,903 |
| DELAND | 14,171,930 | 127,568 | 9,500,363 | 96,641 |
| JAMESTOWN | 10,853,264 | 156,451 | 9,175,408 | 99,796 |
| LONGWOOD | 10,503,647 | 103,137 | 8,910,598 | 75,487 |
| NORTH COASTAL | 68,348,210 | 690,409 | 52,174,280 | 512,093 |
| INVERNESS | 17,175,598 | 139,245 | 13,268,035 | 107,506 |
| MONTICELLO | 13,989,823 | 135,260 | 12,765,020 | 108,998 |
| OCALA | 15,336,855 | 159,228 | 13,526,398 | 133,548 |
| SEVEN SPRINGS | 19,981,989 | 223,917 | 11,590,163 | 143,173 |
| ZEPHYRHILLS | 1,863,945 | 32,759 | 1,024,664 | 18,868 |
| SOUTH CENTRAL | 44,024,959 | 659,807 | 37,493,015 | 489,051 |
| BUENA VISTA | 5,930,916 | 82,064 | 5,340,294 | 70,968 |
| CLERMONT | 2,886,008 | 40,695 | 2,429,259 | 24,720 |
| HIGHLANDS | 9,004,835 | 123,852 | 7,627,718 | 98,641 |
| LAKE WALES | 6,524,094 | 102,546 | 5,557,430 | 78,912 |
| SE ORLANDO | 9,559,059 | 164,247 | 7,885,107 | 113,566 |
| WINTER GARDEN | 10,120,047 | 146,403 | 8,653,207 | 102,244 |
| SOUTH COASTAL | 78,929,634 | 779,216 | 40,558,796 | 422,014 |
| CLEARWATER | 22,606,989 | 234,461 | 11,346,732 | 119,882 |
| ST. PETERSBURG | 28,087,406 | 306,840 | 17,333,464 | 186,553 |
| WALSINGHAM | 28,235,239 | 237,915 | 11,878,600 | 115,579 |
| Grand Total | 236,887,701 | 2,622,644 | 166,856,745 | 1,783,985 |

CEMI5 Unadjusted Report - 2020

| INTERRUPTIONS: | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 + | Cust >5 | CEMI >5 |
|-----------------------|----------------|----------------|----------------|---------------|---------------|---------------|--------------|--------------|--------------|--------------|-------------------|-------------------|
| NORTH CENTRAL | | | | | | | | | | | | |
| Apopka | 31,419 | 13,986 | 4,608 | 2,544 | 713 | 355 | 130 | 47 | 28 | 15 | 575 | 0.54% |
| Deland | 22,415 | 13,146 | 7,282 | 2,952 | 1,986 | 887 | 335 | 112 | 46 | 168 | 1548 | 1.77% |
| Jamestown | 36,884 | 25,410 | 9,038 | 1,742 | 333 | 57 | 70 | 13 | 14 | 2 | 156 | 0.11% |
| Longwood | 28,673 | 12,594 | 6,386 | 2,854 | 375 | 149 | 71 | 1 | 5 | | 226 | 0.24% |
| NORTH CENTRAL | 119,391 | 65,136 | 27,314 | 10,092 | 3,407 | 1,448 | 606 | 173 | 93 | 185 | 2,505 | 0.58% |
| NORTH COASTAL | | | | | | | | | | | | |
| Inverness | 21,566 | 12,447 | 5,076 | 3,676 | 2,810 | 1,075 | 1,101 | 528 | 533 | 824 | 4,061 | 5.14% |
| Monticello | 15,321 | 9,032 | 6,731 | 4,517 | 2,494 | 1,835 | 862 | 363 | 370 | 216 | 3,646 | 6.41% |
| Ocala | 26,658 | 12,865 | 6,069 | 4,281 | 1,568 | 773 | 630 | 360 | 768 | 1,851 | 4,382 | 5.33% |
| Seven Springs | 78,518 | 34,667 | 7,354 | 1,495 | 247 | 101 | | 16 | | | 117 | 0.06% |
| Zephyrhills | 17,195 | 5,192 | 799 | 323 | 39 | | | | | | 0 | 0.00% |
| NORTH COASTAL | 159,258 | 74,203 | 26,029 | 14,292 | 7,158 | 3,784 | 2,593 | 1,267 | 1,671 | 2,891 | 12,206 | 2.74% |
| SOUTH CENTRAL | | | | | | | | | | | | |
| Buena Vista | 30,127 | 10,986 | 4,421 | 826 | 154 | | | | | | 0 | 0.00% |
| Clermont | 13,910 | 6,435 | 2,474 | 506 | 196 | 58 | 1 | | | | 59 | 0.15% |
| Highlands | 16,306 | 9,570 | 3,570 | 1,354 | 1,089 | 487 | 341 | 1,013 | 960 | 265 | 3,066 | 5.33% |
| Lake Wales | 40,487 | 15,320 | 6,323 | 3,170 | 1,982 | 1,651 | 729 | 466 | 78 | 76 | 3,000 | 2.66% |
| SE Orlando | 27,561 | 12,610 | 10,585 | 3,730 | 1,586 | 295 | 73 | 33 | 16 | 24 | 441 | 0.45% |
| Winter Garden | 22,141 | 17,373 | 7,409 | 4,643 | 2,836 | 1,115 | 505 | 138 | 37 | | 1795 | 2.08% |
| SOUTH CENTRAL | 150,532 | 72,294 | 34,782 | 14,229 | 7,843 | 3,606 | 1,649 | 1,650 | 1,091 | 365 | 8,361 | 1.57% |
| SOUTH COASTAL | | | | | | | | | | | | |
| Clearwater | 45,450 | 27,365 | 9,483 | 5,328 | 2,533 | 759 | 84 | 97 | 28 | 18 | 986 | 0.66% |
| St. Petersburg | 61,734 | 34,283 | 17,753 | 7,285 | 3,252 | 3,117 | 891 | 247 | 203 | 22 | 4,480 | 2.44% |
| Walsingham | 57,236 | 29,404 | 13,151 | 5,807 | 1,850 | 369 | 139 | 210 | 60 | 96 | 874 | 0.55% |
| SOUTH COASTAL | 164,420 | 91,052 | 40,387 | 18,420 | 7,635 | 4,245 | 1,114 | 554 | 291 | 136 | 6,340 | 1.29% |
| System | 593,601 | 302,685 | 128,512 | 57,033 | 26,043 | 13,083 | 5,962 | 3,644 | 3,146 | 3,577 | 29,412 | 1.55% |

CEMIS Adjusted Report - 2020

| INTERRUPTIONS: | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 + | Cust >5 | CEMI >5 |
|-----------------------|----------------|----------------|---------------|---------------|---------------|--------------|--------------|--------------|--------------|--------------|-------------------|-------------------|
| NORTH CENTRAL | | | | | | | | | | | | |
| Apopka | 31,074 | 12,929 | 4,684 | 2,289 | 884 | 186 | 81 | 47 | 28 | 15 | 357 | 0.34% |
| Deland | 22,362 | 13,413 | 5,564 | 2,839 | 1,773 | 611 | 248 | 111 | 100 | 40 | 1,110 | 1.27% |
| Jamestown | 30,799 | 18,586 | 6,921 | 1,498 | 331 | 57 | 70 | 13 | 14 | 2 | 156 | 0.11% |
| Longwood | 28,687 | 13,098 | 3,683 | 1,235 | 285 | 140 | 49 | 1 | 5 | | 195 | 0.21% |
| NORTH CENTRAL | 112,922 | 58,026 | 20,852 | 7,861 | 3,273 | 994 | 448 | 172 | 147 | 57 | 1,818 | 0.42% |
| NORTH COASTAL | | | | | | | | | | | | |
| Inverness | 18,957 | 10,824 | 4,821 | 4,383 | 1,535 | 1,147 | 740 | 557 | 581 | 227 | 3,252 | 4.12% |
| Monticello | 15,199 | 8,999 | 6,973 | 4,365 | 2,484 | 1,432 | 785 | 416 | 260 | 192 | 3,085 | 5.42% |
| Ocala | 24,786 | 12,802 | 5,844 | 4,085 | 1,763 | 628 | 535 | 859 | 303 | 1,630 | 3,955 | 4.81% |
| Seven Springs | 66,847 | 25,168 | 5,557 | 1,190 | 241 | 38 | 16 | | | | 54 | 0.03% |
| Zephyrhills | 14,145 | 1,452 | 464 | 22 | | | | | | | - | 0.00% |
| NORTH COASTAL | 139,934 | 59,245 | 23,659 | 14,045 | 6,023 | 3,245 | 2,076 | 1,832 | 1,144 | 2,049 | 10,346 | 2.32% |
| SOUTH CENTRAL | | | | | | | | | | | | |
| Buena Vista | 29,366 | 10,992 | 4,650 | 645 | 77 | | | | | | - | 0.00% |
| Clermont | 13,639 | 3,084 | 867 | 186 | 12 | | 1 | | | | 1 | 0.00% |
| Highlands | 15,968 | 9,285 | 3,568 | 1,173 | 1,083 | 1,032 | 1,198 | 719 | 100 | 24 | 3,073 | 5.34% |
| Lake Wales | 33,709 | 13,618 | 5,938 | 3,193 | 1,573 | 642 | 498 | 410 | 10 | 52 | 1,612 | 1.43% |
| SE Orlando | 25,665 | 13,706 | 8,519 | 2,948 | 606 | 177 | 84 | 14 | 20 | 16 | 311 | 0.32% |
| Winter Garden | 28,344 | 13,282 | 5,633 | 2,134 | 2,276 | 593 | 483 | 120 | 37 | | 1,233 | 1.43% |
| SOUTH CENTRAL | 146,691 | 63,967 | 29,175 | 10,279 | 5,627 | 2,444 | 2,264 | 1,263 | 167 | 92 | 6,230 | 1.17% |
| SOUTH COASTAL | | | | | | | | | | | | |
| Clearwater | 44,545 | 17,407 | 6,162 | 2,312 | 506 | 261 | 101 | 33 | 14 | 4 | 413 | 0.28% |
| St. Petersburg | 54,959 | 24,963 | 12,611 | 5,957 | 1,310 | 552 | 135 | 118 | 35 | 1 | 841 | 0.46% |
| Walsingham | 48,745 | 17,137 | 5,548 | 1,578 | 229 | 242 | 209 | 30 | 21 | 74 | 576 | 0.36% |
| SOUTH COASTAL | 148,249 | 59,507 | 24,321 | 9,847 | 2,045 | 1,055 | 445 | 181 | 70 | 79 | 1,830 | 0.37% |
| System | 547,796 | 240,745 | 98,007 | 42,032 | 16,968 | 7,738 | 5,233 | 3,448 | 1,528 | 2,277 | 20,224 | 1.06% |

MAIFle - Unadjusted (01/01/2020 - 12/31/2020)

| | <u>Customers</u> | <u># momentary</u> | | |
|----------------------|-------------------------|---------------------|--------------------------|-------------------|
| | <u>Served</u> | <u>events</u> | <u>CME</u> | <u>MAIFle</u> |
| NORTH CENTRAL | | | | |
| Apopka | 106,060 | 583 | 727,141 | 6.9 |
| Deland | 87,383 | 176 | 250,393 | 2.9 |
| Jamestown | 143,090 | 32 | 33,184 | 0.2 |
| Longwood | 93,474 | 274 | 351,449 | 3.8 |
| NORTH CENTRAL | 430,007 | 1,065 | 1,362,167 | 3.2 |
| NORTH COASTAL | | | | |
| Inverness | 78,986 | 438 | 578,622 | 7.3 |
| Monticello | 56,898 | 414 | 366,139 | 6.4 |
| Ocala | 82,189 | 439 | 560,706 | 6.8 |
| Seven Springs | 199,724 | 613 | 1,271,762 | 6.4 |
| Zephyrhills | 27,702 | 64 | 154,913 | 5.6 |
| NORTH COASTAL | 445,499 | 1,968 | 2,932,142 | 6.6 |
| SOUTH CENTRAL | | | | |
| Buena Vista | 139,580 | 512 | 583,483 | 4.2 |
| Clermont | 39,009 | 109 | 147,394 | 3.8 |
| Highlands | 57,541 | 409 | 525,897 | 9.1 |
| Lake Wales | 112,855 | 593 | 871,426 | 7.7 |
| SE Orlando | 97,479 | 144 | 182,092 | 1.9 |
| Winter Garden | 86,140 | 483 | 746,348 | 8.7 |
| SOUTH CENTRAL | 532,604 | 2,250 | 3,056,640 | 5.7 |
| SOUTH COASTAL | | | | |
| Clearwater | 149,668 | 482 | 982,151 | 6.6 |
| St. Petersburg | 183,527 | 554 | 1,056,835 | 5.8 |
| Walsingham | 157,817 | 640 | 1,086,684 | 6.9 |
| SOUTH COASTAL | 491,012 | 1,676 | 3,125,670 | 6.4 |
| <u>System</u> | <u>1,899,122</u> | <u>6,959</u> | <u>10,476,619</u> | <u>5.5</u> |

MAIFle - Adjusted (01/01/2020 - 12/31/2020)

| | <u>Customers</u> | <u># momentary</u> | | |
|----------------------|-------------------------|---------------------|--------------------------|-------------------|
| | <u>Served</u> | <u>events</u> | <u>CME</u> | <u>MAIFle</u> |
| NORTH CENTRAL | | | | |
| Apopka | 106,060 | 582 | 725,392 | 6.8 |
| Deland | 87,383 | 168 | 237,392 | 2.7 |
| Jamestown | 143,090 | 32 | 33,184 | 0.2 |
| Longwood | 93,474 | 274 | 351,449 | 3.8 |
| NORTH CENTRAL | 430,007 | 1,056 | 1,347,417 | 3.1 |
| NORTH COASTAL | | | | |
| Inverness | 78,986 | 430 | 566,513 | 7.2 |
| Monticello | 56,898 | 414 | 366,139 | 6.4 |
| Ocala | 82,189 | 431 | 548,699 | 6.7 |
| Seven Springs | 199,724 | 581 | 1,208,340 | 6.1 |
| Zephyrhills | 27,702 | 60 | 144,633 | 5.2 |
| NORTH COASTAL | 445,499 | 1,916 | 2,834,324 | 6.4 |
| SOUTH CENTRAL | | | | |
| Buena Vista | 139,580 | 512 | 583,483 | 4.2 |
| Clermont | 39,009 | 109 | 147,394 | 3.8 |
| Highlands | 57,541 | 409 | 525,897 | 9.1 |
| Lake Wales | 112,855 | 593 | 871,426 | 7.7 |
| SE Orlando | 97,479 | 144 | 182,092 | 1.9 |
| Winter Garden | 86,140 | 483 | 746,348 | 8.7 |
| SOUTH CENTRAL | 532,604 | 2,250 | 3,056,640 | 5.7 |
| SOUTH COASTAL | | | | |
| Clearwater | 149,668 | 443 | 897,637 | 6.0 |
| St. Petersburg | 183,527 | 528 | 1,005,648 | 5.5 |
| Walsingham | 157,817 | 620 | 1,040,671 | 6.6 |
| SOUTH COASTAL | 491,012 | 1,591 | 2,943,956 | 6.0 |
| <u>System</u> | <u>1,899,122</u> | <u>6,813</u> | <u>10,182,337</u> | <u>5.4</u> |



| SYSTEM RELIABILITY INDICES – ABSENT ADJUSTMENTS | | |
|-------------------------------------------------|------------------|--------------|
| Utility Name: Duke Energy Florida | | |
| 2020 | | |
| Region | Operation Center | SAIDI |
| NORTH COASTAL | | 153.5 |
| | Inverness | 217.5 |
| | Monticello | 245.9 |
| | Ocala | 186.6 |
| | Seven Springs | 100.1 |
| | Zephyrhills | 67.3 |
| SOUTH COASTAL | | 160.8 |
| | Clearwater | 151.0 |
| | St. Petersburg | 153.1 |
| | Walsingham | 178.9 |
| NORTH CENTRAL | | 106.0 |
| | Apopka | 94.9 |
| | Deland | 162.2 |
| | Jamestown | 75.9 |
| | Longwood | 112.4 |
| SOUTH CENTRAL | | 82.7 |
| | Buena Vista | 45.5 |
| | Clermont | 74.1 |
| | Highlands | 113.4 |
| | Lake Wales | 78.5 |
| | SE Orlando | 92.4 |
| | Winter Garden | 117.5 |
| SYSTEM | | 124.8 |

Note: SAIDI indices are the contribution to the system level.



| SYSTEM RELIABILITY INDICES – ADJUSTED | | |
|---------------------------------------|------------------|--------------|
| Utility Name: Duke Energy Florida | | |
| 2020 | | |
| Region | Operation Center | SAIDI |
| NORTH COASTAL | | 117.2 |
| | Inverness | 168.0 |
| | Monticello | 224.4 |
| | Ocala | 164.6 |
| | Seven Springs | 58.1 |
| | Zephyrhills | 37.0 |
| SOUTH COASTAL | | 82.6 |
| | Clearwater | 75.8 |
| | St. Petersburg | 94.5 |
| | Walsingham | 75.3 |
| NORTH CENTRAL | | 85.2 |
| | Apopka | 85.3 |
| | Deland | 108.8 |
| | Jamestown | 64.1 |
| | Longwood | 95.3 |
| SOUTH CENTRAL | | 70.4 |
| | Buena Vista | 40.9 |
| | Clermont | 62.3 |
| | Highlands | 96.6 |
| | Lake Wales | 64.7 |
| | SE Orlando | 78.3 |
| | Winter Garden | 100.5 |
| SYSTEM | | 87.9 |

Note: SAIDI indices are the contribution to the system level.

RELIABILITY-RELATED CUSTOMER COMPLAINTS

Please see Attachment H – “2020 Reliability Report” for DEF’s spreadsheet comparing DEF vs. PSC 2020 reliability-related complaints.

a. Describe the five-year patterns/trends in reliability related customer complaints.

DEF receives its customer complaints from the FPSC via a variety of methods (Formal Complaints, Courtesy Calls and Internet Transfers). The 5-year trend is shown below with DEF reliability-related complaint data:

| Complaint Category | FPSC Formal (15 Day/Logged) Complaints | | | | |
|----------------------|----------------------------------------|-----------|------------|-----------|-----------|
| | Year End Total | | | | |
| | 2016 | 2017 | 2018 | 2019 | 2020 |
| Outages - Momentary | 8 | 6 | 8 | 7 | 15 |
| Outages - Frequent | 39 | 35 | 77 | 47 | 35 |
| Outages – Extended | 2 | 23 | 10 | 13 | 7 |
| Voltage | 5 | 2 | 3 | 7 | 10 |
| Equipment/Facilities | 4 | 10 | 16 | 13 | 12 |
| Tree Trimming | 6 | 6 | 6 | 8 | 7 |
| Safety | 0 | 0 | 0 | 0 | 0 |
| Total | 64 | 82 | 120 | 95 | 86 |

b. Describe Company efforts to correlate reliability related complaints with reliability indices for applicable feeder, lateral and subregion.

Reliability complaints are typically driven by localized delivery system performance. The most effective remedy is surgical corrective action based on patrol/survey of a discrete segment in conjunction with analysis of outage cause(s) and duration. Corrective action scope is typically increased when appropriate to ensure maximum impact on established reliability indices such as SAIDI, MAIFIE, CEMI4, and CELID3.

c. Describe the process used by your company to identify and select systematic actions to improve reliability due to customer complaints (if no such program exists explain why).

Systematic corrective actions are prioritized based on expected improvement to established reliability indices such as SAIDI, MAIFIE, CEMI4, and CELID3. Reliability complaints are typically driven by localized delivery system performance. The most effective remedy is surgical corrective action based on patrol/survey of a discrete segment in conjunction with analysis of outage cause(s) and duration. Corrective actions are compared to the reliability work plan to ensure no unnecessary duplication of effort.

WOOD POLE INSPECTION PROGRAM

a. Provide a detailed description of the Company's wood pole inspection program.

DEF's wood pole inspection program's philosophy is to determine the condition of the wood pole plant and provide remediation for any wood poles that are showing signs of decay or fall below the minimum strength requirements outlined by NESC standards.

DEF is utilizing the expertise of Osmose Utilities Services, Inc. for distribution and Quanta Utility Engineering Services (QUES) for transmission to perform the inspections on an eight-year cycle. Inspections include visual inspection, sound and boring and full excavation down to 18 inches below ground line to determine the condition of all poles except for CCA poles less than 16 years of age and poles that cannot be excavated due to obstructions. For CCA poles less than 16 years of age, inspections include visual and sound as well as selective boring to determine the pole condition. In addition, inspections are providing remediation of decayed poles through external and internal treatments. In distribution, if the pole is below NESC standards and has the minimum remaining wood above ground line, reinforcement of the pole with steel C-trusses is often performed to bring the pole back to original strength.

For additional information, please see Attachment K – "Transmission – Wood Pole Inspection - TECP-MIM-TRM-00118-Rev.001."

b. 2020 accomplishments

Distribution

DEF inspected 86,357 wood distribution poles during 2020. This completes 6 years and 8 months of the second 8-year inspection cycle. In addition to the inspections, GPS coordinates and physical attributes were updated and/or verified and inspection results were collected in a central database on all poles inspected.

The distribution wood pole inspection program is planned to complete approximately 1/8 of the distribution pole fleet per year. In cycle 1, the route of the inspections was performed to inspect the coastal poles first, moving inland as the program proceeded. Cycle 2 is being conducted in a manner that provides a more even distribution of work to DEF's engineering and line resources.

Transmission

In 2020, DEF's Transmission Ground Patrols / Sound & Bore inspected 3,371 wood pole structures. This represents approximately 18.6% of the wood pole structures on the DEF Transmission system. For the summary report of the inspection data – See Attachment L – "DEF's 2020 Annual Wood Pole Inspection Report" filed with the FPSC on March 1, 2021. For a full report of inspection data – See Attachment M – a CD containing Excel file - "2020 Florida Pole Inspection Data."

c. Projected accomplishments for 2021

Distribution

DEF's goal for 2021 is to continue cycle two inspections of the system. DEF will continue to utilize the same inspection procedures in 2021 that were used in the past. Projected cost for the 2021 distribution pole inspection program is \$6.3m.

Transmission

Plans for 2021 are to perform visual and sounding inspections on 1/4 of the wood pole system and sound and bore inspections on at least 1/8 of the wood pole system. DEF Transmission plans to inspect at least 1/6 of our non-wood system. All three inspections wood - visuals and sound & bore, and non-wood visual inspections, are performed by a contractor. The entire transmission system will also be aerially patrolled twice via helicopter in 2021.

d. Wood pole inspection reports.

Each wood pole inspection report contains the following:

- A description of the methods used for structural analysis and pole inspection,
- A description of the selection criteria that was used to determine which poles would be inspected, and
- A summary report of the inspection data.

Distribution

Please see Attachment L – “DEF’s 2020 Annual Wood Pole Inspection Report” filed with the FPSC on March 1, 2021.

For a description of the methods used for structural analysis and pole inspection – please refer to Attachment K – “Wood Pole Inspection Plan,” pages 6 - 8.

For the full report of the inspection data - See Attachment M – a CD containing Excel file – “2020 DEF Distribution Pole Inspection Data.”

Transmission

Please see Attachment L – “DEF’s 2020 Annual Wood Pole Inspection Report” filed with the FPSC on March 1, 2021.

For a description of the methods used for structural analysis and pole inspection – please refer to Attachment K – “Wood Pole Inspection Plan.”

For the full report of the inspection data – See Attachment M – a CD containing Excel file – “2020 Florida Pole Inspection Data.”

CCA Pole Sampling Report

Pursuant to Order No. PSC-08-0615-PAA-EI issued September 23, 2008 in Docket No. 080219-EI, the FPSC approved modification to the sounding and boring excavation requirements of Order No. 06-0144-PAA-EI with regard to CCA wood poles less than 16 years old. On Pages 3 and 4 of Order No. PSC-08-0615-PAA-EI, it states,

“ORDERED that, consistent with the deviation granted to Gulf Power Company in Order No. PSC-07-0078-PAA-EU, Progress Energy Florida, Inc., Florida Power & Light Company, and Tampa Electric Company shall be required to sound and selectively bore all CCA poles under the age of 16 years, but shall not be required to perform full excavation on these poles. It is further

ORDERED that Progress Energy Florida, Inc., Florida Power & Light Company, and Tampa Electric Company shall also be required to perform full excavation sampling to validate their inspection method. It is further

ORDERED that the results of the utilities’ sampling shall be filed in their annual distribution reliability reports.”

2020 CCA Pole Sampling Results

Please see Attachment L – “DEF’s 2020 Annual Wood Pole Inspection Report” filed with the FPSC on March 1, 2021. The “CCA Sampling Results for 2020” is included in DEF’s Wood Pole Inspection Report as “Attachment B.”

Reliability Report Attachment Index

| | |
|------------------------------------------------------------------------|---------------------|
| DEF Transmission Outages 2020 – Major Events Excluded | Attachment A |
| DEF Transmission Outages 2020 – Major Events Only | Attachment B |
| 2020 Extreme Weather Exclusions (XVIII)..... | Attachment C and C1 |
| 2020 Actual Adjusted Data Breakdown..... | Attachment C2 |
| 2020 Adjusted Reliability (5 yr. Trend by Cause Code)..... | Attachment D |
| 2021 Program Budget..... | Attachment E |
| 2020 Adjusted Reliability (5 yr. Summary by Region) | Attachment F |
| 2020 Summer Feeder Peaks | Attachment G |
| 2020 Feeder Specific Data | Attachment G (CD) |
| 2020 Reliability Report | Attachment H |
| DEF's Storm Hardening 2019-2021 Projects..... | Attachment I |
| DEF's 2019-2021 Storm Hardening Plan | Attachment J |
| Transmission – Wood Pole Inspection - TECP-MIM-TRM-00118-Rev.001 | Attachment K |
| Wood Pole Inspection Plan | Attachment K |
| DEF's 2020 Annual Wood Pole Inspection Report | Attachment L |
| 2020 DEF Distribution Pole Inspection Data..... | Attachment M (CD) |
| 2020 Florida Pole Inspection Data | Attachment M (CD) |

Attachment A

| OUTAGE_ID | LOCATION | OUTAGE_START_TIME | INITIATINGCAUSE | SUSTAINEDCAUSE | RETAIL_CMI | GRID_CMI |
|-----------|-------------------------------------------------------------------------|---------------------|-----------------------------------------------------------------|------------------------------------------------------------------|------------|-----------|
| 74,712 | North Bartow (NBTW) - West Lake Wales (WLWL) 69kV Line | 01/01/2020 18:13:27 | Line Equipment - Crossarm | Line Equipment - Crossarm | 0 | 33 |
| 74,744 | Fort Meade (FTMD) - Homeland (HMLD) 69kV Line | 01/07/2020 21:28:21 | Line Equipment - Splice/Joint (Line Conductor) | Line Equipment - Conductor (Line) | 328 | 399 |
| 74,831 | LOCKHART | 01/01/2020 09 07:38 | Animal - Squirrel | Breaker Equipment - Failed to Reclose | 104,509 | 104,509 |
| 74,877 | Horse Creek (HORS) - Horse Creek 2 (HOR2) 69kV Line | 01/24/2020 00 56:23 | (Non-Duke) | Other - No Reclose by Design or Policy | 0 | 226 |
| 74,986 | Holopaw (HOLO) - West Lake Wales (WLWL) 230kV Line | 02/07/2020 05 00:12 | Line Equipment - Insulator (Line, Porcelain) | Line Equipment - Insulator (Line, Porcelain) | 6,824 | 6,824 |
| 75,166 | Crystal River East (CREA) - Crystal River South (CRSO) 115kV Line | 02/26/2020 18:31:15 | Line Equipment - Structure (Wood) | Line Equipment - Structure (Wood) | 129,150 | 219,150 |
| 75,358 | HEMPLE | 03/16/2020 17:27:31 | Human Error - Design Problem (Power Delivery) | Human Error - Design Problem (Power Delivery) | 486,628 | 486,628 |
| 75,684 | NORTHBRIDGE | 04/07/2020 19:25:43 | Transformer Equipment - Physical Connection (Clamp, etc.) | Transformer Equipment - Physical Connection (Clamp, etc.) | 39,839 | 39,839 |
| 75,078 | Occidental Swift Creek #1 (OS1) - Occidental Metering (OXYM) 115kV Line | 02/20/2020 23:32:31 | Animal - Bird Nest | Animal - Bird Nest | 28,026 | 28,066 |
| 75,096 | Lake Weir (LWER) - (CEC) Lynn (LYNN) 69kV Line | 02/22/2020 04 08:48 | Line Equipment - Conductor (Line) | Line Equipment - Conductor (Line) | 0 | 2,023,053 |
| 74,807 | WALSINGHAM* | 01/11/2020 07:45:00 | Animal - Squirrel | Animal - Squirrel | 312,288 | 312,288 |
| 74,812 | Ulmerton (ULMR) BK4 | 01/07/2020 10 05:09 | Relay and Control Systems - Relay Failure/Misoperation | Relay and Control Systems - Relay Failure/Misoperation | 1,970,956 | 1,970,956 |
| 74,829 | UCF | 01/16/2020 02:28:25 | Animal - Raccoon | Animal - Raccoon | 209,243 | 209,243 |
| 74,844 | BONNET CREEK | 01/17/2020 07 56:16 | Unknown - Unknown, after Patrol | Breaker Equipment - Failed to Reclose | 12,456 | 12,456 |
| 74,911 | CYPRESSWOOD | 01/29/2020 17:16:26 | Unknown - Unknown, after Patrol | Breaker Equipment - Physical Connection/Hardware (Breaker) | 41,125 | 41,125 |
| 74,916 | GE Pinellas (GEPN) - Largo (LRGO) 69kV Line | 02/03/2020 16:15:56 | CCVT, etc.) | CCPD, CCVT, etc.) | 389,488 | 389,488 |
| 74,757 | NORTHEAST* | 01/07/2020 10:19:00 | Relay and Control Systems - Relay Failure/Misoperation | Relay and Control Systems - Relay Failure/Misoperation | 1,311 | 1,311 |
| 74,932 | CURRY FORD | 01/26/2020 18:26:57 | Unknown - Unknown | Breaker Equipment - Failed to Reclose | 37,356 | 37,356 |
| 75,150 | LURAVILLE* | 02/24/2020 05 02:48 | O&M (Planned or Scheduled) - Operating Switching | O&M (Planned or Scheduled) - Operating Switching | 1,370 | 1,370 |
| 75,292 | SPRING LAKE | 03/09/2020 17:10:57 | Switch Equipment/Malfunction - Disconnect | Switch Equipment/Malfunction - Disconnect | 327,860 | 327,860 |
| 74,793 | Havana (HVNA) - (TEC) Hinson (HIN8) 69kV Line | 01/11/2020 10:30:36 | Weather/Environment - Rain (Includes Fog,Mist,Drizzle) | Vegetation - Tree Falling from Outside ROW | 0 | 285,998 |
| 75,618 | DELAND* | 04/01/2020 00 02:32 | Breaker Equipment - Operating Mechanism | Breaker Equipment - Operating Mechanism | 1,209 | 1,209 |
| 75,144 | ORANGE CITY* | 01/04/2020 11:31:36 | Weather/Environment - Tornado/Twister | Human Error - Incorrect Relay Setting | 14,465 | 14,465 |
| 75,296 | FISHEATING CREEK | 02/12/2020 12:35:37 | Transformer Equipment - Tap Changer (Manual) | Transformer Equipment - Tap Changer (Manual) | 53,506 | 53,506 |
| 75,318 | BROOKSVILLE | 02/29/2020 10:17:38 | Breaker Equipment - Operating Mechanism | Breaker Equipment - Operating Mechanism | 153,524 | 153,524 |
| 75,622 | BROOKSVILLE | 04/04/2020 08 01:00 | Breaker Equipment - Operating Mechanism | Breaker Equipment - Operating Mechanism | 154,160 | 154,160 |
| 76,028 | Avon Park (AVPK) - South Polk (SOPK) 230kV Line | 04/13/2020 19:36:58 | Line Equipment - Insulator (Line, Porcelain) | Line Equipment - Insulator (Line, Porcelain) | 0 | 61 |
| 76,924 | New River (NWRV) - (TECO) Handcart (HCRT) 69kV Line | 05/28/2020 16 08:55 | Weather/Environment - Wind | Line Equipment - Structure (Wood) | 0 | 298,225 |
| 76,926 | Clermont East (CMTE) - Lake Louisa (LLOU) 69kV Line | 05/28/2020 15:48:47 | Lightning - Lightning,Correlated in lightning detection system) | Relay and Control Systems - Reclosing blocked during active work | 0 | 27,846 |
| 79,134 | MARLEY ROAD | 07/29/2020 09:28:04 | O&M (Planned or Scheduled) - Preventive Maintenance Activity | Transformer Equipment - Under Investigation (Transformer?) | | 2,310 |
| 76,218 | DUNDEE* | 04/18/2020 12:32:02 | Public Interference - Vehicle | Public Interference - Vehicle | 145,119 | 145,119 |
| 77,168 | Meadow Woods South (MDWS) - Taft (TAFT) 69kV Line | 06/07/2020 18:20:47 | Lightning - Lightning,Correlated in lightning detection system) | Line Equipment - Static Wire (OHGW) | 277,507 | 277,507 |
| 78,200 | ARBUCKLE CREEK | 07/01/2020 18:43:41 | O&M (Planned or Scheduled) - Preventive Maintenance Activity | Relay and Control Systems - Relay Failure/Misoperation | 2,173 | 2,173 |
| 79,412 | Inglis Mining (IGLM) BK1 | 08/17/2020 07:24:00 | Animal - Squirrel | Animal - Squirrel | | 390 |
| 80,030 | DISSTON* | 09/16/2020 09:39:00 | Human Error - Construction (PD Contractor) | Breaker Equipment - Under Investigation (Breaker) | 315,336 | 315,336 |
| 80,222 | BELLEAIR* | 07/24/2020 19:22:00 | Vegetation - Tree/Tree Limbs Touching or Falling | Breaker Equipment - Close Coil | 148,054 | 148,054 |
| 80,566 | Lake Weir (LWER) - (CEC) Lynn (LYNN) 69kV Line | 10/22/2020 17 51:24 | Line Equipment - Static Wire (OHGW) | - | 0 | 350,941 |
| 81,224 | Brookridge (BKRG) - Twin County Ranch (TWCO) 115kV Line | 11/22/2020 21:47:54 | Public Interference - Vehicle | Public Interference - Vehicle | 0 | 3,731 |
| 81,530 | Whidden Creek 1 (WDC1) BK2 | 12/19/2020 07:17:21 | Unknown - Under Investigation (Unknown) | Other - No Reclose by Design or Policy | | 127 |
| 77,658 | MONTVERDE | 06/05/2020 16 05:21 | Breaker Equipment - Insulating/Interrupting Medium | Breaker Equipment - Insulating/Interrupting Medium | 25,212 | 25,212 |
| 78,454 | Ginnie (GINI) - Trenton (TNTN) 69kV Line | 07/21/2020 16:25:11 | Vegetation - Tree Falling from Outside ROW | Line Equipment - Conductor (Line) | 0 | 138,450 |
| 78,676 | PINECASTLE* | 07/27/2020 16:26:43 | Lightning - Lightning,Correlated in lightning detection system) | Breaker Equipment - Bushing Potential Device | 92,696 | 92,696 |
| 79,766 | SKY LAKE* | 08/27/2020 06:39:29 | Transformer Equipment - Cooling Equipment (Transformer) | Transformer Equipment - Cooling Equipment (Transformer) | 51,224 | 51,224 |
| 78,774 | Occidental Swift Creek #1 (OS1) - Occidental Metering (OXYM) 115kV Line | 07/30/2020 17:34:30 | Vegetation - Tree Falling from Outside ROW | Line Equipment - Conductor (Line) | 98,166 | 98,770 |
| 78,024 | CRYSTAL RIVER S* | 06/19/2020 11:20:41 | Crane) | Crane) | 50,404 | 50,404 |
| 79,634 | Fort White (FWHT) - Jasper South (JASS) 69kV Line | 08/25/2020 08 58:13 | Vegetation - Tree Falling from Outside ROW | Line Equipment - Conductor (Line) | 0 | 18,926 |
| 76,470 | MAXIMO* | 05/10/2020 19:34:16 | Animal - Bird Nest | Animal - Bird Nest | 265,710 | 265,710 |
| 78,924 | BELLEAIR* | 08/01/2020 19:22:24 | Vegetation - Tree/Tree Limbs Touching or Falling | Breaker Equipment - Close Coil | 78,375 | 78,375 |
| 79,102 | Casselberry (CSBY) - Lake Aloma (LALO) 69kV Line | 08/09/2020 18 08:54 | Lightning - Lightning,Correlated in lightning detection system) | - | 2 | 2 |
| 80,848 | Occidental Swift Creek 1 (OS1) BK2 | 10/29/2020 11:30:48 | Bus Equipment - Arrestor (Station Bus) | Bus Equipment - Arrestor (Station Bus) | | 55 |
| 76,564 | New River (NWRV) - (TECO) Cabbage Hill (CABH) 69kV Line | 05/18/2020 09 58:12 | Line Equipment - Conductor (Line) | Line Equipment - Conductor (Line) | 0 | 6,963 |
| 80,314 | East Clearwater (ECLW) BK2 Load | 10/04/2020 12:45:43 | Transformer Equipment - Under Investigation (Transformer?) | Transformer Equipment - Under Investigation (Transformer?) | 9,275 | 9,275 |
| 80,638 | Occidental Swift Creek 1 (OS1) BK3 | 10/24/2020 20:27:36 | Transformer Equipment - Winding, Internal Elements | Transformer Equipment - Winding, Internal Elements | | 798 |
| 80,228 | ZEPHYRHILLS* | 08/09/2020 17 00:00 | Weather/Environment - Wind | Breaker Equipment - Close Coil | 98,640 | 98,640 |
| 77,868 | RIO PINAR | 06/24/2020 08:26:52 | Miscellaneous - Distribution System Equipment | Breaker Equipment - Failed to Reclose | 70,349 | 70,349 |
| 79,460 | ZEPHYRHILLS* | 08/16/2020 17:48:00 | Animal - Bird Nest | Animal - Bird Nest | 505,096 | 505,096 |
| 80,250 | SANTOS | 09/12/2020 13 56:00 | Weather/Environment - Lightning Suspected, yet not correlated | - | 23,103 | 23,103 |
| 78,098 | Floral City (FLRC) - Inverness (INVS) 69kV Line | 07/11/2020 12:23:49 | Lightning - Lightning,Correlated in lightning detection system) | Breaker Equipment - Trip Coil | 0 | 9,060 |

| | | | | |
|-----------------------------------------------------------------------|--------------------------------------------------------------------------------------|------------------------------------------------------------------|---------|---------|
| 78,300 NORTHEAST* | 07/16/2020 18:10:00 Lightning - Lightning,Correlated in lightning detection systm) | Breaker Equipment - Insulating/Interrupting Medium | 413,919 | 413,919 |
| 76,360 LAND O LAKES | 05/03/2020 03:18:21 Relay and Control Systems - Reclosing blocked during active work | Relay and Control Systems - Reclosing blocked during active work | 192,808 | 192,808 |
| 78,782 RIO PINAR | 07/30/2020 19 00:21 Miscellaneous - Distribution System Equipment | Breaker Equipment - Physical Connection/Hardware (Breaker) | 161,014 | 161,014 |
| 80,270 Horse Creek (HORS) - Horse Creek 2 (HOR2) 69kV Line | 10/02/2020 07:39:52 Unknown - Unknown, after Patrol | Other - No Reclose by Design or Policy | 0 | 240 |
| 77,138 Fort Meade (FTMD) - Sand Mountain (SMTN) 69kV Line | 06/04/2020 22:16:49 Unknown - Unknown, after Patrol | Other - No Reclose by Design or Policy | 12,413 | 12,413 |
| 80,118 CLERMONT* | 08/27/2020 02 57:00 Transformer Equipment - TCUL | Transformer Equipment - TCUL | 39,030 | 39,030 |
| 79,862 Frostproof (FSFP) - Lake Wales (LKWL) 69kV Line | 09/06/2020 19 01:01 Weather/Environment - Lightning Suspected, yet not correlated | Line Equipment - Conductor (Line) | 75,426 | 75,426 |
| 80,140 Horse Creek (HORS) - Horse Creek 2 (HOR2) 69kV Line | 05/25/2020 06:14:10 Unknown - Unknown, after Patrol | Other - No Reclose by Design or Policy | 0 | 2 |
| 81,394 TAYLOR AVENUE* | 12/06/2020 08:42:00 Line Equipment - Conductor (Line) | Breaker Equipment - Under Investigation (Breaker) | 315,128 | 315,128 |
| 78,420 EAST CLEARWATER* | 07/18/2020 16:20:35 Weather/Environment - Rain (Includes Fog,Mist,Drizzle) | Breaker Equipment - Close Coil | 224,637 | 224,637 |
| 76,582 BAYWAY | 05/18/2020 10 51:48 Weather/Environment - Rain (Includes Fog,Mist,Drizzle) | Public Interference - Other Foreign Debris | 695,167 | 695,167 |
| 76,194 FORTIETH STREET* | 04/21/2020 12:49:00 Human Error - Incorrect Wiring | Human Error - Incorrect Wiring | 4,952 | 4,952 |
| 80,360 ALACHUA | 09/28/2020 07:32:00 Transformer Equipment - Bushing (Transformer) | Transformer Equipment - Bushing (Transformer) | 5,365 | 5,365 |
| 78,492 Maximo (MXMO) BK2 + 115kV Bus 2 | 07/21/2020 22 56:00 Animal - Snake | Animal - Snake | 68,700 | 68,700 |
| 78,506 Horse Creek (HORS) - Horse Creek 2 (HOR2) 69kV Line | 07/22/2020 12 00:53 Unknown - Unknown, after Patrol | Other - No Reclose by Design or Policy | 0 | 205 |
| 76,404 BITHLO | 05/04/2020 17:18:41 Breaker Equipment - Bushings (Breaker) | Breaker Equipment - Bushings (Breaker) | 343,881 | 343,881 |
| 77,238 PEMBROKE | 06/06/2020 06:12:10 Miscellaneous - Distribution System Equipment | etc.) | 20,947 | 20,947 |
| 77,310 LAKEWOOD* | 06/07/2020 11:20:58 Breaker Equipment - Failed to Reclose | Breaker Equipment - Physical Connection/Hardware (Breaker) | 50,002 | 50,002 |
| 77,446 South Polk (SOPK) - South Fort Meade (SFMD) 115kV Line | 06/19/2020 00 08:43 Unknown - Unknown, after Patrol | Unknown - Unknown, after Patrol | 0 | 17 |
| 80,324 Dunedin (DNDN) 69kV Bus 1 | 10/05/2020 09 53:54 Human Error - Duke Switching Error | Human Error - Duke Switching Error | 839,798 | 839,798 |
| 76,858 LAND O LAKES | 05/26/2020 12 07:55 Human Error - Incorrect Relay Setting | Human Error - Incorrect Relay Setting | 33,624 | 33,624 |
| 80,112 WINTER GARDEN | 09/05/2020 06:12:42 Breaker Equipment - Failed to Reclose | Breaker Equipment - Failed to Reclose | 30,240 | 30,240 |
| 77,314 LAKE WALES | 05/21/2020 18 05:06 Miscellaneous - Distribution System Equipment | System) | 1,851 | 1,851 |
| 77,606 Fort White (FWHT) - Jasper South (JASS) 115kV East Circuit | 06/23/2020 14:35:38 Vegetation - Tree Falling from Outside ROW | Vegetation - Tree Falling from Outside ROW | 0 | 63,184 |
| 77,934 Dunnellon Town (DNLN) - Inglis (INGL) 69kV Line | 07/05/2020 02:20:24 Lightning - Lightning,Correlated in lightning detection systm) | Other - No Reclose by Design or Policy | 0 | 18,631 |
| 78,396 CRAWFORDVILLE | 07/14/2020 23 02:00 Animal - Snake | Animal - Snake | 121,663 | 121,663 |
| 76,988 Floral City (FLRC) - Inverness (INVS) 69kV Line | 05/30/2020 20:14:01 Weather/Environment - Lightning Suspected, yet not correlated | Breaker Equipment - Operating Mechanism | 5,238 | 18,845 |
| 78,694 UCF (UCFL) - UCF North (UCFN) 69kV Line | 07/28/2020 16:40:36 Line Equipment - Insulator (Line, Polymer) | Line Equipment - Insulator (Line, Porcelain) | 3,058 | 3,058 |
| 78,696 UCF (UCFL) - UCF North (UCFN) 69kV Line | 07/28/2020 15:21:20 Lightning - Lightning,Correlated in lightning detection systm) | Line Equipment - Insulator (Line, Porcelain) | 3,031 | 3,031 |
| 80,114 Fort White (FWHT) - Jasper South (JASS) 69kV Line | 09/23/2020 03 58:18 Line Equipment - Crossarm | Line Equipment - Crossarm | 0 | 146,095 |
| 80,382 East Clearwater (ECLW) 69kV Bus 2 | 10/04/2020 12:45:43 Lightning - Lightning,Correlated in lightning detection systm) | Bus Equipment - Insulator (Bus) | 9,275 | 9,275 |
| 76,210 Fort White (FWHT) - Suwannee American Cement (SWAC) 115kV Line | 04/23/2020 21:11:58 Weather/Environment - Wind | Vegetation - Tree/Tree Limbs Touching or Falling | 0 | 60,104 |
| 76,828 SEVEN SPRINGS* | 02/07/2020 06:37:00 Weather/Environment - Rain (Includes Fog,Mist,Drizzle) | Breaker Equipment - Operating Mechanism | 43,254 | 43,254 |
| 77,598 Fort White (FWHT) - Jasper South (JASS) 115kV West Circuit | 06/23/2020 14:35:37 Vegetation - Tree Falling from Outside ROW | Vegetation - Tree Falling from Outside ROW | 0 | 10,129 |
| 77,656 DENHAM* | 06/24/2020 11 51:00 Breaker Equipment - Operating Mechanism | Breaker Equipment - Operating Mechanism | 43,229 | 43,229 |
| 77,860 Dundee (DUND) - Lake Wales (LKWL) 69kV Line | 07/01/2020 16:29:52 Lightning - Lightning,Correlated in lightning detection systm) | Line Equipment - Structure (Wood) | 37,593 | 37,593 |
| 77,646 BELLEAIR* | 06/18/2020 04 59:51 Breaker Equipment - Electrical Controls/Circuitry | Breaker Equipment - Electrical Controls/Circuitry | 39,730 | 39,730 |
| 78,502 BAYWAY | 07/21/2020 22 56:00 Animal - Snake | Animal - Snake | 19,377 | 19,377 |
| 79,738 Denham (DNHM) - (TECO) Cabbage Hill (CABH) 69kV Line | 08/31/2020 11 03:09 Lightning - Lightning,Correlated in lightning detection systm) | Other - No Reclose by Design or Policy | 0 | 19,595 |
| 80,194 Country Oaks (COAK) - East Lake Wales (ELWL) 69kV Line | 09/27/2020 20 55:45 Lightning - Lightning,Correlated in lightning detection systm) | Line Equipment - Static Wire (OHGW) | 95,839 | 106,521 |
| 79,540 Fort Meade (FTMD) - Homeland (HMLD) 69kV Line | 08/20/2020 14:38:46 Vegetation - Tree Falling from Outside ROW | Vegetation - Tree Falling from Outside ROW | 7,553 | 7,678 |
| 79,652 ELFERS* | 08/21/2020 12 51:00 Lightning - Lightning,Observed striking line or equipment | Other - No Reclose by Design or Policy | 151,007 | 151,007 |
| 78,754 MONTVERDE | 07/29/2020 15 02:00 Human Error - Incorrect Wiring | Human Error - Incorrect Wiring | 105,139 | 105,139 |
| 79,046 Horse Creek (HORS) - Horse Creek 2 (HOR2) 69kV Line | 08/07/2020 15 58:46 Weather/Environment - Lightning Suspected, yet not correlated | Other - No Reclose by Design or Policy | 0 | 37 |
| 80,464 CROSS BAYOU* | 10/13/2020 10:40:00 Breaker Equipment - Failed to Reclose | Breaker Equipment - Close Coil | 24,980 | 24,980 |
| 80,528 Chiefland (CHIF) - Inglis (INGL) 69kV Line | 10/19/2020 14:25:53 Line Equipment - Crossarm | Line Equipment - Crossarm | 54,928 | 66,248 |
| 78,770 SUNFLOWER | 07/29/2020 02:16:25 Miscellaneous - Distribution System Equipment | Breaker Equipment - Electrical Controls/Circuitry | 121,628 | 121,628 |
| 80,570 South Polk (SOPK) - South Fort Meade (SFMD) 115kV Line | 10/23/2020 07 06:59 Unknown - Unknown, after Patrol | Unknown - Unknown, after Patrol | 0 | 7 |
| 81,320 Denham (DNHM) - (TECO) Cabbage Hill (CABH) 69kV Line | 12/01/2020 07:42:29 Line Equipment - Structure (Wood) | Line Equipment - Structure (Wood) | 0 | 37,021 |
| 81,456 Tri-City (TRIC) 115kV Bus 2 | 12/14/2020 06:47:31 Switch Equipment/Malfunction - Gang Switch Flash | Switch Equipment/Malfunction - Gang Switch Flash | 635,277 | 635,277 |
| 79,636 Clermont East (CMTE) - Montverde (MTVD) 69kV Line | 08/25/2020 12 00:26 Human Error - Construction (PD Contractor) | Human Error - Construction (PD Contractor) | 258,519 | 258,519 |
| 80,636 Atwater (AWTR) - Liberty (LBTY) 115kV Line | 10/27/2020 01 59:29 Relay and Control Systems - Relay Failure/Misoperation | Relay and Control Systems - Relay Failure/Misoperation | 0 | 16,476 |
| 77,418 FROSTPROOF | 06/16/2020 15 55:46 Miscellaneous - Distribution System Equipment | Breaker Equipment - Failed to Reclose | 107,220 | 107,220 |
| 78,548 Hanson (HNSN) 115kV Bus 1 | 07/23/2020 15:28:38 Lightning - Lightning,Correlated in lightning detection systm) | Relay and Control Systems - Relay Failure/Misoperation | 0 | 228,783 |
| 80,090 New River (NWRV) - (TECO) Cabbage Hill (CABH) 69kV Line | 09/20/2020 12 06:02 Line Equipment - Insulator (Line, Polymer) | Line Equipment - Insulator (Line, Polymer) | 0 | 2,701 |
| 77,012 Fisheating Creek (FISH) BK1 Load | 06/01/2020 05:11:09 Unknown - Unknown, after Completed Engineer Investigation | Unknown - Unknown, after Completed Engineer Investigation | 201,391 | 201,391 |
| 79,768 WILDWOOD CITY | 08/27/2020 13:25:00 Breaker Equipment - Failed to Reclose | Breaker Equipment - Electrical Controls/Circuitry | 103,010 | 103,010 |
| 76,706 Frostproof (FSFP) - Lake Wales (LKWL) 69kV Line | 05/21/2020 17 58:00 Line Equipment - Crossarm | Line Equipment - Crossarm | 39,810 | 39,810 |
| 79,356 Horse Creek (HORS) - Horse Creek 2 (HOR2) 69kV Line | 08/14/2020 21:19:05 Unknown - Unknown, after Patrol | Other - No Reclose by Design or Policy | 0 | 124 |

| | | | | |
|-------------------------------------------------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------|---------|---------|
| 79,518 Fort Green Springs (FGNS) - Vandolah (VAND) 69kV Circuit 1 | 08/19/2020 20:34:21 Breaker Equipment - Trip Coil | Breaker Equipment - Trip Coil | 8 | 8 |
| 79,520 Fort Green Springs (FGNS) - Vandolah (VAND) 69kV Circuit 2 | 08/19/2020 20:34:21 Breaker Equipment - Trip Coil | Breaker Equipment - Trip Coil | 8 | 8 |
| 79,522 Fort Green Springs (FGNS) - Fort Meade (FTMD) 69kV Line | 08/19/2020 20:34:21 Breaker Equipment - Trip Coil | Breaker Equipment - Trip Coil | 8 | 8 |
| 79,524 Fort Green Springs (FGNS) - Peacock (PCOK) 69kV Line | 08/19/2020 20:34:21 Unknown - Unknown, after Patrol | Breaker Equipment - Trip Coil | 8 | 8,867 |
| 79,534 EAST CLEARWATER* | 08/19/2020 20:44:00 Vegetation - Tree/Tree Limbs Touching or Falling | Breaker Equipment - Interrupters | 91,729 | 91,729 |
| 77,496 Horse Creek (HORS) - Horse Creek 2 (HOR2) 69kV Line | 06/19/2020 20:47:39 Unknown - Unknown, after Patrol | Other - No Reclose by Design or Policy | 0 | 192 |
| 77,592 Spring Lake (SPLK) BKS | 06/23/2020 10:23:31 Human Error - Incorrect Wiring | Human Error - Incorrect Wiring | 289,814 | 289,814 |
| 77,944 Martin West (MTNW) - Zuber (ZUBR) 69kV Line | 07/06/2020 04:22:05 Vegetation - Tree Falling from Outside ROW | Vegetation - Tree Falling from Outside ROW | 0 | 879,894 |
| 78,794 Alafaya (ALFY) - UCF North (UCFN) 69kV Line | 07/31/2020 00 56:13 Human Error - Duke Switching Error | Human Error - Duke Switching Error | 97,599 | 97,599 |
| 77,120 Champions Gate (CHMP) - Citrus Center (CITC) 69kV Line | 06/04/2020 10 56:47 Lightning - Lightning, Correlated in lightning detection system | Relay and Control Systems - Relay Failure/Misoperation | 44,486 | 44,486 |
| 78,002 BAY HILL* | 07/01/2020 15:19:22 Miscellaneous - Distribution System Equipment | Breaker Equipment - Close Coil | 24,771 | 24,771 |

Attachment B

DEF TRANSMISSION Outages-Major Events Only

| OUTAGE_ID | LOCATION | OUTAGE_START_TIME | INITIATINGCAUSE | SUSTAINEDCAUSE |
|------------------|----------------------------------------------------------|--------------------------|---------------------------------------|--------------------------------------------|
| 74,961 | Fort Green Springs (FGNS) - Peacock (PCOK) 69kV Line | 02/06/2020 13:49:28 | Weather/Environment - Wind | Line Equipment - Structure (Wood) |
| 74,974 | Madison (MDSN) - Suwannee Transmission (SWTR) 115kV Line | 02/06/2020 19:34:22 | Weather/Environment - Wind | Line Equipment - Structure (Wood) |
| 74,946 | Bradfordville West (BRDW) - Drifton (DFTN) 115kV Line | 02/06/2020 10:47:46 | Weather/Environment - Wind | Vegetation - Tree Falling from Outside ROW |
| 81,490 | Cross Bayou (XBYU) - GE Pinellas (GEPN) 69kV Line | 12/16/2020 15:50:12 | Weather/Environment - Tornado/Twister | Line Equipment - Structure (Wood) |

Attachment C and C1

a Include in the discussion, the type of weather event, strength (wind speeds/surge-flood levels), locations affected, source of meteorological information, and the performance of overhead and underground systems

| Dates | Type of Weather Event | Strength (Wind Speeds/surge-flood levels) | Locations affected | Source of Metrological Information | Performance of Overhead and Underground Systems |
|-------------------------------------------|-----------------------|-------------------------------------------|----------------------------------------------------------------------------------------------------------------|------------------------------------|------------------------------------------------------------|
| 1/4/2020 - 11:00 AM to 11:59 AM | Tornado | Unknown Wind Speed | Deland | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |
| 1/4/2020 - 11:00 PM to 11:59 PM | Tornado | Unknown Wind Speed | Lake Wales | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |
| 4/20/2020 - 9:00 AM to 10:59 AM | Tornado | Unknown Wind Speed | Inverness | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |
| 6/6/2020 - 7:00 PM to 7:59 PM | Tornado | Unknown Wind Speed | SE Orlando | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |
| 8/18/2020 - 3:00 PM to 4:59 PM | Tornado | Unknown Wind Speed | Deland | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |
| 11/11/2020 3:00 PM to 11/12/2020 11:59 AM | Tropical Storm Eta | 39 to 73 mph | Clearwater Inverness Monticello Ocala Seven Springs St. Petersburg Walsingham Zephyrhills | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |
| 12/16/2020 3:00 PM to 4:59 PM | Tornado | Unknown Wind Speed | Clearwater Seven Springs Walsingham | National Weather Service | See response to Section (d) - pg. 10 of Reliability Report |

b. Describe the Company's efforts to avoid or minimize in terms of costs incurred and outage duration any similar events in the future. (Example: Reference specific storm hardening activity.)

Item b Please see response to Storm Hardening Facilities filed in the 2020 SPP.

c. If the method of deriving the weather exclusion is different from the method used for 2018, please explain the changes and provide the CMI and CI for 2019 using the prior method.

c. The exclusion method used is the same since 2005.

d. (Appendix) Provide the 2020 service reliability data for each extreme weather outage event that is excluded from your Company's 2021 Annual Distribution Reliability Report pursuant to Rule 25-6.0455.
 i. A Table
 ii. Electronic File
 iii. Overhead and Underground statistics & forensics. (C, CMI, CI, L-Bar, repair cost, etc.)

| Dates | Overhead vs. Underground | C | CMI | CI | Duration | L-Bar | N |
|-------------------------------------------|--------------------------|---------|------------|--------|----------|---------|-----|
| 1/4/2020 - 11:00 AM to 11:59 AM | OH | 87,353 | 206,775 | 1,140 | 3,307 | 472.4 | 7 |
| | UG | | - | - | - | - | - |
| 1/4/2020 - 11:00 PM to 11:59 PM | OH | 121,845 | 11,200 | 50 | 224 | 224.2 | 1 |
| | UG | | - | - | - | - | - |
| 4/20/2020 - 9:00 AM to 10:59 AM | OH | 78,974 | 654,652 | 2,129 | 11,009 | 379.6 | 29 |
| | UG | | - | - | - | - | - |
| 6/6/2020 - 7:00 PM to 7:59 PM | OH | 97,451 | 395,301 | 1,663 | 4,927 | 1,231.7 | 4 |
| | UG | | - | - | - | - | - |
| 8/18/2020 - 3:00 PM to 4:59 PM | OH | 87,353 | 3,391,430 | 7,602 | 54,901 | 963.2 | 57 |
| | UG | | 237 | 1 | 237 | 237.1 | 1 |
| 11/11/2020 3:00 PM to 11/12/2020 11:59 AM | OH | 936,273 | 30,198,251 | 98,851 | 630,687 | 733.4 | 860 |
| | UG | | 1,841,540 | 2,562 | 64,857 | 600.5 | 108 |
| 12/16/2020 3:00 PM to 4:59 PM | OH | 507,048 | 3,100,576 | 12,948 | 10,307 | 572.6 | 18 |
| | UG | | 41,047 | 358 | 924 | 307.9 | 3 |

Attachment C2

Actual Data: Customer Minutes of Interruption (CMI), Customer Interruptions (CI) and Documented Exclusions

| Year: 2020 | Customer minutes of Interruption (CMI) | | Customer Interruptions (CI) | |
|---------------------------------------|----------------------------------------|-------------|-----------------------------|-------------|
| | Value | % of Actual | Value | % of Actual |
| Reported Actual Data | 236,887,701 | 100% | 2,622,644 | 100% |
| Documented Exclusions | | | | |
| Planned Service Interruptions | 18,124,303 | 7.65% | 385,290 | 14.69% |
| Named Storm | 32,039,791 | 13.53% | 101,413 | 3.87% |
| Tornadoes | 7,801,218 | 3.29% | 25,891 | 0.99% |
| Ice on Lines | | | | |
| Planned Load Management Events | | | | |
| Generation/Transmission Events | 12,065,644 | 5.09% | 326,065 | 12.43%% |
| Extreme Weather (EOC Activation/Fire) | | | | |
| Reported Adjusted Data | 166,856,745 | 70.44% | 1,783,985 | 68.02%% |

Attachment D



CAUSES OF OUTAGE EVENTS – ADJUSTED

Utility Name: Duke Energy Florida LLC Years: 2016 to 2020

| Cause (a) | 2020 | | | 2019 | | | 2018 | | | 2017 | | | 2016 | | |
|------------------------|-----------------------------------|---------------------------------|-----------------------------------------|-----------------------------------|---------------------------------|-----------------------------------------|-----------------------------------|---------------------------------|-----------------------------------------|-----------------------------------|---------------------------------|-----------------------------------------|-----------------------------------|---------------------------------|-----------------------------------------|
| | Number of Outage Events(N) (b) | Average Duration (L-Bar) (c) | Average Restoration Time (CAIDI) (d) | Number of Outage Events(N) (b) | Average Duration (L-Bar) (c) | Average Restoration Time (CAIDI) (d) | Number of Outage Events(N) (b) | Average Duration (L-Bar) (c) | Average Restoration Time (CAIDI) (d) | Number of Outage Events(N) (b) | Average Duration (L-Bar) (c) | Average Restoration Time (CAIDI) (d) | Number of Outage Events(N) (b) | Average Duration (L-Bar) (c) | Average Restoration Time (CAIDI) (d) |
| 1. Animals | 3,882 | 82.1 | 68.8 | 5,127 | 82.0 | 67.3 | 4,566 | 81.6 | 69.1 | 5,596 | 80.0 | 63.9 | 5,369 | 80.3 | 63.1 |
| 2. Vegetation | 9,291 | 160.3 | 110.9 | 8,883 | 159.6 | 108.1 | 8,522 | 148.3 | 106.6 | 8,143 | 150.1 | 102.8 | 7,879 | 144.8 | 99.8 |
| 3. Lightning | 994 | 157.0 | 97.4 | 943 | 168.3 | 106.0 | 1,517 | 157.4 | 103.2 | 1,261 | 151.4 | 80.2 | 1,216 | 150.3 | 85.8 |
| 4. Other Weather | 5,826 | 159.3 | 109.7 | 5,658 | 153.1 | 105.2 | 6,463 | 143.5 | 110.8 | 5,478 | 145.2 | 95.4 | 4,965 | 133.7 | 97.2 |
| 5. Vehicle | 509 | 245.1 | 111.6 | 445 | 249.9 | 119.2 | 599 | 232.7 | 105.2 | 505 | 223.2 | 103.2 | 429 | 235.2 | 102.0 |
| 6. Defective Equipment | 11,973 | 146.4 | 82.4 | 11,921 | 145.8 | 87.0 | 12,038 | 151.8 | 97.3 | 10,475 | 150.0 | 91.0 | 9,195 | 146.7 | 82.4 |
| 7. Unknown | 556 | 87.7 | 69.0 | 859 | 84.5 | 54.5 | 766 | 83.2 | 58.7 | 998 | 93.9 | 64.5 | 1,097 | 90.3 | 63.1 |
| | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | |
| All Other Causes | 7,170 | 181.0 | 71.4 | 8,223 | 169.0 | 75.7 | 8,310 | 173.0 | 82.6 | 8,287 | 179.8 | 76.1 | 7,390 | 173.8 | 72.6 |
| System Totals: | 40,201 | 152.1 | 93.5 | 42,059 | 146.8 | 93.1 | 42,781 | 146.6 | 97.3 | 40,743 | 145.4 | 89.5 | 37,540 | 139.9 | 86.4 |

Attachment E



2021 PROGRAM BUDGET

| CAPITAL | | | | | | | | | | | | | |
|-----------------------------------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|------------|-------------|
| | Jan-21 | Feb-21 | Mar-21 | Apr-21 | May-21 | Jun-21 | Jul-21 | Aug-21 | Sep-21 | Oct-21 | Nov-21 | Dec-21 | Annual |
| 592 - DEF Live Front Swtchgr Replace | 142,773 | 330,739 | 421,133 | 234,029 | 373,436 | 327,483 | 326,330 | 235,685 | 239,304 | 192,559 | 49,449 | 0 | 2,872,920 |
| 956 - DEF Fuse Replacement | 1,142,893 | 2,031,676 | 3,556,303 | 4,468,793 | 4,468,793 | 4,714,610 | 3,992,661 | 3,609,858 | 3,017,176 | 4,796,428 | 3,262,829 | 2,309,177 | 40,765,377 |
| ATS - ATS Replace | 0 | 0 | 0 | 98,623 | 0 | 98,578 | 0 | 99,352 | 0 | 101,522 | 104,382 | 0 | 502,457 |
| CBLDT - UG Cable Repl DT | 211,196 | 209,365 | 206,329 | 206,253 | 205,692 | 206,369 | 205,300 | 208,899 | 212,821 | 214,140 | 223,010 | 220,485 | 2,529,860 |
| CMCDT - Corr Maint Cap DT | 254,340 | 202,001 | 199,969 | 200,007 | 199,479 | 99,970 | 0 | 0 | 0 | 0 | 0 | 0 | 1,155,768 |
| CMCEDT - Corr Maint Cap Emerg DT | 125,665 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 125,665 |
| CMCEOH - Corr Maint Cap Emerg OH | 62,129 | 70,917 | 115,831 | 118,872 | 145,935 | 149,362 | 145,727 | 126,159 | 96,915 | 78,596 | 74,657 | 64,276 | 1,249,376 |
| CMCEUG - Corr Maint Cap Emerg UG | 64,587 | 87,401 | 115,179 | 120,932 | 160,824 | 143,973 | 120,442 | 116,288 | 100,467 | 89,160 | 79,828 | 60,783 | 1,259,863 |
| CMCOH - OH Replace (Other - Planned) | 0 | 0 | 0 | 0 | 78,681 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 78,681 |
| CMCOWP - Corr Maint Cap OH Wire Pri | 759 | 753 | 1,176 | 1,225 | 1,505 | 1,460 | 1,798 | 926 | 867 | 769 | 799 | 725 | 12,762 |
| CMCOWS - Corr Maint Cap OH Wire Sec Svc | 11,291 | 11,199 | 11,044 | 11,040 | 17,423 | 18,037 | 17,951 | 11,743 | 11,376 | 11,225 | 11,444 | 10,874 | 154,647 |
| CMCUG - Corr Maint Cap UG Oth | 42,860 | 61,448 | 84,068 | 102,729 | 116,456 | 126,112 | 116,286 | 108,511 | 100,663 | 81,934 | 59,807 | 49,349 | 1,050,224 |
| CTP1PH - Cst Trnf Pdmt Repl 1PH Leak | 0 | 0 | 0 | 33,212 | 55,203 | 44,313 | 44,085 | 11,222 | 11,437 | 0 | 0 | 0 | 199,471 |
| CTP3PH - Cst Trnf Pdmt Repl 3PH Leak | 0 | 0 | 0 | 99,490 | 99,219 | 24,889 | 0 | 0 | 0 | 0 | 0 | 0 | 223,598 |
| DAIDR - Distribution Automation Rplc | 0 | 0 | 0 | 0 | 131,708 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 131,708 |
| DLS - OH Line Switch Repl | 16,751 | 24,924 | 28,703 | 24,597 | 24,533 | 24,605 | 16,329 | 20,728 | 16,871 | 25,456 | 17,597 | 8,705 | 249,798 |
| GENSWGR - Switchgear Replacement | 0 | 195,015 | 144,786 | 96,545 | 144,428 | 96,509 | 96,156 | 97,281 | 98,803 | 49,690 | 51,106 | 0 | 1,070,318 |
| HYDR - Recloser Repl Hydraulic | 44,743 | 16,652 | 16,472 | 32,949 | 32,860 | 131,764 | 16,407 | 16,613 | 118,178 | 39,627 | 5,834 | 0 | 472,098 |
| MHR - Manhole Lid Retrofit | 0 | 0 | 197,940 | 296,967 | 217,201 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 712,108 |
| NANC - NAN Replacements | 20,429 | 35,490 | 20,075 | 20,079 | 20,025 | 15,054 | 19,998 | 30,349 | 5,137 | 15,502 | 0 | 0 | 202,139 |
| POLCM - Pole Replacement Reactive | 611,526 | 626,025 | 616,988 | 623,249 | 615,093 | 630,098 | 620,501 | 624,756 | 636,421 | 599,899 | 568,491 | 506,575 | 7,279,621 |
| POLIR - Pole Replace Insp FUP | 1,303,193 | 1,588,423 | 1,543,261 | 1,528,875 | 1,517,931 | 1,523,112 | 1,501,640 | 1,406,077 | 1,412,501 | 1,287,030 | 1,226,228 | 306,625 | 16,145,077 |
| POLOTH - Pole Insp FUP Other Prop Units | 9,724 | 8,433 | 15,426 | 8,303 | 11,829 | 14,243 | 10,627 | 9,619 | 12,253 | 9,864 | 6,429 | 3,813 | 120,564 |
| POLRNF - Pole Reinforcement | 82,344 | 93,678 | 92,523 | 91,998 | 91,289 | 91,644 | 90,654 | 92,571 | 94,492 | 94,623 | 98,787 | 97,579 | 1,112,183 |
| RGR - Capacitor Replacement | 131,908 | 198,015 | 229,165 | 240,267 | 189,183 | 116,939 | 31,488 | 36,646 | 33,982 | 22,785 | 30,149 | 23,220 | 1,283,748 |
| RGR - Regulator Replacement | 127,581 | 120,620 | 125,412 | 125,448 | 107,233 | 107,475 | 101,141 | 78,216 | 122,204 | 92,195 | 69,474 | 56,282 | 1,233,280 |
| RNET - Network Sec Main Replace | 201,190 | 199,341 | 196,605 | 196,558 | 196,612 | 196,628 | 195,690 | 198,915 | 202,566 | 203,826 | 211,799 | 209,435 | 2,408,568 |
| RRR - Recloser Electronic Replc | 67,327 | 152,777 | 226,976 | 264,891 | 198,123 | 340,389 | 141,332 | 238,138 | 377,229 | 223,782 | 209,820 | 9,893 | 2,450,678 |
| RTP1PH - Pad Transf 1PH Oil Leak Rplc | 74,741 | 105,809 | 156,248 | 176,993 | 186,890 | 208,386 | 186,550 | 158,396 | 107,666 | 86,677 | 33,948 | 22,367 | 1,504,671 |
| RTP3PH - Pad Transf 3PH Oil Leak Rplc | 184,504 | 320,478 | 385,135 | 430,535 | 519,750 | 520,984 | 496,472 | 479,586 | 371,219 | 280,067 | 144,118 | 71,336 | 4,204,186 |
| RTR1PH - Pad Transf 1PH Non Leak Rplc | 100,530 | 120,759 | 145,346 | 176,500 | 170,848 | 155,719 | 129,243 | 125,729 | 101,176 | 69,636 | 44,231 | 27,361 | 1,367,079 |
| RTR3PH - Pad Transf 3PH Non Leak Rplc | 87,818 | 130,769 | 258,991 | 431,777 | 430,599 | 409,988 | 301,022 | 239,172 | 110,401 | 88,841 | 68,460 | 22,596 | 2,580,435 |
| RTXO - Transf OH Repl | 7,956 | 15,796 | 31,284 | 46,939 | 66,316 | 66,465 | 66,228 | 63,034 | 32,006 | 12,073 | 8,270 | 0 | 416,367 |
| RUCLG - UG Lg Cable Rpl only Replace | 853,176 | 1,819,452 | 776,479 | 1,100,013 | 414,886 | 263,095 | 89,400 | 661,219 | 153,242 | 809,304 | 235,721 | 243,022 | 7,419,008 |
| RUCSEC - UG Cable Repl Sec Svc | 713,680 | 353,593 | 526,408 | 819,152 | 911,797 | 1,336,647 | 1,578,728 | 1,551,512 | 1,804,981 | 1,636,790 | 1,295,481 | 907,413 | 13,436,182 |
| RUCSM - UG Sm Cable Rpl only Replace | 2,111,044 | 2,091,345 | 2,056,580 | 2,055,242 | 2,049,614 | 2,057,320 | 2,045,695 | 2,087,332 | 2,129,740 | 2,143,345 | 845,107 | 834,648 | 22,507,011 |
| SPCCAP - SPCC Containment Cap | 0 | 13,639 | 13,434 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 27,073 |
| VNPTRR - Vault Netwk Prot & Transf Rplc | 0 | 0 | 0 | 132,330 | 131,973 | 132,265 | 0 | 0 | 0 | 0 | 0 | 0 | 396,567 |
| 590 - DEF Trans Retrofit Accelerated | 2,082,193 | 1,876,167 | 1,546,797 | 1,199,104 | 1,208,636 | 1,080,065 | 946,382 | 1,060,042 | 2,392,120 | 771,207 | 680,048 | 672,067 | 15,514,827 |
| 591 - DEF Deteriorated Conductor | 5,689,386 | 4,181,078 | 4,491,599 | 3,578,032 | 2,260,413 | 1,562,879 | 1,783,983 | 1,272,328 | 1,080,960 | 497,130 | 280,889 | 277,539 | 26,956,216 |
| RIOTC - Outage Invest Improv Cap | 360,666 | 715,875 | 686,054 | 789,351 | 695,789 | 743,103 | 603,755 | 610,372 | 713,846 | 624,118 | 532,130 | 275,301 | 7,350,360 |
| RSH - Base Storm Hardening | 492,539 | 488,202 | 901,836 | 721,184 | 719,203 | 601,349 | 478,623 | 487,199 | 496,496 | 312,259 | 195,282 | 193,040 | 6,087,212 |
| 594 - DEF Segmentation & Automation | 4,072,612 | 4,333,678 | 6,407,724 | 4,991,768 | 5,659,536 | 4,622,647 | 6,969,115 | 4,342,396 | 2,324,176 | 1,823,480 | 754,475 | 2,109,914 | 48,411,521 |
| 687 - DEF Circuit Capacity | 1,643,962 | 1,712,735 | 2,484,216 | 2,680,110 | 2,820,629 | 2,088,220 | 980,729 | 357,693 | 229,326 | 111,386 | 72,760 | 279,127 | 15,460,892 |
| 793 - DEF Substation Upgrades | 771,974 | 778,061 | 961,129 | 962,743 | 781,816 | 815,579 | 608,474 | 398,667 | 398,440 | 10,916 | 10,916 | 12,525 | 6,511,240 |
| 974 - DEF ATS Replace & SCADA Enable | 0 | 0 | 213,106 | 106,563 | 318,815 | 639,266 | 530,593 | 322,536 | 218,582 | 439,789 | 0 | 0 | 2,789,250 |
| 516 - DEF Targeted OH/UG Conversion | 3,499,384 | 4,129,945 | 4,978,265 | 6,135,648 | 6,950,152 | 7,292,880 | 6,895,666 | 6,986,095 | 6,806,725 | 6,332,724 | 5,518,013 | 5,670,383 | 71,195,881 |
| HWYN - Highway Nonreimb Cap | 1,582,075 | 1,569,861 | 1,554,339 | 1,555,101 | 1,550,540 | 1,554,038 | 1,548,386 | 1,565,697 | 1,591,481 | 1,601,670 | 1,645,768 | 1,628,531 | 18,947,398 |
| DMAJDL - Major Reliability D Line Cap | 804,749 | 646,952 | 1,008,977 | 1,347,836 | 1,377,844 | 1,567,568 | 2,357,256 | 1,393,269 | 1,189,485 | 1,105,517 | 1,115,751 | 1,068,041 | 14,983,245 |
| DCAPINC - CAPACITY INCREASE - DIST STA | 3,415,368 | 3,248,110 | 3,915,617 | 1,457,519 | 1,463,124 | 1,512,173 | 1,585,461 | 1,445,105 | 1,193,311 | 790,603 | 776,276 | 581,138 | 21,383,804 |
| DKTADD - CIRCUIT ADDITIONS - DIST STA | 0 | 14,564 | 36,071 | 36,131 | 21,943 | 161,745 | 367,779 | 358,981 | 358,773 | 356,791 | 284,114 | 107,974 | 2,104,868 |
| SPPFDHD - SPP Feeder Hardening | 5,138,159 | 5,989,418 | 6,663,577 | 6,888,917 | 7,335,617 | 7,371,091 | 6,463,344 | 5,104,332 | 3,417,021 | 2,077,902 | 1,470,765 | 1,368,261 | 59,288,404 |
| SCDL - Sys Capacity D Line | 611,887 | 1,013,214 | 963,712 | 957,725 | 1,036,813 | 1,209,299 | 1,476,341 | 1,543,868 | 1,885,761 | 1,688,839 | 1,185,099 | 636,592 | 14,209,151 |
| Sum: | 38,973,611 | 41,934,391 | 49,328,290 | 47,417,324 | 48,503,555 | 47,216,567 | 46,301,771 | 39,993,112 | 36,028,598 | 31,901,678 | 23,559,541 | 20,946,970 | 472,105,407 |
| O&M | | | | | | | | | | | | | |
| | Jan-21 | Feb-21 | Mar-21 | Apr-21 | May-21 | Jun-21 | Jul-21 | Aug-21 | Sep-21 | Oct-21 | Nov-21 | Dec-21 | Annual |
| ENVREM - Other Environ Remediation | 25,415 | 33,890 | 47,449 | 59,316 | 55,922 | 59,316 | 57,618 | 67,787 | 50,839 | 49,144 | 25,415 | 33,890 | 566,000 |
| OHTXSPL - OH Transformer Oil Spill | 6,736 | 8,976 | 12,578 | 15,721 | 14,813 | 15,721 | 15,269 | 17,961 | 13,471 | 13,026 | 6,736 | 9,000 | 150,008 |
| PDSPL1 - Pdmt Single Phase Spill | 65,500 | 87,283 | 122,136 | 152,634 | 143,918 | 152,634 | 148,274 | 174,409 | 130,843 | 126,497 | 65,500 | 87,283 | 1,456,913 |
| PDSPL3 - Pdmt Three Phase Spill | 16,270 | 21,689 | 30,366 | 37,957 | 35,781 | 37,957 | 36,881 | 43,378 | 32,529 | 31,457 | 16,270 | 21,797 | 362,332 |
| AVOM - Avian Protection OM | 2,051 | 2,880 | 4,196 | 5,348 | 5,025 | 5,348 | 5,185 | 6,165 | 4,522 | 4,366 | 2,051 | 2,880 | 50,017 |
| CCEMT - Critical Environ Maint | 10,311 | 13,800 | 19,371 | 24,256 | 22,861 | 24,256 | 23,554 | 27,739 | 20,771 | 20,072 | 10,311 | 13,800 | 231,100 |
| CEINS - Critical Environ Inspections | 4,249 | 5,554 | 7,776 | 9,720 | 9,163 | 9,720 | 9,443 | 11,108 | 8,332 | 8,053 | 4,165 | 5,554 | 92,837 |
| POLINS - Pole Inspection | 283,877 | 378,503 | 529,905 | 662,381 | 624,530 | 662,381 | 643,455 | 757,005 | 567,755 | 548,831 | 378,502 | 283,876 | 6,321,000 |

| | | | | | | | | | | | | | |
|--------------------------------------|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|-------------------|--------------------|
| POLOV - Pole Repair Overloaded Pole | 8,514 | 11,353 | 15,895 | 19,867 | 18,732 | 19,867 | 20,301 | 22,708 | 17,030 | 16,464 | 8,514 | 11,353 | 190,598 |
| RIOUT - Outage Invest Improv | 125,417 | 167,222 | 234,114 | 292,644 | 275,920 | 292,644 | 284,279 | 334,448 | 250,836 | 242,479 | 125,417 | 167,222 | 2,792,641 |
| SPCCINS - SPCC Inspection | 700 | 935 | 1,307 | 1,635 | 1,542 | 1,635 | 1,589 | 1,870 | 1,402 | 1,354 | 700 | 935 | 15,804 |
| SPCCOM - SPCC Inspection Repair FUP | 68 | 90 | 126 | 157 | 149 | 157 | 153 | 180 | 136 | 131 | 68 | 90 | 1,501 |
| 956 - DEF Fuse Replacement | 21,215 | 28,286 | 39,596 | 49,498 | 46,668 | 49,498 | 48,083 | 56,573 | 42,427 | 41,011 | 21,215 | 28,286 | 472,355 |
| DPRJOMM - OM on Maintain Capital | 113,945 | 151,935 | 212,703 | 265,880 | 250,687 | 265,880 | 258,286 | 303,862 | 227,898 | 220,298 | 113,945 | 151,935 | 2,537,254 |
| 590 - DEF Trans Retrofit Accelerated | 19,842 | 26,451 | 37,032 | 46,291 | 43,648 | 46,291 | 44,970 | 52,901 | 39,674 | 38,352 | 19,842 | 26,451 | 441,745 |
| 591 - DEF Deteriorated Conductor | 18,658 | 24,877 | 34,830 | 43,544 | 41,049 | 43,544 | 42,295 | 49,763 | 37,321 | 36,072 | 18,658 | 24,877 | 415,488 |
| PQINSE - PQ Cust Engin Inspect OM | 135,236 | 135,236 | 139,665 | 139,665 | 139,665 | 139,665 | 145,412 | 139,665 | 139,665 | 139,665 | 139,665 | 139,665 | 1,678,615 |
| 594 - DEF Segmentation & Automation | 118,293 | 126,497 | 187,673 | 146,206 | 165,960 | 135,239 | 204,651 | 126,801 | 67,429 | 52,882 | 21,603 | 60,667 | 1,413,900 |
| 687 - DEF Circuit Capacity | 54,415 | 58,385 | 78,047 | 79,565 | 83,257 | 66,916 | 37,343 | 16,340 | 10,151 | 4,541 | 1,713 | 10,800 | 501,474 |
| 793 - DEF Substation Upgrades | 6,671 | 6,721 | 8,335 | 8,344 | 6,743 | 6,974 | 5,184 | 3,389 | 3,384 | 0 | 0 | 0 | 55,745 |
| 974 - DEF ATS Replace & SCADA Enable | 0 | 0 | 6,537 | 3,269 | 9,791 | 19,587 | 16,317 | 9,869 | 6,647 | 13,370 | 0 | 0 | 85,386 |
| 516 - DEF Targeted OH/UG Conversion | 64,947 | 70,294 | 74,836 | 89,560 | 115,763 | 117,854 | 118,262 | 118,087 | 114,246 | 114,949 | 115,812 | 163,482 | 1,278,091 |
| DPRJOMH - OM on Highway-Mods | 14,161 | 14,119 | 14,000 | 14,001 | 13,979 | 13,983 | 13,978 | 14,092 | 14,239 | 14,322 | 14,611 | 14,517 | 170,004 |
| DPRJOMS - OM on Capacity Capital | 29,681 | 28,955 | 29,025 | 29,856 | 29,837 | 29,751 | 28,893 | 27,892 | 27,597 | 30,352 | 24,406 | 24,184 | 340,428 |
| SPPFDHD - SPP Feeder Hardening | 204,977 | 240,068 | 267,464 | 276,396 | 294,744 | 295,587 | 260,025 | 204,713 | 136,226 | 82,785 | 58,191 | 54,351 | 2,375,528 |
| Sum: | 1,351,149 | 1,643,999 | 2,154,962 | 2,473,709 | 2,450,145 | 2,512,406 | 2,469,699 | 2,588,704 | 1,965,367 | 1,850,473 | 1,251,198 | 1,284,754 | 23,996,565 |
| Totals: | 40,324,760 | 43,578,390 | 51,483,252 | 49,891,032 | 50,953,700 | 49,728,973 | 48,771,470 | 42,581,816 | 37,993,965 | 33,752,151 | 24,810,739 | 22,231,723 | 496,101,972 |

Attachment F



| SYSTEM RELIABILITY INDICES – ADJUSTED | | | | | | | | | | | | | | | | | | | | | | | | | |
|------------------------------------------------------------|-----------|-----------|-----------|------------|-----------|-----------|-----------|-----------|------------|-----------|-----------|-----------|-----------|------------|-----------|-----------|-----------|-----------|------------|-----------|-----------|-----------|-----------|------------|-----------|
| Utility Name: Duke Energy Florida, LLC, Year: 2016 to 2020 | | | | | | | | | | | | | | | | | | | | | | | | | |
| District or Service Area (a) | 2020 | | | | | 2019 | | | | | 2018 | | | | | 2017 | | | | | 2016 | | | | |
| | SAIDI (b) | CAIDI (c) | SAIFI (d) | MAIFle (e) | CEMIS (f) | SAIDI (b) | CAIDI (c) | SAIFI (d) | MAIFle (e) | CEMIS (f) | SAIDI (b) | CAIDI (c) | SAIFI (d) | MAIFle (e) | CEMIS (f) | SAIDI (b) | CAIDI (c) | SAIFI (d) | MAIFle (e) | CEMIS (f) | SAIDI (b) | CAIDI (c) | SAIFI (d) | MAIFle (e) | CEMIS (f) |
| North Coastal Region* | 117.2 | 101.9 | 1.15 | 6.4 | 2.32% | 169.5 | 108.5 | 1.56 | 9.7 | 5.50% | 168.3 | 111.0 | 1.52 | 13.6 | 4.80% | 154.3 | 106.6 | 1.45 | 8.2 | 2.83% | 154.8 | 111.3 | 1.39 | 7.8 | 4.00% |
| South Coastal Region* | 82.6 | 96.1 | 0.86 | 6.0 | 0.37% | 72.0 | 83.8 | 0.86 | 7.9 | 0.19% | 95.2 | 99.8 | 0.95 | 10.8 | 0.49% | 75.0 | 85.1 | 0.88 | 6.8 | 0.21% | 72.7 | 81.1 | 0.90 | 7.3 | 0.68% |
| North Central Region | 85.2 | 101.5 | 0.84 | 3.1 | 0.42% | 87.0 | 107.7 | 0.81 | 4.7 | 0.41% | 86.4 | 90.4 | 0.96 | 3.6 | 0.42% | 75.5 | 90.0 | 0.84 | 7.6 | 0.37% | 78.1 | 87.0 | 0.90 | 8.6 | 0.36% |
| South Central Region | 70.4 | 76.7 | 0.92 | 5.7 | 1.17% | 85.9 | 84.6 | 1.02 | 8.8 | 0.79% | 84.3 | 90.4 | 0.93 | 11.4 | 0.44% | 69.6 | 83.3 | 0.84 | 6.9 | 0.87% | 78.8 | 78.2 | 1.01 | 7.0 | 1.06% |
| | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | |
| System Averages | 87.9 | 93.5 | 0.94 | 5.4 | 1.06% | 90.5 | 93.1 | 0.97 | 7.6 | 1.02% | 98.5 | 97.3 | 1.01 | 9.7 | 0.95% | 82.7 | 89.5 | 0.92 | 7.2 | 0.73% | 85.0 | 86.4 | 0.98 | 7.6 | 1.09% |

*2020 Had a structure change therefore North Coastal and South Coastal numbers are not comparable to previous years.

Attachment G

2020 FEEDER SPECIFIC DATA

PROVIDED ON CD

Attachment G



2020 Summer Feeder Peaks

| Load Area | NAME | BANK | FEEDER NAME | PLANNER PEAK MVA |
|---------------|---------------|------|-------------|------------------|
| SOUTH COASTAL | ALDERMAN | 1 | C5000 | 7.0 |
| SOUTH COASTAL | ALDERMAN | 1 | C5001 | 5.1 |
| SOUTH COASTAL | ALDERMAN | 1 | C5003 | 7.4 |
| SOUTH COASTAL | ALDERMAN | 2 | C5008 | 8.6 |
| SOUTH COASTAL | ALDERMAN | 2 | C5009 | 9.2 |
| SOUTH COASTAL | ALDERMAN | 3 | C5010 | 4.6 |
| SOUTH COASTAL | ALDERMAN | 3 | C5011 | 5.7 |
| SOUTH COASTAL | ALDERMAN | 3 | C5012 | 11.4 |
| SOUTH COASTAL | ALDERMAN | 2 | C5013 | 8.1 |
| SOUTH COASTAL | ANCLOTE | 8 | C4201 | 9.5 |
| SOUTH COASTAL | ANCLOTE | 8 | C4202 | 8.8 |
| SOUTH COASTAL | ANCLOTE | 8 | C4203 | 9.5 |
| SOUTH COASTAL | ANCLOTE | 8 | C4204 | 7.4 |
| SOUTH COASTAL | ANCLOTE | 7 | C4206 | 5.5 |
| SOUTH COASTAL | ANCLOTE | 7 | C4207 | 10.8 |
| SOUTH COASTAL | ANCLOTE | 7 | C4208 | 7.4 |
| SOUTH COASTAL | BAYBORO PLANT | 2 | X0009 | 8.2 |
| SOUTH COASTAL | BAYBORO PLANT | 1 | X0010 | 3.5 |
| SOUTH COASTAL | BAYBORO PLANT | 2 | X0013 | 3.8 |
| SOUTH COASTAL | BAYBORO PLANT | 1 | X0015 | 3.7 |
| SOUTH COASTAL | BAYBORO PLANT | 2 | X0016 | 9.4 |
| SOUTH COASTAL | BAYBORO PLANT | 2 | X0018 | 9.0 |
| SOUTH COASTAL | BAYBORO PLANT | 1 | X0019 | 8.3 |
| SOUTH COASTAL | BAYBORO PLANT | 1 | X0020 | 5.7 |
| SOUTH COASTAL | BAYBORO PLANT | 2 | X0021 | 7.1 |
| SOUTH COASTAL | BAYVIEW | 1 | C0651 | 11.4 |
| SOUTH COASTAL | BAYVIEW | 1 | C0652 | 9.9 |
| SOUTH COASTAL | BAYVIEW | 1 | C0653 | 9.5 |
| SOUTH COASTAL | BAYVIEW | 1 | C0654 | 10.8 |
| SOUTH COASTAL | BAYVIEW | 2 | C0655 | 7.7 |
| SOUTH COASTAL | BAYVIEW | 2 | C0656 | 10.1 |
| SOUTH COASTAL | BAYVIEW | 2 | C0657 | 10.3 |
| SOUTH COASTAL | BAYVIEW | 2 | C0658 | 7.4 |
| SOUTH COASTAL | BAYWAY | 2 | X0096 | 9.1 |
| SOUTH COASTAL | BAYWAY | 2 | X0097 | 10.8 |
| SOUTH COASTAL | BAYWAY | 2 | X0099 | 11.1 |
| SOUTH COASTAL | BAYWAY | 2 | X0100 | 2.7 |
| SOUTH COASTAL | BELLEAIR | 1 | C1002 | 10.7 |
| SOUTH COASTAL | BELLEAIR | 1 | C1003 | 9.4 |
| SOUTH COASTAL | BELLEAIR | 1 | C1004 | 2.0 |
| SOUTH COASTAL | BELLEAIR | 2 | C1005 | 10.7 |
| SOUTH COASTAL | BELLEAIR | 2 | C1007 | 6.9 |

| | | | | |
|---------------|---------------|---|-------|------|
| SOUTH COASTAL | BELLEAIR | 2 | C1008 | 11.7 |
| SOUTH COASTAL | BELLEAIR | 1 | J1001 | 9.8 |
| SOUTH COASTAL | BROOKER CREEK | 1 | C5400 | 8.1 |
| SOUTH COASTAL | BROOKER CREEK | 1 | C5401 | 3.5 |
| SOUTH COASTAL | BROOKER CREEK | 1 | C5402 | 7.2 |
| SOUTH COASTAL | BROOKER CREEK | 2 | C5404 | 7.8 |
| SOUTH COASTAL | BROOKER CREEK | 2 | C5405 | 10.6 |
| SOUTH COASTAL | BROOKER CREEK | 2 | C5406 | 9.2 |
| SOUTH COASTAL | CENTRAL PLAZA | 1 | X0262 | 10.6 |
| SOUTH COASTAL | CENTRAL PLAZA | 2 | X0263 | 0.8 |
| SOUTH COASTAL | CENTRAL PLAZA | 1 | X0264 | 7.5 |
| SOUTH COASTAL | CENTRAL PLAZA | 2 | X0265 | 5.1 |
| SOUTH COASTAL | CENTRAL PLAZA | 1 | X0266 | 1.2 |
| SOUTH COASTAL | CENTRAL PLAZA | 2 | X0267 | 5.0 |
| SOUTH COASTAL | CENTRAL PLAZA | 1 | X0268 | 7.8 |
| SOUTH COASTAL | CLEARWATER | 1 | C0004 | 7.1 |
| SOUTH COASTAL | CLEARWATER | 1 | C0005 | 11.7 |
| SOUTH COASTAL | CLEARWATER | 1 | C0006 | 2.0 |
| SOUTH COASTAL | CLEARWATER | 1 | C0007 | 5.5 |
| SOUTH COASTAL | CLEARWATER | 2 | C0008 | 1.8 |
| SOUTH COASTAL | CLEARWATER | 2 | C0009 | 2.4 |
| SOUTH COASTAL | CLEARWATER | 2 | C0010 | 9.3 |
| SOUTH COASTAL | CLEARWATER | 2 | C0011 | 9.4 |
| SOUTH COASTAL | CLEARWATER | 3 | C0012 | 9.7 |
| SOUTH COASTAL | CLEARWATER | 3 | C0013 | 4.9 |
| SOUTH COASTAL | CLEARWATER | 3 | C0014 | 7.0 |
| SOUTH COASTAL | CLEARWATER | 3 | C0015 | 6.1 |
| SOUTH COASTAL | CLEARWATER | 4 | C0016 | 9.6 |
| SOUTH COASTAL | CLEARWATER | 4 | C0017 | 9.5 |
| SOUTH COASTAL | CLEARWATER | 4 | C0018 | 6.5 |
| SOUTH COASTAL | CLEARWATER | 4 | C0019 | 5.4 |
| SOUTH COASTAL | CROSS BAYOU | 3 | J0140 | 6.2 |
| SOUTH COASTAL | CROSS BAYOU | 3 | J0141 | 11.9 |
| SOUTH COASTAL | CROSS BAYOU | 1 | J0142 | 12.6 |
| SOUTH COASTAL | CROSS BAYOU | 1 | J0143 | 11.1 |
| SOUTH COASTAL | CROSS BAYOU | 1 | J0144 | 1.5 |
| SOUTH COASTAL | CROSS BAYOU | 1 | J0145 | 8.8 |
| SOUTH COASTAL | CROSS BAYOU | 2 | J0146 | 8.2 |
| SOUTH COASTAL | CROSS BAYOU | 2 | J0147 | 10.8 |
| SOUTH COASTAL | CROSS BAYOU | 2 | J0148 | 10.9 |
| SOUTH COASTAL | CROSS BAYOU | 3 | J0150 | 9.9 |
| SOUTH COASTAL | CROSSROADS | 1 | X0132 | 8.0 |
| SOUTH COASTAL | CROSSROADS | 1 | X0133 | 8.4 |
| SOUTH COASTAL | CROSSROADS | 1 | X0134 | 7.8 |
| SOUTH COASTAL | CROSSROADS | 2 | X0135 | 9.3 |
| SOUTH COASTAL | CROSSROADS | 2 | X0136 | 2.4 |
| SOUTH COASTAL | CROSSROADS | 2 | X0137 | 3.3 |
| SOUTH COASTAL | CROSSROADS | 2 | X0138 | 6.9 |

| | | | | |
|---------------|-----------------|---|-------|------|
| SOUTH COASTAL | CURLEW | 3 | C4972 | 7.6 |
| SOUTH COASTAL | CURLEW | 3 | C4973 | 8.5 |
| SOUTH COASTAL | CURLEW | 2 | C4976 | 10.6 |
| SOUTH COASTAL | CURLEW | 2 | C4985 | 5.4 |
| SOUTH COASTAL | CURLEW | 2 | C4986 | 9.1 |
| SOUTH COASTAL | CURLEW | 3 | C4987 | 6.0 |
| SOUTH COASTAL | CURLEW | 3 | C4988 | 9.0 |
| SOUTH COASTAL | CURLEW | 1 | C4989 | 8.8 |
| SOUTH COASTAL | CURLEW | 1 | C4990 | 9.5 |
| SOUTH COASTAL | CURLEW | 1 | C4991 | 11.0 |
| SOUTH COASTAL | DENHAM | 1 | C0151 | 8.4 |
| SOUTH COASTAL | DENHAM | 1 | C0152 | 8.4 |
| SOUTH COASTAL | DENHAM | 2 | C0153 | 9.8 |
| SOUTH COASTAL | DENHAM | 2 | C0154 | 6.6 |
| SOUTH COASTAL | DENHAM | 2 | C0155 | 9.0 |
| SOUTH COASTAL | DENHAM | 3 | C0156 | 11.7 |
| SOUTH COASTAL | DENHAM | 3 | C0157 | 10.7 |
| SOUTH COASTAL | DENHAM | 3 | C0158 | 11.4 |
| SOUTH COASTAL | DENHAM | 1 | C0159 | 10.1 |
| SOUTH COASTAL | DISSTON | 1 | X0060 | 10.7 |
| SOUTH COASTAL | DISSTON | 1 | X0061 | 4.2 |
| SOUTH COASTAL | DISSTON | 1 | X0062 | 11.4 |
| SOUTH COASTAL | DISSTON | 1 | X0063 | 10.7 |
| SOUTH COASTAL | DISSTON | 2 | X0064 | 9.4 |
| SOUTH COASTAL | DISSTON | 2 | X0065 | 2.7 |
| SOUTH COASTAL | DISSTON | 2 | X0066 | 11.6 |
| SOUTH COASTAL | DISSTON | 2 | X0067 | 8.8 |
| SOUTH COASTAL | DUNEDIN | 1 | C0102 | 8.8 |
| SOUTH COASTAL | DUNEDIN | 1 | C0103 | 9.7 |
| SOUTH COASTAL | DUNEDIN | 2 | C0104 | 8.3 |
| SOUTH COASTAL | DUNEDIN | 2 | C0106 | 5.7 |
| SOUTH COASTAL | DUNEDIN | 3 | C0107 | 9.7 |
| SOUTH COASTAL | DUNEDIN | 3 | C0108 | 7.9 |
| SOUTH COASTAL | EAST CLEARWATER | 1 | C0900 | 9.7 |
| SOUTH COASTAL | EAST CLEARWATER | 1 | C0901 | 6.2 |
| SOUTH COASTAL | EAST CLEARWATER | 1 | C0902 | 11.8 |
| SOUTH COASTAL | EAST CLEARWATER | 1 | C0903 | 7.1 |
| SOUTH COASTAL | EAST CLEARWATER | 2 | C0904 | 9.9 |
| SOUTH COASTAL | EAST CLEARWATER | 2 | C0905 | 7.6 |
| SOUTH COASTAL | EAST CLEARWATER | 2 | C0906 | 8.6 |
| SOUTH COASTAL | EAST CLEARWATER | 2 | C0907 | 10.5 |
| SOUTH COASTAL | EAST CLEARWATER | 3 | C0908 | 5.7 |
| SOUTH COASTAL | EAST CLEARWATER | 3 | C0909 | 8.5 |
| SOUTH COASTAL | EAST CLEARWATER | 3 | C0910 | 10.4 |
| SOUTH COASTAL | EAST CLEARWATER | 3 | C0911 | 8.2 |
| SOUTH COASTAL | ELFERS | 2 | C0950 | 7.1 |
| SOUTH COASTAL | ELFERS | 2 | C0951 | 6.8 |
| SOUTH COASTAL | ELFERS | 2 | C0952 | 7.9 |

| | | | | |
|---------------|--------------------|---|-------|------|
| SOUTH COASTAL | ELFERS | 2 | C0953 | 7.0 |
| SOUTH COASTAL | ELFERS | 1 | C0954 | 4.8 |
| SOUTH COASTAL | ELFERS | 1 | C0955 | 10.7 |
| SOUTH COASTAL | ELFERS | 1 | C0956 | 10.7 |
| SOUTH COASTAL | ELFERS | 1 | C0957 | 9.3 |
| SOUTH COASTAL | FIFTY FIRST STREET | 2 | X0101 | 6.1 |
| SOUTH COASTAL | FIFTY FIRST STREET | 1 | X0102 | 8.4 |
| SOUTH COASTAL | FIFTY FIRST STREET | 2 | X0103 | 9.7 |
| SOUTH COASTAL | FIFTY FIRST STREET | 1 | X0104 | 5.5 |
| SOUTH COASTAL | FIFTY FIRST STREET | 2 | X0105 | 8.9 |
| SOUTH COASTAL | FIFTY FIRST STREET | 1 | X0106 | 4.0 |
| SOUTH COASTAL | FIFTY FIRST STREET | 2 | X0107 | 7.7 |
| SOUTH COASTAL | FIFTY FIRST STREET | 1 | X0108 | 6.5 |
| SOUTH COASTAL | FLORA-MAR | 1 | C4000 | 8.1 |
| SOUTH COASTAL | FLORA-MAR | 1 | C4001 | 8.2 |
| SOUTH COASTAL | FLORA-MAR | 1 | C4002 | 10.2 |
| SOUTH COASTAL | FLORA-MAR | 1 | C4003 | 8.7 |
| SOUTH COASTAL | FLORA-MAR | 2 | C4006 | 10.2 |
| SOUTH COASTAL | FLORA-MAR | 2 | C4007 | 7.8 |
| SOUTH COASTAL | FLORA-MAR | 2 | C4008 | 7.4 |
| SOUTH COASTAL | FLORA-MAR | 2 | C4009 | 8.8 |
| SOUTH COASTAL | FORTIETH STREET | 1 | X0081 | 5.4 |
| SOUTH COASTAL | FORTIETH STREET | 1 | X0082 | 8.9 |
| SOUTH COASTAL | FORTIETH STREET | 2 | X0083 | 7.7 |
| SOUTH COASTAL | FORTIETH STREET | 2 | X0084 | 8.0 |
| SOUTH COASTAL | FORTIETH STREET | 2 | X0085 | 6.6 |
| SOUTH COASTAL | G E PINELLAS | 1 | J0231 | 2.4 |
| SOUTH COASTAL | G E PINELLAS | 2 | J0234 | 2.4 |
| SOUTH COASTAL | G E PINELLAS | 2 | J0235 | 1.2 |
| SOUTH COASTAL | GATEWAY | 1 | X0111 | 9.8 |
| SOUTH COASTAL | GATEWAY | 1 | X0112 | 7.6 |
| SOUTH COASTAL | GATEWAY | 1 | X0113 | 8.7 |
| SOUTH COASTAL | GATEWAY | 1 | X0114 | 3.9 |
| SOUTH COASTAL | GATEWAY | 2 | X0118 | 8.0 |
| SOUTH COASTAL | GATEWAY | 2 | X0119 | 8.0 |
| SOUTH COASTAL | GATEWAY | 2 | X0120 | 8.6 |
| SOUTH COASTAL | GATEWAY | 3 | X0121 | 9.6 |
| SOUTH COASTAL | GATEWAY | 3 | X0122 | 3.5 |
| SOUTH COASTAL | GATEWAY | 3 | X0123 | 6.5 |
| SOUTH COASTAL | GATEWAY | 3 | X0125 | 5.4 |
| SOUTH COASTAL | HIGHLANDS | 2 | C2802 | 8.3 |
| SOUTH COASTAL | HIGHLANDS | 2 | C2803 | 8.3 |
| SOUTH COASTAL | HIGHLANDS | 2 | C2804 | 6.8 |
| SOUTH COASTAL | HIGHLANDS | 1 | C2805 | 8.5 |
| SOUTH COASTAL | HIGHLANDS | 1 | C2806 | 9.9 |
| SOUTH COASTAL | HIGHLANDS | 1 | C2807 | 7.8 |
| SOUTH COASTAL | HIGHLANDS | 2 | C2808 | 8.4 |
| SOUTH COASTAL | KENNETH | 1 | X0050 | 9.2 |

| | | | | |
|---------------|-----------------|---|-------|------|
| SOUTH COASTAL | KENNETH | 1 | X0051 | 7.8 |
| SOUTH COASTAL | KENNETH | 1 | X0052 | 0.4 |
| SOUTH COASTAL | KENNETH | 1 | X0053 | 9.9 |
| SOUTH COASTAL | KENNETH | 2 | X0054 | 0.4 |
| SOUTH COASTAL | KENNETH | 2 | X0055 | 4.9 |
| SOUTH COASTAL | KENNETH | 2 | X0056 | 8.1 |
| SOUTH COASTAL | KENNETH | 2 | X0057 | 9.7 |
| SOUTH COASTAL | LAND-O-LAKES | 1 | C0140 | 10.0 |
| SOUTH COASTAL | LAND-O-LAKES | 1 | C0141 | 11.1 |
| SOUTH COASTAL | LAND-O-LAKES | 1 | C0143 | 13.7 |
| SOUTH COASTAL | LAND-O-LAKES | 2 | C0146 | 8.7 |
| SOUTH COASTAL | LAND-O-LAKES | 2 | C0148 | 6.0 |
| SOUTH COASTAL | LARGO | 1 | J0402 | 3.4 |
| SOUTH COASTAL | LARGO | 1 | J0403 | 9.5 |
| SOUTH COASTAL | LARGO | 1 | J0404 | 8.0 |
| SOUTH COASTAL | LARGO | 1 | J0405 | 7.0 |
| SOUTH COASTAL | LARGO | 2 | J0406 | 7.4 |
| SOUTH COASTAL | LARGO | 2 | J0407 | 11.0 |
| SOUTH COASTAL | LARGO | 2 | J0408 | 5.6 |
| SOUTH COASTAL | LARGO | 2 | J0409 | 6.6 |
| SOUTH COASTAL | MAXIMO | 3 | X0140 | 9.5 |
| SOUTH COASTAL | MAXIMO | 3 | X0141 | 9.5 |
| SOUTH COASTAL | MAXIMO | 3 | X0142 | 9.4 |
| SOUTH COASTAL | MAXIMO | 1 | X0143 | 11.2 |
| SOUTH COASTAL | MAXIMO | 1 | X0144 | 0.7 |
| SOUTH COASTAL | MAXIMO | 1 | X0146 | 8.2 |
| SOUTH COASTAL | MAXIMO | 1 | X0147 | 10.3 |
| SOUTH COASTAL | MAXIMO | 2 | X0149 | 10.9 |
| SOUTH COASTAL | MAXIMO | 2 | X0150 | 8.1 |
| SOUTH COASTAL | MAXIMO | 2 | X0151 | 11.4 |
| SOUTH COASTAL | MAXIMO | 2 | X0152 | 0.7 |
| SOUTH COASTAL | NEW PORT RICHEY | 1 | C0441 | 7.7 |
| SOUTH COASTAL | NEW PORT RICHEY | 1 | C0442 | 7.0 |
| SOUTH COASTAL | NEW PORT RICHEY | 2 | C0443 | 9.7 |
| SOUTH COASTAL | NEW PORT RICHEY | 2 | C0444 | 7.2 |
| SOUTH COASTAL | NORTHEAST | 1 | X0282 | 6.7 |
| SOUTH COASTAL | NORTHEAST | 1 | X0283 | 6.6 |
| SOUTH COASTAL | NORTHEAST | 1 | X0284 | 12.4 |
| SOUTH COASTAL | NORTHEAST | 1 | X0285 | 8.4 |
| SOUTH COASTAL | NORTHEAST | 1 | X0286 | 9.2 |
| SOUTH COASTAL | NORTHEAST | 2 | X0287 | 11.2 |
| SOUTH COASTAL | NORTHEAST | 2 | X0288 | 7.9 |
| SOUTH COASTAL | NORTHEAST | 2 | X0289 | 9.8 |
| SOUTH COASTAL | NORTHEAST | 2 | X0290 | 6.6 |
| SOUTH COASTAL | NORTHEAST | 2 | X0291 | 3.0 |
| SOUTH COASTAL | OAKHURST | 1 | J0221 | 8.4 |
| SOUTH COASTAL | OAKHURST | 3 | J0223 | 8.8 |
| SOUTH COASTAL | OAKHURST | 3 | J0224 | 9.4 |

| | | | | |
|---------------|---------------------|---|-------|------|
| SOUTH COASTAL | OAKHURST | 2 | J0226 | 10.7 |
| SOUTH COASTAL | OAKHURST | 2 | J0227 | 8.8 |
| SOUTH COASTAL | OAKHURST | 1 | J0228 | 9.7 |
| SOUTH COASTAL | OAKHURST | 1 | J0229 | 8.2 |
| SOUTH COASTAL | ODESSA | 2 | C4320 | 13.0 |
| SOUTH COASTAL | ODESSA | 1 | C4322 | 13.3 |
| SOUTH COASTAL | ODESSA | 2 | C4323 | 10.3 |
| SOUTH COASTAL | ODESSA | 2 | C4328 | 8.7 |
| SOUTH COASTAL | ODESSA | 1 | C4329 | 5.5 |
| SOUTH COASTAL | OLDSMAR | 2 | C0604 | 1.7 |
| SOUTH COASTAL | PALM HARBOR | 1 | C0752 | 8.0 |
| SOUTH COASTAL | PALM HARBOR | 1 | C0753 | 8.1 |
| SOUTH COASTAL | PALM HARBOR | 2 | C0755 | 9.2 |
| SOUTH COASTAL | PALM HARBOR | 2 | C0756 | 7.8 |
| SOUTH COASTAL | PALM HARBOR | 2 | C0757 | 10.0 |
| SOUTH COASTAL | PASADENA | 2 | X0211 | 10.6 |
| SOUTH COASTAL | PASADENA | 2 | X0212 | 5.7 |
| SOUTH COASTAL | PASADENA | 2 | X0213 | 5.9 |
| SOUTH COASTAL | PASADENA | 2 | X0214 | 6.8 |
| SOUTH COASTAL | PASADENA | 2 | X0215 | 3.6 |
| SOUTH COASTAL | PASADENA | 1 | X0216 | 5.4 |
| SOUTH COASTAL | PASADENA | 1 | X0217 | 4.2 |
| SOUTH COASTAL | PASADENA | 1 | X0219 | 10.4 |
| SOUTH COASTAL | PASADENA | 1 | X0220 | 7.9 |
| SOUTH COASTAL | PILSBURY | 1 | X0252 | 3.9 |
| SOUTH COASTAL | PILSBURY | 1 | X0253 | 2.1 |
| SOUTH COASTAL | PILSBURY | 1 | X0254 | 9.9 |
| SOUTH COASTAL | PILSBURY | 1 | X0255 | 9.2 |
| SOUTH COASTAL | PILSBURY | 2 | X0256 | 1.2 |
| SOUTH COASTAL | PILSBURY | 2 | X0257 | 10.6 |
| SOUTH COASTAL | PILSBURY | 2 | X0258 | 9.3 |
| SOUTH COASTAL | PILSBURY | 2 | X0259 | 12.3 |
| SOUTH COASTAL | PINELLAS WELL FIELD | 1 | C801 | 1.4 |
| SOUTH COASTAL | PINELLAS WELL FIELD | 1 | C802 | 0.7 |
| SOUTH COASTAL | PORT RICHEY WEST | 2 | C0202 | 9.5 |
| SOUTH COASTAL | PORT RICHEY WEST | 2 | C0203 | 8.3 |
| SOUTH COASTAL | PORT RICHEY WEST | 1 | C0205 | 5.0 |
| SOUTH COASTAL | PORT RICHEY WEST | 1 | C0206 | 9.7 |
| SOUTH COASTAL | PORT RICHEY WEST | 1 | C0207 | 6.8 |
| SOUTH COASTAL | PORT RICHEY WEST | 3 | C0208 | 7.6 |
| SOUTH COASTAL | PORT RICHEY WEST | 3 | C0209 | 9.6 |
| SOUTH COASTAL | PORT RICHEY WEST | 3 | C0210 | 8.4 |
| SOUTH COASTAL | SAFETY HARBOR | 1 | C3518 | 6.6 |
| SOUTH COASTAL | SAFETY HARBOR | 2 | C3521 | 8.7 |
| SOUTH COASTAL | SAFETY HARBOR | 2 | C3523 | 7.0 |
| SOUTH COASTAL | SAFETY HARBOR | 2 | C3524 | 8.9 |
| SOUTH COASTAL | SAFETY HARBOR | 1 | C3525 | 9.0 |
| SOUTH COASTAL | SAFETY HARBOR | 1 | C3527 | 9.5 |

| | | | | |
|---------------|------------------|---|-------|------|
| SOUTH COASTAL | SAFETY HARBOR | 1 | C3528 | 8.3 |
| SOUTH COASTAL | SEMINOLE | 2 | J0889 | 12.0 |
| SOUTH COASTAL | SEMINOLE | 2 | J0890 | 10.5 |
| SOUTH COASTAL | SEMINOLE | 2 | J0891 | 6.4 |
| SOUTH COASTAL | SEMINOLE | 1 | J0892 | 10.9 |
| SOUTH COASTAL | SEMINOLE | 1 | J0893 | 6.7 |
| SOUTH COASTAL | SEMINOLE | 1 | J0894 | 9.4 |
| SOUTH COASTAL | SEMINOLE | 1 | J0895 | 10.8 |
| SOUTH COASTAL | SEMINOLE | 2 | J888 | 7.0 |
| SOUTH COASTAL | SEVEN SPRINGS | 4 | C4500 | 6.8 |
| SOUTH COASTAL | SEVEN SPRINGS | 4 | C4501 | 9.5 |
| SOUTH COASTAL | SEVEN SPRINGS | 6 | C4502 | 7.1 |
| SOUTH COASTAL | SEVEN SPRINGS | 5 | C4507 | 7.4 |
| SOUTH COASTAL | SEVEN SPRINGS | 5 | C4508 | 12.5 |
| SOUTH COASTAL | SEVEN SPRINGS | 5 | C4509 | 7.8 |
| SOUTH COASTAL | SEVEN SPRINGS | 4 | C4510 | 7.0 |
| SOUTH COASTAL | SEVEN SPRINGS | 6 | C4512 | 8.0 |
| SOUTH COASTAL | SIXTEENTH STREET | 1 | X0031 | 9.3 |
| SOUTH COASTAL | SIXTEENTH STREET | 2 | X0032 | 9.3 |
| SOUTH COASTAL | SIXTEENTH STREET | 1 | X0033 | 3.9 |
| SOUTH COASTAL | SIXTEENTH STREET | 2 | X0034 | 10.6 |
| SOUTH COASTAL | SIXTEENTH STREET | 1 | X0035 | 3.0 |
| SOUTH COASTAL | SIXTEENTH STREET | 2 | X0036 | 7.8 |
| SOUTH COASTAL | SIXTEENTH STREET | 2 | X0042 | 5.8 |
| SOUTH COASTAL | SIXTEENTH STREET | 1 | X0043 | 5.1 |
| SOUTH COASTAL | SIXTEENTH STREET | 1 | X0045 | 8.8 |
| SOUTH COASTAL | SIXTEENTH STREET | 2 | X0046 | 9.3 |
| SOUTH COASTAL | STARKEY ROAD | 1 | J0112 | 7.6 |
| SOUTH COASTAL | STARKEY ROAD | 1 | J0113 | 5.0 |
| SOUTH COASTAL | STARKEY ROAD | 1 | J0114 | 7.6 |
| SOUTH COASTAL | STARKEY ROAD | 2 | J0115 | 9.5 |
| SOUTH COASTAL | STARKEY ROAD | 2 | J0116 | 11.5 |
| SOUTH COASTAL | STARKEY ROAD | 2 | J0117 | 3.4 |
| SOUTH COASTAL | STARKEY ROAD | 2 | J0118 | 8.9 |
| SOUTH COASTAL | TARPON SPRINGS | 1 | C0301 | 6.8 |
| SOUTH COASTAL | TARPON SPRINGS | 1 | C0302 | 8.7 |
| SOUTH COASTAL | TARPON SPRINGS | 1 | C0303 | 9.4 |
| SOUTH COASTAL | TARPON SPRINGS | 1 | C0304 | 10.9 |
| SOUTH COASTAL | TARPON SPRINGS | 2 | C0305 | 9.9 |
| SOUTH COASTAL | TARPON SPRINGS | 2 | C0306 | 7.8 |
| SOUTH COASTAL | TARPON SPRINGS | 2 | C0307 | 11.2 |
| SOUTH COASTAL | TARPON SPRINGS | 2 | C0308 | 7.4 |
| SOUTH COASTAL | TAYLOR AVENUE | 2 | J2902 | 8.3 |
| SOUTH COASTAL | TAYLOR AVENUE | 2 | J2903 | 9.5 |
| SOUTH COASTAL | TAYLOR AVENUE | 2 | J2904 | 9.9 |
| SOUTH COASTAL | TAYLOR AVENUE | 1 | J2905 | 8.6 |
| SOUTH COASTAL | TAYLOR AVENUE | 1 | J2906 | 8.6 |
| SOUTH COASTAL | TAYLOR AVENUE | 1 | J2907 | 10.4 |

| | | | | |
|---------------|----------------------|---|-------|------|
| SOUTH COASTAL | THIRTY SECOND STREET | 1 | X0022 | 8.8 |
| SOUTH COASTAL | THIRTY SECOND STREET | 1 | X0023 | 4.0 |
| SOUTH COASTAL | THIRTY SECOND STREET | 1 | X0024 | 5.1 |
| SOUTH COASTAL | THIRTY SECOND STREET | 1 | X0025 | 7.6 |
| SOUTH COASTAL | THIRTY SECOND STREET | 2 | X0026 | 7.6 |
| SOUTH COASTAL | THIRTY SECOND STREET | 2 | X0027 | 11.6 |
| SOUTH COASTAL | THIRTY SECOND STREET | 2 | X0028 | 9.0 |
| SOUTH COASTAL | THIRTY SECOND STREET | 3 | X0029 | 8.0 |
| SOUTH COASTAL | THIRTY SECOND STREET | 3 | X0030 | 11.9 |
| SOUTH COASTAL | THIRTY SECOND STREET | 3 | X0037 | 9.3 |
| SOUTH COASTAL | TRI-CITY | 3 | J5030 | 7.5 |
| SOUTH COASTAL | TRI-CITY | 3 | J5032 | 9.3 |
| SOUTH COASTAL | TRI-CITY | 2 | J5034 | 9.0 |
| SOUTH COASTAL | TRI-CITY | 2 | J5036 | 4.4 |
| SOUTH COASTAL | TRI-CITY | 2 | J5038 | 8.3 |
| SOUTH COASTAL | TRI-CITY | 3 | J5040 | 8.5 |
| SOUTH COASTAL | ULMERTON | 1 | J0240 | 8.4 |
| SOUTH COASTAL | ULMERTON | 1 | J0241 | 9.3 |
| SOUTH COASTAL | ULMERTON | 1 | J0242 | 11.7 |
| SOUTH COASTAL | ULMERTON | 1 | J0243 | 9.6 |
| SOUTH COASTAL | ULMERTON | 2 | J0244 | 8.2 |
| SOUTH COASTAL | ULMERTON | 2 | J0245 | 4.6 |
| SOUTH COASTAL | ULMERTON | 2 | J0246 | 5.0 |
| SOUTH COASTAL | ULMERTON | 2 | J0247 | 9.1 |
| SOUTH COASTAL | ULMERTON WEST | 1 | J0680 | 6.0 |
| SOUTH COASTAL | ULMERTON WEST | 1 | J0682 | 10.6 |
| SOUTH COASTAL | ULMERTON WEST | 1 | J0684 | 9.0 |
| SOUTH COASTAL | ULMERTON WEST | 2 | J0689 | 5.3 |
| SOUTH COASTAL | ULMERTON WEST | 2 | J0690 | 8.1 |
| SOUTH COASTAL | ULMERTON WEST | 2 | J0691 | 7.6 |
| SOUTH COASTAL | ULMERTON WEST | 2 | J0692 | 6.4 |
| SOUTH COASTAL | VINOY | 1 | X0070 | 9.8 |
| SOUTH COASTAL | VINOY | 2 | X0071 | 6.0 |
| SOUTH COASTAL | VINOY | 2 | X0072 | 11.3 |
| SOUTH COASTAL | VINOY | 2 | X0074 | 2.4 |
| SOUTH COASTAL | VINOY | 2 | X0075 | 3.4 |
| SOUTH COASTAL | VINOY | 1 | X0076 | 4.4 |
| SOUTH COASTAL | VINOY | 1 | X0077 | 4.9 |
| SOUTH COASTAL | VINOY | 1 | X0078 | 11.4 |
| SOUTH COASTAL | VINOY | 1 | X0079 | 4.3 |
| SOUTH COASTAL | VINOY | 1 | X0080 | 7.1 |
| SOUTH COASTAL | WALSINGHAM | 2 | J0551 | 11.4 |
| SOUTH COASTAL | WALSINGHAM | 2 | J0552 | 9.4 |
| SOUTH COASTAL | WALSINGHAM | 2 | J0553 | 7.4 |
| SOUTH COASTAL | WALSINGHAM | 2 | J0554 | 10.8 |
| SOUTH COASTAL | WALSINGHAM | 1 | J0555 | 7.6 |
| SOUTH COASTAL | WALSINGHAM | 1 | J0556 | 9.1 |
| SOUTH COASTAL | WALSINGHAM | 1 | J0557 | 10.8 |

| | | | | |
|---------------|-------------------|---|-------|------|
| SOUTH COASTAL | WALSINGHAM | 1 | J0558 | 8.1 |
| SOUTH COASTAL | ZEPHYRHILLS | 2 | C0851 | 10.1 |
| SOUTH COASTAL | ZEPHYRHILLS | 2 | C0852 | 7.9 |
| SOUTH COASTAL | ZEPHYRHILLS | 2 | C0853 | 4.5 |
| SOUTH COASTAL | ZEPHYRHILLS | 1 | C0854 | 5.2 |
| SOUTH COASTAL | ZEPHYRHILLS | 1 | C0855 | 9.5 |
| SOUTH COASTAL | ZEPHYRHILLS | 1 | C0856 | 9.3 |
| SOUTH COASTAL | ZEPHYRHILLS | 1 | C0857 | 4.6 |
| SOUTH COASTAL | ZEPHYRHILLS NORTH | 2 | C0340 | 3.3 |
| SOUTH COASTAL | ZEPHYRHILLS NORTH | 2 | C0341 | 8.3 |
| SOUTH COASTAL | ZEPHYRHILLS NORTH | 1 | C0342 | 7.6 |
| SOUTH COASTAL | ZEPHYRHILLS NORTH | 1 | C0343 | 9.1 |
| SOUTH COASTAL | ZEPHYRHILLS NORTH | 1 | C0344 | 11.0 |
| SOUTH COASTAL | ZEPHYRHILLS NORTH | 2 | C0345 | 3.9 |
| SOUTH CENTRAL | ARBUCKLE CREEK | 1 | K1361 | 3.7 |
| SOUTH CENTRAL | AVALON | 4 | K37 | 6.7 |
| SOUTH CENTRAL | AVALON | 4 | K38 | 0.3 |
| SOUTH CENTRAL | AVON PARK NORTH | 2 | K0891 | 6.6 |
| SOUTH CENTRAL | AVON PARK NORTH | 2 | K0892 | 2.1 |
| SOUTH CENTRAL | AVON PARK NORTH | 1 | K0893 | 6.9 |
| SOUTH CENTRAL | AVON PARK NORTH | 1 | K0894 | 4.8 |
| SOUTH CENTRAL | AVON PARK PLANT | 5 | K0116 | 4.4 |
| SOUTH CENTRAL | AVON PARK PLANT | 5 | K0117 | 5.4 |
| SOUTH CENTRAL | AVON PARK PLANT | 4 | K0118 | 5.6 |
| SOUTH CENTRAL | AVON PARK PLANT | 4 | K0119 | 8.1 |
| SOUTH CENTRAL | BABSON PARK | 1 | K1195 | 3.3 |
| SOUTH CENTRAL | BABSON PARK | 1 | K1196 | 3.8 |
| SOUTH CENTRAL | BARNUM CITY | 1 | K1501 | 9.1 |
| SOUTH CENTRAL | BARNUM CITY | 2 | K1503 | 11.2 |
| SOUTH CENTRAL | BARNUM CITY | 1 | K3360 | 8.5 |
| SOUTH CENTRAL | BARNUM CITY | 2 | K3362 | 11.8 |
| SOUTH CENTRAL | BARNUM CITY | 1 | K3364 | 5.5 |
| SOUTH CENTRAL | BAY HILL | 3 | K67 | 10.0 |
| SOUTH CENTRAL | BAY HILL | 3 | K68 | 9.8 |
| SOUTH CENTRAL | BAY HILL | 1 | K72 | 6.3 |
| SOUTH CENTRAL | BAY HILL | 1 | K73 | 8.1 |
| SOUTH CENTRAL | BAY HILL | 1 | K74 | 9.6 |
| SOUTH CENTRAL | BAY HILL | 2 | K75 | 9.6 |
| SOUTH CENTRAL | BAY HILL | 2 | K76 | 7.9 |
| SOUTH CENTRAL | BAY HILL | 2 | K77 | 4.9 |
| SOUTH CENTRAL | BAY HILL | 3 | K79 | 8.8 |
| SOUTH CENTRAL | BOGGY MARSH | 2 | K957 | 8.1 |
| SOUTH CENTRAL | BOGGY MARSH | 1 | K958 | 8.0 |
| SOUTH CENTRAL | BOGGY MARSH | 1 | K959 | 9.8 |
| SOUTH CENTRAL | BOGGY MARSH | 2 | K960 | 10.8 |
| SOUTH CENTRAL | BOGGY MARSH | 2 | K961 | 10.0 |
| SOUTH CENTRAL | BOGGY MARSH | 1 | K964 | 9.9 |
| SOUTH CENTRAL | BONNET CREEK | 2 | K1230 | 2.1 |

| | | | | |
|---------------|----------------|---|-------|------|
| SOUTH CENTRAL | BONNET CREEK | 2 | K1231 | 7.5 |
| SOUTH CENTRAL | BONNET CREEK | 2 | K1232 | 4.8 |
| SOUTH CENTRAL | BONNET CREEK | 2 | K1234 | 4.2 |
| SOUTH CENTRAL | BONNET CREEK | 1 | K973 | 2.7 |
| SOUTH CENTRAL | BONNET CREEK | 1 | K974 | 4.8 |
| SOUTH CENTRAL | BONNET CREEK | 1 | K975 | 5.3 |
| SOUTH CENTRAL | BONNET CREEK | 1 | K976 | 6.7 |
| SOUTH CENTRAL | CABBAGE ISLAND | 3 | K1613 | 4.9 |
| SOUTH CENTRAL | CABBAGE ISLAND | 2 | K1614 | 6.8 |
| SOUTH CENTRAL | CABBAGE ISLAND | 3 | K1615 | 1.9 |
| SOUTH CENTRAL | CABBAGE ISLAND | 2 | K1616 | 8.8 |
| SOUTH CENTRAL | CABBAGE ISLAND | 2 | K1618 | 6.9 |
| SOUTH CENTRAL | CANOE CREEK | 1 | W0105 | 3.2 |
| SOUTH CENTRAL | CELEBRATION | 2 | K2701 | 8.8 |
| SOUTH CENTRAL | CELEBRATION | 3 | K2703 | 7.0 |
| SOUTH CENTRAL | CELEBRATION | 2 | K2704 | 4.1 |
| SOUTH CENTRAL | CELEBRATION | 3 | K2706 | 9.7 |
| SOUTH CENTRAL | CENTRAL PARK | 1 | K0495 | 12.0 |
| SOUTH CENTRAL | CENTRAL PARK | 2 | K499 | 4.4 |
| SOUTH CENTRAL | CENTRAL PARK | 3 | K800 | 6.6 |
| SOUTH CENTRAL | CENTRAL PARK | 1 | W0493 | 8.3 |
| SOUTH CENTRAL | CENTRAL PARK | 1 | W0494 | 4.5 |
| SOUTH CENTRAL | CENTRAL PARK | 2 | W0496 | 5.1 |
| SOUTH CENTRAL | CENTRAL PARK | 2 | W0497 | 8.8 |
| SOUTH CENTRAL | CENTRAL PARK | 2 | W0498 | 5.2 |
| SOUTH CENTRAL | CENTRAL PARK | 3 | W0500 | 8.2 |
| SOUTH CENTRAL | CENTRAL PARK | 3 | W0501 | 6.0 |
| SOUTH CENTRAL | CHAMPIONS GATE | 2 | K1761 | 7.1 |
| SOUTH CENTRAL | CHAMPIONS GATE | 1 | K1762 | 12.0 |
| SOUTH CENTRAL | CHAMPIONS GATE | 2 | K1763 | 7.7 |
| SOUTH CENTRAL | CHAMPIONS GATE | 1 | K1764 | 9.5 |
| SOUTH CENTRAL | CITRUSVILLE | 1 | K0035 | 5.1 |
| SOUTH CENTRAL | CITRUSVILLE | 1 | K0061 | 1.3 |
| SOUTH CENTRAL | CITRUSVILLE | 1 | K0062 | 8.0 |
| SOUTH CENTRAL | CLARCONA | 1 | M0337 | 11.3 |
| SOUTH CENTRAL | CLARCONA | 2 | M0339 | 3.2 |
| SOUTH CENTRAL | CLARCONA | 2 | M0340 | 5.9 |
| SOUTH CENTRAL | CLARCONA | 3 | M0342 | 8.2 |
| SOUTH CENTRAL | CLARCONA | 1 | M0343 | 10.3 |
| SOUTH CENTRAL | CLARCONA | 2 | M0345 | 11.1 |
| SOUTH CENTRAL | CLARCONA | 2 | M0346 | 9.9 |
| SOUTH CENTRAL | CLARCONA | 3 | M0348 | 6.5 |
| SOUTH CENTRAL | CLARCONA | 3 | M0351 | 7.0 |
| SOUTH CENTRAL | CLERMONT | 1 | K601 | 10.7 |
| SOUTH CENTRAL | CLERMONT | 1 | K602 | 9.6 |
| SOUTH CENTRAL | CLERMONT | 1 | K603 | 9.8 |
| SOUTH CENTRAL | CLERMONT | 2 | K605 | 7.1 |
| SOUTH CENTRAL | CLERMONT | 2 | K606 | 10.4 |

| | | | | |
|---------------|------------------|---|-------|------|
| SOUTH CENTRAL | CLERMONT | 2 | K607 | 8.4 |
| SOUTH CENTRAL | COLONIAL | 1 | K2476 | 10.7 |
| SOUTH CENTRAL | COLONIAL | 1 | K2477 | 8.4 |
| SOUTH CENTRAL | CONWAY | 2 | W0404 | 8.3 |
| SOUTH CENTRAL | CONWAY | 2 | W0405 | 8.1 |
| SOUTH CENTRAL | CONWAY | 1 | W0407 | 6.8 |
| SOUTH CENTRAL | CONWAY | 1 | W0408 | 9.6 |
| SOUTH CENTRAL | COUNTRY OAKS | 1 | K1443 | 4.3 |
| SOUTH CENTRAL | COUNTRY OAKS | 1 | K1446 | 1.9 |
| SOUTH CENTRAL | COUNTRY OAKS | 2 | K1447 | 8.6 |
| SOUTH CENTRAL | CROOKED LAKE | 1 | K1771 | 5.2 |
| SOUTH CENTRAL | CROOKED LAKE | 1 | K1772 | 4.0 |
| SOUTH CENTRAL | CROWN POINT | 1 | K278 | 9.7 |
| SOUTH CENTRAL | CROWN POINT | 1 | K279 | 8.2 |
| SOUTH CENTRAL | CURRY FORD | 1 | W0595 | 8.9 |
| SOUTH CENTRAL | CURRY FORD | 1 | W0597 | 9.3 |
| SOUTH CENTRAL | CURRY FORD | 1 | W0601 | 12.6 |
| SOUTH CENTRAL | CURRY FORD | 2 | W596 | 8.9 |
| SOUTH CENTRAL | CURRY FORD | 2 | W598 | 7.8 |
| SOUTH CENTRAL | CYPRESSWOOD | 1 | K0317 | 3.7 |
| SOUTH CENTRAL | CYPRESSWOOD | 2 | K0561 | 4.0 |
| SOUTH CENTRAL | CYPRESSWOOD | 2 | K0562 | 11.2 |
| SOUTH CENTRAL | CYPRESSWOOD | 1 | K0563 | 5.3 |
| SOUTH CENTRAL | DAVENPORT | 1 | K0007 | 12.7 |
| SOUTH CENTRAL | DAVENPORT | 1 | K0008 | 5.2 |
| SOUTH CENTRAL | DAVENPORT | 1 | K0009 | 7.6 |
| SOUTH CENTRAL | DESOTO CITY | 1 | K3220 | 6.1 |
| SOUTH CENTRAL | DESOTO CITY | 1 | K3221 | 1.2 |
| SOUTH CENTRAL | DESOTO CITY | 2 | K3222 | 1.9 |
| SOUTH CENTRAL | DINNER LAKE | 2 | K1684 | 1.6 |
| SOUTH CENTRAL | DINNER LAKE | 2 | K1685 | 7.2 |
| SOUTH CENTRAL | DINNER LAKE | 2 | K1687 | 2.4 |
| SOUTH CENTRAL | DINNER LAKE | 2 | K1688 | 4.3 |
| SOUTH CENTRAL | DINNER LAKE | 2 | K1689 | 5.3 |
| SOUTH CENTRAL | DINNER LAKE | 1 | K1690 | 6.8 |
| SOUTH CENTRAL | DINNER LAKE | 1 | K1691 | 8.0 |
| SOUTH CENTRAL | DUNDEE | 2 | K3244 | 7.9 |
| SOUTH CENTRAL | DUNDEE | 2 | K3245 | 7.7 |
| SOUTH CENTRAL | DUNDEE | 2 | K3246 | 1.8 |
| SOUTH CENTRAL | EAST LAKE WALES | 1 | K1030 | 6.8 |
| SOUTH CENTRAL | EAST LAKE WALES | 2 | K1031 | 3.1 |
| SOUTH CENTRAL | EAST LAKE WALES | 1 | K1032 | 4.9 |
| SOUTH CENTRAL | FISHEATING CREEK | 1 | K1560 | 9.5 |
| SOUTH CENTRAL | FORT MEADE | 3 | K0170 | 0.1 |
| SOUTH CENTRAL | FORT MEADE | 3 | K0171 | 2.3 |
| SOUTH CENTRAL | FOUR CORNERS | 1 | K1404 | 11.1 |
| SOUTH CENTRAL | FOUR CORNERS | 2 | K1406 | 5.5 |
| SOUTH CENTRAL | FOUR CORNERS | 1 | K1407 | 5.5 |

| | | | | |
|---------------|---------------------|---|-------|------|
| SOUTH CENTRAL | FOUR CORNERS | 2 | K1409 | 3.4 |
| SOUTH CENTRAL | FOUR CORNERS | 3 | K1411 | 6.3 |
| SOUTH CENTRAL | FOUR CORNERS | 3 | K1414 | 5.6 |
| SOUTH CENTRAL | FOUR CORNERS | 3 | K1416 | 11.7 |
| SOUTH CENTRAL | FROSTPROOF | 1 | K0100 | 5.7 |
| SOUTH CENTRAL | FROSTPROOF | 1 | K0101 | 5.6 |
| SOUTH CENTRAL | FROSTPROOF | 1 | K0102 | 5.9 |
| SOUTH CENTRAL | FROSTPROOF | 2 | K0103 | 1.8 |
| SOUTH CENTRAL | FROSTPROOF | 2 | K0104 | 5.0 |
| SOUTH CENTRAL | GROVELAND | 1 | K673 | 7.1 |
| SOUTH CENTRAL | GROVELAND | 1 | K674 | 11.4 |
| SOUTH CENTRAL | GROVELAND | 2 | K675 | 5.9 |
| SOUTH CENTRAL | HAINES CITY | 2 | K0016 | 3.4 |
| SOUTH CENTRAL | HAINES CITY | 2 | K0017 | 9.4 |
| SOUTH CENTRAL | HAINES CITY | 1 | K0018 | 11.7 |
| SOUTH CENTRAL | HAINES CITY | 1 | K0019 | 5.7 |
| SOUTH CENTRAL | HAINES CITY | 2 | K0020 | 6.3 |
| SOUTH CENTRAL | HAINES CITY | 1 | K0021 | 9.4 |
| SOUTH CENTRAL | HAINES CITY | 1 | K0022 | 9.4 |
| SOUTH CENTRAL | HEMPLE | 2 | K2244 | 9.2 |
| SOUTH CENTRAL | HEMPLE | 3 | K2246 | 9.1 |
| SOUTH CENTRAL | HEMPLE | 2 | K2247 | 7.7 |
| SOUTH CENTRAL | HEMPLE | 3 | K2249 | 7.0 |
| SOUTH CENTRAL | HEMPLE | 1 | K2250 | 9.5 |
| SOUTH CENTRAL | HEMPLE | 2 | K2252 | 4.6 |
| SOUTH CENTRAL | HEMPLE | 3 | K2253 | 9.0 |
| SOUTH CENTRAL | HEMPLE | 1 | K2255 | 10.2 |
| SOUTH CENTRAL | HOLOPAW | 2 | W0629 | 7.3 |
| SOUTH CENTRAL | HOLOPAW | 1 | W0630 | 5.3 |
| SOUTH CENTRAL | HOWEY | 1 | K564 | 3.5 |
| SOUTH CENTRAL | HOWEY | 1 | K565 | 6.5 |
| SOUTH CENTRAL | HUNTERS CREEK | 1 | K40 | 11.4 |
| SOUTH CENTRAL | HUNTERS CREEK | 2 | K42 | 4.9 |
| SOUTH CENTRAL | HUNTERS CREEK | 2 | K43 | 9.7 |
| SOUTH CENTRAL | HUNTERS CREEK | 3 | K45 | 10.3 |
| SOUTH CENTRAL | HUNTERS CREEK | 3 | K48 | 7.0 |
| SOUTH CENTRAL | HUNTERS CREEK | 3 | K49 | 12.9 |
| SOUTH CENTRAL | HUNTERS CREEK | 1 | K51 | 8.7 |
| SOUTH CENTRAL | INTERCESSION CITY | 1 | K0966 | 2.3 |
| SOUTH CENTRAL | INTERCESSION CITY | 1 | K0967 | 6.7 |
| SOUTH CENTRAL | INTERNATIONAL DRIVE | 3 | K4815 | 7.5 |
| SOUTH CENTRAL | INTERNATIONAL DRIVE | 2 | K4817 | 6.1 |
| SOUTH CENTRAL | INTERNATIONAL DRIVE | 3 | K4818 | 7.6 |
| SOUTH CENTRAL | INTERNATIONAL DRIVE | 2 | K4820 | 6.3 |
| SOUTH CENTRAL | ISLEWORTH | 1 | K773 | 7.5 |
| SOUTH CENTRAL | ISLEWORTH | 2 | K779 | 10.4 |
| SOUTH CENTRAL | ISLEWORTH | 3 | K781 | 9.7 |
| SOUTH CENTRAL | ISLEWORTH | 3 | K782 | 11.6 |

| | | | | |
|---------------|-------------------|---|-------|------|
| SOUTH CENTRAL | ISLEWORTH | 2 | K784 | 3.3 |
| SOUTH CENTRAL | ISLEWORTH | 3 | K789 | 12.0 |
| SOUTH CENTRAL | ISLEWORTH | 2 | K792 | 10.5 |
| SOUTH CENTRAL | LAKE BRYAN | 3 | K230 | 4.7 |
| SOUTH CENTRAL | LAKE BRYAN | 3 | K231 | 5.5 |
| SOUTH CENTRAL | LAKE BRYAN | 3 | K232 | 6.0 |
| SOUTH CENTRAL | LAKE BRYAN | 2 | K238 | 8.4 |
| SOUTH CENTRAL | LAKE BRYAN | 2 | K239 | 8.0 |
| SOUTH CENTRAL | LAKE BRYAN | 1 | K240 | 2.2 |
| SOUTH CENTRAL | LAKE BRYAN | 1 | K242 | 2.3 |
| SOUTH CENTRAL | LAKE BRYAN | 2 | K244 | 9.9 |
| SOUTH CENTRAL | LAKE LUNTZ | 1 | K3282 | 10.9 |
| SOUTH CENTRAL | LAKE LUNTZ | 2 | K3283 | 9.9 |
| SOUTH CENTRAL | LAKE LUNTZ | 1 | K3284 | 11.8 |
| SOUTH CENTRAL | LAKE LUNTZ | 2 | K3285 | 11.3 |
| SOUTH CENTRAL | LAKE LUNTZ | 2 | K3286 | 9.8 |
| SOUTH CENTRAL | LAKE LUNTZ | 1 | K3287 | 7.1 |
| SOUTH CENTRAL | LAKE MARION | 1 | K1286 | 9.9 |
| SOUTH CENTRAL | LAKE MARION | 2 | K1287 | 12.4 |
| SOUTH CENTRAL | LAKE MARION | 1 | K1288 | 5.7 |
| SOUTH CENTRAL | LAKE OF THE HILLS | 1 | K1884 | 7.0 |
| SOUTH CENTRAL | LAKE OF THE HILLS | 1 | K1885 | 4.8 |
| SOUTH CENTRAL | LAKE PLACID | 1 | K0757 | 3.5 |
| SOUTH CENTRAL | LAKE PLACID | 1 | K0758 | 4.8 |
| SOUTH CENTRAL | LAKE PLACID | 2 | K1066 | 7.1 |
| SOUTH CENTRAL | LAKE PLACID | 2 | K1320 | 5.8 |
| SOUTH CENTRAL | LAKE PLACID NORTH | 1 | K0024 | 3.8 |
| SOUTH CENTRAL | LAKE PLACID NORTH | 2 | K0027 | 2.3 |
| SOUTH CENTRAL | LAKE WALES | 1 | K0053 | 5.4 |
| SOUTH CENTRAL | LAKE WALES | 1 | K0054 | 7.7 |
| SOUTH CENTRAL | LAKE WALES | 1 | K0055 | 7.2 |
| SOUTH CENTRAL | LAKE WALES | 2 | K0056 | 2.6 |
| SOUTH CENTRAL | LAKE WALES | 2 | K0057 | 5.1 |
| SOUTH CENTRAL | LAKE WALES | 2 | K0058 | 7.0 |
| SOUTH CENTRAL | LAKE WILSON | 1 | K881 | 9.8 |
| SOUTH CENTRAL | LAKE WILSON | 1 | K882 | 7.4 |
| SOUTH CENTRAL | LAKE WILSON | 2 | K883 | 8.4 |
| SOUTH CENTRAL | LAKE WILSON | 2 | K884 | 7.3 |
| SOUTH CENTRAL | LAKESWOOD | 1 | K1693 | 7.0 |
| SOUTH CENTRAL | LAKESWOOD | 1 | K1694 | 4.8 |
| SOUTH CENTRAL | LAKESWOOD | 1 | K1695 | 5.6 |
| SOUTH CENTRAL | LAKESWOOD | 2 | K1705 | 5.4 |
| SOUTH CENTRAL | LAKESWOOD | 2 | K1706 | 9.1 |
| SOUTH CENTRAL | LEISURE LAKES | 1 | K1415 | 6.5 |
| SOUTH CENTRAL | LOUGHMAN | 1 | K5078 | 4.5 |
| SOUTH CENTRAL | LOUGHMAN | 1 | K5079 | 8.9 |
| SOUTH CENTRAL | MAGNOLIA RANCH | 2 | W0502 | 13.2 |
| SOUTH CENTRAL | MAGNOLIA RANCH | 2 | W0503 | 5.8 |

| | | | | |
|---------------|--------------------|---|-------|------|
| SOUTH CENTRAL | MAGNOLIA RANCH | 1 | W0504 | 9.4 |
| SOUTH CENTRAL | MARLEY ROAD | 1 | K0120 | 5.2 |
| SOUTH CENTRAL | MEADOW WOODS EAST | 1 | K1060 | 9.8 |
| SOUTH CENTRAL | MEADOW WOODS EAST | 1 | K1061 | 9.9 |
| SOUTH CENTRAL | MEADOW WOODS EAST | 2 | K1063 | 8.6 |
| SOUTH CENTRAL | MEADOW WOODS SOUTH | 2 | K1775 | 8.8 |
| SOUTH CENTRAL | MEADOW WOODS SOUTH | 3 | K1777 | 10.3 |
| SOUTH CENTRAL | MEADOW WOODS SOUTH | 2 | K1778 | 8.1 |
| SOUTH CENTRAL | MEADOW WOODS SOUTH | 3 | K1780 | 8.6 |
| SOUTH CENTRAL | MEADOW WOODS SOUTH | 2 | K1781 | 9.0 |
| SOUTH CENTRAL | MEADOW WOODS SOUTH | 1 | K1783 | 6.6 |
| SOUTH CENTRAL | MEADOW WOODS SOUTH | 1 | K1789 | 2.5 |
| SOUTH CENTRAL | MIDWAY | 1 | K1472 | 7.7 |
| SOUTH CENTRAL | MIDWAY | 1 | K1473 | 9.6 |
| SOUTH CENTRAL | MIDWAY | 1 | K1475 | 9.4 |
| SOUTH CENTRAL | MINNEOLA | 1 | K946 | 6.3 |
| SOUTH CENTRAL | MINNEOLA | 2 | K948 | 7.4 |
| SOUTH CENTRAL | MINNEOLA | 1 | K949 | 7.9 |
| SOUTH CENTRAL | MONTVERDE | 1 | K4831 | 9.4 |
| SOUTH CENTRAL | MONTVERDE | 2 | K4833 | 6.1 |
| SOUTH CENTRAL | MONTVERDE | 1 | K4834 | 7.2 |
| SOUTH CENTRAL | MONTVERDE | 2 | K4836 | 7.9 |
| SOUTH CENTRAL | MONTVERDE | 1 | K4837 | 8.3 |
| SOUTH CENTRAL | MONTVERDE | 2 | K4840 | 10.4 |
| SOUTH CENTRAL | MONTVERDE | 1 | K4841 | 11.0 |
| SOUTH CENTRAL | MONTVERDE | 2 | K4845 | 7.1 |
| SOUTH CENTRAL | NARCOOSSEE | 1 | W0212 | 9.4 |
| SOUTH CENTRAL | NARCOOSSEE | 1 | W0213 | 8.1 |
| SOUTH CENTRAL | NARCOOSSEE | 1 | W0214 | 7.4 |
| SOUTH CENTRAL | NARCOOSSEE | 2 | W0215 | 6.6 |
| SOUTH CENTRAL | NARCOOSSEE | 2 | W0216 | 8.6 |
| SOUTH CENTRAL | NARCOOSSEE | 2 | W0217 | 9.0 |
| SOUTH CENTRAL | NARCOOSSEE | 3 | W0219 | 7.6 |
| SOUTH CENTRAL | NARCOOSSEE | 3 | W0220 | 8.5 |
| SOUTH CENTRAL | NORTHRIDGE | 1 | K1822 | 9.1 |
| SOUTH CENTRAL | NORTHRIDGE | 1 | K1825 | 6.5 |
| SOUTH CENTRAL | OCOEE | 3 | M1086 | 4.9 |
| SOUTH CENTRAL | OCOEE | 3 | M1087 | 6.6 |
| SOUTH CENTRAL | OCOEE | 3 | M1088 | 3.8 |
| SOUTH CENTRAL | OCOEE | 1 | M1090 | 8.1 |
| SOUTH CENTRAL | OCOEE | 1 | M1091 | 5.4 |
| SOUTH CENTRAL | OCOEE | 1 | M1092 | 7.2 |
| SOUTH CENTRAL | OCOEE | 2 | M1094 | 6.8 |
| SOUTH CENTRAL | OCOEE | 2 | M1095 | 4.6 |
| SOUTH CENTRAL | OCOEE | 2 | M1096 | 8.0 |
| SOUTH CENTRAL | OKAHUMPKA | 1 | K284 | 8.6 |
| SOUTH CENTRAL | OKAHUMPKA | 2 | K285 | 6.3 |
| SOUTH CENTRAL | OKAHUMPKA | 2 | K286 | 1.8 |

| | | | | |
|---------------|-----------------|---|-------|------|
| SOUTH CENTRAL | ORANGEWOOD | 1 | K217 | 3.5 |
| SOUTH CENTRAL | ORANGEWOOD | 2 | K218 | 2.8 |
| SOUTH CENTRAL | ORANGEWOOD | 1 | K220 | 1.8 |
| SOUTH CENTRAL | ORANGEWOOD | 1 | K221 | 6.6 |
| SOUTH CENTRAL | ORANGEWOOD | 1 | K222 | 7.5 |
| SOUTH CENTRAL | ORANGEWOOD | 1 | K223 | 2.7 |
| SOUTH CENTRAL | ORANGEWOOD | 1 | K224 | 3.2 |
| SOUTH CENTRAL | ORANGEWOOD | 2 | K225 | 3.9 |
| SOUTH CENTRAL | ORANGEWOOD | 2 | K226 | 6.9 |
| SOUTH CENTRAL | ORANGEWOOD | 2 | K227 | 1.9 |
| SOUTH CENTRAL | ORANGEWOOD | 2 | K228 | 7.0 |
| SOUTH CENTRAL | ORANGEWOOD | 2 | K229 | 1.8 |
| SOUTH CENTRAL | PARKWAY | 1 | K408 | 7.7 |
| SOUTH CENTRAL | PARKWAY | 1 | K409 | 3.6 |
| SOUTH CENTRAL | PINECASTLE | 2 | K0396 | 8.7 |
| SOUTH CENTRAL | PINECASTLE | 1 | W0391 | 6.9 |
| SOUTH CENTRAL | PINECASTLE | 1 | W0392 | 11.2 |
| SOUTH CENTRAL | PINECASTLE | 2 | W0395 | 11.8 |
| SOUTH CENTRAL | POINCIANA | 1 | K1236 | 10.6 |
| SOUTH CENTRAL | POINCIANA | 1 | K1237 | 6.6 |
| SOUTH CENTRAL | POINCIANA | 2 | K1508 | 4.9 |
| SOUTH CENTRAL | POINCIANA | 2 | K1509 | 6.5 |
| SOUTH CENTRAL | POINCIANA | 2 | K1556 | 10.4 |
| SOUTH CENTRAL | POINCIANA | 1 | K1558 | 10.1 |
| SOUTH CENTRAL | POINCIANA | 2 | K1561 | 8.5 |
| SOUTH CENTRAL | POINCIANA | 1 | K1562 | 9.4 |
| SOUTH CENTRAL | POINCIANA NORTH | 3 | K629 | 6.8 |
| SOUTH CENTRAL | POINCIANA NORTH | 3 | K631 | 10.5 |
| SOUTH CENTRAL | REEDY LAKE | 2 | K1102 | 8.5 |
| SOUTH CENTRAL | REEDY LAKE | 1 | K1104 | 9.8 |
| SOUTH CENTRAL | REEDY LAKE | 2 | K1108 | 10.0 |
| SOUTH CENTRAL | REEDY LAKE | 1 | K1110 | 10.0 |
| SOUTH CENTRAL | REEDY LAKE | 1 | K1111 | 11.4 |
| SOUTH CENTRAL | RIO PINAR | 1 | W0968 | 9.9 |
| SOUTH CENTRAL | RIO PINAR | 1 | W0969 | 5.8 |
| SOUTH CENTRAL | RIO PINAR | 1 | W0970 | 12.4 |
| SOUTH CENTRAL | RIO PINAR | 4 | W0971 | 4.6 |
| SOUTH CENTRAL | RIO PINAR | 4 | W0972 | 11.2 |
| SOUTH CENTRAL | RIO PINAR | 4 | W0973 | 9.9 |
| SOUTH CENTRAL | RIO PINAR | 4 | W0974 | 11.1 |
| SOUTH CENTRAL | RIO PINAR | 1 | W0975 | 8.8 |
| SOUTH CENTRAL | SAND LAKE | 1 | K920 | 4.2 |
| SOUTH CENTRAL | SAND LAKE | 2 | K922 | 6.8 |
| SOUTH CENTRAL | SAND LAKE | 2 | K923 | 2.3 |
| SOUTH CENTRAL | SAND LAKE | 1 | K925 | 3.8 |
| SOUTH CENTRAL | SAND LAKE | 1 | K926 | 3.6 |
| SOUTH CENTRAL | SAND LAKE | 2 | K928 | 5.8 |
| SOUTH CENTRAL | SAND LAKE | 2 | K929 | 4.7 |

| | | | | |
|---------------|---------------|---|-------|------|
| SOUTH CENTRAL | SAND LAKE | 1 | K931 | 5.2 |
| SOUTH CENTRAL | SAND LAKE | 1 | K932 | 3.6 |
| SOUTH CENTRAL | SAND LAKE | 2 | K934 | 8.3 |
| SOUTH CENTRAL | SAND MOUNTAIN | 1 | K3201 | 0.3 |
| SOUTH CENTRAL | SEBRING EAST | 1 | K0541 | 2.5 |
| SOUTH CENTRAL | SEBRING EAST | 1 | K0542 | 5.4 |
| SOUTH CENTRAL | SHINGLE CREEK | 2 | K855 | 6.9 |
| SOUTH CENTRAL | SHINGLE CREEK | 1 | K857 | 9.4 |
| SOUTH CENTRAL | SHINGLE CREEK | 2 | K858 | 7.0 |
| SOUTH CENTRAL | SHINGLE CREEK | 1 | K860 | 5.5 |
| SOUTH CENTRAL | SHINGLE CREEK | 1 | K861 | 7.4 |
| SOUTH CENTRAL | SHINGLE CREEK | 2 | K863 | 9.0 |
| SOUTH CENTRAL | SHINGLE CREEK | 2 | K868 | 4.0 |
| SOUTH CENTRAL | SKY LAKE | 1 | W0362 | 7.7 |
| SOUTH CENTRAL | SKY LAKE | 1 | W0363 | 11.2 |
| SOUTH CENTRAL | SKY LAKE | 1 | W0364 | 6.9 |
| SOUTH CENTRAL | SKY LAKE | 2 | W0365 | 8.9 |
| SOUTH CENTRAL | SKY LAKE | 2 | W0366 | 5.7 |
| SOUTH CENTRAL | SKY LAKE | 3 | W0367 | 8.1 |
| SOUTH CENTRAL | SKY LAKE | 3 | W0368 | 6.7 |
| SOUTH CENTRAL | SKY LAKE | 3 | W0369 | 9.2 |
| SOUTH CENTRAL | SOUTH BARTOW | 1 | K0154 | 4.0 |
| SOUTH CENTRAL | SUN'N LAKES | 2 | K1135 | 6.3 |
| SOUTH CENTRAL | SUN'N LAKES | 2 | K1136 | 6.3 |
| SOUTH CENTRAL | SUN'N LAKES | 2 | K1137 | 2.8 |
| SOUTH CENTRAL | SUN'N LAKES | 1 | K1296 | 7.8 |
| SOUTH CENTRAL | SUN'N LAKES | 1 | K1297 | 5.6 |
| SOUTH CENTRAL | SUN'N LAKES | 1 | K1300 | 5.6 |
| SOUTH CENTRAL | TAFT | 2 | K1023 | 7.0 |
| SOUTH CENTRAL | TAFT | 2 | K1024 | 8.5 |
| SOUTH CENTRAL | TAFT | 2 | K1025 | 7.3 |
| SOUTH CENTRAL | TAFT | 1 | K1026 | 7.9 |
| SOUTH CENTRAL | TAFT | 1 | K1027 | 5.1 |
| SOUTH CENTRAL | TAFT | 1 | K1028 | 7.3 |
| SOUTH CENTRAL | TAUNTON ROAD | 1 | K1081 | 5.2 |
| SOUTH CENTRAL | TAUNTON ROAD | 1 | K1083 | 3.2 |
| SOUTH CENTRAL | VINELAND | 1 | K901 | 6.3 |
| SOUTH CENTRAL | VINELAND | 2 | K903 | 10.3 |
| SOUTH CENTRAL | VINELAND | 2 | K904 | 8.6 |
| SOUTH CENTRAL | VINELAND | 3 | K906 | 9.8 |
| SOUTH CENTRAL | VINELAND | 1 | K907 | 4.4 |
| SOUTH CENTRAL | VINELAND | 2 | K909 | 5.2 |
| SOUTH CENTRAL | VINELAND | 2 | K910 | 7.9 |
| SOUTH CENTRAL | VINELAND | 3 | K912 | 3.9 |
| SOUTH CENTRAL | VINELAND | 1 | K913 | 7.5 |
| SOUTH CENTRAL | VINELAND | 3 | K915 | 5.8 |
| SOUTH CENTRAL | VINELAND | 1 | K917 | 8.1 |
| SOUTH CENTRAL | WAUCHULA | 1 | K0245 | 3.1 |

| | | | | |
|---------------|-----------------|---|-------|------|
| SOUTH CENTRAL | WAUCHULA | 2 | K0246 | 3.2 |
| SOUTH CENTRAL | WEST DAVENPORT | 2 | K1521 | 8.6 |
| SOUTH CENTRAL | WEST DAVENPORT | 1 | K1523 | 7.5 |
| SOUTH CENTRAL | WEST DAVENPORT | 1 | K1524 | 5.3 |
| SOUTH CENTRAL | WEST DAVENPORT | 2 | K1526 | 6.8 |
| SOUTH CENTRAL | WEST DAVENPORT | 1 | K1529 | 8.0 |
| SOUTH CENTRAL | WEST LAKE WALES | 2 | K0866 | 5.1 |
| SOUTH CENTRAL | WESTRIDGE | 1 | K0420 | 8.2 |
| SOUTH CENTRAL | WESTRIDGE | 2 | K0421 | 8.6 |
| SOUTH CENTRAL | WESTRIDGE | 1 | K0425 | 9.7 |
| SOUTH CENTRAL | WESTRIDGE | 2 | K0426 | 12.9 |
| SOUTH CENTRAL | WESTRIDGE | 2 | K0428 | 4.6 |
| SOUTH CENTRAL | WEWAHOOTEE | 1 | W1198 | 0.3 |
| SOUTH CENTRAL | WINDERMERE | 3 | K302 | 6.9 |
| SOUTH CENTRAL | WINDERMERE | 1 | K303 | 8.6 |
| SOUTH CENTRAL | WINDERMERE | 1 | K304 | 5.9 |
| SOUTH CENTRAL | WINTER GARDEN | 2 | K201 | 11.4 |
| SOUTH CENTRAL | WINTER GARDEN | 2 | K202 | 8.4 |
| SOUTH CENTRAL | WINTER GARDEN | 2 | K203 | 6.0 |
| SOUTH CENTRAL | WINTER GARDEN | 1 | K204 | 10.8 |
| SOUTH CENTRAL | WINTER GARDEN | 1 | K205 | 11.5 |
| SOUTH CENTRAL | WINTER GARDEN | 1 | K206 | 9.6 |
| SOUTH CENTRAL | WINTER GARDEN | 1 | K207 | 10.2 |
| SOUTH CENTRAL | WOODSMERE | 3 | M0252 | 8.5 |
| SOUTH CENTRAL | WOODSMERE | 3 | M0253 | 2.5 |
| SOUTH CENTRAL | WOODSMERE | 3 | M0254 | 6.0 |
| SOUTH CENTRAL | WOODSMERE | 4 | M0255 | 6.4 |
| SOUTH CENTRAL | WOODSMERE | 4 | M0256 | 8.3 |
| SOUTH CENTRAL | WORLD GATEWAY | 1 | K187 | 8.0 |
| SOUTH CENTRAL | WORLD GATEWAY | 1 | K189 | 5.6 |
| SOUTH CENTRAL | LOUGHMAN | 1 | K5086 | 7.4 |
| SOUTH CENTRAL | WEST LAKE WALES | 2 | K871 | 2.2 |
| NORTH COASTAL | ADAMS | 1 | A0199 | 5.0 |
| NORTH COASTAL | ADAMS | 1 | A0200 | 3.2 |
| NORTH COASTAL | ALACHUA | 1 | A0143 | 1.0 |
| NORTH COASTAL | ALACHUA | 1 | A0144 | 0.3 |
| NORTH COASTAL | APALACHICOLA | 1 | N58 | 5.2 |
| NORTH COASTAL | APALACHICOLA | 1 | N59 | 6.0 |
| NORTH COASTAL | ARCHER | 1 | A0195 | 2.2 |
| NORTH COASTAL | ARCHER | 2 | A0196 | 3.0 |
| NORTH COASTAL | BEACON HILL | 2 | N515 | 1.5 |
| NORTH COASTAL | BEACON HILL | 1 | N516 | 3.3 |
| NORTH COASTAL | BEACON HILL | 2 | N527 | 4.7 |
| NORTH COASTAL | BELLEVIEW | 1 | A0001 | 5.5 |
| NORTH COASTAL | BELLEVIEW | 2 | A0002 | 7.5 |
| NORTH COASTAL | BELLEVIEW | 1 | A0003 | 1.9 |
| NORTH COASTAL | BELLEVIEW | 2 | A0004 | 7.1 |
| NORTH COASTAL | BELLEVIEW | 2 | A0006 | 10.2 |

| | | | | |
|---------------|-----------------------|---|-------|------|
| NORTH COASTAL | BELLEVIEW | 1 | A0012 | 3.4 |
| NORTH COASTAL | BELLEVIEW | 2 | A0014 | 10.9 |
| NORTH COASTAL | BEVERLY HILLS | 2 | A0072 | 6.3 |
| NORTH COASTAL | BEVERLY HILLS | 2 | A0073 | 4.7 |
| NORTH COASTAL | BEVERLY HILLS | 1 | A0074 | 7.1 |
| NORTH COASTAL | BEVERLY HILLS | 1 | A0075 | 7.2 |
| NORTH COASTAL | BEVILLES CORNER | 1 | A0561 | 2.0 |
| NORTH COASTAL | BEVILLES CORNER | 1 | A0562 | 3.6 |
| NORTH COASTAL | BROOKSVILLE | 3 | A0095 | 6.9 |
| NORTH COASTAL | BROOKSVILLE | 3 | A0096 | 8.6 |
| NORTH COASTAL | BROOKSVILLE | 2 | A0097 | 5.4 |
| NORTH COASTAL | BROOKSVILLE | 2 | A0098 | 5.8 |
| NORTH COASTAL | BUSHNELL EAST | 1 | A170 | 10.3 |
| NORTH COASTAL | BUSHNELL EAST | 1 | A171 | 3.7 |
| NORTH COASTAL | CARRABELLE | 1 | N42 | 2.2 |
| NORTH COASTAL | CARRABELLE | 1 | N43 | 6.9 |
| NORTH COASTAL | CARRABELLE BEACH | 1 | N48 | 2.6 |
| NORTH COASTAL | CIRCLE SQUARE | 2 | A0250 | 6.3 |
| NORTH COASTAL | CIRCLE SQUARE | 1 | A0251 | 7.7 |
| NORTH COASTAL | CIRCLE SQUARE | 1 | A0253 | 5.2 |
| NORTH COASTAL | CITRUS HILLS | 2 | A0282 | 6.7 |
| NORTH COASTAL | CITRUS HILLS | 3 | A0283 | 5.6 |
| NORTH COASTAL | CITRUS HILLS | 2 | A0284 | 8.2 |
| NORTH COASTAL | CITRUS HILLS | 3 | A0285 | 4.2 |
| NORTH COASTAL | CITRUS HILLS | 2 | A0286 | 6.2 |
| NORTH COASTAL | COLEMAN | 1 | A0105 | 4.0 |
| NORTH COASTAL | COLEMAN | 2 | A0107 | 3.3 |
| NORTH COASTAL | COLEMAN | 2 | A0108 | 5.5 |
| NORTH COASTAL | CRAWFORDVILLE | 3 | N35 | 6.5 |
| NORTH COASTAL | CRAWFORDVILLE | 2 | N36 | 5.1 |
| NORTH COASTAL | CROSS CITY | 2 | A0115 | 2.8 |
| NORTH COASTAL | CROSS CITY | 2 | A0118 | 3.4 |
| NORTH COASTAL | CROSS CITY | 1 | A0119 | 8.0 |
| NORTH COASTAL | CROSS CITY INDUSTRIAL | 1 | A0046 | 5.0 |
| NORTH COASTAL | CRYSTAL RIVER NORTH | 1 | A0161 | 7.4 |
| NORTH COASTAL | CRYSTAL RIVER NORTH | 1 | A0162 | 6.4 |
| NORTH COASTAL | CRYSTAL RIVER SOUTH | 1 | A0159 | 5.2 |
| NORTH COASTAL | DUNNELLON TOWN | 2 | A0068 | 7.8 |
| NORTH COASTAL | DUNNELLON TOWN | 2 | A0069 | 5.6 |
| NORTH COASTAL | DUNNELLON TOWN | 1 | A0070 | 6.1 |
| NORTH COASTAL | DUNNELLON TOWN | 1 | A0071 | 5.7 |
| NORTH COASTAL | EAGLES NEST | 2 | A0224 | 6.2 |
| NORTH COASTAL | EAGLES NEST | 1 | A0228 | 6.3 |
| NORTH COASTAL | EAST POINT | 1 | N230 | 2.8 |
| NORTH COASTAL | EAST POINT | 1 | N231 | 4.9 |
| NORTH COASTAL | FLORAL CITY | 1 | A0087 | 4.1 |
| NORTH COASTAL | FLORAL CITY | 1 | A0088 | 2.0 |
| NORTH COASTAL | FORT WHITE | 2 | A0020 | 4.2 |

| | | | | |
|---------------|------------------|---|-------|------|
| NORTH COASTAL | G.E. ALACHUA | 1 | A0185 | 0.6 |
| NORTH COASTAL | G.E. ALACHUA | 1 | A0186 | 3.5 |
| NORTH COASTAL | GEORGIA PACIFIC | 1 | A0045 | 6.5 |
| NORTH COASTAL | HERNANDO AIRPORT | 1 | A0430 | 8.7 |
| NORTH COASTAL | HERNANDO AIRPORT | 1 | A0431 | 10.5 |
| NORTH COASTAL | HIGH SPRINGS | 1 | A0015 | 8.1 |
| NORTH COASTAL | HIGH SPRINGS | 2 | A0016 | 5.9 |
| NORTH COASTAL | HOLDER | 1 | A0047 | 6.3 |
| NORTH COASTAL | HOLDER | 2 | A0048 | 6.4 |
| NORTH COASTAL | HOLDER | 1 | A0049 | 4.8 |
| NORTH COASTAL | HOMOSASSA | 3 | A0271 | 7.6 |
| NORTH COASTAL | HOMOSASSA | 3 | A0272 | 7.7 |
| NORTH COASTAL | INDIAN PASS | 1 | N556 | 11.5 |
| NORTH COASTAL | INGLIS | 2 | A0078 | 5.0 |
| NORTH COASTAL | INVERNESS | 1 | A0081 | 6.3 |
| NORTH COASTAL | INVERNESS | 1 | A0082 | 7.5 |
| NORTH COASTAL | INVERNESS | 1 | A0083 | 8.0 |
| NORTH COASTAL | INVERNESS | 2 | A0084 | 8.4 |
| NORTH COASTAL | INVERNESS | 2 | A0085 | 10.0 |
| NORTH COASTAL | JASPER SOUTH | 2 | N191 | 5.0 |
| NORTH COASTAL | JASPER SOUTH | 2 | N192 | 5.0 |
| NORTH COASTAL | JENNINGS | 1 | N195 | 2.4 |
| NORTH COASTAL | LADY LAKE | 1 | A0243 | 8.2 |
| NORTH COASTAL | LADY LAKE | 2 | A0244 | 6.3 |
| NORTH COASTAL | LADY LAKE | 2 | A0245 | 7.1 |
| NORTH COASTAL | LADY LAKE | 1 | A0246 | 9.0 |
| NORTH COASTAL | LAKE WEIR | 1 | A0061 | 5.5 |
| NORTH COASTAL | LAKE WEIR | 2 | A0064 | 7.5 |
| NORTH COASTAL | LEBANON | 1 | A0132 | 5.3 |
| NORTH COASTAL | LURAVILLE | 1 | A0192 | 4.5 |
| NORTH COASTAL | MADISON | 2 | N1 | 4.5 |
| NORTH COASTAL | MADISON | 2 | N2 | 5.8 |
| NORTH COASTAL | MADISON | 1 | N3 | 7.4 |
| NORTH COASTAL | MADISON | 1 | N4 | 3.5 |
| NORTH COASTAL | MARICAMP | 1 | A0333 | 10.9 |
| NORTH COASTAL | MARICAMP | 2 | A0334 | 8.4 |
| NORTH COASTAL | MARICAMP | 1 | A0335 | 7.8 |
| NORTH COASTAL | MARICAMP | 2 | A0336 | 8.2 |
| NORTH COASTAL | MARTIN | 1 | A0038 | 6.5 |
| NORTH COASTAL | MARTIN | 1 | A0039 | 7.2 |
| NORTH COASTAL | MCINTOSH | 1 | A0050 | 3.5 |
| NORTH COASTAL | MCINTOSH | 2 | A0051 | 5.1 |
| NORTH COASTAL | MONTICELLO | 1 | N66 | 3.6 |
| NORTH COASTAL | MONTICELLO | 1 | N67 | 6.4 |
| NORTH COASTAL | MONTICELLO | 2 | N68 | 2.4 |
| NORTH COASTAL | MONTICELLO | 2 | N69 | 6.0 |
| NORTH COASTAL | NEWBERRY | 1 | A0094 | 10.9 |
| NORTH COASTAL | OBRIEN | 1 | A0379 | 4.6 |

| | | | | |
|---------------|-------------------------|---|-------|------|
| NORTH COASTAL | OCHLOCKONEE | 2 | N37 | 4.8 |
| NORTH COASTAL | OCHLOCKONEE | 1 | N38 | 4.6 |
| NORTH COASTAL | ORANGE BLOSSOM | 2 | A0309 | 5.4 |
| NORTH COASTAL | ORANGE BLOSSOM | 1 | A0310 | 8.0 |
| NORTH COASTAL | ORANGE BLOSSOM | 2 | A0388 | 7.4 |
| NORTH COASTAL | ORANGE BLOSSOM | 1 | A0389 | 7.0 |
| NORTH COASTAL | ORANGE BLOSSOM | 1 | A0392 | 7.7 |
| NORTH COASTAL | ORANGE BLOSSOM | 2 | A0394 | 9.1 |
| NORTH COASTAL | PERRY | 2 | N10 | 7.0 |
| NORTH COASTAL | PERRY | 1 | N7 | 5.6 |
| NORTH COASTAL | PERRY | 1 | N8 | 2.3 |
| NORTH COASTAL | PERRY | 2 | N9 | 6.2 |
| NORTH COASTAL | PERRY NORTH | 1 | N14 | 7.4 |
| NORTH COASTAL | PERRY NORTH | 1 | N15 | 8.6 |
| NORTH COASTAL | PINE RIDGE | 1 | A0422 | 7.5 |
| NORTH COASTAL | PINE RIDGE | 1 | A0423 | 7.7 |
| NORTH COASTAL | PINE RIDGE | 1 | A0425 | 5.8 |
| NORTH COASTAL | PORT ST. JOE | 2 | N52 | 3.8 |
| NORTH COASTAL | PORT ST. JOE | 2 | N53 | 5.3 |
| NORTH COASTAL | PORT ST. JOE | 2 | N54 | 4.7 |
| NORTH COASTAL | PORT ST. JOE | 2 | N55 | 0.2 |
| NORTH COASTAL | PORT ST. JOE INDUSTRIAL | 1 | N202 | 4.0 |
| NORTH COASTAL | PORT ST. JOE INDUSTRIAL | 1 | N203 | 1.0 |
| NORTH COASTAL | RAINBOW SPRINGS | 1 | A0368 | 5.6 |
| NORTH COASTAL | RAINBOW SPRINGS | 2 | A0369 | 4.2 |
| NORTH COASTAL | REDDICK | 2 | A0034 | 7.2 |
| NORTH COASTAL | REDDICK | 2 | A0035 | 5.4 |
| NORTH COASTAL | REDDICK | 1 | A0036 | 5.3 |
| NORTH COASTAL | ROSS PRAIRIE | 3 | A0112 | 5.2 |
| NORTH COASTAL | SANTOS | 1 | A0230 | 6.2 |
| NORTH COASTAL | SANTOS | 2 | A0231 | 8.3 |
| NORTH COASTAL | SANTOS | 1 | A0233 | 4.7 |
| NORTH COASTAL | SILVER SPRINGS | 3 | A0153 | 10.5 |
| NORTH COASTAL | SILVER SPRINGS | 3 | A0154 | 6.4 |
| NORTH COASTAL | SILVER SPRINGS SHORES | 2 | A0128 | 5.5 |
| NORTH COASTAL | SILVER SPRINGS SHORES | 1 | A0129 | 13.1 |
| NORTH COASTAL | SILVER SPRINGS SHORES | 1 | A0130 | 6.7 |
| NORTH COASTAL | SILVER SPRINGS SHORES | 2 | A0131 | 10.8 |
| NORTH COASTAL | SOPCHOPPY | 1 | N327 | 5.3 |
| | ST MARKS WEST | 2 | N331 | 4.6 |
| | ST MARKS WEST | 1 | N332 | 7.0 |
| NORTH COASTAL | ST MARKS WEST | 2 | N336 | 3.3 |
| NORTH COASTAL | ST. GEORGE ISLAND | 1 | N233 | 9.4 |
| NORTH COASTAL | ST. GEORGE ISLAND | 1 | N234 | 4.3 |
| NORTH COASTAL | SUWANNEE DISTRIBUTION | 1 | N0324 | 4.0 |
| NORTH COASTAL | SUWANNEE DISTRIBUTION | 4 | N323 | 2.0 |
| NORTH COASTAL | SUWANNEE DISTRIBUTION | 5 | N325 | 5.5 |
| NORTH COASTAL | TANGERINE | 3 | A0262 | 10.7 |

| | | | | |
|---------------|-------------------|---|-------|------|
| NORTH COASTAL | TANGERINE | 3 | A0263 | 4.9 |
| NORTH COASTAL | TANGERINE | 3 | A0264 | 4.4 |
| NORTH COASTAL | TRENTON | 1 | A0090 | 6.3 |
| NORTH COASTAL | TRENTON | 1 | A0091 | 2.0 |
| NORTH COASTAL | TROPIC TERRACE | 2 | A0207 | 7.4 |
| NORTH COASTAL | TROPIC TERRACE | 2 | A0208 | 3.0 |
| NORTH COASTAL | TROPIC TERRACE | 1 | A0212 | 6.8 |
| NORTH COASTAL | TWIN COUNTY RANCH | 1 | A0216 | 5.2 |
| NORTH COASTAL | TWIN COUNTY RANCH | 2 | A0218 | 5.9 |
| NORTH COASTAL | TWIN COUNTY RANCH | 2 | A0219 | 4.3 |
| NORTH COASTAL | TWIN COUNTY RANCH | 1 | A0221 | 5.3 |
| NORTH COASTAL | WAUKEENAH | 1 | N64 | 2.4 |
| NORTH COASTAL | WAUKEENAH | 1 | N65 | 6.8 |
| NORTH COASTAL | WEIRSDALE | 1 | A0321 | 7.6 |
| NORTH COASTAL | WEIRSDALE | 2 | A0322 | 6.0 |
| NORTH COASTAL | WHITE SPRINGS | 2 | N375 | 2.7 |
| NORTH COASTAL | WILDWOOD CITY | 1 | A0395 | 8.5 |
| NORTH COASTAL | WILDWOOD CITY | 2 | A0396 | 6.6 |
| NORTH COASTAL | WILDWOOD CITY | 2 | A0397 | 3.8 |
| NORTH COASTAL | WILDWOOD CITY | 1 | A0398 | 4.5 |
| NORTH COASTAL | WILLISTON | 1 | A0124 | 6.1 |
| NORTH COASTAL | WILLISTON | 2 | A0125 | 9.1 |
| NORTH COASTAL | ZUBER | 1 | A0202 | 8.8 |
| NORTH COASTAL | ZUBER | 1 | A0203 | 5.8 |
| NORTH COASTAL | ZUBER | 2 | A0204 | 7.4 |
| NORTH COASTAL | ZUBER | 2 | A0205 | 5.5 |
| NORTH CENTRAL | ALAFAYA | 2 | W0289 | 9.7 |
| NORTH CENTRAL | ALAFAYA | 2 | W0290 | 8.9 |
| NORTH CENTRAL | ALAFAYA | 3 | W0297 | 10.0 |
| NORTH CENTRAL | ALAFAYA | 3 | W0298 | 9.6 |
| NORTH CENTRAL | ALTAMONTE | 1 | M0571 | 4.7 |
| NORTH CENTRAL | ALTAMONTE | 1 | M0572 | 9.2 |
| NORTH CENTRAL | ALTAMONTE | 1 | M0573 | 4.0 |
| NORTH CENTRAL | ALTAMONTE | 1 | M0574 | 5.1 |
| NORTH CENTRAL | ALTAMONTE | 2 | M0575 | 6.1 |
| NORTH CENTRAL | ALTAMONTE | 2 | M0576 | 8.3 |
| NORTH CENTRAL | ALTAMONTE | 2 | M0578 | 8.9 |
| NORTH CENTRAL | ALTAMONTE | 2 | M0579 | 8.6 |
| NORTH CENTRAL | APOPKA SOUTH | 3 | M0720 | 8.5 |
| NORTH CENTRAL | APOPKA SOUTH | 3 | M0721 | 7.2 |
| NORTH CENTRAL | APOPKA SOUTH | 1 | M0722 | 5.7 |
| NORTH CENTRAL | APOPKA SOUTH | 1 | M0723 | 8.7 |
| NORTH CENTRAL | APOPKA SOUTH | 1 | M0724 | 4.4 |
| NORTH CENTRAL | APOPKA SOUTH | 2 | M0725 | 8.2 |
| NORTH CENTRAL | APOPKA SOUTH | 2 | M0726 | 7.7 |
| NORTH CENTRAL | APOPKA SOUTH | 2 | M0727 | 5.2 |
| NORTH CENTRAL | BARBERVILLE | 1 | W0902 | 6.8 |
| NORTH CENTRAL | BARBERVILLE | 2 | W0903 | 1.8 |

| | | | | |
|---------------|----------------|---|-------|------|
| NORTH CENTRAL | BARBERVILLE | 2 | W0904 | 4.1 |
| NORTH CENTRAL | BAY RIDGE | 2 | M0445 | 3.5 |
| NORTH CENTRAL | BAY RIDGE | 1 | M0447 | 5.3 |
| NORTH CENTRAL | BAY RIDGE | 2 | M0451 | 10.7 |
| NORTH CENTRAL | BAY RIDGE | 1 | M0453 | 6.8 |
| NORTH CENTRAL | BITHLO | 1 | W0951 | 10.0 |
| NORTH CENTRAL | BITHLO | 1 | W0952 | 9.7 |
| NORTH CENTRAL | BITHLO | 1 | W0953 | 9.7 |
| NORTH CENTRAL | BITHLO | 2 | W0954 | 9.4 |
| NORTH CENTRAL | BITHLO | 2 | W0955 | 12.8 |
| NORTH CENTRAL | BITHLO | 2 | W0956 | 9.5 |
| NORTH CENTRAL | CASSADAGA | 3 | W0515 | 7.1 |
| NORTH CENTRAL | CASSADAGA | 3 | W0516 | 7.1 |
| NORTH CENTRAL | CASSADAGA | 3 | W0517 | 5.0 |
| NORTH CENTRAL | CASSADAGA | 2 | W0523 | 4.1 |
| NORTH CENTRAL | CASSADAGA | 2 | W0524 | 8.0 |
| NORTH CENTRAL | CASSELBERRY | 1 | W0017 | 6.6 |
| NORTH CENTRAL | CASSELBERRY | 1 | W0018 | 4.5 |
| NORTH CENTRAL | CASSELBERRY | 1 | W0019 | 8.4 |
| NORTH CENTRAL | CASSELBERRY | 1 | W0020 | 8.4 |
| NORTH CENTRAL | CASSELBERRY | 2 | W0021 | 4.9 |
| NORTH CENTRAL | CASSELBERRY | 2 | W0022 | 9.5 |
| NORTH CENTRAL | CASSELBERRY | 2 | W0025 | 5.6 |
| NORTH CENTRAL | CASSELBERRY | 2 | W0026 | 9.8 |
| NORTH CENTRAL | CASSELBERRY | 3 | W0027 | 11.9 |
| NORTH CENTRAL | CASSELBERRY | 3 | W0028 | 5.2 |
| NORTH CENTRAL | CASSELBERRY | 3 | W0029 | 5.2 |
| NORTH CENTRAL | DELAND | 1 | W0803 | 7.9 |
| NORTH CENTRAL | DELAND | 1 | W0804 | 6.0 |
| NORTH CENTRAL | DELAND | 1 | W0805 | 6.4 |
| NORTH CENTRAL | DELAND | 2 | W0806 | 7.2 |
| NORTH CENTRAL | DELAND | 2 | W0807 | 7.1 |
| NORTH CENTRAL | DELAND | 2 | W0808 | 7.1 |
| NORTH CENTRAL | DELAND | 2 | W0809 | 9.5 |
| NORTH CENTRAL | DELAND EAST | 3 | W1102 | 4.7 |
| NORTH CENTRAL | DELAND EAST | 3 | W1103 | 7.4 |
| NORTH CENTRAL | DELAND EAST | 3 | W1104 | 6.6 |
| NORTH CENTRAL | DELAND EAST | 2 | W1105 | 5.7 |
| NORTH CENTRAL | DELAND EAST | 2 | W1106 | 6.1 |
| NORTH CENTRAL | DELAND EAST | 2 | W1107 | 7.1 |
| NORTH CENTRAL | DELAND EAST | 1 | W1108 | 8.9 |
| NORTH CENTRAL | DELAND EAST | 1 | W1109 | 4.8 |
| NORTH CENTRAL | DELAND EAST | 1 | W1110 | 8.2 |
| NORTH CENTRAL | DELEON SPRINGS | 1 | W0032 | 7.8 |
| NORTH CENTRAL | DELEON SPRINGS | 1 | W0034 | 5.3 |
| NORTH CENTRAL | DELTONA | 3 | W4550 | 5.9 |
| NORTH CENTRAL | DELTONA | 3 | W4553 | 5.0 |
| NORTH CENTRAL | DELTONA | 1 | W4555 | 7.1 |

| | | | | |
|---------------|----------------|---|-------|------|
| NORTH CENTRAL | DELTONA | 3 | W4556 | 8.6 |
| NORTH CENTRAL | DELTONA | 2 | W4558 | 7.8 |
| NORTH CENTRAL | DELTONA | 1 | W4561 | 4.7 |
| NORTH CENTRAL | DELTONA | 3 | W4562 | 8.8 |
| NORTH CENTRAL | DELTONA | 2 | W4564 | 3.8 |
| NORTH CENTRAL | DELTONA | 2 | W4565 | 6.3 |
| NORTH CENTRAL | DELTONA | 1 | W4567 | 6.5 |
| NORTH CENTRAL | DELTONA EAST | 3 | W0121 | 7.7 |
| NORTH CENTRAL | DELTONA EAST | 2 | W0123 | 9.4 |
| NORTH CENTRAL | DELTONA EAST | 3 | W0124 | 8.5 |
| NORTH CENTRAL | DELTONA EAST | 2 | W0126 | 5.3 |
| NORTH CENTRAL | DELTONA EAST | 3 | W0130 | 8.8 |
| NORTH CENTRAL | DELTONA EAST | 2 | W0132 | 8.1 |
| NORTH CENTRAL | DOUGLAS AVENUE | 1 | M1704 | 4.3 |
| NORTH CENTRAL | DOUGLAS AVENUE | 2 | M1706 | 6.4 |
| NORTH CENTRAL | DOUGLAS AVENUE | 1 | M1707 | 4.9 |
| NORTH CENTRAL | DOUGLAS AVENUE | 2 | M1709 | 5.3 |
| NORTH CENTRAL | DOUGLAS AVENUE | 2 | M1712 | 4.3 |
| NORTH CENTRAL | EAST ORANGE | 2 | W0250 | 10.9 |
| NORTH CENTRAL | EAST ORANGE | 3 | W0252 | 8.6 |
| NORTH CENTRAL | EAST ORANGE | 2 | W0253 | 8.7 |
| NORTH CENTRAL | EAST ORANGE | 3 | W0255 | 6.3 |
| NORTH CENTRAL | EAST ORANGE | 2 | W0265 | 7.2 |
| NORTH CENTRAL | EAST ORANGE | 2 | W0271 | 8.9 |
| NORTH CENTRAL | EAST ORANGE | 1 | W0273 | 3.1 |
| NORTH CENTRAL | EAST ORANGE | 3 | W0274 | 11.5 |
| NORTH CENTRAL | EAST ORANGE | 1 | W0276 | 3.8 |
| NORTH CENTRAL | EAST ORANGE | 3 | W0281 | 10.6 |
| NORTH CENTRAL | EATONVILLE | 1 | M1131 | 4.8 |
| NORTH CENTRAL | EATONVILLE | 1 | M1132 | 8.4 |
| NORTH CENTRAL | EATONVILLE | 1 | M1133 | 4.9 |
| NORTH CENTRAL | EATONVILLE | 2 | M1135 | 10.6 |
| NORTH CENTRAL | EATONVILLE | 2 | M1136 | 7.5 |
| NORTH CENTRAL | EATONVILLE | 2 | M1137 | 7.7 |
| NORTH CENTRAL | EATONVILLE | 3 | M1138 | 6.3 |
| NORTH CENTRAL | EATONVILLE | 3 | M1139 | 8.4 |
| NORTH CENTRAL | ECON | 2 | W0318 | 5.4 |
| NORTH CENTRAL | ECON | 1 | W0320 | 8.8 |
| NORTH CENTRAL | ECON | 2 | W0321 | 7.7 |
| NORTH CENTRAL | ECON | 2 | W0324 | 8.1 |
| NORTH CENTRAL | ECON | 1 | W0326 | 10.8 |
| NORTH CENTRAL | ECON | 2 | W0327 | 10.8 |
| NORTH CENTRAL | ECON | 1 | W0329 | 4.7 |
| NORTH CENTRAL | EUSTIS | 2 | M0499 | 5.4 |
| NORTH CENTRAL | EUSTIS | 2 | M0500 | 4.7 |
| NORTH CENTRAL | EUSTIS | 2 | M0501 | 4.4 |
| NORTH CENTRAL | EUSTIS | 1 | M0503 | 6.0 |
| NORTH CENTRAL | EUSTIS | 1 | M0504 | 11.7 |

| | | | | |
|---------------|--------------|---|-------|-------|
| NORTH CENTRAL | EUSTIS SOUTH | 2 | M1054 | 4.8 |
| NORTH CENTRAL | EUSTIS SOUTH | 2 | M1055 | 8.6 |
| NORTH CENTRAL | EUSTIS SOUTH | 2 | M1056 | 6.5 |
| NORTH CENTRAL | EUSTIS SOUTH | 1 | M1057 | 7.2 |
| NORTH CENTRAL | EUSTIS SOUTH | 1 | M1058 | 7.4 |
| NORTH CENTRAL | EUSTIS SOUTH | 1 | M1059 | 6.2 |
| NORTH CENTRAL | FERN PARK | 1 | M0907 | 6.3 |
| NORTH CENTRAL | FERN PARK | 1 | M0908 | 4.7 |
| NORTH CENTRAL | FERN PARK | 1 | M0909 | 4.8 |
| NORTH CENTRAL | HIGHBANKS | 1 | W0751 | 6.6 |
| NORTH CENTRAL | HIGHBANKS | 1 | W0752 | 6.2 |
| NORTH CENTRAL | KELLER ROAD | 1 | M0001 | 8.6 |
| NORTH CENTRAL | KELLER ROAD | 2 | M0002 | 3.6 |
| NORTH CENTRAL | KELLER ROAD | 1 | M0003 | 7.0 |
| NORTH CENTRAL | KELLER ROAD | 2 | M0004 | 6.4 |
| NORTH CENTRAL | KELLY PARK | 2 | M0821 | 5.6 |
| NORTH CENTRAL | KELLY PARK | 2 | M0822 | 3.9 |
| NORTH CENTRAL | LAKE ALOMA | 1 | W0151 | 5.5 |
| NORTH CENTRAL | LAKE ALOMA | 1 | W0153 | 10.8 |
| NORTH CENTRAL | LAKE ALOMA | 2 | W0158 | 3.5 |
| NORTH CENTRAL | LAKE ALOMA | 2 | W0161 | 8.7 |
| NORTH CENTRAL | LAKE EMMA | 2 | M0421 | 5.7 |
| NORTH CENTRAL | LAKE EMMA | 2 | M0422 | 5.7 |
| NORTH CENTRAL | LAKE EMMA | 2 | M0423 | 4.7 |
| NORTH CENTRAL | LAKE EMMA | 2 | M0424 | 5.9 |
| NORTH CENTRAL | LAKE EMMA | 1 | M0425 | 3.7 |
| NORTH CENTRAL | LAKE EMMA | 1 | M0426 | 6.6 |
| NORTH CENTRAL | LAKE EMMA | 1 | M0427 | 4.0 |
| NORTH CENTRAL | LAKE EMMA | 1 | M0428 | 8.09 |
| NORTH CENTRAL | LAKE HELEN | 1 | W1700 | 9.35 |
| NORTH CENTRAL | LAKE HELEN | 2 | W1701 | 6.28 |
| NORTH CENTRAL | LAKE HELEN | 1 | W1703 | 9.19 |
| NORTH CENTRAL | LAKE HELEN | 2 | W1704 | 9.16 |
| NORTH CENTRAL | LISBON | 2 | M1517 | 10.49 |
| NORTH CENTRAL | LISBON | 1 | M1518 | 6.59 |
| NORTH CENTRAL | LISBON | 2 | M1519 | 6.85 |
| NORTH CENTRAL | LISBON | 1 | M1520 | 6.00 |
| NORTH CENTRAL | LOCKHART | 1 | M0400 | 9.46 |
| NORTH CENTRAL | LOCKHART | 2 | M0402 | 8.07 |
| NORTH CENTRAL | LOCKHART | 1 | M0406 | 8.51 |
| NORTH CENTRAL | LOCKHART | 2 | M0408 | 4.20 |
| NORTH CENTRAL | LOCKHART | 1 | M0412 | 9.15 |
| NORTH CENTRAL | LOCKHART | 2 | M0414 | 5.71 |
| NORTH CENTRAL | LOCKHART | 1 | M0415 | 4.65 |
| NORTH CENTRAL | LOCKHART | 2 | M0417 | 5.65 |
| NORTH CENTRAL | LOCKWOOD | 1 | W0480 | 9.21 |
| NORTH CENTRAL | LOCKWOOD | 1 | W0481 | 5.84 |
| NORTH CENTRAL | LOCKWOOD | 1 | W0482 | 7.84 |
| NORTH CENTRAL | LOCKWOOD | 2 | W0483 | 5.99 |
| NORTH CENTRAL | LONGWOOD | 1 | M0142 | 12.71 |
| NORTH CENTRAL | LONGWOOD | 1 | M0143 | 6.88 |
| NORTH CENTRAL | LONGWOOD | 2 | M0144 | 8.92 |
| NORTH CENTRAL | LONGWOOD | 2 | M0145 | 6.54 |
| NORTH CENTRAL | MAITLAND | 3 | M0080 | 8.23 |
| NORTH CENTRAL | MAITLAND | 1 | M0081 | 7.09 |

| | | | | |
|---------------|----------------|---|-------|-------|
| NORTH CENTRAL | MAITLAND | 1 | M0082 | 7.64 |
| NORTH CENTRAL | MAITLAND | 1 | M0084 | 3.32 |
| NORTH CENTRAL | MAITLAND | 2 | M0085 | 6.03 |
| NORTH CENTRAL | MAITLAND | 3 | W0079 | 8.18 |
| NORTH CENTRAL | MAITLAND | 2 | W0086 | 4.67 |
| NORTH CENTRAL | MAITLAND | 2 | W0087 | 10.47 |
| NORTH CENTRAL | MONASTERY | 1 | W0201 | 7.21 |
| NORTH CENTRAL | MONASTERY | 1 | W0202 | 6.03 |
| NORTH CENTRAL | MONASTERY | 1 | W0210 | 8.90 |
| NORTH CENTRAL | MYRTLE LAKE | 2 | M0648 | 8.40 |
| NORTH CENTRAL | MYRTLE LAKE | 2 | M0649 | 9.23 |
| NORTH CENTRAL | MYRTLE LAKE | 2 | M0650 | 5.66 |
| NORTH CENTRAL | MYRTLE LAKE | 2 | M0651 | 7.42 |
| NORTH CENTRAL | MYRTLE LAKE | 3 | M0657 | 8.67 |
| NORTH CENTRAL | MYRTLE LAKE | 3 | M0658 | 9.40 |
| NORTH CENTRAL | MYRTLE LAKE | 3 | M0659 | 7.92 |
| NORTH CENTRAL | NORTH LONGWOOD | 6 | M1749 | 8.96 |
| NORTH CENTRAL | NORTH LONGWOOD | 7 | M1751 | 10.24 |
| NORTH CENTRAL | NORTH LONGWOOD | 6 | M1755 | 6.66 |
| NORTH CENTRAL | NORTH LONGWOOD | 7 | M1757 | 5.91 |
| NORTH CENTRAL | NORTH LONGWOOD | 6 | M1758 | 8.79 |
| NORTH CENTRAL | NORTH LONGWOOD | 7 | M1760 | 6.40 |
| NORTH CENTRAL | NORTH LONGWOOD | 6 | M1761 | 8.79 |
| NORTH CENTRAL | NORTH LONGWOOD | 7 | M1763 | 8.87 |
| NORTH CENTRAL | ORANGE CITY | 3 | W0370 | 6.97 |
| NORTH CENTRAL | ORANGE CITY | 2 | W0372 | 8.10 |
| NORTH CENTRAL | ORANGE CITY | 3 | W0376 | 8.12 |
| NORTH CENTRAL | ORANGE CITY | 2 | W0378 | 3.87 |
| NORTH CENTRAL | ORANGE CITY | 3 | W0382 | 6.41 |
| NORTH CENTRAL | OVIEDO | 1 | W0171 | 8.32 |
| NORTH CENTRAL | OVIEDO | 1 | W0172 | 6.92 |
| NORTH CENTRAL | OVIEDO | 2 | W0174 | 9.26 |
| NORTH CENTRAL | OVIEDO | 2 | W0175 | 6.43 |
| NORTH CENTRAL | OVIEDO | 3 | W0176 | 8.08 |
| NORTH CENTRAL | OVIEDO | 3 | W0181 | 5.22 |
| NORTH CENTRAL | PIEDMONT | 2 | M0471 | 8.01 |
| NORTH CENTRAL | PIEDMONT | 2 | M0472 | 7.03 |
| NORTH CENTRAL | PIEDMONT | 2 | M0473 | 9.73 |
| NORTH CENTRAL | PIEDMONT | 2 | M0474 | 9.43 |
| NORTH CENTRAL | PIEDMONT | 1 | M0475 | 8.35 |
| NORTH CENTRAL | PIEDMONT | 1 | M0476 | 4.86 |
| NORTH CENTRAL | PIEDMONT | 1 | M0477 | 8.05 |
| NORTH CENTRAL | PIEDMONT | 1 | M0478 | 8.90 |
| NORTH CENTRAL | PLYMOUTH SOUTH | 1 | M0702 | 4.53 |
| NORTH CENTRAL | PLYMOUTH SOUTH | 2 | M0704 | 3.38 |
| NORTH CENTRAL | PLYMOUTH SOUTH | 2 | M0706 | 7.27 |
| NORTH CENTRAL | PLYMOUTH SOUTH | 1 | M0707 | 9.16 |
| NORTH CENTRAL | SPRING LAKE | 2 | M0662 | 6.18 |
| NORTH CENTRAL | SPRING LAKE | 2 | M0663 | 6.74 |
| NORTH CENTRAL | SPRING LAKE | 2 | M0664 | 7.35 |
| NORTH CENTRAL | SPRING LAKE | 1 | M0666 | 4.78 |
| NORTH CENTRAL | SPRING LAKE | 1 | M0667 | 9.77 |
| NORTH CENTRAL | SPRING LAKE | 1 | M0668 | 10.05 |
| NORTH CENTRAL | SPRING LAKE | 3 | M0669 | 7.12 |
| NORTH CENTRAL | SPRING LAKE | 3 | M0670 | 7.67 |

| | | | | |
|---------------|--------------|----|-------|-------|
| NORTH CENTRAL | SUNFLOWER | 1 | W0469 | 4.89 |
| NORTH CENTRAL | SUNFLOWER | 1 | W0470 | 10.60 |
| NORTH CENTRAL | SUNFLOWER | 1 | W0471 | 7.74 |
| NORTH CENTRAL | SUNFLOWER | 2 | W0472 | 5.99 |
| NORTH CENTRAL | SUNFLOWER | 2 | W0473 | 8.88 |
| NORTH CENTRAL | SUNFLOWER | 2 | W0474 | 12.53 |
| NORTH CENTRAL | SUNFLOWER | 1 | W0475 | 6.71 |
| NORTH CENTRAL | TAVARES EAST | 1 | M0580 | 5.48 |
| NORTH CENTRAL | TAVARES EAST | 1 | M0581 | 4.91 |
| NORTH CENTRAL | TURNER PLANT | 8 | W0761 | 8.20 |
| NORTH CENTRAL | TURNER PLANT | 8 | W0762 | 6.34 |
| NORTH CENTRAL | TURNER PLANT | 10 | W0763 | 6.74 |
| NORTH CENTRAL | TURNER PLANT | 10 | W0764 | 5.85 |
| NORTH CENTRAL | UCF | 1 | W1012 | 9.45 |
| NORTH CENTRAL | UCF | 1 | W1013 | 8.17 |
| NORTH CENTRAL | UCF | 1 | W1014 | 4.05 |
| NORTH CENTRAL | UCF | 2 | W1015 | 7.03 |
| NORTH CENTRAL | UCF | 2 | W1016 | 11.41 |
| NORTH CENTRAL | UCF | 2 | W1017 | 6.48 |
| NORTH CENTRAL | UCF | 2 | W1018 | 5.38 |
| NORTH CENTRAL | UCF NORTH | 3 | W0940 | 1.76 |
| NORTH CENTRAL | UCF NORTH | 1 | W0942 | 1.71 |
| NORTH CENTRAL | UCF NORTH | 1 | W0980 | 10.17 |
| NORTH CENTRAL | UCF NORTH | 2 | W0981 | 7.00 |
| NORTH CENTRAL | UCF NORTH | 2 | W0982 | 8.94 |
| NORTH CENTRAL | UCF NORTH | 1 | W0983 | 4.51 |
| NORTH CENTRAL | UCF NORTH | 3 | W0988 | 2.65 |
| NORTH CENTRAL | UCF NORTH | 1 | W0989 | 4.67 |
| NORTH CENTRAL | UCF NORTH | 2 | W0992 | 11.04 |
| NORTH CENTRAL | UCF NORTH | 3 | W0994 | 10.00 |
| NORTH CENTRAL | UMATILLA | 2 | M4405 | 6.47 |
| NORTH CENTRAL | UMATILLA | 1 | M4407 | 7.39 |
| NORTH CENTRAL | UMATILLA | 1 | M4408 | 5.01 |
| NORTH CENTRAL | WEKIVA | 1 | M0101 | 5.13 |
| NORTH CENTRAL | WEKIVA | 2 | M0103 | 4.82 |
| NORTH CENTRAL | WEKIVA | 2 | M0104 | 5.01 |
| NORTH CENTRAL | WEKIVA | 1 | M0106 | 6.12 |
| NORTH CENTRAL | WEKIVA | 1 | M0107 | 6.79 |
| NORTH CENTRAL | WEKIVA | 2 | M0109 | 5.01 |
| NORTH CENTRAL | WEKIVA | 2 | M0110 | 8.00 |
| NORTH CENTRAL | WEKIVA | 1 | M0112 | 5.62 |
| NORTH CENTRAL | WEKIVA | 2 | M0113 | 5.97 |
| NORTH CENTRAL | WEKIVA | 1 | M0115 | 4.60 |
| NORTH CENTRAL | WELCH ROAD | 1 | M0542 | 8.49 |
| NORTH CENTRAL | WELCH ROAD | 1 | M0543 | 5.73 |
| NORTH CENTRAL | WELCH ROAD | 3 | M0545 | 6.99 |
| NORTH CENTRAL | WELCH ROAD | 3 | M0548 | 7.15 |
| NORTH CENTRAL | WELCH ROAD | 1 | M0550 | 9.68 |
| NORTH CENTRAL | WELCH ROAD | 1 | M0552 | 6.01 |
| NORTH CENTRAL | WELCH ROAD | 3 | M0554 | 7.00 |
| NORTH CENTRAL | WEST CHAPMAN | 3 | W0700 | 9.02 |
| NORTH CENTRAL | WEST CHAPMAN | 2 | W0702 | 5.22 |
| NORTH CENTRAL | WEST CHAPMAN | 3 | W0703 | 7.76 |
| NORTH CENTRAL | WEST CHAPMAN | 2 | W0705 | 3.66 |
| NORTH CENTRAL | WEST CHAPMAN | 3 | W0708 | 10.78 |

| | | | | |
|---------------|------------------|---|-------|-------|
| NORTH CENTRAL | WINTER PARK | 4 | W0014 | 2.00 |
| NORTH CENTRAL | WINTER PARK | 4 | W0015 | 7.34 |
| NORTH CENTRAL | WINTER PARK | 4 | W0016 | 5.62 |
| NORTH CENTRAL | WINTER PARK EAST | 1 | W0924 | 10.61 |
| NORTH CENTRAL | WINTER PARK EAST | 1 | W0925 | 10.78 |
| NORTH CENTRAL | WINTER PARK EAST | 1 | W0926 | 9.23 |
| NORTH CENTRAL | WINTER PARK EAST | 1 | W0927 | 8.04 |
| NORTH CENTRAL | WINTER PARK EAST | 3 | W0928 | 8.94 |
| NORTH CENTRAL | WINTER PARK EAST | 3 | W0929 | 10.88 |
| NORTH CENTRAL | WINTER PARK EAST | 3 | W0930 | 5.68 |
| NORTH CENTRAL | WINTER PARK EAST | 3 | W0931 | 10.29 |
| NORTH CENTRAL | WINTER SPRINGS | 3 | W0187 | 9.79 |
| NORTH CENTRAL | WINTER SPRINGS | 3 | W0188 | 8.98 |
| NORTH CENTRAL | WINTER SPRINGS | 3 | W0189 | 7.97 |
| NORTH CENTRAL | WINTER SPRINGS | 1 | W0192 | 8.32 |
| NORTH CENTRAL | WINTER SPRINGS | 1 | W0193 | 4.90 |
| NORTH CENTRAL | WINTER SPRINGS | 1 | W0194 | 7.39 |
| NORTH CENTRAL | WINTER SPRINGS | 2 | W0195 | 8.19 |
| NORTH CENTRAL | WINTER SPRINGS | 2 | W0196 | 8.85 |
| NORTH CENTRAL | WOLF LAKE | 1 | M0563 | 5.11 |
| NORTH CENTRAL | WOLF LAKE | 1 | M0564 | 6.12 |
| NORTH CENTRAL | ZELLWOOD | 1 | M0031 | 5.70 |
| NORTH CENTRAL | ZELLWOOD | 1 | M0032 | 0.94 |
| NORTH CENTRAL | ZELLWOOD | 2 | M0033 | 8.79 |
| NORTH CENTRAL | ZELLWOOD | 2 | M0034 | 8.36 |

Attachment H

Received Jan 1 to Dec 31, 2020

88 Complaints

DEF logged as Power Quality & Reliability

| Date Received | PSC Complaint # | DEF Category | PSC Ruling | PSC Closure Code |
|---------------|-----------------|------------------------------------|----------------|------------------------|
| 1/8/2020 | 1330471E | Outage | Non-Infraction | GI-15 Outages |
| 1/22/2020 | 1331291E | Outage | Non-Infraction | GI-11 Repair Service |
| 1/24/2020 | 1331458E | Equipment/Facilities Issues | Non-Infraction | GI-17 Safety Issues |
| 1/28/2020 | 1331680E | Voltage Problems | Non-Infraction | GI-11 Repair Service |
| 1/31/2020 | 1331913E | Outage | Non-Infraction | GI-15 Outages |
| 2/3/2020 | 1331957E | Equipment/Facilities Issues | Non-Infraction | GI-11 Repair Service |
| 2/7/2020 | 1332239E | Outage | Non-Infraction | GI-15 Outages |
| 2/7/2020 | 1332291E | Voltage Problems | Non-Infraction | GI-15 Outages |
| 2/14/2020 | 1332667E | Vegetation Management Distribution | Non-Infraction | GI-11 Repair Service |
| 2/17/2020 | 1332722E | Outage | Non-Infraction | GI-15 Outages |
| 2/20/2020 | 1332979E | Outage | Non-Infraction | GI-15 Outages |
| 2/21/2020 | 1333044E | Outage | Non-Infraction | GI-15 Outages |
| 3/5/2020 | 1334020E | Outage | Non-Infraction | GI-15 Outages |
| 3/10/2020 | 1333733E | Equipment/Facilities Issues | Non-Infraction | GI-17 Safety Issues |
| 3/30/2020 | 1335208E | Vegetation Management Distribution | Non-Infraction | GI-18 Tree Trimming |
| 3/30/2020 | 1335213E | Vegetation Management Distribution | Non-Infraction | GI-72 3-Day Resolution |
| 4/17/2020 | 1336061E | Outage | Non-Infraction | GI-18 Tree Trimming |
| 4/21/2020 | 1336212E | Lighting | Non-Infraction | GI-25 Improper Billing |
| 4/24/2020 | 1336375E | Outage | Non-Infraction | GI-15 Outages |
| 4/28/2020 | 1336594E | Lighting | Non-Infraction | GI-11 Repair Service |
| 5/11/2020 | 1337207E | Vegetation Management Distribution | Non-Infraction | GI-17 Safety Issues |
| 5/14/2020 | 1337393E | Outage | Non-Infraction | GI-15 Outages |
| 5/15/2020 | 1337450E | Outage | Non-Infraction | GI-15 Outages |
| 5/18/2020 | 1337476E | Outage | Non-Infraction | GI-15 Outages |
| 5/18/2020 | 1337528E | Outage | Non-Infraction | GI-15 Outages |
| 5/28/2020 | 1337941E | Outage | Non-Infraction | GI-15 Outages |
| 5/28/2020 | 1337948E | Outage | Non-Infraction | GI-15 Outages |
| 5/28/2020 | 1337977E | Outage | Non-Infraction | GI-15 Outages |
| 5/29/2020 | 1338015E | Outage | Non-Infraction | GI-15 Outages |
| 5/29/2020 | 1338014E | Vegetation Management Distribution | Non-Infraction | GI-15 Outages |
| 6/1/2020 | 1338066E | Outage | Non-Infraction | GI-15 Outages |
| 6/1/2020 | 1338068E | Outage | Non-Infraction | GI-15 Outages |
| 6/1/2020 | 1338075E | Outage | Non-Infraction | GI-15 Outages |
| 6/1/2020 | 1338080E | Outage | Non-Infraction | GI-15 Outages |
| 6/2/2020 | 1338146E | Outage | Non-Infraction | GI-15 Outages |
| 6/2/2020 | 1338168E | Outage | Non-Infraction | GI-15 Outages |
| 6/2/2020 | 1338176E | Outage | Non-Infraction | GI-15 Outages |
| 6/4/2020 | 1338291E | Outage | Non-Infraction | GI-15 Outages |
| 6/4/2020 | 1338291E | Outage | Non-Infraction | GI-15 Outages |
| 6/15/2020 | 1338840E | Voltage Problems | Non-Infraction | GI-15 Outages |
| 6/24/2020 | 1339255E | Outage | Non-Infraction | GI-15 Outages |
| 7/10/2020 | 1340036E | Outage | Non-Infraction | GI-15 Outages |
| 7/14/2020 | 1340172E | Voltage Problems | Non-Infraction | GI-11 Repair Service |
| 7/21/2020 | 1340499E | Outage | Non-Infraction | GI-15 Outages |
| 7/23/2020 | 1340586E | Equipment/Facilities Issues | Non-Infraction | GI-11 Repair Service |
| 7/23/2020 | 1340618E | Outage | Non-Infraction | GI-15 Outages |

Received Jan 1 to Dec 31, 2020

80 Complaints

PSC Service Reliability Only Closure Codes

| Date Received | PSC Complaint # | DEF Category | PSC Closure Code |
|---------------|-----------------|------------------------------------|----------------------|
| 1/8/2020 | 1330471E | Outage | GI-15 Outages |
| 1/22/2020 | 1331291E | Outage | GI-11 Repair Service |
| 1/24/2020 | 1331458E | Equipment/Facilities Issues | GI-17 Safety Issues |
| 1/28/2020 | 1331680E | Voltage Problems | GI-11 Repair Service |
| 1/31/2020 | 1331913E | Outage | GI-15 Outages |
| 2/3/2020 | 1332017E | High Bills | GI-11 Repair Service |
| 2/3/2020 | 1331957E | Equipment/Facilities Issues | GI-11 Repair Service |
| 2/7/2020 | 1332239E | Outage | GI-15 Outages |
| 2/7/2020 | 1332291E | Voltage Problems | GI-15 Outages |
| 2/14/2020 | 1332667E | Vegetation Management Distribution | GI-11 Repair Service |
| 2/17/2020 | 1332722E | Outage | GI-15 Outages |
| 2/20/2020 | 1332979E | Outage | GI-15 Outages |
| 2/21/2020 | 1333044E | Outage | GI-15 Outages |
| 3/5/2020 | 1334020E | Outage | GI-15 Outages |
| 3/10/2020 | 1333733E | Equipment/Facilities Issues | GI-17 Safety Issues |
| 3/30/2020 | 1335208E | Vegetation Management Distribution | GI-18 Tree Trimming |
| 4/17/2020 | 1336061E | Outage | GI-18 Tree Trimming |
| 4/20/2020 | 1336154E | Claims | GI-11 Repair Service |
| 4/24/2020 | 1336371E | Disconnect Non-Pay | GI-11 Repair Service |
| 4/24/2020 | 1336375E | Outage | GI-15 Outages |
| 4/27/2020 | 1336492E | Claims | GI-15 Outages |
| 4/28/2020 | 1336594E | Lighting | GI-11 Repair Service |
| 5/11/2020 | 1337207E | Vegetation Management Distribution | GI-17 Safety Issues |
| 5/14/2020 | 1337393E | Outage | GI-15 Outages |
| 5/15/2020 | 1337450E | Outage | GI-15 Outages |
| 5/18/2020 | 1337476E | Outage | GI-15 Outages |
| 5/18/2020 | 1337528E | Outage | GI-15 Outages |
| 5/28/2020 | 1337941E | Outage | GI-15 Outages |
| 5/28/2020 | 1337948E | Outage | GI-15 Outages |
| 5/28/2020 | 1337977E | Outage | GI-15 Outages |
| 5/29/2020 | 1338015E | Outage | GI-15 Outages |
| 5/29/2020 | 1338014E | Vegetation Management Distribution | GI-15 Outages |
| 6/1/2020 | 1338066E | Outage | GI-15 Outages |
| 6/1/2020 | 1338068E | Outage | GI-15 Outages |
| 6/1/2020 | 1338075E | Outage | GI-15 Outages |
| 6/1/2020 | 1338080E | Outage | GI-15 Outages |
| 6/2/2020 | 1338146E | Outage | GI-15 Outages |
| 6/2/2020 | 1338168E | Outage | GI-15 Outages |
| 6/2/2020 | 1338176E | Outage | GI-15 Outages |
| 6/4/2020 | 1338291E | Outage | GI-15 Outages |
| 6/4/2020 | 1338291E | Outage | GI-15 Outages |
| 6/4/2020 | 1338291E | Outage | GI-15 Outages |
| 6/4/2020 | 1338291E | Outage | GI-15 Outages |
| 6/15/2020 | 1338840E | Voltage Problems | GI-15 Outages |
| 6/24/2020 | 1339255E | Outage | GI-15 Outages |
| 7/10/2020 | 1340036E | Outage | GI-15 Outages |
| 7/14/2020 | 1340172E | Voltage Problems | GI-11 Repair Service |
| 7/21/2020 | 1340499E | Outage | GI-15 Outages |

Attachment I

Storm Hardening Projects 2019-2021

| Zone | Op Center | County | Project | Sub Category | Project Status or Year to Complete |
|---------------|---------------|-----------|----------------------------------------------------------------------------------------------------|-----------------------------------------|------------------------------------|
| South Central | Winter Garden | Orange | Oakland Ave Feeder Tie | Feeder Tie | Completed 2019 |
| South Coastal | St Petersburg | Pinellas | 16th St. X43/X46 4/0 copper to 795 AAC reconductor | Feeder Tie | Planned for 2020 Completion |
| South Central | Highlands | Highlands | US 27 & Hammock Rd | Feeder Tie | Planned for 2020 Completion |
| South Central | Highlands | Highlands | US 27 & Lakeview Rd Phase II | Feeder Tie | Completed 2019 |
| South Central | Highlands | Highlands | State HWY 66 Phase I | Feeder Tie | Completed 2019 |
| South Central | Highlands | Highlands | State HWY 66 Phase II | Feeder Tie | Planned for 2021 Completion |
| South Central | Highlands | Highlands | Lakewood Ave | Feeder Tie | Planned for 2020 Completion |
| North Coastal | Ocala | Marion | Ocala - SE 64th Ave Rd | Feeder Tie | Completed 2019 |
| North Coastal | Monticello | Taylor | Perry North N15 - Reconductor | Feeder Tie | Completed 2019 |
| South Coastal | Seven Springs | Pasco | Denham C151_Denham C152 Feeder Tie | Feeder Tie | Planned for 2021 Completion |
| North Coastal | Monticello | Alachua | High Springs A16 | Deteriorated Conductor | Completed 2019 |
| North Coastal | Monticello | Columbia | Ft White A20, West US 27 Reconductor | Feeder Tie/Deteriorated Conductor | Planned for 2020 Completion |
| South Central | Buena Vista | Orange | Hunters CK_Town Ctr Feeder Tie | Feeder Tie | Planned for 2021 Completion |
| South Central | Lake Wales | Polk | K9 & K5078 Feeder Tie | Feeder Tie | Completed 2019 |
| North Coastal | Inverness | Citrus | Storm Hardening UG Xfms at Sportsman Riverside Townhouses, Homosass | Submersible UG | Completed 2019 |
| North Coastal | Inverness | Citrus | Storm Hardening Gasparilla Cay Subdivision | Submersible UG | Completed 2019 |
| North Coastal | Inverness | Citrus | Storm Hardening along Riverhaven Dr., Homosassa | Submersible UG | Completed 2019 |
| North Coastal | Inverness | Citrus | Storm Hardening Dixie Shores Subdivision, Crystal River. | Submersible UG | Planned for 2020 Completion |
| North Coastal | Inverness | Citrus | Storm Hardening Blue River Cove Subdivision, Homosassa | Submersible UG | Completed 2019 |
| South Coastal | Seven Springs | Pasco | Anclote Substation Bank 7 and Bank 8 Feeder Ties | Feeder Tie | Planned for 2020 Completion |
| South Central | SE Orlando | Orange | GreenTree & Cypress Glenn Grid Strengthening - Phase 1 | OH to UG Conversion | Completed 2019 |
| South Central | SE Orlando | Orange | GreenTree & Cypress Glenn Grid Strengthening - Phase 2 | OH to UG Conversion | Planned for 2020 Completion |
| North Coastal | Inverness | Hernando | Storm Hardening Imperial Estates Underground | Submersible UG | Completed 2019 |
| South Central | Highlands | Highlands | Lake Byrd Reconductor | Deteriorated Conductor | Planned for 2021 Completion |
| North Coastal | Monticello | Alachua | GE Alachua A186, UF Dairy Reconductor | Deteriorated Conductor | Planned for 2021 Completion |
| South Coastal | Zephyrhills | Pasco | Branchline reconductor at Otis Allen and 16th St. | Deteriorated Conductor | Planned for 2021 Completion |
| South Central | Lake Wales | Polk | Alturas Loop Rd | Deteriorated Conductor | Planned for 2021 Completion |
| South Central | Highlands | Highlands | K542 Sebring Airport Terminal | Deteriorated Conductor | Planned for 2021 Completion |
| North Central | Deland | Volusia | W902 Shaw Lake Reconductor | Deteriorated Conductor | Completed 2019 |
| South Central | SE Orlando | Orange | Dawn Drive 5081648-2 | Deteriorated Conductor | Completed 2019 |
| North Coastal | Inverness | Citrus | Citrus Springs - Construct 3 phs 1/0 along Academy Dr & 69kv R/W and eliminate backlot line feeds. | Backlot to Frontlot Conversion | Planned for 2021 Completion |
| North Central | Longwood | Seminole | Fern Park M908 Grid Strengthening | OH to UG Conversion | Planned for 2021 Completion |
| South Coastal | Clearwater | Pinellas | Clearwater C15 Country Club Subdivision | Deteriorated Conductor | Planned for 2021 Completion |
| South Coastal | Seven Springs | Pinellas | Curlew C4988 Spanish Acres Subdivision | Deteriorated Conductor | Project Cancelled. Now under TUG |
| South Central | Winter Garden | Orange | Main Street Feeder Tie | Feeder Tie | Planned for 2021 Completion |
| South Central | Buena Vista | Orange | Summerlake Park Feeder Tie K1111 to K1110 | Feeder Tie | Planned for 2020 Completion |
| North Central | Apopka | Seminole | M109 Smoke Rise Blvd Reliability | OH to UG Conversion/ Backlot Conversion | Planned for 2021 Completion |
| North Central | Apopka | Orange | M34 Dudley Ave Underground Conversion | OH to UG Conversion | Planned for 2021 Completion |
| South Coastal | Seven Springs | Pinellas | Tarpon Springs C305 Magnolia Heights Reconductor | Feeder Tie | Planned for 2021 Completion |
| South Coastal | St Petersburg | Pinellas | 52nd St Reconductor | Feeder Tie | Planned for 2021 Completion |
| South Central | Winter Garden | Orange | SR408 Crossing West of Good Homes | Overhead Line Crossing/Backlot | Planned for 2021 Completion |
| South Central | Clermont | Lake | Hancock Road Feeder Tie K4833_K4841 | Feeder Tie | Planned for 2021 Completion |
| South Central | SE Orlando | Orange | Meadow Woods S Feeder Tie K1789_K1775 | Feeder Tie | Planned for 2021 Completion |
| North Coastal | Monticello | Gulf | Feeder N55 tie to rest of Port St Joe Feeders | Feeder Tie | Planned for 2021 Completion |
| South Central | Buena Vista | Orange | TUG 442313600 Winwood Way | TUG | Planned for 2020 Completion |
| North Central | Jamestown | Orange | TUG 444365498 Lake Pickett | TUG | Completed 2019 |
| South Coastal | Clearwater | Pinellas | TUG 444175916 KENT PL | TUG | Completed 2019 |
| South Coastal | Seven Springs | Pasco | TUG 445908443 US HWY 19 | TUG | Completed 2019 |
| South Coastal | Walsingham | Pinellas | TUG 444000345 WALSINGHAM ROAD | TUG | Completed 2019 |
| South Central | Lake Wales | Polk | TUG 443456879 MASTERPIECE ROAD | TUG | Completed 2019 |
| South Coastal | Clearwater | Pinellas | TUG 444175903 LAKE AVENUE | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442991482 DILLS RD | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442991979 CLARK RD | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442992222 DILLS RD | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442991596 E CAPPAS HWY | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442992262 WAUKEENAH HWY | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442992343 E WASHINGTON ST | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442991942 E WASHINGTON ST | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442992071 E WASHINGTON ST | TUG | Completed 2019 |
| South Central | Lake Wales | Polk | TUG 443588618 W CENTRAL AVENUE | TUG | Completed 2019 |
| South Central | Lake Wales | Polk | TUG 443590662 WAVERLY ROAD | TUG | Completed 2019 |
| South Coastal | Walsingham | Pinellas | TUG 444000839 PARK BLVD | TUG | Completed 2019 |
| South Central | Lake Wales | Polk | TUG 443456476 S 4TH STREET | TUG | Completed 2019 |
| South Coastal | St Petersburg | Pinellas | TUG 443021560 13TH AVENUE SOUTH | TUG | Completed 2019 |
| North Coastal | Monticello | Hamilton | TUG 437462847 SW 41 HWY | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442991852 WAUKEENAH HWY | TUG | Completed 2019 |
| North Coastal | Monticello | Madison | TUG 446863601 S STATE ROAD 53 | TUG | Completed 2019 |
| North Coastal | Monticello | Taylor | TUG 437643458 Johnson Stripling Rd | TUG | Completed 2019 |
| North Central | Deland | Volusia | TUG 443101071 S WOODLAND BLVD | TUG | Completed 2019 |
| North Coastal | Monticello | Levy | TUG 437808024 SE 4 ST | TUG | Completed 2019 |
| North Coastal | Monticello | Taylor | TUG 437643315 MORGAN WHIDDON RD | TUG | Completed 2019 |
| North Coastal | Monticello | Levy | TUG 437808132 OLD FANNIN RD | TUG | Completed 2019 |
| North Central | Deland | Volusia | TUG 443101171 E TAYLOR ROAD | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446551406 CORTEZ BLVD | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446551579 OAKDALE AVENUE | TUG | Planned for 2020 Completion |
| North Central | Deland | Volusia | TUG 443098247 MERCERS FERNERY ROAD | TUG | Completed 2019 |
| North Coastal | Inverness | Citrus | TUG 446947221 N CAROLWOOD PT | TUG | Completed 2019 |
| South Central | Clermont | Lake | TUG 439153957 OLD HWY 50 | TUG | Completed 2019 |
| North Coastal | Inverness | Citrus | TUG 446948589 N.FOREST LAKE DR | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446551410 SINGER LANE | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446551438 KOLLAR STREET | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446551561 CEDAR LANE | TUG | Completed 2019 |
| North Central | Deland | Volusia | TUG 443098221 W WASHINGTON AVE | TUG | Completed 2019 |
| South Coastal | Walsingham | Pinellas | TUG 444121088 US HWY 19 N | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446551401 BROAD STREET | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446551571 PONCE DE LEON BLVD | TUG | Completed 2019 |
| North Coastal | Inverness | Citrus | TUG 410077868 NE 9TH AVENUE | TUG | Completed 2019 |
| North Central | Deland | Volusia | TUG 443098818 CHURCH STREET | TUG | Completed 2019 |
| North Coastal | Inverness | Marion | TUG 446792563 SW HWY 484 | TUG | Completed 2019 |
| North Coastal | Inverness | Marion | TUG 446792833 S US HWY 41 | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446550669 GARDEN STREET | TUG | Completed 2019 |
| North Coastal | Inverness | Citrus | TUG 440373184 W FORT ISLAND TRAIL | TUG | Completed 2019 |
| North Coastal | Inverness | Citrus | TUG 446947915 NORVELL BRYANT HWY | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446550461 BELL AVENUE | TUG | Completed 2019 |
| North Coastal | Inverness | Citrus | TUG 446946957 S RUSSELL ROAD | TUG | Completed 2019 |
| North Coastal | Inverness | Citrus | TUG 446946764 S JUNEAU POINT | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446551358 SPRING HILL DR | TUG | Completed 2019 |
| North Coastal | Monticello | Taylor | TUG 437643271 Johnson Stripling Rd | TUG | Completed 2019 |
| North Coastal | Monticello | Madison | TUG 446928406 NE County Road 255 | TUG | Completed 2019 |
| North Coastal | Inverness | Citrus | TUG 446946878 S. SCARBORO AVENUE | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446551368 AYERS ROAD | TUG | Completed 2019 |
| North Coastal | Ocala | Marion | TUG 446640224 NE 21ST CT | TUG | Completed 2019 |
| North Coastal | Ocala | Marion | TUG 446639397 E HIGHWAY 329 | TUG | Completed 2019 |
| North Coastal | Monticello | Madison | TUG 446928171 NE State Road 6 | TUG | Completed 2019 |
| South Coastal | Clearwater | Pinellas | TUG 444040631 McMullen Booth Rd | TUG | Completed 2019 |
| North Central | Deland | Volusia | TUG 443101562 REYNOLDS ROAD | TUG | Completed 2019 |

| | | | | | |
|---------------|---------------|------------------|-------------------------------------------------------------------|------------------------|-----------------------------|
| North Central | Longwood | Orange | TUG 442901716 DR LOVE DR | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442991535 Jefferson Heights Rd | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442991614 BONNET POND RD | TUG | Completed 2019 |
| North Central | Longwood | Seminole | TUG 442900787 KOKOMO LOOP | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446550619 W JEFFERSON STREET | TUG | Completed 2019 |
| South Coastal | Zephyrhills | Pasco | TUG 444106863 3RD AVENUE | TUG | Completed 2019 |
| North Central | Deland | Volusia | TUG 443098179 S HAYDEN RD | TUG | Completed 2019 |
| North Coastal | Monticello | Lafayette | TUG 445194353 NE CRAWFORD ST | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442991878 N. Jefferson St | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442992412 N. Jefferson St | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442992444 WILLIAM FLOYD RD | TUG | Completed 2019 |
| North Central | Longwood | Orange | TUG 442726346 INDIANA AVENUE | TUG | Planned for 2020 Completion |
| North Coastal | Inverness | Citrus | TUG 446793174 E BRADFORD LANE | TUG | Completed 2019 |
| North Coastal | Monticello | Lafayette | TUG 445194165 E MAIN ST | TUG | Completed 2019 |
| North Coastal | Inverness | Citrus | TUG 440372700 W. HALLS RIVER ROAD | TUG | Completed 2019 |
| North Central | Deland | Volusia | TUG 442972314 MILLS COURT | TUG | Completed 2019 |
| South Coastal | Seven Springs | Pasco | TUG 445971300 BAZSULY CT | TUG | Completed 2019 |
| North Coastal | Monticello | Madison | TUG 446928362 E. US Highway 90 | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446550648 ROOSEVELT AVENUE | TUG | Completed 2020 |
| North Coastal | Monticello | Madison | TUG 446928127 NE COLIN KELLY HWY | TUG | Completed 2019 |
| North Coastal | Monticello | Madison | TUG 446928477 E. US Highway 90 | TUG | Completed 2019 |
| North Central | Deland | Volusia | TUG 442972575 RAINTREE CIRCLE | TUG | Completed 2019 |
| North Coastal | Monticello | Levy | TUG 442992069 Nash Rd | TUG | Completed 2019 |
| North Coastal | Monticello | Taylor | TUG 437643658 S. Warner Ave | TUG | Completed 2019 |
| North Coastal | Monticello | Wakulla | TUG 446034297 Sopchoppy Hwy | TUG | Completed 2019 |
| North Coastal | Inverness | Citrus | TUG 440372992 N CARLEEN TERRACE | TUG | Completed 2019 |
| North Central | Deland | Volusia | TUG 442972886 MARSH ROAD | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442991542 Indian Hills Rd | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442992157 Indian Hills Rd | TUG | Completed 2019 |
| North Coastal | Monticello | Wakulla | TUG 446133723 PORT LEON DR | TUG | Completed 2019 |
| North Coastal | Ocala | Sumter | TUG 442170847 CR 567 | TUG | Completed 2019 |
| North Coastal | Monticello | Taylor | TUG 437643566 JOHNSON STRIPLING RD | TUG | Completed 2019 |
| North Coastal | Ocala | Sumter | TUG 442171308 N US HWY 301 | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442992140 E. Capps Hwy | TUG | Completed 2019 |
| North Coastal | Monticello | Jefferson | TUG 442992370 BOSTON HWY | TUG | Completed 2019 |
| North Coastal | Ocala | Marion | TUG 446639202 NW 75TH AVE | TUG | Completed 2019 |
| North Coastal | Inverness | Citrus | TUG 446948748 E. OLIVE LANE | TUG | Completed 2019 |
| North Coastal | Inverness | Citrus | TUG 446948512 N TRUCKS AVENUE | TUG | Completed 2019 |
| South Coastal | Seven Springs | Pinellas | TUG 445909816 ORANGE ST | TUG | Completed 2019 |
| North Coastal | Monticello | Wakulla | TUG 446034704 Rock Rd | TUG | Completed 2019 |
| South Coastal | Walsingham | Pinellas | TUG 444000493 80TH AVENUE NORTH | TUG | Completed 2019 |
| South Coastal | Clearwater | Pinellas | TUG 444176622 MARIVA AVENUE | TUG | Planned for 2020 Completion |
| North Coastal | Ocala | Marion | TUG 443823907 SE 117TH PLACE | TUG | Completed 2019 |
| South Coastal | Walsingham | Pinellas | TUG 444121839 S BELCHER RD | TUG | Completed 2019 |
| North Central | Deland | Volusia | TUG 443101583 HAMILTON AVENUE | TUG | Completed 2019 |
| North Coastal | Ocala | Marion | TUG 446637870 NE 180TH ST | TUG | Completed 2019 |
| North Coastal | Monticello | Hamilton | TUG 437462945 11TH ST SE | TUG | Completed 2019 |
| North Coastal | Monticello | Taylor | TUG 446034419 Bay Dr | TUG | Planned for 2020 Completion |
| South Central | Buena Vista | Orange | TUG 442314118 PARK AVE | TUG | Completed 2019 |
| North Coastal | Monticello | Wakulla | TUG 446034948 Woodville Hwy | TUG | Completed 2019 |
| North Coastal | Monticello | Taylor | TUG 437643670 N. Helen St | TUG | Completed 2019 |
| South Coastal | Walsingham | Pinellas | TUG 444120484 67TH AVENUE | TUG | Completed 2019 |
| South Central | Apopka | Orange | TUG 445664480 ROUND LAKE RD | TUG | Planned for 2020 Completion |
| South Central | Lake Wales | Polk | TUG 443590177 Edward Ave | TUG | Completed 2020 |
| North Coastal | Monticello | Taylor | TUG 437643278 N. Allen St | TUG | Completed 2019 |
| North Coastal | Inverness | Hernando | TUG 446550431 RAILROAD PLACE | TUG | Completed 2019 |
| North Central | JAMESTOWN | ORANGE | TUG 444231047 Chuluota Rd | TUG | Completed 2019 |
| South Coastal | Zephyrhills | Pasco | TUG 444253097 RYALS RD | TUG | Completed 2019 |
| North Central | Jamestown | Seminole/Orange | Self- Optimizing Grid Team 401 | SOG | Completed 2019 |
| North Central | Jamestown | Seminole/Orange | Self- Optimizing Grid Team 411 | SOG | Completed 2019 |
| North Central | Deland | Volusia | Self- Optimizing Grid Team 424 | SOG | Completed 2019 |
| South Coastal | Clearwater | Pinellas | Self- Optimizing Grid Team 514 | SOG | Completed 2019 |
| South Central | Winter Garden | Orange | Self- Optimizing Grid Team 426 | SOG | Completed 2019 |
| South Central | Lake Wales | Polk | Self- Optimizing Grid Team 402 | SOG | Planned for 2020 Completion |
| North Central | Deland | Volusia | Self- Optimizing Grid Team 403 | SOG | Completed 2019 |
| North Coastal | Monticello | Franklin/Wakulla | Self- Optimizing Grid Team 505 | SOG | Planned for 2020 Completion |
| North Central | Apopka | Orange | Self- Optimizing Grid Team 412 | SOG | Completed 2019 |
| North Central | Longwood | Seminole | Self- Optimizing Grid Team 406 | SOG | Completed 2019 |
| South Central | Lake Wales | Polk | Self- Optimizing Grid Team 413 | SOG | Completed 2019 |
| South Central | Highlands | Highlands | Self- Optimizing Grid Team 408 | SOG | Completed 2019 |
| South Coastal | St Petersburg | Pinellas | Self- Optimizing Grid Team 521 | SOG | Planned for 2020 Completion |
| North Central | Jamestown | Orange | Self- Optimizing Grid Team 407 | SOG | Planned for 2020 Completion |
| North Central | Jamestown | Orange | Self- Optimizing Grid Team 434 | SOG | Planned for 2020 Completion |
| North Coastal | Ocala | Marion | Self- Optimizing Grid Team 527 | SOG | Planned for 2020 Completion |
| South Central | Buena Vista | Polk/Osceola | Self- Optimizing Grid Team 427 | SOG | Planned for 2020 Completion |
| North Central | Deland | Volusia | W902- Pierson-Seville Grid Strengthening Project | Deteriorated Conductor | Planned for 2020 Completion |
| North Coastal | Ocala | Marion | A202- Zuber- Country Rd 326 Grid Strengthening Project | Deteriorated Conductor | Completed 2019 |
| South Coastal | Clearwater | Pinellas | C104- Dunedin High and Highlander park Grid Strengthening Project | Deteriorated Conductor | Planned for 2020 Completion |
| South Central | SE Orlando | Orange | W392- Seminole Drive & Nela Ave Grid Strengthening Project | Deteriorated Conductor | Planned for 2020 Completion |
| South Central | Winter Garden | Orange | M342 Meadowbrook Ave | Deteriorated Conductor | Planned for 2020 Completion |
| North Central | Deland | Volusia | W4564 El Dorado Dr | Deteriorated Conductor | Completed 2019 |
| North Central | Apopka | Lake | M1517 S Fish Camp Rd | Deteriorated Conductor | Planned for 2020 Completion |
| North Central | Apopka | Orange | M707 W Highland Ave | Deteriorated Conductor | Completed 2019 |
| South Central | Buena Vista | Osceola | K881 North Goodman Rd | Deteriorated Conductor | Completed 2019 |
| South Central | Lake Wales | Polk | K8 Horseshoe Creek Rd | Deteriorated Conductor | Completed 2019 |
| North Central | Apopka | Orange | M0554 Ustler Rd | Deteriorated Conductor | Completed 2019 |
| South Central | Lake Wales | Polk | K3245 Water Tank Rd | Deteriorated Conductor | Planned for 2020 Completion |
| North Central | Deland | Volusia | W1703 S Blue Lake Ave | Deteriorated Conductor | Completed 2019 |
| North Central | Jamestown | Orange | W0250 Murdock Blvd | Deteriorated Conductor | Completed 2020 |
| North Central | Deland | Volusia | W0382 S Stone St | Deteriorated Conductor | Planned for 2020 Completion |
| North Central | Apopka | Orange | M417 Pine St | Deteriorated Conductor | Completed 2019 |
| North Coastal | Ocala | Marion | A51 134th Ave Micanopy | Deteriorated Conductor | Planned for 2020 Completion |
| North Central | Deland | Volusia | W4561 S Leavitt Ave | Deteriorated Conductor | Completed 2019 |
| North Central | Deland | Volusia | W4556 Dogwood Ave | Deteriorated Conductor | Completed 2019 |
| North Central | Apopka | Orange | M723 E Cleveland St | Deteriorated Conductor | Planned for 2020 Completion |
| North Central | Deland | Volusia | W1109 N Amelia Ave | Deteriorated Conductor | Completed 2019 |
| North Central | Deland | Volusia | W1110 S Virginia Ave | Deteriorated Conductor | Planned for 2020 Completion |
| North Central | Apopka | Orange | M402 Grace St | Deteriorated Conductor | Planned for 2020 Completion |
| North Central | Apopka | Orange | M33 Zellwood M33 Duda Rd | Deteriorated Conductor | Planned for 2020 Completion |
| South Coastal | Seven Springs | Pinellas | C303 N Spring Blvd & Pampas Ave | Deteriorated Conductor | Planned for 2020 Completion |
| North Central | Apopka | Lake | M1518 Harbor Shores | Deteriorated Conductor | Planned for 2020 Completion |
| North Central | Apopka | Orange | M400- West Lockhart Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| South Central | Buena Vista | Orange | K925- Sand Lake I-Drive Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| South Central | Highlands | Polk | K3205- North Fort Meade Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| North Central | Apopka | Lake | M580 - Tavares East Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Central | Apopka | Seminole | M1709 - Douglas Ave Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| North Central | Apopka | Lake | M1054 - Eustis South Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Central | Apopka | Orange | M33 - Zellwood Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Central | Apopka | Seminole | M476 - Piedmont Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |

| | | | | | |
|---------------|----------------|-----------|-----------------------------------------------------------------------|------------------------|-----------------------------|
| South Central | Buena Vista | Polk | K425 - Westridge Transformer Strengthening Project | Transformer Retrofit | Completed 2020 |
| South Central | SE Orlando | Orange | W0494 - Central Park Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| South Central | SE Orlando | Osceola | W0629 - Holopaw Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| South Central | SE Orlando | Osceola | W0630 - Holopaw Transformer Strengthening Project | Transformer Retrofit | Completed 2020 |
| South Central | SE Orlando | Orange | W0500 - Central Park Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| South Central | SE Orlando | Orange | K1024 - Taft Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| South Central | SE Orlando | Orange | K1025 - Taft Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| South Central | SE Orlando | Osceola | W0105 - Canoe Creek Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Central | Longwood | Orange | M81 - Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| South Central | Highlands | Highlands | K1684 - Dinner Lake Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| South Central | Highlands | Polk | K171 - Fort Meade Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| North Coastal | Inverness | Citrus | A271 - Homosassa Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| North Coastal | Inverness | Marion | A112 - Ross Prairie Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| South Central | Buena Vista | Orange | K1411 - Four Corners Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| South Central | Lake Wales | Osceola | K1614 - Cabbage Island Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| South Central | Lake Wales | Polk | K1196 - Babson Park Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| South Central | Lake Wales | Polk | K1195 - Babson Park Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| South Central | Lake Wales | Polk | K19 - Haines City Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Central | Deland | Volusia | W1107 - Deland East Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Central | Longwood | Seminole | M662 - Spring Lake Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Central | Longwood | Seminole | M145 - Longwood Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Central | Longwood | Seminole | M659 - Myrtle Lake Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| North Central | Longwood | Orange | M1137 - Eatonville Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Coastal | Monticello | Gulf | N201 - Port St. Joe Ind. Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| North Coastal | Monticello | Gulf | N55 - Port St. Joe Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| North Coastal | Monticello | Alachua | A144 - Alachua Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| North Coastal | Monticello | Taylor | N7 - Perry Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Coastal | Monticello | Taylor | N14 - Perry Northwest Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| North Coastal | Monticello | Taylor | N8 - Perry Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Coastal | Monticello | Suwannee | A192 - Luraville Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Coastal | Monticello | Columbia | A20 - Fort White Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Coastal | Monticello | Jefferson | N67 - Monticello Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Coastal | Monticello | Jefferson | N66 - Monticello Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Coastal | Monticello | Alachua | A186 - GE Alachua Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Coastal | Monticello | Jefferson | N69 - Monticello Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| North Coastal | Ocala | Marion | A128 - Silver Springs Shores Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| South Coastal | St Petersburg | Pinellas | X265 - Central Plaza Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| South Coastal | St. Petersburg | Pinellas | X282 - Northeast Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| South Coastal | Walsingham | Pinellas | J114 - Starkey Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| South Coastal | Walsingham | Pinellas | X123 - Gateway Transformer Strengthening Project | Transformer Retrofit | Completed 2019 |
| South Central | Winter Garden | Orange | M339 - Clarcona Transformer Strengthening Project | Transformer Retrofit | Planned for 2020 Completion |
| South Central | Buena Vista | Orange | Live front to Deadfront Switchgear Replacement- 6418272 | Switchgear Replacement | Completed 2019 |
| South Central | Buena Vista | Orange | Live front to Deadfront Switchgear Replacement- 8003405 | Switchgear Replacement | Planned for 2021 completion |
| South Central | Buena Vista | Orange | Live front to Deadfront Switchgear Replacement- 8003486 (K4051/K4050) | Switchgear Replacement | Completed 2019 |
| South Central | Buena Vista | Osceola | Live front to Deadfront Switchgear Replacement 8012875 | Switchgear Replacement | Completed 2019 |
| South Central | Buena Vista | Osceola | Live front to Deadfront Switchgear Replacement 8012876 | Switchgear Replacement | Completed 2019 |
| South Central | Buena Vista | Orange | Live front to Deadfront Switchgear Replacement 8012911 | Switchgear Replacement | Completed 2019 |
| South Central | Buena Vista | Orange | Live front to Deadfront Switchgear Replacement 7837709 | Switchgear Replacement | Completed 2019 |
| South Central | Buena Vista | Orange | Live front to Deadfront Switchgear Replacement 7989918 | Switchgear Replacement | Completed 2019 |
| South Central | Buena Vista | Orange | Live front to Deadfront Switchgear Replacement 7837708 | Switchgear Replacement | Completed 2019 |
| South Central | SEO | Orange | Live front to Deadfront Switchgear Replacement W95249 | Switchgear Replacement | Completed 2019 |
| South Coastal | Clearwater | Pinellas | Live front to Deadfront Switchgear Replacement 6346731 | Switchgear Replacement | Completed 2019 |
| South Coastal | Clearwater | Pinellas | Live front to Deadfront Switchgear Replacement 7823366 | Switchgear Replacement | Completed 2020 |
| South Coastal | Seven Springs | Pasco | Live front to Deadfront Switchgear Replacement 6524810 | Switchgear Replacement | Completed 2019 |
| North Coastal | Inverness | Citrus | Live front to Deadfront Switchgear Replacement 8006311 | Switchgear Replacement | Planned for 2020 Completion |
| North Coastal | Inverness | Marion | Live front to Deadfront Switchgear Replacement 8012466 | Switchgear Replacement | Planned for 2020 Completion |
| North Coastal | Inverness | Citrus | Live front to Deadfront Switchgear Replacement 6524812 | Switchgear Replacement | Planned for 2020 Completion |
| North Coastal | Inverness | Citrus | Live front to Deadfront Switchgear Replacement 6164434 | Switchgear Replacement | Planned for 2020 Completion |
| North Coastal | Inverness | Citrus | Live front to Deadfront Switchgear Replacement 8006321 | Switchgear Replacement | Planned for 2020 Completion |
| North Coastal | Ocala | Sumter | Live front to Deadfront Switchgear Replacement 8012605 | Switchgear Replacement | Planned for 2020 Completion |
| North Central | Apopka | Orange | Live front to Deadfront Switchgear Replacement 6709265 | Switchgear Replacement | Completed 2019 |
| North Central | Apopka | Orange | Live front to Deadfront Switchgear Replacement 6487590 | Switchgear Replacement | Completed 2019 |
| North Central | Jamestown | Orange | Live front to Deadfront Switchgear Replacement 8012155 | Switchgear Replacement | Completed 2019 |
| North Central | Jamestown | Orange | Live front to Deadfront Switchgear Replacement 8012147 | Switchgear Replacement | Planned for 2020 Completion |
| North Central | Jamestown | Orange | Live front to Deadfront Switchgear Replacement 8012153 | Switchgear Replacement | Completed 2019 |
| North Central | Jamestown | Orange | Live front to Deadfront Switchgear Replacement 6858455 | Switchgear Replacement | Planned for 2020 Completion |
| North Central | Jamestown | Orange | Live front to Deadfront Switchgear Replacement 6096748 | Switchgear Replacement | Completed 2019 |
| North Central | Jamestown | Orange | Live front to Deadfront Switchgear Replacement 6096738 | Switchgear Replacement | Planned for 2020 completion |
| North Central | Jamestown | Orange | Live front to Deadfront Switchgear Replacement 8012164 | Switchgear Replacement | Completed 2019 |
| North Central | Jamestown | Orange | Live front to Deadfront Switchgear Replacement 6096737 | Switchgear Replacement | Completed 2019 |
| North Central | Jamestown | Orange | Live front to Deadfront Switchgear Replacement 6173451 | Switchgear Replacement | Completed 2019 |
| North Central | Jamestown | Orange | Live front to Deadfront Switchgear Replacement 8011899 | Switchgear Replacement | Completed 2019 |
| South Central | Winter Garden | Orange | Live front to Deadfront Switchgear Replacement 8012720 | Switchgear Replacement | Completed 2019 |
| South Central | Winter Garden | Orange | Live front to Deadfront Switchgear Replacement 8012721 | Switchgear Replacement | Completed 2019 |
| South Central | Winter Garden | Orange | Live front to Deadfront Switchgear Replacement 8012753 | Switchgear Replacement | Completed 2019 |
| North Coastal | Ocala | Lake | Live front to Deadfront Switchgear Replacement 8012609 | Switchgear Replacement | Completed 2019 |
| North Central | Jamestown | Orange | Live front to Deadfront Switchgear Replacement 6221394 | Switchgear Replacement | Completed 2019 |
| South Central | Winter Garden | Orange | Live front to Deadfront Switchgear Replacement 8012920 | Switchgear Replacement | Planned for 2020 Completion |

Attachment J

I. Introduction:

Rule 25-6.0342, Florida Administrative Code, requires investor-owned electric utilities in Florida to file a Storm Hardening Plan with the Florida Public Service Commission (“FPSC”) no later than 90 days after the effective date of the rule, and every 3 years as a matter of course. Rule 25-6.0342 specifies what must be included in utility storm hardening plans, and Duke Energy Florida (“DEF”) has tracked those rule provisions in its Storm Hardening Plan below:

25-6.0342(3): *Each utility storm hardening plan shall contain a detailed description of the construction standards, policies, and procedures employed to enhance the reliability of overhead and underground electrical transmission and distribution facilities.*

DEF’s construction standards, policies, practices, and procedures related to storm hardening issues are listed below and are attached hereto as **Attachment A:**

Distribution Standards Manual

- i. General Overhead section
 - 1. *Details Florida’s extreme wind contour lines.*
 - 2. *Discusses the use of the Pole Foreman program.*
 - 3. *Details Florida’s extreme wind contour lines.*
 - 4. *Discusses the use of the Pole Foreman program.*
- ii. Addresses NESC adherence standards
- iii. Poles, Guys and Anchors Section
 - 1. *Discusses DEF’s standard pole strengths, sizes, and limitations*
- iv. Primary Construction section
 - 1. *Discusses corporate practices for primary line construction.*
- v. Coastal and Contaminated area section
 - 1. *Discusses corporate practices for primary line construction in coastal areas.*
- vi. Underground General Section

- 1. Discusses location of UG facilities in accessible locations.*
- vii. OH-UG Transition section
 - 1. Discusses corporate practices for primary framing on dip poles.*
- viii. Trenching and Conduit section
 - 1. Discusses corporate practices for trenching and use of conduit on primary UG circuits.*
- ix. Flooding and Storm Surge Requirements
 - 1. Discusses corporate procedures for the installation of UG equipment in areas targeted for storm surge hardening.*

Joint Use – Pole Attachment Guidelines and Clearances

- x. Pole Attachment Guidelines
 - 1. Addresses Pole Attachment and Overlash Procedures.*
 - 2. Addresses Joint Use Construction.*
 - 3. Addresses Guys and Anchors.*
- xi. Joint Use Clearances
 - 1. Addresses Line Clearances.*
 - 2. Addresses Joint Use Clearances.*

Distribution Engineering Manual

- xii. Overhead Design guide section
 - 1. Addresses line location in accessible location.*
 - 2. Addresses NESC compliance.*
 - 3. Discusses Pole Foreman program.*
- xiii. Underground Design guide section
 - 1. Addresses line location in accessible location.*
 - 2. Addresses NESC compliance.*

Transmission - Extreme Wind Loading Design Criteria Guideline for Overhead Transmission Line Structures

- xiv. Standards Position Statement
 - 1. Addresses NESC compliance.*

2. *Addresses American Society of Civil Engineer's Manual 74 (ACSE 74).*
3. *Discusses transmission line importance for reliability.*
4. *Details Florida's extreme wind contour lines.*

Transmission - Line Engineering Design Philosophy

- xv. Overhead Line Design philosophy
 1. *Addresses NESC compliance.*
 2. *Addresses insulator loading criteria.*
 3. *Addresses guy / anchor capacity ratings.*
 4. *Addresses design load cases.*
 5. *Addresses extreme wind guidelines.*
 6. *Addresses structural guidelines.*

In addition to the standards, practices, policies, and procedures identified above, DEF's Wood Pole Inspection Plan, Vegetation Management Plan, and Storm Hardening Plan, all contain standards, practices, policies, and procedures that address system reliability and issues related to extreme weather events. These plans are included herewith as **Attachment B**. In the recent years DEF has enhanced the standards to allow for better reliability, shorten restoration time and lower cost of construction. Some of these enhancements include increase the Basic Insulation Level (BIL) of new construction by increasing spacing between conductors, and increasing the insulators from 15kV to 25kV. Increasing the BIL lowers the opportunity of flashovers and outages due to vegetation crossing phases. DEF has also changed from using wood cross arms to fiberglass cross arms which allow for longevity and less chances of failure during storm due to the stronger material and not rotting due to weather. Duke Energy has also rolled these standards changes enterprise wide to lower cost and allow faster restoration when line techs from other Duke Energy jurisdictions respond to storm restoration in another area as they are familiar with the construction. DEF continuously monitors changes to NESC standards and meets and exceeds those standards as they are adopted in FL.

25-6.0342(3)(a): *Each filing shall, at a minimum, address the extent to which the utility's storm hardening plan complies, at a minimum, with the National Electric Safety Code that is applicable pursuant to subsection 25-6.0345(2), F.A.C.*

All standards, practices, policies, and procedures in the manuals and plans listed above are based on accepted industry practices designed to meet or exceed the requirements of the National Electric Safety Code (NESC). These standards, practices, policies, and procedures are followed on all new construction and all rebuilding and relocations of existing facilities.

25-6.0342(3)(b): *Each filing shall, at a minimum, address the extent to which the utility's storm hardening plan adopts the extreme wind loading standards specified by Figure 250-2(d) of the 2007 edition of the NESC for new construction, major planned work, and critical infrastructure.*

New Construction:

With respect to new construction for transmission poles, DEF's transmission department is building all new construction with either steel or concrete pole material. Virtually all new transmission structures exceed a height of sixty feet above ground and therefore will be constructed using the NESC Extreme Wind Loading criteria.

DEF's design standards can be summarized as: 1) quality construction in adherence with current NESC requirements 2) well defined and consistently executed maintenance plans, and 3) prudent end-of-life equipment replacement programs. When these elements are coupled with a sound and practiced emergency response plan, construction grades as defined by the NESC provide the best balance between cost and performance.

DEF has extensive experience with the performance of Grade C and Grade B construction standards as defined by the NESC. That experience, which includes several hurricane seasons and other severe weather events, indicates that properly constructed and maintained distribution lines meeting all provisions of the NESC perform satisfactorily and provide a prudent and responsible balance between cost and performance.

DEF has not adopted extreme wind standards for all new distribution construction because of the following reasons:

1. Section 250C of the 2007 version of the NESC does not call for the extreme wind design standard for distribution poles which are less than sixty feet in height. Because DEF's distribution poles are less than sixty feet, the extreme wind standard outlined in figure 250-2(d) does not apply.
2. All credible research, which includes extensive studies by the NESC rules committee, demonstrates that applying extreme winds standards would not benefit distribution poles. See Exhibit 4 filed in Docket No. 060172-EU, August 31, 2006 Workshop.
3. Utility experience from around the country further indicates that electrical distribution structures less than sixty feet in height are damaged in extreme wind events by trees, tree limbs, and other flying debris. Thus, applying the extreme wind standard to distribution poles would result in large increases in cost and design complexity without a commensurate benefit.
4. DEF's experience was consistent with that of the other utilities around the nation who found that vegetation and flying debris were the main causes of distribution pole damage, a condition that the extreme wind standard will not address. During Hurricane Irma at least 72% of DEF's pole failures had vegetation involved.

Major planned work:

Consistent with NESC Rule 250C, DEF will use the extreme wind standard for all major planned transmission work, including expansions, rebuilds, and relocations of existing facilities. For the reasons discussed in the new construction section above, DEF has not adopted the extreme wind standard for major planned distribution work, including expansions, rebuilds, or relocations of existing facilities.

Critical infrastructure:

With respect to transmission, virtually all new transmission structures exceed a height of sixty feet above ground and therefore are constructed using the NESC extreme wind loading criteria. Accordingly, Duke will use the extreme wind standard for all major planned transmission work, including expansions, rebuilds, and relocations of existing facilities, irrespective of whether they can be classified as "critical" or "major."

DEF, for the reasons discussed in the new construction section above, has not adopted the extreme wind standard for any of its distribution level critical infrastructure. Placing distribution poles constructed to extreme wind standards around facilities such as hospitals and police stations in DEF's service territory would unnecessarily increase costs and restoration time if those poles are knocked down by falling trees or flying debris such as roofs or signs. DEF's current level of construction, around critical facilities and around all other facilities, has performed well during weather events. DEF Transmission storm hardening initiatives proved effective in that there were no storm hardened structure failures during the 2017 and 2018 Hurricanes that hit Florida.

While no current data or research supports the application of the extreme wind standard to distribution pole construction, DEF is analyzing the extreme wind standard by using its prioritization model for implementation purposes in selected locations throughout its service territory. In conjunction with wind measuring devices, DEF will study the performance of the extreme wind standard at these various sites when a weather event allows for such analysis. From this process, DEF expects to continue to learn and adjust its extreme weather strategy based on information that it will collect and gather from other utilities in Florida and throughout the nation as new standards and applications are applied and tested. After Hurricane Michael, ten Storm Hardened projects – including an Extreme Wind pilot project - were forensically assessed. No broken poles were identified on the Cape San Blas Extreme Wind project; similar results were observed on the other nine projects with only four total broken poles. Several poles along the coastline were leaning badly as a result of the beach shoring and road infrastructure being washed out. Overall, the portions of the system that were Storm Hardened performed well during Hurricane Michael and there was no evidence that Extreme Wind was significantly better than the other project types.

25-6.0342(3)(c): *Each filing shall, at a minimum, address the extent to which the utility's storm hardening plan is designed to mitigate damage to underground and supporting overhead transmission and distribution facilities due to flooding and storm surges.*


In areas where underground equipment may be exposed to minor storm surge and/or

shorter-term water intrusion, DEF has used its prioritization model (discussed in detail below) to identify areas where certain mitigation projects will be put into place to test whether flood mitigation techniques and devices can be used to protect equipment such as switchgears, pad mounted transformers and pedestals. In these selected project sites, DEF will test:

- Stainless steel equipment;
- Submersible connectors;
- Raised mounting boxes;
- Cold shrink sealing tubes; and
- Submersible secondary blocks.

Throughout the year after a significant weather event, DEF will monitor these installations to collect and analyze data to determine how this equipment performs relative to DEF's current design with respect to outage prevention, reduced maintenance, and reduced restoration times. From this process, DEF will continue to learn and will adapt its flood and storm surge strategies based on information that it will collect and based on the information gathered by other utilities in Florida and throughout the nation as new standards and applications are applied and tested.

DEF now utilizes ESRI's ArcGIS software to determine the optimum location for submersible underground facilities. The flood zones were provided by the state and overlaid onto DEF's land base computer system along with other facilities. This method allows DEF to visually determine which geographic areas would most benefit from submersible facilities. See example below.



In addition to the actions discussed above, during major storm events, substations that are in the forecast strike zone will be assessed, if the conditions exist, will have appropriate modes of protection strategically placed around substations/control houses. Those modes of protection include but are not limited to sand bagging, dam-systems, and other flood substation protection equipment. Mobile substations are utilized where applicable to assist restoration.

25-6.0342(3)(d): *Each filing shall, at a minimum, address the extent to which the utility’s storm hardening plan provides for the placement of new and replacement distribution facilities so as to facilitate safe and efficient access for installation and maintenance pursuant to Rule 25-6.0341, F.A.C.*

DEF will continue to use front lot construction for all new distribution facilities and all replacement distribution facilities unless a specific operational, safety, or other site-specific reason exists for not using such construction at a given location. See Distribution Engineering Manual, Page 3.

25-6.0342(4): *Each utility storm hardening plan shall explain the systematic approach the utility will follow to achieve the desired objectives of enhancing reliability and reducing restoration costs and outage times associated with extreme weather events.*

As part of its systematic approach to storm hardening for the 2007-2009 Storm Hardening plan, DEF engaged industry expert Davies Consulting (“DCI”) in developing a comprehensive prioritization model that has helped Duke identify potential hardening projects, procedures, and strategies. DCI has worked with a number of utilities nationally to evaluate their power delivery system major storm preparedness. They have also evaluated options for infrastructure hardening to improve performance and reliability not only day-to-day, but also during major storms. Collaborating with DCI, DEF created an evaluation framework for various hardening options and prioritization of potential alternatives. Since 2007, the model has been improved and enhanced to better reflect the changes in DEF’s overall storm hardening strategy. New software technology such as ESRI’s ArcGIS will be incorporated into the model. As more data becomes available, DEF will continue to adjust its prioritization model as appropriate.

Using a similar evaluation framework for the 2019-2021 Storm Hardening plan, DEF prioritized its proposed projects based on various components that will be discussed in more detail below.

Under the foregoing components of the evaluation framework, the prioritization model is set up to analyze the following hardening alternatives for DEF:

DEF continues to invest in proactive system maintenance activities to improve the reliability and integrity of the system. DEF announced a \$25B investment (at the enterprise level) in the grid over 10 years as part of the Grid Investment Plan (GIP). DEF has begun this project in 2018 with programs including the Self-Optimizing Grid, Deteriorated Conductor, Transformer Retrofit and Targeted Underground. These programs are discussed in detail below.

- Targeted Underground Program

The primary purpose of this hardening activity is to attempt to eliminate tree and debris related outages in the area of exposure by converting heavily vegetated neighborhoods prone to power outages from overhead to underground construction to decrease outages, reduce momentary interruptions, improve major storm restoration time, improve customer satisfaction and reduce costs.
- Deteriorated Conductor Program
 - The primary purpose of this hardening activity is to replace over dutied overhead conductor on the system that is prone to outages due to its brittle composition, small load capacity and poor connection qualities. The GIP focuses on eliminating the small copper conductor with aluminum conductor to improve the overall reliability.
- Transformer Retrofit Program
 - The primary purpose of this hardening activity is to retrofit Completely-Self Protected (CSP) transformers to be locally fused. This work stream corrects common transformer reliability conditions by replacing aged or problematic fuse cutouts and adding fuses where they previously did not exist with more reliable equipment and bringing all associated transformer equipment up to current Duke Energy construction standards. CSP transformers that have not been retrofitted have been a frequent cause of upstream fuse outages. Once retrofitted these transformers would limit the number of customers impacted by transformer or service level issues. This outage mitigation will be accomplished by adding external fused cutouts, replacing bare copper wires with covered copper, and adding animal mitigation to these locations. The retrofitting of CSP transformers is being done in lieu of replacement as a cost-effective method of outage reduction for DEF customers in these locations.
- Self-Optimizing Grid Program

- The primary purpose of this hardening activity is to strategically utilize automated switching device (ASDs) and an automation program to isolate faults on the electric distribution system and automatically reconfigure the system to minimize the number of customers that experience sustained power outages. The Self-Optimizing Grid (SOG) program will transform the radial distribution system into an automated distribution network that provides:
 - 1) connectivity with automated switching,
 - 2) capacity on the circuits to allow most circuits to be restored from alternate sources,
 - 3) automated control with SCADA-enable ASDs to isolate faults and reconfigure the system and
 - 4) segmentation such that the distribution circuits have much smaller line segments, thus reducing the number of customers that are affected by outages.
- Live Front Switchgear Replacement Program
 - The primary purpose of this hardening activity is to replace aged Live Front Switchgear prior to failure. A switchgear is a pad mounted metal enclosure that contains switches and fuses used for switching underground circuits and underground fault isolation. This program will improve overall reliability, result in faster outage restoration and improve safety for those working in the switchgears.

Base programs include:

DEF continues to invest in proactive system maintenance activities to improve the reliability and integrity of the system. DEF is continuing its normal maintenance and reliability improvements through the following programs discussed in detail below:

- Backlot to Frontlot Conversion
 - Taking an existing overhead line located in the rear of a customer's property and relocating it to the front of the customers property. This involves the removal of the existing line in the rear of the property and construction of a new line in the front of the property along with re-

routing service drops to individual customer meters. The primary purpose of this hardening activity is to minimize the number of tree exposures to the line to prevent outages and to expedite the restoration process by allowing faster access in the event an outage occurs.

- Deteriorated Conductor
 - The primary purpose of this hardening activity is similar to the GIP program listed above but targets all over-dutied overhead conductor not just copper.
- Submersible UG
 - Taking an existing UG line and equipment and hardening it to withstand a storm surge via the use of the current DEF storm surge standards. This involves the use of specialized stainless-steel equipment and submersible connections. The primary purpose of this hardening activity is to attempt to minimize the damage caused by a storm surge to the equipment and thus expedite the restoration after the storm surge has receded.
- Feeder ties
 - Tying radial feeders together to provide switching capabilities to reduce outage duration. This hardening alternative will mitigate long outages that would have otherwise occurred as a result of the inability to transfer load/customers to an alternate source.

Although the concept of storm hardening is generally thought of as outage prevention, it is inevitable that outages will still occur during a severe storm as a result of, for example, vegetation and flying debris. Feeder ties will help mitigate the duration of such outages. Tying multiple feeders together will give DEF the ability to minimize duration by serving customers from an alternate source while repairs are being made on the affected segment. Based on DEF's experience in the 2004 -2005 hurricane seasons as well as the recent tropical storms and hurricanes, feeder ties are crucial for a distribution system as it provides the opportunity to maximize the number of customers restored in the shortest timeframe possible. Regardless of what caused the outage during a severe storm, a radial feeder will be out for as long as it takes to make the necessary repairs. On the other hand, a feeder tie would allow DEF to restore as many customers as possible, thereby minimizing the number of customers that are without power for the length of the repair.

The development of the prioritization model begins with compiling a list of desired projects submitted by engineers and field personnel most familiar with the specific region. Each project is then evaluated based on specific criteria listed below but mainly focuses on the historical reliability data from the outage management system (OMS) to determine the locations that would improve reliability on normal days, such as reducing customer interruption and outage duration. DEF then selects a list of projects to represent a sample of the programs listed above that best represents the overall system. These projects performance will be evaluated after storms to continuously improve the reliability and performance of the entire system. DEF also looks for opportunities to enhance the system that would reduce damages during a storm and allow power to be restored quicker. Other criteria considered is as follows:

- Major Storm Outage Reduction Impact
 - Determines the potential benefits that the project provides during a major storm based on reduced damages or the ability to restore power more rapidly.
- Community Storm Impact
 - Evaluates the potential benefits that the proposed project will have on a community's ability to cope with damage.
- Third Party Impact
 - Captures complexities of proposed projects in terms of coordination with third parties such as telecommunication, Cable TV, permitting, easements, costs, etc.
- Overall Reliability
 - Captures the overall potential reliability benefits that the project provides on a day to day basis in terms of reduced customer interruptions and outage duration.
- Financial Cost
 - Provides the financial value of the proposed project based on cost per customer and cost per foot of newly installed wire/cable.

The following hardening project questions are asked when developing projects:

- How many customers are served from the upstream protective device?

- What will be the impact of this project on the restoration time during a major storm?
- At what category of hurricane is the area served by this feeder expected to flood due to storm surges?
- What is the tree density in the area served by this feeder or section?
- What level of tree damage will this project mitigate during a major storm?
- How many critical infrastructure components (lift stations, shelters, hospitals, police, etc.) does this project address?
- How valuable will the project be perceived by the community?
- What are the major obstacles/risks for completing the project? i.e. easements, permits, etc.
- What type of investment is required by joint users (telecoms and cable) to complete this project?
- What is the 3-year average number of CEMI4 customers on this feeder?
- What is the 3-year average number of CMI on this feeder?
- What is the change in the annual SAIDI that this project could result in?
- What is the change in the annual SAIFI that this project could result in?
- What is the construction cost per customer?

25-6.0342(4)(a): *A description of the facilities affected, including technical design specifications, construction standards, and construction methodologies employed.*

All of DEF's facilities are affected to some degree by the standards, policies, procedures, practices, and applications discussed throughout this document. Specific facilities are also addressed herein in detail (i.e. upgrading all transmission poles to concrete and steel, using front lot construction for all new distribution lines where possible). Technical design specifications, construction standards, and construction methodologies are specifically discussed at pages 1 through 3 of this plan and are included in **Attachments A and B**.

25-6.0342(4)(b): *The communities and areas within the utility's service area where the electric infrastructure improvements are to be made.*

As discussed above, all of DEF’s facilities are affected to varying degrees by the standards, policies, procedures, practices, and applications discussed throughout this document. As a result, all areas of DEF’s service territory are impacted by DEF’s storm hardening efforts. Based on DEF’s recent storm experience and/or through the prioritization model a number of projects were identified, please see **Attachment D** for the Distribution Projects completed between 2007 and 2018.

Distribution:

The list below is a sampling of the proposed 2019 – 2021 Storm Hardening projects (please note, proposed hardening projects may or may not be completed during the timeframe, based on emergent work and other factors that cannot be foreseen in advance):

| Op Center | County | Project | Sub Category |
|---------------|----------|--------------------------------------------------|--------------------------------------------|
| Apopka | Seminole | M109 Smoke Rise Blvd Reliability | OH to UG Conversion/ Backlot Conversion |
| Apopka | Orange | M34 Dudley Ave Underground Conversion | OH to UG Conversion |
| Seven Springs | Pinellas | Tarpon Springs C305 Magnolia Heights Reconductor | Feeder Tie |
| St Petersburg | Pinellas | 52nd St Reconductor | Feeder Tie |
| Seven Springs | Pasco | Anclote Substation Bank 7 and Bank 8 Feeder Ties | Feeder Tie |
| Winter Garden | Orange | SR408 Crossing West of Good Homes | Overhead Line Crossing/Backlot |
| Clermont | Lake | Hancock Road Feeder Tie K4833_K4841 | Feeder Tie |
| SE Orlando | Orange | Meadow Woods S Feeder Tie K1789_K1775 | Feeder Tie |
| Inverness | Citrus | Storm Hardening Gasparilla Cay Subdivision | Submersible UG |
| Inverness | Citrus | Storm Hardening along Riverhaven Dr., Homosassa | Submersible UG |
| Monticello | Gulf | Feeder N55 tie to rest of Port St Joe Feeders | Feeder Tie |
| Deland | Volusia | W902- Pierson-Seville Grid Strengthening Project | Deteriorated Conductor |



Storm Hardening Plan

March 1, 2019

| | | | |
|-------------|----------------------|-----------------------------------------------------------------------|------------------------|
| Ocala | Marion | A202- Zuber- County Rd 326 Grid Strengthening Project | Deteriorated Conductor |
| Clearwater | Pinellas | C104- Dunedin High and Highlander park Grid Strengthening Project | Deteriorated Conductor |
| SE Orlando | Orange | W392- Seminole Drive & Nela Ave Grid Strengthening Project | Deteriorated Conductor |
| Apopka | Orange | M400- West Lockhart Transformer Strengthening Project | Transformer Retrofit |
| Buena Vista | Orange | K925- Sand Lake I-Drive Transformer Strengthening Project | Transformer Retrofit |
| Highlands | Polk | K3205- North Fort Meade Transformer Strengthening Project | Transformer Retrofit |
| Monticello | Taylor | N14- Perry Northwest Transformer Strengthening Project | Transformer Retrofit |
| Buena Vista | Orange | Live front to Deadfront Switchgear Replacement- 6418272 | Switchgear Replacement |
| Buena Vista | Orange | Live front to Deadfront Switchgear Replacement- 8003405 | Switchgear Replacement |
| Buena Vista | Orange | Live front to Deadfront Switchgear Replacement- 8003486 (K4051/K4050) | Switchgear Replacement |
| Jamestown | Orange | Self- Optimizing Grid Team 407 | SOG |
| Highlands | Highlands | Self- Optimizing Grid Team 408 | SOG |
| Apopka | Orange | Self- Optimizing Grid Team 412 | SOG |
| Monticello | Franklin/ Wakulla | Self- Optimizing Grid Team 505 | SOG |
| Buena Vista | Orange | TUG 442313600 Winwood Way | TUG |
| Monticello | Jefferson | TUG 442991878 Jefferson St | TUG |
| Inverness | Citrus | TUG 446946764 Juneau Point | TUG |
| Jamestown | Orange | TUG 444365498 Lake Pickett | TUG |

Regarding system hardening projects in general, DEF's approach is to consider the unique circumstances of each potential location considered for hardening by taking into account variables such as:

- operating history and environment;
- community impact and customer input;
- exposure to storm surge and flooding;



Storm Hardening Plan

March 1, 2019

- equipment condition;
- historical and forecast storm experience; and
- potential impacts on third parties;

This surgical approach leads to the best solution for each discrete segment of the delivery system.

Transmission:

The Transmission Department is employing a system-based approach to changing out wood poles to either concrete or steel poles based upon the inspection cycle and condition of pole. These projects are identified during the transmission pole inspection cycles. Specific new, rebuilt or relocated projects that are planned over the next three years are listed below:

| North Florida | | | |
|-----------------------------------------------------------------|---------------|-------------|--------------------|
| Project Name | County | Type | Third Party |
| Montverde to Winter Garden - 69 kV Line Rebuild | Lake | Rebuild | Yes |
| American Cement to Bushnell East - | Sumter | Rebuild/New | Yes |
| Eustis to Dona Vista 69 kV Line Rebuild | Lake | Rebuild | Yes |
| Oak Tap to Havana- New Rebuild 115KV Line | Gadsden | Rebuild | Yes |
| Idylwild - Wacahoota Tap (SI) - Rebuild 69 kV line (Two Phases) | Alachua | Rebuild | Yes |
| Williston - New 230/69 kV Substati | Levy | Rebuild/New | Yes |
| Eustis-Eustis South (EES) 69 kV Line Rebuild | Lake | Rebuild | Yes |
| New Powerline Sub Replacement with | Citrus | Rebuild/New | Yes |
| Deland West-Dona Vista - New 230 kV | Lake | Rebuild | Yes |
| Ginnie-Bell Tp (IS) Rebuild_Bell - | Gilchrist | Rebuild | Yes |



Storm Hardening Plan

March 1, 2019

| | | | |
|-------------------------------------------------------------------|----------|-------------|-----|
| Shady Hills - 230kV Line | Citrus | Rebuild | Yes |
| Coleman to Dixie Tap - 69 kV Line Rebuild | Sumter | Rebuild | Yes |
| Dallas to Orange Blossom - Rebuild 69 kV Line | Sumter | Rebuild | Yes |
| Central Florida to Federal - 69 kV Line Rebuild | Lake | Rebuild | Yes |
| Fort White-Luraville 69kV Line Rebuilds | Columbia | Rebuild | Yes |
| Alachua Tap to Hull Road 69kV Line | Alachua | Rebuild | Yes |
| Nobleton Tap-(SECO) Floral City Tap | Citrus | Rebuild | Yes |
| Central Florida - Picciola Tap 69kV Rebuild | Lake | Rebuild | Yes |
| Tallahassee to Oak City TAP Rebuild | Leon | Rebuild | Yes |
| Suwannee Springs 115kV Switching St | Suwannee | Rebuild/New | Yes |
| Lake Talquin-Brickyard 69kV Rebuild dbl-ckt-capable struc | Leon | Rebuild | Yes |
| Andersen to Wildwood City Tap - 69 kV Line Rebuild | Sumter | Rebuild | Yes |
| New 115kV Suwannee Transmission Sub | Suwannee | Rebuild/New | Yes |
| Florida OHG (Static) Replace | Hernando | Rebuild | Yes |
| Crawfordville - Carrabelle Rebuild as double circuit 115kV & 69kV | Wakulla | Rebuild | Yes |



Storm Hardening Plan

March 1, 2019

| | | | |
|------------------------------------------------------------|----------|------------------|----------|
| Ross Prairie to Marion Oaks Tap 69 kV Line Rebuild | Marion | Rebuild | Yes |
| Mondon Hill - New 230/115 kV Substa | Hernando | Rebuild/New | Yes |
| Dunnellon Town-Rainbow Spgs Tap | Marion | Rebuild | Yes |
| Rainbow Spgs Tp to Rainbow Lk - Reb | Marion | Rebuild | Yes |
| FLUOF | Alachua | Rebuild/New | Yes |
| Industrial Tap - New 15 Mvar Capaci | Lake | Customer Request | Possibly |
| FLGOV - 230T9 - DR-85 GOAB for FDOT | Marion | Governmental | Possibly |
| FLGOV - 1373T6 - MS-233 & MS-234 Ro | Marion | Governmental | Possibly |
| FLGOV - SR 44 BAILEY BRIDGE FOR THE | Sumter | Governmental | Possibly |
| FLGOV - SR 528 & Landstreet Boxout | Marion | Governmental | Possibly |
| FLGOV Citrus County Trail aka Withlacochee Dunnel 437349-1 | Citrus | Governmental | Possibly |
| Coleman to Federal - 69 kV Line Rebuild | Sumter | Governmental | Yes |
| FLGOV MS--67-6 to MS-67-7 SR 326 a | Marion | Governmental | Possibly |
| FLCUST Univ of FL AUF Relocation - | Alachua | Customer Request | Yes |
| US-27 Road Widening - CLC-48A Stub | Lake | Governmental | Possibly |



Storm Hardening Plan

March 1, 2019

| | | | |
|--------------------------------------------------------------------------|----------|------------------|----------|
| FLGOV CLC-73 69kV Fosgate Road at US 27 Lake County contains D-Line Work | Lake | Governmental | Possibly |
| FLGOV MS--67-6 to MS-67-7 69kV SR 326 at CR 25A- FPID 435660-2 | Marion | Governmental | Possibly |
| Old Town North Sub to Cross City Su | Dixie | Rebuild | Yes |
| Brooksville West - Loop in Brookrid | Hernando | Rebuild/New | Possibly |
| Fort White - Replace/Upgrade 115kV | Columbia | Rebuild | Yes |
| Suwannee Transmission Substation 23 | Suwannee | Rebuild/New | Possibly |
| Tallahassee - new 115 kV Yard (New | Leon | Rebuild/New | Yes |
| Install 230/115kV Transformer at Fo | Columbia | Rebuild/New | Possibly |
| TRMP GP (Buckeye) Foley Substation | Taylor | Customer Request | Yes |
| Florida Portfolio of Governmental P | Lake | Customer Request | Possibly |
| Florida Portfolio of Governmental P | Sumter | Governmental | Possibly |
| Florida Portfolio of Governmental P | Sumter | Customer Request | Possibly |
| Florida Portfolio of Governmental P | Hernando | Governmental | Possibly |
| Florida Portfolio of Governmental P | Lake | Governmental | Possibly |
| Florida Portfolio of Governmental P | Hernando | Customer Request | Possibly |



Storm Hardening Plan

March 1, 2019

| | | | |
|-------------------------------------|--------|--------------|----------|
| Florida Portfolio of Governmental P | Marion | Governmental | Possibly |
|-------------------------------------|--------|--------------|----------|

| South Florida | | | |
|-----------------------------------------------------------------------------|---------------|------------------|--------------------|
| Project Name | County | Type | Third Party |
| 60KK8D 285T9 FAIRBANKS | Orange | Customer Request | Yes |
| Northridge to West Davenport - New | Polk | Rebuild | Yes |
| TRMP-2098D1-FGT East - Relay Upgrad | Orange | Rebuild | Yes |
| Bithlo to UCF 69kv Line rebuild | Orange | Rebuild | Yes |
| West Chapman to Winter Park East 69 | Seminole | Rebuild | Yes |
| Oviedo to Winter Springs - 69 kV Line Rebuild | Seminole | Rebuild | Yes |
| Wire Road - New River 230kV Line & 69kV Line Rebuild (formerly Zephyrhills) | Pasco | Rebuild/New | Yes |
| Rio Pinar to Econ to Winter Park East - 230 kV Line Rebuild | Orange | Rebuild | Yes |
| Keystone - New 230-115 kV Substatio | Pinellas | Rebuild | Yes |
| Gateway to 32nd Street (HD-7) - 115 | Pinellas | Rebuild | Yes |
| 40th Street to 16th Street (BFE-2) - 115 kV Line Rebuild | Pinellas | Rebuild | Yes |
| Bayview to East Clearwater (HD-3) - 115 kV Line Rebuild | Pinellas | Rebuild | Yes |



Storm Hardening Plan

March 1, 2019

| | | | |
|--------------------------------------------------|----------|------------------|-----|
| Bayboro Site Purchase | Pinellas | Rebuild/New | Yes |
| North Longwood-Sylvan 230kV (NLSX); | Seminole | Rebuild | Yes |
| Myrtle Lake - Wekiva 230kV Line Rebuild | Seminole | Rebuild | Yes |
| Piedmont - Wekiva 230kV Line Rebuild | Seminole | Rebuild | Yes |
| Vandolah to Whidden - 230 kV Line Rebuild | Hardee | Rebuild/New | Yes |
| West Lake Wales to Lake Wales 69 kV | Polk | Rebuild | Yes |
| Continental - Loop SECO Substation | Hardee | Customer Request | Yes |
| TRMP Ulmerton to Tri-City - 115 kV | Pinellas | Rebuild/New | Yes |
| TRMP 2078 DISSTON-STARKEY RD | Pinellas | Rebuild/New | Yes |
| Hemple to Ocoee 69 kV Line Rebuild | Orange | Rebuild | Yes |
| Deleon Springs to Barberville - 115 | Volusia | Rebuild | Yes |
| Fort Meade to West Lake Wales Line Rebuild | Polk | Rebuild | Yes |
| TRMP-2568 ZUBER INC CAP | Pasco | Rebuild | Yes |
| Gateway to Ulmerton (HD-6) - 115 kV Line Rebuild | Pinellas | Rebuild | Yes |
| Dry Prairie - 230/69kV Substation | Hardee | Rebuild/New | Yes |

| | | | |
|--------------------------------------------------------------------------------------------------------------------------|-----------|------------------|----------|
| Intercession City - Rebuild Interce | Osceola | Rebuild | Yes |
| Lake Aloma to Winter Park East - 69 | Orange | Rebuild | Yes |
| Conway to Pinecastle - 69 kV Line Rebuild | Orange | Rebuild | Yes |
| Haines City East to Poinciana 69 kV | Polk | Rebuild | Yes |
| Davenport to Haines City 69 kV Rebu | Polk | Rebuild | Yes |
| Haines City to Haines City East 69 | Polk | Rebuild | Yes |
| FLGOV 69kV DWB-169 to 181 and DWB-127-6 SR 15 (US 17) from Ponce De Leon Boulevard to East of SR 40, FPID: 410251-1-52-0 | Volusia | Governmental | Possibly |
| FLGOV - 305T8 - AD-18-20,63,64 Sebr | Highlands | Governmental | Possibly |
| FLGOV - 341T2 - AFC-12 Sebring Pkwy | Highlands | Governmental | Possibly |
| FLGOV - 967T4 - WR & RW 69kV Reloca | Orange | Governmental | Possibly |
| FLGOV - POWERLINE ICLW & HP Road Co | Polk | Governmental | Possibly |
| FLGOV - DWB-127-6 Str Relocation fo | Volusia | Governmental | Possibly |
| FLCUST - AUCF-83 Relocate for Dolla | Seminole | Customer Request | Possibly |
| FLGOV-AL-5 to AL-7, US 27 (SR 25) a | Polk | Governmental | Possibly |
| FLCUST WLB-22 to WLB-31 UNIVERSAL OH to UG Conversion | Orange | Customer Request | Possibly |



Storm Hardening Plan

March 1, 2019

| | | | |
|---------------------------------------------------------------------------|----------|------------------|----------|
| Oakhurst to Seminole 69kV Rebuild | Pinellas | Rebuild | Yes |
| Largo to Ulmerton West 69kV Rebuild | Pinellas | Rebuild | Yes |
| Sky Lake to Meadow Woods South - New 230 kV Line & 69 kV Line Rebuilds | Orange | Rebuild/New | Yes |
| Magnolia Ranch to Moss Park -69kV L | Orange | Rebuild | yes |
| Celebration to Lake Wilson - 69kV L | Osceola | Rebuild | Yes |
| Lake Bryan to Orangewood - 69kV Lin | Orange | Rebuild | Yes |
| 410755-2 Bayway Structures Removals | Pinellas | Governmental | Possibly |
| FLGOV West French Ave Pedestrian Bridge ~ | Volusia | Governmental | Possibly |
| FLCUST BFE 52 & BFE 53 115kV DevMar | Pinellas | Customer Request | Possibly |
| FLGOV WO 69kV I-4 Ultimate, Wymore | Orange | Governmental | Possibly |
| FLGOV DWL 230kV DWL & WLLW-SR 60 R/R Overpass @ West Lake Wales Sub | Polk | Governmental | Possibly |
| FLGOV AL-5 to AL-7 69kV US 27 (SR 25) at SR 60- FPID 419243-4-52-01 | Polk | Governmental | Possibly |
| FLGOV SLE 69kV Relocation for Kennedy Blvd Widening (Orange Cnty) | Orange | Governmental | Possibly |
| 605EBD-967T4 WR &RW RELOCATION | Orange | Customer Request | Possibly |
| 60KK8-1967T2 SLM RELO @ KEN | Orange | Customer Request | Possibly |



Storm Hardening Plan

March 1, 2019

| | | | |
|--------------------------------------------------|----------|------------------|----------|
| 60KK8-1967T3 WO RELO @ KEN | Orange | Customer Request | Possibly |
| 605EBD_287T4_WF-63-77-69KV | Seminole | Customer Request | Possibly |
| Largo to Taylor Ave (LTW-1) 69kV Li | Pinellas | Rebuild | Yes |
| Belleair to Largo (LECW-1) - 69 kV Line Rebuild | Pinellas | Rebuild | Yes |
| Lake Bryan to Vineland - 69 kV Line rebuild | Orange | Rebuild | Yes |
| Keller Road - Spring Lake 69kV Line Rebuild | Seminole | Rebuild | Yes |
| Rio Pinar to FGT East 69kv Line Rebuild | Orange | Rebuild | Yes |
| Rio Pinar to Curry Ford (RX) 230 kV Line Rebuild | Orange | Rebuild | Yes |
| Hudson-Golden Acres-New Port Richey | Pasco | Rebuild | Yes |
| Fort Meade - New 69kV Terminal, Ins | Polk | Customer Request | Possibly |
| 32nd Street - Feeder Additions and | Pinellas | Rebuild | Possibly |
| Pilsbury 115kV Series Reactor | Pinellas | Rebuild/New | Possibly |
| Bonnet Creek to Intercession City | Osceola | Rebuild | Yes |
| Barnum City to Westridge - 69 kV Line Rebuild | Polk | Rebuild | Yes |
| TRMP Bayview to Tri-City - 115 kV L | Pinellas | Rebuild/New | Yes |



Storm Hardening Plan

March 1, 2019

| | | | |
|-------------------------------------|----------|------------------|----------|
| TRMP Winter Springs to Sanford/Poin | Seminole | Rebuild | Yes |
| Horse Creek Upgrades to 2,000 amps | Hardee | Customer Request | Possibly |
| Myrtle Lake - NLSX Rebuild | Seminole | Rebuild | Yes |
| Florida Portfolio of Governmental P | Seminole | Customer Request | Possibly |
| Florida Portfolio of Governmental P | Orange | Governmental | Possibly |
| Florida Portfolio of Governmental P | Pinellas | Governmental | Possibly |
| Florida Portfolio of Governmental P | Seminole | Customer Request | Possibly |
| Florida Portfolio of Governmental P | Orange | Governmental | Possibly |
| Florida Portfolio of Governmental P | Seminole | Customer Request | Possibly |
| Florida Portfolio of Governmental P | Orange | Customer Request | Possibly |
| Florida Portfolio of Governmental P | Pinellas | Governmental | Possibly |
| Florida Portfolio of Governmental P | Orange | Governmental | Possibly |
| Florida Portfolio of Governmental P | Seminole | Customer Request | Possibly |
| Florida Portfolio of Governmental P | Pinellas | Customer Request | Possibly |
| Florida Portfolio of Governmental P | Polk | Governmental | Possibly |



Storm Hardening Plan

March 1, 2019

| | | | |
|-------------------------------------|----------|------------------|----------|
| Florida Portfolio of Governmental P | Orange | Governmental | Possibly |
| Florida Portfolio of Governmental P | Pinellas | Governmental | Possibly |
| Daetwyler Drive Customer Relocation | Pinellas | Customer Request | Possibly |

25-6.0342(4)(c): *The extent to which the electric infrastructure improvements involve joint use facilities on which third-party attachments exist.*

In the description of specific hardening projects above, DEF has provided information as to whether the projects involve joint use facilities on which third-party attachments exist. Since 2009, all joint use poles changed out in support of Rule 25-6.0342(6) are scheduled within the company work management system. Communication carriers are notified at the time of the pole change out that transfers are needed. This process is in line with the other company pole maintenance programs and the cost to the communication carriers is minimized. DEF completed the required inspection of every joint use pole on the system in the year end of 2013, and are currently in the 7th year of the second round of inspections and anticipate completing the cycle by year end of 2020.

25-6.0342(4)(d): *An estimate of the costs and benefits to the utility of making the electric infrastructure improvements, including the effect on reducing storm restoration costs and customer outages.*

With respect to system-wide storm and extreme weather applications identified in **Attachment B**, DEF has provided any available cost/benefit information within the documents in **Attachment B**. Additionally, please see the following chart for money that DEF has spent in 2016, 2017 and 2018 on storm hardening and maintenance:



Duke Energy Florida Storm Hardening and Maintenance Costs

| Description | 2016 Actual | 2017 Actual | 2018 Actual |
|-----------------------------------------------------|----------------------|----------------------|----------------------|
| Vegetation Management (Distribution & Transmission) | \$40,076,769 | \$38,691,356 | \$46,784,730 |
| Joint Use Pole Inspection Audit | \$438,525 | \$448,503 | \$442,367 |
| Transmission Pole Inspections | \$1,918,500 | \$1,242,836 | \$1,826,054 |
| Other Transmission Inspections and Maintenance | \$5,649,611 | \$5,649,691 | \$6,084,476 |
| Transmission Hardening Projects | \$110,436,718 | \$109,829,369 | \$185,614,179 |
| Distribution Pole Inspections & Treatments | \$3,998,798 | \$4,536,355 | \$3,992,201 |
| Distribution Hardening Projects | \$42,453,504 | \$41,291,401 | \$44,801,476 |
| Total | \$204,972,425 | \$201,689,511 | \$244,744,007 |

25-6.0342(4)(e): *An estimate of the costs and benefits, obtained pursuant to Rule 25-6.0342(6), provided to third-party attachers affected by the electric infrastructure improvements, including the effect on reducing storm restoration costs and customer outages realized by the third-party attachers.*

With respect to system-wide storm and extreme weather applications identified in **Attachments A and B**, DEF believes that any entity jointly attached to DEF’s equipment would enjoy any benefit that DEF would enjoy from that same application, and DEF has provided any available cost/benefit information within the documents in those attachments.

25-6.0342(5): *Each utility shall maintain written safety, reliability, pole loading capacity, and engineering standards and procedures for attachments by others.*

Please see **Attachment A** and **Attachment C**.

25-6.0342(5): *The attachment standards and procedures shall meet or exceed the NESC so as to assure that third-party facilities do not impair electric safety, adequacy, or*

pole reliability; do not exceed pole loading capacity; and are constructed, installed, maintained, and operated in accordance with generally accepted engineering practices for the utility's service territory.

All third-party joint use attachments on Duke Energy Florida's distribution and transmission poles are engineered and designed to meet or exceed current NESC clearance and wind loading standards. New attachment requests are field inspected before and after attachments to assure company construction standards are being met. All entities proposing to attach joint use attachments to Duke Energy Florida's distribution and transmission poles are given a copy of the company-prepared "Joint Use Attachment Guidelines." Attached hereto as **Attachment C**. These guidelines are a comprehensive collection of information spelling out the company's joint use process, construction standards, timelines, financial responsibilities, and key company contacts responsible for the completing permit requests. All newly proposed joint use attachments are field checked and designed using generally accepted engineering practices to assure the new attachments do not overload the pole or impact safety or reliability of the electric or other attachments. Additionally, annual and full-system audits are performed as detailed in DEF's annual March 1 comprehensive reliability report. For details on this activity, please see **Attachment B**.

25-6.0342(6): *Each utility shall seek input from and attempt in good faith to accommodate concerns raised by other entities with existing agreements to share the use of its electric facilities.*

Since 2009, DEF has continued to communicate with the telecommunications carriers regarding the pole loading project. DEF has diligently cut cost for carriers by suggesting make ready solutions for over loaded pole conditions that do not include pole change outs. Additional guying and attachment rearrangement solutions have saved the communications carriers thousands of dollars annually. DEF continues to answer any questions and address concerns expressed verbally by joint attachers. DEF has taken all input received into consideration in the development and finalization of this storm hardening plan.

2019 Storm Hardening Plan Attachment List**Attachment A:**

1. Distribution Standards Manual
2. Distribution Engineering Manual
3. Transmission Extreme Winds Loading
4. Transmission Line Engineering Design Philosophy

Attachment B:

1. Pole Inspection Plan
2. 2018 PSC Reliability Report Excerpts, pages 39-42, 44-65

Attachment C:

1. Joint Use Pole Guidelines

Attachment D:

1. DEF Storm Hardening 2007-2018 Projects

Attachment K

Document title:

Transmission Wood Pole Inspection, Boring, Excavation, and Treatment Guidelines

Document number:

TECP-MIM-TRM-00118

Revision No.:

001

Keywords:

TEEM-EE, line patrols, groundline inspection, maintenance instructional material

Applies to:

Transmission – All Regions

1.0 Introduction

This maintenance procedure provides specific guidance for performing wood pole groundline inspections including any of the following; sound & boring tests, partial or full excavation of soils, preservative application, and pole wraps. A listing specific of lines and inspection requirements will be included in a work authorization.

The Contractor shall furnish and maintain all tools, equipment, and materials, and labor to properly inspect Duke Energy facilities as set forth in these specifications. This inspection covers both Duke Energy owned and Duke Energy leased poles.

This inspection guideline is to be utilized along with **TECP-MIM-TRM-00026**, Transmission Line Material Condition Assessment Procedure; Ground Patrols.

2.0 Definitions of Units

- 2.1 Pole Position Identification: For multipole structures such as H-frames and suspension or deadend structures, poles are to be identified as A, B, C, etc., from left to right, when facing higher structure numbers. Single pole structures will always identified as pole A.
- 2.2 Crop Damage: To ensure the upmost respect for landowners and planted fields, Duke Energy will not pay crop damage caused by an inspection contractor. All received claims will be forwarded to the contractor.
- 2.3 Standard Access: This rate will be paid when the structure can be accessed by motor vehicle, by foot, or with the use of an ATV such as a four wheeler. The right-of-way may include obstructions including fences, small ditches or streams, and high vegetation that can be driven through.
- 2.4 Hard Access: This rate will be paid when the structure can only be accessed with the aid of vehicles such as tracked a four wheeler or Marsh-Masters. The right-of-way has obstacles such as high water, deep water crossings, deep mud, or extreme rocky terrain that would make traversing by normal means impossible or unsafe. This access rate will be paid in lieu of the standard access rate.
- 2.5 Hourly Rate: An hourly rate will be paid to access a structure when the right-of-way is impassible due to extreme vegetation density or diameter and cannot be driven or walked when utilizing the vehicles listed in Sections 2.3 or 2.4.

- 2.6 Sound & Bore Patrol Requirements: In Florida, a portion of the lines to be patrolled will require three specific inspection tasks including the following; sounding, soil excavation, and boring. They are described in Sections 5.1, 5.2, and 5.3. Only the wood poles encountered on a line for this type of inspection will be compensated for. The contractor will be expected to walk/drive by and skip individual and sections of steel and concrete poles on these lines without payment.
- 2.7 Public Utility Commission of Ohio (PUCO): This specification is applicable to all regions, however, inspection work in Ohio requires the usage of a separate specification titled “Ground-line Inspection and Treatment of Wood Poles”, dated 12/18/07.
- 2.8 Removal of Vines: At times significant amounts of vegetation around the pole should be expected. Removal of such vegetation to access the pole will not be compensated unless they extend 10 foot in height. This unit will also include application of a herbicide around the base of the pole or guy anchor.
- 2.9 Installation of Structure Numbers: A unit price will be paid for the installation of a structure number on a pole as indicated in the work authorization.
- 2.10 Repair of Broken or Stolen Pole Grounds: A unit price will be paid for the repair of broken pole grounds. Duke Energy will provide the squeezeons, staples, wire. The contractor shall wear appropriate PPE and rubber gloves, and provide needed tools.

3.0 Safety Considerations

- 3.1 Contractor performance regarding safety is critical to the success of this contract. The Contractor will be expected to perform in accordance with the range of acceptable performance to meet or exceed goals.
- 3.2 All lines will normally be energized during the course of this work. The contractor shall utilize appropriate protective equipment needed to protect the general public and contractor's employees and to guard against interference with the normal operations of these lines.
- 3.3 Any hazardous conditions encountered that may endanger life, property, or cause an outage shall be reported to the Duke Energy immediately by phone.
- 3.4 When digging around the pole care must be taken not to break the pole ground wire or cause it to disconnect from the ground rod. Pole grounds pulled away from the pole because of work interference shall be re-stapled to the pole after work is completed.
- 3.5 If a pole ground is found to be broken or stolen, the contractor will be compensated to make the repair using approved tools and connectors provided by Duke Energy. Rubber gloves must be worn when performing this task.

4.0 Logistics and Employee Qualifications

- 4.1 Duke Energy will provide locations of all poles to be inspected via electronic shape files.
- 4.2 If the contractor has not previously worked for Duke Energy, proof must be provided that they have at least 5 years of experience in both ground line inspection work and preservative application.
- 4.3 The Contractor shall supply Duke Energy with both a written verification of inspection experience in years and a listing of training opportunities for each employee.
 - 4.3.1 Each pole inspector shall be a permanent, full-time employee of the having at least one year of experience in ground line inspection and treatment work.
 - 4.3.2 Each Foreman/Crew Leader shall be a permanent, full-time employee having at least two years of experience in ground line inspection and treatment work.
 - 4.3.3 Each Supervisor (oversees multiple crew members) shall be a permanent, full-time employee having at least four years of experience in supervising ground line inspection and treatment work.
 - 4.3.4 If Contractor employs non-English speaking persons, Contractor shall ensure that a bilingual person fluent in speaking, reading, and writing both in English and the other language is available at the jobsite where the non-English speaking person(s) are working for purposes of safety and hazard related communications, communicating technical information, emergency response, and similar issues.
- 4.4 All Contractor employees working for Duke Energy shall possess a cellular telephone equipped with voicemail, texting, and with the ability of sending photographs electronically. This is necessary in case of emergency, customer complaint, or other reason. The contractor shall also provide Duke Energy with names and phone numbers prior to the start of work and when personnel changes are made.
- 4.5 The Contractor shall develop a detailed work schedule. This schedule should include the prioritization of lines to be patrolled, anticipated start/finish dates, and names and number of inspectors/supervisors that will be working, etc. This schedule shall be reviewed with Duke Energy prior to the start of work and undated copies shall be sent monthly.
- 4.6 For productivity reasons it is mandatory that the Contractor provides an agreed upon number of pole inspectors to an area.
- 4.7 The Contractor shall report work location(s) via email by no later than 8:00 am to the Duke Energy daily or advise Duke Energy if no work is to be performed on that day.

- 4.8 The successful contractor shall attend a planned face to face “kick-off” meeting prior to the start of work. The agenda for this meeting is to review work plans, schedule, expectations, and safety. The contractor is expected to bring the following to the meeting, if not already completed, the following data.
 - 4.8.1 Names and cellular phone numbers of all hands-on and support employees that will working on the on the Duke Energy system.
 - 4.8.2 Verification of each employees required qualifications and experience. It is expected that the individuals completing the work will attend this meeting.
 - 4.8.3 Safety Data Sheets (SDS) and copies of the chemical labels and preservative materials that will be used, if required.
 - 4.8.4 The Contractor shall supply the Duke Energy names of employee holding responsibility/accountability for the Pesticide Applicator License as issued by the State in which the work will be performed, if applicable.
- 4.9 The Contractor shall obtain, at his expense, any necessary permits from any owner, municipality, or other authority on whose premises the work is to be done prior to the start of work.

5.0 Wood Pole Inspection Requirements

- 5.1 Overall site inspection and pole sounding;
 - 5.1.1 This section is required for ALL wood poles, regardless of regional location.
 - 5.1.2 The site is to be first assessed to ensure there is no danger from any abnormal situations such as unattached conductors, broken crossarms, severely decayed poles, or broken guy wires.
 - 5.1.3 Any requested data collection items for both the pole and structure should be collected, including pole birthmark information, structure configuration, insulator type, etc.
 - 5.1.4 Each pole shall be sounded with a waffle head type hammer thoroughly in all quadrants from groundline to 7 feet high to determine integrity and possible decay. Sounding should leave marks that are recognizable in the event of an audit. (All wood poles are to be sounded regardless of age, species, or treatment).
 - 5.1.5 If any sign of decay, soft wood, hollowness, or abnormal coloration is found, the pole is also to be probed or drilled with a suitable tool to ascertain the extend of the found deterioration.
 - 5.1.6 If the decay is found below grade soil shall be removed as necessary to aid with the testing.
 - 5.1.7 Poles are to be rejected if the decay or shell thickness meets the criteria as defined in Section 6.0.

- 5.2 Soil excavation requirements;
 - 5.2.1 When soil excavation is required in the work authorization, excavation shall be completed as follows;
 - 5.2.2 Excavation should only be initiated after it is determined that the sounding test or visual inspection up the pole does not already deem that the pole needs to be replaced.
 - 5.2.3 Soil is to be removed around the entire pole to a depth of 12 inches. The hole shall extend at least 4 inches from the pole at the 12 inch depth and 10 inches from the pole at groundline.
 - 5.2.4 When poles are located on lawns, the turf shall be removed with care, placed on a ground cover such as a tarp, and carefully replaced when work is completed.
 - 5.2.5 If any sign of decay, soft wood, hollowness, or abnormal coloration is found, the pole is also to be probed or drilled with a suitable tool to ascertain the extend of the deterioration.
 - 5.2.6 CCA poles 15 years old or less are not to be excavated unless decay is found during sounding and probing.
- 5.3 Boring requirements;
 - 5.3.1 When borings are required in the work authorization, they shall be completed as follows;
 - 5.3.2 A 3/8" diameter boring shall be drilled adjacent to where the most suspected decay is found during the sounding test. If no decay is suspected, the boring shall be taken near the deepest check. If there are no checks the boring shall be taken on either side of the pole in the same direction as the line is facing. The boring shall begin pole entry at groundline, be taken at a 45 degree angle, and proceed past the center of the pole.
 - 5.3.3 If decay pockets are detected, a minimum of two additional borings shall be taken to determine the extent of decay. Any pole with a hollow center shall have the thickness determined with a shell depth indicator.
 - 5.3.4 All inspection holes shall be plugged with tightly fitting CCA-treated wood dowels.
 - 5.3.5 Poles are to be rejected if decay or shell thickness meets the criteria as defined in Section 6.0 Pole treatment requirements;
- 5.4 Pole Treatment requirements;
 - 5.4.1 When internal treatment is required in the work authorization, treatment application shall be applied as follows;
 - 5.4.2 Poles with no indication of decay are NOT to be treated.
 - 5.4.3 Poles meeting the criteria to be replaced due to the sounding test, drilling, or visual inspection up the pole are NOT to be treated.
 - 5.4.4 When poles are found to have decay or to be hollow, treatment shall be applied only from below grade to 18 inches above groundline. Treatment is not to be applied above 18 inches.

- 5.4.5 A standard treatment rod and vendor has been included in the bid units. Duke Energy will accept proposals for equivalent treatment products.
 - 5.4.6 Treatment shall utilize a ½” hole is to drilled to ensure the applied product is as close to the decayed pole regions as possible.
 - 5.4.7 The treatment hole shall be drilled at a 30 degree downward angle to a maximum depth of 12 inches, or to the center of the pole.
 - 5.4.8 If preservative rods are used, two shall be applied to each drilled hole.
 - 5.4.9 All preservative holes shall be sealed with a removable threaded plastic plug.
 - 5.4.10 Section 5.5 must be considered before proceeding with treatment.
- 5.5 Re-treatment requirements;
- 5.5.1 If previously treated poles meet the strength requirements to remain in service and it is determined additional preservative is required, before drilling any new holes the following is to be performed;
 - 5.5.1.1 Existing holes in the vicinity of the new needed treatment are to be opened and the existing rods evaluated for decay.
 - 5.5.1.2 If the rods are decayed two new ones are to be inserted.
 - 5.5.1.3 If the existing rods are not decayed adding new ones will not be effective. When this is observed, NO new rods are to be added.
 - 5.5.1.4 If the existing treatment plug is wood, it is to be replaced with a removal plastic plug. If necessary use a larger size as removal of the wood plug may have damaged the hole.

6.0 Pole Reject Criteria

- 6.1 Priority 0 Pole Replacements: These poles shall be reported to Duke Energy via a phone call immediately when found. Replacement efforts will begin immediately.
 - 6.1.1 Pole is broken.
 - 6.1.2 Pole is in imminent danger of failing or has initial signs of failing.
- 6.2 Priority 1 Pole Replacements: These poles have a moderate probability of causing an outage and will be replaced within 12 weeks of identification.
 - 6.2.1 Hammer test or probing at groundline reveals internal rot, decay, or hollowness with a shell thickness of 2 inches or less is found in any location.
 - 6.2.2 Hammer test or probing at groundline reveals rot or decay that extends more than 2 inches into the pole along more than 1/4 of the pole circumference.
 - 6.2.3 Contractor “effective diameter” calculations determine the pole has lost more than 50 percent of the original pole strength.
 - 6.2.4 Woodpecker holes extend through the pole and daylight is visible.
 - 6.2.5 Longitudinal pole deflection exceeds 5 feet.
 - 6.2.6 Extensive longitudinal cracking exists through critical attachments.
 - 6.2.7 Earth washout at the pole base compromises the pole integrity.

- 6.3 Priority 2 Pole Replacement: These poles have a low probability of causing an outage and will be replaced during normal work schedules.
 - 6.3.1 Hammer test or probing at groundline reveals internal rot, decay, or hollowness with a shell thickness of 2 - 4 inches is found at any location.
 - 6.3.2 Hammer test or probing at groundline reveals rot or decay extends 3 or more inches into the pole along more than ¼ of the pole circumference.
 - 6.3.3 Contractor “effective diameter” calculations determine the pole has lost more than 33 percent of the original pole strength.
 - 6.3.4 Hammer test reveals significant shell cracking or soft wood, indicated by sound or caving of the wood.
 - 6.3.5 Woodpecker holes contain extensive nesting cavities in critical locations.
 - 6.3.6 Woodpecker holes are extensive and generally at least “softball” sized.
 - 6.3.7 Pole checks up the pole reveal significant evidence of decay, insect damage, or shell separation, as indicated by caving the pole, sawdust, or sound.
 - 6.3.8 Longitudinal pole deflection is between 3 – 5 feet.
 - 6.3.9 Transverse pole deflection is more than 20 degrees.
 - 6.3.10 Earth washout the pole base requires the pole to be replaced.
 - 6.3.11 Pole must meet NESC “at replacement” strength requirements, which occurs when at least 2/3 of the original required pole strength remains. This is specified in the NESC Code, Table 26101A, Footnote 2.
- 6.4 Priority 9 Pole Repairs: These poles defects have no probability of causing an outage. The identified work will only be tracked and monitored unless the defect eventually qualifies the pole for a Priority 2 status.
 - 6.4.1 Woodpecker holes not meeting the criteria for pole replacements.
 - 6.4.2 Other minor deficiencies as described in document TECP-MIM-TRM-00026.

7.0 Pole Tagging

- 7.1 All inspected poles shall be marked with an aluminum tag identifying the work performed, contractor name, and inspection date that is clearly legible.
- 7.2 Inspection tags shall be placed five (5) feet above groundline on the side of the pole most easily seen from roads or nearby access locations. If none are present, place the tag on the birth mark side of the pole.
- 7.3 A Priority 0 reject pole does not need to be marked. Duke Energy response will be immediate.
- 7.4 A Priority 1 reject pole is to be marked by **two** 1-1/2” by 1-1/2” white aluminum tags placed immediately below the inspection tag.
- 7.5 A Priority 2 reject pole is to be marked by **one** 1-1/2” by 1-1/2” white aluminum tags placed immediately below the inspection tag.

8.0 Photograph Requirements

- 8.1 A digital photograph is required to be taken of all defects that result in a Priority 1 or 2 rejected pole and E-mailed to Duke Energy. The E-mail shall include the Line name, structure number, date, and a brief description of the defect.
- 8.2 The photograph should be at least 1 megapixel in size resolution and be taken at a distance that clearly shows the defect but also includes as much as possible the pole and surroundings.

9.0 Quality Assurance and Quality Control

- 9.1 All work shall be entirely satisfactory to Duke Energy and shall be subject to inspection. The Contractor shall audit no less than 1% of all poles inspected. Poles are to be selected totally at random and be checked for accuracy and quality of work. This audit is to be completed at the Contractor's own expense.
- 9.2 A quality control inspection shall be performed for each time period of not less than one (1) week's work but not to exceed two (2) weeks' previous work. The quality control will be conducted with the Contractor's supervisor and a Duke Energy representative when available.
- 9.3 The quality control inspection shall consist of the partial to complete re-inspection of those poles selected. The re-inspection shall include re-excavation and re-boring if those tasks were performed.
- 9.4 Serious errors found by Duke Energy will be brought to the attention of the Contractor. Corrective actions satisfactory to Duke Energy must be remedied before the next quality control check. The corrective action may include re-working all poles back to the previous quality control check point at no cost to Duke Energy.
- 9.5 Results of Contractor audits shall be communicated electronically to Duke and include the pole inspector names.
- 9.6 Duke Energy shall be issued a copy of the contractor quality control field report.

10.0 Data Collection and Inspection Detail Reports

- 10.1 Data provided to the Contractor will be by electronic files in an Excel or Shape-file type spreadsheet format. All data collected by the contractor shall be added to the spreadsheet and returned without eliminating any fields received from the original Duke Energy provided files. This enables downloading the spreadsheet directly into Duke Energy databases.
- 10.2 Data deliverables and report requirements includes but is not limited to the following;
 - 10.2.1 Maintenance region
 - 10.2.2 Line name, line code, and or line number
 - 10.2.3 Structure number, including poles A, B, C, etc.
 - 10.2.4 Structure GPS coordinates
 - 10.2.5 Date pole inspected
 - 10.2.6 Pole length and class
 - 10.2.7 Pole manufacturer and birthmark date
 - 10.2.8 Pole species

- 10.2.9 Type of external/internal treatments applied
- 10.2.10 Original/effective ground line circumference
- 10.2.11 Observed deficiencies and associated repair/replace priorities
- 10.3 Reporting Requirements
 - 10.3.1 A summary of all poles inspected & work performed on an individual line or substation basis, including number of poles inspected, and failure rate.
 - 10.3.2 Copies of all internal audit reports.
 - 10.3.3 Reports are to be provided only after ALL work on a line is completed in its' entirety.
 - 10.3.4 A weekly inspection progress schedule must be submitted to the Project Manager at the start of each week for the previous weeks work.
 - 10.3.5 Duke Energy must be notified by email as line circuit inspections are completed to monitor timeline for end of circuit files and invoicing.
 - 10.3.6 Invoicing and inspection reports are to be provided only after ALL work on a circuit is completed in its' entirety.
 - 10.3.7 Invoices and end of circuit files must be sent to Duke Energy 30 days or less from time of notification of circuit inspection completion.
 - 10.3.8 All invoicing for current year inspection program must be presented to Duke Energy for final payment no later than December 15th.

Transmission Document Approval Form

issued 5/15/18

Section A: Document identification and type of action

Document no.: TECP-MIM-TRM-00118

Revision no.: 001

Document title: Transmission Wood Pole Inspection, Boring, Excavation, and Treatment Guidelines.

Type of action:

- New Cancellation Suspension
 Revision Ownership Change
 Renumber Periodic review completed, as required

For Document Management staff use only:

- Editorial Change Migration
 Control element revision _____
(does not require approval authority signature)

Applies to: (Select all that apply)

- Duke Energy Duke Energy Indiana, Inc. Department Transmission - All
 Duke Energy Carolinas, LLC Duke Energy Kentucky, Inc. Regions
 Duke Energy Progress, LLC Duke Energy Ohio, Inc. Other _____
 Duke Energy Florida, LLC Group _____

Security Restrictions Required: Yes No

If yes, explain (see [instructions](#) on page 2)

Compliance Applicability: (required field)

- None State Codes/Standards HIPAA Sarbanes-Oxley OSHA _____
 NERC FERC Standards of Conduct Patriot Act Other _____

Complete if submitting a form: (see [instructions](#) on page 2)

Does the form have a parent, governing or instructional procedure? No Yes (Procedure No: _____)

How is the form to be completed or used? Hard Copy (completed by hand) Online Data Entry (fillable PDF)

- Communication plan established Impact Reviews completed

Description of document action or summary of changes:

The incorrect document version was included in the initial release. This revision corrects that mistake.

Section B: Approval **Who should sign?** see [instructions](#) on page 2

Preparer(s)/Author(s)/Writer(s) (signature not required):

Dan Chapoton

| | | |
|----------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|------------------|
| Approval recommended (print name): Dan Chapoton | Dan Chapoton <small>Digitally signed by Dan Chapoton Date: 2018.05.07 12:33:17 -0400</small> (signature) | Date: 5/17/18 |
| Approval recommended (print name): | (signature) | Date: |
| Approval recommended (print name): | (signature) | Date: |
| Final Approval (print name): Dan Maley | Daniel J. Maley <small>Digitally signed by Daniel J. Maley Date: 2018.05.07 15:44:03 -0400</small> (signature) | Date: 5/7/18 |

RETURN SIGNED FORM AS SCANNED PDF VIA E-MAIL OR FAX TO (919) 235-3165

Keywords: procedures and forms; procedures program; daf; ADMP-PRO-ADS-00002; document management program
Applies to: Duke Energy - Transmission

ADMF-PRO-TRM-00004
Rev. 000 07/17
Page 1 of 2

AUTHORIZED COPY

Duke Energy Proprietary Business Information – Not for external distribution



Comprehensive Wood Pole Inspection Plan

May 1, 2019

Purpose and Intent of the Plan:

To implement and update a wood pole inspection program that complies with FPSC Order No. PSC-06-0144-PAA-EI issued February 27, 2006 (the “Plan”). The Plan concerns inspection of wooden transmission and distribution poles, as well as pole inspections for strength requirements related to pole attachments. The Plan is based on the requirements of the National Electric Safety Code (“NESC”) and an average eight-year inspection cycle. The Plan provides a detailed program for gathering pole-specific data, pole inspection enforcement, co-located pole inspection, and estimated program funding. This Plan also sets forth pole inspection standards utilized by Duke Energy Florida (“DEF”) that meet or exceed the requirements of the NESC.

The Plan includes the following specific sub-plans:

- Transmission Wood Pole Inspection Plan (“Transmission Plan”).
- Distribution Wood Pole Inspection Plan (“Distribution Plan”).
- Joint Use Wood Pole Inspection Plan (“Joint Use Plan”).

These three inspection sub-plans are outlined and described below. All of these sub-plans will be evaluated on an ongoing basis to address trends, external factors beyond the Company’s control (such as storms and other weather events), and cost effectiveness.

1) Transmission Wood Pole Inspection Plan

A. Introduction

Ground-line inspection and treatment programs detect and treat decay and mechanical damage of in-service wood poles. DEF’s Transmission Department accomplishes this by identifying poles that are 8 years of age or older and treating these poles as necessary in order to extend their useful life. As required, DEF also assesses poles and structures for incremental attachments that may create additional loads. Poles that can no longer maintain the safety margins required by the NESC (ANSI C2-2002) will be remediated. These inspections result in one of four or a combination of the following actions: (1) No action required; (2) Application of treatment; (3) Repaired; (4) Replaced. (DEF’s Transmission Department follows TECP-MIM-TRM-00118, Transmission Wood Pole Inspection, Boring, Excavation, and Treatment Guideline along with TECP-MIM-TRM-00026, Transmission Line Material Condition Assessment Procedure as assurance of the implementation of the plan.

B. General Plan Provisions

- (i). Pole Inspection Selection Criteria



Comprehensive Wood Pole Inspection Plan

May 1, 2019

Transmission performs ground patrols to inspect transmission system line assets to allow for the planning, scheduling, and prioritization of corrective and preventative maintenance work. These patrols assess the overall condition of the assets including insulators, connections, grounding, and signs, as well as an assessment of pole integrity. These patrols are done on a four-year cycle. The ground patrol inspections categorize wood poles into four conditions, Priority 0, 1, 2, or 9.

In performing inspection and patrols, the following Transmission Line Wood Poles Inspection State Categories shall apply:

Priority 9 is described as meeting ANY of the conditions listed below and should have a repair work order written:

- Woodpecker holes not meeting the criteria for pole replacements; for example:
 - Woodpecker holes are present but can be patched and repaired
 - Woodpecker holes are not located in critical pole locations
 - Woodpecker holes are limited to “baseball” size in diameter, they do not extend into the pole more than 4 inches, and will not hold water
- Other minor deficiencies as described in document TECP-MIM-TRM-00026 or TECP-MIM-TRM-00118

Priority 2 is described as meeting ANY of the conditions listed below and should have a replacement work order written. These poles have a low probability of causing an outage and will be replaced during normal work schedules.

- Hammer test or probing at ground-line reveals internal rot, decay, or hollowness with a shell thickness of 2 - 4 inches is found at any location.
- Hammer test or probing at ground-line reveals rot or decay extends 3 or more inches into the pole along more than one-quarter of the pole circumference.
- Contractor “effective diameter” calculations determine the pole has lost more than 33 percent of the original pole strength.
- Hammer test reveals significant shell cracking or soft wood, indicated by sound or caving of the wood.
- Woodpecker holes contain extensive nesting cavities in critical locations, including vicinity of cross-arm, plank-arm, cross-brace, guy, or insulator connections
- Woodpecker holes are extensive and generally at least “softball” sized.
- Pole checks up the pole reveal significant evidence of decay, insect damage, or shell separation, as indicated by caving the pole, sawdust, or sound.
- Longitudinal pole deflection is between 3 – 5 feet.
- Transverse pole deflection is more than 20 degrees.
- Earth washout at the pole base is so substantial that it requires replacement.
- Pole must meet NESC “at replacement” strength requirements, which occurs when at least two-thirds of the original required pole strength remains. This is specified in the NESC Code, Table 26101A, Footnote 2.



Comprehensive Wood Pole Inspection Plan

May 1, 2019

Priority 1 is described as meeting ANY of the conditions listed below. This pole should have a replacement work order written and will be replaced within 12 weeks of identification.

- Hammer test or probing at ground-line reveals internal rot, decay, or hollowness with a shell thickness of 2 inches or less is found in any location.
- Hammer test or probing at ground-line reveals rot or decay that extends more than 2 inches into the pole along more than one-quarter of the pole circumference.
- Contractor “effective diameter” calculations determine the pole has lost more than 50 percent of the original pole strength.
- Woodpecker holes extend through the pole and daylight is visible.
- Longitudinal pole deflection exceeds 5 feet.
- Extensive longitudinal cracking exists through critical attachments of the pole
- Earth washout at the pole base compromises the pole integrity.

Priority 0 are immediate Pole Replacements; these poles shall be reported, and replacement efforts will begin immediately if the Pole is broken or Pole is in imminent danger of failing or has initial signs of failing.

(ii). Ground-Line Inspections

Ground-line inspections of wood transmission poles are conducted on an average 8-year cycle. This results in, on average, approximately 12.5% of the remaining population of wood poles receiving this type of inspection on an annual basis. (Reference: TECP-MIM-TRM-00118 for inspection requirements.)

Soil excavation requirements

Excavation should only be initiated after it is determined that the sounding test or visual inspection up the pole does not already deem that the pole needs to be replaced. Soil is to be removed around the entire pole to a depth of 12 inches. The hole shall extend at least 4 inches from the pole at the 12-inch depth and 10 inches from the pole at ground-line.

If any sign of decay, soft wood, hollowness, or abnormal coloration is found, the pole is also to be probed or drilled with a suitable tool to ascertain the extend of the deterioration. CCA poles 15 years old or less are not to be excavated unless decay is found during sounding and probing.

Boring requirements

When borings are required a 3/8” diameter boring shall be drilled adjacent to where the most suspected decay is found during the sounding test. If no decay is suspected, the boring shall be taken near the deepest check. If there are no checks the boring shall be taken on either side of the pole in the same direction as the line is facing. The boring shall begin pole entry at ground-line, be taken at a 45-degree angle, and proceed past the center of the pole. If decay pockets are detected, a minimum of two additional borings shall be taken to determine the extent of decay. Any pole with a hollow center shall have the thickness determined



Comprehensive Wood Pole Inspection Plan

May 1, 2019

with a shell depth indicator. All inspection holes shall be plugged with tightly fitting CCA-treated wood dowels.

Pole Treatment requirements

When poles are found to have decay or to be hollow, treatment shall be applied only from below grade to 18-inches above ground-line. Treatment is not to be applied above 18 inches. Treatment shall utilize a ½” hole is drilled to ensure the applied product is as close to the decayed pole regions as possible. The treatment hole shall be drilled at a 30-degree downward angle to a maximum depth of 12 inches, or to the center of the pole. If preservative rods are used, two shall be applied to each drilled hole. All preservative holes shall be sealed with a removable threaded plastic plug.

If previously treated poles meet the strength requirements to remain in service and it is determined additional preservative is required, before drilling any new holes the following is to be performed;

- Existing holes in the vicinity of the new needed treatment are to be opened and the existing rods evaluated for decay.
- If the rods are decayed two new ones are to be inserted.
- If the existing rods are not decayed adding new ones will not be effective. When this is observed, NO new rods are to be added.
- If the existing treatment plug is wood, it is to be replaced with a removal plastic plug. If necessary, use a larger size as removal of the wood plug may have damaged the hole.

Poles with no indication of decay are not to be treated. Poles meeting the criteria to be replaced due to the sounding test, drilling, or visual inspection up the pole are not to be treated.

(iii) Structural Integrity Evaluation

- See 3) Joint Use Pole Inspection Plan, section B, paragraph (ii).

(iv) Records and Reporting

A pole inspection report will be filed with the Florida Public Service Commission by March 1st of each year. The report shall contain the following information:

- 1) A description of the methods used for structural analysis and pole inspection.
- 2) A description of the selection criteria that was used to determine which poles would be inspected.
- 3) A summary report of the inspection data including the following:
 - a. Total number of wood poles in Company inventory. *
 - b. Number of pole inspections planned.



Comprehensive Wood Pole Inspection Plan

May 1, 2019

- c. Number of poles inspected.
- d. Number of poles failing inspection.
- e. Pole failure rate (%) of poles inspected.
- f. Number of poles designated for replacement.
- g. Total number of poles replaced.
- h. Number of poles requiring minor follow-up. *
- i. Number of poles overloaded. *
- j. Methods of inspection used.
- k. Number of pole inspections planned for next annual inspection cycle.
- l. Total number of poles inspected (cumulative) in the 8-year cycle to date.
- m. Percentage of poles inspected (cumulative) in the 8-year cycle to date.

4) A pole inspection report that contains the following detailed information:

- a. Transmission circuit name.
- b. Pole identification number.
- c. Inspection results.
- d. Remediation recommendation.
- e. Status of remediation.

*Estimates based on averages and previous years completions.

C. Program Cost and Funding

- DEF continues to meet the obligations set forth in Order No. PCS-06-0144-PAA-EI. The number of poles inspected per year will start at approximately 3,000 poles but may vary from year to year depending on previous years' accomplishments.

DEF is currently on track to meet the 8-year cycle requirements. The number of poles inspected may vary year to year depending on the previous year's accomplishments with the intent to complete inspections in the required timeframe. The estimated figures in the chart below are "best estimates," given information and facts known at this time and are subject to change or modification.

Wood Pole Program Cost Estimates

| Annual Unit & Cost Estimate | | |
|---------------------------------------|-------|-----------------------------------|
| Cycle | | |
| Years per cycle | 8 | |
| Poles inspected per year | 3,000 | On average; may vary year to year |
| Assumed poles replaced ⁽¹⁾ | 5% | Current future projections |
| O&M Cost | | |



Comprehensive Wood Pole Inspection Plan

May 1, 2019

| | | |
|-----------------------------|--------------|-----------------------------------|
| GL Inspection & Treatment | \$100,000 | On average; may vary year to year |
| Capital Cost ⁽²⁾ | | |
| Hurricane Hardening | \$20,000,000 | On average; may vary year to year |

Note 1: Assumption is made that approximately 5% of the poles inspected will be identified for replacement.

Note 2: Capital Improvements can include various replacements beyond wood pole replacements, such as insulator, conductor and /or static replacements.

2) Distribution Wood Pole Inspection Plan

A. Introduction

In accordance with FPSC Order No. PSC-06-0144-PAA-EI, DEF’s Distribution Department inspects Company-owned wood poles on an average 8-year cycle. These inspections determine the extent of pole decay and any associated loss of strength. The information gathered from these inspections is used to determine pole replacements and to effectuate the extension of pole life through treatment and reinforcement. Additionally, information collected from the wood pole inspections is used to populate regulatory reporting requirements, provide data for loading analyses, identify other equipment maintenance issues, and used to track the results of the inspection program over time.

B. General Plan Provisions

(i). Ground-line Inspection Purpose

- The ground-line inspection process is the industry standard for determining the existing condition of wood pole assets. This inspection helps to determine extent of decay and the remaining strength of a pole. Ground-line inspections also provide insight into the remaining life of a wood pole.
- The ground-line inspection is performed at the base of the pole because the base is the location of the largest “bending moment,” as well as the area subject to the most fungal decay and insect attack. Assessing the condition of the pole at the base is the most efficient way to effectively treat and restore a wood pole.

(ii). Pole Inspection Process

When a wood distribution pole, other than a CCA pole, is inspected, the tasks listed below will be performed. For a CCA type wood distribution pole less than 16 years of age, the inspection will consist of



Comprehensive Wood Pole Inspection Plan

May 1, 2019

a visual above ground inspection and sounding with hammer, both procedures are described below. For CCA poles 16 years of age and greater, all inspection methods described below are used. Boring at Ground Line is also performed on type CCA poles when decay is present.

- Above Ground Observations - Visual inspection of the exterior condition of the pole and visual inspection of components hanging from the pole.
- Partial Excavation – The soil is removed around the base of the pole and the pole is inspected for signs of decay.
- Sound with Hammer – The exterior of the pole is tested with a hammer and the inspector listens for “hollowness” of the pole.
- Bore at Ground Line – The pole is bored at a 45-degree angle below the ground line. This inspection method helps to determine internal decay at the base as well as measure the amount of “good wood” left on the interior of the pole.
- Excavate to 18 Inches (Full Ground Line Inspection) – If significant decay is found during the full excavation, the soil is removed 18 inches below ground line. Decay pockets are identified and bored to determine the extent of decay.
- Removal of Surface Decay – Identified areas of decay are removed down to “good wood” using a sharp pick.
- Prioritization of rejected poles – rejected poles shall be assessed on their overall condition and then prioritized accordingly. Generally, these poles will then be replaced in order of priority, from highest to lowest.
- For poles where obstructions, such as concrete encasement, make full excavation impractical DEF will utilize the best economical inspection process in accordance with Order No. PSC-08-0644-PAA-EI issued October 6, 2008.

(iii) Data Collection

All data collected through the inspection process will be submitted to DEF’s Distribution Department in electronic format by inspection personnel. This data will be used to determine effective circumference and remaining strength of the pole. In evaluating pole conditions, deductions shall be made from the original ground line circumference of a pole to account for hollow heart, internal decay pockets, and removal of external decay. The measured effective critical circumference shall be at the point of greatest decay removal in the vicinity of the ground line taking into account the above applicable deductions. A pole circumference calculator shall be used to determine the measured effective critical circumference. To remain in service “as-is,” the pole shall meet minimum NESC strength requirements. The measured effective critical circumference will be compared to the applicable minimum acceptable circumference listed in the most current versions of ANSI 05.1-1992, American National Standard for Wood Poles, and NESC-C2-1990(1). Poles below the minimum acceptable circumference shall be rejected and will be marked in the field for replacement.

(iv). Structural Integrity Evaluation



Comprehensive Wood Pole Inspection Plan

May 1, 2019

- See Joint Use Pole Inspection Plan, section B, paragraph (i).

(v). Records and Reporting

A pole inspection report will be filed with the Florida Public Service Commission by March 1st of each year. The report shall contain the following information:

- 1) A description of the methods used for structural analysis and pole inspection.
- 2) A description of the selection criteria that was used to determine which poles would be inspected.
- 3) A summary report of the inspection data including the following:
 - a. Total number of wood poles in Company inventory.
 - b. Number of pole inspections planned.
 - c. Number of poles inspected.
 - d. Number of poles failing inspection.
 - e. Pole failure rate (%) of poles inspected.
 - f. Number of poles designated for replacement.
 - g. Total number of poles replaced.
 - h. Number of poles requiring minor follow-up.
 - i. Number of poles overloaded.
 - j. Methods of inspection used.
 - k. Number of pole inspections planned for next annual inspection cycle.
 - l. Total number of poles inspected (cumulative) in the 8-year cycle to date.
 - m. Percentage of poles inspected (cumulative) in the 8-year cycle to date.
- 4) A pole inspection report that contains the following detailed information:
 - a. Distribution circuit name.
 - b. Pole identification number.
 - c. Inspection results.
 - d. Remediation recommendation.
 - e. Status of remediation.

C. Program Cost and Funding

(i). Poles Program Cost Estimates



Comprehensive Wood Pole Inspection Plan

May 1, 2019

DEF continues to successfully meet the obligations set forth in Order No. PSC-06-0144-PAA-EI and continues to inspect poles based on the 8-year cycle as mandated by the FPSC. The number of poles inspected per year is expected to be approximately 100,000 poles but may vary from year to year depending on previous years' accomplishments with the intent to complete inspections in the required timeframe. Funding requirements to meet all aspects of this program will be adjusted from year to year, as well. DEF is currently on track to meet the 8-year cycle requirements.

The estimated figures in the charts below are "best estimates," given information and facts known at this time and are subject to change or modification.

| Annual Unit Estimate | | | | |
|----------------------|------------------------------------------|--------------|---------|------------|
| Years per Cycle | # of Wood Poles to be inspected per year | Replacements | Bracing | Treatments |
| 8 | 100,000 | 5,984 | 700 | 70,000 |

| Annual Cost Estimate | | | | | | | |
|----------------------|--------------------------------|----------------------------------|---------------|------------|--------------|---------------|--------------------|
| Yrs per Cycle | O&M Costs | | Capital | | O&M Total | Capital Total | Program Total Cost |
| | Inspections (S&B + Excavation) | Treatments (add'l to inspection) | Replacements | Braces | | | |
| 8 | \$ 1,400,000 | \$ 2,600,000 | \$ 36,317,000 | \$ 600,000 | \$ 4,021,000 | \$ 36,917,000 | \$ 40,938,000 |

* Inspection and Treatment costs are not currently split in financials. Best estimates were given knowing cost and estimated numbers for treatments.

3) Joint Use Pole Inspection Plan

A. Introduction

DEF currently has approximately 774,000 joint use attachments on distribution poles and approximately 7,400 joint use attachments on transmission poles. On average, DEF receives approximately 3,000 new attachment requests per year. All new attachment requests are reviewed in the field to assure the new attachments meet NESC and company clearance and structural guidelines. The information provided below outlines DEF's attachment permitting process and how DEF intends to gather structural information on certain existing joint use poles over an average 8-year inspection cycle to meet the obligations set forth in Order No. PCS-06-0144-PAA-EI.

B. General Plan Provisions

Comprehensive Wood Pole Inspection Plan

May 1, 2019

(i). Structural Analysis for a Distribution Pole New Joint Use Attachment

When the Joint Use Department receives a request to attach a new communication line to a distribution pole, the following is done to ensure that NESC clearance and loading requirements are met before permitting the new attachment:

- Each pole is field inspected, and the attachment heights of all electric and communication cables and equipment are collected. The pole number, pole size and class (type) are noted as well as span lengths of cables and wires on all sides of the pole.
- For each group of poles in a tangent line, the pole that has the most visible loading, line angle and longest or uneven span length is selected to be modeled for wind loading analysis.
- The selected pole's information is loaded into a software program called "SPIDA CALC" from IJUS. The pole information is analyzed and modeled under the NESC Light District settings of 9psf, no ice, 30° F, at 60 MPH winds to determine current loading percentages.
- If that one pole fails, the next worst-case pole in that group of tangent poles is analyzed as well.
- Each pole is analyzed to determine existing pole loading and the proposed loading with the new attachment.
- If the existing analysis determines the pole is overloaded, a work order is issued to correct the overload. The remedy may include replacing the pole with a larger class pole. If the pole fails only when the new attachment is considered, a work order estimate is made and presented to the communication company wishing to attach.

(ii). Structural Analysis for a Transmission Pole New Joint Use Attachment

When the Joint Use Department receives a request to attach a new communication line to a transmission structure with distribution underbuilt, the following will be done to ensure that NESC clearance and loading requirements are met before permitting the new attachment:

- The attachment heights of all electric and communication cables and equipment are collected. The pole number, pole size and class (type) are noted as well as span lengths of cables and wires on all sides of the pole.
- All structure information is modeled by transmission line engineering in PLS-CADD software for structural analysis.
- Line Engineering uses a most conservative approach by grouping the structures per request by "worst-case." The structure rating, material type, line angle, and span lengths are used to determine the most conservative approach.
- The selected structure information is loaded into the PLS-CADD software. NESC criteria is used and determined based on the pole location, rating of the line, and year of installation.
- Each structure is analyzed using a pass/fail approach with the existing pole loading and the proposed loading with the new attachment. If a structure fails in a specific grouping, the attachment request is denied for those grouped structures. If the most conservative structure passes, the next "worst-case" structure is then analyzed per grouping.

Comprehensive Wood Pole Inspection Plan

May 1, 2019

- If the existing analysis determines the structure is overloaded, this information is shared with maintenance and the wood pole replacement team to determine if the structure may need to be replaced or is in a replacement plan.
- If the structure is replaced, the GIS database is updated and an engineering change request (ECR) is created to reflect the date the new structure was installed.

(iii). Analysis of Existing Joint Use Attachments on Distribution Poles

There are approximately 774,000 joint use attachments on approximately 450,000 distribution poles in the DEF system. All distribution poles with joint use attachments will be inspected on an average 8-year audit cycle to determine existing structural analysis for wind loading. These audits will start at the sub-station where the feeder originates. For each group of poles in a tangent line, the pole that has the most visible loading, line angle, and longest or uneven span length will be selected to be modeled for wind loading analysis. Each pole modeled will be field inspected. The attachment heights of all electric and communication cables and equipment will be collected. The pole age, pole type, pole number, pole size / class, span lengths of cables and wires, and the size of all cables and wires on all sides of the pole will be collected.

The selected pole's information will then be loaded into a software program called "SPIDA CALC" from IJUS. The pole information will be analyzed and modeled under the NESC Light District settings of 9psf, no ice, 30° F, at 60 MPH winds to determine current loading percentages. If that one pole fails, the next worst-case pole in that group of tangent poles will be analyzed as well. Each pole analyzed will determine the existing pole loading of all electric and communication attachments on that pole. If the existing analysis determines the pole is overloaded, a work order will be issued to correct the overload. The remedy may include replacing the pole with a larger class pole. Should the original pole analyzed meet the NESC loading requirements, all similar poles in that tangent line of poles will be noted as structurally sound and entered into the database as "PASSED" structural analysis. Poles rated at 100% or lower will be designated as "PASSED." Poles that are analyzed and determined to be more than 100% loaded will be designated as "FAILED," and corrected. If the pole is changed out, the GIS database will be updated to reflect the date the new pole was installed.

(iv). Analysis of Existing Joint Use Attachments on Transmission Poles

The following analysis will be completed to ensure that NESC clearance and loading requirements are met in the event existing attachments are found that were not included in the Section B. (ii) Structural Analysis for New Joint Use Attachments:

- The attachment heights of all electric and communication cables and equipment are collected. The pole number, pole size and class (type) are noted as well as span lengths of cables and wires on all sides of the pole.



Comprehensive Wood Pole Inspection Plan

May 1, 2019

- All structure information is modeled by transmission line engineering in PLS-CADD software for structural analysis.
- Line Engineering uses a most conservative approach by grouping the structures of a given circuit by “worst-case.” The structure rating, material type, line angle, and span lengths are used to determine the most conservative approach.
- The selected structure information is loaded into the PLS-CADD software. NESC criteria is used and determined based on the pole location, rating of the line, and year of installation.
- Each structure is analyzed using a pass/fail approach with the existing pole loading. If a structure fails in a specific grouping, the wood pole replacement team and maintenance group are notified to determine if the structure may need to be replaced or is in the replacement plan. If the most conservative structure passes, the next “worst-case” structure is then analyzed per grouping.
- If the structure is replaced, the GIS database is updated and an engineering change request (ECR) is created to reflect the date the new structure was installed.

(v). Records and Reporting

A pole inspection report will be filed with the Florida Public Service Commission by March 1st of each year. The report shall contain the following information:

- 1) A description of the methods used for structural analysis and pole inspection.
- 2) A description of the selection criteria that was used to determine which poles would be inspected.
- 3) A summary report of the inspection data including the following:
 - a. Number of poles inspected.
 - b. Number of poles not requiring remediation.
 - c. Number of poles requiring remedial action.
 - d. Number of poles requiring minor follow up.
 - e. Number of poles requiring a change in inspection cycle.
 - f. Number of poles that were overloaded.
 - g. Number of inspections planned.

C. Program Cost and Funding

(i). Pole Analysis Funding



Comprehensive Wood Pole Inspection Plan

May 1, 2019

As stated above, there are currently approximately 774,000 joint use attachments on approximately 450,000 distribution poles and approximately 7,400 joint use attachments on transmission poles. DEF will analyze the “worst case” poles in a tangent line of similar poles as deemed appropriate during field inspections.

In order to meet the obligations, set forth in Order No. PCS-06-0144-PAA-EI, DEF requires incremental funding annually to successfully gather data and enter it into the required reporting format. See calculation that follows. The estimated figures in these charts are “best estimates,” given information and facts known at this time and are subject to change or modification.

| Annual Unit & Cost Estimate | | | | | | | | | |
|----------------------------------------|-------------------------------|------------------------------------|-----------------------------------|-----------------------------------|-------------------------------|------------------------------------|------------------------------------|-----------------------------------|---------------------------------------|
| Distribution poles with joint use | Annual inspected (8-yr cycle) | 10% of Distribution poles analyzed | 1% of Distribution poles replaced | Transmission poles with joint use | Annual inspected (8-yr cycle) | 30% of Transmission poles analyzed | 10% of Transmission poles replaced | Total cost to analyze poles (O&M) | Total cost to replace poles (capital) |
| 450,000 | 56,000 | 5,600 | 56 | 5900 | 738 | 221 | 22 | \$551,950 | \$585,000 |

Document title:

Transmission Wood Pole Inspection, Boring, Excavation, and Treatment Guidelines

Document number:

TECP-MIM-TRM-00118

Revision No.:

001

Keywords:

TEEM-EE, line patrols, groundline inspection, maintenance instructional material

Applies to:

Transmission – All Regions

1.0 Introduction

This maintenance procedure provides specific guidance for performing wood pole groundline inspections including any of the following; sound & boring tests, partial or full excavation of soils, preservative application, and pole wraps. A listing specific of lines and inspection requirements will be included in a work authorization.

The Contractor shall furnish and maintain all tools, equipment, and materials, and labor to properly inspect Duke Energy facilities as set forth in these specifications. This inspection covers both Duke Energy owned and Duke Energy leased poles.

This inspection guideline is to be utilized along with **TECP-MIM-TRM-00026**, Transmission Line Material Condition Assessment Procedure; Ground Patrols.

2.0 Definitions of Units

- 2.1 Pole Position Identification: For multipole structures such as H-frames and suspension or deadend structures, poles are to be identified as A, B, C, etc., from left to right, when facing higher structure numbers. Single pole structures will always identified as pole A.
- 2.2 Crop Damage: To ensure the upmost respect for landowners and planted fields, Duke Energy will not pay crop damage caused by an inspection contractor. All received claims will be forwarded to the contractor.
- 2.3 Standard Access: This rate will be paid when the structure can be accessed by motor vehicle, by foot, or with the use of an ATV such as a four wheeler. The right-of-way may include obstructions including fences, small ditches or streams, and high vegetation that can be driven through.
- 2.4 Hard Access: This rate will be paid when the structure can only be accessed with the aid of vehicles such as tracked a four wheeler or Marsh-Masters. The right-of-way has obstacles such as high water, deep water crossings, deep mud, or extreme rocky terrain that would make traversing by normal means impossible or unsafe. This access rate will be paid in lieu of the standard access rate.
- 2.5 Hourly Rate: An hourly rate will be paid to access a structure when the right-of-way is impassible due to extreme vegetation density or diameter and cannot be driven or walked when utilizing the vehicles listed in Sections 2.3 or 2.4.

- 2.6 Sound & Bore Patrol Requirements: In Florida, a portion of the lines to be patrolled will require three specific inspection tasks including the following; sounding, soil excavation, and boring. They are described in Sections 5.1, 5.2, and 5.3. Only the wood poles encountered on a line for this type of inspection will be compensated for. The contractor will be expected to walk/drive by and skip individual and sections of steel and concrete poles on these lines without payment.
- 2.7 Public Utility Commission of Ohio (PUCO): This specification is applicable to all regions, however, inspection work in Ohio requires the usage of a separate specification titled “Ground-line Inspection and Treatment of Wood Poles”, dated 12/18/07.
- 2.8 Removal of Vines: At times significant amounts of vegetation around the pole should be expected. Removal of such vegetation to access the pole will not be compensated unless they extend 10 foot in height. This unit will also include application of a herbicide around the base of the pole or guy anchor.
- 2.9 Installation of Structure Numbers: A unit price will be paid for the installation of a structure number on a pole as indicated in the work authorization.
- 2.10 Repair of Broken or Stolen Pole Grounds: A unit price will be paid for the repair of broken pole grounds. Duke Energy will provide the squeezeons, staples, wire. The contractor shall wear appropriate PPE and rubber gloves, and provide needed tools.

3.0 Safety Considerations

- 3.1 Contractor performance regarding safety is critical to the success of this contract. The Contractor will be expected to perform in accordance with the range of acceptable performance to meet or exceed goals.
- 3.2 All lines will normally be energized during the course of this work. The contractor shall utilize appropriate protective equipment needed to protect the general public and contractor's employees and to guard against interference with the normal operations of these lines.
- 3.3 Any hazardous conditions encountered that may endanger life, property, or cause an outage shall be reported to the Duke Energy immediately by phone.
- 3.4 When digging around the pole care must be taken not to break the pole ground wire or cause it to disconnect from the ground rod. Pole grounds pulled away from the pole because of work interference shall be re-stapled to the pole after work is completed.
- 3.5 If a pole ground is found to be broken or stolen, the contractor will be compensated to make the repair using approved tools and connectors provided by Duke Energy. Rubber gloves must be worn when performing this task.

4.0 Logistics and Employee Qualifications

- 4.1 Duke Energy will provide locations of all poles to be inspected via electronic shape files.
- 4.2 If the contractor has not previously worked for Duke Energy, proof must be provided that they have at least 5 years of experience in both ground line inspection work and preservative application.
- 4.3 The Contractor shall supply Duke Energy with both a written verification of inspection experience in years and a listing of training opportunities for each employee.
 - 4.3.1 Each pole inspector shall be a permanent, full-time employee of the having at least one year of experience in ground line inspection and treatment work.
 - 4.3.2 Each Foreman/Crew Leader shall be a permanent, full-time employee having at least two years of experience in ground line inspection and treatment work.
 - 4.3.3 Each Supervisor (oversees multiple crew members) shall be a permanent, full-time employee having at least four years of experience in supervising ground line inspection and treatment work.
 - 4.3.4 If Contractor employs non-English speaking persons, Contractor shall ensure that a bilingual person fluent in speaking, reading, and writing both in English and the other language is available at the jobsite where the non-English speaking person(s) are working for purposes of safety and hazard related communications, communicating technical information, emergency response, and similar issues.
- 4.4 All Contractor employees working for Duke Energy shall possess a cellular telephone equipped with voicemail, texting, and with the ability of sending photographs electronically. This is necessary in case of emergency, customer complaint, or other reason. The contractor shall also provide Duke Energy with names and phone numbers prior to the start of work and when personnel changes are made.
- 4.5 The Contractor shall develop a detailed work schedule. This schedule should include the prioritization of lines to be patrolled, anticipated start/finish dates, and names and number of inspectors/supervisors that will be working, etc. This schedule shall be reviewed with Duke Energy prior to the start of work and undated copies shall be sent monthly.
- 4.6 For productivity reasons it is mandatory that the Contractor provides an agreed upon number of pole inspectors to an area.
- 4.7 The Contractor shall report work location(s) via email by no later than 8:00 am to the Duke Energy daily or advise Duke Energy if no work is to be performed on that day.

- 4.8 The successful contractor shall attend a planned face to face “kick-off” meeting prior to the start of work. The agenda for this meeting is to review work plans, schedule, expectations, and safety. The contractor is expected to bring the following to the meeting, if not already completed, the following data.
 - 4.8.1 Names and cellular phone numbers of all hands-on and support employees that will working on the on the Duke Energy system.
 - 4.8.2 Verification of each employees required qualifications and experience. It is expected that the individuals completing the work will attend this meeting.
 - 4.8.3 Safety Data Sheets (SDS) and copies of the chemical labels and preservative materials that will be used, if required.
 - 4.8.4 The Contractor shall supply the Duke Energy names of employee holding responsibility/accountability for the Pesticide Applicator License as issued by the State in which the work will be performed, if applicable.
- 4.9 The Contractor shall obtain, at his expense, any necessary permits from any owner, municipality, or other authority on whose premises the work is to be done prior to the start of work.

5.0 Wood Pole Inspection Requirements

- 5.1 Overall site inspection and pole sounding;
 - 5.1.1 This section is required for ALL wood poles, regardless of regional location.
 - 5.1.2 The site is to be first assessed to ensure there is no danger from any abnormal situations such as unattached conductors, broken crossarms, severely decayed poles, or broken guy wires.
 - 5.1.3 Any requested data collection items for both the pole and structure should be collected, including pole birthmark information, structure configuration, insulator type, etc.
 - 5.1.4 Each pole shall be sounded with a waffle head type hammer thoroughly in all quadrants from groundline to 7 feet high to determine integrity and possible decay. Sounding should leave marks that are recognizable in the event of an audit. (All wood poles are to be sounded regardless of age, species, or treatment).
 - 5.1.5 If any sign of decay, soft wood, hollowness, or abnormal coloration is found, the pole is also to be probed or drilled with a suitable tool to ascertain the extend of the found deterioration.
 - 5.1.6 If the decay is found below grade soil shall be removed as necessary to aid with the testing.
 - 5.1.7 Poles are to be rejected if the decay or shell thickness meets the criteria as defined in Section 6.0.

- 5.2 Soil excavation requirements;
 - 5.2.1 When soil excavation is required in the work authorization, excavation shall be completed as follows;
 - 5.2.2 Excavation should only be initiated after it is determined that the sounding test or visual inspection up the pole does not already deem that the pole needs to be replaced.
 - 5.2.3 Soil is to be removed around the entire pole to a depth of 12 inches. The hole shall extend at least 4 inches from the pole at the 12 inch depth and 10 inches from the pole at groundline.
 - 5.2.4 When poles are located on lawns, the turf shall be removed with care, placed on a ground cover such as a tarp, and carefully replaced when work is completed.
 - 5.2.5 If any sign of decay, soft wood, hollowness, or abnormal coloration is found, the pole is also to be probed or drilled with a suitable tool to ascertain the extend of the deterioration.
 - 5.2.6 CCA poles 15 years old or less are not to be excavated unless decay is found during sounding and probing.
- 5.3 Boring requirements;
 - 5.3.1 When borings are required in the work authorization, they shall be completed as follows;
 - 5.3.2 A 3/8" diameter boring shall be drilled adjacent to where the most suspected decay is found during the sounding test. If no decay is suspected, the boring shall be taken near the deepest check. If there are no checks the boring shall be taken on either side of the pole in the same direction as the line is facing. The boring shall begin pole entry at groundline, be taken at a 45 degree angle, and proceed past the center of the pole.
 - 5.3.3 If decay pockets are detected, a minimum of two additional borings shall be taken to determine the extent of decay. Any pole with a hollow center shall have the thickness determined with a shell depth indicator.
 - 5.3.4 All inspection holes shall be plugged with tightly fitting CCA-treated wood dowels.
 - 5.3.5 Poles are to be rejected if decay or shell thickness meets the criteria as defined in Section 6.0 Pole treatment requirements;
- 5.4 Pole Treatment requirements;
 - 5.4.1 When internal treatment is required in the work authorization, treatment application shall be applied as follows;
 - 5.4.2 Poles with no indication of decay are NOT to be treated.
 - 5.4.3 Poles meeting the criteria to be replaced due to the sounding test, drilling, or visual inspection up the pole are NOT to be treated.
 - 5.4.4 When poles are found to have decay or to be hollow, treatment shall be applied only from below grade to 18 inches above groundline. Treatment is not to be applied above 18 inches.

- 5.4.5 A standard treatment rod and vendor has been included in the bid units. Duke Energy will accept proposals for equivalent treatment products.
 - 5.4.6 Treatment shall utilize a ½” hole is to drilled to ensure the applied product is as close to the decayed pole regions as possible.
 - 5.4.7 The treatment hole shall be drilled at a 30 degree downward angle to a maximum depth of 12 inches, or to the center of the pole.
 - 5.4.8 If preservative rods are used, two shall be applied to each drilled hole.
 - 5.4.9 All preservative holes shall be sealed with a removable threaded plastic plug.
 - 5.4.10 Section 5.5 must be considered before proceeding with treatment.
- 5.5 Re-treatment requirements;
- 5.5.1 If previously treated poles meet the strength requirements to remain in service and it is determined additional preservative is required, before drilling any new holes the following is to be performed;
 - 5.5.1.1 Existing holes in the vicinity of the new needed treatment are to be opened and the existing rods evaluated for decay.
 - 5.5.1.2 If the rods are decayed two new ones are to be inserted.
 - 5.5.1.3 If the existing rods are not decayed adding new ones will not be effective. When this is observed, NO new rods are to be added.
 - 5.5.1.4 If the existing treatment plug is wood, it is to be replaced with a removal plastic plug. If necessary use a larger size as removal of the wood plug may have damaged the hole.

6.0 Pole Reject Criteria

- 6.1 Priority 0 Pole Replacements: These poles shall be reported to Duke Energy via a phone call immediately when found. Replacement efforts will begin immediately.
 - 6.1.1 Pole is broken.
 - 6.1.2 Pole is in imminent danger of failing or has initial signs of failing.
- 6.2 Priority 1 Pole Replacements: These poles have a moderate probability of causing an outage and will be replaced within 12 weeks of identification.
 - 6.2.1 Hammer test or probing at groundline reveals internal rot, decay, or hollowness with a shell thickness of 2 inches or less is found in any location.
 - 6.2.2 Hammer test or probing at groundline reveals rot or decay that extends more than 2 inches into the pole along more than 1/4 of the pole circumference.
 - 6.2.3 Contractor “effective diameter” calculations determine the pole has lost more than 50 percent of the original pole strength.
 - 6.2.4 Woodpecker holes extend through the pole and daylight is visible.
 - 6.2.5 Longitudinal pole deflection exceeds 5 feet.
 - 6.2.6 Extensive longitudinal cracking exists through critical attachments.
 - 6.2.7 Earth washout at the pole base compromises the pole integrity.

- 6.3 Priority 2 Pole Replacement: These poles have a low probability of causing an outage and will be replaced during normal work schedules.
 - 6.3.1 Hammer test or probing at groundline reveals internal rot, decay, or hollowness with a shell thickness of 2 - 4 inches is found at any location.
 - 6.3.2 Hammer test or probing at groundline reveals rot or decay extends 3 or more inches into the pole along more than ¼ of the pole circumference.
 - 6.3.3 Contractor “effective diameter” calculations determine the pole has lost more than 33 percent of the original pole strength.
 - 6.3.4 Hammer test reveals significant shell cracking or soft wood, indicated by sound or caving of the wood.
 - 6.3.5 Woodpecker holes contain extensive nesting cavities in critical locations.
 - 6.3.6 Woodpecker holes are extensive and generally at least “softball” sized.
 - 6.3.7 Pole checks up the pole reveal significant evidence of decay, insect damage, or shell separation, as indicated by caving the pole, sawdust, or sound.
 - 6.3.8 Longitudinal pole deflection is between 3 – 5 feet.
 - 6.3.9 Transverse pole deflection is more than 20 degrees.
 - 6.3.10 Earth washout the pole base requires the pole to be replaced.
 - 6.3.11 Pole must meet NESC “at replacement” strength requirements, which occurs when at least 2/3 of the original required pole strength remains. This is specified in the NESC Code, Table 26101A, Footnote 2.
- 6.4 Priority 9 Pole Repairs: These poles defects have no probability of causing an outage. The identified work will only be tracked and monitored unless the defect eventually qualifies the pole for a Priority 2 status.
 - 6.4.1 Woodpecker holes not meeting the criteria for pole replacements.
 - 6.4.2 Other minor deficiencies as described in document TECP-MIM-TRM-00026.

7.0 Pole Tagging

- 7.1 All inspected poles shall be marked with an aluminum tag identifying the work performed, contractor name, and inspection date that is clearly legible.
- 7.2 Inspection tags shall be placed five (5) feet above groundline on the side of the pole most easily seen from roads or nearby access locations. If none are present, place the tag on the birth mark side of the pole.
- 7.3 A Priority 0 reject pole does not need to be marked. Duke Energy response will be immediate.
- 7.4 A Priority 1 reject pole is to be marked by **two** 1-1/2” by 1-1/2” white aluminum tags placed immediately below the inspection tag.
- 7.5 A Priority 2 reject pole is to be marked by **one** 1-1/2” by 1-1/2” white aluminum tags placed immediately below the inspection tag.

8.0 Photograph Requirements

- 8.1 A digital photograph is required to be taken of all defects that result in a Priority 1 or 2 rejected pole and E-mailed to Duke Energy. The E-mail shall include the Line name, structure number, date, and a brief description of the defect.
- 8.2 The photograph should be at least 1 megapixel in size resolution and be taken at a distance that clearly shows the defect but also includes as much as possible the pole and surroundings.

9.0 Quality Assurance and Quality Control

- 9.1 All work shall be entirely satisfactory to Duke Energy and shall be subject to inspection. The Contractor shall audit no less than 1% of all poles inspected. Poles are to be selected totally at random and be checked for accuracy and quality of work. This audit is to be completed at the Contractor's own expense.
- 9.2 A quality control inspection shall be performed for each time period of not less than one (1) week's work but not to exceed two (2) weeks' previous work. The quality control will be conducted with the Contractor's supervisor and a Duke Energy representative when available.
- 9.3 The quality control inspection shall consist of the partial to complete re-inspection of those poles selected. The re-inspection shall include re-excavation and re-boring if those tasks were performed.
- 9.4 Serious errors found by Duke Energy will be brought to the attention of the Contractor. Corrective actions satisfactory to Duke Energy must be remedied before the next quality control check. The corrective action may include re-working all poles back to the previous quality control check point at no cost to Duke Energy.
- 9.5 Results of Contractor audits shall be communicated electronically to Duke and include the pole inspector names.
- 9.6 Duke Energy shall be issued a copy of the contractor quality control field report.

10.0 Data Collection and Inspection Detail Reports

- 10.1 Data provided to the Contractor will be by electronic files in an Excel or Shape-file type spreadsheet format. All data collected by the contractor shall be added to the spreadsheet and returned without eliminating any fields received from the original Duke Energy provided files. This enables downloading the spreadsheet directly into Duke Energy databases.
- 10.2 Data deliverables and report requirements includes but is not limited to the following;
 - 10.2.1 Maintenance region
 - 10.2.2 Line name, line code, and or line number
 - 10.2.3 Structure number, including poles A, B, C, etc.
 - 10.2.4 Structure GPS coordinates
 - 10.2.5 Date pole inspected
 - 10.2.6 Pole length and class
 - 10.2.7 Pole manufacturer and birthmark date
 - 10.2.8 Pole species

- 10.2.9 Type of external/internal treatments applied
- 10.2.10 Original/effective ground line circumference
- 10.2.11 Observed deficiencies and associated repair/replace priorities
- 10.3 Reporting Requirements
 - 10.3.1 A summary of all poles inspected & work performed on an individual line or substation basis, including number of poles inspected, and failure rate.
 - 10.3.2 Copies of all internal audit reports.
 - 10.3.3 Reports are to be provided only after ALL work on a line is completed in its' entirety.
 - 10.3.4 A weekly inspection progress schedule must be submitted to the Project Manager at the start of each week for the previous weeks work.
 - 10.3.5 Duke Energy must be notified by email as line circuit inspections are completed to monitor timeline for end of circuit files and invoicing.
 - 10.3.6 Invoicing and inspection reports are to be provided only after ALL work on a circuit is completed in its' entirety.
 - 10.3.7 Invoices and end of circuit files must be sent to Duke Energy 30 days or less from time of notification of circuit inspection completion.
 - 10.3.8 All invoicing for current year inspection program must be presented to Duke Energy for final payment no later than December 15th.

Transmission Document Approval Form

issued 5/15/18

Section A: Document identification and type of action

Document no.: TECP-MIM-TRM-00118

Revision no.: 001

Document title: Transmission Wood Pole Inspection, Boring, Excavation, and Treatment Guidelines.

Type of action:

- New Cancellation Suspension
 Revision Ownership Change
 Renumber Periodic review completed, as required

For Document Management staff use only:

- Editorial Change Migration
 Control element revision _____
(does not require approval authority signature)

Applies to: (Select all that apply)

- Duke Energy Duke Energy Indiana, Inc. Department Transmission - All
 Duke Energy Carolinas, LLC Duke Energy Kentucky, Inc. Regions
 Duke Energy Progress, LLC Duke Energy Ohio, Inc. Other _____
 Duke Energy Florida, LLC Group _____

Security Restrictions Required: Yes No

If yes, explain (see [instructions](#) on page 2)

Compliance Applicability: (required field)

- None State Codes/Standards HIPAA Sarbanes-Oxley OSHA _____
 NERC FERC Standards of Conduct Patriot Act Other _____

Complete if submitting a form: (see [instructions](#) on page 2)

Does the form have a parent, governing or instructional procedure? No Yes (Procedure No: _____)

How is the form to be completed or used? Hard Copy (completed by hand) Online Data Entry (fillable PDF)

- Communication plan established Impact Reviews completed

Description of document action or summary of changes:

The incorrect document version was included in the initial release. This revision corrects that mistake.

Section B: Approval **Who should sign?** see [instructions](#) on page 2

Preparer(s)/Author(s)/Writer(s) (signature not required):

Dan Chapoton

| | | |
|----------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|------------------|
| Approval recommended (print name): Dan Chapoton | Dan Chapoton <small>Digitally signed by Dan Chapoton Date: 2018.05.07 12:33:17 04'00'</small> (signature) | Date: 5/17/18 |
| Approval recommended (print name): | (signature) | Date: |
| Approval recommended (print name): | (signature) | Date: |
| Final Approval (print name): Dan Maley | Daniel J. Maley <small>Digitally signed by Daniel J. Maley Date: 2018.05.07 15:44:03 -04'00'</small> (signature) | Date: 5/7/18 |

RETURN SIGNED FORM AS SCANNED PDF VIA E-MAIL OR FAX TO (919) 235-3165

Keywords procedures and forms; procedures program; daf; ADMP-PRO-ADS-00002; document management program
Applies to Duke Energy - Transmission

ADMF-PRO-TRM-00004
Rev. 000 07/17
Page 1 of 2

AUTHORIZED COPY

Duke Energy Proprietary Business Information – Not for external distribution

Attachment L



Matthew R. Bernier
ASSOCIATE GENERAL COUNSEL

March 1, 2021

VIA ELECTRONIC FILING

Adam J. Teitzman, Commission Clerk
Florida Public Service Commission
2540 Shumard Oak Boulevard
Tallahassee, Florida 32399-0850

Re: 2020 Annual Wood Pole Inspection Report; Undocketed

Dear Mr. Teitzman;

Pursuant to Order Numbers PSC-06-0144-PAA-EI and PSC-07-0918-PAA-PU, please find enclosed Duke Energy Florida, LLC's ("DEF") Annual Wood Pole Inspection Report for CY 2020. This information is also contained in DEF's 2020 Annual Service Reliability Report dated March 1, 2021.

Thank you for your assistance in this matter. Please feel free to call me at (850) 521-1428 should you have any questions concerning this filing.

Sincerely,

/s/ Matthew R. Bernier

Matthew R. Bernier

MRB/cmw
Enclosure

cc: Penelope Buys, FPSC Division of Engineering

Duke Energy Florida (Distribution) Annual Wood Pole Inspection Report (Reporting Year 2020)

| a | b | c | d | e | f | g | h | i | j | k | l | m |
|---------------------------------------------------|--------------------------------------------------------------------------------------------|---------------------------------------------|------------------------------------------------------|------------------------------------------------|--------------------------------------------------------------|--------------------------------------------------|-------------------------------------------------------------|----------------------------------------------|------------------------------------------------------------------------------|----------------------------------------------------------------|---------------------------------------------------------------------|---------------------------------------------------------------|
| Total # of Wooden Poles in the Company Inventory | # of Pole Inspections Planned this Annual Inspection | # of Poles Inspected this Annual Inspection | # of Poles Failing Inspection this Annual Inspection | Pole Failure Rate (%) this Annual Inspection | # of Poles Designated for Replacement this Annual Inspection | Total # of Poles Replaced this Annual Inspection | # of Poles Requiring Minor Follow-up this Annual Inspection | # of Poles Overloaded this Annual Inspection | Method(s) V = Visual E = Excavation P= Prod S = Sound B= Bore | # of Pole Inspections Planned for Next Annual Inspection Cycle | Total # of Poles Inspected (Cumulative) in the 8-Year Cycle To Date | % of Poles Inspected (Cumulative) in the 8-Year Cycle To Date |
| 820,626 | 100,000 | 86,357 | 1,746 | 2% | 1,024 | 2,696 | 1,730 | N/A | V, E, S, B, P | 158,000 | 671,512 | 81.8% |
| If b - c > 0, provide explanation | N/A | | | | | | | | | | | |
| If d - g > 0, provide explanation | N/A | | | | | | | | | | | |
| Description of selection criteria for inspections | Poles for inspection in 2020 were chosen based on geographic location to continue cycle 2. | | | | | | | | | | | |

- Poles noted in column “d” are for ground line rejects only. Additional poles are replaced based on pole top issues but are not included in this number.
- Failure rate in column “e” is for ground line rejects only.

Duke Energy Florida (Transmission) Annual Wood Pole Inspection Report (Reporting Year 2020)

| a | b | c | d | e | f | g | h | i | j | k | l | m |
|---------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|------------------------------------------------------|----------------------------------------------|--------------------------------------------------------------|--------------------------------------------------|-------------------------------------------------------------|----------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| Total # of Wooden Poles in the Company Inventory | # of Pole Inspections Planned this Annual Inspection | # of Poles Inspected this Annual Inspection | # of Poles Failing Inspection this Annual Inspection | Pole Failure Rate (%) this Annual Inspection | # of Poles Designated for Replacement this Annual Inspection | Total # of Poles Replaced this annual Inspection | # of Poles Requiring Minor Follow-up this Annual Inspection | # of Poles Overloaded this Annual Inspection | Method(s) V=Visual E=Excavation P= Prod S=Sound & B=Bore R=Resistograph | # of Poles Inspections Planned for Next Annual Inspection Cycle | Total # of Poles Inspected (cumulative in the 8-Year Cycle to Date) | % of Poles Inspected (Cumulative) in the 8-Year Cycle to Date |
| 18,130 | 7,500 | 3,531 | 1,858 | 52.62% | 688 | 1,111 | 540 | 1 | V = 12,031 (W,S,C) S&B = 3,371 (W) V(S) = 407 (LT) 12,438 = Total V Total Structures, includes LT | 5,043 | Inspected 13 = 1,273 Inspected 14 = 4,891 Inspected 15 = 5,856 Inspected 16 = 2,280 Inspected 17 = 1,902 Inspected 18 = 923 Inspected 19 = 4,545 Inspected 20 = 3,371 Total = 25,041 | 138.12% |
| | | | | | | Total: 766 + 334 = 1111 | | | Total S&B = 3,371 | | *2012 not included in cumm. totals. See note below. | *2012 not included in cumm. totals. See note below. |
| If b - c > 0, provide explanation | DEF Transmission visually inspects transmission lines with wood poles on 4 year cycle; estimating 'Planned Inspection-S&B' target based on 1/3 of the remaining balance; actual inspected equates to ~ 1/4 of balance (double the 1/8 requirement for S&B). | | | | | | | | | | | |
| If d - g > 0, provide explanation | Inspections were completed through the end of the year. Some poles found to have 'failed' in 2019 were replaced in 2019, while others have been prioritized and worked into schedule for 2020. Defective/failed poles found in late 2019 are prioritized and worked into schedule for 2020; *1,027 were wood replaced within Maintenance (705) & DOT/Reio/Upgrades/Additions (322) for 2019. | | | | | | | | | | | |
| Description of Selection Criteria for Inspections | DEF Transmission conducts Sound & Bore on wood poles on an 8-year cycle as per FPSC ruling. *DEF has been working toward data true-up – as stated in past Reliability Reports – to remain compliant with report due dates and still be responsive in reporting; DEF is providing updated S&B data (previous data may have included all inspections.) 2012 data was not available at this time of reporting; however, the 7 year Cum shows 100.5% of S&B on Remaining Wood Pole Inventory. DEF visually inspects Transmission lines with Steel or Concrete Poles and Lattice Towers on a 6-year cycle. DEF visually inspects Transmission lines containing wood poles on a 4-year cycle; estimating 'Planned Inspection-S&B' targeting 1/3 of wood pole remaining balance; Actuals completed at 1/4 of remaining balance. DEF's Annual Service Reliability Report Inspection criteria is included in: Attachment K-Transmission Wood pole Inspection-TECP-MIM-TRM-00118-Rev.001 | | | | | | | | | | | |

Duke Energy Florida CCA Pole Sampling Results (Less than 16 Years of Age) (Reporting Year 2020)

| a | b | c | d | e | f | g | h | i | j | k | l | m |
|-------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------|-------------------------------------------------------------------------|------------------------------------------------------------------------------------|-------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|--------------------------------------------------|-------------------------------------------------------------------------------------------|----------------------------------------------|------------------------------------------------------------------------------|----------------------------------------------------------------|---------------------------------------------------------------------|
| Total # of CCA Poles Less than 16 Years of Age in the Company Inventory | Total # of Pole Inspections Planned this Annual Inspection | # of CCA Poles Less than 16 years of age Inspected this Annual Inspection | # of CCA Poles Less than 16 years of age sampled this Annual Inspection | # of CCA Poles Less than 16 Years of Age Failing Inspection this Annual Inspection | CCA Poles Less than 16 Years of Age Failure Rate (%) this Annual Inspection | # of CCA Poles Less than 16 Years of Age Designated for Replacement this Annual Inspection | Total # of Poles Replaced this Annual Inspection | # of CCA Poles Less than 16 Years of Age Requiring Minor Follow-up this Annual Inspection | # of Poles Overloaded this Annual Inspection | Method(s) V = Visual E = Excavation P= Prod S = Sound B= Bore | # of Pole Inspections Planned for Next Annual Inspection Cycle | Total # of Poles Inspected (Cumulative) in the 8-Year Cycle To Date |
| 104,049 | 100,000 | 19,963 | 590 | 0 | 0% | 0 | N/A | 3 | N/A | V, E, S, B, P | N/A | N/A |
| If b - c > 0, provide explanation | N/A | | | | | | | | | | | |
| If d - g > 0, provide explanation | N/A | | | | | | | | | | | |
| Description of selection criteria for inspections | CCA poles to experience full inspection are randomly selected to represent a quantity of 1% or more of the total CCA poles less than 16 years of age in the inspection zone. | | | | | | | | | | | |

Attachment M

2020 DEF DISTRIBUTION POLE INSPECTION DATA

PROVIDED ON CD

Attachment M

2020 FLORIDA POLE INSPECTION DATA

PROVIDED ON CD