

ORIGINAL

RECEIVED-FPSC

Legal Department

07 JUN 15 PM 4:18

JENNIFER S. KAY
Senior Operations Counsel - Florida

AT&T Florida
150 South Monroe Street
Room 400
Tallahassee, Florida 32301
(305) 347-5332

COMMISSION
CLERK

June 15, 2007

Ann Cole
Commission Clerk
Florida Public Service Commission
2540 Shumard Oak Boulevard
Tallahassee, FL 32399-0850

070000


Re: AT&T Florida's Pole Inspection Report June 2006 through
December 2006

Dear Ms. Cole:

On March 1, 2007, BellSouth Telecommunications, Inc. d/b/a AT&T Florida ("AT&T Florida") submitted its Pole Inspection Report for June 2006 through December 2006 (the "Inspection Report"), pursuant to Florida Public Service Commission Order No. PSC-06-0168-PAA-TL in Docket No. 060077-TL. AT&T Florida submitted the Inspection Report under a claim of confidentiality pursuant to Section 364.183(3), Florida Statutes, and Rule 25-22.006, Florida Administrative Code, because the Inspection Report contained proprietary confidential business information.

- CMP
- COM
- CTR
- ECR
- GCL
- OPC
- RCA
- SCR
- SGA

AT&T Florida has narrowed the claim of confidentiality to certain information contained in the Inspection Report. Attached is an explanation of AT&T Florida's revised claim of confidentiality, including line item references to the confidential information. Two (2) redacted copies and one (1) highlighted copy of the Inspection Report are also provided.

Sincerely,

Jennifer S. Kay

Enclosure

SEC cc: Ms. Lisa Harvey (w/o proprietary enclosure)
OTH Ms. Beth Salak (w/o proprietary enclosure)

conf records

(See DN 01941-01
This claim of confidentiality was filed by or on behalf of a "telco" for Confidential DN 04830-01. The document is in locked storage pending advice on handling. To access the material, your name must be on the CASR. If undocketed, your division director must provide written permission before you can access it.

DOCUMENT NUMBER-DATE

04829 JUN 15 07

FPSC-COMMISSION CLERK

ATTACHMENT A

**AT&T Florida
AT&T Florida Pole Inspection Report June 2006 through December 2006**

Page 1 of 1

06/15/07

**AT&T FLORIDA'S POLE INSPECTION REPORT
JUNE 2006 THROUGH DECEMBER 2006**

Explanation of Proprietary Information

1. This information is considered by BellSouth Telecommunications, Inc. d/b/a AT&T Florida ("AT&T Florida") to be proprietary confidential business information within the scope of Section 364.183 (3) of the Florida Statutes. The information is intended to be and is treated by AT&T Florida as private, and has not otherwise been disclosed to the public. Further, the disclosure of this information would cause harm to the Company's business operations as third parties may attempt to take the information out of context and use it to form a predicate for claims or lawsuits against the Company. To the extent a third party had a valid claim or lawsuit against the Company, that party would have the opportunity to seek this information through the discovery process in a legal action. AT&T Florida does not concede that such claims or lawsuits would have merit and, to the contrary, believes that its infrastructure has performed well in past storms.
2. This information is the product of an internal audit of AT&T Florida's pole inventory and, thus, is considered proprietary confidential business information by the Company within the scope of Section 364.183 (3) of the Florida Statutes.

<u>LOCATION</u>	<u>REASON</u>
Page 3, Lines 22, 24 and 29	1, 2
Page 4, Columns A and B, lines 1 thru 22 and 24	1, 2
Page 5, Bar Graphs in Columns A thru Y, Percentages in lines 1 thru 7	1, 2
Page 6, Columns A and B, lines 1 thru 41	1, 2
Page 7, Bar Graphs in Columns A thru NN, Percentages in lines 1 thru 10	1, 2
Page 9, Lines 1, 3, 9, 18, 26 and 34	1, 2
Page 10, Lines 3 and 6	1, 2
Page 11, Columns A thru I, lines 1 thru 28	1, 2
Page 12, Columns A thru I, lines 1 thru 51	1, 2
Page 13, Columns A thru I, lines 1 thru 18	1, 2
Page 14, Columns A thru I, lines 1 thru 30	1, 2
Page 15, Columns A thru I, lines 1 thru 51	1, 2
Page 16, Columns A thru I, lines 1 thru 16	1, 2

ATTACHMENT B

**AT&T Florida
AT&T Florida Pole Inspection Report June 2006 through December 2006
Page 1 of 1
06/15/07**

**AT&T FLORIDA'S POLE INSPECTION REPORT
JUNE 2006 THROUGH DECEMBER 2006**

TWO REDACTED COPIES

REDACTED

Legal Department

JAMES MEZA III
General Counsel – Florida

Licensed in LA only

AT&T Florida
150 South Monroe Street
Suite 400
Tallahassee, Florida 32301
(305) 347-5558

*Licensed in LA only
Authorized House Counsel - FL*

March 1, 2007

Mrs. Blanca S. Bayo
Director, Division of the Commission Clerk
and Administrative Services
Florida Public Service Commission
2540 Shumard Oak Boulevard
Tallahassee, Florida 32399-0850

In Re: AT&T Florida Pole Inspection June 2006 through December 2006

Dear Mrs. Bayo:

Attached is AT&T Florida's pole inspection report for June 2006 through December 2006 pursuant to PSC Order No. Order No. PSC-06-0168-PAA-TL.

BellSouth, pursuant to Section 364.183(3), Florida Statutes, and Rule 25-22.006, Florida Administrative Code, hereby makes a claim of confidentiality for its pole inspection report. The responses contain proprietary confidential business information.

Sincerely,



James Meza

Annual Pole Inspection Report of BellSouth Telecommunications, Inc. d/b/a
AT&T Florida
June 2006 – December 2006

BellSouth Telecommunications, Inc. d/b/a AT&T Florida ("AT&T Florida"), pursuant to Order NO. PSC-06-0168-PAA-TL, DOCKET NO. 060077-TL ("Pole Inspection Order"), submits the following information regarding its pole inspection process for the initial reporting period of June, 2006 – December, 2006.

1) A review of the methods the company used to determine NESC compliance for strength and structural integrity of the wood poles included in the previous year's annual inspections, taking into account pole loadings where required:

AT&T Florida partnered with Florida Power & Light Company and Keys Energy in South Florida to perform joint pole inspections during this reporting period. In connection with this process, AT&T Florida contracted with OSMOSE to inspect AT&T Florida's wood poles. OSMOSE forwarded inspection data to AT&T Florida at regular intervals, and AT&T Florida performed quality control checks to validate the inspection data. As information, AT&T Florida has also held preliminary meetings with Gulf Power Company to begin joint pole inspections in 2007.

Using National Electric Safety Code ("NESC") Grade C Construction Standards as the guideline to determine NESC compliance for strength and structural integrity, and taking into account pole loadings where required, AT&T Florida used the following inspection process for its wood poles:

➤ **Visual Inspection**

If OSMOSE found an obvious defect that justified pole replacement, no additional inspection was performed. OSMOSE designated the pole as "Non-restorable" and identified it to AT&T Florida Engineering and Construction forces as a pole to be replaced.

When replacing a pole, AT&T Florida notifies the power company and third party attachers that they need to transfer their facilities to the new pole. Once all facilities are removed or transferred, AT&T Florida removes the old pole.

➤ **Sound and Bore**

If no obvious defect was found on the initial visual inspection, OSMOSE conducted a sound and bore test on the pole to determine the soundness of the interior and exterior of the pole.

➤ **Ground Line Excavation**

OSMOSE performed ground line excavation on every pole, except where the pole base was surrounded by concrete and/or asphalt, or other factors existed that would make excavation hazardous, such as the presence of buried power facilities.

➤ **Load Calculation**

Using a software application (OCALC) that it developed, and which is used throughout the industry to analyze pole loading data, OSMOSE performed a load calculation on each pole inspected. The load calculation is based on NESC Grade C Construction standards. It identifies potential loading defects based on remaining pole strength and the profile of all attachments, whether owned by AT&T Florida, the power company, or a third party.

OSMOSE also considered other factors to determine the strength and structural integrity of the poles, including:

- Year Pole Manufactured
- Height and Class of Pole
- Species or Material of Pole
- Original Groundline Circumference
- Current Effective Groundline Circumference
- Category of Decay Type, if Present
- Measurements of Decay Width and Depth

2) An explanation of the inspected poles selection criteria, including, among other things, geographic location and the rationale for including each such selection criterion:

AT&T Florida met with its power company partners to determine which areas would be inspected first. The key factors they used to define the geographical area for the first inspection were coastal exposure, population density, and critical infrastructure customers, such as hospitals, 911 centers, etc.

The areas chosen crossed 46 AT&T Florida Wire Centers. Thirty three (33) of these wire centers have coastal exposure. Of the 13 wire centers remaining, 11 were in the Metro Miami and Metro Fort Lauderdale areas.

3) Summary data and results of the company's previous year's wood pole inspections, addressing the strength, structural integrity, and loading requirements of the NESC (See Attachment B to this Order):

AT&T Florida's completed Attachment B is attached hereto.

REDACTED

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30

4) The cause(s) of each pole failure for poles failing inspection, to the extent that such cause(s) can be discerned in the inspection. Also, the specific actions the company has taken or will take to correct each pole failure.

AT&T Florida adopted a very aggressive definition of a pole "failing inspection." Specifically, AT&T Florida instructed OSMOSE to identify not only poles that warranted replacement, but also poles that had minimal defects. Thus, the fact that a pole is classified here as "failing inspection" does not mean that the pole was in danger of falling. In determining whether to replace a pole, AT&T Florida considered the following factors:

- > Whether the pole had a defect (e.g., shell rot, damage from insect infestation);
- > The extent of the defect (i.e., minimal or significant);
- > Whether remediation would effectively extend the life of the pole; and
- > Whether transfer of the existing power and/or telecommunications facilities would be simple or complex. (A complex transfer would include situations where the attachments involved transition from aerial to buried on a pole; where equipment other than cable or conductors would need to be moved; and where "corner" poles with cable/guying arrangements would be involved, as opposed to straight line poles.)

Of the 21,955 poles inspected, AT&T Florida identified [REDACTED] poles that merit replacement promptly and AT&T Florida plans to do so. The Company identified an additional [REDACTED] poles that do not merit replacement in the near future but that, based on an analysis of the foregoing factors, it intends to replace in the next 18 months

Table 1 below outlines the primary reasons that poles were classified as "failing inspection," to the extent that such information could be discerned from the inspection. Table 2 outlines the age of those poles. As information, [REDACTED] of the poles in this universe were 30 years old or greater.

REDACTED


Table 1

Primary Reason for Failure Classification

	A	B
Primary Reason	Number of Poles	% of Total Poles Failed
Shell Rot	[REDACTED]	[REDACTED]
Rotten Butt	[REDACTED]	[REDACTED]
Decayed Top	[REDACTED]	[REDACTED]
Woodpecker Holes	[REDACTED]	[REDACTED]
Split Top	[REDACTED]	[REDACTED]
Heart Rot Above	[REDACTED]	[REDACTED]
Heart Rot	[REDACTED]	[REDACTED]
Shell Rot Above	[REDACTED]	[REDACTED]
Hazardous Conditions	[REDACTED]	[REDACTED]
Excessive Checking / Cracking	[REDACTED]	[REDACTED]
Internal Decay	[REDACTED]	[REDACTED]
Exposed Pocket	[REDACTED]	[REDACTED]
Exposed Pocket Above	[REDACTED]	[REDACTED]
Internal Decay Above	[REDACTED]	[REDACTED]
Previous Reject	[REDACTED]	[REDACTED]
Enclosed Pocket Above	[REDACTED]	[REDACTED]
Excessive Cracking/Checking	[REDACTED]	[REDACTED]
Fire Damage	[REDACTED]	[REDACTED]
Lightning Damage	[REDACTED]	[REDACTED]
Mechanical Damage	[REDACTED]	[REDACTED]
Wood Borers	[REDACTED]	[REDACTED]
Total	[REDACTED]	[REDACTED]

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24

[REDACTED] of 21,955 Poles Inspected - [REDACTED] Merit Replacement



- J Shell Rot
- O Rotten Butt
- P Decayed Top
- U Woodpecker Holes
- U Split Top
- π Heart Rot Above
- o Heart Rot
- F Shell Rot Above
- H Hazardous Conditions
- 4 Excessive Checking / Cracking
- r Internal Decay
- 3 Exposed Pocket
- 2 Exposed Pocket Above
- o Internal Decay Above
- o Previous Reject
- o Enclosed Pocket Above
- c Excessive Cracking/Checking
- < Fire Damage
- E Lightning Damage
- X Mechanical Damage
- Y Wood Borers

Poles "Tasting Inspection" By Primary Cause

REJECTED

S

REDACTED

Table 2

Age of Poles Classified as "Failing Inspection"

A B

Age of Pole	Number of Poles	% of Total Poles Failed
1935	[REDACTED]	[REDACTED]
1939	[REDACTED]	[REDACTED]
1950	[REDACTED]	[REDACTED]
1952	[REDACTED]	[REDACTED]
1953	[REDACTED]	[REDACTED]
1954	[REDACTED]	[REDACTED]
1955	[REDACTED]	[REDACTED]
1956	[REDACTED]	[REDACTED]
1957	[REDACTED]	[REDACTED]
1958	[REDACTED]	[REDACTED]
1959	[REDACTED]	[REDACTED]
1960	[REDACTED]	[REDACTED]
1961	[REDACTED]	[REDACTED]
1962	[REDACTED]	[REDACTED]
1963	[REDACTED]	[REDACTED]
1964	[REDACTED]	[REDACTED]
1965	[REDACTED]	[REDACTED]
1966	[REDACTED]	[REDACTED]
1967	[REDACTED]	[REDACTED]
1968	[REDACTED]	[REDACTED]
1969	[REDACTED]	[REDACTED]
1970	[REDACTED]	[REDACTED]
1971	[REDACTED]	[REDACTED]
1972	[REDACTED]	[REDACTED]
1974	[REDACTED]	[REDACTED]
1975	[REDACTED]	[REDACTED]
1977	[REDACTED]	[REDACTED]
1978	[REDACTED]	[REDACTED]
1979	[REDACTED]	[REDACTED]
1980	[REDACTED]	[REDACTED]
1982	[REDACTED]	[REDACTED]
1984	[REDACTED]	[REDACTED]
1985	[REDACTED]	[REDACTED]
1986	[REDACTED]	[REDACTED]
1987	[REDACTED]	[REDACTED]
1988	[REDACTED]	[REDACTED]
1989	[REDACTED]	[REDACTED]
1990	[REDACTED]	[REDACTED]
1992	[REDACTED]	[REDACTED]
1993	[REDACTED]	[REDACTED]
Total	[REDACTED]	[REDACTED]

REDACTED

% of Poles "Failing Inspection"

1
2
3
4
5
6
7
8
9
10

A 1935
B 1938
C 1950
D 1952
E 1953
F 1954
G 1955
H 1956
I 1957
J 1958
K 1959
L 1960
M 1961
N 1962
O 1963
P 1964
Q 1965
R 1966
S 1967
T 1968
U 1969
V 1970
W 1971
X 1972
Y 1974
Z 1975
AA 1977
AB 1978
AC 1979
AD 1980
AE 1982
AF 1984
AG 1985
AH 1986
AI 1987
AJ 1988
AK 1989
AL 1990
AM 1992
AN 1993

POLE INSPECTION REPORT

COMPANY: AT&T Florida

Summary of Pole Inspections
Period: June, 2006 – December, 2006

Type of Inspection:

See Response (1) in AT&T Florida's Annual Pole Inspection Report.

Type of Pole: Class ____ **Material** ____ **Vintage** ____ **Installed Population** ____

See Attachment #1 to this Attachment B.

Number of inspections planned and number completed: Include reason for any variance between planned and completed pole inspections. All variances justification should address resultant backlog, if any, and plans to address any backlog.

Planned – 28,707

Completed – 21,955

The most efficient and effective pole inspection process is to perform joint inspections within a defined geography in conjunction with a power company. Within any defined geography, be it power company substation boundaries or AT&T Florida wire center boundaries, the mix of ownership of poles will vary. The "Planned" number of AT&T Florida inspections represents a six month average forecast of inspections, based on AT&T Florida's total pole population within the state of Florida and the requirement that all poles be inspected over an 8 year cycle. The "Completed" number of inspections represents the total number of AT&T Florida poles inspected during the six month period of this report (June, 2006 – December-2006).

The difference between the "Planned" and "Completed" does not represent a backlog of inspections; rather it is indicative of the ownership ratios between AT&T Florida and power companies within the geographical areas selected for the first inspection period. Future inspection periods may therefore result in more completions than the average forecast of planned inspections. AT&T Florida is committed to completing an inspection of all its poles over an 8 year period.

Number of inspected poles addressing a prior backlog

None

See explanation above.

Number of poles failing the inspection

Of the 21,955 poles inspected, AT&T Florida identified [redacted] poles that merit replacement promptly and AT&T Florida plans to do so. The Company identified an additional [redacted] poles that do not merit replacement in the near future but that, based on an analysis of the factors in Response (4) in AT&T Florida's Annual Inspection Report, it intends to replace in the next 18 months.

10-09-02-03-04-05-06-07-08-09-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37

Number of poles requiring minor follow-up

[redacted]

'Minor follow-up' is defined by a need to make a subsequent visit to a pole for some type of remediation work. Remediation work would include activities such as straightening a pole that may be leaning or installing a "truss" or brace to a pole to correct a minor defect.

Number of poles requiring a change in inspection cycle

[redacted]

Due to AT&T Florida's aggressive pole replacement criteria and remediation of poles identified as needing minor follow-up, no AT&T Florida-owned poles were identified or are anticipated to require a change in inspection cycle.

Number of poles that required no change in inspection cycle or remediation

[redacted]

Due to AT&T Florida's aggressive pole replacement criteria and remediation of poles identified as needing minor follow-up, 17, 889 AT&T Florida-owned poles require no change in inspection cycle or remediation.

Number of poles that were overloaded

[redacted]

See Response (1) in AT&T Florida's Annual Pole Inspection Report for a more detailed description of the loading calculation process.

REDACTED

— (M) FW D
J 6 0 1 9 7

Number of poles with an estimated remaining pole life of less than 8 years

[REDACTED]

Due to AT&T Florida's aggressive pole replacement criteria and remediation of poles identified as needing minor follow-up, [REDACTED] AT&T Florida-owned poles in the inspection area will have a remaining pole life of less than 8 years.

REDACTED

Attachment #1

Type of Pole: Class__ Material__ Vintage__ Installed Population__

The following table represents the Installed Population of poles owned by AT&T Florida, by Class and Vintage.

- AT&T Florida does not keep records as to the type or material of poles owned by AT&T Florida. AT&T Florida is not aware of any pole within the Installed Population that is anything other than Southern Pine. No result of any inspection during this period identified any pole material other than Southern Pine.
- This data is derived from an extract from AT&T Florida Property Records.
- This extract will be provided each year and will reflect any changes recorded to AT&T Florida Property Records made during the previous year.

VINTAGE	CLASS									Grand Total
	A	B	C	D	E	F	G	H	I	
	1	2	3	4	5	6	7	8	9	
1901										
1908										
1909										
1910										
1913										
1914										
1916										
1917										
1918										
1919										
1920										
1921										
1922										
1923										
1924										
1925										
1926										
1927										
1928										
1929										
1930										
1931										
1932										
1933										
1934										
1935										
1936										
1937										

1901-1937

RETRACTED

VINTAGE	CLASS									Grand Total
	A 1	B 2	C 3	D 4	E 5	F 6	G 7	H 8	H 9	
1938										
1939										
1940										
1941										
1942										
1943										
1944										
1945										
1946										
1947										
1948										
1949										
1950										
1951										
1952										
1953										
1954										
1955										
1956										
1957										
1958										
1959										
1960										
1961										
1962										
1963										
1964										
1965										
1966										
1967										
1968										
1969										
1970										
1971										
1972										
1973										
1974										
1975										
1976										
1977										
1978										
1979										
1980										
1981										
1982										
1983										
1984										
1985										
1986										
1987										
1988										

REDACTED

VINTAGE	CLASS									Grand Total
	A 1	B 2	C 3	D 4	E 5	F 6	G 7	H 8	H 9	
1989										
1990										
1991										
1992										
1993										
1994										
1995										
1996										
1997										
1998										
1999										
2000										
2001										
2002										
2003										
2004										
2005										
Grand Total										

109916402

REFLECTED

Type of Pole: Class__ Material__ Vintage__ Installed Population__

The following table represents the percentage of the Installed Population of poles owned by AT&T Florida, based on vintage.

- AT&T Florida does not keep records as to the type, or material of poles owned by AT&T Florida. AT&T Florida is not aware of any pole in within the Installed Population that is anything other than Southern Pine. No result of any inspection during this period identified any pole material other than Southern Pine.
- This data is derived from an extract from AT&T Florida Property Records.
- This extract will be provided each year and will reflect any changes recorded to AT&T Florida Property Records made during the previous year.

Vintage	CLASS									Grand Total
	A 1	B 2	C 3	D 4	E 5	F 6	G 7	H 8	I 9	
1901										
1908										
1909										
1910										
1913										
1914										
1916										
1917										
1918										
1919										
1920										
1921										
1922										
1923										
1924										
1925										
1926										
1927										
1928										
1929										
1930										
1931										
1932										
1933										
1934										
1935										
1936										
1937										
1938										
1939										

REDACTED

Vintage	CLASS								Grand Total
	A 1	B 2	C 3	D 4	E 5	F 6	G 7	H 8	
1940									
1941									
1942									
1943									
1944									
1945									
1946									
1947									
1948									
1949									
1950									
1951									
1952									
1953									
1954									
1955									
1956									
1957									
1958									
1959									
1960									
1961									
1962									
1963									
1964									
1965									
1966									
1967									
1968									
1969									
1970									
1971									
1972									
1973									
1974									
1975									
1976									
1977									
1978									
1979									
1980									
1981									
1982									
1983									
1984									
1985									
1986									
1987									
1988									
1989									
1990									

REDACTED

Vintage	CLASS									Grand Total
	A 1	B 2	C 3	D 4	E 5	F 6	G 7	H 8	H 9	
1991										
1992										
1993										
1994										
1995										
1996										
1997										
1998										
1999										
2000										
2001										
2002										
2003										
2004										
2005										
Grand Total										

Handwritten notes on the right side of the table:
= 1991-1995 = 1996-1998 = 1999-2005 = 1991-1995 = 1996-1998 = 1999-2005

CONFIDENTIAL

State of Florida



Public Service Commission

CAPITAL CIRCLE OFFICE CENTER • 2540 SHUMARD OAK BOULEVARD
TALLAHASSEE, FLORIDA 32399-0850

-M-E-M-O-R-A-N-D-U-M-

DATE: 6-15-07
TO: Jennifer S. Kay
FROM: T. Henry, Division of the Commission Clerk &
Administrative Services
RE: **Acknowledgment of Receipt of Confidential Filing**

This will acknowledge receipt of a **CONFIDENTIAL DOCUMENT** filed in Docket No. 070000 or (if filed in an undocketed matter) concerning Role inspection report June - Dec '06, and filed on behalf of AT & T Fla. / Kay. The document will be maintained in locked storage.

Any questions regarding this matter should be directed to Marguerite Lockard at (850) 413-6770.

I:\Confid\ackconf.doc

PSC/CCA019-C(Rev 12/06)

CONFIDENTIAL

DOCUMENT NUMBER-DATE

04830 JUN 15 5

FPSC-COMMISSION CLERK