

Town of Havana, Florida

Re: Docket No. 20170215-EU - Review of electric utility hurricane preparedness and restoration actions.

1. Please provide the following information for a specific example where storm hardened structures incurred damage and required repair or replacement due to Hurricane Irma.
 - a. A description of the damage incurred (i.e. broken pole, displaced underground vault, etc.).
 - b. A description of the repair process, including a description of any temporary repairs that required a follow-up trip.
 - c. A description of the repair process if the facilities had not been hardened.

The Town of Havana incurred no damage to storm hardened structures during Hurricane Irma.
