Economic Potential - RIM

Passing Measures Results

[Economic Potential or Achievable Potential] – [TRC or RIM]

Customer Class	Measure Name	Segment	Vintage	*Measure Name	TRC	RIM	PCT	Summer (MW)	Winter (MW)	Energy (GWh)
Residential	Spray Foam Insulation(Base R2)	Single Family	New	N_SF_Spray I	1.53	1.27	1.20	0	0	0
Residential	Home Energy Management System	Single Family	New	N_SF_Home	1.83	1.13	1.62	0	0	0
Residential	Ceiling Insulation(R2 to R38)	Single Family	New	N_SF_Ceiling	7.31	1.27	5.73	0	0	0
Residential	Ceiling Insulation(R19 to R38)	Single Family	New	N_SF_Ceiling	1.35	1.27	1.06	0	0	0
Residential	Ceiling Insulation(R12 to R38)	Single Family	New	N_SF_Ceiling	2.29	1.27	1.80	0	0	0
Residential	Wall Insulation	Single Family	Existing	E_SF_Wall In	1.35	1.27	1.06	21	10	23
Residential	Spray Foam Insulation(Base R2)	Single Family	Existing	E_SF_Spray I	1.53	1.27	1.20	180	78	287
Residential	Home Energy Management System	Single Family	Existing	E_SF_Home I	1.83	1.13	1.62	3	1	4
Residential	Energy Star Windows	Single Family	Existing	E_SF_Energy	3.62	1.27	2.84	56	23	112
Residential	Duct Repair	Single Family	Existing	E_SF_Duct R	3.64	1.13	3.22	53	20	82
Residential	Ceiling Insulation(R2 to R38)	Single Family	Existing	E_SF_Ceiling	7.31	1.27	5.73	18	8	27
Residential	Ceiling Insulation(R19 to R38)	Single Family	Existing	E_SF_Ceiling	1.35	1.27	1.06	11	5	17
Residential	Ceiling Insulation(R12 to R38)	Single Family	Existing	E_SF_Ceiling	2.29	1.27	1.80	54	25	83
Residential	Air Sealing-Infiltration Control	Single Family	Existing	E_SF_Air Sea	1.30	1.13	1.15	58	22	89
Residential	15 SEER Air Source Heat Pump	Single Family	Turnover	T_SF_15 SEE	1.50	1.22	1.23	63	119	147
Residential	14 SEER ASHP from base electric resistance heating	Single Family	Turnover	T_SF_14 SEE	3.50	1.19	2.94	0	96	148
Residential	15 SEER Air Source Heat Pump	Single Family	New	N_SF_15 SEE	1.50	1.22	1.23	1	2	3
Residential	14 SEER ASHP from base electric resistance heating	Single Family	New	N_SF_14 SEE	3.50	1.19	2.94	0	2	3
Residential	16 SEER Central AC	Single Family	Turnover	T_SF_16 SEE	1.53	1.10	1.39	37	0	72
Residential	15 SEER Central AC	Single Family	Turnover	T_SF_15 SEE	1.60	1.10	1.45	0	0	0
Residential	16 SEER Central AC	Single Family	New	N_SF_16 SEE	1.53	1.10	1.39	1	0	1
Residential	15 SEER Central AC	Single Family	New	N_SF_15 SEE	1.60	1.10	1.45	0	0	0
Residential	Home Energy Management System	Multi-Family	New	N_MF_Home	1.32	1.13	1.16	0	0	0
Residential	Ceiling Insulation(R2 to R38)	Multi-Family	New	N_MF_Ceilin	5.30	1.27	4.16	0	0	0
Residential	Ceiling Insulation(R12 to R38)	Multi-Family	New	N_MF_Ceilin	1.71	1.27	1.34	0	0	0
Residential	Home Energy Management System	Multi-Family	Existing	E_MF_Home	1.32	1.13	1.16	3	1	3
Residential	Energy Star Windows	Multi-Family	Existing	E_MF_Energ	3.62	1.27	2.84	28	5	55
Residential	Duct Repair	Multi-Family	Existing	E_MF_Duct I	2.37	1.13	2.09	82	14	91
Residential	Ceiling Insulation(R2 to R38)	Multi-Family	Existing	E_MF_Ceilin	5.30	1.27	4.16	54	22	83
Residential	Ceiling Insulation(R12 to R38)	Multi-Family	Existing	E_MF_Ceilin	1.71	1.27	1.34	17	8	26
Residential	Air Sealing-Infiltration Control	Multi-Family	Existing	E_MF_Air Se	1.42	1.13	1.26	45	8	50
Residential	14 SEER ASHP from base electric resistance heating	Multi-Family	Turnover	T_MF_14 SE	3.20	1.19	2.69	0	8	12
Residential	14 SEER ASHP from base electric resistance heating	Multi-Family	New	N_MF_14 SE	3.20	1.19	2.69	0	0	0
Residential	Home Energy Management System	Manufactured Home	New	N_MH_Home	2.03	1.13	1.79	0	0	0
Residential	Ceiling Insulation(R2 to R38)	Manufactured Home	New	N_MH_Ceilin	5.17	1.27	4.06	0	0	0
Residential	Ceiling Insulation(R12 to R38)	Manufactured Home	New	N_MH_Ceilin	1.61	1.27	1.26	0	0	0
Residential	Wall Insulation	Manufactured Home	Existing	E_MH_Wall	1.56	1.27	1.22	5	3	5
Residential	Home Energy Management System	Manufactured Home	Existing	E_MH_Home	2.03	1.13	1.79	5	1	4
Residential	Energy Star Windows	Manufactured Home	Existing	E_MH_Energ	3.62	1.27	2.84	13	2	26
Residential	Duct Repair	Manufactured Home	Existing	E_MH_Duct	3.56	1.13	3.15	58	10	60
Residential	Ceiling Insulation(R2 to R38)	Manufactured Home	Existing	E_MH_Ceilin	5.17	1.27	4.06	25	16	41
Residential	Ceiling Insulation(R12 to R38)	Manufactured Home	Existing	E_MH_Ceilin	1.61	1.27	1.26	7	5	12
Residential	Air Sealing-Infiltration Control	Manufactured Home	Existing	E_MH_Air Se	2.03	1.13	1.79	32	6	33
Residential	14 SEER ASHP from base electric resistance heating	Manufactured Home	Turnover	T_MH_14 SE	2.17	1.19	1.82	0	4	6
Residential	14 SEER ASHP from base electric resistance heating	Manufactured Home	New	N_MH_14 SE	2.17	1.19	1.82	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Assembly	Turnover	T_AS_High E	2.55	1.17	2.19	0	0	1
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	College and University	Turnover	T_CU_High E	2.83	1.17	2.42	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Grocery	Turnover	T_GR_High E	1.41	1.17	1.21	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Healthcare	Turnover	T_HC_High E	5.55	1.17	4.76	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Hospitals	Turnover	T_HS_High E	5.26	1.17	4.50	1	0	3
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Institutional	Turnover	T_IN_High Ef	1.38	1.17	1.18	0	0	1
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Lodging/Hospitality	Turnover	T_LG_High E	4.21	1.17	3.61	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Miscellaneous	Turnover	T_MS_High E	1.42	1.17	1.22	0	0	1
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Offices	Turnover	T_OF_High E	2.87	1.17	2.46	1	0	2
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Restaurants	Turnover	T_RS_High E	4.13	1.17	3.54	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Retail	Turnover	T_RT_High E	3.24	1.17	2.78	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Schools K-12	Turnover	T_SC_High E	2.82	1.17	2.41	0	0	1
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Assembly	New	N_AS_High E	2.55	1.17	2.19	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	College and University	New	N_CU_High E	2.83	1.17	2.42	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Grocery	New	N_GR_High E	1.41	1.17	1.21	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Healthcare	New	N_HC_High E	5.55	1.17	4.76	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Hospitals	New	N_HS_High E	5.26	1.17	4.50	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Institutional	New	N_IN_High E	1.38	1.17	1.18	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Lodging/Hospitality	New	N_LG_High E	4.21	1.17	3.61	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Miscellaneous	New	N_MS_High E	1.42	1.17	1.22	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Offices	New	N_OF_High E	2.87	1.17	2.46	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Restaurants	New	N_RS_High E	4.13	1.17	3.54	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Retail	New	N_RT_High E	3.24	1.17	2.78	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Schools K-12	New	N_SC_High E	2.82	1.17	2.41	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Assembly	Turnover	T_AS_High E	1.48	1.17	1.27	0	0	1
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	College and University	Turnover	T_CU_High E	1.65	1.17	1.41	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Healthcare	Turnover	T_HC_High E	3.23	1.17	2.77	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Hospitals	Turnover	T_HS_High E	3.06	1.17	2.62	1	0	2
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Lodging/Hospitality	Turnover	T_LG_High E	2.45	1.17	2.10	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Offices	Turnover	T_OF_High E	1.67	1.17	1.43	0	0	1
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Restaurants	Turnover	T_RS_High E	2.40	1.17	2.06	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Retail	Turnover	T_RT_High E	1.88	1.17	1.61	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Schools K-12	Turnover	T_SC_High E	1.64	1.17	1.40	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Assembly	New	N_AS_High E	1.48	1.17	1.27	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	College and University	New	N_CU_High E	1.65	1.17	1.41	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Healthcare	New	N_HC_High E	3.23	1.17	2.77	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Hospitals	New	N_HS_High E	3.06	1.17	2.62	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Lodging/Hospitality	New	N_LG_High E	2.45	1.17	2.10	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Offices	New	N_OF_High E	1.67	1.17	1.43	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Restaurants	New	N_RS_High E	2.40	1.17	2.06	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Retail	New	N_RT_High E	1.88	1.17	1.61	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Schools K-12	New	N_SC_High E	1.64	1.17	1.40	0	0	0
Commercial	High Efficiency DX 135k- less than 240k BTU	Healthcare	Turnover	T_HC_High E	1.51	1.18	1.28	3	0	7
Commercial	High Efficiency DX 135k- less than 240k BTU	Hospitals	Turnover	T_HS_High E	1.43	1.18	1.22	1	0	3
Commercial	High Efficiency DX 135k- less than 240k BTU	Healthcare	New	N_HC_High E	1.51	1.18	1.28	0	0	0
Commercial	High Efficiency DX 135k- less than 240k BTU	Hospitals	New	N_HS_High E	1.43	1.18	1.22	0	0	0
Commercial	High Efficiency PTAC	Grocery	Turnover	T_GR_High E	4.86	1.35	3.60	0	0	0

Economic Potential - RIM

Falling Measures Results

[Economic Potential or Achievable Potential] – [TRC or RIM]

Customer Class	Measure Name	Segment	Vintage	*Measure Name	TRC	RIM	PCT	Summer (MW)	Winter (MW)	Energy (GWh)	Reason For Failure
Residential	Energy Star Clothes Dryer	Single Family	Turnover	T_SF_Energy	0.31	0.47	0.65	0	0	0	Fail RIM
Residential	Energy Star Clothes Dryer	Multi-Family	Turnover	T_MF_Energ	0.31	0.47	0.65	0	0	0	Fail RIM
Residential	Energy Star Clothes Dryer	Manufactured Home	Turnover	T_MH_Energ	0.31	0.47	0.65	0	0	0	Fail RIM
Residential	Energy Star Clothes Dryer	Single Family	New	N_SF_Energy	0.31	0.47	0.65	0	0	0	Fail RIM
Residential	Energy Star Clothes Dryer	Multi-Family	New	N_MF_Energ	0.31	0.47	0.65	0	0	0	Fail RIM
Residential	Energy Star Clothes Dryer	Manufactured Home	New	N_MH_Energ	0.31	0.47	0.65	0	0	0	Fail RIM
Residential	Energy Star Clothes Washer	Single Family	Turnover	T_SF_Energy	7.20	0.69	10.41	0	0	0	Fail RIM
Residential	Energy Star Clothes Washer	Multi-Family	Turnover	T_MF_Energ	7.20	0.69	10.41	0	0	0	Fail RIM
Residential	Energy Star Clothes Washer	Manufactured Home	Turnover	T_MH_Energ	7.20	0.69	10.41	0	0	0	Fail RIM
Residential	Energy Star Clothes Washer	Single Family	New	N_SF_Energy	7.20	0.69	10.41	0	0	0	Fail RIM
Residential	Energy Star Clothes Washer	Multi-Family	New	N_MF_Energ	7.20	0.69	10.41	0	0	0	Fail RIM
Residential	Energy Star Clothes Washer	Manufactured Home	New	N_MH_Energ	7.20	0.69	10.41	0	0	0	Fail RIM
Residential	Energy Star Dishwasher	Single Family	Turnover	T_SF_Energy	0.00	0.40	0.00	0	0	0	Fail RIM
Residential	Energy Star Dishwasher	Multi-Family	Turnover	T_MF_Energ	0.00	0.40	0.00	0	0	0	Fail RIM
Residential	Energy Star Dishwasher	Manufactured Home	Turnover	T_MH_Energ	0.00	0.40	0.00	0	0	0	Fail RIM
Residential	Energy Star Dishwasher	Single Family	New	N_SF_Energy	0.00	0.40	0.00	0	0	0	Fail RIM
Residential	Energy Star Dishwasher	Multi-Family	New	N_MF_Energ	0.00	0.40	0.00	0	0	0	Fail RIM
Residential	Energy Star Dishwasher	Manufactured Home	New	N_MH_Energ	0.00	0.40	0.00	0	0	0	Fail RIM
Residential	Energy Star Freezer	Single Family	Turnover	T_SF_Energy	0.34	0.42	0.81	0	0	0	Fail RIM
Residential	Energy Star Freezer	Multi-Family	Turnover	T_MF_Energ	0.34	0.42	0.81	0	0	0	Fail RIM
Residential	Energy Star Freezer	Manufactured Home	Turnover	T_MH_Energ	0.34	0.42	0.81	0	0	0	Fail RIM
Residential	Energy Star Freezer	Single Family	New	N_SF_Energy	0.34	0.42	0.81	0	0	0	Fail RIM
Residential	Energy Star Freezer	Multi-Family	New	N_MF_Energ	0.34	0.42	0.81	0	0	0	Fail RIM
Residential	Energy Star Freezer	Manufactured Home	New	N_MH_Energ	0.34	0.42	0.81	0	0	0	Fail RIM
Residential	Energy Star Refrigerator	Single Family	Turnover	T_SF_Energy	0.66	0.44	1.50	0	0	0	Fail RIM
Residential	Energy Star Refrigerator	Multi-Family	Turnover	T_MF_Energ	0.66	0.44	1.50	0	0	0	Fail RIM
Residential	Energy Star Refrigerator	Manufactured Home	Turnover	T_MH_Energ	0.66	0.44	1.50	0	0	0	Fail RIM
Residential	Energy Star Refrigerator	Single Family	New	N_SF_Energy	0.66	0.44	1.50	0	0	0	Fail RIM
Residential	Energy Star Refrigerator	Multi-Family	New	N_MF_Energ	0.66	0.44	1.50	0	0	0	Fail RIM
Residential	Energy Star Refrigerator	Manufactured Home	New	N_MH_Energ	0.66	0.44	1.50	0	0	0	Fail RIM
Residential	Heat Pump Clothes Dryer	Single Family	Turnover	T_SF_Heat P	0.15	0.48	0.31	0	0	0	Fail RIM
Residential	Heat Pump Clothes Dryer	Multi-Family	Turnover	T_MF_Heat P	0.15	0.48	0.31	0	0	0	Fail RIM
Residential	Heat Pump Clothes Dryer	Manufactured Home	Turnover	T_MH_Heat P	0.15	0.48	0.31	0	0	0	Fail RIM
Residential	Heat Pump Clothes Dryer	Single Family	New	N_SF_Heat P	0.15	0.48	0.31	0	0	0	Fail RIM
Residential	Heat Pump Clothes Dryer	Multi-Family	New	N_MF_Heat P	0.15	0.48	0.31	0	0	0	Fail RIM
Residential	Heat Pump Clothes Dryer	Manufactured Home	New	N_MH_Heat	0.15	0.48	0.31	0	0	0	Fail RIM
Residential	High Efficiency Convection Oven	Single Family	Turnover	T_SF_High E	0.14	0.89	0.16	0	0	0	Fail RIM
Residential	High Efficiency Convection Oven	Multi-Family	Turnover	T_MF_High E	0.14	0.89	0.16	0	0	0	Fail RIM
Residential	High Efficiency Convection Oven	Manufactured Home	Turnover	T_MH_High E	0.14	0.89	0.16	0	0	0	Fail RIM
Residential	High Efficiency Convection Oven	Single Family	New	N_SF_High E	0.14	0.89	0.16	0	0	0	Fail RIM
Residential	High Efficiency Convection Oven	Multi-Family	New	N_MF_High E	0.14	0.89	0.16	0	0	0	Fail RIM
Residential	High Efficiency Convection Oven	Manufactured Home	New	N_MH_High	0.14	0.89	0.16	0	0	0	Fail RIM
Residential	High Efficiency Induction Cooktop	Single Family	Turnover	T_SF_High E	1.99	0.82	2.42	0	0	0	Fail RIM
Residential	High Efficiency Induction Cooktop	Multi-Family	Turnover	T_MF_High E	1.99	0.82	2.42	0	0	0	Fail RIM
Residential	High Efficiency Induction Cooktop	Manufactured Home	Turnover	T_MH_High E	1.99	0.82	2.42	0	0	0	Fail RIM
Residential	High Efficiency Induction Cooktop	Single Family	New	N_SF_High E	1.99	0.82	2.42	0	0	0	Fail RIM
Residential	High Efficiency Induction Cooktop	Multi-Family	New	N_MF_High E	1.99	0.82	2.42	0	0	0	Fail RIM
Residential	High Efficiency Induction Cooktop	Manufactured Home	New	N_MH_High	1.99	0.82	2.42	0	0	0	Fail RIM
Residential	Heat Pump Water Heater	Single Family	Turnover	T_SF_Heat P	0.96	0.61	1.59	0	0	0	Fail RIM
Residential	Heat Pump Water Heater	Multi-Family	Turnover	T_MF_Heat P	0.76	0.61	1.25	0	0	0	Fail RIM
Residential	Heat Pump Water Heater	Manufactured Home	Turnover	T_MH_Heat P	0.75	0.61	1.24	0	0	0	Fail RIM
Residential	Heat Pump Water Heater	Single Family	New	N_SF_Heat P	0.96	0.61	1.59	0	0	0	Fail RIM
Residential	Heat Pump Water Heater	Multi-Family	New	N_MF_Heat P	0.76	0.61	1.25	0	0	0	Fail RIM
Residential	Heat Pump Water Heater	Manufactured Home	New	N_MH_Heat	0.75	0.61	1.24	0	0	0	Fail RIM
Residential	Instantaneous Hot Water System	Single Family	Turnover	T_SF_Instant	0.08	0.70	0.11	0	0	0	Fail RIM
Residential	Instantaneous Hot Water System	Multi-Family	Turnover	T_MF_Instan	0.06	0.70	0.09	0	0	0	Fail RIM
Residential	Instantaneous Hot Water System	Manufactured Home	Turnover	T_MH_Instan	0.06	0.70	0.09	0	0	0	Fail RIM
Residential	Instantaneous Hot Water System	Single Family	New	N_SF_Instant	0.08	0.70	0.11	0	0	0	Fail RIM
Residential	Instantaneous Hot Water System	Multi-Family	New	N_MF_Instan	0.06	0.70	0.09	0	0	0	Fail RIM
Residential	Instantaneous Hot Water System	Manufactured Home	New	N_MH_Instan	0.06	0.70	0.09	0	0	0	Fail RIM
Residential	Solar Water Heater	Single Family	Turnover	T_SF_Solar V	0.16	0.38	0.41	0	0	0	Fail RIM
Residential	Solar Water Heater	Multi-Family	Turnover	T_MF_Solar	0.12	0.38	0.32	0	0	0	Fail RIM
Residential	Solar Water Heater	Manufactured Home	Turnover	T_MH_Solar	0.12	0.38	0.32	0	0	0	Fail RIM
Residential	Solar Water Heater	Single Family	New	N_SF_Solar V	0.16	0.38	0.41	0	0	0	Fail RIM
Residential	Solar Water Heater	Multi-Family	New	N_MF_Solar	0.12	0.38	0.32	0	0	0	Fail RIM
Residential	Solar Water Heater	Manufactured Home	New	N_MH_Solar	0.12	0.38	0.32	0	0	0	Fail RIM
Residential	Energy Star Air Purifier	Single Family	Turnover	T_SF_Energy	0.00	0.42	0.00	0	0	0	Fail RIM
Residential	Energy Star Air Purifier	Multi-Family	Turnover	T_MF_Energ	0.00	0.42	0.00	0	0	0	Fail RIM
Residential	Energy Star Air Purifier	Manufactured Home	Turnover	T_MH_Energ	0.00	0.42	0.00	0	0	0	Fail RIM
Residential	Energy Star Air Purifier	Single Family	New	N_SF_Energy	0.00	0.42	0.00	0	0	0	Fail RIM
Residential	Energy Star Air Purifier	Multi-Family	New	N_MF_Energ	0.00	0.42	0.00	0	0	0	Fail RIM
Residential	Energy Star Air Purifier	Manufactured Home	New	N_MH_Energ	0.00	0.42	0.00	0	0	0	Fail RIM
Residential	Energy Star Audio-Video Equipment	Single Family	Turnover	T_SF_Energy	0.08	0.23	0.33	0	0	0	Fail RIM
Residential	Energy Star Audio-Video Equipment	Multi-Family	Turnover	T_MF_Energ	0.08	0.23	0.33	0	0	0	Fail RIM
Residential	Energy Star Audio-Video Equipment	Manufactured Home	Turnover	T_MH_Energ	0.08	0.23	0.33	0	0	0	Fail RIM
Residential	Energy Star Audio-Video Equipment	Single Family	New	N_SF_Energy	0.08	0.23	0.33	0	0	0	Fail RIM
Residential	Energy Star Audio-Video Equipment	Multi-Family	New	N_MF_Energ	0.08	0.23	0.33	0	0	0	Fail RIM
Residential	Energy Star Audio-Video Equipment	Manufactured Home	New	N_MH_Energ	0.08	0.23	0.33	0	0	0	Fail RIM
Residential	Energy Star Imaging Equipment	Single Family	Turnover	T_SF_Energy	0.00	0.33	0.00	0	0	0	Fail RIM
Residential	Energy Star Imaging Equipment	Multi-Family	Turnover	T_MF_Energ	0.00	0.33	0.00	0	0	0	Fail RIM
Residential	Energy Star Imaging Equipment	Manufactured Home	Turnover	T_MH_Energ	0.00	0.33	0.00	0	0	0	Fail RIM
Residential	Energy Star Imaging Equipment	Single Family	New	N_SF_Energy	0.00	0.33	0.00	0	0	0	Fail RIM
Residential	Energy Star Imaging Equipment	Multi-Family	New	N_MF_Energ	0.00	0.33	0.00	0	0	0	Fail RIM
Residential	Energy Star Imaging Equipment	Manufactured Home	New	N_MH_Energ	0.00	0.33	0.00	0	0	0	Fail RIM
Residential	Energy Star Personal Computer	Single Family	Turnover	T_SF_Energy	0.73	0.40	1.80	0	0	0	Fail RIM
Residential	Energy Star Personal Computer	Multi-Family	Turnover	T_MF_Energ	0.73	0.40	1.80	0	0	0	Fail RIM
Residential	Energy Star Personal Computer	Manufactured Home	Turnover	T_MH_Energ	0.73	0.40	1.80	0	0	0	Fail RIM
Residential	Energy Star Personal Computer	Single Family	New	N_SF_Energy	0.73	0.40	1.80	0	0	0	Fail RIM
Residential	Energy Star Personal Computer	Multi-Family	New	N_MF_Energ	0.73	0.40	1.80	0	0	0	Fail RIM
Residential	Energy Star Personal Computer	Manufactured Home	New	N_MH_Energ	0.73	0.40	1.80	0	0	0	Fail RIM
Residential	Energy Star TV	Single Family	Turnover	T_SF_Energy	0.12	0.45	0.27	0	0	0	Fail RIM
Residential	Energy Star TV	Multi-Family	Turnover	T_MF_Energ	0.12	0.45	0.27	0	0	0	Fail RIM

Economic Potential - TRC

Passing Measures Results

[Economic Potential or Achievable Potential] – [TRC or RIM]

Customer Class	Measure Name	Segment	Vintage	*Measure Name	TRC	RIM	PCT	Summer (MW)	Winter (MW)	Energy (GWh)
Residential	Thermostatic Shower Restriction Valve	Single Family	New	N_SF_Therm	1.59	0.50	3.17	0	0	0
Residential	Thermostatic Shower Restriction Valve	Single Family	Existing	E_SF_Therm	1.59	0.50	3.17	0	0	1
Residential	Spray Foam Insulation(Base R2)	Single Family	New	N_SF_Spray I	1.53	1.27	1.20	0	0	0
Residential	Home Energy Management System	Single Family	New	N_SF_Home	1.83	1.13	1.62	0	0	0
Residential	Ceiling Insulation(R2 to R38)	Single Family	New	N_SF_Ceiling	7.31	1.27	5.73	0	0	0
Residential	Ceiling Insulation(R19 to R38)	Single Family	New	N_SF_Ceiling	1.35	1.27	1.06	0	0	0
Residential	Ceiling Insulation(R12 to R38)	Single Family	New	N_SF_Ceiling	2.29	1.27	1.80	0	0	0
Residential	Wall Insulation	Single Family	Existing	E_SF_Wall In	1.35	1.27	1.06	20	8	19
Residential	Spray Foam Insulation(Base R2)	Single Family	Existing	E_SF_Spray I	1.53	1.27	1.20	0	0	0
Residential	Home Energy Management System	Single Family	Existing	E_SF_Home I	1.83	1.13	1.62	3	1	4
Residential	Energy Star Windows	Single Family	Existing	E_SF_Energy	3.62	1.27	2.84	55	24	111
Residential	Duct Repair	Single Family	Existing	E_SF_Duct R	3.64	1.13	3.22	58	25	92
Residential	Ceiling Insulation(R2 to R38)	Single Family	Existing	E_SF_Ceiling	7.31	1.27	5.73	186	81	282
Residential	Ceiling Insulation(R19 to R38)	Single Family	Existing	E_SF_Ceiling	1.35	1.27	1.06	11	4	16
Residential	Ceiling Insulation(R12 to R38)	Single Family	Existing	E_SF_Ceiling	2.29	1.27	1.80	54	21	80
Residential	Air Sealing-Infiltration Control	Single Family	Existing	E_SF_Air Sea	1.30	1.13	1.15	58	22	89
Residential	High Efficiency Induction Cooktop	Single Family	Turnover	T_SF_High E	1.99	0.82	2.42	8	1	20
Residential	High Efficiency Induction Cooktop	Single Family	New	N_SF_High E	1.99	0.82	2.42	0	0	0
Residential	Variable Speed Pool Pump	Single Family	Turnover	T_SF_Variabl	1.40	0.47	2.99	0	0	0
Residential	Two Speed Pool Pump	Single Family	Turnover	T_SF_Two Sp	1.40	0.47	2.99	9	10	62
Residential	Variable Speed Pool Pump	Single Family	New	N_SF_Variab	1.40	0.47	2.99	0	0	0
Residential	Two Speed Pool Pump	Single Family	New	N_SF_Two S	1.40	0.47	2.99	0	0	1
Residential	LED Specialty Lamps-5W Chandelier	Single Family	Turnover	T_SF_LED S	1.43	0.37	3.86	1	1	8
Residential	LED Specialty Lamps-5W Chandelier	Single Family	New	N_SF_LED S	1.43	0.37	3.86	0	0	0
Residential	LED - 9W Flood	Single Family	Turnover	T_SF_LED -	1.34	0.37	3.63	19	20	215
Residential	CFL-13W	Single Family	Turnover	T_SF_CFL-1	1.17	0.35	3.37	7	7	81
Residential	LED - 9W Flood	Single Family	New	N_SF_LED -	1.34	0.37	3.63	0	0	4
Residential	CFL-13W	Single Family	New	N_SF_CFL-1	1.17	0.35	3.37	0	0	1
Residential	15 SEER Air Source Heat Pump	Single Family	Turnover	T_SF_15 SEE	1.50	1.22	1.23	63	90	143
Residential	14 SEER ASHP from base electric resistance heating	Single Family	Turnover	T_SF_14 SEE	3.50	1.19	2.94	0	100	154
Residential	15 SEER Air Source Heat Pump	Single Family	New	N_SF_15 SEE	1.50	1.22	1.23	1	2	3
Residential	14 SEER ASHP from base electric resistance heating	Single Family	New	N_SF_14 SEE	3.50	1.19	2.94	0	2	3
Residential	16 SEER Central AC	Single Family	Turnover	T_SF_16 SEE	1.53	1.10	1.39	0	0	0
Residential	15 SEER Central AC	Single Family	Turnover	T_SF_15 SEE	1.60	1.10	1.45	20	0	40
Residential	16 SEER Central AC	Single Family	New	N_SF_16 SEE	1.53	1.10	1.39	0	0	0
Residential	15 SEER Central AC	Single Family	New	N_SF_15 SEE	1.60	1.10	1.45	0	0	1
Residential	Thermostatic Shower Restriction Valve	Multi-Family	New	N_MF_Therm	1.25	0.50	2.49	0	0	0
Residential	Thermostatic Shower Restriction Valve	Multi-Family	Existing	E_MF_Therm	1.25	0.50	2.49	1	1	7
Residential	Home Energy Management System	Multi-Family	New	N_MF_Home	1.32	1.13	1.16	0	0	0
Residential	Ceiling Insulation(R2 to R38)	Multi-Family	New	N_MF_Ceilin	5.30	1.27	4.16	0	0	0
Residential	Ceiling Insulation(R12 to R38)	Multi-Family	New	N_MF_Ceilin	1.71	1.27	1.34	0	0	0
Residential	Home Energy Management System	Multi-Family	Existing	E_MF_Home	1.32	1.13	1.16	3	1	2
Residential	Energy Star Windows	Multi-Family	Existing	E_MF_Energ	3.62	1.27	2.84	28	5	55
Residential	Duct Repair	Multi-Family	Existing	E_MF_Duct I	2.37	1.13	2.09	84	14	93
Residential	Ceiling Insulation(R2 to R38)	Multi-Family	Existing	E_MF_Ceilin	5.30	1.27	4.16	54	22	83
Residential	Ceiling Insulation(R12 to R38)	Multi-Family	Existing	E_MF_Ceilin	1.71	1.27	1.34	15	7	24
Residential	Air Sealing-Infiltration Control	Multi-Family	Existing	E_MF_Air Se	1.42	1.13	1.26	45	8	50
Residential	High Efficiency Induction Cooktop	Multi-Family	Turnover	T_MF_High I	1.99	0.82	2.42	3	0	6
Residential	High Efficiency Induction Cooktop	Multi-Family	New	N_MF_High I	1.99	0.82	2.42	0	0	0
Residential	Variable Speed Pool Pump	Multi-Family	Turnover	T_MF_Variab	1.40	0.47	2.99	0	0	0
Residential	Two Speed Pool Pump	Multi-Family	Turnover	T_MF_Two S	1.40	0.47	2.99	0	0	0
Residential	Variable Speed Pool Pump	Multi-Family	New	N_MF_Variab	1.40	0.47	2.99	0	0	0
Residential	Two Speed Pool Pump	Multi-Family	New	N_MF_Two S	1.40	0.47	2.99	0	0	0
Residential	LED Specialty Lamps-5W Chandelier	Multi-Family	Turnover	T_MF_LED S	1.43	0.37	3.86	0	0	4
Residential	LED Specialty Lamps-5W Chandelier	Multi-Family	New	N_MF_LED S	1.43	0.37	3.86	0	0	0
Residential	LED - 9W Flood	Multi-Family	Turnover	T_MF_LED -	1.34	0.37	3.63	9	9	98
Residential	CFL-13W	Multi-Family	Turnover	T_MF_CFL-1	1.17	0.35	3.37	3	3	37
Residential	LED - 9W Flood	Multi-Family	New	N_MF_LED -	1.34	0.37	3.63	0	0	2
Residential	CFL-13W	Multi-Family	New	N_MF_CFL-1	1.17	0.35	3.37	0	0	1
Residential	14 SEER ASHP from base electric resistance heating	Multi-Family	Turnover	T_MF_14 SE	3.20	1.19	2.69	0	8	12
Residential	14 SEER ASHP from base electric resistance heating	Multi-Family	New	N_MF_14 SE	3.20	1.19	2.69	0	0	0
Residential	Thermostatic Shower Restriction Valve	Manufactured Home	New	N_MH_Therm	1.24	0.50	2.47	0	0	0
Residential	Thermostatic Shower Restriction Valve	Manufactured Home	Existing	E_MH_Therm	1.24	0.50	2.47	0	0	1
Residential	Home Energy Management System	Manufactured Home	New	N_MH_Home	2.03	1.13	1.79	0	0	0
Residential	Ceiling Insulation(R2 to R38)	Manufactured Home	New	N_MH_Ceilin	5.17	1.27	4.06	0	0	0
Residential	Ceiling Insulation(R12 to R38)	Manufactured Home	New	N_MH_Ceilin	1.61	1.27	1.26	0	0	0
Residential	Wall Insulation	Manufactured Home	Existing	E_MH_Wall I	1.56	1.27	1.22	4	2	4
Residential	Home Energy Management System	Manufactured Home	Existing	E_MH_Home	2.03	1.13	1.79	5	1	4
Residential	Energy Star Windows	Manufactured Home	Existing	E_MH_Energ	3.62	1.27	2.84	13	2	26
Residential	Duct Repair	Manufactured Home	Existing	E_MH_Duct	3.56	1.13	3.15	59	11	62
Residential	Ceiling Insulation(R2 to R38)	Manufactured Home	Existing	E_MH_Ceilin	5.17	1.27	4.06	25	16	41
Residential	Ceiling Insulation(R12 to R38)	Manufactured Home	Existing	E_MH_Ceilin	1.61	1.27	1.26	6	5	11
Residential	Air Sealing-Infiltration Control	Manufactured Home	Existing	E_MH_Air Se	2.03	1.13	1.79	33	6	34
Residential	High Efficiency Induction Cooktop	Manufactured Home	Turnover	T_MH_High I	1.99	0.82	2.42	1	0	2
Residential	High Efficiency Induction Cooktop	Manufactured Home	New	N_MH_High	1.99	0.82	2.42	0	0	0
Residential	Variable Speed Pool Pump	Manufactured Home	Turnover	T_MH_Variab	1.40	0.47	2.99	0	0	0
Residential	Two Speed Pool Pump	Manufactured Home	Turnover	T_MH_Two S	1.40	0.47	2.99	0	0	0
Residential	Variable Speed Pool Pump	Manufactured Home	New	N_MH_Varia	1.40	0.47	2.99	0	0	0
Residential	Two Speed Pool Pump	Manufactured Home	New	N_MH_Two S	1.40	0.47	2.99	0	0	0
Residential	LED Specialty Lamps-5W Chandelier	Manufactured Home	Turnover	T_MH_LED S	1.43	0.37	3.86	0	0	1
Residential	LED Specialty Lamps-5W Chandelier	Manufactured Home	New	N_MH_LED	1.43	0.37	3.86	0	0	0
Residential	LED - 9W Flood	Manufactured Home	Turnover	T_MH_LED -	1.34	0.37	3.63	2	3	28
Residential	CFL-13W	Manufactured Home	Turnover	T_MH_CFL-1	1.17	0.35	3.37	1	1	11
Residential	LED - 9W Flood	Manufactured Home	New	N_MH_LED	1.34	0.37	3.63	0	0	0
Residential	CFL-13W	Manufactured Home	New	N_MH_CFL-	1.17	0.35	3.37	0	0	0
Residential	14 SEER ASHP from base electric resistance heating	Manufactured Home	Turnover	T_MH_14 SE	2.17	1.19	1.82	0	4	6
Residential	14 SEER ASHP from base electric resistance heating	Manufactured Home	New	N_MH_14 SE	2.17	1.19	1.82	0	0	0
Commercial	Retro-Commissioning	Assembly	New	N_AS_Retro-	1.32	0.93	1.42	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Assembly	New	N_AS_PSC to	1.19	0.58	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Assembly	New	N_AS_PSC to	1.84	0.58	3.15	0	0	0
Commercial	Retro-Commissioning	Assembly	Existing	E_AS_Retro-	1.32	0.93	1.42	2	2	12
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Assembly	Existing	E_AS_PSC to	1.19	0.58	2.05	0	0	0

Economic Potential - TRM

Falling Measures Results

[Economic Potential or Achievable Potential] – [TRC or RIM]

Customer Class	Measure Name	Segment	Vintage	*Measure Name	TRC	RIM	PCT	Summer (MW)	Winter (MW)	Energy (GWh)	Reason For Failure
Residential	Energy Star Clothes Dryer	Single Family	Turnover	T_SF_Energy	0.31	0.47	0.65	0	0	0	Fail TRC
Residential	Energy Star Clothes Dryer	Multi-Family	Turnover	T_MF_Energ	0.31	0.47	0.65	0	0	0	Fail TRC
Residential	Energy Star Clothes Dryer	Manufactured Home	Turnover	T_MH_Energ	0.31	0.47	0.65	0	0	0	Fail TRC
Residential	Energy Star Clothes Dryer	Single Family	New	N_SF_Energy	0.31	0.47	0.65	0	0	0	Fail TRC
Residential	Energy Star Clothes Dryer	Multi-Family	New	N_MF_Energ	0.31	0.47	0.65	0	0	0	Fail TRC
Residential	Energy Star Clothes Dryer	Manufactured Home	New	N_MH_Energ	0.31	0.47	0.65	0	0	0	Fail TRC
Residential	Energy Star Clothes Washer	Single Family	Turnover	T_SF_Energy	7.20	0.69	10.41	0	0	0	Fail 2-year Threshold
Residential	Energy Star Clothes Washer	Multi-Family	Turnover	T_MF_Energ	7.20	0.69	10.41	0	0	0	Fail 2-year Threshold
Residential	Energy Star Clothes Washer	Manufactured Home	Turnover	T_MH_Energ	7.20	0.69	10.41	0	0	0	Fail 2-year Threshold
Residential	Energy Star Clothes Washer	Single Family	New	N_SF_Energy	7.20	0.69	10.41	0	0	0	Fail 2-year Threshold
Residential	Energy Star Clothes Washer	Multi-Family	New	N_MF_Energ	7.20	0.69	10.41	0	0	0	Fail 2-year Threshold
Residential	Energy Star Clothes Washer	Manufactured Home	New	N_MH_Energ	7.20	0.69	10.41	0	0	0	Fail 2-year Threshold
Residential	Energy Star Dishwasher	Single Family	Turnover	T_SF_Energy	0.00	0.40	0.00	0	0	0	Fail TRC
Residential	Energy Star Dishwasher	Multi-Family	Turnover	T_MF_Energ	0.00	0.40	0.00	0	0	0	Fail TRC
Residential	Energy Star Dishwasher	Manufactured Home	Turnover	T_MH_Energ	0.00	0.40	0.00	0	0	0	Fail TRC
Residential	Energy Star Dishwasher	Single Family	New	N_SF_Energy	0.00	0.40	0.00	0	0	0	Fail TRC
Residential	Energy Star Dishwasher	Multi-Family	New	N_MF_Energ	0.00	0.40	0.00	0	0	0	Fail TRC
Residential	Energy Star Dishwasher	Manufactured Home	New	N_MH_Energ	0.00	0.40	0.00	0	0	0	Fail TRC
Residential	Energy Star Freezer	Single Family	Turnover	T_SF_Energy	0.34	0.42	0.81	0	0	0	Fail TRC
Residential	Energy Star Freezer	Multi-Family	Turnover	T_MF_Energ	0.34	0.42	0.81	0	0	0	Fail TRC
Residential	Energy Star Freezer	Manufactured Home	Turnover	T_MH_Energ	0.34	0.42	0.81	0	0	0	Fail TRC
Residential	Energy Star Freezer	Single Family	New	N_SF_Energy	0.34	0.42	0.81	0	0	0	Fail TRC
Residential	Energy Star Freezer	Multi-Family	New	N_MF_Energ	0.34	0.42	0.81	0	0	0	Fail TRC
Residential	Energy Star Freezer	Manufactured Home	New	N_MH_Energ	0.34	0.42	0.81	0	0	0	Fail TRC
Residential	Energy Star Refrigerator	Single Family	Turnover	T_SF_Energy	0.66	0.44	1.50	0	0	0	Fail TRC
Residential	Energy Star Refrigerator	Multi-Family	Turnover	T_MF_Energ	0.66	0.44	1.50	0	0	0	Fail TRC
Residential	Energy Star Refrigerator	Manufactured Home	Turnover	T_MH_Energ	0.66	0.44	1.50	0	0	0	Fail TRC
Residential	Energy Star Refrigerator	Single Family	New	N_SF_Energy	0.66	0.44	1.50	0	0	0	Fail TRC
Residential	Energy Star Refrigerator	Multi-Family	New	N_MF_Energ	0.66	0.44	1.50	0	0	0	Fail TRC
Residential	Energy Star Refrigerator	Manufactured Home	New	N_MH_Energ	0.66	0.44	1.50	0	0	0	Fail TRC
Residential	Heat Pump Clothes Dryer	Single Family	Turnover	T_SF_Heat P	0.15	0.48	0.31	0	0	0	Fail TRC
Residential	Heat Pump Clothes Dryer	Multi-Family	Turnover	T_MF_Heat P	0.15	0.48	0.31	0	0	0	Fail TRC
Residential	Heat Pump Clothes Dryer	Manufactured Home	Turnover	T_MH_Heat P	0.15	0.48	0.31	0	0	0	Fail TRC
Residential	Heat Pump Clothes Dryer	Single Family	New	N_SF_Heat P	0.15	0.48	0.31	0	0	0	Fail TRC
Residential	Heat Pump Clothes Dryer	Multi-Family	New	N_MF_Heat P	0.15	0.48	0.31	0	0	0	Fail TRC
Residential	Heat Pump Clothes Dryer	Manufactured Home	New	N_MH_Heat	0.15	0.48	0.31	0	0	0	Fail TRC
Residential	High Efficiency Convection Oven	Single Family	Turnover	T_SF_High E	0.14	0.89	0.16	0	0	0	Fail TRC
Residential	High Efficiency Convection Oven	Multi-Family	Turnover	T_MF_High E	0.14	0.89	0.16	0	0	0	Fail TRC
Residential	High Efficiency Convection Oven	Manufactured Home	Turnover	T_MH_High E	0.14	0.89	0.16	0	0	0	Fail TRC
Residential	High Efficiency Convection Oven	Single Family	New	N_SF_High E	0.14	0.89	0.16	0	0	0	Fail TRC
Residential	High Efficiency Convection Oven	Multi-Family	New	N_MF_High E	0.14	0.89	0.16	0	0	0	Fail TRC
Residential	High Efficiency Convection Oven	Manufactured Home	New	N_MH_High	0.14	0.89	0.16	0	0	0	Fail TRC
Residential	Heat Pump Water Heater	Single Family	Turnover	T_SF_Heat P	0.96	0.61	1.59	0	0	0	Fail TRC
Residential	Heat Pump Water Heater	Multi-Family	Turnover	T_MF_Heat P	0.76	0.61	1.25	0	0	0	Fail TRC
Residential	Heat Pump Water Heater	Manufactured Home	Turnover	T_MH_Heat P	0.75	0.61	1.24	0	0	0	Fail TRC
Residential	Heat Pump Water Heater	Single Family	New	N_SF_Heat P	0.96	0.61	1.59	0	0	0	Fail TRC
Residential	Heat Pump Water Heater	Multi-Family	New	N_MF_Heat P	0.76	0.61	1.25	0	0	0	Fail TRC
Residential	Heat Pump Water Heater	Manufactured Home	New	N_MH_Heat	0.75	0.61	1.24	0	0	0	Fail TRC
Residential	Instantaneous Hot Water System	Single Family	Turnover	T_SF_Instant	0.08	0.70	0.11	0	0	0	Fail TRC
Residential	Instantaneous Hot Water System	Multi-Family	Turnover	T_MF_Instan	0.06	0.70	0.09	0	0	0	Fail TRC
Residential	Instantaneous Hot Water System	Manufactured Home	Turnover	T_MH_Instan	0.06	0.70	0.09	0	0	0	Fail TRC
Residential	Instantaneous Hot Water System	Single Family	New	N_SF_Instant	0.08	0.70	0.11	0	0	0	Fail TRC
Residential	Instantaneous Hot Water System	Multi-Family	New	N_MF_Instan	0.06	0.70	0.09	0	0	0	Fail TRC
Residential	Instantaneous Hot Water System	Manufactured Home	New	N_MH_Instan	0.06	0.70	0.09	0	0	0	Fail TRC
Residential	Solar Water Heater	Single Family	Turnover	T_SF_Solar V	0.16	0.38	0.41	0	0	0	Fail TRC
Residential	Solar Water Heater	Multi-Family	Turnover	T_MF_Solar	0.12	0.38	0.32	0	0	0	Fail TRC
Residential	Solar Water Heater	Manufactured Home	Turnover	T_MH_Solar	0.12	0.38	0.32	0	0	0	Fail TRC
Residential	Solar Water Heater	Single Family	New	N_SF_Solar V	0.16	0.38	0.41	0	0	0	Fail TRC
Residential	Solar Water Heater	Multi-Family	New	N_MF_Solar	0.12	0.38	0.32	0	0	0	Fail TRC
Residential	Solar Water Heater	Manufactured Home	New	N_MH_Solar	0.12	0.38	0.32	0	0	0	Fail TRC
Residential	Energy Star Air Purifier	Single Family	Turnover	T_SF_Energy	0.00	0.42	0.00	0	0	0	Fail TRC
Residential	Energy Star Air Purifier	Multi-Family	Turnover	T_MF_Energ	0.00	0.42	0.00	0	0	0	Fail TRC
Residential	Energy Star Air Purifier	Manufactured Home	Turnover	T_MH_Energ	0.00	0.42	0.00	0	0	0	Fail TRC
Residential	Energy Star Air Purifier	Single Family	New	N_SF_Energy	0.00	0.42	0.00	0	0	0	Fail TRC
Residential	Energy Star Air Purifier	Multi-Family	New	N_MF_Energ	0.00	0.42	0.00	0	0	0	Fail TRC
Residential	Energy Star Air Purifier	Manufactured Home	New	N_MH_Energ	0.00	0.42	0.00	0	0	0	Fail TRC
Residential	Energy Star Audio-Video Equipment	Single Family	Turnover	T_SF_Energy	0.08	0.23	0.33	0	0	0	Fail TRC
Residential	Energy Star Audio-Video Equipment	Multi-Family	Turnover	T_MF_Energ	0.08	0.23	0.33	0	0	0	Fail TRC
Residential	Energy Star Audio-Video Equipment	Manufactured Home	Turnover	T_MH_Energ	0.08	0.23	0.33	0	0	0	Fail TRC
Residential	Energy Star Audio-Video Equipment	Single Family	New	N_SF_Energy	0.08	0.23	0.33	0	0	0	Fail TRC
Residential	Energy Star Audio-Video Equipment	Multi-Family	New	N_MF_Energ	0.08	0.23	0.33	0	0	0	Fail TRC
Residential	Energy Star Audio-Video Equipment	Manufactured Home	New	N_MH_Energ	0.08	0.23	0.33	0	0	0	Fail TRC
Residential	Energy Star Imaging Equipment	Single Family	Turnover	T_SF_Energy	0.00	0.33	0.00	0	0	0	Fail TRC
Residential	Energy Star Imaging Equipment	Multi-Family	Turnover	T_MF_Energ	0.00	0.33	0.00	0	0	0	Fail TRC
Residential	Energy Star Imaging Equipment	Manufactured Home	Turnover	T_MH_Energ	0.00	0.33	0.00	0	0	0	Fail TRC
Residential	Energy Star Imaging Equipment	Single Family	New	N_SF_Energy	0.00	0.33	0.00	0	0	0	Fail TRC
Residential	Energy Star Imaging Equipment	Multi-Family	New	N_MF_Energ	0.00	0.33	0.00	0	0	0	Fail TRC
Residential	Energy Star Imaging Equipment	Manufactured Home	New	N_MH_Energ	0.00	0.33	0.00	0	0	0	Fail TRC
Residential	Energy Star Personal Computer	Single Family	Turnover	T_SF_Energy	0.73	0.40	1.80	0	0	0	Fail TRC
Residential	Energy Star Personal Computer	Multi-Family	Turnover	T_MF_Energ	0.73	0.40	1.80	0	0	0	Fail TRC
Residential	Energy Star Personal Computer	Manufactured Home	Turnover	T_MH_Energ	0.73	0.40	1.80	0	0	0	Fail TRC
Residential	Energy Star Personal Computer	Single Family	New	N_SF_Energy	0.73	0.40	1.80	0	0	0	Fail TRC
Residential	Energy Star Personal Computer	Multi-Family	New	N_MF_Energ	0.73	0.40	1.80	0	0	0	Fail TRC
Residential	Energy Star Personal Computer	Manufactured Home	New	N_MH_Energ	0.73	0.40	1.80	0	0	0	Fail TRC
Residential	Energy Star TV	Single Family	Turnover	T_SF_Energy	0.12	0.45	0.27	0	0	0	Fail TRC
Residential	Energy Star TV	Multi-Family	Turnover	T_MF_Energ	0.12	0.45	0.27	0	0	0	Fail TRC
Residential	Energy Star TV	Manufactured Home	Turnover	T_MH_Energ	0.12	0.45	0.27	0	0	0	Fail TRC
Residential	Energy Star TV	Single Family	New	N_SF_Energy	0.12	0.45	0.27	0	0	0	Fail TRC
Residential	Energy Star TV	Multi-Family	New	N_MF_Energ	0.12	0.45	0.27	0	0	0	Fail TRC
Residential	Energy Star TV	Manufactured Home	New	N_MH_Energ	0.12	0.45	0.27	0	0	0	Fail TRC
Residential	15 SEER Air Source Heat Pump	Multi-Family	Turnover	T_MF_15 SE	0.97	1.22	0.79	0	0	0	Fail TRC
Residential	15 SEER Air Source Heat Pump	Manufactured Home	Turnover	T_MH_15 SE	0.93	1.22	0.76	0	0	0	Fail TRC

Commercial	High Efficiency PTAC	Institutional	Turnover	T_IN_High E	4.76	1.35	3.52	0	0	0
Commercial	High Efficiency PTAC	Miscellaneous	Turnover	T_MS_High E	4.28	1.18	3.64	0	0	0
Commercial	High Efficiency PTAC	Warehouse	Turnover	T_WR_High E	2.14	1.35	1.58	0	0	0
Commercial	High Efficiency PTAC	Grocery	New	N_GR_High E	4.86	1.35	3.60	0	0	0
Commercial	High Efficiency PTAC	Institutional	New	N_IN_High E	4.76	1.35	3.52	0	0	0
Commercial	High Efficiency PTAC	Miscellaneous	New	N_MS_High E	4.28	1.18	3.64	0	0	0
Commercial	High Efficiency PTAC	Warehouse	New	N_WR_High	2.14	1.35	1.58	0	0	0
Commercial	High Efficiency PTHP	Grocery	Turnover	T_GR_High E	5.01	1.33	3.76	0	0	0
Commercial	High Efficiency PTHP	Institutional	Turnover	T_IN_High E	4.80	1.33	3.60	0	0	0
Commercial	High Efficiency PTHP	Miscellaneous	Turnover	T_MS_High E	4.92	1.33	3.69	0	0	0
Commercial	High Efficiency PTHP	Warehouse	Turnover	T_WR_High E	2.17	1.33	1.63	0	0	0
Commercial	High Efficiency PTHP	Grocery	New	N_GR_High E	5.01	1.33	3.76	0	0	0
Commercial	High Efficiency PTHP	Institutional	New	N_IN_High E	4.80	1.33	3.60	0	0	0
Commercial	High Efficiency PTHP	Miscellaneous	New	N_MS_High E	4.92	1.33	3.69	0	0	0
Commercial	High Efficiency PTHP	Warehouse	New	N_WR_High	2.17	1.33	1.63	0	0	0
Commercial	Efficient Battery Charger	Assembly	Turnover	T_AS_Efficie	1.63	1.02	1.59	1	0	1
Commercial	Efficient Battery Charger	College and University	Turnover	T_CU_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Grocery	Turnover	T_GR_Efficie	1.63	1.02	1.59	1	0	2
Commercial	Efficient Battery Charger	Healthcare	Turnover	T_HC_Efficie	1.63	1.02	1.59	1	0	2
Commercial	Efficient Battery Charger	Hospitals	Turnover	T_HS_Efficie	1.63	1.02	1.59	1	0	2
Commercial	Efficient Battery Charger	Institutional	Turnover	T_IN_Efficien	1.63	1.02	1.59	1	0	2
Commercial	Efficient Battery Charger	Lodging/Hospitality	Turnover	T_LG_Efficie	1.63	1.02	1.59	2	0	4
Commercial	Efficient Battery Charger	Miscellaneous	Turnover	T_MS_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Offices	Turnover	T_OF_Efficie	1.63	1.02	1.59	6	0	10
Commercial	Efficient Battery Charger	Restaurants	Turnover	T_RS_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Retail	Turnover	T_RT_Efficie	1.63	1.02	1.59	3	0	6
Commercial	Efficient Battery Charger	Schools K-12	Turnover	T_SC_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Warehouse	Turnover	T_WR_Effici	1.63	1.02	1.59	1	0	2
Commercial	Efficient Battery Charger	Assembly	New	N_AS_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	College and University	New	N_CU_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Grocery	New	N_GR_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Healthcare	New	N_HC_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Hospitals	New	N_HS_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Institutional	New	N_IN_Efficien	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Lodging/Hospitality	New	N_LG_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Miscellaneous	New	N_MS_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Offices	New	N_OF_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Restaurants	New	N_RS_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Retail	New	N_RT_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Schools K-12	New	N_SC_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Warehouse	New	N_WR_Effici	1.63	1.02	1.59	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Assembly	Existing	E_AS_Ceiling	4.67	1.22	3.83	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	College and University	Existing	E_CU_Ceiling	4.64	1.21	3.83	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Grocery	Existing	E_GR_Ceiling	4.79	1.25	3.83	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Healthcare	Existing	E_HC_Ceiling	4.67	1.22	3.83	0	0	10
Commercial	Ceiling Insulation(R2 to R38)	Hospitals	Existing	E_HS_Ceiling	4.64	1.21	3.83	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Institutional	Existing	E_IN_Ceiling	4.67	1.22	3.83	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Lodging/Hospitality	Existing	E_LG_Ceiling	4.64	1.21	3.83	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Miscellaneous	Existing	E_MS_Ceilin	4.67	1.22	3.83	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Offices	Existing	E_OF_Ceiling	4.67	1.22	3.83	0	0	7
Commercial	Ceiling Insulation(R2 to R38)	Restaurants	Existing	E_RS_Ceiling	4.79	1.25	3.83	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Retail	Existing	E_RT_Ceiling	4.79	1.25	3.83	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Schools K-12	Existing	E_SC_Ceiling	4.67	1.22	3.83	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Assembly	New	N_AS_Ceiling	4.58	1.22	3.76	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	College and University	New	N_CU_Ceilin	4.55	1.21	3.76	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Grocery	New	N_GR_Ceilin	4.70	1.25	3.76	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Healthcare	New	N_HC_Ceilin	4.58	1.22	3.76	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Hospitals	New	N_HS_Ceiling	4.55	1.21	3.76	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Institutional	New	N_IN_Ceiling	4.58	1.22	3.76	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Lodging/Hospitality	New	N_LG_Ceiling	4.55	1.21	3.76	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Miscellaneous	New	N_MS_Ceilin	4.58	1.22	3.76	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Offices	New	N_OF_Ceiling	4.58	1.22	3.76	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Restaurants	New	N_RS_Ceiling	4.70	1.25	3.76	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Retail	New	N_RT_Ceiling	4.70	1.25	3.76	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Schools K-12	New	N_SC_Ceiling	4.58	1.22	3.76	0	0	0
Commercial	Duct Sealing Repair	Assembly	Existing	E_AS_Duct S	4.94	1.64	3.01	0	0	0
Commercial	Duct Sealing Repair	College and University	Existing	E_CU_Duct S	7.49	1.64	4.57	0	0	0
Commercial	Duct Sealing Repair	Retail	Existing	E_RT_Duct S	9.12	1.64	5.56	4	0	20
Commercial	Duct Sealing Repair	Schools K-12	Existing	E_SC_Duct S	7.49	1.64	4.57	0	0	0
Commercial	Duct Sealing Repair	Warehouse	Existing	E_WR_Duct S	2.41	1.64	1.47	0	0	0
Commercial	Duct Sealing Repair	Assembly	New	N_AS_Duct S	4.94	1.64	3.01	0	0	0
Commercial	Duct Sealing Repair	College and University	New	N_CU_Duct S	7.49	1.64	4.57	0	0	0
Commercial	Duct Sealing Repair	Retail	New	N_RT_Duct S	9.12	1.64	5.56	0	0	0
Commercial	Duct Sealing Repair	Schools K-12	New	N_SC_Duct S	7.49	1.64	4.57	0	0	0
Commercial	Duct Sealing Repair	Warehouse	New	N_WR_Duct	2.41	1.64	1.47	0	0	0
Commercial	Low U-Value Windows	Assembly	Existing	E_AS_Low U	1.46	1.12	1.31	2	0	6
Commercial	Low U-Value Windows	College and University	Existing	E_CU_Low U	1.46	1.12	1.31	0	0	0
Commercial	Low U-Value Windows	Grocery	Existing	E_GR_Low U	1.46	1.12	1.31	2	0	5
Commercial	Low U-Value Windows	Healthcare	Existing	E_HC_Low U	1.46	1.12	1.31	2	0	7
Commercial	Low U-Value Windows	Hospitals	Existing	E_HS_Low U	1.46	1.12	1.31	2	0	7
Commercial	Low U-Value Windows	Institutional	Existing	E_IN_Low U-	1.46	1.12	1.31	1	0	3
Commercial	Low U-Value Windows	Lodging/Hospitality	Existing	E_LG_Low U	1.66	1.27	1.31	6	0	13
Commercial	Low U-Value Windows	Miscellaneous	Existing	E_MS_Low U	1.38	1.06	1.31	5	0	14
Commercial	Low U-Value Windows	Offices	Existing	E_OF_Low U	1.46	1.12	1.31	4	0	12
Commercial	Low U-Value Windows	Restaurants	Existing	E_RS_Low U	1.46	1.12	1.31	6	0	17
Commercial	Low U-Value Windows	Retail	Existing	E_RT_Low U	1.46	1.12	1.31	4	0	12
Commercial	Low U-Value Windows	Schools K-12	Existing	E_SC_Low U	1.46	1.12	1.31	1	0	2
Commercial	Low U-Value Windows	Warehouse	Existing	E_WR_Low U	1.38	1.06	1.31	0	0	1
Commercial	Programmable Thermostat	Lodging/Hospitality	Existing	E_LG_Progra	6.93	5.54	1.25	0	0	0
Commercial	Programmable Thermostat	Lodging/Hospitality	New	N_LG_Progra	6.93	5.54	1.25	0	0	0
Commercial	Smart Thermostat	Lodging/Hospitality	Existing	E_LG_Smart	12.30	5.54	2.22	0	2	13
Commercial	Smart Thermostat	Lodging/Hospitality	New	N_LG_Smart	12.30	5.54	2.22	0	0	0
Commercial	Thermal Energy Storage	Assembly	Existing	E_AS_Therm	2.46	9999.00	9999.00	4	1	-1
Commercial	Thermal Energy Storage	College and University	Existing	E_CU_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Grocery	Existing	E_GR_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Healthcare	Existing	E_HC_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Hospitals	Existing	E_HS_Therm	2.46	9999.00	9999.00	13	4	-2
Commercial	Thermal Energy Storage	Institutional	Existing	E_IN_Therma	2.46	9999.00	9999.00	2	0	0
Commercial	Thermal Energy Storage	Lodging/Hospitality	Existing	E_LG_Therm	2.46	9999.00	9999.00	1	0	0
Commercial	Thermal Energy Storage	Miscellaneous	Existing	E_MS_Therm	2.46	9999.00	9999.00	3	1	0
Commercial	Thermal Energy Storage	Offices	Existing	E_OF_Therm	2.46	9999.00	9999.00	5	1	-1
Commercial	Thermal Energy Storage	Restaurants	Existing	E_RS_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Retail	Existing	E_RT_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Schools K-12	Existing	E_SC_Therm	2.46	9999.00	9999.00	1	0	0
Commercial	Thermal Energy Storage	Warehouse	Existing	E_WR_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Assembly	New	N_AS_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	College and University	New	N_CU_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Grocery	New	N_GR_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Healthcare	New	N_HC_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Hospitals	New	N_HS_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Institutional	New	N_IN_Therma	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Lodging/Hospitality	New	N_LG_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Miscellaneous	New	N_MS_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Offices	New	N_OF_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Restaurants	New	N_RS_Therm	2.46	9999.00	9999.00	0	0	0

Residential	Energy Star TV	Manufactured Home	Turnover	T_MH_Energ	0.12	0.45	0.27	0	0	0	Fail RIM
Residential	Energy Star TV	Single Family	New	N_SF_Energy	0.12	0.45	0.27	0	0	0	Fail RIM
Residential	Energy Star TV	Multi-Family	New	N_MF_Energ	0.12	0.45	0.27	0	0	0	Fail RIM
Residential	Energy Star TV	Manufactured Home	New	N_MH_Energ	0.12	0.45	0.27	0	0	0	Fail RIM
Residential	15 SEER Air Source Heat Pump	Multi-Family	Turnover	T_MF_15 SE	0.97	1.22	0.79	0	0	0	Fail PCT
Residential	15 SEER Air Source Heat Pump	Manufactured Home	Turnover	T_MH_15 SE	0.93	1.22	0.76	0	0	0	Fail PCT
Residential	15 SEER Air Source Heat Pump	Multi-Family	New	N_MF_15 SE	0.97	1.22	0.79	0	0	0	Fail PCT
Residential	15 SEER Air Source Heat Pump	Manufactured Home	New	N_MH_15 SE	0.93	1.22	0.76	0	0	0	Fail PCT
Residential	15 SEER Central AC	Multi-Family	Turnover	T_MF_15 SE	1.09	1.10	0.99	0	0	0	Fail PCT
Residential	15 SEER Central AC	Manufactured Home	Turnover	T_MH_15 SE	0.99	1.10	0.90	0	0	0	Fail PCT
Residential	15 SEER Central AC	Multi-Family	New	N_MF_15 SE	1.09	1.10	0.99	0	0	0	Fail PCT
Residential	15 SEER Central AC	Manufactured Home	New	N_MH_15 SE	0.99	1.10	0.90	0	0	0	Fail PCT
Residential	16 SEER Air Source Heat Pump	Single Family	Turnover	T_SF_16 SE	0.99	1.22	0.81	0	0	0	Fail PCT
Residential	16 SEER Air Source Heat Pump	Multi-Family	Turnover	T_MF_16 SE	0.73	1.22	0.59	0	0	0	Fail PCT
Residential	16 SEER Air Source Heat Pump	Manufactured Home	Turnover	T_MH_16 SE	0.61	1.22	0.50	0	0	0	Fail PCT
Residential	16 SEER Air Source Heat Pump	Single Family	New	N_SF_16 SE	0.99	1.22	0.81	0	0	0	Fail PCT
Residential	16 SEER Air Source Heat Pump	Multi-Family	New	N_MF_16 SE	0.73	1.22	0.59	0	0	0	Fail PCT
Residential	16 SEER Air Source Heat Pump	Manufactured Home	New	N_MH_16 SE	0.61	1.22	0.50	0	0	0	Fail PCT
Residential	16 SEER Central AC	Multi-Family	Turnover	T_MF_16 SE	1.04	1.10	0.95	0	0	0	Fail PCT
Residential	16 SEER Central AC	Manufactured Home	Turnover	T_MH_16 SE	0.95	1.10	0.86	0	0	0	Fail PCT
Residential	16 SEER Central AC	Multi-Family	New	N_MF_16 SE	1.04	1.10	0.95	0	0	0	Fail PCT
Residential	16 SEER Central AC	Manufactured Home	New	N_MH_16 SE	0.95	1.10	0.86	0	0	0	Fail PCT
Residential	17 SEER Air Source Heat Pump	Single Family	Turnover	T_SF_17 SE	0.86	1.22	0.71	0	0	0	Fail PCT
Residential	17 SEER Air Source Heat Pump	Multi-Family	Turnover	T_MF_17 SE	0.65	1.22	0.53	0	0	0	Fail PCT
Residential	17 SEER Air Source Heat Pump	Manufactured Home	Turnover	T_MH_17 SE	0.54	1.22	0.44	0	0	0	Fail PCT
Residential	17 SEER Air Source Heat Pump	Single Family	New	N_SF_17 SE	0.86	1.22	0.71	0	0	0	Fail PCT
Residential	17 SEER Air Source Heat Pump	Multi-Family	New	N_MF_17 SE	0.65	1.22	0.53	0	0	0	Fail PCT
Residential	17 SEER Air Source Heat Pump	Manufactured Home	New	N_MH_17 SE	0.54	1.22	0.44	0	0	0	Fail PCT
Residential	17 SEER Central AC	Single Family	Turnover	T_SF_17 SE	0.67	1.10	0.61	0	0	0	Fail PCT
Residential	17 SEER Central AC	Multi-Family	Turnover	T_MF_17 SE	0.61	1.10	0.56	0	0	0	Fail PCT
Residential	17 SEER Central AC	Manufactured Home	Turnover	T_MH_17 SE	0.41	1.10	0.38	0	0	0	Fail PCT
Residential	17 SEER Central AC	Single Family	New	N_SF_17 SE	0.67	1.10	0.61	0	0	0	Fail PCT
Residential	17 SEER Central AC	Multi-Family	New	N_MF_17 SE	0.61	1.10	0.56	0	0	0	Fail PCT
Residential	17 SEER Central AC	Manufactured Home	New	N_MH_17 SE	0.41	1.10	0.38	0	0	0	Fail PCT
Residential	18 SEER Air Source Heat Pump	Single Family	Turnover	T_SF_18 SE	0.80	1.22	0.65	0	0	0	Fail PCT
Residential	18 SEER Air Source Heat Pump	Multi-Family	Turnover	T_MF_18 SE	0.54	1.22	0.44	0	0	0	Fail PCT
Residential	18 SEER Air Source Heat Pump	Manufactured Home	Turnover	T_MH_18 SE	0.49	1.22	0.40	0	0	0	Fail PCT
Residential	18 SEER Air Source Heat Pump	Single Family	New	N_SF_18 SE	0.80	1.22	0.65	0	0	0	Fail PCT
Residential	18 SEER Air Source Heat Pump	Multi-Family	New	N_MF_18 SE	0.54	1.22	0.44	0	0	0	Fail PCT
Residential	18 SEER Air Source Heat Pump	Manufactured Home	New	N_MH_18 SE	0.49	1.22	0.40	0	0	0	Fail PCT
Residential	18 SEER Central AC	Single Family	Turnover	T_SF_18 SE	0.59	1.10	0.54	0	0	0	Fail PCT
Residential	18 SEER Central AC	Multi-Family	Turnover	T_MF_18 SE	0.50	1.10	0.45	0	0	0	Fail PCT
Residential	18 SEER Central AC	Manufactured Home	Turnover	T_MH_18 SE	0.37	1.10	0.33	0	0	0	Fail PCT
Residential	18 SEER Central AC	Single Family	New	N_SF_18 SE	0.59	1.10	0.54	0	0	0	Fail PCT
Residential	18 SEER Central AC	Multi-Family	New	N_MF_18 SE	0.50	1.10	0.45	0	0	0	Fail PCT
Residential	18 SEER Central AC	Manufactured Home	New	N_MH_18 SE	0.37	1.10	0.33	0	0	0	Fail PCT
Residential	21 SEER Air Source Heat Pump	Single Family	Turnover	T_SF_21 SE	0.75	1.22	0.61	0	0	0	Fail PCT
Residential	21 SEER Air Source Heat Pump	Multi-Family	Turnover	T_MF_21 SE	0.48	1.22	0.39	0	0	0	Fail PCT
Residential	21 SEER Air Source Heat Pump	Manufactured Home	Turnover	T_MH_21 SE	0.47	1.22	0.38	0	0	0	Fail PCT
Residential	21 SEER Air Source Heat Pump	Single Family	New	N_SF_21 SE	0.75	1.22	0.61	0	0	0	Fail PCT
Residential	21 SEER Air Source Heat Pump	Multi-Family	New	N_MF_21 SE	0.48	1.22	0.39	0	0	0	Fail PCT
Residential	21 SEER Air Source Heat Pump	Manufactured Home	New	N_MH_21 SE	0.47	1.22	0.38	0	0	0	Fail PCT
Residential	21 SEER ASHP from base electric resistance heating	Single Family	Turnover	T_SF_21 SE	1.00	1.22	0.82	0	0	0	Fail PCT
Residential	21 SEER ASHP from base electric resistance heating	Multi-Family	Turnover	T_MF_21 SE	0.65	1.22	0.53	0	0	0	Fail PCT
Residential	21 SEER ASHP from base electric resistance heating	Manufactured Home	Turnover	T_MH_21 SE	0.62	1.22	0.51	0	0	0	Fail PCT
Residential	21 SEER ASHP from base electric resistance heating	Single Family	New	N_SF_21 SE	1.00	1.22	0.82	0	0	0	Fail PCT
Residential	21 SEER ASHP from base electric resistance heating	Multi-Family	New	N_MF_21 SE	0.65	1.22	0.53	0	0	0	Fail PCT
Residential	21 SEER ASHP from base electric resistance heating	Manufactured Home	New	N_MH_21 SE	0.62	1.22	0.51	0	0	0	Fail PCT
Residential	21 SEER Central AC	Single Family	Turnover	T_SF_21 SE	0.57	1.10	0.52	0	0	0	Fail PCT
Residential	21 SEER Central AC	Multi-Family	Turnover	T_MF_21 SE	0.43	1.10	0.39	0	0	0	Fail PCT
Residential	21 SEER Central AC	Manufactured Home	Turnover	T_MH_21 SE	0.35	1.10	0.32	0	0	0	Fail PCT
Residential	21 SEER Central AC	Single Family	New	N_SF_21 SE	0.57	1.10	0.52	0	0	0	Fail PCT
Residential	21 SEER Central AC	Multi-Family	New	N_MF_21 SE	0.43	1.10	0.39	0	0	0	Fail PCT
Residential	21 SEER Central AC	Manufactured Home	New	N_MH_21 SE	0.35	1.10	0.32	0	0	0	Fail PCT
Residential	Energy Star Room AC	Single Family	Turnover	T_SF_Energy	6.94	0.92	7.54	0	0	0	Fail RIM
Residential	Energy Star Room AC	Multi-Family	Turnover	T_MF_Energ	6.94	0.92	7.54	0	0	0	Fail RIM
Residential	Energy Star Room AC	Manufactured Home	Turnover	T_MH_Energ	6.94	0.92	7.54	0	0	0	Fail RIM
Residential	Energy Star Room AC	Single Family	New	N_SF_Energy	6.94	0.92	7.54	0	0	0	Fail RIM
Residential	Energy Star Room AC	Multi-Family	New	N_MF_Energ	6.94	0.92	7.54	0	0	0	Fail RIM
Residential	Energy Star Room AC	Manufactured Home	New	N_MH_Energ	6.94	0.92	7.54	0	0	0	Fail RIM
Residential	Ground Source Heat Pump	Single Family	Turnover	T_SF_Ground	0.35	1.28	0.27	0	0	0	Fail PCT
Residential	Ground Source Heat Pump	Multi-Family	Turnover	T_MF_Groun	0.37	1.28	0.29	0	0	0	Fail PCT
Residential	Ground Source Heat Pump	Manufactured Home	Turnover	T_MH_Groun	0.35	1.28	0.27	0	0	0	Fail PCT
Residential	Ground Source Heat Pump	Single Family	New	N_SF_Ground	0.35	1.28	0.27	0	0	0	Fail PCT
Residential	Ground Source Heat Pump	Multi-Family	New	N_MF_Groun	0.37	1.28	0.29	0	0	0	Fail PCT
Residential	Ground Source Heat Pump	Manufactured Home	New	N_MH_Groun	0.35	1.28	0.27	0	0	0	Fail PCT
Residential	Variable Refrigerant Flow (VRF) HVAC Systems	Single Family	Turnover	T_SF_Variabl	0.81	1.19	0.68	0	0	0	Fail PCT
Residential	Variable Refrigerant Flow (VRF) HVAC Systems	Multi-Family	Turnover	T_MF_Variab	0.66	1.19	0.55	0	0	0	Fail PCT
Residential	Variable Refrigerant Flow (VRF) HVAC Systems	Manufactured Home	Turnover	T_MH_Variab	0.81	1.19	0.68	0	0	0	Fail PCT
Residential	Variable Refrigerant Flow (VRF) HVAC Systems	Single Family	New	N_SF_Variab	1.03	1.19	0.87	0	0	0	Fail PCT
Residential	Variable Refrigerant Flow (VRF) HVAC Systems	Multi-Family	New	N_MF_Variab	0.89	1.19	0.75	0	0	0	Fail PCT
Residential	Variable Refrigerant Flow (VRF) HVAC Systems	Manufactured Home	New	N_MH_Varia	1.03	1.19	0.87	0	0	0	Fail PCT
Residential	CFL - 15W Flood (Exterior)	Single Family	Turnover	T_SF_CFL -	2.51	0.25	10.18	0	0	0	Fail RIM
Residential	CFL - 15W Flood (Exterior)	Multi-Family	Turnover	T_MF_CFL -	2.51	0.25	10.18	0	0	0	Fail RIM
Residential	CFL - 15W Flood (Exterior)	Manufactured Home	Turnover	T_MH_CFL -	2.51	0.25	10.18	0	0	0	Fail RIM
Residential	CFL - 15W Flood (Exterior)	Single Family	New	N_SF_CFL -	2.51	0.25	10.18	0	0	0	Fail RIM
Residential	CFL - 15W Flood (Exterior)	Multi-Family	New	N_MF_CFL -	2.51	0.25	10.18	0	0	0	Fail RIM
Residential	CFL - 15W Flood (Exterior)	Manufactured Home	New	N_MH_CFL -	2.51	0.25	10.18	0	0	0	Fail RIM
Residential	CFL - 15W Flood	Single Family	Turnover	T_SF_CFL -	0.36	0.35	1.02	0	0	0	Fail RIM
Residential	CFL - 15W Flood	Multi-Family	Turnover	T_MF_CFL -	0.36	0.35	1.02	0	0	0	Fail RIM
Residential	CFL - 15W Flood	Manufactured Home	Turnover	T_MH_CFL -	0.36	0.35	1.02	0	0	0	Fail RIM
Residential	CFL - 15W Flood	Single Family	New	N_SF_CFL -	0.36	0.35	1.02	0	0	0	Fail RIM
Residential	CFL - 15W Flood	Multi-Family	New	N_MF_CFL -	0.36	0.35	1.02	0	0	0	Fail RIM
Residential	CFL - 15W Flood	Manufactured Home	New	N_MH_CFL -	0.36	0.35	1.02	0	0	0	Fail RIM
Residential	CFL-13W	Single Family	Turnover	T_SF_CFL-13	1.17	0.35	3.37	0	0	0	Fail RIM
Residential	CFL-13W	Multi-Family	Turnover	T_MF_CFL-1	1.17	0.35	3.37	0	0	0	Fail RIM
Residential	CFL-13W	Manufactured Home	Turnover	T_MH_CFL-1	1.17	0.35	3.37	0	0	0	Fail RIM
Residential	CFL-13W	Single Family	New	N_SF_CFL-1	1.17	0.35	3.37	0	0	0	Fail RIM
Residential	CFL-13W	Multi-Family	New	N_MF_CFL-1	1.17	0.35	3.37	0	0	0	Fail RIM
Residential	CFL-13W	Manufactured Home	New	N_MH_CFL-	1.17	0.35	3.37	0	0	0	Fail RIM
Residential	CFL-23W	Single Family	Turnover	T_SF_CFL-2	2.55	0.35	7.33	0	0	0	Fail RIM
Residential	CFL-23W	Multi-Family	Turnover	T_MF_CFL-2	2.55	0.35	7.33	0	0	0	Fail RIM
Residential	CFL-23W	Manufactured Home	Turnover	T_MH_CFL-2	2.55	0.35	7.33	0	0	0	Fail RIM
Residential	CFL-23W	Single Family	New	N_SF_CFL-2	2.55	0.35	7.33	0	0	0	Fail RIM
Residential	CFL-23W	Multi-Family	New	N_MF_CFL-2	2.55	0.35	7.33	0	0	0	Fail RIM
Residential	CFL-23W	Manufactured Home	New	N_MH_CFL-2	2.55	0.35	7.33	0	0	0	Fail RIM
Residential	LED - 14W	Single Family	Turnover	T_SF_LED -	3.42	0.37	9.24	0	0	0	Fail RIM
Residential	LED - 14W	Multi-Family	Turnover	T_MF_LED -	3.42	0.37	9.24	0	0	0	Fail RIM
Residential	LED - 14W	Manufactured Home	Turnover	T_MH_LED -	3.42	0.37	9.24	0	0	0	Fail RIM
Residential	LED - 14W	Single Family	New	N_SF_LED -	3.42	0.37	9.24	0	0	0	Fail RIM
Residential	LED - 14W	Multi-Family	New	N_MF_LED -	3.42	0.37	9.24	0	0	0	Fail RIM
Residential	LED - 14W	Manufactured Home	New	N_MH_LED	3.42	0.37	9.24	0	0	0	Fail RIM
Residential	LED - 9W Flood (Exterior)	Single Family	Turnover	T_SF_LED -	4.38	0.25	17.36	0	0	0	Fail RIM
Residential	LED - 9W Flood (Exterior)	Multi-Family	Turnover	T_MF_LED -	4.38	0.25	17.36	0	0	0	Fail RIM
Residential	LED - 9W Flood (Exterior)	Manufactured Home	Turnover	T_MH_LED -	4.38	0.25	17.36	0	0	0	Fail RIM

Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Assembly	Existing	E_AS_PSC to	1.84	0.58	3.15	0	0	0
Commercial	Facility Energy Management System	Assembly	New	N_AS_Facilit	1.03	0.73	1.41	0	0	0
Commercial	Facility Energy Management System	Assembly	Existing	E_AS_Facilit	1.03	0.73	1.41	1	0	3
Commercial	Thermal Energy Storage	Assembly	New	N_AS_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	HVAC tune-up	Assembly	New	N_AS_HVAC	1.20	0.95	1.26	0	0	0
Commercial	Duct Sealing Repair	Assembly	New	N_AS_Duct S	4.94	1.64	3.01	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Assembly	New	N_AS_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Assembly	New	N_AS_Ceiling	4.58	1.22	3.76	0	0	0
Commercial	Wall Insulation	Assembly	Existing	E_AS_Wall I	3.42	1.22	2.81	0	0	0
Commercial	Thermal Energy Storage	Assembly	Existing	E_AS_Therm	2.46	9999.00	9999.00	4	1	-1
Commercial	Low U-Value Windows	Assembly	Existing	E_AS_Low U	1.46	1.12	1.31	2	0	5
Commercial	HVAC tune-up	Assembly	Existing	E_AS_HVAC	1.20	0.95	1.26	0	0	0
Commercial	Duct Sealing Repair	Assembly	Existing	E_AS_Duct S	4.94	1.64	3.01	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Assembly	Existing	E_AS_Chille	2.43	0.52	4.69	2	0	14
Commercial	Ceiling Insulation(R2 to R38)	Assembly	Existing	E_AS_Ceiling	4.67	1.22	3.83	0	0	0
Commercial	VSD Controlled Compressor	Assembly	New	N_AS_VSD C	2.22	0.61	3.66	0	0	0
Commercial	VSD Controlled Compressor	Assembly	Existing	E_AS_VSD C	2.22	0.61	3.66	0	0	1
Commercial	Variable Speed Pool Pump	Assembly	Turnover	T_AS_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Assembly	Turnover	T_AS_Solar F	1.08	0.33	3.23	0	0	0
Commercial	Variable Speed Pool Pump	Assembly	New	N_AS_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Assembly	New	N_AS_Solar I	1.08	0.33	3.23	0	0	0
Commercial	Efficient Battery Charger	Assembly	Turnover	T_AS_Efficie	1.63	1.02	1.59	1	0	1
Commercial	Efficient Battery Charger	Assembly	New	N_AS_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Assembly	Turnover	T_AS_Energy	1.32	0.48	2.73	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Assembly	New	N_AS_Energy	1.32	0.48	2.73	0	0	0
Commercial	Demand Controlled Ventilation	Assembly	New	N_AS_Demar	3.09	1.25	2.46	0	0	0
Commercial	Demand Controlled Ventilation	Assembly	Existing	E_AS_Demar	3.09	1.25	2.46	0	1	1
Commercial	High Bay LED	Assembly	Turnover	T_AS_High B	2.93	0.68	4.33	2	2	13
Commercial	High Bay LED	Assembly	New	N_AS_High B	2.93	0.68	4.33	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Assembly	Turnover	T_AS_High E	2.20	0.89	2.48	1	0	2
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Assembly	Turnover	T_AS_High E	1.48	1.17	1.27	0	0	1
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Assembly	Turnover	T_AS_High E	2.55	1.17	2.19	0	0	1
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Assembly	New	N_AS_High E	2.20	0.89	2.48	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Assembly	New	N_AS_High E	1.48	1.17	1.27	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Assembly	New	N_AS_High E	2.55	1.17	2.19	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Assembly	Turnover	T_AS_Energy	2.78	0.58	4.78	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Assembly	New	N_AS_Energy	2.78	0.58	4.78	0	0	0
Commercial	Efficient Exhaust Hood	Assembly	Turnover	T_AS_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Assembly	Turnover	T_AS_Energy	1.28	0.65	1.97	0	0	0
Commercial	Efficient Exhaust Hood	Assembly	New	N_AS_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Assembly	New	N_AS_Energy	1.28	0.65	1.97	0	0	0
Commercial	Heat Pump Water Heater	Assembly	Turnover	T_AS_Heat P	2.14	0.58	3.68	0	0	0
Commercial	Heat Pump Water Heater	Assembly	New	N_AS_Heat P	2.14	0.58	3.68	0	0	0
Commercial	Retro-Commissioning	College and University	New	N_CU_Retro-	1.82	0.85	2.15	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	College and University	New	N_CU_PSC to	1.15	0.56	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	College and University	New	N_CU_PSC to	1.77	0.56	3.15	0	0	0
Commercial	Retro-Commissioning	College and University	Existing	E_CU_Retro-	1.82	0.85	2.15	1	0	1
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	College and University	Existing	E_CU_PSC to	1.15	0.56	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	College and University	Existing	E_CU_PSC to	1.77	0.56	3.15	0	0	0
Commercial	Facility Energy Management System	College and University	New	N_CU_Facilit	1.28	0.60	2.14	0	0	0
Commercial	Facility Energy Management System	College and University	Existing	E_CU_Facilit	1.28	0.60	2.14	0	0	0
Commercial	Thermal Energy Storage	College and University	New	N_CU_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Duct Sealing Repair	College and University	New	N_CU_Duct S	7.49	1.64	4.57	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	College and University	New	N_CU_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	College and University	New	N_CU_Ceilin	4.55	1.21	3.76	0	0	0
Commercial	Wall Insulation	College and University	Existing	E_CU_Wall I	3.30	1.21	2.72	0	0	0
Commercial	Thermal Energy Storage	College and University	Existing	E_CU_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Low U-Value Windows	College and University	Existing	E_CU_Low U	1.46	1.12	1.31	0	0	0
Commercial	Duct Sealing Repair	College and University	Existing	E_CU_Duct S	7.49	1.64	4.57	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	College and University	Existing	E_CU_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	College and University	Existing	E_CU_Ceiling	4.64	1.21	3.83	0	0	0
Commercial	ECM Motors on Furnaces	College and University	New	N_CU_ECM	1.22	0.56	2.19	0	0	0
Commercial	ECM Motors on Furnaces	College and University	Existing	E_CU_ECM	1.22	0.56	2.19	0	0	0
Commercial	VSD Controlled Compressor	College and University	New	N_CU_VSD C	2.06	0.56	3.66	0	0	0
Commercial	VSD Controlled Compressor	College and University	Existing	E_CU_VSD C	2.06	0.56	3.66	0	0	0
Commercial	Variable Speed Pool Pump	College and University	Turnover	T_CU_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	College and University	Turnover	T_CU_Solar F	1.08	0.33	3.23	0	0	0
Commercial	Variable Speed Pool Pump	College and University	New	N_CU_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	College and University	New	N_CU_Solar	1.08	0.33	3.23	0	0	0
Commercial	Efficient Battery Charger	College and University	Turnover	T_CU_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	College and University	New	N_CU_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	College and University	Turnover	T_CU_Energy	1.32	0.48	2.73	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	College and University	New	N_CU_Energy	1.32	0.48	2.73	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	College and University	Turnover	T_CU_High E	2.44	0.89	2.75	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	College and University	Turnover	T_CU_High E	1.65	1.17	1.41	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	College and University	Turnover	T_CU_High E	2.83	1.17	2.42	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	College and University	New	N_CU_High E	2.44	0.89	2.75	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	College and University	New	N_CU_High E	1.65	1.17	1.41	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	College and University	New	N_CU_High E	2.83	1.17	2.42	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	College and University	Turnover	T_CU_Energy	2.59	0.54	4.78	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	College and University	New	N_CU_Energy	2.59	0.54	4.78	0	0	0
Commercial	Efficient Exhaust Hood	College and University	Turnover	T_CU_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	College and University	Turnover	T_CU_Energy	1.28	0.65	1.97	0	0	0
Commercial	Efficient Exhaust Hood	College and University	New	N_CU_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	College and University	New	N_CU_Energy	1.28	0.65	1.97	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Grocery	New	N_GR_PSC to	1.19	0.58	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Grocery	New	N_GR_PSC to	1.84	0.58	3.15	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Grocery	Existing	E_GR_PSC to	1.19	0.58	2.05	1	0	5
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Grocery	Existing	E_GR_PSC to	1.84	0.58	3.15	1	0	10
Commercial	Thermal Energy Storage	Grocery	New	N_GR_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Facility Commissioning	Grocery	New	N_GR_Facilit	1.50	0.67	2.25	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Grocery	New	N_GR_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Grocery	New	N_GR_Ceilin	4.70	1.25	3.76	0	0	0
Commercial	Wall Insulation	Grocery	Existing	E_GR_Wall I	3.46	1.25	2.76	0	0	0
Commercial	Thermal Energy Storage	Grocery	Existing	E_GR_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Low U-Value Windows	Grocery	Existing	E_GR_Low U	1.46	1.12	1.31	2	0	5
Commercial	Chilled Water System - Variable Speed Drives	Grocery	Existing	E_GR_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Grocery	Existing	E_GR_Ceiling	4.79	1.25	3.83	0	0	0
Commercial	High Efficiency PTHP	Grocery	Turnover	T_GR_High E	5.01	1.33	3.76	0	0	0
Commercial	High Efficiency PTAC	Grocery	Turnover	T_GR_High E	4.86	1.35	3.60	0	0	0
Commercial	High Efficiency PTHP	Grocery	New	N_GR_High E	5.01	1.33	3.76	0	0	0
Commercial	High Efficiency PTAC	Grocery	New	N_GR_High E	4.86	1.35	3.60	0	0	0
Commercial	ECM Motors on Furnaces	Grocery	New	N_GR_ECM	1.82	0.48	3.76	0	0	0
Commercial	ECM Motors on Furnaces	Grocery	Existing	E_GR_ECM	1.82	0.48	3.76	0	0	0
Commercial	VSD Controlled Compressor	Grocery	New	N_GR_VSD C	2.22	0.61	3.66	0	0	0
Commercial	VSD Controlled Compressor	Grocery	Existing	E_GR_VSD C	2.22	0.61	3.66	1	0	3
Commercial	Variable Speed Pool Pump	Grocery	Turnover	T_GR_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Grocery	Turnover	T_GR_Solar F	1.08	0.33	3.23	0	0	0
Commercial	Variable Speed Pool Pump	Grocery	New	N_GR_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Grocery	New	N_GR_Solar	1.08	0.33	3.23	0	0	0
Commercial	Premium T8 - Fixture Replacement	Grocery	Turnover	T_GR_Premiu	1.23	0.65	1.90	1	0	2
Commercial	Premium T8 - Fixture Replacement	Grocery	New	N_GR_Premiu	1.23	0.65	1.90	0	0	0
Commercial	Efficient Battery Charger	Grocery	Turnover	T_GR_Efficie	1.63	1.02	1.59	1	0	2
Commercial	Efficient Battery Charger	Grocery	New	N_GR_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Grocery	Turnover	T_GR_Energy	1.32	0.48	2.73	0	0	0

Residential	15 SEER Air Source Heat Pump	Multi-Family	New	N_MF_15 SE	0.97	1.22	0.79	0	0	0	Fail TRC
Residential	15 SEER Air Source Heat Pump	Manufactured Home	New	N_MH_15 SE	0.93	1.22	0.76	0	0	0	Fail TRC
Residential	15 SEER Central AC	Multi-Family	Turnover	T_MF_15 SE	1.09	1.10	0.99	0	0	0	Fail PCT
Residential	15 SEER Central AC	Manufactured Home	Turnover	T_MH_15 SE	0.99	1.10	0.90	0	0	0	Fail TRC
Residential	15 SEER Central AC	Multi-Family	New	N_MF_15 SE	1.09	1.10	0.99	0	0	0	Fail PCT
Residential	15 SEER Central AC	Manufactured Home	New	N_MH_15 SE	0.99	1.10	0.90	0	0	0	Fail TRC
Residential	16 SEER Air Source Heat Pump	Single Family	Turnover	T_SF_16 SE	0.99	1.22	0.81	0	0	0	Fail TRC
Residential	16 SEER Air Source Heat Pump	Multi-Family	Turnover	T_MF_16 SE	0.73	1.22	0.59	0	0	0	Fail TRC
Residential	16 SEER Air Source Heat Pump	Manufactured Home	Turnover	T_MH_16 SE	0.61	1.22	0.50	0	0	0	Fail TRC
Residential	16 SEER Air Source Heat Pump	Single Family	New	N_SF_16 SE	0.99	1.22	0.81	0	0	0	Fail TRC
Residential	16 SEER Air Source Heat Pump	Multi-Family	New	N_MF_16 SE	0.73	1.22	0.59	0	0	0	Fail TRC
Residential	16 SEER Air Source Heat Pump	Manufactured Home	New	N_MH_16 SE	0.61	1.22	0.50	0	0	0	Fail TRC
Residential	16 SEER Central AC	Multi-Family	Turnover	T_MF_16 SE	1.04	1.10	0.95	0	0	0	Fail PCT
Residential	16 SEER Central AC	Manufactured Home	Turnover	T_MH_16 SE	0.95	1.10	0.86	0	0	0	Fail TRC
Residential	16 SEER Central AC	Multi-Family	New	N_MF_16 SE	1.04	1.10	0.95	0	0	0	Fail PCT
Residential	16 SEER Central AC	Manufactured Home	New	N_MH_16 SE	0.95	1.10	0.86	0	0	0	Fail TRC
Residential	17 SEER Air Source Heat Pump	Single Family	Turnover	T_SF_17 SE	0.86	1.22	0.71	0	0	0	Fail TRC
Residential	17 SEER Air Source Heat Pump	Multi-Family	Turnover	T_MF_17 SE	0.65	1.22	0.53	0	0	0	Fail TRC
Residential	17 SEER Air Source Heat Pump	Manufactured Home	Turnover	T_MH_17 SE	0.54	1.22	0.44	0	0	0	Fail TRC
Residential	17 SEER Air Source Heat Pump	Single Family	New	N_SF_17 SE	0.86	1.22	0.71	0	0	0	Fail TRC
Residential	17 SEER Air Source Heat Pump	Multi-Family	New	N_MF_17 SE	0.65	1.22	0.53	0	0	0	Fail TRC
Residential	17 SEER Air Source Heat Pump	Manufactured Home	New	N_MH_17 SE	0.54	1.22	0.44	0	0	0	Fail TRC
Residential	17 SEER Central AC	Single Family	Turnover	T_SF_17 SE	0.67	1.10	0.61	0	0	0	Fail TRC
Residential	17 SEER Central AC	Multi-Family	Turnover	T_MF_17 SE	0.61	1.10	0.56	0	0	0	Fail TRC
Residential	17 SEER Central AC	Manufactured Home	Turnover	T_MH_17 SE	0.41	1.10	0.38	0	0	0	Fail TRC
Residential	17 SEER Central AC	Single Family	New	N_SF_17 SE	0.67	1.10	0.61	0	0	0	Fail TRC
Residential	17 SEER Central AC	Multi-Family	New	N_MF_17 SE	0.61	1.10	0.56	0	0	0	Fail TRC
Residential	17 SEER Central AC	Manufactured Home	New	N_MH_17 SE	0.41	1.10	0.38	0	0	0	Fail TRC
Residential	18 SEER Air Source Heat Pump	Single Family	Turnover	T_SF_18 SE	0.80	1.22	0.65	0	0	0	Fail TRC
Residential	18 SEER Air Source Heat Pump	Multi-Family	Turnover	T_MF_18 SE	0.54	1.22	0.44	0	0	0	Fail TRC
Residential	18 SEER Air Source Heat Pump	Manufactured Home	Turnover	T_MH_18 SE	0.49	1.22	0.40	0	0	0	Fail TRC
Residential	18 SEER Air Source Heat Pump	Single Family	New	N_SF_18 SE	0.80	1.22	0.65	0	0	0	Fail TRC
Residential	18 SEER Air Source Heat Pump	Multi-Family	New	N_MF_18 SE	0.54	1.22	0.44	0	0	0	Fail TRC
Residential	18 SEER Air Source Heat Pump	Manufactured Home	New	N_MH_18 SE	0.49	1.22	0.40	0	0	0	Fail TRC
Residential	18 SEER Central AC	Single Family	Turnover	T_SF_18 SE	0.59	1.10	0.54	0	0	0	Fail TRC
Residential	18 SEER Central AC	Multi-Family	Turnover	T_MF_18 SE	0.50	1.10	0.45	0	0	0	Fail TRC
Residential	18 SEER Central AC	Manufactured Home	Turnover	T_MH_18 SE	0.37	1.10	0.33	0	0	0	Fail TRC
Residential	18 SEER Central AC	Single Family	New	N_SF_18 SE	0.59	1.10	0.54	0	0	0	Fail TRC
Residential	18 SEER Central AC	Multi-Family	New	N_MF_18 SE	0.50	1.10	0.45	0	0	0	Fail TRC
Residential	18 SEER Central AC	Manufactured Home	New	N_MH_18 SE	0.37	1.10	0.33	0	0	0	Fail TRC
Residential	21 SEER Air Source Heat Pump	Single Family	Turnover	T_SF_21 SE	0.75	1.22	0.61	0	0	0	Fail TRC
Residential	21 SEER Air Source Heat Pump	Multi-Family	Turnover	T_MF_21 SE	0.48	1.22	0.39	0	0	0	Fail TRC
Residential	21 SEER Air Source Heat Pump	Manufactured Home	Turnover	T_MH_21 SE	0.47	1.22	0.38	0	0	0	Fail TRC
Residential	21 SEER Air Source Heat Pump	Single Family	New	N_SF_21 SE	0.75	1.22	0.61	0	0	0	Fail TRC
Residential	21 SEER Air Source Heat Pump	Multi-Family	New	N_MF_21 SE	0.48	1.22	0.39	0	0	0	Fail TRC
Residential	21 SEER Air Source Heat Pump	Manufactured Home	New	N_MH_21 SE	0.47	1.22	0.38	0	0	0	Fail TRC
Residential	21 SEER ASHP from base electric resistance heating	Single Family	Turnover	T_SF_21 SE	1.00	1.22	0.82	0	0	0	Fail TRC
Residential	21 SEER ASHP from base electric resistance heating	Multi-Family	Turnover	T_MF_21 SE	0.65	1.22	0.53	0	0	0	Fail TRC
Residential	21 SEER ASHP from base electric resistance heating	Manufactured Home	Turnover	T_MH_21 SE	0.62	1.22	0.51	0	0	0	Fail TRC
Residential	21 SEER ASHP from base electric resistance heating	Single Family	New	N_SF_21 SE	1.00	1.22	0.82	0	0	0	Fail TRC
Residential	21 SEER ASHP from base electric resistance heating	Multi-Family	New	N_MF_21 SE	0.65	1.22	0.53	0	0	0	Fail TRC
Residential	21 SEER ASHP from base electric resistance heating	Manufactured Home	New	N_MH_21 SE	0.62	1.22	0.51	0	0	0	Fail TRC
Residential	21 SEER Central AC	Single Family	Turnover	T_SF_21 SE	0.57	1.10	0.52	0	0	0	Fail TRC
Residential	21 SEER Central AC	Multi-Family	Turnover	T_MF_21 SE	0.43	1.10	0.39	0	0	0	Fail TRC
Residential	21 SEER Central AC	Manufactured Home	Turnover	T_MH_21 SE	0.35	1.10	0.32	0	0	0	Fail TRC
Residential	21 SEER Central AC	Single Family	New	N_SF_21 SE	0.57	1.10	0.52	0	0	0	Fail TRC
Residential	21 SEER Central AC	Multi-Family	New	N_MF_21 SE	0.43	1.10	0.39	0	0	0	Fail TRC
Residential	21 SEER Central AC	Manufactured Home	New	N_MH_21 SE	0.35	1.10	0.32	0	0	0	Fail TRC
Residential	Energy Star Room AC	Single Family	Turnover	T_SF_Energy	6.94	0.92	7.54	0	0	0	Fail 2-year Threshold
Residential	Energy Star Room AC	Multi-Family	Turnover	T_MF_Energ	6.94	0.92	7.54	0	0	0	Fail 2-year Threshold
Residential	Energy Star Room AC	Manufactured Home	Turnover	T_MH_Energ	6.94	0.92	7.54	0	0	0	Fail 2-year Threshold
Residential	Energy Star Room AC	Single Family	New	N_SF_Energy	6.94	0.92	7.54	0	0	0	Fail 2-year Threshold
Residential	Energy Star Room AC	Multi-Family	New	N_MF_Energ	6.94	0.92	7.54	0	0	0	Fail 2-year Threshold
Residential	Energy Star Room AC	Manufactured Home	New	N_MH_Energ	6.94	0.92	7.54	0	0	0	Fail 2-year Threshold
Residential	Ground Source Heat Pump	Single Family	Turnover	T_SF_Ground	0.35	1.28	0.27	0	0	0	Fail TRC
Residential	Ground Source Heat Pump	Multi-Family	Turnover	T_MF_Groun	0.37	1.28	0.29	0	0	0	Fail TRC
Residential	Ground Source Heat Pump	Manufactured Home	Turnover	T_MH_Groun	0.35	1.28	0.27	0	0	0	Fail TRC
Residential	Ground Source Heat Pump	Single Family	New	N_SF_Ground	0.35	1.28	0.27	0	0	0	Fail TRC
Residential	Ground Source Heat Pump	Multi-Family	New	N_MF_Groun	0.37	1.28	0.29	0	0	0	Fail TRC
Residential	Ground Source Heat Pump	Manufactured Home	New	N_MH_Groun	0.35	1.28	0.27	0	0	0	Fail TRC
Residential	Variable Refrigerant Flow (VRF) HVAC Systems	Single Family	Turnover	T_SF_Variabl	0.81	1.19	0.68	0	0	0	Fail TRC
Residential	Variable Refrigerant Flow (VRF) HVAC Systems	Multi-Family	Turnover	T_MF_Variab	0.66	1.19	0.55	0	0	0	Fail TRC
Residential	Variable Refrigerant Flow (VRF) HVAC Systems	Manufactured Home	Turnover	T_MH_Variab	0.81	1.19	0.68	0	0	0	Fail TRC
Residential	Variable Refrigerant Flow (VRF) HVAC Systems	Single Family	New	N_SF_Variab	1.03	1.19	0.87	0	0	0	Fail PCT
Residential	Variable Refrigerant Flow (VRF) HVAC Systems	Multi-Family	New	N_MF_Variab	0.89	1.19	0.75	0	0	0	Fail TRC
Residential	Variable Refrigerant Flow (VRF) HVAC Systems	Manufactured Home	New	N_MH_Varia	1.03	1.19	0.87	0	0	0	Fail PCT
Residential	CFL - 15W Flood (Exterior)	Single Family	Turnover	T_SF_CFL -	2.51	0.25	10.18	0	0	0	Fail 2-year Threshold
Residential	CFL - 15W Flood (Exterior)	Multi-Family	Turnover	T_MF_CFL -	2.51	0.25	10.18	0	0	0	Fail 2-year Threshold
Residential	CFL - 15W Flood (Exterior)	Manufactured Home	Turnover	T_MH_CFL -	2.51	0.25	10.18	0	0	0	Fail 2-year Threshold
Residential	CFL - 15W Flood (Exterior)	Single Family	New	N_SF_CFL -	2.51	0.25	10.18	0	0	0	Fail 2-year Threshold
Residential	CFL - 15W Flood (Exterior)	Multi-Family	New	N_MF_CFL -	2.51	0.25	10.18	0	0	0	Fail 2-year Threshold
Residential	CFL - 15W Flood (Exterior)	Manufactured Home	New	N_MH_CFL -	2.51	0.25	10.18	0	0	0	Fail 2-year Threshold
Residential	CFL - 15W Flood	Single Family	Turnover	T_SF_CFL -	0.36	0.35	1.02	0	0	0	Fail TRC
Residential	CFL - 15W Flood	Multi-Family	Turnover	T_MF_CFL -	0.36	0.35	1.02	0	0	0	Fail TRC
Residential	CFL - 15W Flood	Manufactured Home	Turnover	T_MH_CFL -	0.36	0.35	1.02	0	0	0	Fail TRC
Residential	CFL - 15W Flood	Single Family	New	N_SF_CFL -	0.36	0.35	1.02	0	0	0	Fail TRC
Residential	CFL - 15W Flood	Multi-Family	New	N_MF_CFL -	0.36	0.35	1.02	0	0	0	Fail TRC
Residential	CFL - 15W Flood	Manufactured Home	New	N_MH_CFL -	0.36	0.35	1.02	0	0	0	Fail TRC
Residential	CFL-23W	Single Family	Turnover	T_SF_CFL-23	2.55	0.35	7.33	0	0	0	Fail 2-year Threshold
Residential	CFL-23W	Multi-Family	Turnover	T_MF_CFL-2	2.55	0.35	7.33	0	0	0	Fail 2-year Threshold
Residential	CFL-23W	Manufactured Home	Turnover	T_MH_CFL-2	2.55	0.35	7.33	0	0	0	Fail 2-year Threshold
Residential	CFL-23W	Single Family	New	N_SF_CFL-2	2.55	0.35	7.33	0	0	0	Fail 2-year Threshold
Residential	CFL-23W	Multi-Family	New	N_MF_CFL-2	2.55	0.35	7.33	0	0	0	Fail 2-year Threshold
Residential	CFL-23W	Manufactured Home	New	N_MH_CFL-2	2.55	0.35	7.33	0	0	0	Fail 2-year Threshold
Residential	LED - 14W	Single Family	Turnover	T_SF_LED -	3.42	0.37	9.24	0	0	0	Fail 2-year Threshold
Residential	LED - 14W	Multi-Family	Turnover	T_MF_LED -	3.42	0.37	9.24	0	0	0	Fail 2-year Threshold
Residential	LED - 14W	Manufactured Home	Turnover	T_MH_LED -	3.42	0.37	9.24	0	0	0	Fail 2-year Threshold
Residential	LED - 14W	Single Family	New	N_SF_LED -	3.42	0.37	9.24	0	0	0	Fail 2-year Threshold
Residential	LED - 14W	Multi-Family	New	N_MF_LED -	3.42	0.37	9.24	0	0	0	Fail 2-year Threshold
Residential	LED - 14W	Manufactured Home	New	N_MH_LED	3.42	0.37	9.24	0	0	0	Fail 2-year Threshold
Residential	LED - 9W Flood (Exterior)	Single Family	Turnover	T_SF_LED -	4.38	0.25	17.36	0	0	0	Fail 2-year Threshold
Residential	LED - 9W Flood (Exterior)	Multi-Family	Turnover	T_MF_LED -	4.38	0.25	17.36	0	0	0	Fail 2-year Threshold
Residential	LED - 9W Flood (Exterior)	Manufactured Home	Turnover	T_MH_LED -	4.38	0.25	17.36	0	0	0	Fail 2-year Threshold
Residential	LED - 9W Flood (Exterior)	Single Family	New	N_SF_LED -	4.38	0.25	17.36	0	0	0	Fail 2-year Threshold
Residential	LED - 9W Flood (Exterior)	Multi-Family	New	N_MF_LED -	4.38	0.25	17.36	0	0	0	Fail 2-year Threshold
Residential	LED - 9W Flood (Exterior)	Manufactured Home	New	N_MH_LED	4.38	0.25	17.36	0	0	0	Fail 2-year Threshold
Residential	LED - 9W	Single Family	Turnover	T_SF_LED -	3.02	0.37	8.14	0	0	0	Fail 2-year Threshold
Residential	LED - 9W	Multi-Family	Turnover	T_MF_LED -	3.02	0.37	8.14	0	0	0	Fail 2-year Threshold
Residential	LED - 9W	Manufactured Home	Turnover	T_MH_LED -	3.02	0.37	8.14	0	0	0	Fail 2-year Threshold
Residential	LED - 9W	Single Family	New	N_SF_LED -	3.02	0.37	8.14	0	0	0	Fail 2-year Threshold
Residential	LED - 9W	Multi-Family	New	N_MF_LED -	3.02	0.37	8.14	0	0	0	Fail 2-year Threshold
Residential	LED - 9W	Manufactured Home	New	N_MH_LED	3.02	0.37	8.14	0	0	0	Fail 2-year Threshold
Residential	Linear LED	Single Family	Turnover	T_SF_Linear	2.63	0.26	9.96	0	0	0	Fail 2-year Threshold
Residential	Linear LED	Multi-Family	Turnover	T_MF_Linear	2.63	0.26	9.96	0	0	0	Fail 2-year Threshold
Residential	Linear LED	Manufactured Home	Turnover	T_MH_Linear	2.63	0.26	9.96	0	0	0	Fail 2-year Threshold

Commercial	Thermal Energy Storage	Retail	New	N_RT_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Schools K-12	New	N_SC_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Thermal Energy Storage	Warehouse	New	N_WR_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Wall Insulation	Assembly	Existing	E_AS_Wall I	3.42	1.22	2.81	0	0	0
Commercial	Wall Insulation	College and University	Existing	E_CU_Wall I	3.30	1.21	2.72	0	0	0
Commercial	Wall Insulation	Grocery	Existing	E_GR_Wall I	3.46	1.25	2.76	0	0	0
Commercial	Wall Insulation	Healthcare	Existing	E_HC_Wall I	3.27	1.22	2.69	0	0	3
Commercial	Wall Insulation	Hospitals	Existing	E_HS_Wall I	3.35	1.21	2.76	0	0	0
Commercial	Wall Insulation	Institutional	Existing	E_IN_Wall In	3.32	1.22	2.72	0	0	0
Commercial	Wall Insulation	Lodging/Hospitality	Existing	E_LG_Wall I	3.30	1.21	2.72	0	0	0
Commercial	Wall Insulation	Miscellaneous	Existing	E_MS_Wall I	3.37	1.22	2.76	0	0	0
Commercial	Wall Insulation	Offices	Existing	E_OF_Wall I	3.37	1.22	2.76	0	0	21
Commercial	Wall Insulation	Restaurants	Existing	E_RS_Wall I	3.51	1.25	2.81	0	0	0
Commercial	Wall Insulation	Retail	Existing	E_RT_Wall I	3.46	1.25	2.76	3	0	13
Commercial	Wall Insulation	Schools K-12	Existing	E_SC_Wall I	3.47	1.22	2.85	0	0	0
Commercial	Demand Controlled Ventilation	Assembly	Existing	E_AS_Demar	3.09	1.25	2.46	0	1	1
Commercial	Demand Controlled Ventilation	Grocery	Existing	E_GR_Demar	1.40	1.25	1.12	0	1	1
Commercial	Demand Controlled Ventilation	Lodging/Hospitality	Existing	E_LG_Demar	5.03	1.25	4.01	1	7	11
Commercial	Demand Controlled Ventilation	Miscellaneous	Existing	E_MS_Demar	4.56	1.25	3.64	0	0	1
Commercial	Demand Controlled Ventilation	Offices	Existing	E_OF_Demar	4.78	1.25	3.81	2	10	17
Commercial	Demand Controlled Ventilation	Restaurants	Existing	E_RS_Demar	1.51	1.25	1.20	0	1	3
Commercial	Demand Controlled Ventilation	Retail	Existing	E_RT_Demar	3.38	1.25	2.69	2	10	17
Commercial	Demand Controlled Ventilation	Warehouse	Existing	E_WR_Dema	1.26	1.25	1.00	0	1	1
Commercial	Demand Controlled Ventilation	Assembly	New	N_AS_Demar	3.09	1.25	2.46	0	0	0
Commercial	Demand Controlled Ventilation	Grocery	New	N_GR_Demar	1.40	1.25	1.12	0	0	0
Commercial	Demand Controlled Ventilation	Lodging/Hospitality	New	N_LG_Demar	5.03	1.25	4.01	0	0	0
Commercial	Demand Controlled Ventilation	Miscellaneous	New	N_MS_Dema	4.56	1.25	3.64	0	0	0
Commercial	Demand Controlled Ventilation	Offices	New	N_OF_Demar	4.78	1.25	3.81	0	0	0
Commercial	Demand Controlled Ventilation	Restaurants	New	N_RS_Demar	1.51	1.25	1.20	0	0	0
Commercial	Demand Controlled Ventilation	Retail	New	N_RT_Demar	3.38	1.25	2.69	0	0	0
Commercial	Demand Controlled Ventilation	Warehouse	New	N_WR_Dema	1.26	1.25	1.00	0	0	0
Residential	Central air conditioner - Load Shed	Single Family	Existing		Passed	Passed	N/A	748	0	0
Residential	Central air conditioner - Load Shed	Multi Family	Existing		Passed	Passed	N/A	182	0	0
Residential	Central air conditioner - Load Shed	Mobile Home/Other	Existing		Passed	Passed	N/A	135	0	0
Residential	Central Heating - Load Shed	Single Family	Existing		Passed	Passed	N/A	0	1,486	0
Residential	Central Heating - Load Shed	Multi Family	Existing		Passed	Passed	N/A	0	434	0
Residential	Central Heating - Load Shed	Mobile Home/Other	Existing		Passed	Passed	N/A	0	276	0
Residential	Central air conditioner - 50% cycling	Single Family	Existing		Passed	Passed	N/A	0	0	0
Residential	Central air conditioner - 50% cycling	Multi Family	Existing		Passed	Passed	N/A	0	0	0
Residential	Central air conditioner - 50% cycling	Mobile Home/Other	Existing		Passed	Passed	N/A	0	0	0
Residential	Central Heating - 50% cycling	Single Family	Existing		Passed	Passed	N/A	0	0	0
Residential	Central Heating - 50% cycling	Multi Family	Existing		Passed	Passed	N/A	0	0	0
Residential	Central Heating - 50% cycling	Mobile Home/Other	Existing		Passed	Passed	N/A	0	0	0
Residential	Water heater switches	Single Family	Existing		Passed	Passed	N/A	109	206	0
Residential	Water heater switches	Multi Family	Existing		Passed	Passed	N/A	57	107	0
Residential	Water heater switches	Mobile Home/Other	Existing		Passed	Passed	N/A	22	41	0
Residential	Pool pump switches	Single Family	Existing		Passed	Passed	N/A	181	76	0
Residential	Pool pump switches	Multi Family	Existing		Passed	Passed	N/A	0	0	0
Residential	Pool pump switches	Mobile Home/Other	Existing		Passed	Passed	N/A	0	0	0
Residential	Room AC control	Single Family	New		Passed	Passed	N/A	0	0	0
Residential	Room AC control	Multi Family	New		Passed	Passed	N/A	0	0	0
Residential	Room AC control	Mobile Home/Other	New		Passed	Passed	N/A	0	0	0
Residential	Smart thermostats - Utility Installation	Single Family	New		Passed	Passed	N/A	0	0	0
Residential	Smart thermostats - Utility Installation	Multi Family	New		Passed	Passed	N/A	0	0	0
Residential	Smart thermostats - Utility Installation	Mobile Home/Other	New		Passed	Passed	N/A	0	0	0
Residential	Smart thermostats - BYOT	Single Family	New		Passed	Passed	N/A	0	0	0
Residential	Smart thermostats - BYOT	Multi Family	New		Passed	Passed	N/A	0	0	0
Residential	Smart thermostats - BYOT	Mobile Home/Other	New		Passed	Passed	N/A	0	0	0
Residential	CPP + Tech	Single Family	New		Passed	Passed	N/A	0	0	0
Residential	CPP + Tech	Multi Family	New		Passed	Passed	N/A	0	0	0
Residential	CPP + Tech	Mobile Home/Other	New		Passed	Passed	N/A	0	0	0
Small C&I	Central air conditioner - Load Shed	0-15,000 kWh	New		Passed	Passed	N/A	64	0	0
Small C&I	Central air conditioner - Load Shed	15,001-25,000 kWh	New		Passed	Passed	N/A	17	0	0
Small C&I	Central air conditioner - Load Shed	25,001-50,000 kWh	New		Passed	Passed	N/A	11	0	0
Small C&I	Central air conditioner - Load Shed	50,001 kWh +	New		Passed	Passed	N/A	12	0	0
Small C&I	Central Heating - Load Shed	0-15,000 kWh	New		Passed	Passed	N/A	0	35	0
Small C&I	Central Heating - Load Shed	15,001-25,000 kWh	New		Passed	Passed	N/A	0	16	0
Small C&I	Central Heating - Load Shed	25,001-50,000 kWh	New		Passed	Passed	N/A	0	14	0
Small C&I	Central Heating - Load Shed	50,001 kWh +	New		Passed	Passed	N/A	0	8	0
Small C&I	Central air conditioner - 50% cycling	0-15,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	Central air conditioner - 50% cycling	15,001-25,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	Central air conditioner - 50% cycling	25,001-50,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	Central air conditioner - 50% cycling	50,001 kWh +	New		Passed	Passed	N/A	0	0	0
Small C&I	Central Heating - 50% cycling	0-15,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	Central Heating - 50% cycling	15,001-25,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	Central Heating - 50% cycling	25,001-50,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	Central Heating - 50% cycling	50,001 kWh +	New		Passed	Passed	N/A	0	0	0
Small C&I	Smart thermostats - Utility Installation	0-15,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	Smart thermostats - Utility Installation	15,001-25,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	Smart thermostats - Utility Installation	25,001-50,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	Smart thermostats - Utility Installation	50,001 kWh +	New		Passed	Passed	N/A	0	0	0
Small C&I	Smart thermostats - BYOT	0-15,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	Smart thermostats - BYOT	15,001-25,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	Smart thermostats - BYOT	25,001-50,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	Smart thermostats - BYOT	50,001 kWh +	New		Passed	Passed	N/A	0	0	0
Small C&I	CPP + Tech	0-15,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	CPP + Tech	15,001-25,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	CPP + Tech	25,001-50,000 kWh	New		Passed	Passed	N/A	0	0	0
Small C&I	CPP + Tech	50,001 kWh +	New		Passed	Passed	N/A	0	0	0
Large C&I	Auto DR	0-50 kW	New		Passed	Passed	N/A	503	537	0
Large C&I	Auto DR	51-300 kW	New		Passed	Passed	N/A	702	684	0
Large C&I	Auto DR	301-500 kW	New		Passed	Passed	N/A	174	160	0
Large C&I	Auto DR	501 kW +	Existing		Passed	Passed	N/A	374	334	0
Large C&I	CPP	0-50 kW	New		Passed	Passed	N/A	0	0	0
Large C&I	CPP	51-300 kW	New		Passed	Passed	N/A	0	0	0
Large C&I	CPP	301-500 kW	New		Passed	Passed	N/A	0	0	0
Large C&I	CPP	501 kW +	New		Passed	Passed	N/A	0	0	0
Large C&I	Firm Service Level	0-50 kW	New		Passed	Passed	N/A	0	0	0
Large C&I	Firm Service Level	51-300 kW	New		Passed	Passed	N/A	0	0	0
Large C&I	Firm Service Level	301-500 kW	New		Passed	Passed	N/A	0	0	0
Large C&I	Firm Service Level	501 kW +	Existing		Passed	Passed	N/A	0	0	0
Large C&I	Guaranteed Load Drop	0-50 kW	New		Passed	Passed	N/A	0	0	0
Large C&I	Guaranteed Load Drop	51-300 kW	New		Passed	Passed	N/A	0	0	0
Large C&I	Guaranteed Load Drop	301-500 kW	New		Passed	Passed	N/A	0	0	0

Residential	LED - 9W Flood (Exterior)	Single Family	New	N_SF_LED -	4.38	0.25	17.36	0	0	0	Fail RIM
Residential	LED - 9W Flood (Exterior)	Multi-Family	New	N_MF_LED -	4.38	0.25	17.36	0	0	0	Fail RIM
Residential	LED - 9W Flood (Exterior)	Manufactured Home	New	N_MH_LED	4.38	0.25	17.36	0	0	0	Fail RIM
Residential	LED - 9W Flood	Single Family	Turnover	T_SF_LED -	1.34	0.37	3.63	0	0	0	Fail RIM
Residential	LED - 9W Flood	Multi-Family	Turnover	T_MF_LED -	1.34	0.37	3.63	0	0	0	Fail RIM
Residential	LED - 9W Flood	Manufactured Home	Turnover	T_MH_LED -	1.34	0.37	3.63	0	0	0	Fail RIM
Residential	LED - 9W Flood	Single Family	New	N_SF_LED -	1.34	0.37	3.63	0	0	0	Fail RIM
Residential	LED - 9W Flood	Multi-Family	New	N_MF_LED -	1.34	0.37	3.63	0	0	0	Fail RIM
Residential	LED - 9W Flood	Manufactured Home	New	N_MH_LED	1.34	0.37	3.63	0	0	0	Fail RIM
Residential	LED - 9W	Single Family	Turnover	T_SF_LED -	3.02	0.37	8.14	0	0	0	Fail RIM
Residential	LED - 9W	Multi-Family	Turnover	T_MF_LED -	3.02	0.37	8.14	0	0	0	Fail RIM
Residential	LED - 9W	Manufactured Home	Turnover	T_MH_LED -	3.02	0.37	8.14	0	0	0	Fail RIM
Residential	LED - 9W	Single Family	New	N_SF_LED -	3.02	0.37	8.14	0	0	0	Fail RIM
Residential	LED - 9W	Multi-Family	New	N_MF_LED -	3.02	0.37	8.14	0	0	0	Fail RIM
Residential	LED - 9W	Manufactured Home	New	N_MH_LED	3.02	0.37	8.14	0	0	0	Fail RIM
Residential	LED Specialty Lamps-5W Chandelier	Single Family	Turnover	T_SF_LED S	1.43	0.37	3.86	0	0	0	Fail RIM
Residential	LED Specialty Lamps-5W Chandelier	Multi-Family	Turnover	T_MF_LED S	1.43	0.37	3.86	0	0	0	Fail RIM
Residential	LED Specialty Lamps-5W Chandelier	Manufactured Home	Turnover	T_MH_LED S	1.43	0.37	3.86	0	0	0	Fail RIM
Residential	LED Specialty Lamps-5W Chandelier	Single Family	New	N_SF_LED S	1.43	0.37	3.86	0	0	0	Fail RIM
Residential	LED Specialty Lamps-5W Chandelier	Multi-Family	New	N_MF_LED S	1.43	0.37	3.86	0	0	0	Fail RIM
Residential	LED Specialty Lamps-5W Chandelier	Manufactured Home	New	N_MH_LED	1.43	0.37	3.86	0	0	0	Fail RIM
Residential	Linear LED	Single Family	Turnover	T_SF_Linear	2.63	0.26	9.96	0	0	0	Fail RIM
Residential	Linear LED	Multi-Family	Turnover	T_MF_Linear	2.63	0.26	9.96	0	0	0	Fail RIM
Residential	Linear LED	Manufactured Home	Turnover	T_MH_Linear	2.63	0.26	9.96	0	0	0	Fail RIM
Residential	Linear LED	Single Family	New	N_SF_Linear	2.63	0.26	9.96	0	0	0	Fail RIM
Residential	Linear LED	Multi-Family	New	N_MF_Linear	2.63	0.26	9.96	0	0	0	Fail RIM
Residential	Linear LED	Manufactured Home	New	N_MH_Linea	2.63	0.26	9.96	0	0	0	Fail RIM
Residential	Low Wattage T8 Fixture	Single Family	Turnover	T_SF_Low W	5.51	0.26	20.86	0	0	0	Fail RIM
Residential	Low Wattage T8 Fixture	Multi-Family	Turnover	T_MF_Low W	5.51	0.26	20.86	0	0	0	Fail RIM
Residential	Low Wattage T8 Fixture	Manufactured Home	Turnover	T_MH_Low W	5.51	0.26	20.86	0	0	0	Fail RIM
Residential	Low Wattage T8 Fixture	Single Family	New	N_SF_Low W	5.51	0.26	20.86	0	0	0	Fail RIM
Residential	Low Wattage T8 Fixture	Multi-Family	New	N_MF_Low W	5.51	0.26	20.86	0	0	0	Fail RIM
Residential	Low Wattage T8 Fixture	Manufactured Home	New	N_MH_Low W	5.51	0.26	20.86	0	0	0	Fail RIM
Residential	Energy Star Bathroom Ventilating Fan	Single Family	Turnover	T_SF_Energy	0.22	0.43	0.50	0	0	0	Fail RIM
Residential	Energy Star Bathroom Ventilating Fan	Multi-Family	Turnover	T_MF_Energy	0.22	0.43	0.50	0	0	0	Fail RIM
Residential	Energy Star Bathroom Ventilating Fan	Manufactured Home	Turnover	T_MH_Energ	0.22	0.43	0.50	0	0	0	Fail RIM
Residential	Energy Star Bathroom Ventilating Fan	Single Family	New	N_SF_Energy	0.22	0.43	0.50	0	0	0	Fail RIM
Residential	Energy Star Bathroom Ventilating Fan	Multi-Family	New	N_MF_Energ	0.22	0.43	0.50	0	0	0	Fail RIM
Residential	Energy Star Bathroom Ventilating Fan	Manufactured Home	New	N_MH_Energ	0.22	0.43	0.50	0	0	0	Fail RIM
Residential	Energy Star Ceiling Fan	Single Family	Turnover	T_SF_Energy	0.23	0.27	0.86	0	0	0	Fail RIM
Residential	Energy Star Ceiling Fan	Multi-Family	Turnover	T_MF_Energy	0.23	0.27	0.86	0	0	0	Fail RIM
Residential	Energy Star Ceiling Fan	Manufactured Home	Turnover	T_MH_Energ	0.23	0.27	0.86	0	0	0	Fail RIM
Residential	Energy Star Ceiling Fan	Single Family	New	N_SF_Energy	0.23	0.27	0.86	0	0	0	Fail RIM
Residential	Energy Star Ceiling Fan	Multi-Family	New	N_MF_Energ	0.23	0.27	0.86	0	0	0	Fail RIM
Residential	Energy Star Ceiling Fan	Manufactured Home	New	N_MH_Energ	0.23	0.27	0.86	0	0	0	Fail RIM
Residential	Energy Star Dehumidifier	Single Family	Turnover	T_SF_Energy	6.55	0.51	12.88	0	0	0	Fail RIM
Residential	Energy Star Dehumidifier	Multi-Family	Turnover	T_MF_Energ	6.55	0.51	12.88	0	0	0	Fail RIM
Residential	Energy Star Dehumidifier	Manufactured Home	Turnover	T_MH_Energ	6.55	0.51	12.88	0	0	0	Fail RIM
Residential	Energy Star Dehumidifier	Single Family	New	N_SF_Energy	6.55	0.51	12.88	0	0	0	Fail RIM
Residential	Energy Star Dehumidifier	Multi-Family	New	N_MF_Energ	6.55	0.51	12.88	0	0	0	Fail RIM
Residential	Energy Star Dehumidifier	Manufactured Home	New	N_MH_Energ	6.03	0.51	11.87	0	0	0	Fail RIM
Residential	Heat Pump Pool Heater	Single Family	Turnover	T_SF_Heat P	3.49	0.23	15.00	0	0	0	Fail RIM
Residential	Heat Pump Pool Heater	Multi-Family	Turnover	T_MF_Heat P	3.49	0.23	15.00	0	0	0	Fail RIM
Residential	Heat Pump Pool Heater	Manufactured Home	Turnover	T_MH_Heat I	3.49	0.23	15.00	0	0	0	Fail RIM
Residential	Heat Pump Pool Heater	Single Family	New	N_SF_Heat P	3.49	0.23	15.00	0	0	0	Fail RIM
Residential	Heat Pump Pool Heater	Multi-Family	New	N_MF_Heat I	3.49	0.23	15.00	0	0	0	Fail RIM
Residential	Heat Pump Pool Heater	Manufactured Home	New	N_MH_Heat	3.49	0.23	15.00	0	0	0	Fail RIM
Residential	Solar Pool Heater	Single Family	Turnover	T_SF_Solar P	0.98	0.23	4.21	0	0	0	Fail RIM
Residential	Solar Pool Heater	Multi-Family	Turnover	T_MF_Solar	0.98	0.23	4.21	0	0	0	Fail RIM
Residential	Solar Pool Heater	Manufactured Home	Turnover	T_MH_Solar	0.98	0.23	4.21	0	0	0	Fail RIM
Residential	Solar Pool Heater	Single Family	New	N_SF_Solar P	0.98	0.23	4.21	0	0	0	Fail RIM
Residential	Solar Pool Heater	Multi-Family	New	N_MF_Solar	0.98	0.23	4.21	0	0	0	Fail RIM
Residential	Solar Pool Heater	Manufactured Home	New	N_MH_Solar	0.98	0.23	4.21	0	0	0	Fail RIM
Residential	Solar Powered Pool Pumps	Single Family	Turnover	T_SF_Solar P	0.46	0.47	0.99	0	0	0	Fail RIM
Residential	Solar Powered Pool Pumps	Multi-Family	Turnover	T_MF_Solar	0.46	0.47	0.99	0	0	0	Fail RIM
Residential	Solar Powered Pool Pumps	Manufactured Home	Turnover	T_MH_Solar	0.46	0.47	0.99	0	0	0	Fail RIM
Residential	Solar Powered Pool Pumps	Single Family	New	N_SF_Solar P	0.46	0.47	0.99	0	0	0	Fail RIM
Residential	Solar Powered Pool Pumps	Multi-Family	New	N_MF_Solar	0.46	0.47	0.99	0	0	0	Fail RIM
Residential	Solar Powered Pool Pumps	Manufactured Home	New	N_MH_Solar	0.46	0.47	0.99	0	0	0	Fail RIM
Residential	Two Speed Pool Pump	Single Family	Turnover	T_SF_Two Sp	1.40	0.47	2.99	0	0	0	Fail RIM
Residential	Two Speed Pool Pump	Multi-Family	Turnover	T_MF_Two S	1.40	0.47	2.99	0	0	0	Fail RIM
Residential	Two Speed Pool Pump	Manufactured Home	Turnover	T_MH_Two S	1.40	0.47	2.99	0	0	0	Fail RIM
Residential	Two Speed Pool Pump	Single Family	New	N_SF_Two Sp	1.40	0.47	2.99	0	0	0	Fail RIM
Residential	Two Speed Pool Pump	Multi-Family	New	N_MF_Two S	1.40	0.47	2.99	0	0	0	Fail RIM
Residential	Two Speed Pool Pump	Manufactured Home	New	N_MH_Two S	1.40	0.47	2.99	0	0	0	Fail RIM
Residential	Variable Speed Pool Pump	Single Family	Turnover	T_SF_Variabl	1.40	0.47	2.99	0	0	0	Fail RIM
Residential	Variable Speed Pool Pump	Multi-Family	Turnover	T_MF_Variab	1.40	0.47	2.99	0	0	0	Fail RIM
Residential	Variable Speed Pool Pump	Manufactured Home	Turnover	T_MH_Variab	1.40	0.47	2.99	0	0	0	Fail RIM
Residential	Variable Speed Pool Pump	Single Family	New	N_SF_Variab	1.40	0.47	2.99	0	0	0	Fail RIM
Residential	Variable Speed Pool Pump	Multi-Family	New	N_MF_Variab	1.40	0.47	2.99	0	0	0	Fail RIM
Residential	Variable Speed Pool Pump	Manufactured Home	New	N_MH_Varia	1.40	0.47	2.99	0	0	0	Fail RIM
Residential	Removal of 2nd Refrigerator-Freezer	Single Family	Existing	E_SF_Remov	4.12	0.36	11.53	0	0	0	Fail RIM
Residential	Removal of 2nd Refrigerator-Freezer	Multi-Family	Existing	E_MF_Remov	4.12	0.36	11.53	0	0	0	Fail RIM
Residential	Removal of 2nd Refrigerator-Freezer	Manufactured Home	Existing	E_MH_Remo	4.12	0.36	11.53	0	0	0	Fail RIM
Residential	Removal of 2nd Refrigerator-Freezer	Single Family	New	N_SF_Remov	4.12	0.36	11.53	0	0	0	Fail RIM
Residential	Removal of 2nd Refrigerator-Freezer	Multi-Family	New	N_MF_Remo	4.12	0.36	11.53	0	0	0	Fail RIM
Residential	Removal of 2nd Refrigerator-Freezer	Manufactured Home	New	N_MH_Remo	4.12	0.36	11.53	0	0	0	Fail RIM
Residential	Drain Water Heat Recovery	Single Family	Existing	E_SF_Drain W	0.18	0.55	0.34	0	0	0	Fail RIM
Residential	Drain Water Heat Recovery	Multi-Family	Existing	E_MF_Drain	0.16	0.55	0.29	0	0	0	Fail RIM
Residential	Drain Water Heat Recovery	Manufactured Home	Existing	E_MH_Drain	0.23	0.55	0.42	0	0	0	Fail RIM
Residential	Drain Water Heat Recovery	Single Family	New	N_SF_Drain W	0.23	0.55	0.42	0	0	0	Fail RIM
Residential	Drain Water Heat Recovery	Multi-Family	New	N_MF_Drain	0.20	0.55	0.36	0	0	0	Fail RIM
Residential	Drain Water Heat Recovery	Manufactured Home	New	N_MH_Drain	0.29	0.55	0.53	0	0	0	Fail RIM
Residential	Faucet Aerator	Single Family	Existing	E_SF_Faucet	11.91	0.50	23.79	0	0	0	Fail RIM
Residential	Faucet Aerator	Multi-Family	Existing	E_MF_Fauce	9.36	0.50	18.70	0	0	0	Fail RIM
Residential	Faucet Aerator	Manufactured Home	Existing	E_MH_Fauce	9.29	0.50	18.56	0	0	0	Fail RIM
Residential	Faucet Aerator	Single Family	New	N_SF_Faucet	4.96	0.50	9.91	0	0	0	Fail RIM
Residential	Faucet Aerator	Multi-Family	New	N_MF_Fauce	3.90	0.50	7.79	0	0	0	Fail RIM
Residential	Faucet Aerator	Manufactured Home	New	N_MH_Fauce	3.87	0.50	7.73	0	0	0	Fail RIM
Residential	Heat Trap	Single Family	Existing	E_SF_Heat T	0.58	0.50	1.16	0	0	0	Fail RIM
Residential	Heat Trap	Multi-Family	Existing	E_MF_Heat T	0.46	0.50	0.91	0	0	0	Fail RIM
Residential	Heat Trap	Manufactured Home	Existing	E_MH_Heat T	0.45	0.50	0.91	0	0	0	Fail RIM
Residential	Heat Trap	Single Family	New	N_SF_Heat T	0.58	0.50	1.16	0	0	0	Fail RIM
Residential	Heat Trap	Multi-Family	New	N_MF_Heat T	0.46	0.50	0.91	0	0	0	Fail RIM

Commercial	Energy Star Uninterruptable Power Supply	Grocery	New	N_GR_Energ	1.32	0.48	2.73	0	0	0
Commercial	Demand Controlled Ventilation	Grocery	New	N_GR_Demar	1.40	1.25	1.12	0	0	0
Commercial	Demand Controlled Ventilation	Grocery	Existing	E_GR_Demar	1.40	1.25	1.12	0	1	1
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Grocery	Turnover	T_GR_High E	1.21	0.89	1.37	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Grocery	Turnover	T_GR_High E	1.41	1.17	1.21	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Grocery	New	N_GR_High E	1.21	0.89	1.37	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Grocery	New	N_GR_High E	1.41	1.17	1.21	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Grocery	Turnover	T_GR_Energy	2.78	0.58	4.78	11	5	76
Commercial	Energy Star Commercial Solid Door Refrigerator	Grocery	New	N_GR_Energ	2.78	0.58	4.78	0	0	1
Commercial	Efficient Exhaust Hood	Grocery	Turnover	T_GR_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Grocery	Turnover	T_GR_Energy	1.28	0.65	1.97	0	0	0
Commercial	Efficient Exhaust Hood	Grocery	New	N_GR_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Grocery	New	N_GR_Energ	1.28	0.65	1.97	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Healthcare	New	N_HC_PSC to	1.15	0.56	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Healthcare	New	N_HC_PSC to	1.77	0.56	3.15	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Healthcare	Existing	E_HC_PSC to	1.15	0.56	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Healthcare	Existing	E_HC_PSC to	1.77	0.56	3.15	0	0	0
Commercial	Facility Energy Management System	Healthcare	New	N_HC_Facilit	4.14	0.73	5.67	0	0	0
Commercial	Facility Energy Management System	Healthcare	Existing	E_HC_Facilit	4.14	0.73	5.67	0	0	0
Commercial	Thermal Energy Storage	Healthcare	New	N_HC_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Smart Thermostat	Healthcare	New	N_HC_Smart	1.13	0.30	3.72	0	0	0
Commercial	HVAC tune-up_RTU	Healthcare	New	N_HC_HVAC	1.72	0.84	2.06	0	0	0
Commercial	Dedicated Outdoor Air System on VRF unit	Healthcare	New	N_HC_Dedica	1.69	0.89	1.91	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Healthcare	New	N_HC_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Healthcare	New	N_HC_Ceilin	4.58	1.22	3.76	0	0	0
Commercial	Wall Insulation	Healthcare	Existing	E_HC_Wall I	3.27	1.22	2.69	0	0	3
Commercial	Thermal Energy Storage	Healthcare	Existing	E_HC_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Smart Thermostat	Healthcare	Existing	E_HC_Smart	1.13	0.30	3.72	0	0	7
Commercial	Low U-Value Windows	Healthcare	Existing	E_HC_Low U	1.46	1.12	1.31	2	0	6
Commercial	HVAC tune-up_RTU	Healthcare	Existing	E_HC_HVAC	1.72	0.84	2.06	3	0	8
Commercial	Dedicated Outdoor Air System on VRF unit	Healthcare	Existing	E_HC_Dedica	1.69	0.89	1.91	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Healthcare	Existing	E_HC_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Healthcare	Existing	E_HC_Ceiling	4.67	1.22	3.83	0	0	10
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Healthcare	Turnover	T_HC_Variab	1.73	0.89	1.95	0	0	1
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Healthcare	New	N_HC_Variab	1.73	0.89	1.95	0	0	0
Commercial	VSD Controlled Compressor	Healthcare	New	N_HC_VSD C	2.06	0.56	3.66	0	0	0
Commercial	VSD Controlled Compressor	Healthcare	Existing	E_HC_VSD C	2.06	0.56	3.66	0	0	1
Commercial	Variable Speed Pool Pump	Healthcare	Turnover	T_HC_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Healthcare	Turnover	T_HC_Solar I	1.08	0.33	3.23	0	0	0
Commercial	Variable Speed Pool Pump	Healthcare	New	N_HC_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Healthcare	New	N_HC_Solar	1.08	0.33	3.23	0	0	0
Commercial	High Efficiency DX 135k- less than 240k BTU	Healthcare	Turnover	T_HC_High E	1.51	1.18	1.28	3	0	7
Commercial	High Efficiency DX 135k- less than 240k BTU	Healthcare	New	N_HC_High E	1.51	1.18	1.28	0	0	0
Commercial	Premium T8 - Fixture Replacement	Healthcare	Turnover	T_HC_Premiu	1.11	0.65	1.72	0	0	2
Commercial	Premium T8 - Fixture Replacement	Healthcare	New	N_HC_Premiu	1.11	0.65	1.72	0	0	0
Commercial	Efficient Battery Charger	Healthcare	Turnover	T_HC_Efficie	1.63	1.02	1.59	1	0	2
Commercial	Efficient Battery Charger	Healthcare	New	N_HC_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Healthcare	Turnover	T_HC_Energy	1.32	0.48	2.73	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Healthcare	New	N_HC_Energ	1.32	0.48	2.73	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Healthcare	Turnover	T_HC_High E	4.78	0.89	5.39	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Healthcare	Turnover	T_HC_High E	3.23	1.17	2.77	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Healthcare	Turnover	T_HC_High E	5.55	1.17	4.76	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Healthcare	New	N_HC_High E	4.78	0.89	5.39	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Healthcare	New	N_HC_High E	3.23	1.17	2.77	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Healthcare	New	N_HC_High E	5.55	1.17	4.76	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Healthcare	Turnover	T_HC_Energy	2.59	0.54	4.78	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Healthcare	New	N_HC_Energ	2.59	0.54	4.78	0	0	0
Commercial	Efficient Exhaust Hood	Healthcare	Turnover	T_HC_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Healthcare	Turnover	T_HC_Energy	1.28	0.65	1.97	0	0	0
Commercial	Efficient Exhaust Hood	Healthcare	New	N_HC_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Healthcare	New	N_HC_Energ	1.28	0.65	1.97	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Hospitals	New	N_HS_PSC to	1.15	0.56	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Hospitals	New	N_HS_PSC to	1.77	0.56	3.15	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Hospitals	Existing	E_HS_PSC to	1.15	0.56	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Hospitals	Existing	E_HS_PSC to	1.77	0.56	3.15	0	0	0
Commercial	Facility Energy Management System	Hospitals	New	N_HS_Facilit	3.41	0.60	5.67	0	0	0
Commercial	Facility Energy Management System	Hospitals	Existing	E_HS_Facilit	3.41	0.60	5.67	1	0	4
Commercial	Thermal Energy Storage	Hospitals	New	N_HS_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Smart Thermostat	Hospitals	New	N_HS_Smart	1.73	0.44	3.92	0	0	0
Commercial	HVAC tune-up_RTU	Hospitals	New	N_HS_HVAC	1.63	0.84	1.95	0	0	0
Commercial	Dedicated Outdoor Air System on VRF unit	Hospitals	New	N_HS_Dedica	1.61	0.89	1.82	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Hospitals	New	N_HS_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Hospitals	New	N_HS_Ceiling	4.55	1.21	3.76	0	0	0
Commercial	Wall Insulation	Hospitals	Existing	E_HS_Wall In	3.35	1.21	2.76	0	0	0
Commercial	Thermal Energy Storage	Hospitals	Existing	E_HS_Therm	2.46	9999.00	9999.00	13	4	-2
Commercial	Smart Thermostat	Hospitals	Existing	E_HS_Smart	1.73	0.44	3.92	1	0	8
Commercial	Low U-Value Windows	Hospitals	Existing	E_HS_Low U	1.46	1.12	1.31	2	0	6
Commercial	HVAC tune-up_RTU	Hospitals	Existing	E_HS_HVAC	1.63	0.84	1.95	1	0	3
Commercial	Dedicated Outdoor Air System on VRF unit	Hospitals	Existing	E_HS_Dedica	1.61	0.89	1.82	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Hospitals	Existing	E_HS_Chille	2.43	0.52	4.69	1	0	11
Commercial	Ceiling Insulation(R2 to R38)	Hospitals	Existing	E_HS_Ceiling	4.64	1.21	3.83	0	0	0
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Hospitals	Turnover	T_HS_Variab	1.65	0.89	1.86	0	0	0
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Hospitals	New	N_HS_Variab	1.65	0.89	1.86	0	0	0
Commercial	ECM Motors on Furnaces	Hospitals	New	N_HS_ECM I	2.18	0.56	3.90	0	0	0
Commercial	ECM Motors on Furnaces	Hospitals	Existing	E_HS_ECM I	2.18	0.56	3.90	0	0	0
Commercial	VSD Controlled Compressor	Hospitals	New	N_HS_VSD C	2.06	0.56	3.66	0	0	0
Commercial	VSD Controlled Compressor	Hospitals	Existing	E_HS_VSD C	2.06	0.56	3.66	0	0	1
Commercial	Variable Speed Pool Pump	Hospitals	Turnover	T_HS_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Hospitals	Turnover	T_HS_Solar I	1.08	0.33	3.23	0	0	0
Commercial	Variable Speed Pool Pump	Hospitals	New	N_HS_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Hospitals	New	N_HS_Solar I	1.08	0.33	3.23	0	0	0
Commercial	High Efficiency DX 135k- less than 240k BTU	Hospitals	Turnover	T_HS_High E	1.43	1.18	1.22	1	0	3
Commercial	High Efficiency DX 135k- less than 240k BTU	Hospitals	New	N_HS_High E	1.43	1.18	1.22	0	0	0
Commercial	Premium T8 - Fixture Replacement	Hospitals	Turnover	T_HS_Premiu	1.01	0.43	2.33	0	0	2
Commercial	Premium T8 - Fixture Replacement	Hospitals	New	N_HS_Premiu	1.01	0.43	2.33	0	0	0
Commercial	Efficient Battery Charger	Hospitals	Turnover	T_HS_Efficie	1.63	1.02	1.59	1	0	2
Commercial	Efficient Battery Charger	Hospitals	New	N_HS_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Hospitals	Turnover	T_HS_Energy	1.32	0.48	2.73	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Hospitals	New	N_HS_Energ	1.32	0.48	2.73	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Hospitals	Turnover	T_HS_High E	4.53	0.89	5.11	1	0	5
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Hospitals	Turnover	T_HS_High E	3.06	1.17	2.62	1	0	2
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Hospitals	Turnover	T_HS_High E	5.26	1.17	4.50	1	0	3
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Hospitals	New	N_HS_High E	4.53	0.89	5.11	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Hospitals	New	N_HS_High E	3.06	1.17	2.62	0	0	0

Residential	Linear LED	Single Family	New	N_SF_Linear	2.63	0.26	9.96	0	0	0	Fail 2-year Threshold
Residential	Linear LED	Multi-Family	New	N_MF_Linear	2.63	0.26	9.96	0	0	0	Fail 2-year Threshold
Residential	Linear LED	Manufactured Home	New	N_MH_Linea	2.63	0.26	9.96	0	0	0	Fail 2-year Threshold
Residential	Low Wattage T8 Fixture	Single Family	Turnover	T_SF_Low W	5.51	0.26	20.86	0	0	0	Fail 2-year Threshold
Residential	Low Wattage T8 Fixture	Multi-Family	Turnover	T_MF_Low W	5.51	0.26	20.86	0	0	0	Fail 2-year Threshold
Residential	Low Wattage T8 Fixture	Manufactured Home	Turnover	T_MH_Low W	5.51	0.26	20.86	0	0	0	Fail 2-year Threshold
Residential	Low Wattage T8 Fixture	Single Family	New	N_SF_Low W	5.51	0.26	20.86	0	0	0	Fail 2-year Threshold
Residential	Low Wattage T8 Fixture	Multi-Family	New	N_MF_Low W	5.51	0.26	20.86	0	0	0	Fail 2-year Threshold
Residential	Low Wattage T8 Fixture	Manufactured Home	New	N_MH_Low W	5.51	0.26	20.86	0	0	0	Fail 2-year Threshold
Residential	Energy Star Bathroom Ventilating Fan	Single Family	Turnover	T_SF_Energy	0.22	0.43	0.50	0	0	0	Fail TRC
Residential	Energy Star Bathroom Ventilating Fan	Multi-Family	Turnover	T_MF_Energy	0.22	0.43	0.50	0	0	0	Fail TRC
Residential	Energy Star Bathroom Ventilating Fan	Manufactured Home	Turnover	T_MH_Energ	0.22	0.43	0.50	0	0	0	Fail TRC
Residential	Energy Star Bathroom Ventilating Fan	Single Family	New	N_SF_Energy	0.22	0.43	0.50	0	0	0	Fail TRC
Residential	Energy Star Bathroom Ventilating Fan	Multi-Family	New	N_MF_Energ	0.22	0.43	0.50	0	0	0	Fail TRC
Residential	Energy Star Bathroom Ventilating Fan	Manufactured Home	New	N_MH_Energ	0.22	0.43	0.50	0	0	0	Fail TRC
Residential	Energy Star Ceiling Fan	Single Family	Turnover	T_SF_Energy	0.23	0.27	0.86	0	0	0	Fail TRC
Residential	Energy Star Ceiling Fan	Multi-Family	Turnover	T_MF_Energy	0.23	0.27	0.86	0	0	0	Fail TRC
Residential	Energy Star Ceiling Fan	Manufactured Home	Turnover	T_MH_Energ	0.23	0.27	0.86	0	0	0	Fail TRC
Residential	Energy Star Ceiling Fan	Single Family	New	N_SF_Energy	0.23	0.27	0.86	0	0	0	Fail TRC
Residential	Energy Star Ceiling Fan	Multi-Family	New	N_MF_Energ	0.23	0.27	0.86	0	0	0	Fail TRC
Residential	Energy Star Ceiling Fan	Manufactured Home	New	N_MH_Energ	0.23	0.27	0.86	0	0	0	Fail TRC
Residential	Energy Star Dehumidifier	Single Family	Turnover	T_SF_Energy	6.55	0.51	12.88	0	0	0	Fail 2-year Threshold
Residential	Energy Star Dehumidifier	Multi-Family	Turnover	T_MF_Energ	6.55	0.51	12.88	0	0	0	Fail 2-year Threshold
Residential	Energy Star Dehumidifier	Manufactured Home	Turnover	T_MH_Energ	6.55	0.51	12.88	0	0	0	Fail 2-year Threshold
Residential	Energy Star Dehumidifier	Single Family	New	N_SF_Energy	6.55	0.51	12.88	0	0	0	Fail 2-year Threshold
Residential	Energy Star Dehumidifier	Multi-Family	New	N_MF_Energ	6.55	0.51	12.88	0	0	0	Fail 2-year Threshold
Residential	Energy Star Dehumidifier	Manufactured Home	New	N_MH_Energ	6.03	0.51	11.87	0	0	0	Fail 2-year Threshold
Residential	Heat Pump Pool Heater	Single Family	Turnover	T_SF_Heat P	3.49	0.23	15.00	0	0	0	Fail 2-year Threshold
Residential	Heat Pump Pool Heater	Multi-Family	Turnover	T_MF_Heat P	3.49	0.23	15.00	0	0	0	Fail 2-year Threshold
Residential	Heat Pump Pool Heater	Manufactured Home	Turnover	T_MH_Heat I	3.49	0.23	15.00	0	0	0	Fail 2-year Threshold
Residential	Heat Pump Pool Heater	Single Family	New	N_SF_Heat P	3.49	0.23	15.00	0	0	0	Fail 2-year Threshold
Residential	Heat Pump Pool Heater	Multi-Family	New	N_MF_Heat I	3.49	0.23	15.00	0	0	0	Fail 2-year Threshold
Residential	Heat Pump Pool Heater	Manufactured Home	New	N_MH_Heat I	3.49	0.23	15.00	0	0	0	Fail 2-year Threshold
Residential	Solar Pool Heater	Single Family	Turnover	T_SF_Solar P	0.98	0.23	4.21	0	0	0	Fail TRC
Residential	Solar Pool Heater	Multi-Family	Turnover	T_MF_Solar	0.98	0.23	4.21	0	0	0	Fail TRC
Residential	Solar Pool Heater	Manufactured Home	Turnover	T_MH_Solar	0.98	0.23	4.21	0	0	0	Fail TRC
Residential	Solar Pool Heater	Single Family	New	N_SF_Solar P	0.98	0.23	4.21	0	0	0	Fail TRC
Residential	Solar Pool Heater	Multi-Family	New	N_MF_Solar	0.98	0.23	4.21	0	0	0	Fail TRC
Residential	Solar Pool Heater	Manufactured Home	New	N_MH_Solar	0.98	0.23	4.21	0	0	0	Fail TRC
Residential	Solar Powered Pool Pumps	Single Family	Turnover	T_SF_Solar P	0.46	0.47	0.99	0	0	0	Fail TRC
Residential	Solar Powered Pool Pumps	Multi-Family	Turnover	T_MF_Solar	0.46	0.47	0.99	0	0	0	Fail TRC
Residential	Solar Powered Pool Pumps	Manufactured Home	Turnover	T_MH_Solar	0.46	0.47	0.99	0	0	0	Fail TRC
Residential	Solar Powered Pool Pumps	Single Family	New	N_SF_Solar P	0.46	0.47	0.99	0	0	0	Fail TRC
Residential	Solar Powered Pool Pumps	Multi-Family	New	N_MF_Solar	0.46	0.47	0.99	0	0	0	Fail TRC
Residential	Solar Powered Pool Pumps	Manufactured Home	New	N_MH_Solar	0.46	0.47	0.99	0	0	0	Fail TRC
Residential	Removal of 2nd Refrigerator-Freezer	Single Family	Existing	E_SF_Remov	4.12	0.36	11.53	0	0	0	Fail 2-year Threshold
Residential	Removal of 2nd Refrigerator-Freezer	Multi-Family	Existing	E_MF_Remov	4.12	0.36	11.53	0	0	0	Fail 2-year Threshold
Residential	Removal of 2nd Refrigerator-Freezer	Manufactured Home	Existing	E_MH_Remo	4.12	0.36	11.53	0	0	0	Fail 2-year Threshold
Residential	Removal of 2nd Refrigerator-Freezer	Single Family	New	N_SF_Remov	4.12	0.36	11.53	0	0	0	Fail 2-year Threshold
Residential	Removal of 2nd Refrigerator-Freezer	Multi-Family	New	N_MF_Remo	4.12	0.36	11.53	0	0	0	Fail 2-year Threshold
Residential	Removal of 2nd Refrigerator-Freezer	Manufactured Home	New	N_MH_Remo	4.12	0.36	11.53	0	0	0	Fail 2-year Threshold
Residential	Drain Water Heat Recovery	Single Family	Existing	E_SF_Drain W	0.18	0.55	0.34	0	0	0	Fail TRC
Residential	Drain Water Heat Recovery	Multi-Family	Existing	E_MF_Drain	0.16	0.55	0.29	0	0	0	Fail TRC
Residential	Drain Water Heat Recovery	Manufactured Home	Existing	E_MH_Drain	0.23	0.55	0.42	0	0	0	Fail TRC
Residential	Drain Water Heat Recovery	Single Family	New	N_SF_Drain W	0.23	0.55	0.42	0	0	0	Fail TRC
Residential	Drain Water Heat Recovery	Multi-Family	New	N_MF_Drain	0.20	0.55	0.36	0	0	0	Fail TRC
Residential	Drain Water Heat Recovery	Manufactured Home	New	N_MH_Drain	0.29	0.55	0.53	0	0	0	Fail TRC
Residential	Faucet Aerator	Single Family	Existing	E_SF_Faucet	11.91	0.50	23.79	0	0	0	Fail 2-year Threshold
Residential	Faucet Aerator	Multi-Family	Existing	E_MF_Fauce	9.36	0.50	18.70	0	0	0	Fail 2-year Threshold
Residential	Faucet Aerator	Manufactured Home	Existing	E_MH_Fauce	9.29	0.50	18.56	0	0	0	Fail 2-year Threshold
Residential	Faucet Aerator	Single Family	New	N_SF_Faucet	4.96	0.50	9.91	0	0	0	Fail 2-year Threshold
Residential	Faucet Aerator	Multi-Family	New	N_MF_Fauce	3.90	0.50	7.79	0	0	0	Fail 2-year Threshold
Residential	Faucet Aerator	Manufactured Home	New	N_MH_Fauce	3.87	0.50	7.73	0	0	0	Fail 2-year Threshold
Residential	Heat Trap	Single Family	Existing	E_SF_Heat T	0.58	0.50	1.16	0	0	0	Fail TRC
Residential	Heat Trap	Multi-Family	Existing	E_MF_Heat T	0.46	0.50	0.91	0	0	0	Fail TRC
Residential	Heat Trap	Manufactured Home	Existing	E_MH_Heat T	0.45	0.50	0.91	0	0	0	Fail TRC
Residential	Heat Trap	Single Family	New	N_SF_Heat T	0.58	0.50	1.16	0	0	0	Fail TRC
Residential	Heat Trap	Multi-Family	New	N_MF_Heat T	0.46	0.50	0.91	0	0	0	Fail TRC
Residential	Heat Trap	Manufactured Home	New	N_MH_Heat T	0.45	0.50	0.91	0	0	0	Fail TRC
Residential	Hot Water Pipe Insulation	Single Family	Existing	E_SF_Hot Wa	5.69	0.54	10.56	0	0	0	Fail 2-year Threshold
Residential	Hot Water Pipe Insulation	Multi-Family	Existing	E_MF_Hot W	4.87	0.54	9.05	0	0	0	Fail 2-year Threshold
Residential	Hot Water Pipe Insulation	Manufactured Home	Existing	E_MH_Hot W	7.21	0.54	13.39	0	0	0	Fail 2-year Threshold
Residential	Hot Water Pipe Insulation	Single Family	New	N_SF_Hot W	5.69	0.54	10.56	0	0	0	Fail 2-year Threshold
Residential	Hot Water Pipe Insulation	Multi-Family	New	N_MF_Hot W	4.87	0.54	9.05	0	0	0	Fail 2-year Threshold
Residential	Hot Water Pipe Insulation	Manufactured Home	New	N_MH_Hot W	7.21	0.54	13.39	0	0	0	Fail 2-year Threshold
Residential	Low Flow Showerhead	Single Family	Existing	E_SF_Low Fl	18.89	0.48	39.40	0	0	0	Fail 2-year Threshold
Residential	Low Flow Showerhead	Multi-Family	Existing	E_MF_Low F	14.85	0.48	30.97	0	0	0	Fail 2-year Threshold
Residential	Low Flow Showerhead	Manufactured Home	Existing	E_MH_Low F	14.73	0.48	30.72	0	0	0	Fail 2-year Threshold
Residential	Low Flow Showerhead	Single Family	New	N_SF_Low Fl	18.89	0.48	39.40	0	0	0	Fail 2-year Threshold
Residential	Low Flow Showerhead	Multi-Family	New	N_MF_Low F	14.85	0.48	30.97	0	0	0	Fail 2-year Threshold
Residential	Low Flow Showerhead	Manufactured Home	New	N_MH_Low F	14.73	0.48	30.72	0	0	0	Fail 2-year Threshold
Residential	Water Heater Blanket	Single Family	Existing	E_SF_Water	0.51	0.43	1.17	0	0	0	Fail TRC
Residential	Water Heater Blanket	Multi-Family	Existing	E_MF_Water	0.51	0.43	1.17	0	0	0	Fail TRC
Residential	Water Heater Blanket	Manufactured Home	Existing	E_MH_Water	0.51	0.43	1.17	0	0	0	Fail TRC
Residential	Water Heater Blanket	Single Family	New	N_SF_Water	0.48	0.43	1.12	0	0	0	Fail TRC
Residential	Water Heater Blanket	Multi-Family	New	N_MF_Water	0.48	0.43	1.12	0	0	0	Fail TRC
Residential	Water Heater Blanket	Manufactured Home	New	N_MH_Water	0.48	0.43	1.12	0	0	0	Fail TRC
Residential	Water Heater Thermostat Setback	Single Family	Existing	E_SF_Water	4.23	0.43	9.91	0	0	0	Fail 2-year Threshold
Residential	Water Heater Thermostat Setback	Multi-Family	Existing	E_MF_Water	4.23	0.43	9.91	0	0	0	Fail 2-year Threshold
Residential	Water Heater Thermostat Setback	Manufactured Home	Existing	E_MH_Water	4.23	0.43	9.91	0	0	0	Fail 2-year Threshold
Residential	Water Heater Thermostat Setback	Single Family	New	N_SF_Water	4.23	0.43	9.91	0	0	0	Fail 2-year Threshold
Residential	Water Heater Thermostat Setback	Multi-Family	New	N_MF_Water	4.23	0.43	9.91	0	0	0	Fail 2-year Threshold
Residential	Water Heater Thermostat Setback	Manufactured Home	New	N_MH_Water	4.23	0.43	9.91	0	0	0	Fail 2-year Threshold
Residential	Water Heater Timeclock	Single Family	Existing	E_SF_Water	0.12	0.24	0.50	0	0	0	Fail TRC
Residential	Water Heater Timeclock	Multi-Family	Existing	E_MF_Water	0.10	0.24	0.43	0	0	0	Fail TRC
Residential	Water Heater Timeclock	Manufactured Home	Existing	E_MH_Water	0.15	0.24	0.64	0	0	0	Fail TRC
Residential	Water Heater Timeclock	Single Family	New	N_SF_Water	0.12	0.24	0.50	0	0	0	Fail TRC
Residential	Water Heater Timeclock	Multi-Family	New	N_MF_Water	0.10	0.24	0.43	0	0	0	Fail TRC
Residential	Water Heater Timeclock	Manufactured Home	New	N_MH_Water	0.15	0.24	0.64	0	0	0	Fail TRC
Residential	Smart Power Strip	Single Family	Existing	E_SF_Smart I	1.04	0.35	2.95	0	0	0	Fail 2-year Threshold
Residential	Smart Power Strip	Multi-Family	Existing	E_MF_Smart	1.04	0.35	2.95	0	0	0	Fail 2-year Threshold
Residential	Smart Power Strip	Manufactured Home	Existing	E_MH_Smart	1.04	0.35	2.95	0	0	0	Fail 2-year Threshold
Residential	Smart Power Strip	Single Family	New	N_SF_Smart	1.04	0.35	2.95	0	0	0	Fail 2-year Threshold
Residential	Smart Power Strip	Multi-Family	New	N_MF_Smart	1.04	0.35	2.95	0	0	0	Fail 2-year Threshold

Large C&I	Guaranteed Load Drop	501 kW +	Existing		Passed	Passed	N/A	0	0	0

Residential	Heat Trap	Manufactured Home	New	N_MH_Heat	0.45	0.50	0.91	0	0	0	Fail RIM
Residential	Hot Water Pipe Insulation	Single Family	Existing	E_SF_Hot W	5.69	0.54	10.56	0	0	0	Fail RIM
Residential	Hot Water Pipe Insulation	Multi-Family	Existing	E_MF_Hot W	4.87	0.54	9.05	0	0	0	Fail RIM
Residential	Hot Water Pipe Insulation	Manufactured Home	Existing	E_MH_Hot W	7.21	0.54	13.39	0	0	0	Fail RIM
Residential	Hot Water Pipe Insulation	Single Family	New	N_SF_Hot W	5.69	0.54	10.56	0	0	0	Fail RIM
Residential	Hot Water Pipe Insulation	Multi-Family	New	N_MF_Hot W	4.87	0.54	9.05	0	0	0	Fail RIM
Residential	Hot Water Pipe Insulation	Manufactured Home	New	N_MH_Hot W	7.21	0.54	13.39	0	0	0	Fail RIM
Residential	Low Flow Showerhead	Single Family	Existing	E_SF_Low Fl	18.89	0.48	39.40	0	0	0	Fail RIM
Residential	Low Flow Showerhead	Multi-Family	Existing	E_MF_Low F	14.85	0.48	30.97	0	0	0	Fail RIM
Residential	Low Flow Showerhead	Manufactured Home	Existing	E_MH_Low F	14.73	0.48	30.72	0	0	0	Fail RIM
Residential	Low Flow Showerhead	Single Family	New	N_SF_Low F	18.89	0.48	39.40	0	0	0	Fail RIM
Residential	Low Flow Showerhead	Multi-Family	New	N_MF_Low F	14.85	0.48	30.97	0	0	0	Fail RIM
Residential	Low Flow Showerhead	Manufactured Home	New	N_MH_Low F	14.73	0.48	30.72	0	0	0	Fail RIM
Residential	Thermostatic Shower Restriction Valve	Single Family	Existing	E_SF_Therm	1.59	0.50	3.17	0	0	0	Fail RIM
Residential	Thermostatic Shower Restriction Valve	Multi-Family	Existing	E_MF_Therm	1.25	0.50	2.49	0	0	0	Fail RIM
Residential	Thermostatic Shower Restriction Valve	Manufactured Home	Existing	E_MH_Therm	1.24	0.50	2.47	0	0	0	Fail RIM
Residential	Thermostatic Shower Restriction Valve	Single Family	New	N_SF_Therm	1.59	0.50	3.17	0	0	0	Fail RIM
Residential	Thermostatic Shower Restriction Valve	Multi-Family	New	N_MF_Therm	1.25	0.50	2.49	0	0	0	Fail RIM
Residential	Thermostatic Shower Restriction Valve	Manufactured Home	New	N_MH_Therm	1.24	0.50	2.47	0	0	0	Fail RIM
Residential	Water Heater Blanket	Single Family	Existing	E_SF_Water	0.51	0.43	1.17	0	0	0	Fail RIM
Residential	Water Heater Blanket	Multi-Family	Existing	E_MF_Water	0.51	0.43	1.17	0	0	0	Fail RIM
Residential	Water Heater Blanket	Manufactured Home	Existing	E_MH_Water	0.51	0.43	1.17	0	0	0	Fail RIM
Residential	Water Heater Blanket	Single Family	New	N_SF_Water	0.48	0.43	1.12	0	0	0	Fail RIM
Residential	Water Heater Blanket	Multi-Family	New	N_MF_Water	0.48	0.43	1.12	0	0	0	Fail RIM
Residential	Water Heater Blanket	Manufactured Home	New	N_MH_Water	0.48	0.43	1.12	0	0	0	Fail RIM
Residential	Water Heater Thermostat Setback	Single Family	Existing	E_SF_Water	4.23	0.43	9.91	0	0	0	Fail RIM
Residential	Water Heater Thermostat Setback	Multi-Family	Existing	E_MF_Water	4.23	0.43	9.91	0	0	0	Fail RIM
Residential	Water Heater Thermostat Setback	Manufactured Home	Existing	E_MH_Water	4.23	0.43	9.91	0	0	0	Fail RIM
Residential	Water Heater Thermostat Setback	Single Family	New	N_SF_Water	4.23	0.43	9.91	0	0	0	Fail RIM
Residential	Water Heater Thermostat Setback	Multi-Family	New	N_MF_Water	4.23	0.43	9.91	0	0	0	Fail RIM
Residential	Water Heater Thermostat Setback	Manufactured Home	New	N_MH_Water	4.23	0.43	9.91	0	0	0	Fail RIM
Residential	Water Heater Timeclock	Single Family	Existing	E_SF_Water	0.12	0.24	0.50	0	0	0	Fail RIM
Residential	Water Heater Timeclock	Multi-Family	Existing	E_MF_Water	0.10	0.24	0.43	0	0	0	Fail RIM
Residential	Water Heater Timeclock	Manufactured Home	Existing	E_MH_Water	0.15	0.24	0.64	0	0	0	Fail RIM
Residential	Water Heater Timeclock	Single Family	New	N_SF_Water	0.12	0.24	0.50	0	0	0	Fail RIM
Residential	Water Heater Timeclock	Multi-Family	New	N_MF_Water	0.10	0.24	0.43	0	0	0	Fail RIM
Residential	Water Heater Timeclock	Manufactured Home	New	N_MH_Water	0.15	0.24	0.64	0	0	0	Fail RIM
Residential	Smart Power Strip	Single Family	Existing	E_SF_Smart	1.04	0.35	2.95	0	0	0	Fail RIM
Residential	Smart Power Strip	Multi-Family	Existing	E_MF_Smart	1.04	0.35	2.95	0	0	0	Fail RIM
Residential	Smart Power Strip	Manufactured Home	Existing	E_MH_Smart	1.04	0.35	2.95	0	0	0	Fail RIM
Residential	Smart Power Strip	Single Family	New	N_SF_Smart	1.04	0.35	2.95	0	0	0	Fail RIM
Residential	Smart Power Strip	Multi-Family	New	N_MF_Smart	1.04	0.35	2.95	0	0	0	Fail RIM
Residential	Smart Power Strip	Manufactured Home	New	N_MH_Smart	1.04	0.35	2.95	0	0	0	Fail RIM
Residential	Air Sealing-Infiltration Control	Single Family	New	N_SF_Air Sea	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Air Sealing-Infiltration Control	Multi-Family	New	N_MF_Air Se	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Air Sealing-Infiltration Control	Manufactured Home	New	N_MH_Air Se	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Ceiling Insulation(R19 to R38)	Multi-Family	Existing	E_MF_Ceilin	1.01	1.27	0.79	0	0	0	Fail PCT
Residential	Ceiling Insulation(R19 to R38)	Manufactured Home	Existing	E_MH_Ceilin	0.92	1.27	0.72	0	0	0	Fail PCT
Residential	Ceiling Insulation(R19 to R38)	Multi-Family	New	N_MF_Ceilin	1.01	1.27	0.79	0	0	0	Fail PCT
Residential	Ceiling Insulation(R19 to R38)	Manufactured Home	New	N_MH_Ceilin	0.92	1.27	0.72	0	0	0	Fail PCT
Residential	Ceiling Insulation(R30 to R38)	Single Family	Existing	E_SF_Ceiling	0.53	1.27	0.42	0	0	0	Fail PCT
Residential	Ceiling Insulation(R30 to R38)	Multi-Family	Existing	E_MF_Ceilin	0.39	1.27	0.30	0	0	0	Fail PCT
Residential	Ceiling Insulation(R30 to R38)	Manufactured Home	Existing	E_MH_Ceilin	0.35	1.27	0.28	0	0	0	Fail PCT
Residential	Ceiling Insulation(R30 to R38)	Single Family	New	N_SF_Ceiling	0.53	1.27	0.42	0	0	0	Fail PCT
Residential	Ceiling Insulation(R30 to R38)	Multi-Family	New	N_MF_Ceilin	0.39	1.27	0.30	0	0	0	Fail PCT
Residential	Ceiling Insulation(R30 to R38)	Manufactured Home	New	N_MH_Ceilin	0.35	1.27	0.28	0	0	0	Fail PCT
Residential	Central AC Tune Up	Single Family	Existing	E_SF_Centra	0.18	0.73	0.25	0	0	0	Fail RIM
Residential	Central AC Tune Up	Multi-Family	Existing	E_MF_Centra	0.09	0.73	0.12	0	0	0	Fail RIM
Residential	Central AC Tune Up	Manufactured Home	Existing	E_MH_Centr	0.12	0.73	0.17	0	0	0	Fail RIM
Residential	Central AC Tune Up	Single Family	New	N_SF_Centra	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Central AC Tune Up	Multi-Family	New	N_MF_Centra	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Central AC Tune Up	Manufactured Home	New	N_MH_Centr	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Duct Insulation	Single Family	Existing	E_SF_Duct In	0.16	1.22	0.13	0	0	0	Fail PCT
Residential	Duct Insulation	Multi-Family	Existing	E_MF_Duct I	0.12	1.22	0.10	0	0	0	Fail PCT
Residential	Duct Insulation	Manufactured Home	Existing	E_MH_Duct	0.18	1.22	0.14	0	0	0	Fail PCT
Residential	Duct Insulation	Single Family	New	N_SF_Duct In	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Duct Insulation	Multi-Family	New	N_MF_Duct I	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Duct Insulation	Manufactured Home	New	N_MH_Duct	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Duct Repair	Single Family	New	N_SF_Duct R	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Duct Repair	Multi-Family	New	N_MF_Duct I	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Duct Repair	Manufactured Home	New	N_MH_Duct	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Energy Star Certified Roof Products	Single Family	Existing	E_SF_Energy	0.00	1.27	0.00	0	0	0	Fail PCT
Residential	Energy Star Certified Roof Products	Multi-Family	Existing	E_MF_Energ	0.00	1.27	0.00	0	0	0	Fail PCT
Residential	Energy Star Certified Roof Products	Manufactured Home	Existing	E_MH_Energ	0.00	1.27	0.00	0	0	0	Fail PCT
Residential	Energy Star Certified Roof Products	Single Family	New	N_SF_Energy	0.00	1.27	0.00	0	0	0	Fail PCT
Residential	Energy Star Certified Roof Products	Multi-Family	New	N_MF_Energ	0.00	1.27	0.00	0	0	0	Fail PCT
Residential	Energy Star Certified Roof Products	Manufactured Home	New	N_MH_Energ	0.00	1.27	0.00	0	0	0	Fail PCT
Residential	Energy Star Door	Single Family	Existing	E_SF_Energy	1.15	1.27	0.90	0	0	0	Fail PCT
Residential	Energy Star Door	Multi-Family	Existing	E_MF_Energ	1.15	1.27	0.90	0	0	0	Fail PCT
Residential	Energy Star Door	Manufactured Home	Existing	E_MH_Energ	1.15	1.27	0.90	0	0	0	Fail PCT
Residential	Energy Star Door	Single Family	New	N_SF_Energy	0.82	1.27	0.64	0	0	0	Fail PCT
Residential	Energy Star Door	Multi-Family	New	N_MF_Energ	0.82	1.27	0.64	0	0	0	Fail PCT
Residential	Energy Star Door	Manufactured Home	New	N_MH_Energ	0.82	1.27	0.64	0	0	0	Fail PCT
Residential	Energy Star Windows	Single Family	New	N_SF_Energy	1.24	1.27	0.97	0	0	0	Fail PCT
Residential	Energy Star Windows	Multi-Family	New	N_MF_Energ	1.24	1.27	0.97	0	0	0	Fail PCT
Residential	Energy Star Windows	Manufactured Home	New	N_MH_Energ	1.24	1.27	0.97	0	0	0	Fail PCT
Residential	Floor Insulation	Single Family	Existing	E_SF_Floor I	0.08	1.27	0.06	0	0	0	Fail PCT
Residential	Floor Insulation	Multi-Family	Existing	E_MF_Floor	0.04	1.27	0.03	0	0	0	Fail PCT
Residential	Floor Insulation	Manufactured Home	Existing	E_MH_Floor	0.07	1.27	0.05	0	0	0	Fail PCT
Residential	Floor Insulation	Single Family	New	N_SF_Floor I	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Floor Insulation	Multi-Family	New	N_MF_Floor	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Floor Insulation	Manufactured Home	New	N_MH_Floor	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Green Roof	Single Family	Existing	E_SF_Green	0.09	1.27	0.07	0	0	0	Fail PCT
Residential	Green Roof	Multi-Family	Existing	E_MF_Green	0.07	1.27	0.05	0	0	0	Fail PCT
Residential	Green Roof	Manufactured Home	Existing	E_MH_Green	0.10	1.27	0.07	0	0	0	Fail PCT
Residential	Green Roof	Single Family	New	N_SF_Green	0.09	1.27	0.07	0	0	0	Fail PCT
Residential	Green Roof	Multi-Family	New	N_MF_Green	0.07	1.27	0.05	0	0	0	Fail PCT
Residential	Green Roof	Manufactured Home	New	N_MH_Green	0.10	1.27	0.07	0	0	0	Fail PCT
Residential	Heat Pump Tune Up	Single Family	Existing	E_SF_Heat P	0.39	0.89	0.44	0	0	0	Fail RIM
Residential	Heat Pump Tune Up	Multi-Family	Existing	E_MF_Heat P	0.26	0.89	0.29	0	0	0	Fail RIM
Residential	Heat Pump Tune Up	Manufactured Home	Existing	E_MH_Heat P	0.38	0.89	0.43	0	0	0	Fail RIM
Residential	Heat Pump Tune Up	Single Family	New	N_SF_Heat P	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Heat Pump Tune Up	Multi-Family	New	N_MF_Heat P	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Heat Pump Tune Up	Manufactured Home	New	N_MH_Heat	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	HVAC ECM Motor	Single Family	Existing	E_SF_HVAC	0.30	1.22	0.24	0	0	0	Fail PCT
Residential	HVAC ECM Motor	Multi-Family	Existing	E_MF_HVAC	0.30	1.22	0.24	0	0	0	Fail PCT
Residential	HVAC ECM Motor	Manufactured Home	Existing	E_MH_HVAC	0.30	1.22	0.24	0	0	0	Fail PCT
Residential	HVAC ECM Motor	Single Family	New	N_SF_HVAC	0.30	1.22	0.24	0	0	0	Fail PCT
Residential	HVAC ECM Motor	Multi-Family	New	N_MF_HVAC	0.30	1.22	0.24	0	0	0	Fail PCT
Residential	HVAC ECM Motor	Manufactured Home	New	N_MH_HVAC	0.30	1.22	0.24	0	0	0	Fail PCT
Residential	Programmable Thermostat	Single Family	Existing	E_SF_Progra	0.19	0.26	0.73	0	0	0	Fail RIM
Residential	Programmable Thermostat	Multi-Family	Existing	E_MF_Progra	0.12	0.26	0.47	0	0	0	Fail RIM
Residential	Programmable Thermostat	Manufactured Home	Existing	E_MH_Progra	0.18	0.26	0.71	0	0	0	Fail RIM
Residential	Programmable Thermostat	Single Family	New	N_SF_Progra	0.98	0.26	3.85	0	0	0	Fail RIM
Residential	Programmable Thermostat	Multi-Family	New	N_MF_Progra	0.64	0.26	2.50	0	0	0	Fail RIM
Residential	Programmable Thermostat	Manufactured Home	New	N_MH_Progr	0.96	0.26	3.76	0	0	0	Fail RIM
Residential	Radiant Barrier	Single Family	Existing	E_SF_Radian	1.07	1.27	0.84	0	0	0	Fail PCT
Residential	Radiant Barrier	Multi-Family	Existing	E_MF_Radian	0.85	1.27	0.67	0	0	0	Fail PCT
Residential	Radiant Barrier	Manufactured Home	Existing	E_MH_Radia	1.24	1.27	0.98	0	0	0	Fail PCT

Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Hospitals	New	N_HS_High E	5.26	1.17	4.50	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Hospitals	Turnover	T_HS_Energy	2.59	0.54	4.78	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Hospitals	New	N_HS_Energy	2.59	0.54	4.78	0	0	0
Commercial	Efficient Exhaust Hood	Hospitals	Turnover	T_HS_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Hospitals	Turnover	T_HS_Energy	1.28	0.65	1.97	0	0	1
Commercial	Efficient Exhaust Hood	Hospitals	New	N_HS_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Hospitals	New	N_HS_Energy	1.28	0.65	1.97	0	0	0
Commercial	Solar Water Heater	Hospitals	Turnover	T_HS_Solar	1.09	0.45	2.43	0	0	0
Commercial	Solar Water Heater	Hospitals	New	N_HS_Solar	1.09	0.45	2.43	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Institutional	New	N_IN_PSC to	1.19	0.58	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Institutional	New	N_IN_PSC to	1.84	0.58	3.15	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Institutional	Existing	E_IN_PSC to	1.19	0.58	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Institutional	Existing	E_IN_PSC to	1.84	0.58	3.15	0	0	0
Commercial	Thermal Energy Storage	Institutional	New	N_IN_Therma	2.46	9999.00	9999.00	0	0	0
Commercial	Smart Thermostat	Institutional	New	N_IN_Smart	1.31	0.30	4.30	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Institutional	New	N_IN_Chilled	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Institutional	New	N_IN_Ceiling	4.58	1.22	3.76	0	0	0
Commercial	Wall Insulation	Institutional	Existing	E_IN_Wall In	3.32	1.22	2.72	0	0	0
Commercial	Thermal Energy Storage	Institutional	Existing	E_IN_Therma	2.46	9999.00	9999.00	2	0	0
Commercial	Smart Thermostat	Institutional	Existing	E_IN_Smart	1.31	0.30	4.30	0	0	4
Commercial	Low U-Value Windows	Institutional	Existing	E_IN_Low U-	1.46	1.12	1.31	1	0	3
Commercial	Chilled Water System - Variable Speed Drives	Institutional	Existing	E_IN_Chilled	2.43	0.52	4.69	1	0	9
Commercial	Ceiling Insulation(R2 to R38)	Institutional	Existing	E_IN_Ceiling	4.67	1.22	3.83	0	0	0
Commercial	High Efficiency PTHP	Institutional	Turnover	T_IN_High E	4.80	1.33	3.60	0	0	0
Commercial	High Efficiency PTAC	Institutional	Turnover	T_IN_High E	4.76	1.35	3.52	0	0	0
Commercial	High Efficiency PTHP	Institutional	New	N_IN_High E	4.80	1.33	3.60	0	0	0
Commercial	High Efficiency PTAC	Institutional	New	N_IN_High E	4.76	1.35	3.52	0	0	0
Commercial	VSD Controlled Compressor	Institutional	New	N_IN_VSD C	2.22	0.61	3.66	0	0	0
Commercial	VSD Controlled Compressor	Institutional	Existing	E_IN_VSD C	2.22	0.61	3.66	0	0	1
Commercial	Variable Speed Pool Pump	Institutional	Turnover	T_IN_Variabl	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Institutional	Turnover	T_IN_Solar P	1.08	0.33	3.23	0	0	0
Commercial	Variable Speed Pool Pump	Institutional	New	N_IN_Variabl	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Institutional	New	N_IN_Solar P	1.08	0.33	3.23	0	0	0
Commercial	Efficient Battery Charger	Institutional	Turnover	T_IN_Efficien	1.63	1.02	1.59	1	0	2
Commercial	Efficient Battery Charger	Institutional	New	N_IN_Efficien	1.63	1.02	1.59	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Institutional	Turnover	T_IN_Energy	1.32	0.48	2.73	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Institutional	New	N_IN_Energy	1.32	0.48	2.73	0	0	0
Commercial	High Bay LED	Institutional	Turnover	T_IN_High Ba	3.37	0.68	4.96	0	0	0
Commercial	High Bay LED	Institutional	New	N_IN_High B	3.37	0.68	4.96	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Institutional	Turnover	T_IN_High E	1.19	0.89	1.34	0	0	1
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Institutional	Turnover	T_IN_High E	1.38	1.17	1.18	0	0	1
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Institutional	New	N_IN_High E	1.19	0.89	1.34	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Institutional	New	N_IN_High E	1.38	1.17	1.18	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Institutional	Turnover	T_IN_Energy	2.78	0.58	4.78	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Institutional	New	N_IN_Energy	2.78	0.58	4.78	0	0	0
Commercial	Efficient Exhaust Hood	Institutional	Turnover	T_IN_Efficien	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Institutional	Turnover	T_IN_Energy	1.28	0.65	1.97	0	0	0
Commercial	Efficient Exhaust Hood	Institutional	New	N_IN_Efficien	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Institutional	New	N_IN_Energy	1.28	0.65	1.97	0	0	0
Commercial	Solar Water Heater	Institutional	Turnover	T_IN_Solar W	1.29	0.45	2.89	0	0	2
Commercial	Solar Water Heater	Institutional	New	N_IN_Solar W	1.29	0.45	2.89	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Lodging/Hospitality	New	N_LG_PSC to	1.15	0.56	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Lodging/Hospitality	New	N_LG_PSC to	1.77	0.56	3.15	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Lodging/Hospitality	Existing	E_LG_PSC to	1.15	0.56	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Lodging/Hospitality	Existing	E_LG_PSC to	1.77	0.56	3.15	0	0	0
Commercial	Facility Energy Management System	Lodging/Hospitality	New	N_LG_Facilit	2.68	0.84	3.20	0	0	0
Commercial	Facility Energy Management System	Lodging/Hospitality	Existing	E_LG_Facilit	2.68	0.84	3.20	0	0	1
Commercial	Thermal Energy Storage	Lodging/Hospitality	New	N_LG_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Smart Thermostat	Lodging/Hospitality	New	N_LG_Smart	12.30	5.54	2.22	0	0	0
Commercial	Programmable Thermostat	Lodging/Hospitality	New	N_LG_Progra	6.93	5.54	1.25	0	0	0
Commercial	HVAC tune-up_RTU	Lodging/Hospitality	New	N_LG_HVAC	1.31	0.84	1.56	0	0	0
Commercial	HVAC tune-up	Lodging/Hospitality	New	N_LG_HVAC	1.99	0.95	2.09	0	0	0
Commercial	Dedicated Outdoor Air System on VRF unit	Lodging/Hospitality	New	N_LG_Dedica	1.06	0.74	1.44	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Lodging/Hospitality	New	N_LG_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Lodging/Hospitality	New	N_LG_Ceiling	4.55	1.21	3.76	0	0	0
Commercial	Wall Insulation	Lodging/Hospitality	Existing	E_LG_Wall I	3.30	1.21	2.72	0	0	0
Commercial	Thermal Energy Storage	Lodging/Hospitality	Existing	E_LG_Therm	2.46	9999.00	9999.00	1	0	0
Commercial	Smart Thermostat	Lodging/Hospitality	Existing	E_LG_Smart	12.30	5.54	2.22	0	2	13
Commercial	Programmable Thermostat	Lodging/Hospitality	Existing	E_LG_Progra	6.93	5.54	1.25	0	0	0
Commercial	Low U-Value Windows	Lodging/Hospitality	Existing	E_LG_Low U	1.66	1.27	1.31	6	0	13
Commercial	HVAC tune-up_RTU	Lodging/Hospitality	Existing	E_LG_HVAC	1.31	0.84	1.56	2	0	4
Commercial	HVAC tune-up	Lodging/Hospitality	Existing	E_LG_HVAC	1.99	0.95	2.09	0	0	0
Commercial	Dedicated Outdoor Air System on VRF unit	Lodging/Hospitality	Existing	E_LG_Dedica	1.06	0.74	1.44	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Lodging/Hospitality	Existing	E_LG_Chille	2.43	0.52	4.69	1	0	6
Commercial	Ceiling Insulation(R2 to R38)	Lodging/Hospitality	Existing	E_LG_Ceiling	4.64	1.21	3.83	0	0	0
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Lodging/Hospitality	Turnover	T_LG_Variab	1.08	0.74	1.48	0	0	1
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Lodging/Hospitality	New	N_LG_Variab	1.08	0.74	1.48	0	0	0
Commercial	ECM Motors on Furnaces	Lodging/Hospitality	New	N_LG_ECM	1.12	0.48	2.31	0	0	0
Commercial	ECM Motors on Furnaces	Lodging/Hospitality	Existing	E_LG_ECM	1.12	0.48	2.31	0	0	0
Commercial	VSD Controlled Compressor	Lodging/Hospitality	New	N_LG_VSD C	2.06	0.56	3.66	0	0	0
Commercial	VSD Controlled Compressor	Lodging/Hospitality	Existing	E_LG_VSD C	2.06	0.56	3.66	0	0	3
Commercial	Variable Speed Pool Pump	Lodging/Hospitality	Turnover	T_LG_Variab	1.65	0.70	2.35	0	0	2
Commercial	Solar Pool Heater	Lodging/Hospitality	Turnover	T_LG_Solar	1.08	0.33	3.23	0	0	0
Commercial	Variable Speed Pool Pump	Lodging/Hospitality	New	N_LG_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Lodging/Hospitality	New	N_LG_Solar	1.08	0.33	3.23	0	0	0
Commercial	Efficient Battery Charger	Lodging/Hospitality	Turnover	T_LG_Efficie	1.63	1.02	1.59	2	0	4
Commercial	Efficient Battery Charger	Lodging/Hospitality	New	N_LG_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Lodging/Hospitality	Turnover	T_LG_Energy	1.32	0.48	2.73	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Lodging/Hospitality	New	N_LG_Energy	1.32	0.48	2.73	0	0	0
Commercial	Demand Controlled Ventilation	Lodging/Hospitality	New	N_LG_Deman	5.03	1.25	4.01	0	0	0
Commercial	Demand Controlled Ventilation	Lodging/Hospitality	Existing	E_LG_Deman	5.03	1.25	4.01	1	7	11
Commercial	High Bay LED	Lodging/Hospitality	Turnover	T_LG_High B	3.83	0.68	5.65	0	0	0
Commercial	High Bay LED	Lodging/Hospitality	New	N_LG_High B	3.83	0.68	5.65	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Lodging/Hospitality	Turnover	T_LG_High E	3.63	0.89	4.09	0	0	1
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Lodging/Hospitality	Turnover	T_LG_High E	2.45	1.17	2.10	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Lodging/Hospitality	Turnover	T_LG_High E	4.21	1.17	3.61	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Lodging/Hospitality	New	N_LG_High E	3.63	0.89	4.09	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Lodging/Hospitality	New	N_LG_High E	2.45	1.17	2.10	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Lodging/Hospitality	New	N_LG_High E	4.21	1.17	3.61	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Lodging/Hospitality	Turnover	T_LG_Energy	2.59	0.54	4.78	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Lodging/Hospitality	New	N_LG_Energy	2.59	0.54	4.78	0	0	0
Commercial	Efficient Exhaust Hood	Lodging/Hospitality	Turnover	T_LG_Efficie	3.36	0.75	4.49	0	0	1
Commercial	Energy Star Hot Food Holding Cabinet	Lodging/Hospitality	Turnover	T_LG_Energy	1.28	0.65	1.97	0	0	2
Commercial	Efficient Exhaust Hood	Lodging/Hospitality	New	N_LG_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Lodging/Hospitality	New	N_LG_Energy	1.28	0.65	1.97	0	0	0
Commercial	Solar Water Heater	Lodging/Hospitality	Turnover	T_LG_Solar	1.29	0.45	2.89	0	0	2
Commercial	Solar Water Heater	Lodging/Hospitality	New	N_LG_Solar	1.29	0.45	2.89	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Miscellaneous	New	N_MS_PSC t	1.19	0.58	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Miscellaneous	New	N_MS_PSC t	1.84	0.58	3.15	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Miscellaneous	Existing	E_MS_PSC t	1.19	0.58	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Miscellaneous	Existing	E_MS_PSC t	1.84	0.58	3.15	0	0	0
Commercial	Facility Energy Management System	Miscellaneous	New	N_MS_Facilit	3.18	0.73	4.36	0	0	0
Commercial	Facility Energy Management System	Miscellaneous	Existing	E_MS_Facilit	3.18	0.73	4.36	3	0	14
Commercial	Thermal Energy Storage	Miscellaneous	New	N_MS_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Miscellaneous	New	N_MS_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Miscellaneous	New	N_MS_Ceilin	4.58	1.22	3.76	0	0	0
Commercial	Wall Insulation	Miscellaneous	Existing	E_MS_Wall I	3.37	1.22	2.76	0	0	0
Commercial	Thermal Energy Storage	Miscellaneous	Existing	E_MS_Therm	2.46	9999.00	9999.00	3	1	0
Commercial	Low U-Value Windows	Miscellaneous	Existing	E_MS_Low U	1.38	1.06	1.31	4	0	13

Residential	Smart Power Strip	Manufactured Home	New	N_MH_Smart	1.04	0.35	2.95	0	0	0	Fail 2-year Threshold
Residential	Air Sealing-Infiltration Control	Single Family	New	N_SF_Air Sea	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Air Sealing-Infiltration Control	Multi-Family	New	N_MF_Air Se	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Air Sealing-Infiltration Control	Manufactured Home	New	N_MH_Air Se	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Ceiling Insulation(R19 to R38)	Multi-Family	Existing	E_MF_Ceilin	1.01	1.27	0.79	0	0	0	Fail PCT
Residential	Ceiling Insulation(R19 to R38)	Manufactured Home	Existing	E_MH_Ceilin	0.92	1.27	0.72	0	0	0	Fail TRC
Residential	Ceiling Insulation(R19 to R38)	Multi-Family	New	N_MF_Ceilin	1.01	1.27	0.79	0	0	0	Fail PCT
Residential	Ceiling Insulation(R19 to R38)	Manufactured Home	New	N_MH_Ceilin	0.92	1.27	0.72	0	0	0	Fail TRC
Residential	Ceiling Insulation(R30 to R38)	Single Family	Existing	E_SF_Ceiling	0.53	1.27	0.42	0	0	0	Fail TRC
Residential	Ceiling Insulation(R30 to R38)	Multi-Family	Existing	E_MF_Ceilin	0.39	1.27	0.30	0	0	0	Fail TRC
Residential	Ceiling Insulation(R30 to R38)	Manufactured Home	Existing	E_MH_Ceilin	0.35	1.27	0.28	0	0	0	Fail TRC
Residential	Ceiling Insulation(R30 to R38)	Single Family	New	N_SF_Ceiling	0.53	1.27	0.42	0	0	0	Fail TRC
Residential	Ceiling Insulation(R30 to R38)	Multi-Family	New	N_MF_Ceilin	0.39	1.27	0.30	0	0	0	Fail TRC
Residential	Ceiling Insulation(R30 to R38)	Manufactured Home	New	N_MH_Ceilin	0.35	1.27	0.28	0	0	0	Fail TRC
Residential	Central AC Tune Up	Single Family	Existing	E_SF_Centra	0.18	0.73	0.25	0	0	0	Fail TRC
Residential	Central AC Tune Up	Multi-Family	Existing	E_MF_Centra	0.09	0.73	0.12	0	0	0	Fail TRC
Residential	Central AC Tune Up	Manufactured Home	Existing	E_MH_Centr	0.12	0.73	0.17	0	0	0	Fail TRC
Residential	Central AC Tune Up	Single Family	New	N_SF_Centra	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Central AC Tune Up	Multi-Family	New	N_MF_Centra	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Central AC Tune Up	Manufactured Home	New	N_MH_Centr	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Duct Insulation	Single Family	Existing	E_SF_Duct In	0.16	1.22	0.13	0	0	0	Fail TRC
Residential	Duct Insulation	Multi-Family	Existing	E_MF_Duct I	0.12	1.22	0.10	0	0	0	Fail TRC
Residential	Duct Insulation	Manufactured Home	Existing	E_MH_Duct	0.18	1.22	0.14	0	0	0	Fail TRC
Residential	Duct Insulation	Single Family	New	N_SF_Duct In	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Duct Insulation	Multi-Family	New	N_MF_Duct I	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Duct Insulation	Manufactured Home	New	N_MH_Duct	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Duct Repair	Single Family	New	N_SF_Duct R	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Duct Repair	Multi-Family	New	N_MF_Duct I	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Duct Repair	Manufactured Home	New	N_MH_Duct	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Energy Star Certified Roof Products	Single Family	Existing	E_SF_Energy	0.00	1.27	0.00	0	0	0	Fail TRC
Residential	Energy Star Certified Roof Products	Multi-Family	Existing	E_MF_Energ	0.00	1.27	0.00	0	0	0	Fail TRC
Residential	Energy Star Certified Roof Products	Manufactured Home	Existing	E_MH_Energ	0.00	1.27	0.00	0	0	0	Fail TRC
Residential	Energy Star Certified Roof Products	Single Family	New	N_SF_Energy	0.00	1.27	0.00	0	0	0	Fail TRC
Residential	Energy Star Certified Roof Products	Multi-Family	New	N_MF_Energ	0.00	1.27	0.00	0	0	0	Fail TRC
Residential	Energy Star Certified Roof Products	Manufactured Home	New	N_MH_Energ	0.00	1.27	0.00	0	0	0	Fail TRC
Residential	Energy Star Door	Single Family	Existing	E_SF_Energy	1.15	1.27	0.90	0	0	0	Fail PCT
Residential	Energy Star Door	Multi-Family	Existing	E_MF_Energ	1.15	1.27	0.90	0	0	0	Fail PCT
Residential	Energy Star Door	Manufactured Home	Existing	E_MH_Energ	1.15	1.27	0.90	0	0	0	Fail PCT
Residential	Energy Star Door	Single Family	New	N_SF_Energy	0.82	1.27	0.64	0	0	0	Fail TRC
Residential	Energy Star Door	Multi-Family	New	N_MF_Energ	0.82	1.27	0.64	0	0	0	Fail TRC
Residential	Energy Star Door	Manufactured Home	New	N_MH_Energ	0.82	1.27	0.64	0	0	0	Fail TRC
Residential	Energy Star Windows	Single Family	New	N_SF_Energy	1.24	1.27	0.97	0	0	0	Fail PCT
Residential	Energy Star Windows	Multi-Family	New	N_MF_Energ	1.24	1.27	0.97	0	0	0	Fail PCT
Residential	Energy Star Windows	Manufactured Home	New	N_MH_Energ	1.24	1.27	0.97	0	0	0	Fail PCT
Residential	Floor Insulation	Single Family	Existing	E_SF_Floor I	0.08	1.27	0.06	0	0	0	Fail TRC
Residential	Floor Insulation	Multi-Family	Existing	E_MF_Floor	0.04	1.27	0.03	0	0	0	Fail TRC
Residential	Floor Insulation	Manufactured Home	Existing	E_MH_Floor	0.07	1.27	0.05	0	0	0	Fail TRC
Residential	Floor Insulation	Single Family	New	N_SF_Floor I	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Floor Insulation	Multi-Family	New	N_MF_Floor	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Floor Insulation	Manufactured Home	New	N_MH_Floor	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Green Roof	Single Family	Existing	E_SF_Green	0.09	1.27	0.07	0	0	0	Fail TRC
Residential	Green Roof	Multi-Family	Existing	E_MF_Green	0.07	1.27	0.05	0	0	0	Fail TRC
Residential	Green Roof	Manufactured Home	Existing	E_MH_Green	0.10	1.27	0.07	0	0	0	Fail TRC
Residential	Green Roof	Single Family	New	N_SF_Green	0.09	1.27	0.07	0	0	0	Fail TRC
Residential	Green Roof	Multi-Family	New	N_MF_Green	0.07	1.27	0.05	0	0	0	Fail TRC
Residential	Green Roof	Manufactured Home	New	N_MH_Green	0.10	1.27	0.07	0	0	0	Fail TRC
Residential	Heat Pump Tune Up	Single Family	Existing	E_SF_Heat P	0.39	0.89	0.44	0	0	0	Fail TRC
Residential	Heat Pump Tune Up	Multi-Family	Existing	E_MF_Heat P	0.26	0.89	0.29	0	0	0	Fail TRC
Residential	Heat Pump Tune Up	Manufactured Home	Existing	E_MH_Heat P	0.38	0.89	0.43	0	0	0	Fail TRC
Residential	Heat Pump Tune Up	Single Family	New	N_SF_Heat P	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Heat Pump Tune Up	Multi-Family	New	N_MF_Heat P	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Heat Pump Tune Up	Manufactured Home	New	N_MH_Heat	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	HVAC ECM Motor	Single Family	Existing	E_SF_HVAC	0.30	1.22	0.24	0	0	0	Fail TRC
Residential	HVAC ECM Motor	Multi-Family	Existing	E_MF_HVAC	0.30	1.22	0.24	0	0	0	Fail TRC
Residential	HVAC ECM Motor	Manufactured Home	Existing	E_MH_HVAC	0.30	1.22	0.24	0	0	0	Fail TRC
Residential	HVAC ECM Motor	Single Family	New	N_SF_HVAC	0.30	1.22	0.24	0	0	0	Fail TRC
Residential	HVAC ECM Motor	Multi-Family	New	N_MF_HVAC	0.30	1.22	0.24	0	0	0	Fail TRC
Residential	HVAC ECM Motor	Manufactured Home	New	N_MH_HVAC	0.30	1.22	0.24	0	0	0	Fail TRC
Residential	Programmable Thermostat	Single Family	Existing	E_SF_Progra	0.19	0.26	0.73	0	0	0	Fail TRC
Residential	Programmable Thermostat	Multi-Family	Existing	E_MF_Progra	0.12	0.26	0.47	0	0	0	Fail TRC
Residential	Programmable Thermostat	Manufactured Home	Existing	E_MH_Progra	0.18	0.26	0.71	0	0	0	Fail TRC
Residential	Programmable Thermostat	Single Family	New	N_SF_Progra	0.98	0.26	3.85	0	0	0	Fail TRC
Residential	Programmable Thermostat	Multi-Family	New	N_MF_Progra	0.64	0.26	2.50	0	0	0	Fail TRC
Residential	Programmable Thermostat	Manufactured Home	New	N_MH_Progr	0.96	0.26	3.76	0	0	0	Fail TRC
Residential	Radiant Barrier	Single Family	Existing	E_SF_Radian	1.07	1.27	0.84	0	0	0	Fail PCT
Residential	Radiant Barrier	Multi-Family	Existing	E_MF_Radian	0.85	1.27	0.67	0	0	0	Fail TRC
Residential	Radiant Barrier	Manufactured Home	Existing	E_MH_Radia	1.24	1.27	0.98	0	0	0	Fail PCT
Residential	Radiant Barrier	Single Family	New	N_SF_Radian	1.07	1.27	0.84	0	0	0	Fail PCT
Residential	Radiant Barrier	Multi-Family	New	N_MF_Radia	0.85	1.27	0.67	0	0	0	Fail TRC
Residential	Radiant Barrier	Manufactured Home	New	N_MH_Radia	1.24	1.27	0.98	0	0	0	Fail PCT
Residential	Sealed crawlspace	Single Family	Existing	E_SF_Sealed	0.04	1.13	0.03	0	0	0	Fail TRC
Residential	Sealed crawlspace	Multi-Family	Existing	E_MF_Sealed	0.02	1.13	0.02	0	0	0	Fail TRC
Residential	Sealed crawlspace	Manufactured Home	Existing	E_MH_Sealed	0.03	1.13	0.03	0	0	0	Fail TRC
Residential	Sealed crawlspace	Single Family	New	N_SF_Sealed	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Sealed crawlspace	Multi-Family	New	N_MF_Sealed	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Sealed crawlspace	Manufactured Home	New	N_MH_Seale	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Smart Thermostat	Single Family	Existing	E_SF_Smart	0.28	0.26	1.08	0	0	0	Fail TRC
Residential	Smart Thermostat	Multi-Family	Existing	E_MF_Smart	0.18	0.26	0.70	0	0	0	Fail TRC
Residential	Smart Thermostat	Manufactured Home	Existing	E_MH_Smart	0.27	0.26	1.05	0	0	0	Fail TRC
Residential	Smart Thermostat	Single Family	New	N_SF_Smart	0.57	0.26	2.24	0	0	0	Fail TRC
Residential	Smart Thermostat	Multi-Family	New	N_MF_Smart	0.37	0.26	1.45	0	0	0	Fail TRC
Residential	Smart Thermostat	Manufactured Home	New	N_MH_Smart	0.56	0.26	2.19	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R12)	Single Family	Existing	E_SF_Spray I	0.55	1.27	0.43	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R12)	Multi-Family	Existing	E_MF_Spray	0.44	1.27	0.35	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R12)	Manufactured Home	Existing	E_MH_Spray	0.52	1.27	0.41	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R12)	Single Family	New	N_SF_Spray I	0.55	1.27	0.43	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R12)	Multi-Family	New	N_MF_Spray	0.44	1.27	0.35	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R12)	Manufactured Home	New	N_MH_Spray	0.52	1.27	0.41	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R19)	Single Family	Existing	E_SF_Spray I	0.39	1.27	0.30	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R19)	Multi-Family	Existing	E_MF_Spray	0.32	1.27	0.25	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R19)	Manufactured Home	Existing	E_MH_Spray	0.40	1.27	0.31	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R19)	Single Family	New	N_SF_Spray I	0.39	1.27	0.30	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R19)	Multi-Family	New	N_MF_Spray	0.32	1.27	0.25	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R19)	Manufactured Home	New	N_MH_Spray	0.40	1.27	0.31	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R2)	Multi-Family	Existing	E_MF_Spray	1.14	1.27	0.90	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R2)	Manufactured Home	Existing	E_MH_Spray	1.23	1.27	0.96	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R2)	Multi-Family	New	N_MF_Spray	1.14	1.27	0.90	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R2)	Manufactured Home	New	N_MH_Spray	1.23	1.27	0.96	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R30)	Single Family	Existing	E_SF_Spray I	0.27	1.27	0.21	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R30)	Multi-Family	Existing	E_MF_Spray	0.23	1.27	0.18	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R30)	Manufactured Home	Existing	E_MH_Spray	0.32	1.27	0.25	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R30)	Single Family	New	N_SF_Spray I	0.33	1.27	0.26	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R30)	Multi-Family	New	N_MF_Spray	0.23	1.27	0.18	0	0	0	Fail TRC
Residential	Spray Foam Insulation(Base R30)	Manufactured Home	New	N_MH_Spray	0.34	1.27	0.27	0	0	0	Fail TRC
Residential	Storm Door	Single Family	Existing	E_SF_Storm	0.84	1.27	0.66	0	0	0	Fail TRC
Residential	Storm Door	Multi-Family	Existing	E_MF_Storm	0.84	1.27	0.66	0	0	0	Fail TRC
Residential	Storm Door	Manufactured Home	Existing	E_MH_Storm	0.84	1.27	0.66	0	0	0	Fail TRC
Residential	Storm Door	Single Family	New	N_SF_Storm	0.55	1.27	0.43	0	0	0	Fail TRC
Residential	Storm Door	Multi-Family	New	N_MF_Storm	0.55	1.27	0.43	0	0	0	Fail TRC

Residential	Radiant Barrier	Single Family	New	N_SF_Radian	1.07	1.27	0.84	0	0	0	Fail PCT
Residential	Radiant Barrier	Multi-Family	New	N_MF_Radia	0.85	1.27	0.67	0	0	0	Fail PCT
Residential	Radiant Barrier	Manufactured Home	New	N_MH_Radia	1.24	1.27	0.98	0	0	0	Fail PCT
Residential	Sealed crawlspace	Single Family	Existing	E_SF_Sealed	0.04	1.13	0.03	0	0	0	Fail PCT
Residential	Sealed crawlspace	Multi-Family	Existing	E_MF_Sealed	0.02	1.13	0.02	0	0	0	Fail PCT
Residential	Sealed crawlspace	Manufactured Home	Existing	E_MH_Seale	0.03	1.13	0.03	0	0	0	Fail PCT
Residential	Sealed crawlspace	Single Family	New	N_SF_Sealed	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Sealed crawlspace	Multi-Family	New	N_MF_Seale	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Sealed crawlspace	Manufactured Home	New	N_MH_Seale	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Smart Thermostat	Single Family	Existing	E_SF_Smart	0.28	0.26	1.08	0	0	0	Fail RIM
Residential	Smart Thermostat	Multi-Family	Existing	E_MF_Smart	0.18	0.26	0.70	0	0	0	Fail RIM
Residential	Smart Thermostat	Manufactured Home	Existing	E_MH_Smart	0.27	0.26	1.05	0	0	0	Fail RIM
Residential	Smart Thermostat	Single Family	New	N_SF_Smart	0.57	0.26	2.24	0	0	0	Fail RIM
Residential	Smart Thermostat	Multi-Family	New	N_MF_Smart	0.37	0.26	1.45	0	0	0	Fail RIM
Residential	Smart Thermostat	Manufactured Home	New	N_MH_Smart	0.56	0.26	2.19	0	0	0	Fail RIM
Residential	Spray Foam Insulation(Base R12)	Single Family	Existing	E_SF_Spray	0.55	1.27	0.43	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R12)	Multi-Family	Existing	E_MF_Spray	0.44	1.27	0.35	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R12)	Manufactured Home	Existing	E_MH_Spray	0.52	1.27	0.41	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R12)	Single Family	New	N_SF_Spray	0.55	1.27	0.43	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R12)	Multi-Family	New	N_MF_Spray	0.44	1.27	0.35	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R12)	Manufactured Home	New	N_MH_Spray	0.52	1.27	0.41	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R19)	Single Family	Existing	E_SF_Spray	0.39	1.27	0.30	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R19)	Multi-Family	Existing	E_MF_Spray	0.32	1.27	0.25	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R19)	Manufactured Home	Existing	E_MH_Spray	0.40	1.27	0.31	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R19)	Single Family	New	N_SF_Spray	0.39	1.27	0.30	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R19)	Multi-Family	New	N_MF_Spray	0.32	1.27	0.25	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R19)	Manufactured Home	New	N_MH_Spray	0.40	1.27	0.31	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R2)	Multi-Family	Existing	E_MF_Spray	1.14	1.27	0.90	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R2)	Manufactured Home	Existing	E_MH_Spray	1.23	1.27	0.96	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R2)	Multi-Family	New	N_MF_Spray	1.14	1.27	0.90	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R2)	Manufactured Home	New	N_MH_Spray	1.23	1.27	0.96	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R30)	Single Family	Existing	E_SF_Spray	0.27	1.27	0.21	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R30)	Multi-Family	Existing	E_MF_Spray	0.23	1.27	0.18	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R30)	Manufactured Home	Existing	E_MH_Spray	0.32	1.27	0.25	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R30)	Single Family	New	N_SF_Spray	0.33	1.27	0.26	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R30)	Multi-Family	New	N_MF_Spray	0.23	1.27	0.18	0	0	0	Fail PCT
Residential	Spray Foam Insulation(Base R30)	Manufactured Home	New	N_MH_Spray	0.34	1.27	0.27	0	0	0	Fail PCT
Residential	Storm Door	Single Family	Existing	E_SF_Storm	0.84	1.27	0.66	0	0	0	Fail PCT
Residential	Storm Door	Multi-Family	Existing	E_MF_Storm	0.84	1.27	0.66	0	0	0	Fail PCT
Residential	Storm Door	Manufactured Home	Existing	E_MH_Storm	0.84	1.27	0.66	0	0	0	Fail PCT
Residential	Storm Door	Single Family	New	N_SF_Storm	0.55	1.27	0.43	0	0	0	Fail PCT
Residential	Storm Door	Multi-Family	New	N_MF_Storm	0.55	1.27	0.43	0	0	0	Fail PCT
Residential	Storm Door	Manufactured Home	New	N_MH_Storm	0.55	1.27	0.43	0	0	0	Fail PCT
Residential	Wall Insulation	Multi-Family	Existing	E_MF_Wall I	0.73	1.27	0.57	0	0	0	Fail PCT
Residential	Wall Insulation	Single Family	New	N_SF_Wall In	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Wall Insulation	Multi-Family	New	N_MF_Wall I	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Wall Insulation	Manufactured Home	New	N_MH_Wall	0.00	0.00	0.00	0	0	0	Fail RIM
Residential	Window Sun Protection	Single Family	Existing	E_SF_Windo	0.24	0.86	0.28	0	0	0	Fail RIM
Residential	Window Sun Protection	Multi-Family	Existing	E_MF_Windo	0.20	0.86	0.24	0	0	0	Fail RIM
Residential	Window Sun Protection	Manufactured Home	Existing	E_MH_Wind	0.16	0.86	0.19	0	0	0	Fail RIM
Residential	Window Sun Protection	Single Family	New	N_SF_Windo	0.24	0.86	0.28	0	0	0	Fail RIM
Residential	Window Sun Protection	Multi-Family	New	N_MF_Windo	0.20	0.86	0.24	0	0	0	Fail RIM
Residential	Window Sun Protection	Manufactured Home	New	N_MH_Wind	0.16	0.86	0.19	0	0	0	Fail RIM
Residential	Exterior Lighting Controls	Single Family	Existing	E_SF_Exterio	0.28	0.25	1.12	0	0	0	Fail RIM
Residential	Exterior Lighting Controls	Multi-Family	Existing	E_MF_Exteri	0.28	0.25	1.12	0	0	0	Fail RIM
Residential	Exterior Lighting Controls	Manufactured Home	Existing	E_MH_Exteri	0.28	0.25	1.12	0	0	0	Fail RIM
Residential	Exterior Lighting Controls	Single Family	New	N_SF_Exterio	0.28	0.25	1.12	0	0	0	Fail RIM
Residential	Exterior Lighting Controls	Multi-Family	New	N_MF_Exteri	0.28	0.25	1.12	0	0	0	Fail RIM
Residential	Exterior Lighting Controls	Manufactured Home	New	N_MH_Exter	0.28	0.25	1.12	0	0	0	Fail RIM
Residential	Interior Lighting Controls	Single Family	Existing	E_SF_Interior	0.20	0.41	0.48	0	0	0	Fail RIM
Residential	Interior Lighting Controls	Multi-Family	Existing	E_MF_Interio	0.20	0.41	0.48	0	0	0	Fail RIM
Residential	Interior Lighting Controls	Manufactured Home	Existing	E_MH_Interio	0.20	0.41	0.48	0	0	0	Fail RIM
Residential	Interior Lighting Controls	Single Family	New	N_SF_Interio	0.20	0.41	0.48	0	0	0	Fail RIM
Residential	Interior Lighting Controls	Multi-Family	New	N_MF_Interio	0.20	0.41	0.48	0	0	0	Fail RIM
Residential	Interior Lighting Controls	Manufactured Home	New	N_MH_Interio	0.20	0.41	0.48	0	0	0	Fail RIM
Residential	Solar Attic Fan	Single Family	Existing	E_SF_Solar A	0.47	0.83	0.57	0	0	0	Fail RIM
Residential	Solar Attic Fan	Multi-Family	Existing	E_MF_Solar	0.23	0.83	0.27	0	0	0	Fail RIM
Residential	Solar Attic Fan	Manufactured Home	Existing	E_MH_Solar	0.31	0.83	0.38	0	0	0	Fail RIM
Residential	Solar Attic Fan	Single Family	New	N_SF_Solar A	0.47	0.83	0.57	0	0	0	Fail RIM
Residential	Solar Attic Fan	Multi-Family	New	N_MF_Solar	0.23	0.83	0.27	0	0	0	Fail RIM
Residential	Solar Attic Fan	Manufactured Home	New	N_MH_Solar	0.31	0.83	0.38	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Assembly	Turnover	T_AS_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	College and University	Turnover	T_CU_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Grocery	Turnover	T_GR_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Healthcare	Turnover	T_HC_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Hospitals	Turnover	T_HS_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Institutional	Turnover	T_IN_Efficier	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Lodging/Hospitality	Turnover	T_LG_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Miscellaneous	Turnover	T_MS_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Offices	Turnover	T_OF_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Restaurants	Turnover	T_RS_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Retail	Turnover	T_RT_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Schools K-12	Turnover	T_SC_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Warehouse	Turnover	T_WR_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Assembly	New	N_AS_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	College and University	New	N_CU_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Grocery	New	N_GR_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Healthcare	New	N_HC_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Hospitals	New	N_HS_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Institutional	New	N_IN_Efficier	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Lodging/Hospitality	New	N_LG_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Miscellaneous	New	N_MS_Effici	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Offices	New	N_OF_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Restaurants	New	N_RS_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Retail	New	N_RT_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Schools K-12	New	N_SC_Efficie	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Efficient Exhaust Hood	Warehouse	New	N_WR_Effici	3.36	0.75	4.49	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Assembly	Turnover	T_AS_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	College and University	Turnover	T_CU_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Grocery	Turnover	T_GR_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Healthcare	Turnover	T_HC_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Hospitals	Turnover	T_HS_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Institutional	Turnover	T_IN_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Lodging/Hospitality	Turnover	T_LG_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Miscellaneous	Turnover	T_MS_Energ	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Offices	Turnover	T_OF_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Restaurants	Turnover	T_RS_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Retail	Turnover	T_RT_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Schools K-12	Turnover	T_SC_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Warehouse	Turnover	T_WR_Energ	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Assembly	New	N_AS_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	College and University	New	N_CU_Energ	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Grocery	New	N_GR_Energ	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Healthcare	New	N_HC_Energ	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Hospitals	New	N_HS_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Institutional	New	N_IN_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Lodging/Hospitality	New	N_LG_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Miscellaneous	New	N_MS_Energ	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Offices	New	N_OF_Energy	3.00	0.61	4.93	0	0	0	Fail RIM

Commercial	Chilled Water System - Variable Speed Drives	Miscellaneous	Existing	E_MS_Chille	2.43	0.52	4.69	1	0	10
Commercial	Ceiling Insulation(R2 to R38)	Miscellaneous	Existing	E_MS_Ceilin	4.67	1.22	3.83	0	0	0
Commercial	High Efficiency PTHP	Miscellaneous	Turnover	T_MS_High E	4.92	1.33	3.69	0	0	0
Commercial	High Efficiency PTAC	Miscellaneous	Turnover	T_MS_High E	4.28	1.18	3.64	0	0	0
Commercial	High Efficiency PTHP	Miscellaneous	New	N_MS_High E	4.92	1.33	3.69	0	0	0
Commercial	High Efficiency PTAC	Miscellaneous	New	N_MS_High E	4.28	1.18	3.64	0	0	0
Commercial	Water Cooled Refrigeration Heat Recovery	Miscellaneous	New	N_MS_Water	1.06	0.43	2.45	0	0	0
Commercial	Water Cooled Refrigeration Heat Recovery	Miscellaneous	Existing	E_MS_Water	1.06	0.43	2.45	0	0	0
Commercial	VSD Controlled Compressor	Miscellaneous	New	N_MS_VSD C	2.22	0.61	3.66	0	0	1
Commercial	VSD Controlled Compressor	Miscellaneous	Existing	E_MS_VSD C	2.22	0.61	3.66	5	2	35
Commercial	Variable Speed Pool Pump	Miscellaneous	Turnover	T_MS_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Miscellaneous	Turnover	T_MS_Solar	1.08	0.33	3.23	0	0	0
Commercial	Variable Speed Pool Pump	Miscellaneous	New	N_MS_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Miscellaneous	New	N_MS_Solar	1.08	0.33	3.23	0	0	0
Commercial	Efficient Battery Charger	Miscellaneous	Turnover	T_MS_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Miscellaneous	New	N_MS_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Miscellaneous	Turnover	T_MS_Energy	1.32	0.48	2.73	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Miscellaneous	New	N_MS_Energ	1.32	0.48	2.73	0	0	0
Commercial	Demand Controlled Ventilation	Miscellaneous	New	N_MS_Dema	4.56	1.25	3.64	0	0	0
Commercial	Demand Controlled Ventilation	Miscellaneous	Existing	E_MS_Demai	4.56	1.25	3.64	0	0	1
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Miscellaneous	Turnover	T_MS_High E	1.23	0.89	1.38	0	0	1
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Miscellaneous	Turnover	T_MS_High E	1.42	1.17	1.22	0	0	1
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Miscellaneous	New	N_MS_High E	1.23	0.89	1.38	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Miscellaneous	New	N_MS_High E	1.42	1.17	1.22	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Miscellaneous	Turnover	T_MS_Energy	2.78	0.58	4.78	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Miscellaneous	New	N_MS_Energ	2.78	0.58	4.78	0	0	0
Commercial	Efficient Exhaust Hood	Miscellaneous	Turnover	T_MS_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Miscellaneous	Turnover	T_MS_Energy	1.28	0.65	1.97	0	0	0
Commercial	Efficient Exhaust Hood	Miscellaneous	New	N_MS_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Miscellaneous	New	N_MS_Energ	1.28	0.65	1.97	0	0	0
Commercial	Solar Water Heater	Miscellaneous	Turnover	T_MS_Solar V	1.21	0.45	2.71	0	0	0
Commercial	Solar Water Heater	Miscellaneous	New	N_MS_Solar	1.21	0.45	2.71	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Offices	New	N_OF_PSC to	1.19	0.58	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Offices	New	N_OF_PSC to	1.84	0.58	3.15	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Offices	Existing	E_OF_PSC to	1.19	0.58	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Offices	Existing	E_OF_PSC to	1.84	0.58	3.15	0	0	0
Commercial	Facility Energy Management System	Offices	New	N_OF_Facilit	4.27	0.73	5.85	0	0	0
Commercial	Facility Energy Management System	Offices	Existing	E_OF_Facilit	4.27	0.73	5.85	1	0	7
Commercial	Thermal Energy Storage	Offices	New	N_OF_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Smart Thermostat	Offices	New	N_OF_Smart	1.22	0.30	4.00	0	0	0
Commercial	HVAC tune-up	Offices	New	N_OF_HVAC	1.19	0.84	1.42	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Offices	New	N_OF_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Offices	New	N_OF_Ceiling	4.58	1.22	3.76	0	0	0
Commercial	Wall Insulation	Offices	Existing	E_OF_Wall I	3.37	1.22	2.76	0	0	21
Commercial	Thermal Energy Storage	Offices	Existing	E_OF_Therm	2.46	9999.00	9999.00	5	1	-1
Commercial	Smart Thermostat	Offices	Existing	E_OF_Smart	1.22	0.30	4.00	0	0	20
Commercial	Low U-Value Windows	Offices	Existing	E_OF_Low U	1.46	1.12	1.31	4	0	11
Commercial	HVAC tune-up	Offices	Existing	E_OF_HVAC	1.19	0.84	1.42	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Offices	Existing	E_OF_Chille	2.43	0.52	4.69	2	0	22
Commercial	Ceiling Insulation(R2 to R38)	Offices	Existing	E_OF_Ceiling	4.67	1.22	3.83	0	0	7
Commercial	VSD Controlled Compressor	Offices	New	N_OF_VSD C	2.22	0.61	3.66	0	0	0
Commercial	VSD Controlled Compressor	Offices	Existing	E_OF_VSD C	2.22	0.61	3.66	1	0	5
Commercial	Variable Speed Pool Pump	Offices	Turnover	T_OF_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Offices	Turnover	T_OF_Solar F	1.08	0.33	3.23	0	0	0
Commercial	Variable Speed Pool Pump	Offices	New	N_OF_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Offices	New	N_OF_Solar I	1.08	0.33	3.23	0	0	0
Commercial	Efficient Battery Charger	Offices	Turnover	T_OF_Efficie	1.63	1.02	1.59	5	0	10
Commercial	Efficient Battery Charger	Offices	New	N_OF_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Offices	Turnover	T_OF_Energy	1.32	0.48	2.73	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Offices	New	N_OF_Energy	1.32	0.48	2.73	0	0	0
Commercial	Demand Controlled Ventilation	Offices	New	N_OF_Demar	4.78	1.25	3.81	0	0	0
Commercial	Demand Controlled Ventilation	Offices	Existing	E_OF_Demar	4.78	1.25	3.81	2	10	17
Commercial	High Bay LED	Offices	Turnover	T_OF_High B	3.32	0.68	4.89	0	0	0
Commercial	High Bay LED	Offices	New	N_OF_High B	3.32	0.68	4.89	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Offices	Turnover	T_OF_High E	2.47	0.89	2.79	1	0	4
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Offices	Turnover	T_OF_High E	1.67	1.17	1.43	0	0	1
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Offices	Turnover	T_OF_High E	2.87	1.17	2.46	1	0	2
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Offices	New	N_OF_High E	2.47	0.89	2.79	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Offices	New	N_OF_High E	1.67	1.17	1.43	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Offices	New	N_OF_High E	2.87	1.17	2.46	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Offices	Turnover	T_OF_Energy	2.78	0.58	4.78	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Offices	New	N_OF_Energy	2.78	0.58	4.78	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Offices	Turnover	T_OF_Energy	1.28	0.65	1.97	0	0	0
Commercial	Efficient Exhaust Hood	Offices	Turnover	T_OF_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Efficient Exhaust Hood	Offices	New	N_OF_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Offices	New	N_OF_Energy	1.28	0.65	1.97	0	0	0
Commercial	Solar Water Heater	Offices	Turnover	T_OF_Solar V	1.12	0.45	2.51	0	0	1
Commercial	Solar Water Heater	Offices	New	N_OF_Solar V	1.12	0.45	2.51	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Restaurants	New	N_RS_PSC to	1.15	0.56	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Restaurants	New	N_RS_PSC to	1.77	0.56	3.15	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Restaurants	Existing	E_RS_PSC to	1.15	0.56	2.05	0	0	4
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Restaurants	Existing	E_RS_PSC to	1.77	0.56	3.15	1	0	4
Commercial	Thermal Energy Storage	Restaurants	New	N_RS_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Programmable Thermostat	Restaurants	New	N_RS_Progra	4.20	0.99	4.25	0	0	0
Commercial	HVAC tune-up_RTU	Restaurants	New	N_RS_HVAC	1.28	0.84	1.54	0	0	0
Commercial	HVAC tune-up	Restaurants	New	N_RS_HVAC	1.95	0.95	2.05	0	0	0
Commercial	Facility Commissioning	Restaurants	New	N_RS_Facilit	1.45	0.67	2.18	0	0	0
Commercial	Dedicated Outdoor Air System on VRF unit	Restaurants	New	N_RS_Dedica	1.34	0.89	1.51	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Restaurants	New	N_RS_Chille	2.43	0.52	4.69	0	0	2
Commercial	Ceiling Insulation(R2 to R38)	Restaurants	New	N_RS_Ceiling	4.70	1.25	3.76	0	0	0
Commercial	Wall Insulation	Restaurants	Existing	E_RS_Wall In	3.51	1.25	2.81	0	0	0
Commercial	Thermal Energy Storage	Restaurants	Existing	E_RS_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Programmable Thermostat	Restaurants	Existing	E_RS_Progra	4.20	0.99	4.25	2	0	6
Commercial	Low U-Value Windows	Restaurants	Existing	E_RS_Low U	1.46	1.12	1.31	6	0	17
Commercial	HVAC tune-up_RTU	Restaurants	Existing	E_RS_HVAC	1.28	0.84	1.54	5	0	13
Commercial	HVAC tune-up	Restaurants	Existing	E_RS_HVAC	1.95	0.95	2.05	0	0	0
Commercial	Dedicated Outdoor Air System on VRF unit	Restaurants	Existing	E_RS_Dedica	1.34	0.89	1.51	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Restaurants	Existing	E_RS_Chille	2.43	0.52	4.69	0	0	2
Commercial	Ceiling Insulation(R2 to R38)	Restaurants	Existing	E_RS_Ceiling	4.79	1.25	3.83	0	0	0
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Restaurants	Turnover	T_RS_Variab	1.40	0.89	1.57	0	0	1
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Restaurants	New	N_RS_Variab	1.40	0.89	1.57	0	0	0
Commercial	VSD Controlled Compressor	Restaurants	New	N_RS_VSD C	2.06	0.56	3.66	0	0	0
Commercial	VSD Controlled Compressor	Restaurants	Existing	E_RS_VSD C	2.06	0.56	3.66	0	0	1
Commercial	Variable Speed Pool Pump	Restaurants	Turnover	T_RS_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Restaurants	Turnover	T_RS_Solar F	1.08	0.33	3.23	0	0	0
Commercial	Variable Speed Pool Pump	Restaurants	New	N_RS_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Restaurants	New	N_RS_Solar I	1.08	0.33	3.23	0	0	0
Commercial	Efficient Battery Charger	Restaurants	Turnover	T_RS_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Restaurants	New	N_RS_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Restaurants	Turnover	T_RS_Energy	1.32	0.48	2.73	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Restaurants	New	N_RS_Energy	1.32	0.48	2.73	0	0	0
Commercial	Demand Controlled Ventilation	Restaurants	New	N_RS_Demar	1.51	1.25	1.20	0	0	0
Commercial	Demand Controlled Ventilation	Restaurants	Existing	E_RS_Demar	1.51	1.25	1.20	0	1	3
Commercial	High Bay LED	Restaurants	Turnover	T_RS_High B	3.42	0.68	5.05	0	0	0
Commercial	High Bay LED	Restaurants	New	N_RS_High B	3.42	0.68	5.05	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Restaurants	Turnover	T_RS_High E	3.56	0.89	4.01	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Restaurants	Turnover	T_RS_High E	2.40	1.17	2.06	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Restaurants	Turnover	T_RS_High E	4.13	1.17	3.54	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Restaurants	New	N_RS_High E	3.56	0.89	4.01	0	0	0

Residential	Storm Door	Manufactured Home	New	N_MH_Storm	0.55	1.27	0.43	0	0	0	Fail TRC
Residential	Wall Insulation	Multi-Family	Existing	E_MF_Wall I	0.73	1.27	0.57	0	0	0	Fail TRC
Residential	Wall Insulation	Single Family	New	N_SF_Wall In	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Wall Insulation	Multi-Family	New	N_MF_Wall I	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Wall Insulation	Manufactured Home	New	N_MH_Wall	0.00	0.00	0.00	0	0	0	Fail TRC
Residential	Window Sun Protection	Single Family	Existing	E_SF_Windo	0.24	0.86	0.28	0	0	0	Fail TRC
Residential	Window Sun Protection	Multi-Family	Existing	E_MF_Windo	0.20	0.86	0.24	0	0	0	Fail TRC
Residential	Window Sun Protection	Manufactured Home	Existing	E_MH_Wind	0.16	0.86	0.19	0	0	0	Fail TRC
Residential	Window Sun Protection	Single Family	New	N_SF_Windo	0.24	0.86	0.28	0	0	0	Fail TRC
Residential	Window Sun Protection	Multi-Family	New	N_MF_Windo	0.20	0.86	0.24	0	0	0	Fail TRC
Residential	Window Sun Protection	Manufactured Home	New	N_MH_Wind	0.16	0.86	0.19	0	0	0	Fail TRC
Residential	Exterior Lighting Controls	Single Family	Existing	E_SF_Exterio	0.28	0.25	1.12	0	0	0	Fail TRC
Residential	Exterior Lighting Controls	Multi-Family	Existing	E_MF_Exteri	0.28	0.25	1.12	0	0	0	Fail TRC
Residential	Exterior Lighting Controls	Manufactured Home	Existing	E_MH_Exteri	0.28	0.25	1.12	0	0	0	Fail TRC
Residential	Exterior Lighting Controls	Single Family	New	N_SF_Exterio	0.28	0.25	1.12	0	0	0	Fail TRC
Residential	Exterior Lighting Controls	Multi-Family	New	N_MF_Exteri	0.28	0.25	1.12	0	0	0	Fail TRC
Residential	Exterior Lighting Controls	Manufactured Home	New	N_MH_Exter	0.28	0.25	1.12	0	0	0	Fail TRC
Residential	Interior Lighting Controls	Single Family	Existing	E_SF_Interior	0.20	0.41	0.48	0	0	0	Fail TRC
Residential	Interior Lighting Controls	Multi-Family	Existing	E_MF_Interio	0.20	0.41	0.48	0	0	0	Fail TRC
Residential	Interior Lighting Controls	Manufactured Home	Existing	E_MH_Interio	0.20	0.41	0.48	0	0	0	Fail TRC
Residential	Interior Lighting Controls	Single Family	New	N_SF_Interio	0.20	0.41	0.48	0	0	0	Fail TRC
Residential	Interior Lighting Controls	Multi-Family	New	N_MF_Interio	0.20	0.41	0.48	0	0	0	Fail TRC
Residential	Interior Lighting Controls	Manufactured Home	New	N_MH_Interio	0.20	0.41	0.48	0	0	0	Fail TRC
Residential	Solar Attic Fan	Single Family	Existing	E_SF_Solar A	0.47	0.83	0.57	0	0	0	Fail TRC
Residential	Solar Attic Fan	Multi-Family	Existing	E_MF_Solar	0.23	0.83	0.27	0	0	0	Fail TRC
Residential	Solar Attic Fan	Manufactured Home	Existing	E_MH_Solar	0.31	0.83	0.38	0	0	0	Fail TRC
Residential	Solar Attic Fan	Single Family	New	N_SF_Solar A	0.47	0.83	0.57	0	0	0	Fail TRC
Residential	Solar Attic Fan	Multi-Family	New	N_MF_Solar	0.23	0.83	0.27	0	0	0	Fail TRC
Residential	Solar Attic Fan	Manufactured Home	New	N_MH_Solar	0.31	0.83	0.38	0	0	0	Fail TRC
Commercial	Energy Star Commercial Oven	Assembly	Turnover	T_AS_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	College and University	Turnover	T_CU_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Grocery	Turnover	T_GR_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Healthcare	Turnover	T_HC_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Hospitals	Turnover	T_HS_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Institutional	Turnover	T_IN_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Lodging/Hospitality	Turnover	T_LG_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Miscellaneous	Turnover	T_MS_Energ	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Offices	Turnover	T_OF_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Restaurants	Turnover	T_RS_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Retail	Turnover	T_RT_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Schools K-12	Turnover	T_SC_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Warehouse	Turnover	T_WR_Energ	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Assembly	New	N_AS_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	College and University	New	N_CU_Energ	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Grocery	New	N_GR_Energ	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Healthcare	New	N_HC_Energ	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Hospitals	New	N_HS_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Institutional	New	N_IN_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Lodging/Hospitality	New	N_LG_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Miscellaneous	New	N_MS_Energ	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Offices	New	N_OF_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Restaurants	New	N_RS_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Retail	New	N_RT_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Schools K-12	New	N_SC_Energy	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Oven	Warehouse	New	N_WR_Energ	3.00	0.61	4.93	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Fryer	Assembly	Turnover	T_AS_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	College and University	Turnover	T_CU_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Grocery	Turnover	T_GR_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Healthcare	Turnover	T_HC_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Hospitals	Turnover	T_HS_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Institutional	Turnover	T_IN_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Lodging/Hospitality	Turnover	T_LG_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Miscellaneous	Turnover	T_MS_Energ	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Offices	Turnover	T_OF_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Restaurants	Turnover	T_RS_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Retail	Turnover	T_RT_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Schools K-12	Turnover	T_SC_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Warehouse	Turnover	T_WR_Energ	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Assembly	New	N_AS_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	College and University	New	N_CU_Energ	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Grocery	New	N_GR_Energ	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Healthcare	New	N_HC_Energ	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Hospitals	New	N_HS_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Institutional	New	N_IN_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Lodging/Hospitality	New	N_LG_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Miscellaneous	New	N_MS_Energ	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Offices	New	N_OF_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Restaurants	New	N_RS_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Retail	New	N_RT_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Schools K-12	New	N_SC_Energy	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Fryer	Warehouse	New	N_WR_Energ	0.23	0.61	0.38	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Assembly	Turnover	T_AS_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	College and University	Turnover	T_CU_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Grocery	Turnover	T_GR_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Healthcare	Turnover	T_HC_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Hospitals	Turnover	T_HS_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Institutional	Turnover	T_IN_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Lodging/Hospitality	Turnover	T_LG_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Miscellaneous	Turnover	T_MS_Energ	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Offices	Turnover	T_OF_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Restaurants	Turnover	T_RS_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Retail	Turnover	T_RT_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Schools K-12	Turnover	T_SC_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Warehouse	Turnover	T_WR_Energ	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Assembly	New	N_AS_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	College and University	New	N_CU_Energ	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Grocery	New	N_GR_Energ	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Healthcare	New	N_HC_Energ	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Hospitals	New	N_HS_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Institutional	New	N_IN_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Lodging/Hospitality	New	N_LG_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Miscellaneous	New	N_MS_Energ	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Offices	New	N_OF_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Restaurants	New	N_RS_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Retail	New	N_RT_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Schools K-12	New	N_SC_Energy	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Griddle	Warehouse	New	N_WR_Energ	0.00	0.61	0.00	0	0	0	Fail TRC
Commercial	Energy Star Steamer	Assembly	Turnover	T_AS_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	College and University	Turnover	T_CU_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Grocery	Turnover	T_GR_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Healthcare	Turnover	T_HC_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Hospitals	Turnover	T_HS_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Institutional	Turnover	T_IN_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Lodging/Hospitality	Turnover	T_LG_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Miscellaneous	Turnover	T_MS_Energ	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Offices	Turnover	T_OF_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Restaurants	Turnover	T_RS_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Retail	Turnover	T_RT_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Schools K-12	Turnover	T_SC_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold

Commercial	Energy Star Commercial Oven	Restaurants	New	N_RS_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Retail	New	N_RT_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Schools K-12	New	N_SC_Energy	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Commercial Oven	Warehouse	New	N_WR_Energ	3.00	0.61	4.93	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Assembly	Turnover	T_AS_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	College and University	Turnover	T_CU_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Grocery	Turnover	T_GR_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Healthcare	Turnover	T_HC_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Hospitals	Turnover	T_HS_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Institutional	Turnover	T_IN_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Lodging/Hospitality	Turnover	T_LG_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Miscellaneous	Turnover	T_MS_Energ	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Offices	Turnover	T_OF_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Restaurants	Turnover	T_RS_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Retail	Turnover	T_RT_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Schools K-12	Turnover	T_SC_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Warehouse	Turnover	T_WR_Energ	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Assembly	New	N_AS_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	College and University	New	N_CU_Energ	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Grocery	New	N_GR_Energ	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Healthcare	New	N_HC_Energ	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Hospitals	New	N_HS_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Institutional	New	N_IN_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Lodging/Hospitality	New	N_LG_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Miscellaneous	New	N_MS_Energ	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Offices	New	N_OF_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Restaurants	New	N_RS_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Retail	New	N_RT_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Schools K-12	New	N_SC_Energy	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Fryer	Warehouse	New	N_WR_Energ	0.23	0.61	0.38	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Assembly	Turnover	T_AS_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	College and University	Turnover	T_CU_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Grocery	Turnover	T_GR_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Healthcare	Turnover	T_HC_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Hospitals	Turnover	T_HS_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Institutional	Turnover	T_IN_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Lodging/Hospitality	Turnover	T_LG_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Miscellaneous	Turnover	T_MS_Energ	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Offices	Turnover	T_OF_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Restaurants	Turnover	T_RS_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Retail	Turnover	T_RT_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Schools K-12	Turnover	T_SC_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Warehouse	Turnover	T_WR_Energ	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Assembly	New	N_AS_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	College and University	New	N_CU_Energ	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Grocery	New	N_GR_Energ	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Healthcare	New	N_HC_Energ	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Hospitals	New	N_HS_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Institutional	New	N_IN_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Lodging/Hospitality	New	N_LG_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Miscellaneous	New	N_MS_Energ	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Offices	New	N_OF_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Restaurants	New	N_RS_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Retail	New	N_RT_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Schools K-12	New	N_SC_Energy	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Griddle	Warehouse	New	N_WR_Energ	0.00	0.61	0.00	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Assembly	Turnover	T_AS_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	College and University	Turnover	T_CU_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Grocery	Turnover	T_GR_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Healthcare	Turnover	T_HC_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Hospitals	Turnover	T_HS_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Institutional	Turnover	T_IN_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Lodging/Hospitality	Turnover	T_LG_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Miscellaneous	Turnover	T_MS_Energ	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Offices	Turnover	T_OF_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Restaurants	Turnover	T_RS_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Retail	Turnover	T_RT_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Schools K-12	Turnover	T_SC_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Warehouse	Turnover	T_WR_Energ	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Assembly	New	N_AS_Energ	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	College and University	New	N_CU_Energ	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Grocery	New	N_GR_Energ	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Healthcare	New	N_HC_Energ	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Hospitals	New	N_HS_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Institutional	New	N_IN_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Lodging/Hospitality	New	N_LG_Energ	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Miscellaneous	New	N_MS_Energ	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Offices	New	N_OF_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Restaurants	New	N_RS_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Retail	New	N_RT_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Schools K-12	New	N_SC_Energy	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Hot Food Holding Cabinet	Warehouse	New	N_WR_Energ	1.28	0.65	1.97	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Assembly	Turnover	T_AS_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	College and University	Turnover	T_CU_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Grocery	Turnover	T_GR_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Healthcare	Turnover	T_HC_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Hospitals	Turnover	T_HS_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Institutional	Turnover	T_IN_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Lodging/Hospitality	Turnover	T_LG_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Miscellaneous	Turnover	T_MS_Energ	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Offices	Turnover	T_OF_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Restaurants	Turnover	T_RS_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Retail	Turnover	T_RT_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Schools K-12	Turnover	T_SC_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Warehouse	Turnover	T_WR_Energ	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Assembly	New	N_AS_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	College and University	New	N_CU_Energ	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Grocery	New	N_GR_Energ	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Healthcare	New	N_HC_Energ	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Hospitals	New	N_HS_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Institutional	New	N_IN_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Lodging/Hospitality	New	N_LG_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Miscellaneous	New	N_MS_Energ	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Offices	New	N_OF_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Restaurants	New	N_RS_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Retail	New	N_RT_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Schools K-12	New	N_SC_Energy	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Energy Star Steamer	Warehouse	New	N_WR_Energ	6.42	0.58	11.14	0	0	0	Fail RIM
Commercial	Induction Cooktops	Assembly	Turnover	T_AS_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	College and University	Turnover	T_CU_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Grocery	Turnover	T_GR_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Healthcare	Turnover	T_HC_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Hospitals	Turnover	T_HS_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Institutional	Turnover	T_IN_Inducti	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Lodging/Hospitality	Turnover	T_LG_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Miscellaneous	Turnover	T_MS_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Offices	Turnover	T_OF_Induct	0.39	0.67	0.58	0	0	0	Fail RIM

Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Restaurants	New	N_RS_High E	2.40	1.17	2.06	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Restaurants	New	N_RS_High E	4.13	1.17	3.54	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Restaurants	Turnover	T_RS_Energy	2.59	0.54	4.78	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Restaurants	New	N_RS_Energy	2.59	0.54	4.78	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Restaurants	Turnover	T_RS_Energy	1.28	0.65	1.97	2	1	10
Commercial	Efficient Exhaust Hood	Restaurants	Turnover	T_RS_Efficie	3.36	0.75	4.49	1	0	4
Commercial	Efficient Exhaust Hood	Restaurants	New	N_RS_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Restaurants	New	N_RS_Energy	1.28	0.65	1.97	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Retail	New	N_RT_PSC to	1.19	0.58	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Retail	New	N_RT_PSC to	1.84	0.58	3.15	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Retail	Existing	E_RT_PSC to	1.19	0.58	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Retail	Existing	E_RT_PSC to	1.84	0.58	3.15	0	0	0
Commercial	Facility Energy Management System	Retail	New	N_RT_Facilit	2.18	0.84	2.60	0	0	0
Commercial	Facility Energy Management System	Retail	Existing	E_RT_Facilit	2.18	0.84	2.60	3	1	12
Commercial	Thermal Energy Storage	Retail	New	N_RT_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Smart Thermostat	Retail	New	N_RT_Smart	1.63	0.99	1.65	0	0	0
Commercial	HVAC tune-up_RTU	Retail	New	N_RT_HVAC	1.01	0.84	1.20	0	0	0
Commercial	HVAC tune-up	Retail	New	N_RT_HVAC	1.53	0.95	1.60	0	0	0
Commercial	Duct Sealing Repair	Retail	New	N_RT_Duct S	9.12	1.64	5.56	0	0	0
Commercial	Dedicated Outdoor Air System on VRF unit	Retail	New	N_RT_Dedica	1.03	0.89	1.16	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Retail	New	N_RT_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Retail	New	N_RT_Ceiling	4.70	1.25	3.76	0	0	0
Commercial	Wall Insulation	Retail	Existing	E_RT_Wall I	3.46	1.25	2.76	3	0	13
Commercial	Thermal Energy Storage	Retail	Existing	E_RT_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Smart Thermostat	Retail	Existing	E_RT_Smart	1.63	0.99	1.65	6	0	16
Commercial	Low U-Value Windows	Retail	Existing	E_RT_Low U	1.46	1.12	1.31	4	0	12
Commercial	HVAC tune-up_RTU	Retail	Existing	E_RT_HVAC	1.01	0.84	1.20	8	0	21
Commercial	HVAC tune-up	Retail	Existing	E_RT_HVAC	1.53	0.95	1.60	0	0	0
Commercial	Duct Sealing Repair	Retail	Existing	E_RT_Duct S	9.12	1.64	5.56	4	0	20
Commercial	Dedicated Outdoor Air System on VRF unit	Retail	Existing	E_RT_Dedica	1.03	0.89	1.16	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Retail	Existing	E_RT_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Retail	Existing	E_RT_Ceiling	4.79	1.25	3.83	0	0	0
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Retail	Turnover	T_RT_Variab	1.07	0.89	1.21	0	0	1
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Retail	New	N_RT_Variab	1.07	0.89	1.21	0	0	0
Commercial	ECM Motors on Furnaces	Retail	New	N_RT_ECM M	2.45	0.48	5.06	0	0	0
Commercial	ECM Motors on Furnaces	Retail	Existing	E_RT_ECM M	2.45	0.48	5.06	0	0	0
Commercial	VSD Controlled Compressor	Retail	New	N_RT_VSD C	2.22	0.61	3.66	0	0	0
Commercial	VSD Controlled Compressor	Retail	Existing	E_RT_VSD C	2.22	0.61	3.66	1	0	3
Commercial	Variable Speed Pool Pump	Retail	Turnover	T_RT_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Retail	Turnover	T_RT_Solar F	1.08	0.33	3.23	0	0	0
Commercial	Variable Speed Pool Pump	Retail	New	N_RT_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Retail	New	N_RT_Solar F	1.08	0.33	3.23	0	0	0
Commercial	Premium T8 - Fixture Replacement	Retail	Turnover	T_RT_Premiu	1.10	0.65	1.70	2	0	10
Commercial	Premium T8 - Fixture Replacement	Retail	New	N_RT_Premiu	1.10	0.65	1.70	0	0	0
Commercial	Efficient Battery Charger	Retail	Turnover	T_RT_Efficie	1.63	1.02	1.59	3	0	5
Commercial	Efficient Battery Charger	Retail	New	N_RT_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Retail	Turnover	T_RT_Energy	1.32	0.48	2.73	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Retail	New	N_RT_Energy	1.32	0.48	2.73	0	0	0
Commercial	Demand Controlled Ventilation	Retail	New	N_RT_Demar	3.38	1.25	2.69	0	0	0
Commercial	Demand Controlled Ventilation	Retail	Existing	E_RT_Demar	3.38	1.25	2.69	2	10	17
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Retail	Turnover	T_RT_High E	2.79	0.89	3.15	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Retail	Turnover	T_RT_High E	1.88	1.17	1.61	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Retail	Turnover	T_RT_High E	3.24	1.17	2.78	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Retail	New	N_RT_High E	2.79	0.89	3.15	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Retail	New	N_RT_High E	1.88	1.17	1.61	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Retail	New	N_RT_High E	3.24	1.17	2.78	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Retail	Turnover	T_RT_Energy	2.78	0.58	4.78	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Retail	New	N_RT_Energy	2.78	0.58	4.78	0	0	3
Commercial	Energy Star Hot Food Holding Cabinet	Retail	Turnover	T_RT_Energy	1.28	0.65	1.97	0	0	0
Commercial	Efficient Exhaust Hood	Retail	Turnover	T_RT_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Efficient Exhaust Hood	Retail	New	N_RT_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Retail	New	N_RT_Energy	1.28	0.65	1.97	0	0	0
Commercial	Retro-Commissioning	Schools K-12	New	N_SC_Retro-	1.99	0.93	2.15	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Schools K-12	New	N_SC_PSC to	1.15	0.56	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Schools K-12	New	N_SC_PSC to	1.77	0.56	3.15	0	0	0
Commercial	Retro-Commissioning	Schools K-12	Existing	E_SC_Retro-	1.99	0.93	2.15	1	1	4
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Schools K-12	Existing	E_SC_PSC to	1.15	0.56	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Schools K-12	Existing	E_SC_PSC to	1.77	0.56	3.15	0	0	0
Commercial	Facility Energy Management System	Schools K-12	New	N_SC_Facilit	1.56	0.73	2.14	0	0	0
Commercial	Facility Energy Management System	Schools K-12	Existing	E_SC_Facility	1.56	0.73	2.14	0	0	0
Commercial	Thermal Energy Storage	Schools K-12	New	N_SC_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	HVAC tune-up	Schools K-12	New	N_SC_HVAC	1.33	0.95	1.39	0	0	0
Commercial	Duct Sealing Repair	Schools K-12	New	N_SC_Duct S	7.49	1.64	4.57	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Schools K-12	New	N_SC_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Schools K-12	New	N_SC_Ceiling	4.58	1.22	3.76	0	0	0
Commercial	Wall Insulation	Schools K-12	Existing	E_SC_Wall I	3.47	1.22	2.85	0	0	0
Commercial	Thermal Energy Storage	Schools K-12	Existing	E_SC_Therm	2.46	9999.00	9999.00	1	0	0
Commercial	Low U-Value Windows	Schools K-12	Existing	E_SC_Low U	1.46	1.12	1.31	1	0	2
Commercial	HVAC tune-up	Schools K-12	Existing	E_SC_HVAC	1.33	0.95	1.39	0	0	0
Commercial	Duct Sealing Repair	Schools K-12	Existing	E_SC_Duct S	7.49	1.64	4.57	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Schools K-12	Existing	E_SC_Chille	2.43	0.52	4.69	0	0	4
Commercial	Ceiling Insulation(R2 to R38)	Schools K-12	Existing	E_SC_Ceiling	4.67	1.22	3.83	0	0	0
Commercial	ECM Motors on Furnaces	Schools K-12	New	N_SC_ECM M	1.23	0.26	4.66	0	0	0
Commercial	ECM Motors on Furnaces	Schools K-12	Existing	E_SC_ECM M	1.23	0.26	4.66	0	0	0
Commercial	VSD Controlled Compressor	Schools K-12	New	N_SC_VSD C	2.06	0.56	3.66	0	0	0
Commercial	VSD Controlled Compressor	Schools K-12	Existing	E_SC_VSD C	2.06	0.56	3.66	0	0	0
Commercial	Variable Speed Pool Pump	Schools K-12	Turnover	T_SC_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Schools K-12	Turnover	T_SC_Solar F	1.08	0.33	3.23	0	0	0
Commercial	Variable Speed Pool Pump	Schools K-12	New	N_SC_Variab	1.65	0.70	2.35	0	0	0
Commercial	Solar Pool Heater	Schools K-12	New	N_SC_Solar F	1.08	0.33	3.23	0	0	0
Commercial	Efficient Battery Charger	Schools K-12	Turnover	T_SC_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Efficient Battery Charger	Schools K-12	New	N_SC_Efficie	1.63	1.02	1.59	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Schools K-12	Turnover	T_SC_Energy	1.32	0.48	2.73	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Schools K-12	New	N_SC_Energy	1.32	0.48	2.73	0	0	0
Commercial	High Bay LED	Schools K-12	Turnover	T_SC_High B	2.43	0.68	3.58	0	0	0
Commercial	High Bay Fluorescent (T5)	Schools K-12	Turnover	T_SC_High B	3.58	0.68	5.28	0	0	0
Commercial	High Bay LED	Schools K-12	New	N_SC_High E	2.43	0.68	3.58	0	0	0
Commercial	High Bay Fluorescent (T5)	Schools K-12	New	N_SC_High E	3.58	0.68	5.28	0	0	0
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Schools K-12	Turnover	T_SC_High E	2.43	0.89	2.74	0	0	1
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Schools K-12	Turnover	T_SC_High E	1.64	1.17	1.40	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Schools K-12	Turnover	T_SC_High E	2.82	1.17	2.41	0	0	1
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Schools K-12	New	N_SC_High E	2.43	0.89	2.74	0	0	0
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Schools K-12	New	N_SC_High E	1.64	1.17	1.40	0	0	0
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Schools K-12	New	N_SC_High E	2.82	1.17	2.41	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Schools K-12	Turnover	T_SC_Energy	2.59	0.54	4.78	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Schools K-12	New	N_SC_Energy	2.59	0.54	4.78	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Schools K-12	Turnover	T_SC_Energy	1.28	0.65	1.97	0	0	0
Commercial	Efficient Exhaust Hood	Schools K-12	Turnover	T_SC_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Efficient Exhaust Hood	Schools K-12	New	N_SC_Efficie	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Schools K-12	New	N_SC_Energy	1.28	0.65	1.97	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Warehouse	New	N_WR_PSC t	1.19	0.58	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Warehouse	New	N_WR_PSC t	1.84	0.58	3.15	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Warehouse	Existing	E_WR_PSC t	1.19	0.58	2.05	0	0	0
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Warehouse	Existing	E_WR_PSC t	1.84	0.58	3.15	0	0	0
Commercial	Thermal Energy Storage	Warehouse	New	N_WR_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Duct Sealing Repair	Warehouse	New	N_WR_Duct	2.41	1.64	1.47	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Warehouse	New	N_WR_Chille	2.43	0.52	4.69	0	0	0

Commercial	Energy Star Steamer	Warehouse	Turnover	T_WR_Energ	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Assembly	New	N_AS_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	College and University	New	N_CU_Energ	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Grocery	New	N_GR_Energ	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Healthcare	New	N_HC_Energ	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Hospitals	New	N_HS_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Institutional	New	N_IN_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Lodging/Hospitality	New	N_LG_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Miscellaneous	New	N_MS_Energ	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Offices	New	N_OF_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Restaurants	New	N_RS_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Retail	New	N_RT_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Schools K-12	New	N_SC_Energy	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Steamer	Warehouse	New	N_WR_Energ	6.42	0.58	11.14	0	0	0	Fail 2-year Threshold
Commercial	Induction Cooktops	Assembly	Turnover	T_AS_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	College and University	Turnover	T_CU_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Grocery	Turnover	T_GR_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Healthcare	Turnover	T_HC_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Hospitals	Turnover	T_HS_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Institutional	Turnover	T_IN_Inducti	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Lodging/Hospitality	Turnover	T_LG_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Miscellaneous	Turnover	T_MS_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Offices	Turnover	T_OF_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Restaurants	Turnover	T_RS_Inducti	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Retail	Turnover	T_RT_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Schools K-12	Turnover	T_SC_Inducti	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Warehouse	Turnover	T_WR_Induc	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Assembly	New	N_AS_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	College and University	New	N_CU_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Grocery	New	N_GR_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Healthcare	New	N_HC_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Hospitals	New	N_HS_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Institutional	New	N_IN_Inducti	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Lodging/Hospitality	New	N_LG_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Miscellaneous	New	N_MS_Induc	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Offices	New	N_OF_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Restaurants	New	N_RS_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Retail	New	N_RT_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Schools K-12	New	N_SC_Induct	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Induction Cooktops	Warehouse	New	N_WR_Induc	0.39	0.67	0.58	0	0	0	Fail TRC
Commercial	Energy Star Commercial Dishwasher	Assembly	Turnover	T_AS_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	College and University	Turnover	T_CU_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Grocery	Turnover	T_GR_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Healthcare	Turnover	T_HC_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Hospitals	Turnover	T_HS_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Institutional	Turnover	T_IN_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Lodging/Hospitality	Turnover	T_LG_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Miscellaneous	Turnover	T_MS_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Offices	Turnover	T_OF_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Restaurants	Turnover	T_RS_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Retail	Turnover	T_RT_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Schools K-12	Turnover	T_SC_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Warehouse	Turnover	T_WR_Energ	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Assembly	New	N_AS_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	College and University	New	N_CU_Energ	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Grocery	New	N_GR_Energ	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Healthcare	New	N_HC_Energ	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Hospitals	New	N_HS_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Institutional	New	N_IN_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Lodging/Hospitality	New	N_LG_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Miscellaneous	New	N_MS_Energ	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Offices	New	N_OF_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Restaurants	New	N_RS_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Retail	New	N_RT_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Schools K-12	New	N_SC_Energy	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Dishwasher	Warehouse	New	N_WR_Energ	12.68	0.44	28.60	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	College and University	Turnover	T_CU_Heat P	6.41	0.76	8.47	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Grocery	Turnover	T_GR_Heat P	6.56	0.89	7.36	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Healthcare	Turnover	T_HC_Heat P	2.86	0.58	4.91	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Hospitals	Turnover	T_HS_Heat P	7.50	0.76	9.90	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Institutional	Turnover	T_IN_Heat Pu	6.86	0.58	11.78	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Lodging/Hospitality	Turnover	T_LG_Heat P	10.50	0.89	11.78	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Miscellaneous	Turnover	T_MS_Heat P	6.43	0.58	11.05	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Offices	Turnover	T_OF_Heat P	5.96	0.58	10.23	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Restaurants	Turnover	T_RS_Heat P	5.47	0.89	6.14	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Retail	Turnover	T_RT_Heat P	6.50	0.89	7.29	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Schools K-12	Turnover	T_SC_Heat P	0.89	0.58	1.53	0	0	0	Fail TRC
Commercial	Heat Pump Water Heater	Warehouse	Turnover	T_WR_Heat P	4.29	0.58	7.36	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	College and University	New	N_CU_Heat P	6.41	0.76	8.47	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Grocery	New	N_GR_Heat P	6.56	0.89	7.36	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Healthcare	New	N_HC_Heat P	2.86	0.58	4.91	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Hospitals	New	N_HS_Heat P	7.50	0.76	9.90	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Institutional	New	N_IN_Heat Pu	6.86	0.58	11.78	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Lodging/Hospitality	New	N_LG_Heat P	10.50	0.89	11.78	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Miscellaneous	New	N_MS_Heat P	6.43	0.58	11.05	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Offices	New	N_OF_Heat P	5.96	0.58	10.23	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Restaurants	New	N_RS_Heat P	5.47	0.89	6.14	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Retail	New	N_RT_Heat P	6.50	0.89	7.29	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Water Heater	Schools K-12	New	N_SC_Heat P	0.89	0.58	1.53	0	0	0	Fail TRC
Commercial	Heat Pump Water Heater	Warehouse	New	N_WR_Heat P	4.29	0.58	7.36	0	0	0	Fail 2-year Threshold
Commercial	Instantaneous Hot Water System	Assembly	Turnover	T_AS_Instant	0.10	0.56	0.18	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	College and University	Turnover	T_CU_Instant	0.31	0.76	0.40	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Grocery	Turnover	T_GR_Instant	0.19	0.53	0.35	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Healthcare	Turnover	T_HC_Instant	0.13	0.56	0.23	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Hospitals	Turnover	T_HS_Instant	0.36	0.76	0.47	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Institutional	Turnover	T_IN_Instanta	0.31	0.56	0.56	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Lodging/Hospitality	Turnover	T_LG_Instant	0.30	0.53	0.56	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Miscellaneous	Turnover	T_MS_Instan	0.29	0.56	0.53	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Offices	Turnover	T_OF_Instant	0.27	0.56	0.49	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Restaurants	Turnover	T_RS_Instant	0.16	0.53	0.29	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Retail	Turnover	T_RT_Instant	0.19	0.53	0.35	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Schools K-12	Turnover	T_SC_Instant	0.04	0.56	0.07	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Warehouse	Turnover	T_WR_Instan	0.20	0.56	0.35	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Assembly	New	N_AS_Instant	0.10	0.56	0.18	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	College and University	New	N_CU_Instan	0.31	0.76	0.40	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Grocery	New	N_GR_Instan	0.19	0.53	0.35	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Healthcare	New	N_HC_Instan	0.13	0.56	0.23	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Hospitals	New	N_HS_Instant	0.36	0.76	0.47	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Institutional	New	N_IN_Instanta	0.31	0.56	0.56	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Lodging/Hospitality	New	N_LG_Instant	0.30	0.53	0.56	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Miscellaneous	New	N_MS_Instan	0.29	0.56	0.53	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Offices	New	N_OF_Instant	0.27	0.56	0.49	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Restaurants	New	N_RS_Instant	0.16	0.53	0.29	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Retail	New	N_RT_Instant	0.19	0.53	0.35	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Schools K-12	New	N_SC_Instant	0.04	0.56	0.07	0	0	0	Fail TRC
Commercial	Instantaneous Hot Water System	Warehouse	New	N_WR_Instar	0.20	0.56	0.35	0	0	0	Fail TRC
Commercial	Solar Water Heater	Assembly	Turnover	T_AS_Solar V	0.40	0.45	0.90	0	0	0	Fail TRC

Commercial	Induction Cooktops	Restaurants	Turnover	T_RS_Inducti	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Retail	Turnover	T_RT_Inducti	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Schools K-12	Turnover	T_SC_Inducti	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Warehouse	Turnover	T_WR_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Assembly	New	N_AS_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	College and University	New	N_CU_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Grocery	New	N_GR_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Healthcare	New	N_HC_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Hospitals	New	N_HS_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Institutional	New	N_IN_Inducti	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Lodging/Hospitality	New	N_LG_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Miscellaneous	New	N_MS_Induc	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Offices	New	N_OF_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Restaurants	New	N_RS_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Retail	New	N_RT_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Schools K-12	New	N_SC_Induct	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Induction Cooktops	Warehouse	New	N_WR_Induc	0.39	0.67	0.58	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Assembly	Turnover	T_AS_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	College and University	Turnover	T_CU_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Grocery	Turnover	T_GR_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Healthcare	Turnover	T_HC_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Hospitals	Turnover	T_HS_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Institutional	Turnover	T_IN_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Lodging/Hospitality	Turnover	T_LG_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Miscellaneous	Turnover	T_MS_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Offices	Turnover	T_OF_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Restaurants	Turnover	T_RS_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Retail	Turnover	T_RT_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Schools K-12	Turnover	T_SC_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Warehouse	Turnover	T_WR_Energ	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Assembly	New	N_AS_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	College and University	New	N_CU_Energ	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Grocery	New	N_GR_Energ	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Healthcare	New	N_HC_Energ	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Hospitals	New	N_HS_Energ	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Institutional	New	N_IN_Energy	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Lodging/Hospitality	New	N_LG_Energ	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Miscellaneous	New	N_MS_Energ	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Offices	New	N_OF_Energ	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Restaurants	New	N_RS_Energ	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Retail	New	N_RT_Energ	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Schools K-12	New	N_SC_Energ	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Energy Star Commercial Dishwasher	Warehouse	New	N_WR_Energ	12.68	0.44	28.60	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Assembly	Turnover	T_AS_Heat P	2.14	0.58	3.68	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	College and University	Turnover	T_CU_Heat P	6.41	0.76	8.47	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Grocery	Turnover	T_GR_Heat P	6.56	0.89	7.36	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Healthcare	Turnover	T_HC_Heat P	2.86	0.58	4.91	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Hospitals	Turnover	T_HS_Heat P	7.50	0.76	9.90	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Institutional	Turnover	T_IN_Heat Pu	6.86	0.58	11.78	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Lodging/Hospitality	Turnover	T_LG_Heat P	10.50	0.89	11.78	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Miscellaneous	Turnover	T_MS_Heat P	6.43	0.58	11.05	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Offices	Turnover	T_OF_Heat P	5.96	0.58	10.23	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Restaurants	Turnover	T_RS_Heat P	5.47	0.89	6.14	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Retail	Turnover	T_RT_Heat P	6.50	0.89	7.29	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Schools K-12	Turnover	T_SC_Heat P	0.89	0.58	1.53	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Warehouse	Turnover	T_WR_Heat	4.29	0.58	7.36	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Assembly	New	N_AS_Heat P	2.14	0.58	3.68	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	College and University	New	N_CU_Heat P	6.41	0.76	8.47	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Grocery	New	N_GR_Heat P	6.56	0.89	7.36	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Healthcare	New	N_HC_Heat P	2.86	0.58	4.91	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Hospitals	New	N_HS_Heat P	7.50	0.76	9.90	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Institutional	New	N_IN_Heat Pu	6.86	0.58	11.78	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Lodging/Hospitality	New	N_LG_Heat P	10.50	0.89	11.78	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Miscellaneous	New	N_MS_Heat P	6.43	0.58	11.05	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Offices	New	N_OF_Heat P	5.96	0.58	10.23	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Restaurants	New	N_RS_Heat P	5.47	0.89	6.14	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Retail	New	N_RT_Heat P	6.50	0.89	7.29	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Schools K-12	New	N_SC_Heat P	0.89	0.58	1.53	0	0	0	Fail RIM
Commercial	Heat Pump Water Heater	Warehouse	New	N_WR_Heat	4.29	0.58	7.36	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Assembly	Turnover	T_AS_Instant	0.10	0.56	0.18	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	College and University	Turnover	T_CU_Instant	0.31	0.76	0.40	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Grocery	Turnover	T_GR_Instant	0.19	0.53	0.35	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Healthcare	Turnover	T_HC_Instant	0.13	0.56	0.23	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Hospitals	Turnover	T_HS_Instant	0.36	0.76	0.47	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Institutional	Turnover	T_IN_Instanta	0.31	0.56	0.56	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Lodging/Hospitality	Turnover	T_LG_Instant	0.30	0.53	0.56	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Miscellaneous	Turnover	T_MS_Instan	0.29	0.56	0.53	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Offices	Turnover	T_OF_Instant	0.27	0.56	0.49	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Restaurants	Turnover	T_RS_Instant	0.16	0.53	0.29	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Retail	Turnover	T_RT_Instant	0.19	0.53	0.35	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Schools K-12	Turnover	T_SC_Instant	0.04	0.56	0.07	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Warehouse	Turnover	T_WR_Instan	0.20	0.56	0.35	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Assembly	New	N_AS_Instant	0.10	0.56	0.18	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	College and University	New	N_CU_Instan	0.31	0.76	0.40	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Grocery	New	N_GR_Instan	0.19	0.53	0.35	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Healthcare	New	N_HC_Instan	0.13	0.56	0.23	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Hospitals	New	N_HS_Instant	0.36	0.76	0.47	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Institutional	New	N_IN_Instanta	0.31	0.56	0.56	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Lodging/Hospitality	New	N_LG_Instant	0.30	0.53	0.56	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Miscellaneous	New	N_MS_Instan	0.29	0.56	0.53	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Offices	New	N_OF_Instant	0.27	0.56	0.49	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Restaurants	New	N_RS_Instant	0.16	0.53	0.29	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Retail	New	N_RT_Instant	0.19	0.53	0.35	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Schools K-12	New	N_SC_Instant	0.04	0.56	0.07	0	0	0	Fail RIM
Commercial	Instantaneous Hot Water System	Warehouse	New	N_WR_Instar	0.20	0.56	0.35	0	0	0	Fail RIM
Commercial	Solar Water Heater	Assembly	Turnover	T_AS_Solar	0.40	0.45	0.90	0	0	0	Fail RIM
Commercial	Solar Water Heater	College and University	Turnover	T_CU_Solar	0.93	0.45	2.08	0	0	0	Fail RIM
Commercial	Solar Water Heater	Grocery	Turnover	T_GR_Solar	0.81	0.45	1.80	0	0	0	Fail RIM
Commercial	Solar Water Heater	Healthcare	Turnover	T_HC_Solar	0.54	0.45	1.20	0	0	0	Fail RIM
Commercial	Solar Water Heater	Hospitals	Turnover	T_HS_Solar	1.09	0.45	2.43	0	0	0	Fail RIM
Commercial	Solar Water Heater	Institutional	Turnover	T_IN_Solar W	1.29	0.45	2.89	0	0	0	Fail RIM
Commercial	Solar Water Heater	Lodging/Hospitality	Turnover	T_LG_Solar	1.29	0.45	2.89	0	0	0	Fail RIM
Commercial	Solar Water Heater	Miscellaneous	Turnover	T_MS_Solar	1.21	0.45	2.71	0	0	0	Fail RIM
Commercial	Solar Water Heater	Offices	Turnover	T_OF_Solar	1.12	0.45	2.51	0	0	0	Fail RIM
Commercial	Solar Water Heater	Restaurants	Turnover	T_RS_Solar	0.67	0.45	1.50	0	0	0	Fail RIM
Commercial	Solar Water Heater	Retail	Turnover	T_RT_Solar	0.80	0.45	1.79	0	0	0	Fail RIM
Commercial	Solar Water Heater	Schools K-12	Turnover	T_SC_Solar	0.17	0.45	0.38	0	0	0	Fail RIM
Commercial	Solar Water Heater	Warehouse	Turnover	T_WR_Solar	0.81	0.45	1.80	0	0	0	Fail RIM
Commercial	Solar Water Heater	Assembly	New	N_AS_Solar	0.40	0.45	0.90	0	0	0	Fail RIM
Commercial	Solar Water Heater	College and University	New	N_CU_Solar	0.93	0.45	2.08	0	0	0	Fail RIM
Commercial	Solar Water Heater	Grocery	New	N_GR_Solar	0.81	0.45	1.80	0	0	0	Fail RIM
Commercial	Solar Water Heater	Healthcare	New	N_HC_Solar	0.54	0.45	1.20	0	0	0	Fail RIM
Commercial	Solar Water Heater	Hospitals	New	N_HS_Solar	1.09	0.45	2.43	0	0	0	Fail RIM
Commercial	Solar Water Heater	Institutional	New	N_IN_Solar	1.29	0.45	2.89	0	0	0	Fail RIM
Commercial	Solar Water Heater	Lodging/Hospitality	New	N_LG_Solar	1.29	0.45	2.89	0	0	0	Fail RIM
Commercial	Solar Water Heater	Miscellaneous	New	N_MS_Solar	1.21	0.45	2.71	0	0	0	Fail RIM

Commercial	Ceiling Insulation(R2 to R38)	Warehouse	New	N_WR_Ceilin	2.01	0.71	2.83	0	0	0
Commercial	Wall Insulation	Warehouse	Existing	E_WR_Wall	1.99	0.71	2.81	0	0	0
Commercial	Thermal Energy Storage	Warehouse	Existing	E_WR_Therm	2.46	9999.00	9999.00	0	0	0
Commercial	Low U-Value Windows	Warehouse	Existing	E_WR_Low U	1.38	1.06	1.31	0	0	1
Commercial	Duct Sealing Repair	Warehouse	Existing	E_WR_Duct	2.41	1.64	1.47	0	0	0
Commercial	Chilled Water System - Variable Speed Drives	Warehouse	Existing	E_WR_Chille	2.43	0.52	4.69	0	0	0
Commercial	Ceiling Insulation(R2 to R38)	Warehouse	Existing	E_WR_Ceilin	2.01	0.71	2.83	0	0	0
Commercial	High Efficiency PTHP	Warehouse	Turnover	T_WR_High	2.17	1.33	1.63	0	0	0
Commercial	High Efficiency PTAC	Warehouse	Turnover	T_WR_High	2.14	1.35	1.58	0	0	0
Commercial	High Efficiency PTHP	Warehouse	New	N_WR_High	2.17	1.33	1.63	0	0	0
Commercial	High Efficiency PTAC	Warehouse	New	N_WR_High	2.14	1.35	1.58	0	0	0
Commercial	VSD Controlled Compressor	Warehouse	New	N_WR_VSD	2.22	0.61	3.66	0	0	0
Commercial	VSD Controlled Compressor	Warehouse	Existing	E_WR_VSD	2.22	0.61	3.66	0	0	1
Commercial	Solar Pool Heater	Warehouse	Turnover	T_WR_Solar	1.08	0.33	3.23	0	0	0
Commercial	Solar Pool Heater	Warehouse	New	N_WR_Solar	1.08	0.33	3.23	0	0	0
Commercial	Efficient Battery Charger	Warehouse	Turnover	T_WR_Effici	1.63	1.02	1.59	1	0	2
Commercial	Efficient Battery Charger	Warehouse	New	N_WR_Effici	1.63	1.02	1.59	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Warehouse	Turnover	T_WR_Energ	1.32	0.48	2.73	0	0	0
Commercial	Energy Star Uninterruptable Power Supply	Warehouse	New	N_WR_Energ	1.32	0.48	2.73	0	0	0
Commercial	Demand Controlled Ventilation	Warehouse	New	N_WR_Dema	1.26	1.25	1.00	0	0	0
Commercial	Demand Controlled Ventilation	Warehouse	Existing	E_WR_Dema	1.26	1.25	1.00	0	1	1
Commercial	High Bay LED	Warehouse	Turnover	T_WR_High	3.90	0.68	5.75	11	10	57
Commercial	High Bay LED	Warehouse	New	N_WR_High	3.90	0.68	5.75	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Warehouse	Turnover	T_WR_Energ	2.78	0.58	4.78	0	0	0
Commercial	Energy Star Commercial Solid Door Refrigerator	Warehouse	New	N_WR_Energ	2.78	0.58	4.78	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Warehouse	Turnover	T_WR_Energ	1.28	0.65	1.97	0	0	0
Commercial	Efficient Exhaust Hood	Warehouse	Turnover	T_WR_Effici	3.36	0.75	4.49	0	0	0
Commercial	Efficient Exhaust Hood	Warehouse	New	N_WR_Effici	3.36	0.75	4.49	0	0	0
Commercial	Energy Star Hot Food Holding Cabinet	Warehouse	New	N_WR_Energ	1.28	0.65	1.97	0	0	0
Industrial	Process Refrig Controls	Agriculture and Assembly		AA_Process	1.45	0.58	2.50	0	0	0
Industrial	Pump Equipment Upgrade	Agriculture and Assembly		AA_Pump Eq	2.14	0.57	3.73	0	0	3
Industrial	Fan Equipment Upgrades	Agriculture and Assembly		AA_Fan Equi	2.94	0.57	5.12	0	0	2
Industrial	Efficient Lighting - Other Interior Lighting	Agriculture and Assembly		AA_Efficient	1.54	0.58	2.63	1	1	6
Industrial	Efficient Lighting - High Bay	Agriculture and Assembly		AA_Efficient	2.84	0.58	4.86	2	2	13
Industrial	Compressed Air Controls	Agriculture and Assembly		AA_Compres	2.25	0.56	4.02	0	0	3
Industrial	Compressed Air Equipment	Agriculture and Assembly		AA_Compres	2.76	0.57	4.81	1	1	5
Industrial	Process Heat Improved Controls	Chemicals and Plastics		CP_Process H	1.05	0.58	1.81	0	0	0
Industrial	Process Heat Equipment Upgrade	Chemicals and Plastics		CP_Process H	1.79	0.53	3.40	1	1	4
Industrial	Process Refrig Controls	Chemicals and Plastics		CP_Process R	2.02	0.58	3.48	0	0	1
Industrial	Pump Equipment Upgrade	Chemicals and Plastics		CP_Pump Eq	2.80	0.57	4.88	1	1	6
Industrial	Motor Equipment Upgrades	Chemicals and Plastics		CP_Motor Eq	1.91	0.52	3.68	0	0	2
Industrial	Fan Equipment Upgrades	Chemicals and Plastics		CP_Fan Equi	2.80	0.57	4.88	0	0	1
Industrial	Efficient Lighting - Other Interior Lighting	Chemicals and Plastics		CP_Efficient	1.54	0.58	2.63	2	2	11
Industrial	Efficient Lighting - High Bay	Chemicals and Plastics		CP_Efficient	2.84	0.58	4.86	1	1	4
Industrial	Process Refrig Equipment Upgrade	Construction		CS_Process R	2.01	0.53	3.81	0	0	1
Industrial	Efficient Lighting - Other Interior Lighting	Construction		CS_Efficient	1.54	0.58	2.63	0	0	1
Industrial	Efficient Lighting - High Bay	Construction		CS_Efficient	2.84	0.58	4.86	0	0	1
Industrial	HVAC Recommissioning	Construction		CS_HVAC Re	1.82	0.53	3.41	0	0	1
Industrial	Efficient Lighting - Other Interior Lighting	Electrical and Electronic Equip.		EE_Efficient	1.54	0.58	2.63	0	0	3
Industrial	Efficient Lighting - High Bay	Electrical and Electronic Equip.		EE_Efficient	2.84	0.58	4.86	0	0	1
Industrial	Process Refrig Equipment Upgrade	Lumber/Furniture/Pulp/Paper		LP_Process R	1.73	0.53	3.29	0	0	0
Industrial	Pump System Optimization	Lumber/Furniture/Pulp/Paper		LP_Pump Sys	1.62	0.52	3.12	1	1	6
Industrial	Pump Equipment Upgrade	Lumber/Furniture/Pulp/Paper		LP_Pump Eq	2.01	0.57	3.50	1	1	5
Industrial	Fan Equipment Upgrades	Lumber/Furniture/Pulp/Paper		LP_Fan Equi	2.74	0.57	4.78	0	0	4
Industrial	Efficient Lighting - Other Interior Lighting	Lumber/Furniture/Pulp/Paper		LP_Efficient	1.54	0.58	2.63	1	1	4
Industrial	Efficient Lighting - High Bay	Lumber/Furniture/Pulp/Paper		LP_Efficient	2.84	0.58	4.86	0	0	2
Industrial	Process Refrig Controls	Metal Products and Machinery		MM_Process	1.08	0.58	1.86	0	0	0
Industrial	Process Refrig Equipment Upgrade	Metal Products and Machinery		MM_Process	2.12	0.53	4.03	0	0	0
Industrial	Efficient Lighting - Other Interior Lighting	Metal Products and Machinery		MM_Efficient	1.54	0.58	2.63	0	0	2
Industrial	Efficient Lighting - High Bay	Metal Products and Machinery		MM_Efficient	2.84	0.58	4.86	0	0	3
Industrial	Process Refrig Equipment Upgrade	Miscellaneous Manufacturing		MS_Process	1.75	0.53	3.33	0	0	0
Industrial	Motor Equipment Upgrades	Miscellaneous Manufacturing		MS_Motor Eq	1.89	0.52	3.62	0	0	0
Industrial	Efficient Lighting - Other Interior Lighting	Miscellaneous Manufacturing		MS_Efficient	1.54	0.58	2.63	0	0	3
Industrial	Efficient Lighting - High Bay	Miscellaneous Manufacturing		MS_Efficient	2.84	0.58	4.86	0	0	3
Industrial	HVAC Equipment Upgrades	Miscellaneous Manufacturing		MS_HVAC E	2.37	0.61	3.90	2	2	13
Industrial	Efficient Lighting - Other Interior Lighting	Primary Resources Industries		PR_Efficient	1.54	0.58	2.63	0	0	3
Industrial	Efficient Lighting - High Bay	Primary Resources Industries		PR_Efficient	2.84	0.58	4.86	1	1	5
Industrial	HVAC Equipment Upgrades	Primary Resources Industries		PR_HVAC Eq	3.21	0.61	5.29	0	0	1
Industrial	Process Heat Equipment Upgrade	Stone/Clay/Glass/Concrete		ST_Process H	1.79	0.53	3.40	2	2	13
Industrial	Process Refrig Equipment Upgrade	Stone/Clay/Glass/Concrete		ST_Process R	1.61	0.53	3.06	0	0	0
Industrial	Efficient Lighting - Other Interior Lighting	Stone/Clay/Glass/Concrete		ST_Efficient	1.54	0.58	2.63	0	0	2
Industrial	Efficient Lighting - High Bay	Stone/Clay/Glass/Concrete		ST_Efficient	2.84	0.58	4.86	0	0	1
Industrial	Compressed Air Equipment	Stone/Clay/Glass/Concrete		ST_Compress	2.87	0.57	5.00	0	0	1
Industrial	Motor Optimization	Textiles and Leather		TX_Motor Op	1.34	0.52	2.57	0	0	0
Industrial	Efficient Lighting - Other Interior Lighting	Textiles and Leather		TX_Efficient	1.54	0.58	2.63	0	0	0
Industrial	Efficient Lighting - High Bay	Textiles and Leather		TX_Efficient	2.84	0.58	4.86	0	0	0
Industrial	Building Envelope Improvements	Textiles and Leather		TX_Building	2.32	0.59	3.93	0	0	0
Industrial	Pump Equipment Upgrade	Transportation Equipment		TR_Pump Eq	2.50	0.57	4.36	0	0	0
Industrial	Fan Equipment Upgrades	Transportation Equipment		TR_Fan Equi	2.50	0.57	4.36	0	0	0
Industrial	Efficient Lighting - Other Interior Lighting	Transportation Equipment		TR_Efficient	1.54	0.58	2.63	0	0	3
Industrial	Efficient Lighting - High Bay	Transportation Equipment		TR_Efficient	2.84	0.58	4.86	0	0	1
Industrial	HVAC Recommissioning	Transportation Equipment		TR_HVAC Re	1.81	0.53	3.39	0	0	1
Industrial	Process Refrig Equipment Upgrade	Water and Wastewater		WW_Process	2.01	0.53	3.81	0	0	0
Industrial	Efficient Lighting - Other Interior Lighting	Water and Wastewater		WW_Efficien	1.54	0.58	2.63	0	0	0
Industrial	Efficient Lighting - High Bay	Water and Wastewater		WW_Efficien	2.84	0.58	4.86	0	0	0
Industrial	HVAC Recommissioning	Water and Wastewater		WW_HVAC	1.82	0.53	3.41	0	0	0
Residential	Central air conditioner - Load Shed	Single Family	Existing		Passed	Passed	Passed	748	0	0
Residential	Central air conditioner - Load Shed	Multi Family	Existing		Passed	Passed	Passed	182	0	0
Residential	Central air conditioner - Load Shed	Mobile Home/Other	Existing		Passed	Passed	Passed	135	0	0
Residential	Central Heating - Load Shed	Single Family	Existing		Passed	Passed	Passed	0	1,486	0
Residential	Central Heating - Load Shed	Multi Family	Existing		Passed	Passed	Passed	0	434	0
Residential	Central Heating - Load Shed	Mobile Home/Other	Existing		Passed	Passed	Passed	0	276	0
Residential	Central air conditioner - 50% cycling	Single Family	Existing		Passed	Passed	Passed	0	0	0
Residential	Central air conditioner - 50% cycling	Multi Family	Existing		Passed	Passed	Passed	0	0	0
Residential	Central air conditioner - 50% cycling	Mobile Home/Other	Existing		Passed	Passed	Passed	0	0	0
Residential	Central Heating - 50% cycling	Single Family	Existing		Passed	Passed	Passed	0	0	0
Residential	Central Heating - 50% cycling	Multi Family	Existing		Passed	Passed	Passed	0	0	0
Residential	Central Heating - 50% cycling	Mobile Home/Other	Existing		Passed	Passed	Passed	0	0	0
Residential	Water heater switches	Single Family	Existing		Passed	Passed	Passed	109	206	0
Residential	Water heater switches	Multi Family	Existing		Passed	Passed	Passed	57	107	0
Residential	Water heater switches	Mobile Home/Other	Existing		Passed	Passed	Passed	22	41	0
Residential	Pool pump switches	Single Family	Existing		Passed	Passed	Passed	181	76	0
Residential	Pool pump switches	Multi Family	Existing		Passed	Passed	Passed	0	0	0
Residential	Pool pump switches	Mobile Home/Other	Existing		Passed	Passed	Passed	0	0	0
Residential	Room AC control	Single Family	New		Passed	Passed	Passed	0	0	0
Residential	Room AC control	Multi Family	New		Passed	Passed	Passed	0	0	0
Residential	Room AC control	Mobile Home/Other	New		Passed	Passed	Passed	0	0	0
Residential	Smart thermostats - Utility Installation	Single Family	New		Passed	Passed	Passed	0	0	0
Residential	Smart thermostats - Utility Installation	Multi Family	New		Passed	Passed	Passed	0	0	0
Residential	Smart thermostats - Utility Installation	Mobile Home/Other	New		Passed	Passed	Passed	0	0	0
Residential	Smart thermostats - BYOT	Single Family	New		Passed	Passed	Passed	0	0	0
Residential	Smart thermostats - BYOT	Multi Family	New		Passed	Passed	Passed	0	0	0
Residential	Smart thermostats - BYOT	Mobile Home/Other	New		Passed	Passed	Passed	0	0	0
Residential	CPP + Tech	Single Family	New		Passed	Passed	Passed	0	0	0
Residential	CPP + Tech	Multi Family	New		Passed	Passed	Passed	0	0	0
Residential	CPP + Tech	Mobile Home/Other	New		Passed	Passed	Passed	0	0	0

Commercial	Solar Water Heater	College and University	Turnover	T_CU_Solar	0.93	0.45	2.08	0	0	0	Fail TRC
Commercial	Solar Water Heater	Grocery	Turnover	T_GR_Solar	0.81	0.45	1.80	0	0	0	Fail TRC
Commercial	Solar Water Heater	Healthcare	Turnover	T_HC_Solar	0.54	0.45	1.20	0	0	0	Fail TRC
Commercial	Solar Water Heater	Restaurants	Turnover	T_RS_Solar	0.67	0.45	1.50	0	0	0	Fail TRC
Commercial	Solar Water Heater	Retail	Turnover	T_RT_Solar	0.80	0.45	1.79	0	0	0	Fail TRC
Commercial	Solar Water Heater	Schools K-12	Turnover	T_SC_Solar	0.17	0.45	0.38	0	0	0	Fail TRC
Commercial	Solar Water Heater	Warehouse	Turnover	T_WR_Solar	0.81	0.45	1.80	0	0	0	Fail TRC
Commercial	Solar Water Heater	Assembly	New	N_AS_Solar	0.40	0.45	0.90	0	0	0	Fail TRC
Commercial	Solar Water Heater	College and University	New	N_CU_Solar	0.93	0.45	2.08	0	0	0	Fail TRC
Commercial	Solar Water Heater	Grocery	New	N_GR_Solar	0.81	0.45	1.80	0	0	0	Fail TRC
Commercial	Solar Water Heater	Healthcare	New	N_HC_Solar	0.54	0.45	1.20	0	0	0	Fail TRC
Commercial	Solar Water Heater	Restaurants	New	N_RS_Solar	0.67	0.45	1.50	0	0	0	Fail TRC
Commercial	Solar Water Heater	Retail	New	N_RT_Solar	0.80	0.45	1.79	0	0	0	Fail TRC
Commercial	Solar Water Heater	Schools K-12	New	N_SC_Solar	0.17	0.45	0.38	0	0	0	Fail TRC
Commercial	Solar Water Heater	Warehouse	New	N_WR_Solar	0.81	0.45	1.80	0	0	0	Fail TRC
Commercial	CFL - 15W Flood	Assembly	Turnover	T_AS_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	College and University	Turnover	T_CU_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Grocery	Turnover	T_GR_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Healthcare	Turnover	T_HC_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Hospitals	Turnover	T_HS_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Institutional	Turnover	T_IN_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Lodging/Hospitality	Turnover	T_LG_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Miscellaneous	Turnover	T_MS_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Offices	Turnover	T_OF_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Restaurants	Turnover	T_RS_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Retail	Turnover	T_RT_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Schools K-12	Turnover	T_SC_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Warehouse	Turnover	T_WR_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Assembly	New	N_AS_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	College and University	New	N_CU_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Grocery	New	N_GR_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Healthcare	New	N_HC_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Hospitals	New	N_HS_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Institutional	New	N_IN_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Lodging/Hospitality	New	N_LG_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Miscellaneous	New	N_MS_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Offices	New	N_OF_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Restaurants	New	N_RS_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Retail	New	N_RT_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Schools K-12	New	N_SC_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	CFL - 15W Flood	Warehouse	New	N_WR_CFL -	8.99	0.27	33.19	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency HID Lighting	Assembly	Turnover	T_AS_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	College and University	Turnover	T_CU_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Grocery	Turnover	T_GR_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Healthcare	Turnover	T_HC_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Hospitals	Turnover	T_HS_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Institutional	Turnover	T_IN_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Lodging/Hospitality	Turnover	T_LG_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Miscellaneous	Turnover	T_MS_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Offices	Turnover	T_OF_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Restaurants	Turnover	T_RS_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Retail	Turnover	T_RT_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Schools K-12	Turnover	T_SC_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Warehouse	Turnover	T_WR_High	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Assembly	New	N_AS_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	College and University	New	N_CU_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Grocery	New	N_GR_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Healthcare	New	N_HC_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Hospitals	New	N_HS_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Institutional	New	N_IN_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Lodging/Hospitality	New	N_LG_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Miscellaneous	New	N_MS_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Offices	New	N_OF_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Restaurants	New	N_RS_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Retail	New	N_RT_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Schools K-12	New	N_SC_High E	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	High Efficiency HID Lighting	Warehouse	New	N_WR_High	0.71	0.29	2.47	0	0	0	Fail TRC
Commercial	LED - 9W Flood	Assembly	Turnover	T_AS_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	College and University	Turnover	T_CU_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Grocery	Turnover	T_GR_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Healthcare	Turnover	T_HC_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Hospitals	Turnover	T_HS_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Institutional	Turnover	T_IN_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Lodging/Hospitality	Turnover	T_LG_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Miscellaneous	Turnover	T_MS_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Offices	Turnover	T_OF_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Restaurants	Turnover	T_RS_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Retail	Turnover	T_RT_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Schools K-12	Turnover	T_SC_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Warehouse	Turnover	T_WR_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Assembly	New	N_AS_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	College and University	New	N_CU_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Grocery	New	N_GR_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Healthcare	New	N_HC_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Hospitals	New	N_HS_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Institutional	New	N_IN_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Lodging/Hospitality	New	N_LG_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Miscellaneous	New	N_MS_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Offices	New	N_OF_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Restaurants	New	N_RS_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Retail	New	N_RT_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Schools K-12	New	N_SC_LED -	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED - 9W Flood	Warehouse	New	N_WR_LED	23.16	0.29	79.36	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Assembly	Turnover	T_AS_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	College and University	Turnover	T_CU_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Grocery	Turnover	T_GR_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Healthcare	Turnover	T_HC_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Hospitals	Turnover	T_HS_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Institutional	Turnover	T_IN_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Lodging/Hospitality	Turnover	T_LG_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Miscellaneous	Turnover	T_MS_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Offices	Turnover	T_OF_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Restaurants	Turnover	T_RS_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Retail	Turnover	T_RT_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Schools K-12	Turnover	T_SC_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Warehouse	Turnover	T_WR_LED	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Assembly	New	N_AS_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	College and University	New	N_CU_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Grocery	New	N_GR_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Healthcare	New	N_HC_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Hospitals	New	N_HS_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Institutional	New	N_IN_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Lodging/Hospitality	New	N_LG_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Miscellaneous	New	N_MS_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Offices	New	N_OF_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Restaurants	New	N_RS_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold

Commercial	Solar Water Heater	Offices	New	N_OF_Solar	1.12	0.45	2.51	0	0	0	Fail RIM
Commercial	Solar Water Heater	Restaurants	New	N_RS_Solar	0.67	0.45	1.50	0	0	0	Fail RIM
Commercial	Solar Water Heater	Retail	New	N_RT_Solar	0.80	0.45	1.79	0	0	0	Fail RIM
Commercial	Solar Water Heater	Schools K-12	New	N_SC_Solar	0.17	0.45	0.38	0	0	0	Fail RIM
Commercial	Solar Water Heater	Warehouse	New	N_WR_Solar	0.81	0.45	1.80	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Assembly	Turnover	T_AS_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	College and University	Turnover	T_CU_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Grocery	Turnover	T_GR_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Healthcare	Turnover	T_HC_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Hospitals	Turnover	T_HS_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Institutional	Turnover	T_IN_CFL - 1	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Lodging/Hospitality	Turnover	T_LG_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Miscellaneous	Turnover	T_MS_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Offices	Turnover	T_OF_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Restaurants	Turnover	T_RS_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Retail	Turnover	T_RT_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Schools K-12	Turnover	T_SC_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Warehouse	Turnover	T_WR_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Assembly	New	N_AS_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	College and University	New	N_CU_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Grocery	New	N_GR_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Healthcare	New	N_HC_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Hospitals	New	N_HS_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Institutional	New	N_IN_CFL - 1	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Lodging/Hospitality	New	N_LG_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Miscellaneous	New	N_MS_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Offices	New	N_OF_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Restaurants	New	N_RS_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Retail	New	N_RT_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Schools K-12	New	N_SC_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	CFL - 15W Flood	Warehouse	New	N_WR_CFL -	8.99	0.27	33.19	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Assembly	Turnover	T_AS_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	College and University	Turnover	T_CU_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Grocery	Turnover	T_GR_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Healthcare	Turnover	T_HC_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Hospitals	Turnover	T_HS_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Institutional	Turnover	T_IN_High Ef	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Lodging/Hospitality	Turnover	T_LG_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Miscellaneous	Turnover	T_MS_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Offices	Turnover	T_OF_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Restaurants	Turnover	T_RS_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Retail	Turnover	T_RT_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Schools K-12	Turnover	T_SC_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Warehouse	Turnover	T_WR_High	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Assembly	New	N_AS_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	College and University	New	N_CU_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Grocery	New	N_GR_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Healthcare	New	N_HC_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Hospitals	New	N_HS_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Institutional	New	N_IN_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Lodging/Hospitality	New	N_LG_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Miscellaneous	New	N_MS_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Offices	New	N_OF_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Restaurants	New	N_RS_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Retail	New	N_RT_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Schools K-12	New	N_SC_High E	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	High Efficiency HID Lighting	Warehouse	New	N_WR_High	0.71	0.29	2.47	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Assembly	Turnover	T_AS_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	College and University	Turnover	T_CU_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Grocery	Turnover	T_GR_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Healthcare	Turnover	T_HC_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Hospitals	Turnover	T_HS_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Institutional	Turnover	T_IN_LED - 9	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Lodging/Hospitality	Turnover	T_LG_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Miscellaneous	Turnover	T_MS_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Offices	Turnover	T_OF_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Restaurants	Turnover	T_RS_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Retail	Turnover	T_RT_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Schools K-12	Turnover	T_SC_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Warehouse	Turnover	T_WR_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Assembly	New	N_AS_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	College and University	New	N_CU_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Grocery	New	N_GR_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Healthcare	New	N_HC_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Hospitals	New	N_HS_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Institutional	New	N_IN_LED - 9	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Lodging/Hospitality	New	N_LG_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Miscellaneous	New	N_MS_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Offices	New	N_OF_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Restaurants	New	N_RS_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Retail	New	N_RT_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Schools K-12	New	N_SC_LED -	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED - 9W Flood	Warehouse	New	N_WR_LED	23.16	0.29	79.36	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Assembly	Turnover	T_AS_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	College and University	Turnover	T_CU_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Grocery	Turnover	T_GR_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Healthcare	Turnover	T_HC_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Hospitals	Turnover	T_HS_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Institutional	Turnover	T_IN_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Lodging/Hospitality	Turnover	T_LG_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Miscellaneous	Turnover	T_MS_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Offices	Turnover	T_OF_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Restaurants	Turnover	T_RS_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Retail	Turnover	T_RT_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Schools K-12	Turnover	T_SC_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Warehouse	Turnover	T_WR_LED	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Assembly	New	N_AS_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	College and University	New	N_CU_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Grocery	New	N_GR_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Healthcare	New	N_HC_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Hospitals	New	N_HS_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Institutional	New	N_IN_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Lodging/Hospitality	New	N_LG_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Miscellaneous	New	N_MS_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Offices	New	N_OF_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Restaurants	New	N_RS_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Retail	New	N_RT_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Schools K-12	New	N_SC_LED D	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Exterior)	Warehouse	New	N_WR_LED	3.49	0.29	11.95	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Assembly	Turnover	T_AS_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	College and University	Turnover	T_CU_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Grocery	Turnover	T_GR_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Healthcare	Turnover	T_HC_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Hospitals	Turnover	T_HS_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Institutional	Turnover	T_IN_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Lodging/Hospitality	Turnover	T_LG_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Miscellaneous	Turnover	T_MS_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Offices	Turnover	T_OF_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Restaurants	Turnover	T_RS_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Retail	Turnover	T_RT_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Schools K-12	Turnover	T_SC_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Warehouse	Turnover	T_WR_LED	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Assembly	New	N_AS_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	College and University	New	N_CU_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Grocery	New	N_GR_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Healthcare	New	N_HC_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Hospitals	New	N_HS_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Institutional	New	N_IN_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Lodging/Hospitality	New	N_LG_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Miscellaneous	New	N_MS_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Offices	New	N_OF_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Restaurants	New	N_RS_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Retail	New	N_RT_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Schools K-12	New	N_SC_LED E	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Exterior Lighting	Warehouse	New	N_WR_LED	0.75	0.29	2.62	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Assembly	Turnover	T_AS_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	College and University	Turnover	T_CU_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Grocery	Turnover	T_GR_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Healthcare	Turnover	T_HC_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Hospitals	Turnover	T_HS_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Institutional	Turnover	T_IN_LED Pa	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Lodging/Hospitality	Turnover	T_LG_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Miscellaneous	Turnover	T_MS_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Offices	Turnover	T_OF_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Restaurants	Turnover	T_RS_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Retail	Turnover	T_RT_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Schools K-12	Turnover	T_SC_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Warehouse	Turnover	T_WR_LED	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Assembly	New	N_AS_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	College and University	New	N_CU_LED P	7.79	0.29	26.44	0	0	0	Fail RIM

Small C&I	Central air conditioner - Load Shed	0-15,000 kWh	New		Passed	Passed	Passed	64	0	0
Small C&I	Central air conditioner - Load Shed	15,001-25,000 kWh	New		Passed	Passed	Passed	17	0	0
Small C&I	Central air conditioner - Load Shed	25,001-50,000 kWh	New		Passed	Passed	Passed	11	0	0
Small C&I	Central air conditioner - Load Shed	50,001 kWh +	New		Passed	Passed	Passed	12	0	0
Small C&I	Central Heating - Load Shed	0-15,000 kWh	New		Passed	Passed	Passed	0	35	0
Small C&I	Central Heating - Load Shed	15,001-25,000 kWh	New		Passed	Passed	Passed	0	16	0
Small C&I	Central Heating - Load Shed	25,001-50,000 kWh	New		Passed	Passed	Passed	0	14	0
Small C&I	Central Heating - Load Shed	50,001 kWh +	New		Passed	Passed	Passed	0	8	0
Small C&I	Central air conditioner - 50% cycling	0-15,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	Central air conditioner - 50% cycling	15,001-25,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	Central air conditioner - 50% cycling	25,001-50,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	Central air conditioner - 50% cycling	50,001 kWh +	New		Passed	Passed	Passed	0	0	0
Small C&I	Central Heating - 50% cycling	0-15,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	Central Heating - 50% cycling	15,001-25,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	Central Heating - 50% cycling	25,001-50,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	Central Heating - 50% cycling	50,001 kWh +	New		Passed	Passed	Passed	0	0	0
Small C&I	Smart thermostats - Utility Installation	0-15,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	Smart thermostats - Utility Installation	15,001-25,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	Smart thermostats - Utility Installation	25,001-50,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	Smart thermostats - Utility Installation	50,001 kWh +	New		Passed	Passed	Passed	0	0	0
Small C&I	Smart thermostats - BYOT	0-15,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	Smart thermostats - BYOT	15,001-25,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	Smart thermostats - BYOT	25,001-50,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	Smart thermostats - BYOT	50,001 kWh +	New		Passed	Passed	Passed	0	0	0
Small C&I	CPP + Tech	0-15,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	CPP + Tech	15,001-25,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	CPP + Tech	25,001-50,000 kWh	New		Passed	Passed	Passed	0	0	0
Small C&I	CPP + Tech	50,001 kWh +	New		Passed	Passed	Passed	0	0	0
Large C&I	Auto DR	0-50 kW	New		Passed	Passed	Passed	503	537	0
Large C&I	Auto DR	51-300 kW	New		Passed	Passed	Passed	702	684	0
Large C&I	Auto DR	301-500 kW	New		Passed	Passed	Passed	174	160	0
Large C&I	Auto DR	501 kW +	Existing		Passed	Passed	Passed	374	334	0
Large C&I	CPP	0-50 kW	New		Passed	Passed	Passed	0	0	0
Large C&I	CPP	51-300 kW	New		Passed	Passed	Passed	0	0	0
Large C&I	CPP	301-500 kW	New		Passed	Passed	Passed	0	0	0
Large C&I	CPP	501 kW +	New		Passed	Passed	Passed	0	0	0
Large C&I	Firm Service Level	0-50 kW	New		Passed	Passed	Passed	0	0	0
Large C&I	Firm Service Level	51-300 kW	New		Passed	Passed	Passed	0	0	0
Large C&I	Firm Service Level	301-500 kW	New		Passed	Passed	Passed	0	0	0
Large C&I	Firm Service Level	501 kW +	Existing		Passed	Passed	Passed	0	0	0
Large C&I	Guaranteed Load Drop	0-50 kW	New		Passed	Passed	Passed	0	0	0
Large C&I	Guaranteed Load Drop	51-300 kW	New		Passed	Passed	Passed	0	0	0
Large C&I	Guaranteed Load Drop	301-500 kW	New		Passed	Passed	Passed	0	0	0
Large C&I	Guaranteed Load Drop	501 kW +	Existing		Passed	Passed	Passed	0	0	0

Commercial	LED Display Lighting (Exterior)	Retail	New	N_RT_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Schools K-12	New	N_SC_LED D	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Exterior)	Warehouse	New	N_WR_LED	3.49	0.29	11.95	0	0	0	Fail 2-year Threshold
Commercial	LED Exterior Lighting	Assembly	Turnover	T_AS_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	College and University	Turnover	T_CU_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Grocery	Turnover	T_GR_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Healthcare	Turnover	T_HC_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Hospitals	Turnover	T_HS_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Institutional	Turnover	T_IN_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Lodging/Hospitality	Turnover	T_LG_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Miscellaneous	Turnover	T_MS_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Offices	Turnover	T_OF_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Restaurants	Turnover	T_RS_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Retail	Turnover	T_RT_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Schools K-12	Turnover	T_SC_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Warehouse	Turnover	T_WR_LED	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Assembly	New	N_AS_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	College and University	New	N_CU_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Grocery	New	N_GR_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Healthcare	New	N_HC_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Hospitals	New	N_HS_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Institutional	New	N_IN_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Lodging/Hospitality	New	N_LG_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Miscellaneous	New	N_MS_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Offices	New	N_OF_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Restaurants	New	N_RS_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Retail	New	N_RT_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Schools K-12	New	N_SC_LED E	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Exterior Lighting	Warehouse	New	N_WR_LED	0.75	0.29	2.62	0	0	0	Fail TRC
Commercial	LED Parking Lighting	Assembly	Turnover	T_AS_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	College and University	Turnover	T_CU_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Grocery	Turnover	T_GR_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Healthcare	Turnover	T_HC_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Hospitals	Turnover	T_HS_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Institutional	Turnover	T_IN_LED Pa	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Lodging/Hospitality	Turnover	T_LG_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Miscellaneous	Turnover	T_MS_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Offices	Turnover	T_OF_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Restaurants	Turnover	T_RS_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Retail	Turnover	T_RT_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Schools K-12	Turnover	T_SC_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Warehouse	Turnover	T_WR_LED	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Assembly	New	N_AS_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	College and University	New	N_CU_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Grocery	New	N_GR_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Healthcare	New	N_HC_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Hospitals	New	N_HS_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Institutional	New	N_IN_LED Pa	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Lodging/Hospitality	New	N_LG_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Miscellaneous	New	N_MS_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Offices	New	N_OF_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Restaurants	New	N_RS_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Retail	New	N_RT_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Schools K-12	New	N_SC_LED P	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Parking Lighting	Warehouse	New	N_WR_LED	7.79	0.29	26.44	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Assembly	Turnover	T_AS_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	College and University	Turnover	T_CU_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Grocery	Turnover	T_GR_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Healthcare	Turnover	T_HC_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Hospitals	Turnover	T_HS_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Institutional	Turnover	T_IN_LED St	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Lodging/Hospitality	Turnover	T_LG_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Miscellaneous	Turnover	T_MS_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Offices	Turnover	T_OF_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Restaurants	Turnover	T_RS_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Retail	Turnover	T_RT_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Schools K-12	Turnover	T_SC_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Warehouse	Turnover	T_WR_LED	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Assembly	New	N_AS_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	College and University	New	N_CU_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Grocery	New	N_GR_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Healthcare	New	N_HC_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Hospitals	New	N_HS_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Institutional	New	N_IN_LED St	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Lodging/Hospitality	New	N_LG_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Miscellaneous	New	N_MS_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Offices	New	N_OF_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Restaurants	New	N_RS_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Retail	New	N_RT_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Schools K-12	New	N_SC_LED S	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Street Lights	Warehouse	New	N_WR_LED	2.65	0.29	8.99	0	0	0	Fail 2-year Threshold
Commercial	LED Traffic and Crosswalk Lighting	Assembly	Turnover	T_AS_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	College and University	Turnover	T_CU_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Grocery	Turnover	T_GR_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Healthcare	Turnover	T_HC_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Hospitals	Turnover	T_HS_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Institutional	Turnover	T_IN_LED Tr	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Lodging/Hospitality	Turnover	T_LG_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Miscellaneous	Turnover	T_MS_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Offices	Turnover	T_OF_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Restaurants	Turnover	T_RS_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Retail	Turnover	T_RT_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Schools K-12	Turnover	T_SC_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Warehouse	Turnover	T_WR_LED	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Assembly	New	N_AS_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	College and University	New	N_CU_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Grocery	New	N_GR_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Healthcare	New	N_HC_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Hospitals	New	N_HS_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Institutional	New	N_IN_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Lodging/Hospitality	New	N_LG_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Miscellaneous	New	N_MS_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Offices	New	N_OF_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Restaurants	New	N_RS_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Retail	New	N_RT_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Schools K-12	New	N_SC_LED T	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	LED Traffic and Crosswalk Lighting	Warehouse	New	N_WR_LED	0.12	0.28	0.42	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Assembly	Turnover	T_AS_Geoth	0.08	1.19	0.06	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	College and University	Turnover	T_CU_Geoth	0.05	0.66	0.07	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Grocery	Turnover	T_GR_Geoth	0.04	1.19	0.04	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Healthcare	Turnover	T_HC_Geoth	0.16	1.19	0.14	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Hospitals	Turnover	T_HS_Geoth	0.09	0.66	0.13	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Institutional	Turnover	T_IN_Geothe	0.04	1.19	0.03	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Lodging/Hospitality	Turnover	T_LG_Geoth	0.12	1.19	0.10	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Miscellaneous	Turnover	T_MS_Geoth	0.04	1.19	0.04	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Offices	Turnover	T_OF_Geoth	0.08	1.19	0.07	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Restaurants	Turnover	T_RS_Geoth	0.12	1.19	0.10	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Retail	Turnover	T_RT_Geoth	0.10	1.19	0.08	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Schools K-12	Turnover	T_SC_Geoth	0.08	1.19	0.07	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Warehouse	Turnover	T_WR_Geoth	0.02	1.19	0.02	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Assembly	New	N_AS_Geoth	0.08	1.19	0.06	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	College and University	New	N_CU_Geoth	0.05	0.66	0.07	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Grocery	New	N_GR_Geoth	0.04	1.19	0.04	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Healthcare	New	N_HC_Geoth	0.16	1.19	0.14	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Hospitals	New	N_HS_Geoth	0.09	0.66	0.13	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Institutional	New	N_IN_Geothe	0.04	1.19	0.03	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Lodging/Hospitality	New	N_LG_Geoth	0.12	1.19	0.10	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Miscellaneous	New	N_MS_Geoth	0.04	1.19	0.04	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Offices	New	N_OF_Geoth	0.08	1.19	0.07	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Restaurants	New	N_RS_Geoth	0.12	1.19	0.10	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Retail	New	N_RT_Geoth	0.10	1.19	0.08	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Schools K-12	New	N_SC_Geoth	0.08	1.19	0.07	0	0	0	Fail TRC
Commercial	Geothermal Heat Pump	Warehouse	New	N_WR_Geoth	0.02	1.19	0.02	0	0	0	Fail TRC
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Warehouse	Turnover	T_WR_High	0.53	0.89	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Warehouse	New	N_WR_High	0.53	0.89	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Warehouse	Turnover	T_WR_High	0.62	1.17	0.53	0	0	0	Fail TRC
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Warehouse	New	N_WR_High	0.62	1.17	0.53	0	0	0	Fail TRC
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Grocery	Turnover	T_GR_High E	0.82	1.17	0.70	0	0	0	Fail TRC
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Institutional	Turnover	T_IN_High E	0.80	1.17	0.69	0	0	0	Fail TRC
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Miscellaneous	Turnover	T_MS_High E	0.83	1.17	0.71	0	0	0	Fail TRC
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Warehouse	Turnover	T_WR_High	0.36	1.17	0.31	0	0	0	Fail TRC
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Grocery	New	N_GR_High E	0.82	1.17	0.70	0	0	0	Fail TRC
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Institutional	New	N_IN_High E	0.80	1.17	0.69	0	0	0	Fail TRC
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Miscellaneous	New	N_MS_High E	0.83	1.17	0.71	0	0	0	Fail TRC
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Warehouse	New	N_WR_High	0.36	1.17	0.31	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Assembly	Turnover	T_AS_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	College and University	Turnover	T_CU_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Grocery	Turnover	T_GR_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Healthcare	Turnover	T_HC_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Hospitals	Turnover	T_HS_High E	0.67	0.80	0.83	0	0	0	Fail TRC

Commercial	LED Parking Lighting	Grocery	New	N_GR_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Healthcare	New	N_HC_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Hospitals	New	N_HS_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Institutional	New	N_IN_LED Pa	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Lodging/Hospitality	New	N_LG_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Miscellaneous	New	N_MS_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Offices	New	N_OF_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Restaurants	New	N_RS_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Retail	New	N_RT_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Schools K-12	New	N_SC_LED P	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Parking Lighting	Warehouse	New	N_WR_LED	7.79	0.29	26.44	0	0	0	Fail RIM
Commercial	LED Street Lights	Assembly	Turnover	T_AS_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	College and University	Turnover	T_CU_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Grocery	Turnover	T_GR_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Healthcare	Turnover	T_HC_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Hospitals	Turnover	T_HS_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Institutional	Turnover	T_IN_LED St	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Lodging/Hospitality	Turnover	T_LG_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Miscellaneous	Turnover	T_MS_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Offices	Turnover	T_OF_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Restaurants	Turnover	T_RS_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Retail	Turnover	T_RT_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Schools K-12	Turnover	T_SC_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Warehouse	Turnover	T_WR_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Assembly	New	N_AS_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	College and University	New	N_CU_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Grocery	New	N_GR_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Healthcare	New	N_HC_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Hospitals	New	N_HS_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Institutional	New	N_IN_LED St	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Lodging/Hospitality	New	N_LG_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Miscellaneous	New	N_MS_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Offices	New	N_OF_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Restaurants	New	N_RS_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Retail	New	N_RT_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Schools K-12	New	N_SC_LED S	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Street Lights	Warehouse	New	N_WR_LED	2.65	0.29	8.99	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Assembly	Turnover	T_AS_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	College and University	Turnover	T_CU_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Grocery	Turnover	T_GR_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Healthcare	Turnover	T_HC_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Hospitals	Turnover	T_HS_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Institutional	Turnover	T_IN_LED Tr	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Lodging/Hospitality	Turnover	T_LG_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Miscellaneous	Turnover	T_MS_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Offices	Turnover	T_OF_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Restaurants	Turnover	T_RS_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Retail	Turnover	T_RT_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Schools K-12	Turnover	T_SC_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Warehouse	Turnover	T_WR_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Assembly	New	N_AS_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	College and University	New	N_CU_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Grocery	New	N_GR_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Healthcare	New	N_HC_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Hospitals	New	N_HS_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Institutional	New	N_IN_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Lodging/Hospitality	New	N_LG_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Miscellaneous	New	N_MS_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Offices	New	N_OF_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Restaurants	New	N_RS_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Retail	New	N_RT_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Schools K-12	New	N_SC_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	LED Traffic and Crosswalk Lighting	Warehouse	New	N_WR_LED T	0.12	0.28	0.42	0	0	0	Fail RIM
Commercial	Geothermal Heat Pump	Assembly	Turnover	T_AS_Geoth	0.08	1.19	0.06	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	College and University	Turnover	T_CU_Geoth	0.05	0.66	0.07	0	0	0	Fail RIM
Commercial	Geothermal Heat Pump	Grocery	Turnover	T_GR_Geoth	0.04	1.19	0.04	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Healthcare	Turnover	T_HC_Geoth	0.16	1.19	0.14	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Hospitals	Turnover	T_HS_Geoth	0.09	0.66	0.13	0	0	0	Fail RIM
Commercial	Geothermal Heat Pump	Institutional	Turnover	T_IN_Geothe	0.04	1.19	0.03	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Lodging/Hospitality	Turnover	T_LG_Geoth	0.12	1.19	0.10	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Miscellaneous	Turnover	T_MS_Geoth	0.04	1.19	0.04	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Offices	Turnover	T_OF_Geoth	0.08	1.19	0.07	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Restaurants	Turnover	T_RS_Geoth	0.12	1.19	0.10	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Retail	Turnover	T_RT_Geoth	0.10	1.19	0.08	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Schools K-12	Turnover	T_SC_Geoth	0.08	1.19	0.07	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Warehouse	Turnover	T_WR_Geoth	0.02	1.19	0.02	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Assembly	New	N_AS_Geoth	0.08	1.19	0.06	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	College and University	New	N_CU_Geoth	0.05	0.66	0.07	0	0	0	Fail RIM
Commercial	Geothermal Heat Pump	Grocery	New	N_GR_Geoth	0.04	1.19	0.04	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Healthcare	New	N_HC_Geoth	0.16	1.19	0.14	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Hospitals	New	N_HS_Geoth	0.09	0.66	0.13	0	0	0	Fail RIM
Commercial	Geothermal Heat Pump	Institutional	New	N_IN_Geothe	0.04	1.19	0.03	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Lodging/Hospitality	New	N_LG_Geoth	0.12	1.19	0.10	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Miscellaneous	New	N_MS_Geoth	0.04	1.19	0.04	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Offices	New	N_OF_Geoth	0.08	1.19	0.07	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Restaurants	New	N_RS_Geoth	0.12	1.19	0.10	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Retail	New	N_RT_Geoth	0.10	1.19	0.08	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Schools K-12	New	N_SC_Geoth	0.08	1.19	0.07	0	0	0	Fail PCT
Commercial	Geothermal Heat Pump	Warehouse	New	N_WR_Geoth	0.02	1.19	0.02	0	0	0	Fail PCT
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Assembly	Turnover	T_AS_High E	2.20	0.89	2.48	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	College and University	Turnover	T_CU_High E	2.44	0.89	2.75	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Grocery	Turnover	T_GR_High E	1.21	0.89	1.37	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Healthcare	Turnover	T_HC_High E	4.78	0.89	5.39	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Hospitals	Turnover	T_HS_High E	4.53	0.89	5.11	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Institutional	Turnover	T_IN_High E	1.19	0.89	1.34	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Lodging/Hospitality	Turnover	T_LG_High E	3.63	0.89	4.09	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Miscellaneous	Turnover	T_MS_High E	1.23	0.89	1.38	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Offices	Turnover	T_OF_High E	2.47	0.89	2.79	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Restaurants	Turnover	T_RS_High E	3.56	0.89	4.01	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Retail	Turnover	T_RT_High E	2.79	0.89	3.15	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Schools K-12	Turnover	T_SC_High E	2.43	0.89	2.74	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Warehouse	Turnover	T_WR_High E	0.53	0.89	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Assembly	New	N_AS_High E	2.20	0.89	2.48	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	College and University	New	N_CU_High E	2.44	0.89	2.75	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Grocery	New	N_GR_High E	1.21	0.89	1.37	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Healthcare	New	N_HC_High E	4.78	0.89	5.39	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Hospitals	New	N_HS_High E	4.53	0.89	5.11	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Institutional	New	N_IN_High E	1.19	0.89	1.34	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Lodging/Hospitality	New	N_LG_High E	3.63	0.89	4.09	0	0	0	Fail RIM

Commercial	High Efficiency Data Center Cooling	Institutional	Turnover	T_IN_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Lodging/Hospitality	Turnover	T_LG_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Miscellaneous	Turnover	T_MS_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Offices	Turnover	T_OF_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Restaurants	Turnover	T_RS_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Retail	Turnover	T_RT_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Schools K-12	Turnover	T_SC_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Warehouse	Turnover	T_WR_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Assembly	New	N_AS_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	College and University	New	N_CU_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Grocery	New	N_GR_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Healthcare	New	N_HC_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Hospitals	New	N_HS_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Institutional	New	N_IN_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Lodging/Hospitality	New	N_LG_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Miscellaneous	New	N_MS_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Offices	New	N_OF_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Restaurants	New	N_RS_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Retail	New	N_RT_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Schools K-12	New	N_SC_High E	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency Data Center Cooling	Warehouse	New	N_WR_High	0.67	0.80	0.83	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Assembly	Turnover	T_AS_High E	0.69	1.18	0.59	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	College and University	Turnover	T_CU_High E	0.77	1.18	0.65	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Grocery	Turnover	T_GR_High E	0.38	1.18	0.33	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Institutional	Turnover	T_IN_High E	0.37	1.18	0.32	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Lodging/Hospitality	Turnover	T_LG_High E	1.15	1.18	0.97	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Miscellaneous	Turnover	T_MS_High E	0.39	1.18	0.33	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Offices	Turnover	T_OF_High E	0.78	1.18	0.66	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Restaurants	Turnover	T_RS_High E	1.12	1.18	0.96	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Retail	Turnover	T_RT_High E	0.88	1.18	0.75	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Schools K-12	Turnover	T_SC_High E	0.77	1.18	0.65	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Warehouse	Turnover	T_WR_High E	0.17	1.18	0.14	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Assembly	New	N_AS_High E	0.69	1.18	0.59	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	College and University	New	N_CU_High E	0.77	1.18	0.65	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Grocery	New	N_GR_High E	0.38	1.18	0.33	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Institutional	New	N_IN_High E	0.37	1.18	0.32	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Lodging/Hospitality	New	N_LG_High E	1.15	1.18	0.97	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Miscellaneous	New	N_MS_High E	0.39	1.18	0.33	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Offices	New	N_OF_High E	0.78	1.18	0.66	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Restaurants	New	N_RS_High E	1.12	1.18	0.96	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Retail	New	N_RT_High E	0.88	1.18	0.75	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Schools K-12	New	N_SC_High E	0.77	1.18	0.65	0	0	0	Fail TRC
Commercial	High Efficiency DX 135k- less than 240k BTU	Warehouse	New	N_WR_High	0.17	1.18	0.14	0	0	0	Fail TRC
Commercial	High Efficiency PTAC	Assembly	Turnover	T_AS_High E	8.81	1.35	6.52	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	College and University	Turnover	T_CU_High E	6.57	0.91	7.23	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Healthcare	Turnover	T_HC_High E	19.16	1.35	14.18	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Hospitals	Turnover	T_HS_High E	12.20	0.91	13.43	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Lodging/Hospitality	Turnover	T_LG_High E	14.55	1.35	10.77	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Offices	Turnover	T_OF_High E	8.63	1.18	7.34	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Restaurants	Turnover	T_RS_High E	14.27	1.35	10.56	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Retail	Turnover	T_RT_High E	11.19	1.35	8.28	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Schools K-12	Turnover	T_SC_High E	9.72	1.35	7.20	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Assembly	New	N_AS_High E	8.81	1.35	6.52	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	College and University	New	N_CU_High E	6.57	0.91	7.23	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Healthcare	New	N_HC_High E	19.16	1.35	14.18	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Hospitals	New	N_HS_High E	12.20	0.91	13.43	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Lodging/Hospitality	New	N_LG_High E	14.55	1.35	10.77	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Offices	New	N_OF_High E	8.63	1.18	7.34	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Restaurants	New	N_RS_High E	14.27	1.35	10.56	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Retail	New	N_RT_High E	11.19	1.35	8.28	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Schools K-12	New	N_SC_High E	9.72	1.35	7.20	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Assembly	Turnover	T_AS_High E	8.80	1.33	6.61	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	College and University	Turnover	T_CU_High E	6.49	0.89	7.33	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Healthcare	Turnover	T_HC_High E	19.08	1.33	14.33	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Hospitals	Turnover	T_HS_High E	12.06	0.89	13.60	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Lodging/Hospitality	Turnover	T_LG_High E	14.47	1.33	10.87	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Offices	Turnover	T_OF_High E	9.84	1.33	7.39	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Restaurants	Turnover	T_RS_High E	14.53	1.33	10.91	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Retail	Turnover	T_RT_High E	11.31	1.33	8.50	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Schools K-12	Turnover	T_SC_High E	9.85	1.33	7.40	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Assembly	New	N_AS_High E	8.80	1.33	6.61	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	College and University	New	N_CU_High E	6.49	0.89	7.33	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Healthcare	New	N_HC_High E	19.08	1.33	14.33	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Hospitals	New	N_HS_High E	12.06	0.89	13.60	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Lodging/Hospitality	New	N_LG_High E	14.47	1.33	10.87	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Offices	New	N_OF_High E	9.84	1.33	7.39	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Restaurants	New	N_RS_High E	14.53	1.33	10.91	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Retail	New	N_RT_High E	11.31	1.33	8.50	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Schools K-12	New	N_SC_High E	9.85	1.33	7.40	0	0	0	Fail 2-year Threshold
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Assembly	Turnover	T_AS_Variab	0.81	0.89	0.91	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	College and University	Turnover	T_CU_Variab	0.74	0.74	1.00	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Grocery	Turnover	T_GR_Variab	0.50	0.89	0.56	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Institutional	Turnover	T_IN_Variabl	0.45	0.89	0.51	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Miscellaneous	Turnover	T_MS_Variab	0.45	0.89	0.51	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Offices	Turnover	T_OF_Variab	0.88	0.89	1.00	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Schools K-12	Turnover	T_SC_Variab	0.93	0.89	1.05	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Warehouse	Turnover	T_WR_Variab	0.21	0.89	0.24	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Assembly	New	N_AS_Variab	0.81	0.89	0.91	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	College and University	New	N_CU_Variab	0.74	0.74	1.00	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Grocery	New	N_GR_Variab	0.50	0.89	0.56	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Institutional	New	N_IN_Variabl	0.45	0.89	0.51	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Miscellaneous	New	N_MS_Variab	0.45	0.89	0.51	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Offices	New	N_OF_Variab	0.88	0.89	1.00	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Schools K-12	New	N_SC_Variab	0.93	0.89	1.05	0	0	0	Fail TRC
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Warehouse	New	N_WR_Varia	0.21	0.89	0.24	0	0	0	Fail TRC
Commercial	CFL-23W	Assembly	Turnover	T_AS_CFL-2	9.84	0.64	15.34	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	College and University	Turnover	T_CU_CFL-2	10.06	0.43	23.51	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Grocery	Turnover	T_GR_CFL-2	19.01	0.64	29.57	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Healthcare	Turnover	T_HC_CFL-2	17.20	0.64	26.82	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Hospitals	Turnover	T_HS_CFL-2	15.52	0.43	36.28	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Institutional	Turnover	T_IN_CFL-23	11.29	0.64	17.60	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Lodging/Hospitality	Turnover	T_LG_CFL-2	12.87	0.64	20.02	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Miscellaneous	Turnover	T_MS_CFL-2	15.08	0.64	23.51	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Offices	Turnover	T_OF_CFL-2	11.13	0.64	17.35	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Restaurants	Turnover	T_RS_CFL-2	11.51	0.64	17.91	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Retail	Turnover	T_RT_CFL-2	17.09	0.64	26.58	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Schools K-12	Turnover	T_SC_CFL-2	8.14	0.64	12.69	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Warehouse	Turnover	T_WR_CFL-2	13.08	0.64	20.40	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Assembly	New	N_AS_CFL-2	9.84	0.64	15.34	0	0	0	Fail 2-year Threshold

Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Miscellaneous	New	N_MS_High I	1.23	0.89	1.38	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Offices	New	N_OF_High E	2.47	0.89	2.79	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Restaurants	New	N_RS_High E	3.56	0.89	4.01	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Retail	New	N_RT_High E	2.79	0.89	3.15	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Schools K-12	New	N_SC_High E	2.43	0.89	2.74	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Warehouse	New	N_WR_High	0.53	0.89	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Warehouse	Turnover	T_WR_High I	0.62	1.17	0.53	0	0	0	Fail PCT
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Warehouse	New	N_WR_High	0.62	1.17	0.53	0	0	0	Fail PCT
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Grocery	Turnover	T_GR_High E	0.82	1.17	0.70	0	0	0	Fail PCT
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Institutional	Turnover	T_IN_High Ef	0.80	1.17	0.69	0	0	0	Fail PCT
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Miscellaneous	Turnover	T_MS_High I	0.83	1.17	0.71	0	0	0	Fail PCT
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Warehouse	Turnover	T_WR_High I	0.36	1.17	0.31	0	0	0	Fail PCT
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Grocery	New	N_GR_High E	0.82	1.17	0.70	0	0	0	Fail PCT
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Institutional	New	N_IN_High E	0.80	1.17	0.69	0	0	0	Fail PCT
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Miscellaneous	New	N_MS_High I	0.83	1.17	0.71	0	0	0	Fail PCT
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Warehouse	New	N_WR_High	0.36	1.17	0.31	0	0	0	Fail PCT
Commercial	High Efficiency Data Center Cooling	Assembly	Turnover	T_AS_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	College and University	Turnover	T_CU_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Grocery	Turnover	T_GR_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Healthcare	Turnover	T_HC_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Hospitals	Turnover	T_HS_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Institutional	Turnover	T_IN_High Ef	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Lodging/Hospitality	Turnover	T_LG_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Miscellaneous	Turnover	T_MS_High I	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Offices	Turnover	T_OF_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Restaurants	Turnover	T_RS_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Retail	Turnover	T_RT_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Schools K-12	Turnover	T_SC_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Warehouse	Turnover	T_WR_High I	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Assembly	New	N_AS_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	College and University	New	N_CU_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Grocery	New	N_GR_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Healthcare	New	N_HC_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Hospitals	New	N_HS_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Institutional	New	N_IN_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Lodging/Hospitality	New	N_LG_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Miscellaneous	New	N_MS_High I	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Offices	New	N_OF_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Restaurants	New	N_RS_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Retail	New	N_RT_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Schools K-12	New	N_SC_High E	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency Data Center Cooling	Warehouse	New	N_WR_High	0.67	0.80	0.83	0	0	0	Fail RIM
Commercial	High Efficiency DX 135k- less than 240k BTU	Assembly	Turnover	T_AS_High E	0.69	1.18	0.59	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	College and University	Turnover	T_CU_High E	0.77	1.18	0.65	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Grocery	Turnover	T_GR_High E	0.38	1.18	0.33	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Institutional	Turnover	T_IN_High Ef	0.37	1.18	0.32	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Lodging/Hospitality	Turnover	T_LG_High E	1.15	1.18	0.97	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Miscellaneous	Turnover	T_MS_High I	0.39	1.18	0.33	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Offices	Turnover	T_OF_High E	0.78	1.18	0.66	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Restaurants	Turnover	T_RS_High E	1.12	1.18	0.96	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Retail	Turnover	T_RT_High E	0.88	1.18	0.75	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Schools K-12	Turnover	T_SC_High E	0.77	1.18	0.65	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Warehouse	Turnover	T_WR_High I	0.17	1.18	0.14	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Assembly	New	N_AS_High E	0.69	1.18	0.59	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	College and University	New	N_CU_High E	0.77	1.18	0.65	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Grocery	New	N_GR_High E	0.38	1.18	0.33	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Institutional	New	N_IN_High E	0.37	1.18	0.32	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Lodging/Hospitality	New	N_LG_High E	1.15	1.18	0.97	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Miscellaneous	New	N_MS_High I	0.39	1.18	0.33	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Offices	New	N_OF_High E	0.78	1.18	0.66	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Restaurants	New	N_RS_High E	1.12	1.18	0.96	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Retail	New	N_RT_High E	0.88	1.18	0.75	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Schools K-12	New	N_SC_High E	0.77	1.18	0.65	0	0	0	Fail PCT
Commercial	High Efficiency DX 135k- less than 240k BTU	Warehouse	New	N_WR_High	0.17	1.18	0.14	0	0	0	Fail PCT
Commercial	High Efficiency PTAC	Assembly	Turnover	T_AS_High E	8.81	1.35	6.52	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	College and University	Turnover	T_CU_High E	6.57	0.91	7.23	0	0	0	Fail RIM
Commercial	High Efficiency PTAC	Healthcare	Turnover	T_HC_High E	19.16	1.35	14.18	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Hospitals	Turnover	T_HS_High E	12.20	0.91	13.43	0	0	0	Fail RIM
Commercial	High Efficiency PTAC	Lodging/Hospitality	Turnover	T_LG_High E	14.55	1.35	10.77	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Offices	Turnover	T_OF_High E	8.63	1.18	7.34	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Restaurants	Turnover	T_RS_High E	14.27	1.35	10.56	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Retail	Turnover	T_RT_High E	11.19	1.35	8.28	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Schools K-12	Turnover	T_SC_High E	9.72	1.35	7.20	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Assembly	New	N_AS_High E	8.81	1.35	6.52	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	College and University	New	N_CU_High E	6.57	0.91	7.23	0	0	0	Fail RIM
Commercial	High Efficiency PTAC	Healthcare	New	N_HC_High E	19.16	1.35	14.18	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Hospitals	New	N_HS_High E	12.20	0.91	13.43	0	0	0	Fail RIM
Commercial	High Efficiency PTAC	Lodging/Hospitality	New	N_LG_High E	14.55	1.35	10.77	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Offices	New	N_OF_High E	8.63	1.18	7.34	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Restaurants	New	N_RS_High E	14.27	1.35	10.56	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Retail	New	N_RT_High E	11.19	1.35	8.28	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTAC	Schools K-12	New	N_SC_High E	9.72	1.35	7.20	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Assembly	Turnover	T_AS_High E	8.80	1.33	6.61	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	College and University	Turnover	T_CU_High E	6.49	0.89	7.33	0	0	0	Fail RIM
Commercial	High Efficiency PTHP	Healthcare	Turnover	T_HC_High E	19.08	1.33	14.33	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Hospitals	Turnover	T_HS_High E	12.06	0.89	13.60	0	0	0	Fail RIM
Commercial	High Efficiency PTHP	Lodging/Hospitality	Turnover	T_LG_High E	14.47	1.33	10.87	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Offices	Turnover	T_OF_High E	9.84	1.33	7.39	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Restaurants	Turnover	T_RS_High E	14.53	1.33	10.91	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Retail	Turnover	T_RT_High E	11.31	1.33	8.50	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Schools K-12	Turnover	T_SC_High E	9.85	1.33	7.40	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Assembly	New	N_AS_High E	8.80	1.33	6.61	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	College and University	New	N_CU_High E	6.49	0.89	7.33	0	0	0	Fail RIM
Commercial	High Efficiency PTHP	Healthcare	New	N_HC_High E	19.08	1.33	14.33	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Hospitals	New	N_HS_High E	12.06	0.89	13.60	0	0	0	Fail RIM
Commercial	High Efficiency PTHP	Lodging/Hospitality	New	N_LG_High E	14.47	1.33	10.87	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Offices	New	N_OF_High E	9.84	1.33	7.39	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Restaurants	New	N_RS_High E	14.53	1.33	10.91	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Retail	New	N_RT_High E	11.31	1.33	8.50	0	0	0	Fail 2-year Threshold
Commercial	High Efficiency PTHP	Schools K-12	New	N_SC_High E	9.85	1.33	7.40	0	0	0	Fail 2-year Threshold
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Assembly	Turnover	T_AS_Variab	0.81	0.89	0.91	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	College and University	Turnover	T_CU_Variab	0.74	0.74	1.00	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Grocery	Turnover	T_GR_Variab	0.50	0.89	0.56	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Healthcare	Turnover	T_HC_Variab	1.73	0.89	1.95	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Hospitals	Turnover	T_HS_Variab	1.65	0.89	1.86	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Institutional	Turnover	T_IN_Variabl	0.45	0.89	0.51	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Lodging/Hospitality	Turnover	T_LG_Variab	1.08	0.74	1.48	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Miscellaneous	Turnover	T_MS_Variab	0.45	0.89	0.51	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Offices	Turnover	T_OF_Variab	0.88	0.89	1.00	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Restaurants	Turnover	T_RS_Variab	1.40	0.89	1.57	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Retail	Turnover	T_RT_Variab	1.07	0.89	1.21	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Schools K-12	Turnover	T_SC_Variab	0.93	0.89	1.05	0	0	0	Fail RIM

Commercial	CFL-23W	College and University	New	N_CU_CFL-2	10.06	0.43	23.51	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Grocery	New	N_GR_CFL-2	19.01	0.64	29.57	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Healthcare	New	N_HC_CFL-2	17.20	0.64	26.82	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Hospitals	New	N_HS_CFL-2	15.52	0.43	36.28	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Institutional	New	N_IN_CFL-23	11.29	0.64	17.60	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Lodging/Hospitality	New	N_LG_CFL-2	12.87	0.64	20.02	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Miscellaneous	New	N_MS_CFL-2	15.08	0.64	23.51	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Offices	New	N_OF_CFL-2	11.13	0.64	17.35	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Restaurants	New	N_RS_CFL-2	11.51	0.64	17.91	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Retail	New	N_RT_CFL-2	17.09	0.64	26.58	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Schools K-12	New	N_SC_CFL-2	8.14	0.64	12.69	0	0	0	Fail 2-year Threshold
Commercial	CFL-23W	Warehouse	New	N_WR_CFL-2	13.08	0.64	20.40	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Assembly	Turnover	T_AS_High B	4.33	0.68	6.38	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	College and University	Turnover	T_CU_High E	6.63	0.68	9.78	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Grocery	Turnover	T_GR_High E	8.34	0.68	12.30	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Healthcare	Turnover	T_HC_High E	7.57	0.68	11.16	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Hospitals	Turnover	T_HS_High B	10.24	0.68	15.09	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Institutional	Turnover	T_IN_High Ba	4.97	0.68	7.32	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Lodging/Hospitality	Turnover	T_LG_High B	5.65	0.68	8.33	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Miscellaneous	Turnover	T_MS_High I	6.63	0.68	9.78	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Offices	Turnover	T_OF_High B	4.90	0.68	7.22	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Restaurants	Turnover	T_RS_High B	5.05	0.68	7.45	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Retail	Turnover	T_RT_High B	7.50	0.68	11.06	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Warehouse	Turnover	T_WR_High I	5.76	0.68	8.48	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Assembly	New	N_AS_High E	4.33	0.68	6.38	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	College and University	New	N_CU_High I	6.63	0.68	9.78	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Grocery	New	N_GR_High I	8.34	0.68	12.30	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Healthcare	New	N_HC_High I	7.57	0.68	11.16	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Hospitals	New	N_HS_High E	10.24	0.68	15.09	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Institutional	New	N_IN_High B	4.97	0.68	7.32	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Lodging/Hospitality	New	N_LG_High I	5.65	0.68	8.33	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Miscellaneous	New	N_MS_High I	6.63	0.68	9.78	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Offices	New	N_OF_High E	4.90	0.68	7.22	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Restaurants	New	N_RS_High E	5.05	0.68	7.45	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Retail	New	N_RT_High E	7.50	0.68	11.06	0	0	0	Fail 2-year Threshold
Commercial	High Bay Fluorescent (T5)	Warehouse	New	N_WR_High	5.76	0.68	8.48	0	0	0	Fail 2-year Threshold
Commercial	High Bay LED	College and University	Turnover	T_CU_High E	4.50	0.68	6.63	0	0	0	Fail 2-year Threshold
Commercial	High Bay LED	Grocery	Turnover	T_GR_High E	5.66	0.68	8.34	0	0	0	Fail 2-year Threshold
Commercial	High Bay LED	Healthcare	Turnover	T_HC_High E	5.13	0.68	7.56	0	0	0	Fail 2-year Threshold
Commercial	High Bay LED	Hospitals	Turnover	T_HS_High B	6.94	0.68	10.23	0	0	0	Fail 2-year Threshold
Commercial	High Bay LED	Miscellaneous	Turnover	T_MS_High I	4.50	0.68	6.63	0	0	0	Fail 2-year Threshold
Commercial	High Bay LED	Retail	Turnover	T_RT_High B	5.08	0.68	7.50	0	0	0	Fail 2-year Threshold
Commercial	High Bay LED	College and University	New	N_CU_High I	4.50	0.68	6.63	0	0	0	Fail 2-year Threshold
Commercial	High Bay LED	Grocery	New	N_GR_High I	5.66	0.68	8.34	0	0	0	Fail 2-year Threshold
Commercial	High Bay LED	Healthcare	New	N_HC_High I	5.13	0.68	7.56	0	0	0	Fail 2-year Threshold
Commercial	High Bay LED	Hospitals	New	N_HS_High E	6.94	0.68	10.23	0	0	0	Fail 2-year Threshold
Commercial	High Bay LED	Miscellaneous	New	N_MS_High I	4.50	0.68	6.63	0	0	0	Fail 2-year Threshold
Commercial	High Bay LED	Retail	New	N_RT_High E	5.08	0.68	7.50	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Assembly	Turnover	T_AS_LED -	21.51	0.79	27.11	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	College and University	Turnover	T_CU_LED -	20.95	0.50	41.55	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Grocery	Turnover	T_GR_LED -	41.56	0.80	52.25	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Healthcare	Turnover	T_HC_LED -	37.60	0.79	47.39	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Hospitals	Turnover	T_HS_LED -	32.33	0.50	64.11	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Institutional	Turnover	T_IN_LED - 1	24.67	0.79	31.09	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Lodging/Hospitality	Turnover	T_LG_LED -	28.14	0.80	35.38	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Miscellaneous	Turnover	T_MS_LED -	32.96	0.79	41.55	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Offices	Turnover	T_OF_LED -	24.32	0.79	30.66	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Restaurants	Turnover	T_RS_LED -	25.16	0.80	31.64	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Retail	Turnover	T_RT_LED -	37.36	0.80	46.98	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Schools K-12	Turnover	T_SC_LED -	17.79	0.79	22.42	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Warehouse	Turnover	T_WR_LED -	28.59	0.79	36.04	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Assembly	New	N_AS_LED -	21.51	0.79	27.11	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	College and University	New	N_CU_LED -	20.95	0.50	41.55	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Grocery	New	N_GR_LED -	41.56	0.80	52.25	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Healthcare	New	N_HC_LED -	37.60	0.79	47.39	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Hospitals	New	N_HS_LED -	32.33	0.50	64.11	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Institutional	New	N_IN_LED -	24.67	0.79	31.09	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Lodging/Hospitality	New	N_LG_LED -	28.14	0.80	35.38	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Miscellaneous	New	N_MS_LED -	32.96	0.79	41.55	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Offices	New	N_OF_LED -	24.32	0.79	30.66	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Restaurants	New	N_RS_LED -	25.16	0.80	31.64	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Retail	New	N_RT_LED -	37.36	0.80	46.98	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Schools K-12	New	N_SC_LED -	17.79	0.79	22.42	0	0	0	Fail 2-year Threshold
Commercial	LED - 14W	Warehouse	New	N_WR_LED	28.59	0.79	36.04	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Assembly	Turnover	T_AS_LED D	6.89	0.81	8.55	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	College and University	Turnover	T_CU_LED D	6.70	0.51	13.11	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Grocery	Turnover	T_GR_LED D	13.17	0.80	16.49	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Healthcare	Turnover	T_HC_LED D	12.04	0.81	14.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Hospitals	Turnover	T_HS_LED D	10.35	0.51	20.23	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Institutional	Turnover	T_IN_LED D	7.90	0.81	9.81	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Lodging/Hospitality	Turnover	T_LG_LED D	8.92	0.80	11.17	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Miscellaneous	Turnover	T_MS_LED I	10.56	0.81	13.11	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Offices	Turnover	T_OF_LED D	7.79	0.81	9.68	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Restaurants	Turnover	T_RS_LED D	7.98	0.80	9.98	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Retail	Turnover	T_RT_LED D	11.84	0.80	14.82	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Schools K-12	Turnover	T_SC_LED D	5.70	0.81	7.08	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Warehouse	Turnover	T_WR_LED I	9.16	0.81	11.37	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Assembly	New	N_AS_LED I	6.89	0.81	8.55	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	College and University	New	N_CU_LED I	6.70	0.51	13.11	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Grocery	New	N_GR_LED I	13.17	0.80	16.49	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Healthcare	New	N_HC_LED I	12.04	0.81	14.95	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Hospitals	New	N_HS_LED I	10.35	0.51	20.23	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Institutional	New	N_IN_LED D	7.90	0.81	9.81	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Lodging/Hospitality	New	N_LG_LED I	8.92	0.80	11.17	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Miscellaneous	New	N_MS_LED I	10.56	0.81	13.11	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Offices	New	N_OF_LED I	7.79	0.81	9.68	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Restaurants	New	N_RS_LED I	7.98	0.80	9.98	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Retail	New	N_RT_LED I	11.84	0.80	14.82	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Schools K-12	New	N_SC_LED I	5.70	0.81	7.08	0	0	0	Fail 2-year Threshold
Commercial	LED Display Lighting (Interior)	Warehouse	New	N_WR_LED	9.16	0.81	11.37	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Assembly	Turnover	T_AS_LED L	10.80	0.80	13.53	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	College and University	Turnover	T_CU_LED L	10.59	0.51	20.74	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Grocery	Turnover	T_GR_LED L	20.91	0.80	26.08	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Healthcare	Turnover	T_HC_LED L	18.89	0.80	23.65	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Hospitals	Turnover	T_HS_LED L	16.35	0.51	32.00	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Institutional	Turnover	T_IN_LED Li	12.39	0.80	15.52	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Lodging/Hospitality	Turnover	T_LG_LED L	14.16	0.80	17.66	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Miscellaneous	Turnover	T_MS_LED L	16.56	0.80	20.74	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Offices	Turnover	T_OF_LED L	12.22	0.80	15.30	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Restaurants	Turnover	T_RS_LED L	12.66	0.80	15.79	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Retail	Turnover	T_RT_LED L	18.79	0.80	23.45	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Schools K-12	Turnover	T_SC_LED L	8.94	0.80	11.19	0	0	0	Fail 2-year Threshold

Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Warehouse	Turnover	T_WR_Variab	0.21	0.89	0.24	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Assembly	New	N_AS_Variab	0.81	0.89	0.91	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	College and University	New	N_CU_Variab	0.74	0.74	1.00	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Grocery	New	N_GR_Variab	0.50	0.89	0.56	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Healthcare	New	N_HC_Variab	1.73	0.89	1.95	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Hospitals	New	N_HS_Variab	1.65	0.89	1.86	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Institutional	New	N_IN_Variab	0.45	0.89	0.51	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Lodging/Hospitality	New	N_LG_Variab	1.68	0.74	1.48	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Miscellaneous	New	N_MS_Variab	0.45	0.89	0.51	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Offices	New	N_OF_Variab	0.88	0.89	1.00	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Restaurants	New	N_RS_Variab	1.40	0.89	1.57	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Retail	New	N_RT_Variab	1.07	0.89	1.21	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Schools K-12	New	N_SC_Variab	0.93	0.89	1.05	0	0	0	Fail RIM
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Warehouse	New	N_WR_Varia	0.21	0.89	0.24	0	0	0	Fail RIM
Commercial	CFL-23W	Assembly	Turnover	T_AS_CFL-2	9.84	0.64	15.34	0	0	0	Fail RIM
Commercial	CFL-23W	College and University	Turnover	T_CU_CFL-2	10.06	0.43	23.51	0	0	0	Fail RIM
Commercial	CFL-23W	Grocery	Turnover	T_GR_CFL-2	19.01	0.64	29.57	0	0	0	Fail RIM
Commercial	CFL-23W	Healthcare	Turnover	T_HC_CFL-2	17.20	0.64	26.82	0	0	0	Fail RIM
Commercial	CFL-23W	Hospitals	Turnover	T_HS_CFL-2	15.52	0.43	36.28	0	0	0	Fail RIM
Commercial	CFL-23W	Institutional	Turnover	T_IN_CFL-2	11.29	0.64	17.60	0	0	0	Fail RIM
Commercial	CFL-23W	Lodging/Hospitality	Turnover	T_LG_CFL-2	12.87	0.64	20.02	0	0	0	Fail RIM
Commercial	CFL-23W	Miscellaneous	Turnover	T_MS_CFL-2	15.08	0.64	23.51	0	0	0	Fail RIM
Commercial	CFL-23W	Offices	Turnover	T_OF_CFL-2	11.13	0.64	17.35	0	0	0	Fail RIM
Commercial	CFL-23W	Restaurants	Turnover	T_RS_CFL-2	11.51	0.64	17.91	0	0	0	Fail RIM
Commercial	CFL-23W	Retail	Turnover	T_RT_CFL-2	17.09	0.64	26.58	0	0	0	Fail RIM
Commercial	CFL-23W	Schools K-12	Turnover	T_SC_CFL-2	8.14	0.64	12.69	0	0	0	Fail RIM
Commercial	CFL-23W	Warehouse	Turnover	T_WR_CFL-2	13.08	0.64	20.40	0	0	0	Fail RIM
Commercial	CFL-23W	Assembly	New	N_AS_CFL-2	9.84	0.64	15.34	0	0	0	Fail RIM
Commercial	CFL-23W	College and University	New	N_CU_CFL-2	10.06	0.43	23.51	0	0	0	Fail RIM
Commercial	CFL-23W	Grocery	New	N_GR_CFL-2	19.01	0.64	29.57	0	0	0	Fail RIM
Commercial	CFL-23W	Healthcare	New	N_HC_CFL-2	17.20	0.64	26.82	0	0	0	Fail RIM
Commercial	CFL-23W	Hospitals	New	N_HS_CFL-2	15.52	0.43	36.28	0	0	0	Fail RIM
Commercial	CFL-23W	Institutional	New	N_IN_CFL-2	11.29	0.64	17.60	0	0	0	Fail RIM
Commercial	CFL-23W	Lodging/Hospitality	New	N_LG_CFL-2	12.87	0.64	20.02	0	0	0	Fail RIM
Commercial	CFL-23W	Miscellaneous	New	N_MS_CFL-2	15.08	0.64	23.51	0	0	0	Fail RIM
Commercial	CFL-23W	Offices	New	N_OF_CFL-2	11.13	0.64	17.35	0	0	0	Fail RIM
Commercial	CFL-23W	Restaurants	New	N_RS_CFL-2	11.51	0.64	17.91	0	0	0	Fail RIM
Commercial	CFL-23W	Retail	New	N_RT_CFL-2	17.09	0.64	26.58	0	0	0	Fail RIM
Commercial	CFL-23W	Schools K-12	New	N_SC_CFL-2	8.14	0.64	12.69	0	0	0	Fail RIM
Commercial	CFL-23W	Warehouse	New	N_WR_CFL-2	13.08	0.64	20.40	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Assembly	Turnover	T_AS_High B	4.33	0.68	6.38	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	College and University	Turnover	T_CU_High B	6.63	0.68	9.78	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Grocery	Turnover	T_GR_High B	8.34	0.68	12.30	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Healthcare	Turnover	T_HC_High B	7.57	0.68	11.16	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Hospitals	Turnover	T_HS_High B	10.24	0.68	15.09	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Institutional	Turnover	T_IN_High B	4.97	0.68	7.32	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Lodging/Hospitality	Turnover	T_LG_High B	5.65	0.68	8.33	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Miscellaneous	Turnover	T_MS_High B	6.63	0.68	9.78	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Offices	Turnover	T_OF_High B	4.90	0.68	7.22	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Restaurants	Turnover	T_RS_High B	5.05	0.68	7.45	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Retail	Turnover	T_RT_High B	7.50	0.68	11.06	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Schools K-12	Turnover	T_SC_High B	3.58	0.68	5.28	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Warehouse	Turnover	T_WR_High	5.76	0.68	8.48	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Assembly	New	N_AS_High B	4.33	0.68	6.38	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	College and University	New	N_CU_High B	6.63	0.68	9.78	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Grocery	New	N_GR_High B	8.34	0.68	12.30	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Healthcare	New	N_HC_High B	7.57	0.68	11.16	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Hospitals	New	N_HS_High B	10.24	0.68	15.09	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Institutional	New	N_IN_High B	4.97	0.68	7.32	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Lodging/Hospitality	New	N_LG_High B	5.65	0.68	8.33	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Miscellaneous	New	N_MS_High B	6.63	0.68	9.78	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Offices	New	N_OF_High B	4.90	0.68	7.22	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Restaurants	New	N_RS_High B	5.05	0.68	7.45	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Retail	New	N_RT_High B	7.50	0.68	11.06	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Schools K-12	New	N_SC_High B	3.58	0.68	5.28	0	0	0	Fail RIM
Commercial	High Bay Fluorescent (T5)	Warehouse	New	N_WR_High	5.76	0.68	8.48	0	0	0	Fail RIM
Commercial	High Bay LED	Assembly	Turnover	T_AS_High B	2.93	0.68	4.33	0	0	0	Fail RIM
Commercial	High Bay LED	College and University	Turnover	T_CU_High B	4.50	0.68	6.63	0	0	0	Fail RIM
Commercial	High Bay LED	Grocery	Turnover	T_GR_High B	5.66	0.68	8.34	0	0	0	Fail RIM
Commercial	High Bay LED	Healthcare	Turnover	T_HC_High B	5.13	0.68	7.56	0	0	0	Fail RIM
Commercial	High Bay LED	Hospitals	Turnover	T_HS_High B	6.94	0.68	10.23	0	0	0	Fail RIM
Commercial	High Bay LED	Institutional	Turnover	T_IN_High B	3.37	0.68	4.96	0	0	0	Fail RIM
Commercial	High Bay LED	Lodging/Hospitality	Turnover	T_LG_High B	3.83	0.68	5.65	0	0	0	Fail RIM
Commercial	High Bay LED	Miscellaneous	Turnover	T_MS_High B	4.50	0.68	6.63	0	0	0	Fail RIM
Commercial	High Bay LED	Offices	Turnover	T_OF_High B	3.32	0.68	4.89	0	0	0	Fail RIM
Commercial	High Bay LED	Restaurants	Turnover	T_RS_High B	3.42	0.68	5.05	0	0	0	Fail RIM
Commercial	High Bay LED	Retail	Turnover	T_RT_High B	5.08	0.68	7.50	0	0	0	Fail RIM
Commercial	High Bay LED	Schools K-12	Turnover	T_SC_High B	2.43	0.68	3.58	0	0	0	Fail RIM
Commercial	High Bay LED	Warehouse	Turnover	T_WR_High	3.90	0.68	5.75	0	0	0	Fail RIM
Commercial	LED - 14W	Assembly	Turnover	T_AS_LED -	21.51	0.79	27.11	0	0	0	Fail RIM
Commercial	LED - 14W	College and University	Turnover	T_CU_LED -	20.95	0.50	41.55	0	0	0	Fail RIM
Commercial	LED - 14W	Grocery	Turnover	T_GR_LED -	41.56	0.80	52.25	0	0	0	Fail RIM
Commercial	LED - 14W	Healthcare	Turnover	T_HC_LED -	37.60	0.79	47.39	0	0	0	Fail RIM
Commercial	LED - 14W	Hospitals	Turnover	T_HS_LED -	32.33	0.50	64.11	0	0	0	Fail RIM
Commercial	LED - 14W	Institutional	Turnover	T_IN_LED -	24.67	0.79	31.09	0	0	0	Fail RIM
Commercial	LED - 14W	Lodging/Hospitality	Turnover	T_LG_LED -	28.14	0.80	35.38	0	0	0	Fail RIM
Commercial	LED - 14W	Miscellaneous	Turnover	T_MS_LED -	32.96	0.79	41.55	0	0	0	Fail RIM
Commercial	LED - 14W	Offices	Turnover	T_OF_LED -	24.32	0.79	30.66	0	0	0	Fail RIM
Commercial	LED - 14W	Restaurants	Turnover	T_RS_LED -	25.16	0.80	31.64	0	0	0	Fail RIM
Commercial	LED - 14W	Retail	Turnover	T_RT_LED -	37.36	0.80	46.98	0	0	0	Fail RIM
Commercial	LED - 14W	Schools K-12	Turnover	T_SC_LED -	17.79	0.79	22.42	0	0	0	Fail RIM
Commercial	LED - 14W	Warehouse	Turnover	T_WR_LED	28.59	0.79	36.04	0	0	0	Fail RIM
Commercial	LED - 14W	Assembly	New	N_AS_LED -	21.51	0.79	27.11	0	0	0	Fail RIM
Commercial	LED - 14W	College and University	New	N_CU_LED -	20.95	0.50	41.55	0	0	0	Fail RIM
Commercial	LED - 14W	Grocery	New	N_GR_LED -	41.56	0.80	52.25	0	0	0	Fail RIM
Commercial	LED - 14W	Healthcare	New	N_HC_LED	37.60	0.79	47.39	0	0	0	Fail RIM
Commercial	LED - 14W	Hospitals	New	N_HS_LED -	32.33	0.50	64.11	0	0	0	Fail RIM
Commercial	LED - 14W	Institutional	New	N_IN_LED -	24.67	0.79	31.09	0	0	0	Fail RIM
Commercial	LED - 14W	Lodging/Hospitality	New	N_LG_LED -	28.14	0.80	35.38	0	0	0	Fail RIM
Commercial	LED - 14W	Miscellaneous	New	N_MS_LED	32.96	0.79	41.55	0	0	0	Fail RIM
Commercial	LED - 14W	Offices	New	N_OF_LED -	24.32	0.79	30.66	0	0	0	Fail RIM
Commercial	LED - 14W	Restaurants	New	N_RS_LED -	25.16	0.80	31.64	0	0	0	Fail RIM
Commercial	LED - 14W	Retail	New	N_RT_LED -	37.36	0.80	46.98	0	0	0	Fail RIM
Commercial	LED - 14W	Schools K-12	New	N_SC_LED -	17.79	0.79	22.42	0	0	0	Fail RIM
Commercial	LED - 14W	Warehouse	New	N_WR_LED	28.59	0.79	36.04	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Assembly	Turnover	T_AS_LED D	6.88	0.81	8.55	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	College and University	Turnover	T_CU_LED D	6.78	0.51	13.11	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Grocery	Turnover	T_GR_LED D	13.17	0.80	16.49	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Healthcare	Turnover	T_HC_LED D	12.04	0.81	14.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Hospitals	Turnover	T_HS_LED D	15.18	0.43	35.25	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Institutional	Turnover	T_IN_LED D	11.01	0.64	17.09	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Lodging/Hospitality	Turnover	T_LG_LED D	12.51	0.64	19.45	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Miscellaneous	Turnover	T_MS_LED D	14.71	0.64	22.84	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Offices	Turnover	T_OF_LED D	10.85	0.64	16.86	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Restaurants	Turnover	T_RS_LED D	11.19	0.64	17.39	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Retail	Turnover	T_RT_LED D	16.61	0.64	25.83	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Schools K-12	Turnover	T_SC_LED D	7.94	0.64	12.33	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Warehouse	Turnover	T_WR_LED D	12.76	0.64	19.81	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Assembly	New	N_AS_LED D	9.59	0.64	14.90	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	College and University	New	N_CU_LED D	9.84	0.43	22.84	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Grocery	New	N_GR_LED D	18.48	0.64	28.73	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Healthcare	New	N_HC_LED D	16.77	0.64	26.05	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Hospitals	New	N_HS_LED D	15.18	0.43	35.25	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Institutional	New	N_IN_LED D	11.01	0.64	17.09	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Lodging/Hospitality	New	N_LG_LED D	12.51	0.64	19.45	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Miscellaneous	New	N_MS_LED D	14.71	0.64	22.84	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Offices	New	N_OF_LED D	10.85	0.64	16.86	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Restaurants	New	N_RS_LED D	11.19	0.64	17.39	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Retail	New	N_RT_LED D	16.61	0.64	25.83	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Schools K-12	New	N_SC_LED D	7.94	0.64	12.33	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Warehouse	New	N_WR_LED D	12.76	0.64	19.81	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Assembly	Turnover	T_AS_LED L	8.45	0.80	10.61	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	College and University	Turnover	T_CU_LED L	8.26	0.51	16.26	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Grocery	Turnover	T_GR_LED L	16.28	0.80	20.45	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Healthcare	Turnover	T_HC_LED L	14.77	0.80	18.54	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Hospitals	Turnover	T_HS_LED L	12.75	0.51	25.09	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Institutional	Turnover	T_IN_LED L	9.69	0.80	12.17	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Lodging/Hospitality	Turnover	T_LG_LED L	11.02	0.80	13.85	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Miscellaneous	Turnover	T_MS_LED L	12.95	0.80	16.26	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Offices	Turnover	T_OF_LED L	9.56	0.80	12.00	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Restaurants	Turnover	T_RS_LED L	9.86	0.80	12.38	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Retail	Turnover	T_RT_LED L	14.63	0.80	18.38	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Schools K-12	Turnover	T_SC_LED L	6.99	0.80	8.77	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Warehouse	Turnover	T_WR_LED	11.24	0.80	14.10	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Assembly	New	N_AS_LED L	8.45	0.80	10.61	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	College and University	New	N_CU_LED L	8.26	0.51	16.26	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Grocery	New	N_GR_LED L	16.28	0.80	20.45	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Healthcare	New	N_HC_LED L	14.77	0.80	18.54	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Hospitals	New	N_HS_LED L	12.75	0.51	25.09	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Institutional	New	N_IN_LED L	9.69	0.80	12.17	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Lodging/Hospitality	New	N_LG_LED L	11.02	0.80	13.85	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Miscellaneous	New	N_MS_LED L	12.95	0.80	16.26	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Offices	New	N_OF_LED L	9.56	0.80	12.00	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Restaurants	New	N_RS_LED L	9.86	0.80	12.38	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Retail	New	N_RT_LED L	14.63	0.80	18.38	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Schools K-12	New	N_SC_LED L	6.99	0.80	8.77	0	0	0	Fail 2-year Threshold
Commercial	LED Linear - Fixture Replacement	Warehouse	New	N_WR_LED	11.24	0.80	14.10	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Fixture Replacement	Assembly	Turnover	T_AS_Premi	0.63	0.65	0.98	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	College and University	Turnover	T_CU_Premi	0.65	0.43	1.51	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Institutional	Turnover	T_IN_Premi	0.73	0.65	1.13	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Lodging/Hospitality	Turnover	T_LG_Premi	0.83	0.65	1.28	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Miscellaneous	Turnover	T_MS_Premi	0.97	0.65	1.51	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Offices	Turnover	T_OF_Premi	0.72	0.65	1.11	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Restaurants	Turnover	T_RS_Premi	0.74	0.65	1.15	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Schools K-12	Turnover	T_SC_Premi	0.52	0.65	0.81	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Warehouse	Turnover	T_WR_Premi	0.84	0.65	1.31	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Assembly	New	N_AS_Premi	0.63	0.65	0.98	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	College and University	New	N_CU_Premi	0.65	0.43	1.51	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Institutional	New	N_IN_Premi	0.73	0.65	1.13	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Lodging/Hospitality	New	N_LG_Premi	0.83	0.65	1.28	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Miscellaneous	New	N_MS_Premi	0.97	0.65	1.51	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Offices	New	N_OF_Premi	0.72	0.65	1.11	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Restaurants	New	N_RS_Premi	0.74	0.65	1.15	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Schools K-12	New	N_SC_Premi	0.52	0.65	0.81	0	0	0	Fail TRC
Commercial	Premium T8 - Fixture Replacement	Warehouse	New	N_WR_Premi	0.84	0.65	1.31	0	0	0	Fail TRC
Commercial	Premium T8 - Lamp Replacement	Assembly	Turnover	T_AS_Premi	9.59	0.64	14.90	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	College and University	Turnover	T_CU_Premi	9.84	0.43	22.84	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Grocery	Turnover	T_GR_Premi	18.48	0.64	28.73	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Healthcare	Turnover	T_HC_Premi	16.77	0.64	26.05	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Hospitals	Turnover	T_HS_Premi	15.18	0.43	35.25	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Institutional	Turnover	T_IN_Premi	11.01	0.64	17.09	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Lodging/Hospitality	Turnover	T_LG_Premi	12.51	0.64	19.45	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Miscellaneous	Turnover	T_MS_Premi	14.71	0.64	22.84	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Offices	Turnover	T_OF_Premi	10.85	0.64	16.86	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Restaurants	Turnover	T_RS_Premi	11.19	0.64	17.39	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Retail	Turnover	T_RT_Premi	16.61	0.64	25.83	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Schools K-12	Turnover	T_SC_Premi	7.94	0.64	12.33	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Warehouse	Turnover	T_WR_Premi	12.76	0.64	19.81	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Assembly	New	N_AS_Premi	9.59	0.64	14.90	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	College and University	New	N_CU_Premi	9.84	0.43	22.84	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Grocery	New	N_GR_Premi	18.48	0.64	28.73	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Healthcare	New	N_HC_Premi	16.77	0.64	26.05	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Hospitals	New	N_HS_Premi	15.18	0.43	35.25	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Institutional	New	N_IN_Premi	11.01	0.64	17.09	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Lodging/Hospitality	New	N_LG_Premi	12.51	0.64	19.45	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Miscellaneous	New	N_MS_Premi	14.71	0.64	22.84	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Offices	New	N_OF_Premi	10.85	0.64	16.86	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Restaurants	New	N_RS_Premi	11.19	0.64	17.39	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Retail	New	N_RT_Premi	16.61	0.64	25.83	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Schools K-12	New	N_SC_Premi	7.94	0.64	12.33	0	0	0	Fail 2-year Threshold
Commercial	Premium T8 - Lamp Replacement	Warehouse	New	N_WR_Premi	12.76	0.64	19.81	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Commercial Clothes Washer	Assembly	Turnover	T_AS_ENER	0.29	0.27	1.11	0	0	0	Fail TRC
Commercial	ENERGY STAR Commercial Clothes Washer	College and University	Turnover	T_CU_ENER	0.46	0.42	1.11	0	0	0	Fail TRC
Commercial	ENERGY STAR Commercial Clothes Washer	Grocery	Turnover	T_GR_ENER	0.43	0.39	1.11	0	0	0	Fail TRC
Commercial	ENERGY STAR Commercial Clothes Washer	Healthcare	Turnover	T_HC_ENER	0.43	0.39	1.11	0	0	0	Fail TRC
Commercial	ENERGY STAR Commercial Clothes Washer	Hospitals	Turnover	T_HS_EN

Commercial	LED Display Lighting (Interior)	Hospitals	Turnover	T_HS_LED D	10.35	0.51	20.23	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Institutional	Turnover	T_IN_LED D	7.90	0.81	9.81	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Lodging/Hospitality	Turnover	T_LG_LED D	8.92	0.80	11.17	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Miscellaneous	Turnover	T_MS_LED D	10.56	0.81	13.11	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Offices	Turnover	T_OF_LED D	7.79	0.81	9.68	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Restaurants	Turnover	T_RS_LED D	7.98	0.80	9.98	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Retail	Turnover	T_RT_LED D	11.84	0.80	14.82	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Schools K-12	Turnover	T_SC_LED D	5.70	0.81	7.08	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Warehouse	Turnover	T_WR_LED D	9.16	0.81	11.37	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Assembly	New	N_AS_LED D	6.89	0.81	8.55	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	College and University	New	N_CU_LED D	6.70	0.51	13.11	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Grocery	New	N_GR_LED D	13.17	0.80	16.49	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Healthcare	New	N_HC_LED D	12.04	0.81	14.95	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Hospitals	New	N_HS_LED D	10.35	0.51	20.23	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Institutional	New	N_IN_LED D	7.90	0.81	9.81	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Lodging/Hospitality	New	N_LG_LED D	8.92	0.80	11.17	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Miscellaneous	New	N_MS_LED D	10.56	0.81	13.11	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Offices	New	N_OF_LED D	7.79	0.81	9.68	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Restaurants	New	N_RS_LED D	7.98	0.80	9.98	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Retail	New	N_RT_LED D	11.84	0.80	14.82	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Schools K-12	New	N_SC_LED D	5.70	0.81	7.08	0	0	0	Fail RIM
Commercial	LED Display Lighting (Interior)	Warehouse	New	N_WR_LED	9.16	0.81	11.37	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Assembly	Turnover	T_AS_LED L	10.80	0.80	13.53	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	College and University	Turnover	T_CU_LED L	10.59	0.51	20.74	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Grocery	Turnover	T_GR_LED L	20.91	0.80	26.08	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Healthcare	Turnover	T_HC_LED L	18.89	0.80	23.65	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Hospitals	Turnover	T_HS_LED L	16.35	0.51	32.00	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Institutional	Turnover	T_IN_LED L	12.39	0.80	15.52	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Lodging/Hospitality	Turnover	T_LG_LED L	14.16	0.80	17.66	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Miscellaneous	Turnover	T_MS_LED L	16.56	0.80	20.74	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Offices	Turnover	T_OF_LED L	12.22	0.80	15.30	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Restaurants	Turnover	T_RS_LED L	12.66	0.80	15.79	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Retail	Turnover	T_RT_LED L	18.79	0.80	23.45	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Schools K-12	Turnover	T_SC_LED L	8.94	0.80	11.19	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Warehouse	Turnover	T_WR_LED	14.37	0.80	17.99	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Assembly	New	N_AS_LED L	10.80	0.80	13.53	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	College and University	New	N_CU_LED L	10.59	0.51	20.74	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Grocery	New	N_GR_LED L	20.91	0.80	26.08	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Healthcare	New	N_HC_LED L	18.89	0.80	23.65	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Hospitals	New	N_HS_LED L	16.35	0.51	32.00	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Institutional	New	N_IN_LED L	12.39	0.80	15.52	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Lodging/Hospitality	New	N_LG_LED L	14.16	0.80	17.66	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Miscellaneous	New	N_MS_LED L	16.56	0.80	20.74	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Offices	New	N_OF_LED L	12.22	0.80	15.30	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Restaurants	New	N_RS_LED L	12.66	0.80	15.79	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Retail	New	N_RT_LED L	18.79	0.80	23.45	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Schools K-12	New	N_SC_LED L	8.94	0.80	11.19	0	0	0	Fail RIM
Commercial	LED Linear - Fixture Replacement	Warehouse	New	N_WR_LED	14.37	0.80	17.99	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Assembly	Turnover	T_AS_LED L	8.45	0.80	10.61	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	College and University	Turnover	T_CU_LED L	8.26	0.51	16.26	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Grocery	Turnover	T_GR_LED L	16.28	0.80	20.45	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Healthcare	Turnover	T_HC_LED L	14.77	0.80	18.54	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Hospitals	Turnover	T_HS_LED L	12.75	0.51	25.09	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Institutional	Turnover	T_IN_LED L	9.69	0.80	12.17	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Lodging/Hospitality	Turnover	T_LG_LED L	11.02	0.80	13.85	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Miscellaneous	Turnover	T_MS_LED L	12.95	0.80	16.26	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Offices	Turnover	T_OF_LED L	9.56	0.80	12.00	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Restaurants	Turnover	T_RS_LED L	9.86	0.80	12.38	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Retail	Turnover	T_RT_LED L	14.63	0.80	18.38	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Schools K-12	Turnover	T_SC_LED L	6.99	0.80	8.77	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Warehouse	Turnover	T_WR_LED	11.24	0.80	14.10	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Assembly	New	N_AS_LED L	8.45	0.80	10.61	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	College and University	New	N_CU_LED L	8.26	0.51	16.26	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Grocery	New	N_GR_LED L	16.28	0.80	20.45	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Healthcare	New	N_HC_LED L	14.77	0.80	18.54	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Hospitals	New	N_HS_LED L	12.75	0.51	25.09	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Institutional	New	N_IN_LED L	9.69	0.80	12.17	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Lodging/Hospitality	New	N_LG_LED L	11.02	0.80	13.85	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Miscellaneous	New	N_MS_LED L	12.95	0.80	16.26	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Offices	New	N_OF_LED L	9.56	0.80	12.00	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Restaurants	New	N_RS_LED L	9.86	0.80	12.38	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Retail	New	N_RT_LED L	14.63	0.80	18.38	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Schools K-12	New	N_SC_LED L	6.99	0.80	8.77	0	0	0	Fail RIM
Commercial	LED Linear - Lamp Replacement	Warehouse	New	N_WR_LED	11.24	0.80	14.10	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Assembly	Turnover	T_AS_Premi	0.63	0.65	0.98	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	College and University	Turnover	T_CU_Premi	0.65	0.43	1.51	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Grocery	Turnover	T_GR_Premi	1.23	0.65	1.90	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Healthcare	Turnover	T_HC_Premi	1.11	0.65	1.72	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Hospitals	Turnover	T_HS_Premi	1.01	0.43	2.33	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Institutional	Turnover	T_IN_Premi	0.73	0.65	1.13	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Lodging/Hospitality	Turnover	T_LG_Premi	0.83	0.65	1.28	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Miscellaneous	Turnover	T_MS_Premi	0.97	0.65	1.51	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Offices	Turnover	T_OF_Premi	0.72	0.65	1.11	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Restaurants	Turnover	T_RS_Premi	0.74	0.65	1.15	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Retail	Turnover	T_RT_Premi	1.10	0.65	1.70	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Schools K-12	Turnover	T_SC_Premi	0.52	0.65	0.81	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Warehouse	Turnover	T_WR_Premi	0.84	0.65	1.31	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Assembly	New	N_AS_Premi	0.63	0.65	0.98	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	College and University	New	N_CU_Premi	0.65	0.43	1.51	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Grocery	New	N_GR_Premi	1.23	0.65	1.90	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Healthcare	New	N_HC_Premi	1.11	0.65	1.72	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Hospitals	New	N_HS_Premi	1.01	0.43	2.33	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Institutional	New	N_IN_Premi	0.73	0.65	1.13	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Lodging/Hospitality	New	N_LG_Premi	0.83	0.65	1.28	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Miscellaneous	New	N_MS_Premi	0.97	0.65	1.51	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Offices	New	N_OF_Premi	0.72	0.65	1.11	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Restaurants	New	N_RS_Premi	0.74	0.65	1.15	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Retail	New	N_RT_Premi	1.10	0.65	1.70	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Schools K-12	New	N_SC_Premi	0.52	0.65	0.81	0	0	0	Fail RIM
Commercial	Premium T8 - Fixture Replacement	Warehouse	New	N_WR_Premi	0.84	0.65	1.31	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Assembly	Turnover	T_AS_Premi	9.59	0.64	14.90	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	College and University	Turnover	T_CU_Premi	9.84	0.43	22.84	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Grocery	Turnover	T_GR_Premi	18.48	0.64	28.73	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Healthcare	Turnover	T_HC_Premi	16.77	0.64	26.05	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Hospitals	Turnover	T_HS_Premi	15.18	0.43	35.25	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Institutional	Turnover	T_IN_Premi	11.01	0.64	17.09	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Lodging/Hospitality	Turnover	T_LG_Premi	12.51	0.64	19.45	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Miscellaneous	Turnover	T_MS_Premi	14.71	0.64	22.84	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Offices	Turnover	T_OF_Premi	10.85	0.64	16.86	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Restaurants	Turnover	T_RS_Premi	11.19	0.64	17.39	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Retail	Turnover	T_RT_Premi	16.61	0.64	25.83	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Schools K-12	Turnover	T_SC_Premi	7.94	0.64	12.33	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Warehouse	Turnover	T_WR_Premi	12.76	0.64	19.81	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Assembly	New	N_AS_Premi	9.59	0.64	14.90	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	College and University	New	N_CU_Premi	9.84	0.43	22.84	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Grocery	New	N_GR_Premi	18.48	0.64	28.73	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Healthcare	New	N_HC_Premi	16.77	0.64	26.05	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Hospitals	New	N_HS_Premi	15.18	0.43	35.25	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Institutional	New	N_IN_Premi	11.01	0.64	17.09	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Lodging/Hospitality	New	N_LG_Premi	12.51	0.64	19.45	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Miscellaneous	New	N_MS_Premi	14.71	0.64	22.84	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Offices	New	N_OF_Premi	10.85	0.64	16.86	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Restaurants	New	N_RS_Premi	11.19	0.64	17.39	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Retail	New	N_RT_Premi	16.61	0.64	25.83	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Schools K-12	New	N_SC_Premi	7.94	0.64	12.33	0	0	0	Fail RIM
Commercial	Premium T8 - Lamp Replacement	Warehouse	New	N_WR_Premi	12.76	0.64	19.81	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Assembly	Turnover	T_AS_ENER	0.29	0.27	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	College and University	Turnover	T_CU_ENER	0.46	0.42	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Grocery	Turnover	T_GR_ENER	0.43	0.39	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Healthcare	Turnover	T_HC_ENER	0.43	0.39	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Hospitals	Turnover	T_HS_ENER	0.46	0.42	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Institutional	Turnover	T_IN_ENER	0.29	0.27	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Lodging/Hospitality	Turnover	T_LG_ENER	0.46	0.42	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Miscellaneous	Turnover	T_MS_ENER	0.29	0.27	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Offices	Turnover	T_OF_ENER	0.43	0.39	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Restaurants	Turnover	T_RS_ENER	0.29	0.27	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Retail	Turnover	T_RT_ENER	0.43	0.39	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Schools K-12	Turnover	T_SC_ENER	0.46	0.42	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Warehouse	Turnover	T_WR_ENER	0.29	0.27	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Assembly	New	N_AS_ENER	0.29	0.27	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	College and University	New	N_CU_ENER	0.46	0.42	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Grocery	New	N_GR_ENER	0.43	0.39	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Healthcare	New	N_HC_ENER	0.43	0.39	1.11	0	0	0	Fail RIM

Commercial	ENERGY STAR Water Cooler	Warehouse	Turnover	T_WR_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Water Cooler	Assembly	New	N_AS_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Water Cooler	College and University	New	N_CU_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Water Cooler	Grocery	New	N_GR_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Water Cooler	Healthcare	New	N_HC_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Water Cooler	Hospitals	New	N_HS_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Water Cooler	Institutional	New	N_IN_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Water Cooler	Lodging/Hospitality	New	N_LG_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Water Cooler	Miscellaneous	New	N_MS_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Water Cooler	Offices	New	N_OF_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Water Cooler	Restaurants	New	N_RS_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Water Cooler	Retail	New	N_RT_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Water Cooler	Schools K-12	New	N_SC_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	ENERGY STAR Water Cooler	Warehouse	New	N_WR_ENER	3.00	0.59	5.08	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Assembly	Turnover	T_AS_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	College and University	Turnover	T_CU_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Grocery	Turnover	T_GR_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Healthcare	Turnover	T_HC_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Hospitals	Turnover	T_HS_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Institutional	Turnover	T_IN_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Lodging/Hospitality	Turnover	T_LG_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Miscellaneous	Turnover	T_MS_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Offices	Turnover	T_OF_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Restaurants	Turnover	T_RS_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Retail	Turnover	T_RT_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Schools K-12	Turnover	T_SC_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Warehouse	Turnover	T_WR_Heat	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Assembly	New	N_AS_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	College and University	New	N_CU_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Grocery	New	N_GR_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Healthcare	New	N_HC_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Hospitals	New	N_HS_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Institutional	New	N_IN_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Lodging/Hospitality	New	N_LG_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Miscellaneous	New	N_MS_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Offices	New	N_OF_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Restaurants	New	N_RS_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Retail	New	N_RT_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Schools K-12	New	N_SC_Heat P	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Heat Pump Pool Heater	Warehouse	New	N_WR_Heat	3.84	0.33	11.49	0	0	0	Fail 2-year Threshold
Commercial	Solar Powered Pool Pump	Assembly	Turnover	T_AS_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	College and University	Turnover	T_CU_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Grocery	Turnover	T_GR_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Healthcare	Turnover	T_HC_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Hospitals	Turnover	T_HS_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Institutional	Turnover	T_IN_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Lodging/Hospitality	Turnover	T_LG_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Miscellaneous	Turnover	T_MS_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Offices	Turnover	T_OF_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Restaurants	Turnover	T_RS_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Retail	Turnover	T_RT_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Schools K-12	Turnover	T_SC_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Assembly	New	N_AS_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	College and University	New	N_CU_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Grocery	New	N_GR_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Healthcare	New	N_HC_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Hospitals	New	N_HS_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Institutional	New	N_IN_Solar	1.00	0.70	1.42	0	0	0	Fail TRC
Commercial	Solar Powered Pool Pump	Lodging/Hospitality

Commercial	ENERGY STAR Commercial Clothes Washer	Hospitals	New	N_HS_ENER	0.46	0.42	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Institutional	New	N_IN_ENER	0.29	0.27	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Lodging/Hospitality	New	N_LG_ENER	0.46	0.42	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Miscellaneous	New	N_MS_ENER	0.29	0.27	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Offices	New	N_OF_ENER	0.43	0.39	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Restaurants	New	N_RS_ENER	0.29	0.27	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Retail	New	N_RT_ENER	0.43	0.39	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Schools K-12	New	N_SC_ENER	0.46	0.42	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Commercial Clothes Washer	Warehouse	New	N_WR_ENE	0.29	0.27	1.11	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Assembly	Turnover	T_AS_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	College and University	Turnover	T_CU_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Grocery	Turnover	T_GR_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Healthcare	Turnover	T_HC_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Hospitals	Turnover	T_HS_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Institutional	Turnover	T_IN_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Lodging/Hospitality	Turnover	T_LG_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Miscellaneous	Turnover	T_MS_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Offices	Turnover	T_OF_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Restaurants	Turnover	T_RS_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Retail	Turnover	T_RT_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Schools K-12	Turnover	T_SC_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Warehouse	Turnover	T_WR_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Assembly	New	N_AS_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	College and University	New	N_CU_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Grocery	New	N_GR_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Healthcare	New	N_HC_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Hospitals	New	N_HS_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Institutional	New	N_IN_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Lodging/Hospitality	New	N_LG_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Miscellaneous	New	N_MS_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Offices	New	N_OF_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Restaurants	New	N_RS_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Retail	New	N_RT_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Schools K-12	New	N_SC_ENER	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	ENERGY STAR Water Cooler	Warehouse	New	N_WR_ENE	3.00	0.59	5.08	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Assembly	Turnover	T_AS_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	College and University	Turnover	T_CU_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Grocery	Turnover	T_GR_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Healthcare	Turnover	T_HC_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Hospitals	Turnover	T_HS_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Institutional	Turnover	T_IN_Heat Pi	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Lodging/Hospitality	Turnover	T_LG_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Miscellaneous	Turnover	T_MS_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Offices	Turnover	T_OF_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Restaurants	Turnover	T_RS_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Retail	Turnover	T_RT_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Schools K-12	Turnover	T_SC_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Warehouse	Turnover	T_WR_Heat	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Assembly	New	N_AS_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	College and University	New	N_CU_Heat	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Grocery	New	N_GR_Heat	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Healthcare	New	N_HC_Heat	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Hospitals	New	N_HS_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Institutional	New	N_IN_Heat Pi	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Lodging/Hospitality	New	N_LG_Heat	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Miscellaneous	New	N_MS_Heat	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Offices	New	N_OF_Heat	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Restaurants	New	N_RS_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Retail	New	N_RT_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Schools K-12	New	N_SC_Heat P	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Heat Pump Pool Heater	Warehouse	New	N_WR_Heat	3.84	0.33	11.49	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Assembly	Turnover	T_AS_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	College and University	Turnover	T_CU_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Grocery	Turnover	T_GR_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Healthcare	Turnover	T_HC_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Hospitals	Turnover	T_HS_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Institutional	Turnover	T_IN_Solar P	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Lodging/Hospitality	Turnover	T_LG_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Miscellaneous	Turnover	T_MS_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Offices	Turnover	T_OF_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Restaurants	Turnover	T_RS_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Retail	Turnover	T_RT_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Schools K-12	Turnover	T_SC_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Warehouse	Turnover	T_WR_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Assembly	New	N_AS_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	College and University	New	N_CU_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Grocery	New	N_GR_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Healthcare	New	N_HC_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Hospitals	New	N_HS_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Institutional	New	N_IN_Solar P	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Lodging/Hospitality	New	N_LG_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Miscellaneous	New	N_MS_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Offices	New	N_OF_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Restaurants	New	N_RS_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Retail	New	N_RT_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Schools K-12	New	N_SC_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Pool Heater	Warehouse	New	N_WR_Solar	1.08	0.33	3.23	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Assembly	Turnover	T_AS_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	College and University	Turnover	T_CU_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Grocery	Turnover	T_GR_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Healthcare	Turnover	T_HC_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Hospitals	Turnover	T_HS_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Institutional	Turnover	T_IN_Solar P	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Lodging/Hospitality	Turnover	T_LG_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Miscellaneous	Turnover	T_MS_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Offices	Turnover	T_OF_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Restaurants	Turnover	T_RS_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Retail	Turnover	T_RT_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Schools K-12	Turnover	T_SC_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Assembly	New	N_AS_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	College and University	New	N_CU_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Grocery	New	N_GR_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Healthcare	New	N_HC_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Hospitals	New	N_HS_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Institutional	New	N_IN_Solar P	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Lodging/Hospitality	New	N_LG_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Miscellaneous	New	N_MS_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Offices	New	N_OF_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Restaurants	New	N_RS_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Retail	New	N_RT_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Schools K-12	New	N_SC_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Solar Powered Pool Pump	Warehouse	New	N_WR_Solar	1.00	0.70	1.42	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Assembly	Turnover	T_AS_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	College and University	Turnover	T_CU_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Grocery	Turnover	T_GR_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Healthcare	Turnover	T_HC_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Hospitals	Turnover	T_HS_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Institutional	Turnover	T_IN_Two Sp	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Lodging/Hospitality	Turnover	T_LG_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Miscellaneous	Turnover	T_MS_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Offices	Turnover	T_OF_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Restaurants	Turnover	T_RS_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Retail	Turnover	T_RT_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Schools K-12	Turnover	T_SC_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Warehouse	Turnover	T_WR_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Assembly	New	N_AS_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	College and University	New	N_CU_Two S	4.78	0.70	6.81	0	0	0	Fail RIM

Commercial	Energy Star Servers	College and University	Turnover	T_CU_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Grocery	Turnover	T_GR_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Healthcare	Turnover	T_HC_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Hospitals	Turnover	T_HS_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Institutional	Turnover	T_IN_Energy	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Lodging/Hospitality	Turnover	T_LG_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Miscellaneous	Turnover	T_MS_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Offices	Turnover	T_OF_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Restaurants	Turnover	T_RS_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Retail	Turnover	T_RT_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Schools K-12	Turnover	T_SC_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Warehouse	Turnover	T_WR_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Assembly	New	N_AS_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	College and University	New	N_CU_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Grocery	New	N_GR_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Healthcare	New	N_HC_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Hospitals	New	N_HS_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Institutional	New	N_IN_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Lodging/Hospitality	New	N_LG_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Miscellaneous	New	N_MS_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Offices	New	N_OF_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Restaurants	New	N_RS_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Retail	New	N_RT_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Schools K-12	New	N_SC_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Servers	Warehouse	New	N_WR_Energ	2.60	0.46	5.62	0	0	0	Fail 2-year Threshold
Commercial	Server Virtualization	Assembly	Turnover	T_AS_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	College and University	Turnover	T_CU_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Grocery	Turnover	T_GR_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Healthcare	Turnover	T_HC_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Hospitals	Turnover	T_HS_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Institutional	Turnover	T_IN_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Lodging/Hospitality	Turnover	T_LG_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Miscellaneous	Turnover	T_MS_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Offices	Turnover	T_OF_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Restaurants	Turnover	T_RS_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Retail	Turnover	T_RT_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Schools K-12	Turnover	T_SC_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Warehouse	Turnover	T_WR_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Assembly	New	N_AS_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	College and University	New	N_CU_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Grocery	New	N_GR_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Healthcare	New	N_HC_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Hospitals	New	N_HS_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Institutional	New	N_IN_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Lodging/Hospitality	New	N_LG_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Miscellaneous	New	N_MS_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Offices	New	N_OF_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Restaurants	New	N_RS_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Retail	New	N_RT_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Schools K-12	New	N_SC_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Server Virtualization	Warehouse	New	N_WR_Server	0.15	0.46	0.32	0	0	0	Fail TRC
Commercial	Energy Star Commercial Glass Door Freezer	Assembly	Turnover	T_AS_Energ	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	College and University	Turnover	T_CU_Energ	13.23	0.54	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Grocery	Turnover	T_GR_Energ	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Healthcare	Turnover	T_HC_Energ	13.23	0.54	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Hospitals	Turnover	T_HS_Energ	13.23	0.54	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Institutional	Turnover	T_IN_Energy	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Lodging/Hospitality	Turnover	T_LG_Energ	13.23	0.54	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Miscellaneous	Turnover	T_MS_Energ	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Offices	Turnover	T_OF_Energ	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Restaurants	Turnover	T_RS_Energ	13.23	0.54	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Retail	Turnover	T_RT_Energ	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Schools K-12	Turnover	T_SC_Energ	13.23	0.54	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Warehouse	Turnover	T_WR_Energ	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Assembly	New	N_AS_Energ	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	College and University	New	N_CU_Energ	13.23	0.54	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Grocery	New	N_GR_Energ	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Healthcare	New	N_HC_Energ	13.23	0.54	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Hospitals	New	N_HS_Energ	13.23	0.54	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Institutional	New	N_IN_Energ	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Lodging/Hospitality	New	N_LG_Energ	13.23	0.54	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Miscellaneous	New	N_MS_Energ	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Offices	New	N_OF_Energ	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Restaurants	New	N_RS_Energ	13.23	0.54	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Retail	New	N_RT_Energ	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Schools K-12	New	N_SC_Energ	13.23	0.54	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Freezer	Warehouse	New	N_WR_Energ	14.02	0.57	24.40	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Refrigerator	Assembly	Turnover	T_AS_Energ	2.98	0.57	5.19	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Refrigerator	College and University	Turnover	T_CU_Energ	2.81	0.54	5.19	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Glass Door Refrigerator	Grocery	Turnover	T_GR_Energ	2.98	0.57	5.19

Commercial	Two Speed Pool Pump	Grocery	New	N_GR_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Healthcare	New	N_HC_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Hospitals	New	N_HS_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Institutional	New	N_IN_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Lodging/Hospitality	New	N_LG_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Miscellaneous	New	N_MS_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Offices	New	N_OF_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Restaurants	New	N_RS_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Retail	New	N_RT_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Schools K-12	New	N_SC_Two S	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Two Speed Pool Pump	Warehouse	New	N_WR_Two	4.78	0.70	6.81	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Assembly	Turnover	T_AS_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	College and University	Turnover	T_CU_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Grocery	Turnover	T_GR_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Healthcare	Turnover	T_HC_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Hospitals	Turnover	T_HS_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Institutional	Turnover	T_IN_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Lodging/Hospitality	Turnover	T_LG_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Miscellaneous	Turnover	T_MS_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Offices	Turnover	T_OF_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Restaurants	Turnover	T_RS_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Retail	Turnover	T_RT_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Schools K-12	Turnover	T_SC_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Assembly	New	N_AS_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	College and University	New	N_CU_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Grocery	New	N_GR_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Healthcare	New	N_HC_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Hospitals	New	N_HS_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Institutional	New	N_IN_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Lodging/Hospitality	New	N_LG_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Miscellaneous	New	N_MS_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Offices	New	N_OF_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Restaurants	New	N_RS_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Retail	New	N_RT_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	Variable Speed Pool Pump	Schools K-12	New	N_SC_Variab	1.65	0.70	2.35	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Assembly	Turnover	T_AS_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	College and University	Turnover	T_CU_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Grocery	Turnover	T_GR_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Healthcare	Turnover	T_HC_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Hospitals	Turnover	T_HS_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Institutional	Turnover	T_IN_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Lodging/Hospitality	Turnover	T_LG_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Miscellaneous	Turnover	T_MS_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Offices	Turnover	T_OF_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Restaurants	Turnover	T_RS_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Retail	Turnover	T_RT_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Schools K-12	Turnover	T_SC_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Warehouse	Turnover	T_WR_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Assembly	New	N_AS_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	College and University	New	N_CU_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Grocery	New	N_GR_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Healthcare	New	N_HC_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Hospitals	New	N_HS_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Institutional	New	N_IN_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Lodging/Hospitality	New	N_LG_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Miscellaneous	New	N_MS_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Offices	New	N_OF_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Restaurants	New	N_RS_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Retail	New	N_RT_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Schools K-12	New	N_SC_ENER	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	ENERGY STAR Imaging Equipment	Warehouse	New	N_WR_ENE	0.16	0.45	0.36	0	0	0	Fail RIM
Commercial	Energy Star PCs	Assembly	Turnover	T_AS_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	College and University	Turnover	T_CU_Energ	1.12	0.52	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Grocery	Turnover	T_GR_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Healthcare	Turnover	T_HC_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Hospitals	Turnover	T_HS_Energ	1.12	0.52	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Institutional	Turnover	T_IN_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Lodging/Hospitality	Turnover	T_LG_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Miscellaneous	Turnover	T_MS_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Offices	Turnover	T_OF_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Restaurants	Turnover	T_RS_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Retail	Turnover	T_RT_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Schools K-12	Turnover	T_SC_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Warehouse	Turnover	T_WR_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Assembly	New	N_AS_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	College and University	New	N_CU_Energ	1.12	0.52	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Grocery	New	N_GR_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Healthcare	New	N_HC_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Hospitals	New	N_HS_Energ	1.12	0.52	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Institutional	New	N_IN_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Lodging/Hospitality	New	N_LG_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Miscellaneous	New	N_MS_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Offices	New	N_OF_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Restaurants	New	N_RS_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Retail	New	N_RT_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Schools K-12	New	N_SC_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star PCs	Warehouse	New	N_WR_Energ	0.97	0.45	2.14	0	0	0	Fail RIM
Commercial	Energy Star Servers	Assembly	Turnover	T_AS_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	College and University	Turnover	T_CU_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Grocery	Turnover	T_GR_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Healthcare	Turnover	T_HC_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Hospitals	Turnover	T_HS_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Institutional	Turnover	T_IN_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Lodging/Hospitality	Turnover	T_LG_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Miscellaneous	Turnover	T_MS_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Offices	Turnover	T_OF_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Restaurants	Turnover	T_RS_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Retail	Turnover	T_RT_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Schools K-12	Turnover	T_SC_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Warehouse	Turnover	T_WR_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Assembly	New	N_AS_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	College and University	New	N_CU_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Grocery	New	N_GR_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Healthcare	New	N_HC_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Hospitals	New	N_HS_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Institutional	New	N_IN_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Lodging/Hospitality	New	N_LG_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Miscellaneous	New	N_MS_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Offices	New	N_OF_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Restaurants	New	N_RS_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Retail	New	N_RT_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Schools K-12	New	N_SC_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Servers	Warehouse	New	N_WR_Energ	2.60	0.46	5.62	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Assembly	Turnover	T_AS_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	College and University	Turnover	T_CU_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Grocery	Turnover	T_GR_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Healthcare	Turnover	T_HC_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Hospitals	Turnover	T_HS_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Institutional	Turnover	T_IN_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Lodging/Hospitality	Turnover	T_LG_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Miscellaneous	Turnover	T_MS_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Offices	Turnover	T_OF_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Restaurants	Turnover	T_RS_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Retail	Turnover	T_RT_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Schools K-12	Turnover	T_SC_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Warehouse	Turnover	T_WR_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Assembly	New	N_AS_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	College and University	New	N_CU_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Grocery	New	N_GR_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Healthcare	New	N_HC_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Hospitals	New	N_HS_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Institutional	New	N_IN_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Lodging/Hospitality	New	N_LG_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Miscellaneous	New	N_MS_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Offices	New	N_OF_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Restaurants	New	N_RS_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Retail	New	N_RT_Energ	1.32	0.48	2.73	0	0	0	Fail RIM

Commercial	Energy Star Commercial Solid Door Freezer	Retail	New	N_RT_Energ	8.18	0.58	14.08	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Solid Door Freezer	Schools K-12	New	N_SC_Energ	7.63	0.54	14.08	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Commercial Solid Door Freezer	Warehouse	New	N_WR_Energ	8.18	0.58	14.08	0	0	0	Fail 2-year Threshold
Commercial	Energy Star Ice Maker	Assembly	Turnover	T_AS_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	College and University	Turnover	T_CU_Energ	0.29	0.47	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Grocery	Turnover	T_GR_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Healthcare	Turnover	T_HC_Energ	0.29	0.47	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Hospitals	Turnover	T_HS_Energ	0.29	0.47	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Institutional	Turnover	T_IN_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Lodging/Hospitality	Turnover	T_LG_Energ	0.29	0.47	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Miscellaneous	Turnover	T_MS_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Offices	Turnover	T_OF_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Restaurants	Turnover	T_RS_Energ	0.29	0.47	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Retail	Turnover	T_RT_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Schools K-12	Turnover	T_SC_Energ	0.29	0.47	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Warehouse	Turnover	T_WR_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Assembly	New	N_AS_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	College and University	New	N_CU_Energ	0.29	0.47	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Grocery	New	N_GR_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Healthcare	New	N_HC_Energ	0.29	0.47	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Hospitals	New	N_HS_Energ	0.29	0.47	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Institutional	New	N_IN_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Lodging/Hospitality	New	N_LG_Energ	0.29	0.47	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Miscellaneous	New	N_MS_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Offices	New	N_OF_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Restaurants	New	N_RS_Energ	0.29	0.47	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Retail	New	N_RT_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Schools K-12	New	N_SC_Energ	0.29	0.47	0.62	0	0	0	Fail TRC
Commercial	Energy Star Ice Maker	Warehouse	New	N_WR_Energ	0.32	0.51	0.62	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Assembly	Turnover	T_AS_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	College and University	Turnover	T_CU_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Grocery	Turnover	T_GR_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Healthcare	Turnover	T_HC_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Hospitals	Turnover	T_HS_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Institutional	Turnover	T_IN_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Lodging/Hospitality	Turnover	T_LG_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Miscellaneous	Turnover	T_MS_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Offices	Turnover	T_OF_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Restaurants	Turnover	T_RS_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Retail	Turnover	T_RT_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Schools K-12	Turnover	T_SC_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Warehouse	Turnover	T_WR_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Assembly	New	N_AS_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	College and University	New	N_CU_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Grocery	New	N_GR_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Healthcare	New	N_HC_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Hospitals	New	N_HS_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Institutional	New	N_IN_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Lodging/Hospitality	New	N_LG_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Miscellaneous	New	N_MS_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Offices	New	N_OF_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Restaurants	New	N_RS_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Retail	New	N_RT_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Schools K-12	New	N_SC_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Refrigerator	Warehouse	New	N_WR_Energ	0.55	0.55	1.01	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Assembly	Turnover	T_AS_Energ	0.67	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	College and University	Turnover	T_CU_Energ	0.68	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Grocery	Turnover	T_GR_Energ	0.67	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Healthcare	Turnover	T_HC_Energ	0.68	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Hospitals	Turnover	T_HS_Energ	0.68	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Institutional	Turnover	T_IN_Energ	0.67	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Lodging/Hospitality	Turnover	T_LG_Energ	0.68	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Miscellaneous	Turnover	T_MS_Energ	0.67	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Offices	Turnover	T_OF_Energ	0.67	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Restaurants	Turnover	T_RS_Energ	0.68	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Retail	Turnover	T_RT_Energ	0.67	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Schools K-12	Turnover	T_SC_Energ	0.68	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Warehouse	Turnover	T_WR_Energ	0.67	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Assembly	New	N_AS_Energ	0.67	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	College and University	New	N_CU_Energ	0.68	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Grocery	New	N_GR_Energ	0.67	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Healthcare	New	N_HC_Energ	0.68	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Hospitals	New	N_HS_Energ	0.68	0.61	1.10	0	0	0	Fail TRC
Commercial	Energy Star Vending Machine	Institutional	New	N_IN_Energ	0

Commercial	Energy Star Uninterruptable Power Supply	Schools K-12	New	N_SC_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Energy Star Uninterruptable Power Supply	Warehouse	New	N_WR_Energ	1.32	0.48	2.73	0	0	0	Fail RIM
Commercial	Server Virtualization	Assembly	Turnover	T_AS_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	College and University	Turnover	T_CU_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Grocery	Turnover	T_GR_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Healthcare	Turnover	T_HC_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Hospitals	Turnover	T_HS_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Institutional	Turnover	T_IN_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Lodging/Hospitality	Turnover	T_LG_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Miscellaneous	Turnover	T_MS_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Offices	Turnover	T_OF_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Restaurants	Turnover	T_RS_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Retail	Turnover	T_RT_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Schools K-12	Turnover	T_SC_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Warehouse	Turnover	T_WR_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Assembly	New	N_AS_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	College and University	New	N_CU_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Grocery	New	N_GR_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Healthcare	New	N_HC_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Hospitals	New	N_HS_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Institutional	New	N_IN_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Lodging/Hospitality	New	N_LG_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Miscellaneous	New	N_MS_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Offices	New	N_OF_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Restaurants	New	N_RS_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Retail	New	N_RT_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Schools K-12	New	N_SC_Server	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Server Virtualization	Warehouse	New	N_WR_Serve	0.15	0.46	0.32	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Assembly	Turnover	T_AS_Energ	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	College and University	Turnover	T_CU_Energ	13.23	0.54	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Grocery	Turnover	T_GR_Energ	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Healthcare	Turnover	T_HC_Energ	13.23	0.54	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Hospitals	Turnover	T_HS_Energ	13.23	0.54	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Institutional	Turnover	T_IN_Energy	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Lodging/Hospitality	Turnover	T_LG_Energ	13.23	0.54	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Miscellaneous	Turnover	T_MS_Energ	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Offices	Turnover	T_OF_Energ	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Restaurants	Turnover	T_RS_Energ	13.23	0.54	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Retail	Turnover	T_RT_Energ	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Schools K-12	Turnover	T_SC_Energ	13.23	0.54	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Warehouse	Turnover	T_WR_Energ	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Assembly	New	N_AS_Energ	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	College and University	New	N_CU_Energ	13.23	0.54	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Grocery	New	N_GR_Energ	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Healthcare	New	N_HC_Energ	13.23	0.54	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Hospitals	New	N_HS_Energ	13.23	0.54	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Institutional	New	N_IN_Energy	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Lodging/Hospitality	New	N_LG_Energ	13.23	0.54	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Miscellaneous	New	N_MS_Energ	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Offices	New	N_OF_Energ	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Restaurants	New	N_RS_Energ	13.23	0.54	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Retail	New	N_RT_Energ	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Schools K-12	New	N_SC_Energ	13.23	0.54	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Freezer	Warehouse	New	N_WR_Energ	14.02	0.57	24.40	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Assembly	Turnover	T_AS_Energ	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	College and University	Turnover	T_CU_Energ	2.81	0.54	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Grocery	Turnover	T_GR_Energ	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Healthcare	Turnover	T_HC_Energ	2.81	0.54	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Hospitals	Turnover	T_HS_Energ	2.81	0.54	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Institutional	Turnover	T_IN_Energy	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Lodging/Hospitality	Turnover	T_LG_Energ	2.81	0.54	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Miscellaneous	Turnover	T_MS_Energ	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Offices	Turnover	T_OF_Energ	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Restaurants	Turnover	T_RS_Energ	2.81	0.54	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Retail	Turnover	T_RT_Energ	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Schools K-12	Turnover	T_SC_Energ	2.81	0.54	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Warehouse	Turnover	T_WR_Energ	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Assembly	New	N_AS_Energ	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	College and University	New	N_CU_Energ	2.81	0.54	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Grocery	New	N_GR_Energ	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Healthcare	New	N_HC_Energ	2.81	0.54	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Hospitals	New	N_HS_Energ	2.81	0.54	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Institutional	New	N_IN_Energy	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Lodging/Hospitality	New	N_LG_Energ	2.81	0.54	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Miscellaneous	New	N_MS_Energ	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Offices	New	N_OF_Energ	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Restaurants	New	N_RS_Energ	2.81	0.54	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Retail	New	N_RT_Energ	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Schools K-12	New	N_SC_Energ	2.81	0.54	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Glass Door Refrigerator	Warehouse	New	N_WR_Energ	2.98	0.57	5.19	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Assembly	Turnover	T_AS_Energ	8.18	0.58	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	College and University	Turnover	T_CU_Energ	7.63	0.54	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Grocery	Turnover	T_GR_Energ	8.18	0.58	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Healthcare	Turnover	T_HC_Energ	7.63	0.54	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Hospitals	Turnover	T_HS_Energ	7.63	0.54	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Institutional	Turnover	T_IN_Energy	8.18	0.58	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Lodging/Hospitality	Turnover	T_LG_Energ	7.63	0.54	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Miscellaneous	Turnover	T_MS_Energ	8.18	0.58	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Offices	Turnover	T_OF_Energ	8.18	0.58	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Restaurants	Turnover	T_RS_Energ	7.63	0.54	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Retail	Turnover	T_RT_Energ	8.18	0.58	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Schools K-12	Turnover	T_SC_Energ	7.63	0.54	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Warehouse	Turnover	T_WR_Energ	8.18	0.58	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Assembly	New	N_AS_Energ	8.18	0.58	14.08	0	0	0	Fail RIM

Commercial	High Speed Fans	Hospitals	Turnover	T_HS_High S	0.87	0.44	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Institutional	Turnover	T_IN_High S	0.89	0.46	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Lodging/Hospitality	Turnover	T_LG_High S	0.87	0.44	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Miscellaneous	Turnover	T_MS_High S	0.89	0.46	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Offices	Turnover	T_OF_High S	0.89	0.46	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Restaurants	Turnover	T_RS_High S	0.87	0.44	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Retail	Turnover	T_RT_High S	0.89	0.46	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Schools K-12	Turnover	T_SC_High S	0.87	0.44	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Warehouse	Turnover	T_WR_High	0.89	0.46	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Assembly	New	N_AS_High S	0.89	0.46	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	College and University	New	N_CU_High	0.87	0.44	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Grocery	New	N_GR_High S	0.89	0.46	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Healthcare	New	N_HC_High S	0.87	0.44	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Hospitals	New	N_HS_High S	0.87	0.44	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Institutional	New	N_IN_High S	0.89	0.46	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Lodging/Hospitality	New	N_LG_High S	0.87	0.44	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Miscellaneous	New	N_MS_High	0.89	0.46	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Offices	New	N_OF_High S	0.89	0.46	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Restaurants	New	N_RS_High S	0.87	0.44	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Retail	New	N_RT_High S	0.89	0.46	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Schools K-12	New	N_SC_High S	0.87	0.44	1.95	0	0	0	Fail TRC
Commercial	High Speed Fans	Warehouse	New	N_WR_High	0.89	0.46	1.95	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Assembly	Existing	E_AS_Drain	0.11	0.80	0.13	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	College and University	Existing	E_CU_Drain	0.23	0.73	0.33	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Grocery	Existing	E_GR_Drain	0.30	1.10	0.27	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Healthcare	Existing	E_HC_Drain	0.14	0.80	0.18	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Hospitals	Existing	E_HS_Drain	0.26	0.73	0.36	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Institutional	Existing	E_IN_Drain	0.34	0.80	0.43	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Lodging/Hospitality	Existing	E_LG_Drain	0.47	1.10	0.43	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Miscellaneous	Existing	E_MS_Drain	0.32	0.80	0.40	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Offices	Existing	E_OF_Drain	0.30	0.80	0.37	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Restaurants	Existing	E_RS_Drain	0.25	1.10	0.22	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Retail	Existing	E_RT_Drain	0.29	1.10	0.27	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Schools K-12	Existing	E_SC_Drain	0.04	0.80	0.06	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Warehouse	Existing	E_WR_Drain	0.21	0.80	0.27	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Assembly	New	N_AS_Drain	0.10	0.80	0.13	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	College and University	New	N_CU_Drain	0.22	0.73	0.30	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Grocery	New	N_GR_Drain	0.28	1.10	0.26	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Healthcare	New	N_HC_Drain	0.14	0.80	0.17	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Hospitals	New	N_HS_Drain	0.25	0.73	0.35	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Institutional	New	N_IN_Drain	0.33	0.80	0.41	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Lodging/Hospitality	New	N_LG_Drain	0.45	1.10	0.41	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Miscellaneous	New	N_MS_Drain	0.31	0.80	0.39	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Offices	New	N_OF_Drain	0.29	0.80	0.36	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Restaurants	New	N_RS_Drain	0.24	1.10	0.21	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Retail	New	N_RT_Drain	0.28	1.10	0.25	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Schools K-12	New	N_SC_Drain	0.04	0.80	0.05	0	0	0	Fail TRC
Commercial	Drain Water Heat Recovery	Warehouse	New	N_WR_Drain	0.21	0.80	0.26	0	0	0	Fail TRC
Commercial	Faucet Aerator	Assembly	Existing	E_AS_Faucet	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	College and University	Existing	E_CU_Faucet	6.69	0.68	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Grocery	Existing	E_GR_Faucet	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Healthcare	Existing	E_HC_Faucet	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Hospitals	Existing	E_HS_Faucet	6.69	0.68	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Institutional	Existing	E_IN_Faucet	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Lodging/Hospitality	Existing	E_LG_Faucet	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Miscellaneous	Existing	E_MS_Faucet	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Offices	Existing	E_OF_Faucet	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Restaurants	Existing	E_RS_Faucet	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Retail	Existing	E_RT_Faucet	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Schools K-12	Existing	E_SC_Faucet	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Warehouse	Existing	E_WR_Fauce	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Assembly	New	N_AS_Faucet	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	College and University	New	N_CU_Faucet	6.69	0.68	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Grocery	New	N_GR_Faucet	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Healthcare	New	N_HC_Faucet	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Hospitals	New	N_HS_Faucet	6.69	0.68	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Institutional	New	N_IN_Faucet	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Lodging/Hospitality	New	N_LG_Faucet	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Miscellaneous	New	N_MS_Faucet	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Offices	New	N_OF_Faucet	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Restaurants	New	N_RS_Faucet	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Retail	New	N_RT_Faucet	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Schools K-12	New	N_SC_Faucet	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Warehouse	New	N_WR_Fauce	6.44	0.65	9.85	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Circulation Pump Control	Assembly	Existing	E_AS_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	College and University	Existing	E_CU_Hot W	0.87	0.55	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Grocery	Existing	E_GR_Hot W	0.46	0.29	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Healthcare	Existing	E_HC_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Hospitals	Existing	E_HS_Hot W	0.87	0.55	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Institutional	Existing	E_IN_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Lodging/Hospitality	Existing	E_LG_Hot W	0.46	0.29	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Miscellaneous	Existing	E_MS_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Offices	Existing	E_OF_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Restaurants	Existing	E_RS_Hot W	0.46	0.29	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Retail	Existing	E_RT_Hot W	0.46	0.29	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Schools K-12	Existing	E_SC_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Warehouse	Existing	E_WR_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Assembly	New	N_AS_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	College and University	New	N_CU_Hot W	0.87	0.55	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Grocery	New	N_GR_Hot W	0.46	0.29	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Healthcare	New	N_HC_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Hospitals	New	N_HS_Hot W	0.87	0.55	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Institutional	New	N_IN_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Lodging/Hospitality	New	N_LG_Hot W	0.46	0.29	1.57	0	0	0	Fail TRC

Commercial	Energy Star Commercial Solid Door Freezer	College and University	New	N_CU_Energ	7.63	0.54	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Grocery	New	N_GR_Energ	8.18	0.58	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Healthcare	New	N_HC_Energ	7.63	0.54	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Hospitals	New	N_HS_Energ	7.63	0.54	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Institutional	New	N_IN_Energ	8.18	0.58	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Lodging/Hospitality	New	N_LG_Energ	7.63	0.54	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Miscellaneous	New	N_MS_Energ	8.18	0.58	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Offices	New	N_OF_Energ	8.18	0.58	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Restaurants	New	N_RS_Energ	7.63	0.54	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Retail	New	N_RT_Energ	8.18	0.58	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Schools K-12	New	N_SC_Energ	7.63	0.54	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Freezer	Warehouse	New	N_WR_Energ	8.18	0.58	14.08	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Assembly	Turnover	T_AS_Energ	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	College and University	Turnover	T_CU_Energ	2.59	0.54	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Grocery	Turnover	T_GR_Energ	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Healthcare	Turnover	T_HC_Energ	2.59	0.54	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Hospitals	Turnover	T_HS_Energ	2.59	0.54	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Institutional	Turnover	T_IN_Energy	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Lodging/Hospitality	Turnover	T_LG_Energ	2.59	0.54	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Miscellaneous	Turnover	T_MS_Energ	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Offices	Turnover	T_OF_Energ	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Restaurants	Turnover	T_RS_Energ	2.59	0.54	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Retail	Turnover	T_RT_Energ	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Schools K-12	Turnover	T_SC_Energ	2.59	0.54	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Warehouse	Turnover	T_WR_Energ	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Assembly	New	N_AS_Energ	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	College and University	New	N_CU_Energ	2.59	0.54	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Grocery	New	N_GR_Energ	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Healthcare	New	N_HC_Energ	2.59	0.54	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Hospitals	New	N_HS_Energ	2.59	0.54	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Institutional	New	N_IN_Energ	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Lodging/Hospitality	New	N_LG_Energ	2.59	0.54	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Miscellaneous	New	N_MS_Energ	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Offices	New	N_OF_Energ	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Restaurants	New	N_RS_Energ	2.59	0.54	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Retail	New	N_RT_Energ	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Schools K-12	New	N_SC_Energ	2.59	0.54	4.78	0	0	0	Fail RIM
Commercial	Energy Star Commercial Solid Door Refrigerator	Warehouse	New	N_WR_Energ	2.78	0.58	4.78	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Assembly	Turnover	T_AS_Energ	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	College and University	Turnover	T_CU_Energ	0.29	0.47	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Grocery	Turnover	T_GR_Energ	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Healthcare	Turnover	T_HC_Energ	0.29	0.47	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Hospitals	Turnover	T_HS_Energ	0.29	0.47	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Institutional	Turnover	T_IN_Energy	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Lodging/Hospitality	Turnover	T_LG_Energ	0.29	0.47	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Miscellaneous	Turnover	T_MS_Energ	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Offices	Turnover	T_OF_Energ	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Restaurants	Turnover	T_RS_Energ	0.29	0.47	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Retail	Turnover	T_RT_Energ	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Schools K-12	Turnover	T_SC_Energ	0.29	0.47	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Warehouse	Turnover	T_WR_Energ	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Assembly	New	N_AS_Energ	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	College and University	New	N_CU_Energ	0.29	0.47	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Grocery	New	N_GR_Energ	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Healthcare	New	N_HC_Energ	0.29	0.47	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Hospitals	New	N_HS_Energ	0.29	0.47	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Institutional	New	N_IN_Energ	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Lodging/Hospitality	New	N_LG_Energ	0.29	0.47	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Miscellaneous	New	N_MS_Energ	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Offices	New	N_OF_Energ	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Restaurants	New	N_RS_Energ	0.29	0.47	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Retail	New	N_RT_Energ	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Schools K-12	New	N_SC_Energ	0.29	0.47	0.62	0	0	0	Fail RIM
Commercial	Energy Star Ice Maker	Warehouse	New	N_WR_Energ	0.32	0.51	0.62	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Assembly	Turnover	T_AS_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	College and University	Turnover	T_CU_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Grocery	Turnover	T_GR_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Healthcare	Turnover	T_HC_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Hospitals	Turnover	T_HS_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Institutional	Turnover	T_IN_Energy	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Lodging/Hospitality	Turnover	T_LG_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Miscellaneous	Turnover	T_MS_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Offices	Turnover	T_OF_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Restaurants	Turnover	T_RS_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Retail	Turnover	T_RT_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Schools K-12	Turnover	T_SC_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Warehouse	Turnover	T_WR_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Assembly	New	N_AS_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	College and University	New	N_CU_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Grocery	New	N_GR_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Healthcare	New	N_HC_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Hospitals	New	N_HS_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Institutional	New	N_IN_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Lodging/Hospitality	New	N_LG_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Miscellaneous	New	N_MS_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Offices	New	N_OF_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Restaurants	New	N_RS_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Retail	New	N_RT_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Schools K-12	New	N_SC_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Refrigerator	Warehouse	New	N_WR_Energ	0.55	0.55	1.01	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Assembly	Turnover	T_AS_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	College and University	Turnover	T_CU_Energy	0.68	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Grocery	Turnover	T_GR_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Healthcare	Turnover	T_HC_Energy	0.68	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Hospitals	Turnover	T_HS_Energy	0.68	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Institutional	Turnover	T_IN_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Lodging/Hospitality	Turnover	T_LG_Energy	0.68	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Miscellaneous	Turnover	T_MS_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Offices	Turnover	T_OF_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Restaurants	Turnover	T_RS_Energy	0.68	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Retail	Turnover	T_RT_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Schools K-12	Turnover	T_SC_Energy	0.68	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Warehouse	Turnover	T_WR_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Assembly	New	N_AS_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	College and University	New	N_CU_Energy	0.68	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Grocery	New	N_GR_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Healthcare	New	N_HC_Energy	0.68	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Hospitals	New	N_HS_Energy	0.68	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Institutional	New	N_IN_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Lodging/Hospitality	New	N_LG_Energy	0.68	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Miscellaneous	New	N_MS_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Offices	New	N_OF_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Restaurants	New	N_RS_Energy	0.68	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Retail	New	N_RT_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Schools K-12	New	N_SC_Energy	0.68	0.61	1.10	0	0	0	Fail RIM
Commercial	Energy Star Vending Machine	Warehouse	New	N_WR_Energy	0.67	0.61	1.10	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Assembly	Turnover	T_AS_Refrig	0.95	0.50	1.90	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	College and University	Turnover	T_CU_Refrig	0.89	0.47	1.90	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Grocery	Turnover	T_GR_Refrig	0.95	0.50	1.90	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Healthcare	Turnover	T_HC_Refrig	0.89	0.47	1.90	0	0	0	Fail RIM

Commercial	Hot Water Circulation Pump Control	Miscellaneous	New	N_MS_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Offices	New	N_OF_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Restaurants	New	N_RS_Hot W	0.46	0.29	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Retail	New	N_RT_Hot W	0.46	0.29	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Schools K-12	New	N_SC_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Circulation Pump Control	Warehouse	New	N_WR_Hot W	0.61	0.39	1.57	0	0	0	Fail TRC
Commercial	Hot Water Pipe Insulation	Assembly	Existing	E_AS_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	College and University	Existing	E_CU_Hot W	3.85	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Grocery	Existing	E_GR_Hot W	4.02	0.54	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Healthcare	Existing	E_HC_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Hospitals	Existing	E_HS_Hot W	3.85	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Institutional	Existing	E_IN_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Lodging/Hospitality	Existing	E_LG_Hot W	4.02	0.54	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Miscellaneous	Existing	E_MS_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Offices	Existing	E_OF_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Restaurants	Existing	E_RS_Hot W	4.02	0.54	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Retail	Existing	E_RT_Hot W	4.02	0.54	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Schools K-12	Existing	E_SC_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Warehouse	Existing	E_WR_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Assembly	New	N_AS_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	College and University	New	N_CU_Hot W	3.85	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Grocery	New	N_GR_Hot W	4.02	0.54	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Healthcare	New	N_HC_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Hospitals	New	N_HS_Hot W	3.85	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Institutional	New	N_IN_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Lodging/Hospitality	New	N_LG_Hot W	4.02	0.54	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Miscellaneous	New	N_MS_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Offices	New	N_OF_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Restaurants	New	N_RS_Hot W	4.02	0.54	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Retail	New	N_RT_Hot W	4.02	0.54	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Schools K-12	New	N_SC_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Hot Water Pipe Insulation	Warehouse	New	N_WR_Hot W	3.88	0.52	7.43	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Assembly	Existing	E_AS_Low F	6.65	0.58	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	College and University	Existing	E_CU_Low F	10.18	0.89	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Grocery	Existing	E_GR_Low F	10.18	0.89	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Healthcare	Existing	E_HC_Low F	7.76	0.68	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Hospitals	Existing	E_HS_Low F	7.76	0.68	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Institutional	Existing	E_IN_Low F	6.65	0.58	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Lodging/Hospitality	Existing	E_LG_Low F	11.76	1.03	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Miscellaneous	Existing	E_MS_Low F	6.65	0.58	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Offices	Existing	E_OF_Low F	6.65	0.58	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Restaurants	Existing	E_RS_Low F	10.18	0.89	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Retail	Existing	E_RT_Low F	10.18	0.89	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Schools K-12	Existing	E_SC_Low F	6.65	0.58	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Warehouse	Existing	E_WR_Low	6.65	0.58	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Assembly	New	N_AS_Low F	6.65	0.58	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	College and University	New	N_CU_Low F	10.18	0.89	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Grocery	New	N_GR_Low F	10.18	0.89	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Healthcare	New	N_HC_Low F	7.76	0.68	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Hospitals	New	N_HS_Low F	7.76	0.68	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Institutional	New	N_IN_Low F	6.65	0.58	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Lodging/Hospitality	New	N_LG_Low F	11.76	1.03	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Miscellaneous	New	N_MS_Low F	6.65	0.58	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Offices	New	N_OF_Low F	6.65	0.58	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Restaurants	New	N_RS_Low F	10.18	0.89	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Retail	New	N_RT_Low F	10.18	0.89	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Schools K-12	New	N_SC_Low F	6.65	0.58	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Warehouse	New	N_WR_Low	6.65	0.58	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Assembly	Existing	E_AS_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	College and University	Existing	E_CU_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Grocery	Existing	E_GR_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Healthcare	Existing	E_HC_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Hospitals	Existing	E_HS_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Institutional	Existing	E_IN_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Lodging/Hospitality	Existing	E_LG_Low-F	4.34	0.84	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Miscellaneous	Existing	E_MS_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Offices	Existing	E_OF_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Restaurants	Existing	E_RS_Low-F	2.45	0.48	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Retail	Existing	E_RT_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Schools K-12	Existing	E_SC_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Warehouse	Existing	E_WR_Low	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Assembly	New	N_AS_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	College and University	New	N_CU_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Grocery	New	N_GR_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Healthcare	New	N_HC_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Hospitals	New	N_HS_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Institutional	New	N_IN_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Lodging/Hospitality	New	N_LG_Low-F	4.34	0.84	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Miscellaneous	New	N_MS_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse Sprayers	Offices	New	N_OF_Low-F	2.93	0.57	5.15	0	0	0	Fail 2-year Threshold
Commercial	Low-Flow Pre-Rinse

Commercial	Refrigerated Display Case LED Lighting	Hospitals	Turnover	T_HS_Refrig	0.89	0.47	1.90	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Institutional	Turnover	T_IN_Refrig	0.95	0.50	1.90	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Lodging/Hospitality	Turnover	T_LG_Refrig	0.89	0.47	1.90	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Miscellaneous	Turnover	T_MS_Refrig	0.95	0.50	1.90	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Offices	Turnover	T_OF_Refrig	0.95	0.50	1.90	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Restaurants	Turnover	T_RS_Refrig	0.89	0.47	1.90	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Retail	Turnover	T_RT_Refrig	0.95	0.50	1.90	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Schools K-12	Turnover	T_SC_Refrig	0.89	0.47	1.90	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Warehouse	Turnover	T_WR_Refrig	0.95	0.50	1.90	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Assembly	New	N_AS_Refrig	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	College and University	New	N_CU_Refrig	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Grocery	New	N_GR_Refrig	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Healthcare	New	N_HC_Refrig	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Hospitals	New	N_HS_Refrig	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Institutional	New	N_IN_Refrig	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Lodging/Hospitality	New	N_LG_Refrig	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Miscellaneous	New	N_MS_Refrig	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Offices	New	N_OF_Refrig	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Restaurants	New	N_RS_Refrig	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Retail	New	N_RT_Refrig	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Schools K-12	New	N_SC_Refrig	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Refrigerated Display Case LED Lighting	Warehouse	New	N_WR_Refrig	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Assembly	Turnover	T_AS_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	College and University	Turnover	T_CU_10HP	0.19	0.56	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Grocery	Turnover	T_GR_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Healthcare	Turnover	T_HC_10HP	0.19	0.56	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Hospitals	Turnover	T_HS_10HP	0.19	0.56	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Institutional	Turnover	T_IN_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Lodging/Hospitality	Turnover	T_LG_10HP	0.19	0.56	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Miscellaneous	Turnover	T_MS_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Offices	Turnover	T_OF_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Restaurants	Turnover	T_RS_10HP	0.19	0.56	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Retail	Turnover	T_RT_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Schools K-12	Turnover	T_SC_10HP	0.19	0.56	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Warehouse	Turnover	T_WR_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Assembly	New	N_AS_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	College and University	New	N_CU_10HP	0.19	0.56	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Grocery	New	N_GR_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Healthcare	New	N_HC_10HP	0.19	0.56	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Hospitals	New	N_HS_10HP	0.19	0.56	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Institutional	New	N_IN_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Lodging/Hospitality	New	N_LG_10HP	0.19	0.56	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Miscellaneous	New	N_MS_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Offices	New	N_OF_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Restaurants	New	N_RS_10HP	0.19	0.56	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Retail	New	N_RT_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Schools K-12	New	N_SC_10HP	0.19	0.56	0.33	0	0	0	Fail RIM
Commercial	10HP Open Drip-Proof(ODP) Motor	Warehouse	New	N_WR_10HP	0.19	0.58	0.33	0	0	0	Fail RIM
Commercial	High Speed Fans	Assembly	Turnover	T_AS_High S	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	College and University	Turnover	T_CU_High S	0.87	0.44	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Grocery	Turnover	T_GR_High S	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Healthcare	Turnover	T_HC_High S	0.87	0.44	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Hospitals	Turnover	T_HS_High S	0.87	0.44	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Institutional	Turnover	T_IN_High Sp	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Lodging/Hospitality	Turnover	T_LG_High S	0.87	0.44	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Miscellaneous	Turnover	T_MS_High S	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Offices	Turnover	T_OF_High S	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Restaurants	Turnover	T_RS_High S	0.87	0.44	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Retail	Turnover	T_RT_High S	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Schools K-12	Turnover	T_SC_High S	0.87	0.44	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Warehouse	Turnover	T_WR_High S	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Assembly	New	N_AS_High S	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	College and University	New	N_CU_High S	0.87	0.44	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Grocery	New	N_GR_High S	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Healthcare	New	N_HC_High S	0.87	0.44	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Hospitals	New	N_HS_High S	0.87	0.44	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Institutional	New	N_IN_High Sp	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Lodging/Hospitality	New	N_LG_High S	0.87	0.44	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Miscellaneous	New	N_MS_High S	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Offices	New	N_OF_High S	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Restaurants	New	N_RS_High S	0.87	0.44	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Retail	New	N_RT_High S	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Schools K-12	New	N_SC_High S	0.87	0.44	1.95	0	0	0	Fail RIM
Commercial	High Speed Fans	Warehouse	New	N_WR_High	0.89	0.46	1.95	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Assembly	Existing	E_AS_Drain	0.11	0.80	0.13	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	College and University	Existing	E_CU_Drain	0.23	0.73	0.31	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Grocery	Existing	E_GR_Drain	0.30	1.10	0.27	0	0	0	Fail PCT
Commercial	Drain Water Heat Recovery	Healthcare	Existing	E_HC_Drain	0.14	0.80	0.18	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Hospitals	Existing	E_HS_Drain	0.26	0.73	0.36	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Institutional	Existing	E_IN_Drain	0.34	0.80	0.43	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Lodging/Hospitality	Existing	E_LG_Drain	0.47	1.10	0.43	0	0	0	Fail PCT
Commercial	Drain Water Heat Recovery	Miscellaneous	Existing	E_MS_Drain	0.32	0.80	0.40	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Offices	Existing	E_OF_Drain	0.30	0.80	0.37	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Restaurants	Existing	E_RS_Drain	0.25	1.10	0.22	0	0	0	Fail PCT
Commercial	Drain Water Heat Recovery	Retail	Existing	E_RT_Drain	0.29	1.10	0.27	0	0	0	Fail PCT
Commercial	Drain Water Heat Recovery	Schools K-12	Existing	E_SC_Drain	0.04	0.80	0.06	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Warehouse	Existing	E_WR_Drain	0.21	0.80	0.27	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Assembly	New	N_AS_Drain	0.10	0.80	0.13	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	College and University	New	N_CU_Drain	0.22	0.73	0.30	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Grocery	New	N_GR_Drain	0.28	1.10	0.26	0	0	0	Fail PCT
Commercial	Drain Water Heat Recovery	Healthcare	New	N_HC_Drain	0.14	0.80	0.17	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Hospitals	New	N_HS_Drain	0.25	0.73	0.35	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Institutional	New	N_IN_Drain	0.33	0.80	0.41	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Lodging/Hospitality	New	N_LG_Drain	0.45	1.10	0.41	0	0	0	Fail PCT
Commercial	Drain Water Heat Recovery	Miscellaneous	New	N_MS_Drain	0.31	0.80	0.39	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Offices	New	N_OF_Drain	0.29	0.80	0.36	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Restaurants	New	N_RS_Drain	0.24	1.10	0.21	0	0	0	Fail PCT
Commercial	Drain Water Heat Recovery	Retail	New	N_RT_Drain	0.28	1.10	0.25	0	0	0	Fail PCT
Commercial	Drain Water Heat Recovery	Schools K-12	New	N_SC_Drain	0.04	0.80	0.05	0	0	0	Fail RIM
Commercial	Drain Water Heat Recovery	Warehouse	New	N_WR_Drain	0.21	0.80	0.26	0	0	0	Fail RIM
Commercial	Faucet Aerator	Assembly	Existing	E_AS_Faucet	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	College and University	Existing	E_CU_Fauce	6.69	0.68	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Grocery	Existing	E_GR_Fauce	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Healthcare	Existing	E_HC_Fauce	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Hospitals	Existing	E_HS_Fauce	6.69	0.68	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Institutional	Existing	E_IN_Fauce	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Lodging/Hospitality	Existing	E_LG_Fauce	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Miscellaneous	Existing	E_MS_Fauce	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Offices	Existing	E_OF_Fauce	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Restaurants	Existing	E_RS_Fauce	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Retail	Existing	E_RT_Fauce	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Schools K-12	Existing	E_SC_Fauce	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Warehouse	Existing	E_WR_Fauce	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Assembly	New	N_AS_Fauce	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	College and University	New	N_CU_Fauce	6.69	0.68	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Grocery	New	N_GR_Fauce	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Healthcare	New	N_HC_Fauce	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Hospitals	New	N_HS_Fauce	6.69	0.68	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Institutional	New	N_IN_Fauce	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Lodging/Hospitality	New	N_LG_Fauce	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Miscellaneous	New	N_MS_Fauce	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Offices	New	N_OF_Fauce	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Restaurants	New	N_RS_Fauce	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Retail	New	N_RT_Fauce	10.17	1.03	9.85	0	0	0	Fail 2-year Threshold
Commercial	Faucet Aerator	Schools K-12	New	N_SC_Fauce	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Faucet Aerator	Warehouse	New	N_WR_Fauce	6.44	0.65	9.85	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Assembly	Existing	E_AS_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	College and University	Existing	E_CU_Hot W	0.87	0.55	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Grocery	Existing	E_GR_Hot W	0.46	0.29	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Healthcare	Existing	E_HC_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Hospitals	Existing	E_HS_Hot W	0.87	0.55	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Institutional	Existing	E_IN_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Lodging/Hospitality	Existing	E_LG_Hot W	0.46	0.29	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Miscellaneous	Existing	E_MS_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Offices	Existing	E_OF_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Restaurants	Existing	E_RS_Hot W	0.46	0.29	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Retail	Existing	E_RT_Hot W	0.46	0.29	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Schools K-12	Existing	E_SC_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Warehouse	Existing	E_WR_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM

Commercial	Thermostatic Shower Restriction Valve	Retail	Existing	E_RT_Therm	20.12	0.89	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Schools K-12	Existing	E_SC_Therm	13.15	0.58	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Warehouse	Existing	E_WR_Therm	13.15	0.58	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Assembly	New	N_AS_Therm	13.15	0.58	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	College and University	New	N_CU_Therm	20.12	0.89	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Grocery	New	N_GR_Therm	20.12	0.89	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Healthcare	New	N_HC_Therm	15.34	0.68	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Hospitals	New	N_HS_Therm	15.34	0.68	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Institutional	New	N_IN_Therm	13.15	0.58	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Lodging/Hospitality	New	N_LG_Therm	23.26	1.03	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Miscellaneous	New	N_MS_Therm	13.15	0.58	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Offices	New	N_OF_Therm	13.15	0.58	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Restaurants	New	N_RS_Therm	20.12	0.89	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Retail	New	N_RT_Therm	20.12	0.89	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Schools K-12	New	N_SC_Therm	13.15	0.58	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Warehouse	New	N_WR_Therm	13.15	0.58	22.58	0	0	0	Fail 2-year Threshold
Commercial	Bi-Level Lighting Control (Exterior)	Assembly	Existing	E_AS_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	College and University	Existing	E_CU_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Grocery	Existing	E_GR_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Healthcare	Existing	E_HC_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Hospitals	Existing	E_HS_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Institutional	Existing	E_IN_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Lodging/Hospitality	Existing	E_LG_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Miscellaneous	Existing	E_MS_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Offices	Existing	E_OF_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Restaurants	Existing	E_RS_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Retail	Existing	E_RT_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Schools K-12	Existing	E_SC_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Warehouse	Existing	E_WR_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Assembly	New	N_AS_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	College and University	New	N_CU_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Grocery	New	N_GR_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Healthcare	New	N_HC_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Hospitals	New	N_HS_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Institutional	New	N_IN_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Lodging/Hospitality	New	N_LG_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Miscellaneous	New	N_MS_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Offices	New	N_OF_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Restaurants	New	N_RS_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Retail	New	N_RT_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Schools K-12	New	N_SC_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Exterior)	Warehouse	New	N_WR_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Assembly	Existing	E_AS_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	College and University	Existing	E_CU_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Grocery	Existing	E_GR_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Healthcare	Existing	E_HC_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Hospitals	Existing	E_HS_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Institutional	Existing	E_IN_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Lodging/Hospitality	Existing	E_LG_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Miscellaneous	Existing	E_MS_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Offices	Existing	E_OF_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Restaurants	Existing	E_RS_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Retail	Existing	E_RT_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Schools K-12	Existing	E_SC_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Warehouse	Existing	E_WR_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Assembly	New	N_AS_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	College and University	New	N_CU_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Grocery	New	N_GR_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Healthcare	New	N_HC_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Hospitals	New	N_HS_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Institutional	New	N_IN_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Lodging/Hospitality	New	N_LG_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Miscellaneous	New	N_MS_Outdo	0.76	0.27	2.80	0	0	0	Fail TRC
Commercial	Outdoor Lighting Controls	Offices	New	N_OF_Outdo

Commercial	Hot Water Circulation Pump Control	Assembly	New	N_AS_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	College and University	New	N_CU_Hot W	0.87	0.55	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Grocery	New	N_GR_Hot W	0.46	0.29	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Healthcare	New	N_HC_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Hospitals	New	N_HS_Hot W	0.87	0.55	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Institutional	New	N_IN_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Lodging/Hospitality	New	N_LG_Hot W	0.46	0.29	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Miscellaneous	New	N_MS_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Offices	New	N_OF_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Restaurants	New	N_RS_Hot W	0.46	0.29	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Retail	New	N_RT_Hot W	0.46	0.29	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Schools K-12	New	N_SC_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM
Commercial	Hot Water Circulation Pump Control	Warehouse	New	N_WR_Hot W	0.61	0.39	1.57	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Assembly	Existing	E_AS_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	College and University	Existing	E_CU_Hot W	3.85	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Grocery	Existing	E_GR_Hot W	4.02	0.54	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Healthcare	Existing	E_HC_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Hospitals	Existing	E_HS_Hot W	3.85	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Institutional	Existing	E_IN_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Lodging/Hospitality	Existing	E_LG_Hot W	4.02	0.54	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Miscellaneous	Existing	E_MS_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Offices	Existing	E_OF_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Restaurants	Existing	E_RS_Hot W	4.02	0.54	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Retail	Existing	E_RT_Hot W	4.02	0.54	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Schools K-12	Existing	E_SC_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Warehouse	Existing	E_WR_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Assembly	New	N_AS_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	College and University	New	N_CU_Hot W	3.85	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Grocery	New	N_GR_Hot W	4.02	0.54	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Healthcare	New	N_HC_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Hospitals	New	N_HS_Hot W	3.85	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Institutional	New	N_IN_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Lodging/Hospitality	New	N_LG_Hot W	4.02	0.54	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Miscellaneous	New	N_MS_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Offices	New	N_OF_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Restaurants	New	N_RS_Hot W	4.02	0.54	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Retail	New	N_RT_Hot W	4.02	0.54	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Schools K-12	New	N_SC_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Hot Water Pipe Insulation	Warehouse	New	N_WR_Hot W	3.88	0.52	7.43	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Assembly	Existing	E_AS_Low F	6.65	0.58	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	College and University	Existing	E_CU_Low F	10.18	0.89	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Grocery	Existing	E_GR_Low F	10.18	0.89	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Healthcare	Existing	E_HC_Low F	7.76	0.68	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Hospitals	Existing	E_HS_Low F	7.76	0.68	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Institutional	Existing	E_IN_Low F	6.65	0.58	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Lodging/Hospitality	Existing	E_LG_Low F	11.76	1.03	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Miscellaneous	Existing	E_MS_Low F	6.65	0.58	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Offices	Existing	E_OF_Low F	6.65	0.58	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Restaurants	Existing	E_RS_Low F	10.18	0.89	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Retail	Existing	E_RT_Low F	10.18	0.89	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Schools K-12	Existing	E_SC_Low F	6.65	0.58	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Warehouse	Existing	E_WR_Low	6.65	0.58	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Assembly	New	N_AS_Low F	6.65	0.58	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	College and University	New	N_CU_Low F	10.18	0.89	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Grocery	New	N_GR_Low F	10.18	0.89	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Healthcare	New	N_HC_Low F	7.76	0.68	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Hospitals	New	N_HS_Low F	7.76	0.68	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Institutional	New	N_IN_Low F	6.65	0.58	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Lodging/Hospitality	New	N_LG_Low F	11.76	1.03	11.42	0	0	0	Fail 2-year Threshold
Commercial	Low Flow Shower Head	Miscellaneous	New	N_MS_Low F	6.65	0.58	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Offices	New	N_OF_Low F	6.65	0.58	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Restaurants	New	N_RS_Low F	10.18	0.89	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Retail	New	N_RT_Low F	10.18	0.89	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Schools K-12	New	N_SC_Low F	6.65	0.58	11.42	0	0	0	Fail RIM
Commercial	Low Flow Shower Head	Warehouse	New	N_WR_Low	6.65	0.58	11.42	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Assembly	Existing	E_AS_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	College and University	Existing	E_CU_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Grocery	Existing	E_GR_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Healthcare	Existing	E_HC_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Hospitals	Existing	E_HS_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Institutional	Existing	E_IN_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Lodging/Hospitality	Existing	E_LG_Low-F	4.34	0.84	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Miscellaneous	Existing	E_MS_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Offices	Existing	E_OF_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Restaurants	Existing	E_RS_Low-F	2.45	0.48	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Retail	Existing	E_RT_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Schools K-12	Existing	E_SC_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Warehouse	Existing	E_WR_Low-	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Assembly	New	N_AS_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	College and University	New	N_CU_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Grocery	New	N_GR_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Healthcare	New	N_HC_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Hospitals	New	N_HS_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Institutional	New	N_IN_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Lodging/Hospitality	New	N_LG_Low-F	4.34	0.84	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Miscellaneous	New	N_MS_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Offices	New	N_OF_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Restaurants	New	N_RS_Low-F	2.45	0.48	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Retail	New	N_RT_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Schools K-12	New	N_SC_Low-F	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Low-Flow Pre-Rinse Sprayers	Warehouse	New	N_WR_Low-	2.93	0.57	5.15	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Assembly	Existing	E_AS_Tank V	0.36	0.40	0.90	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	College and University	Existing	E_CU_Tank V	0.36	0.40	0.90	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Grocery	Existing	E_GR_Tank V	0.36	0.40	0.90	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Healthcare	Existing	E_HC_Tank V	0.36	0.40	0.90	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Hospitals	Existing	E_HS_Tank V	0.36	0.40	0.90	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Institutional	Existing	E_IN_Tank V	0.36	0.40	0.90	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Lodging/Hospitality	Existing	E_LG_Tank V	0.36	0.40	0.90	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Miscellaneous	Existing	E_MS_Tank V	0.36	0.40	0.90	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Offices	Existing	E_OF_Tank V	0.36	0.40	0.90	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Restaurants	Existing	E_RS_Tank V	0.36	0.40	0.90	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Retail	Existing	E_RT_Tank V	0.36	0.40	0.90	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Schools K-12	Existing	E_SC_Tank V	0.36	0.40	0.90	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Warehouse	Existing	E_WR_Tank	0.36	0.40	0.90	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Assembly	New	N_AS_Tank	0.34	0.40	0.86	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	College and University	New	N_CU_Tank	0.34	0.40	0.86	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Grocery	New	N_GR_Tank	0.34	0.40	0.86	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Healthcare	New	N_HC_Tank	0.34	0.40	0.86	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Hospitals	New	N_HS_Tank	0.34	0.40	0.86	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Institutional	New	N_IN_Tank	0.34	0.40	0.86	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Lodging/Hospitality	New	N_LG_Tank	0.34	0.40	0.86	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Miscellaneous	New	N_MS_Tank	0.34	0.40	0.86	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Offices	New	N_OF_Tank	0.34	0.40	0.86	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Restaurants	New	N_RS_Tank	0.34	0.40	0.86	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Retail	New	N_RT_Tank	0.34	0.40	0.86	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Schools K-12	New	N_SC_Tank	0.34	0.40	0.86	0	0	0	Fail RIM
Commercial	Tank Wrap on Water Heater	Warehouse	New	N_WR_Tank	0.34	0.40	0.86	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Assembly	Existing	E_AS_Therm	13.15	0.58	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	College and University	Existing	E_CU_Therm	20.12	0.89	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Grocery	Existing	E_GR_Therm	20.12	0.89	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Healthcare	Existing	E_HC_Therm	15.34	0.68	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Hospitals	Existing	E_HS_Therm	15.34	0.68	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Institutional	Existing	E_IN_Therm	13.15	0.58	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Lodging/Hospitality	Existing	E_LG_Therm	23.26	1.03	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Miscellaneous	Existing	E_MS_Therm	13.15	0.58	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Offices	Existing	E_OF_Therm	13.15	0.58	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Restaurants	Existing	E_RS_Therm	20.12	0.89	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Retail	Existing	E_RT_Therm	20.12	0.89	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Schools K-12	Existing	E_SC_Therm	13.15	0.58	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Warehouse	Existing	E_WR_Therm	13.15	0.58	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Assembly	New	N_AS_Therm	13.15	0.58	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	College and University	New	N_CU_Therm	20.12	0.89	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Grocery	New	N_GR_Therm	20.12	0.89	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Healthcare	New	N_HC_Therm	15.34	0.68	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Hospitals	New	N_HS_Therm	15.34	0.68	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Institutional	New	N_IN_Therm	13.15	0.58	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Lodging/Hospitality	New	N_LG_Therm	23.26	1.03	22.58	0	0	0	Fail 2-year Threshold
Commercial	Thermostatic Shower Restriction Valve	Miscellaneous	New	N_MS_Therm	13.15	0.58	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Offices	New	N_OF_Therm	13.15	0.58	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Restaurants	New	N_RS_Therm	20.12	0.89	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Retail	New	N_RT_Therm	20.12	0.89	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Schools K-12	New	N_SC_Therm	13.15	0.58	22.58	0	0	0	Fail RIM
Commercial	Thermostatic Shower Restriction Valve	Warehouse	New	N_WR_Therm	13.15	0.58	22.58	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Assembly	Existing	E_AS_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	College and University	Existing	E_CU_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Grocery	Existing	E_GR_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Healthcare	Existing	E_HC_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Hospitals	Existing	E_HS_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Institutional	Existing	E_IN_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Lodging/Hospitality	Existing	E_LG_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Miscellaneous	Existing	E_MS_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Offices	Existing	E_OF_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Restaurants	Existing	E_RS_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Retail	Existing	E_RT_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Schools K-12	Existing	E_SC_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Warehouse	Existing	E_WR_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Assembly	New	N_AS_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	College and University	New	N_CU_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Grocery	New	N_GR_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Exterior)	Healthcare	New	N_HC_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM

Commercial	Ceiling Insulation(R12 to R38)	Lodging/Hospitality	New	N_LG_Ceilin	0.66	1.21	0.55	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R12 to R38)	Miscellaneous	New	N_MS_Ceilin	0.66	1.22	0.55	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R12 to R38)	Offices	New	N_OF_Ceilin	0.66	1.22	0.55	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R12 to R38)	Restaurants	New	N_RS_Ceilin	0.68	1.25	0.55	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R12 to R38)	Retail	New	N_RT_Ceilin	0.68	1.25	0.55	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R12 to R38)	Schools K-12	New	N_SC_Ceilin	0.66	1.22	0.55	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R12 to R38)	Warehouse	New	N_WR_Ceilin	0.39	0.71	0.55	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Assembly	Existing	E_AS_Ceilin	0.36	1.22	0.30	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	College and University	Existing	E_CU_Ceilin	0.36	1.21	0.30	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Grocery	Existing	E_GR_Ceilin	0.37	1.25	0.30	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Healthcare	Existing	E_HC_Ceilin	0.36	1.22	0.30	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Hospitals	Existing	E_HS_Ceilin	0.36	1.21	0.30	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Institutional	Existing	E_IN_Ceilin	0.36	1.22	0.30	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Lodging/Hospitality	Existing	E_LG_Ceilin	0.36	1.21	0.30	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Miscellaneous	Existing	E_MS_Ceilin	0.36	1.22	0.30	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Offices	Existing	E_OF_Ceilin	0.36	1.22	0.30	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Restaurants	Existing	E_RS_Ceilin	0.37	1.25	0.30	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Retail	Existing	E_RT_Ceilin	0.37	1.25	0.30	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Schools K-12	Existing	E_SC_Ceilin	0.36	1.22	0.30	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Warehouse	Existing	E_WR_Ceilin	0.21	0.71	0.30	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Assembly	New	N_AS_Ceilin	0.36	1.22	0.29	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	College and University	New	N_CU_Ceilin	0.36	1.21	0.29	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Grocery	New	N_GR_Ceilin	0.37	1.25	0.29	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Healthcare	New	N_HC_Ceilin	0.36	1.22	0.29	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Hospitals	New	N_HS_Ceilin	0.36	1.21	0.29	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Institutional	New	N_IN_Ceilin	0.36	1.22	0.29	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Lodging/Hospitality	New	N_LG_Ceilin	0.36	1.21	0.29	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Miscellaneous	New	N_MS_Ceilin	0.36	1.22	0.29	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Offices	New	N_OF_Ceilin	0.36	1.22	0.29	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Restaurants	New	N_RS_Ceilin	0.37	1.25	0.29	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Retail	New	N_RT_Ceilin	0.37	1.25	0.29	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Schools K-12	New	N_SC_Ceilin	0.36	1.22	0.29	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R19 to R38)	Warehouse	New	N_WR_Ceilin	0.21	0.71	0.29	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R30 to R38)	Assembly	Existing	E_AS_Ceilin	0.13	1.22	0.10	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R30 to R38)	College and University	Existing	E_CU_Ceilin	0.13	1.21	0.10	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R30 to R38)	Grocery	Existing	E_GR_Ceilin	0.13	1.25	0.10	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R30 to R38)	Healthcare	Existing	E_HC_Ceilin	0.13	1.22	0.10	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R30 to R38)	Hospitals	Existing	E_HS_Ceilin	0.13	1.21	0.10	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R30 to R38)	Institutional	Existing	E_IN_Ceilin	0.13	1.22	0.10	0	0	0	Fail TRC
Commercial	Ceiling Insulation(R30 to R38)	Lodging/Hospitality	Existing	E_LG_Ceilin	0.13	1.21	0.10	0	0	0	F

Commercial	Bi-Level Lighting Control (Exterior)	Hospitals	New	N_HS_Bi-Le	0.67	0.27	2.45	0	0	0	Fail RIM	
Commercial	Bi-Level Lighting Control (Exterior)	Institutional	New	N_IN_Bi-Lev	0.67	0.27	2.45	0	0	0	Fail RIM	
Commercial	Bi-Level Lighting Control (Exterior)	Lodging/Hospitality	New	N_LG_Bi-Le	0.67	0.27	2.45	0	0	0	Fail RIM	
Commercial	Bi-Level Lighting Control (Exterior)	Miscellaneous	New	N_MS_Bi-Le	0.67	0.27	2.45	0	0	0	Fail RIM	
Commercial	Bi-Level Lighting Control (Exterior)	Offices	New	N_OF_Bi-Le	0.67	0.27	2.45	0	0	0	Fail RIM	
Commercial	Bi-Level Lighting Control (Exterior)	Restaurants	New	N_RS_Bi-Le	0.67	0.27	2.45	0	0	0	Fail RIM	
Commercial	Bi-Level Lighting Control (Exterior)	Retail	New	N_RT_Bi-Le	0.67	0.27	2.45	0	0	0	Fail RIM	
Commercial	Bi-Level Lighting Control (Exterior)	Schools K-12	New	N_SC_Bi-Le	0.67	0.27	2.45	0	0	0	Fail RIM	
Commercial	Bi-Level Lighting Control (Exterior)	Warehouse	New	N_WR_Bi-Le	0.67	0.27	2.45	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Assembly	Existing	E_AS_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	College and University	Existing	E_CU_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Grocery	Existing	E_GR_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Healthcare	Existing	E_HC_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Hospitals	Existing	E_HS_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Institutional	Existing	E_IN_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Lodging/Hospitality	Existing	E_LG_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Miscellaneous	Existing	E_MS_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Offices	Existing	E_OF_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Restaurants	Existing	E_RS_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Retail	Existing	E_RT_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Schools K-12	Existing	E_SC_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Warehouse	Existing	E_WR_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Assembly	New	N_AS_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	College and University	New	N_CU_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Grocery	New	N_GR_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Healthcare	New	N_HC_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Hospitals	New	N_HS_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Institutional	New	N_IN_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Lodging/Hospitality	New	N_LG_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Miscellaneous	New	N_MS_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Offices	New	N_OF_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Restaurants	New	N_RS_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Retail	New	N_RT_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Schools K-12	New	N_SC_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Outdoor Lighting Controls	Warehouse	New	N_WR_Outdo	0.76	0.27	2.80	0	0	0	Fail RIM	
Commercial	Air Curtains	Assembly	Existing	E_AS_Air Cu	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	College and University	Existing	E_CU_Air Cu	0.01	0.47	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Grocery	Existing	E_GR_Air Cu	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Healthcare	Existing	E_HC_Air Cu	0.01	0.47	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Hospitals	Existing	E_HS_Air Cu	0.01	0.47	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Institutional	Existing	E_IN_Air Cu	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Lodging/Hospitality	Existing	E_LG_Air Cu	0.01	0.47	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Miscellaneous	Existing	E_MS_Air Cu	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Offices	Existing	E_OF_Air Cu	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Restaurants	Existing	E_RS_Air Cu	0.01	0.47	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Retail	Existing	E_RT_Air Cu	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Schools K-12	Existing	E_SC_Air Cu	0.01	0.47	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Warehouse	Existing	E_WR_Air C	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Assembly	New	N_AS_Air Cu	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	College and University	New	N_CU_Air Cu	0.01	0.47	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Grocery	New	N_GR_Air Cu	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Healthcare	New	N_HC_Air Cu	0.01	0.47	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Hospitals	New	N_HS_Air Cu	0.01	0.47	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Institutional	New	N_IN_Air Cu	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Lodging/Hospitality	New	N_LG_Air Cu	0.01	0.47	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Miscellaneous	New	N_MS_Air Cu	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Offices	New	N_OF_Air Cu	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Restaurants	New	N_RS_Air Cu	0.01	0.47	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Retail	New	N_RT_Air Cu	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Schools K-12	New	N_SC_Air Cu	0.01	0.47	0.01	0	0	0	Fail RIM	
Commercial	Air Curtains	Warehouse	New	N_WR_Air C	0.01	0.49	0.01	0	0	0	Fail RIM	
Commercial	Airside Economizer	Assembly	Existing	E_AS_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	College and University	Existing	E_CU_Airside	15.94	0.50	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Grocery	Existing	E_GR_Airside	9.20	0.29	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Healthcare	Existing	E_HC_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Hospitals	Existing	E_HS_Airside	15.94	0.50	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Institutional	Existing	E_IN_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Lodging/Hospitality	Existing	E_LG_Airside	9.20	0.29	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Miscellaneous	Existing	E_MS_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Offices	Existing	E_OF_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Restaurants	Existing	E_RS_Airside	9.20	0.29	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Retail	Existing	E_RT_Airside	9.20	0.29	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Schools K-12	Existing	E_SC_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Warehouse	Existing	E_WR_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Assembly	New	N_AS_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	College and University	New	N_CU_Airside	15.94	0.50	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Grocery	New	N_GR_Airside	9.20	0.29	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Healthcare	New	N_HC_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Hospitals	New	N_HS_Airside	15.94	0.50	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Institutional	New	N_IN_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Lodging/Hospitality	New	N_LG_Airside	9.20	0.29	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Miscellaneous	New	N_MS_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Offices	New	N_OF_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Restaurants	New	N_RS_Airside	9.20	0.29	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Retail	New	N_RT_Airside	9.20	0.29	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Schools K-12	New	N_SC_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Airside Economizer	Warehouse	New	N_WR_Airside	8.84	0.28	31.84	0	0	0	Fail RIM	
Commercial	Ceiling Insulation(R12 to R38)	Assembly	Existing	E_AS_Ceiling	0.68	1.22	0.56	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	College and University	Existing	E_CU_Ceilin	0.67	1.21	0.56	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Grocery	Existing	E_GR_Ceilin	0.69	1.25	0.56	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Healthcare	Existing	E_HC_Ceilin	0.68	1.22	0.56	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Hospitals	Existing	E_HS_Ceilin	0.67	1.21	0.56	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Institutional	Existing	E_IN_Ceiling	0.68	1.22	0.56	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Lodging/Hospitality	Existing	E_LG_Ceilin	0.67	1.21	0.56	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Miscellaneous	Existing	E_MS_Ceilin	0.68	1.22	0.56	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Offices	Existing	E_OF_Ceilin	0.68	1.22	0.56	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Restaurants	Existing	E_RS_Ceilin	0.69	1.25	0.56	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Retail	Existing	E_RT_Ceilin	0.69	1.25	0.56	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Schools K-12	Existing	E_SC_Ceilin	0.68	1.22	0.56	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Warehouse	Existing	E_WR_Ceilin	0.39	0.71	0.56	0	0	0	Fail RIM	
Commercial	Ceiling Insulation(R12 to R38)	Assembly	New	N_AS_Ceilin	0.66	1.22	0.55	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	College and University	New	N_CU_Ceilin	0.66	1.21	0.55	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Grocery	New	N_GR_Ceilin	0.68	1.25	0.55	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Healthcare	New	N_HC_Ceilin	0.66	1.22	0.55	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Hospitals	New	N_HS_Ceilin	0.66	1.21	0.55	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Institutional	New	N_IN_Ceiling	0.66	1.22	0.55	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Lodging/Hospitality	New	N_LG_Ceilin	0.66	1.21	0.55	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Miscellaneous	New	N_MS_Ceilin	0.66	1.22	0.55	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Offices	New	N_OF_Ceilin	0.66	1.22	0.55	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Restaurants	New	N_RS_Ceilin	0.68	1.25	0.55	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Retail	New	N_RT_Ceilin	0.68	1.25	0.55	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Schools K-12	New	N_SC_Ceilin	0.66	1.22	0.55	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R12 to R38)	Warehouse	New	N_WR_Ceilin	0.39	0.71	0.55	0	0	0	Fail RIM	
Commercial	Ceiling Insulation(R19 to R38)	Assembly	Existing	E_AS_Ceilin	0.36	1.22	0.30	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	College and University	Existing	E_CU_Ceilin	0.36	1.21	0.30	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Grocery	Existing	E_GR_Ceilin	0.37	1.25	0.30	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Healthcare	Existing	E_HC_Ceilin	0.36	1.22	0.30	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Hospitals	Existing	E_HS_Ceilin	0.36	1.21	0.30	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Institutional	Existing	E_IN_Ceiling	0.36	1.22	0.30	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Lodging/Hospitality	Existing	E_LG_Ceilin	0.36	1.21	0.30	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Miscellaneous	Existing	E_MS_Ceilin	0.36	1.22	0.30	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Offices	Existing	E_OF_Ceilin	0.36	1.22	0.30	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Restaurants	Existing	E_RS_Ceilin	0.37	1.25	0.30	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Retail	Existing	E_RT_Ceilin	0.37	1.25	0.30	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Schools K-12	Existing	E_SC_Ceilin	0.36	1.22	0.30	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Warehouse	Existing	E_WR_Ceilin	0.21	0.71	0.30	0	0	0	Fail RIM	
Commercial	Ceiling Insulation(R19 to R38)	Assembly	New	N_AS_Ceilin	0.36	1.22	0.29	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	College and University	New	N_CU_Ceilin	0.36	1.21	0.29	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Grocery	New	N_GR_Ceilin	0.37	1.25	0.29	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Healthcare	New	N_HC_Ceilin	0.36	1.22	0.29	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Hospitals	New	N_HS_Ceilin	0.36	1.21	0.29	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Institutional	New	N_IN_Ceiling	0.36	1.22	0.29	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Lodging/Hospitality	New	N_LG_Ceilin	0.36	1.21	0.29	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Miscellaneous	New	N_MS_Ceilin	0.36	1.22	0.29	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Offices	New	N_OF_Ceilin	0.36	1.22	0.29	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Restaurants	New	N_RS_Ceilin	0.37	1.25	0.29	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Retail	New	N_RT_Ceilin	0.37	1.25	0.29	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Schools K-12	New	N_SC_Ceilin	0.36	1.22	0.29	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R19 to R38)	Warehouse	New	N_WR_Ceilin	0.21	0.71	0.29	0	0	0	Fail RIM	
Commercial	Ceiling Insulation(R2 to R38)	Warehouse	Existing	E_WR_Ceilin	2.01	0.71	2.83	0	0	0	Fail RIM	
Commercial	Ceiling Insulation(R2 to R38)	Warehouse	New	N_WR_Ceilin	2.01	0.71	2.83	0	0	0	Fail RIM	
Commercial	Ceiling Insulation(R30 to R38)	Assembly	Existing	E_AS_Ceilin	0.13	1.22	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	College and University	Existing	E_CU_Ceilin	0.13	1.21	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Grocery	Existing	E_GR_Ceilin	0.13	1.25	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Healthcare	Existing	E_HC_Ceilin	0.13	1.22	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Hospitals	Existing	E_HS_Ceilin	0.13	1.21	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Institutional	Existing	E_IN_Ceiling	0.13	1.22	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Lodging/Hospitality	Existing	E_LG_Ceilin	0.13	1.21	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Miscellaneous	Existing	E_MS_Ceilin	0.13	1.22	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Offices	Existing	E_OF_Ceilin	0.13	1.22	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Restaurants	Existing	E_RS_Ceilin	0.13	1.25	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Retail	Existing	E_RT_Ceilin	0.13	1.25	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Schools K-12	Existing	E_SC_Ceilin	0.13	1.22	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Warehouse	Existing	E_WR_Ceilin	0.07	0.71	0.10	0	0	0	Fail RIM	
Commercial	Ceiling Insulation(R30 to R38)	Assembly	New	N_AS_Ceilin	0.13	1.22	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	College and University	New	N_CU_Ceilin	0.12	1.21	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Grocery	New	N_GR_Ceilin	0.13	1.25	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Healthcare	New	N_HC_Ceilin	0.13	1.22	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Hospitals	New	N_HS_Ceilin	0.12	1.21	0.10	0	0	0	Fail PCT	
Commercial	Ceiling Insulation(R30 to R38)	Institutional	New	N_IN_Ceiling	0.13	1.22	0.10	0	0	0	Fail PCT	
Commercial	Duct Insulation	Miscellaneous	Existing	E_MS_Duct	0.26	1.42	0.18	0	0	0	Fail TRC	
Commercial	Duct Insulation	Offices	Existing	E_OF_Duct	0.35	1.42	0.24	0	0	0	Fail TRC	
Commercial	Duct Insulation	Restaurants	Existing	E_RS_Duct	0.79	1.42	0.56	0	0	0	Fail TRC	
Commercial	Duct Insulation	Retail	Existing	E_RT_Duct	0.15	1.42	0.11	0	0	0	Fail TRC	
Commercial	Duct Insulation	Schools K-12	Existing	E_SC_Duct	0.13	1.42	0.09	0	0	0	Fail TRC	
Commercial	Duct Insulation	Warehouse	Existing	E_WR_Duct	0.04	1.42	0.03	0	0	0	Fail TRC	
Commercial	Duct Insulation	Assembly	New	N_AS_Duct	0.08	1.42	0.06	0	0	0	Fail TRC	
Commercial	Duct Insulation	College and University	New	N_CU_Duct	0.13	1.42	0.09	0	0	0	Fail TRC	
Commercial	Duct Insulation	Grocery	New	N_GR_Duct	0.82	1.42	0.58	0	0	0	Fail TRC	
Commercial	Duct Insulation	Healthcare	New	N_HC_Duct	0.34	1.42	0.24	0	0	0	Fail TRC	
Commercial	Duct Insulation	Hospitals	New	N_HS_Duct	0.34	1.42	0.24	0	0	0	Fail TRC	
Commercial	Duct Insulation	Institutional	New	N_IN_Duct	0.38	1.42	0.27	0	0	0	Fail TRC	
Commercial	Duct Insulation	Lodging/Hospitality	New	N_LG_Duct	0.19	1.42	0.13	0	0	0	Fail TRC	
Commercial	Duct Insulation	Miscellaneous	New	N_MS_Duct	0.26	1.42	0.18	0	0	0	Fail TRC	
Commercial	Duct Insulation	Offices	New	N_OF_Duct	0.35	1.42	0.24	0	0	0	Fail TRC	
Commercial	Duct Insulation	Restaurants	New	N_RS_Duct	0.79	1.42	0.56	0	0	0	Fail TRC	
Commercial	Duct Insulation	Retail	New	N_RT_Duct	0.15	1.42	0.11	0	0	0	Fail TRC	
Commercial	Duct Insulation	Schools K-12	New	N_SC_Duct	0.13	1.42	0.09	0	0	0	Fail TRC	
Commercial	Duct Insulation	Warehouse	New	N_WR_Duct	0.04	1.42	0.03	0	0	0	Fail TRC	
Commercial	Duct Sealing Repair	Grocery	Existing	E_GR_Duct	48.67	1.64	29.68	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Healthcare	Existing	E_HC_Duct	19.89	1.64	12.13	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Hospitals	Existing	E_HS_Duct	19.89	1.64	12.13	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Institutional	Existing	E_IN_Duct	22.43	1.64	13.68	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Lodging/Hospitality	Existing	E_LG_Duct	11.23	1.64	6.85	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Miscellaneous	Existing	E_MS_Duct	15.28	1.64	9.32	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Offices	Existing	E_OF_Duct	20.53	1.64	12.52	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Restaurants	Existing	E_RS_Duct	47.04	1.64	28.69	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Grocery	New	N_GR_Duct	48.67	1.64	29.68	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Healthcare	New	N_HC_Duct	19.89	1.64	12.13	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Hospitals	New	N_HS_Duct	19.89	1.64	12.13	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Institutional	New	N_IN_Duct	22.43	1.64	13.68	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Lodging/Hospitality	New	N_LG_Duct	11.23	1.64	6.85	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Miscellaneous	New	N_MS_Duct	15.28	1.64	9.32	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Offices	New	N_OF_Duct	20.53	1.64	12.52	0	0	0	Fail 2-year Threshold	
Commercial	Duct Sealing Repair	Restaurants	New	N_RS_Duct	47.04	1.64	28.69	0	0	0	Fail 2-year Threshold	
Commercial	ECM Motors on Furnaces	Assembly	Existing	E_AS_ECM	0.58	0.26	2.19	0	0	0	Fail TRC	
Commercial	ECM Motors on Furnaces	Healthcare	Existing	E_HC_ECM	0.90	0.26	3.43	0	0	0	Fail TRC	
Commercial	ECM Motors on Furnaces	Institutional	Existing	E_IN_ECM	0.50	0.26	1.91	0	0	0	Fail TRC	
Commercial	ECM Motors on Furnaces	Miscellaneous	Existing	E_MS_ECM	0.32	0.26	1.21	0	0	0	Fail TRC	
Commercial	ECM Motors on Furnaces	Offices	Existing	E_OF_ECM	0.34	0.26	1.28	0	0	0	Fail TRC	
Commercial	ECM Motors on Furnaces	Restaurants	Existing	E_RS_ECM	3.90	0.48	8.07	0	0	0	Fail 2-year Threshold	
Commercial	ECM Motors on Furnaces	Warehouse	Existing	E_WR_ECM	0.32	0.26	1.21	0	0	0	Fail TRC	
Commercial	ECM Motors on Furnaces	Assembly	New	N_AS_ECM	0.58	0.26	2.19	0	0	0	Fail TRC	
Commercial	ECM Motors on Furnaces	Healthcare	New	N_HC_ECM	0.90	0.26	3.43	0	0	0	Fail TRC	
Commercial	ECM Motors on Furnaces	Institutional	New	N_IN_ECM	0.50	0.26

Commercial	Ceiling Insulation(R30 to R38)	Lodging/Hospitality	New	N_LG_Ceilin	0.12	1.21	0.10	0	0	0	Fail PCT
Commercial	Ceiling Insulation(R30 to R38)	Miscellaneous	New	N_MS_Ceilin	0.13	1.22	0.10	0	0	0	Fail PCT
Commercial	Ceiling Insulation(R30 to R38)	Offices	New	N_OF_Ceilin	0.13	1.22	0.10	0	0	0	Fail PCT
Commercial	Ceiling Insulation(R30 to R38)	Restaurants	New	N_RS_Ceilin	0.13	1.25	0.10	0	0	0	Fail PCT
Commercial	Ceiling Insulation(R30 to R38)	Retail	New	N_RT_Ceilin	0.13	1.25	0.10	0	0	0	Fail PCT
Commercial	Ceiling Insulation(R30 to R38)	Schools K-12	New	N_SC_Ceilin	0.13	1.22	0.10	0	0	0	Fail PCT
Commercial	Ceiling Insulation(R30 to R38)	Warehouse	New	N_WR_Ceilir	0.07	0.71	0.10	0	0	0	Fail RIM
Commercial	Chilled Water Controls Optimization	Assembly	Existing	E_AS_Chille	17.50	1.01	17.35	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	College and University	Existing	E_CU_Chille	38.95	0.70	55.53	0	0	0	Fail RIM
Commercial	Chilled Water Controls Optimization	Grocery	Existing	E_GR_Chille	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Chilled Water Controls Optimization	Healthcare	Existing	E_HC_Chille	26.72	1.01	26.48	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Hospitals	Existing	E_HS_Chille	107.89	0.70	153.80	0	0	0	Fail RIM
Commercial	Chilled Water Controls Optimization	Institutional	Existing	E_IN_Chiller	9.46	1.01	9.37	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Lodging/Hospitality	Existing	E_LG_Chille	72.73	1.01	72.08	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Miscellaneous	Existing	E_MS_Chille	22.52	1.01	22.32	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Offices	Existing	E_OF_Chille	23.07	1.01	22.86	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Restaurants	Existing	E_RS_Chille	28.37	1.01	28.11	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Retail	Existing	E_RT_Chille	20.76	1.01	20.57	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Schools K-12	Existing	E_SC_Chille	15.92	1.01	15.78	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Warehouse	Existing	E_WR_Chill	6.15	1.01	6.10	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Assembly	New	N_AS_Chille	17.50	1.01	17.35	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	College and University	New	N_CU_Chille	38.95	0.70	55.53	0	0	0	Fail RIM
Commercial	Chilled Water Controls Optimization	Grocery	New	N_GR_Chille	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Chilled Water Controls Optimization	Healthcare	New	N_HC_Chille	26.72	1.01	26.48	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Hospitals	New	N_HS_Chille	107.89	0.70	153.80	0	0	0	Fail RIM
Commercial	Chilled Water Controls Optimization	Institutional	New	N_IN_Chiller	9.46	1.01	9.37	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Lodging/Hospitality	New	N_LG_Chille	72.73	1.01	72.08	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Miscellaneous	New	N_MS_Chille	22.52	1.01	22.32	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Offices	New	N_OF_Chille	23.07	1.01	22.86	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Restaurants	New	N_RS_Chille	28.37	1.01	28.11	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Retail	New	N_RT_Chille	20.76	1.01	20.57	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Schools K-12	New	N_SC_Chille	15.92	1.01	15.78	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water Controls Optimization	Warehouse	New	N_WR_Chill	6.15	1.01	6.10	0	0	0	Fail 2-year Threshold
Commercial	Chilled Water System - Variable Speed Drives	Assembly	Existing	E_AS_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	College and University	Existing	E_CU_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Grocery	Existing	E_GR_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Healthcare	Existing	E_HC_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Hospitals	Existing	E_HS_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Institutional	Existing	E_IN_Chiller	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Lodging/Hospitality	Existing	E_LG_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Miscellaneous	Existing	E_MS_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Offices	Existing	E_OF_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Restaurants	Existing	E_RS_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Retail	Existing	E_RT_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Schools K-12	Existing	E_SC_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Warehouse	Existing	E_WR_Chill	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Assembly	New	N_AS_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	College and University	New	N_CU_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Grocery	New	N_GR_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Healthcare	New	N_HC_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Hospitals	New	N_HS_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Institutional	New	N_IN_Chiller	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Lodging/Hospitality	New	N_LG_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Miscellaneous	New	N_MS_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Offices	New	N_OF_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Restaurants	New	N_RS_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Retail	New	N_RT_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Schools K-12	New	N_SC_Chille	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Chilled Water System - Variable Speed Drives	Warehouse	New	N_WR_Chill	2.43	0.52	4.69	0	0	0	Fail RIM
Commercial	Cool Roof	Assembly	Existing	E_AS_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	College and University	Existing	E_CU_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Grocery	Existing	E_GR_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Healthcare	Existing	E_HC_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Hospitals	Existing	E_HS_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Institutional	Existing	E_IN_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Lodging/Hospitality	Existing	E_LG_Cool R	0.18	1.47	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Miscellaneous	Existing	E_MS_Cool R	0.07	0.56	0.12	0	0	0	Fail RIM
Commercial	Cool Roof	Offices	Existing	E_OF_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Restaurants	Existing	E_RS_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Retail	Existing	E_RT_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Schools K-12	Existing	E_SC_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Warehouse	Existing	E_WR_Cool	0.07	0.56	0.12	0	0	0	Fail RIM
Commercial	Cool Roof	Assembly	New	N_AS_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	College and University	New	N_CU_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Grocery	New	N_GR_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Healthcare	New	N_HC_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Hospitals	New	N_HS_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Institutional	New	N_IN_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Lodging/Hospitality	New	N_LG_Cool R	0.18	1.47	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Miscellaneous	New	N_MS_Cool R	0.07	0.56	0.12	0	0	0	Fail RIM
Commercial	Cool Roof	Offices	New	N_OF_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Restaurants	New	N_RS_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Retail	New	N_RT_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Schools K-12	New	N_SC_Cool R	0.15	1.18	0.12	0	0	0	Fail PCT
Commercial	Cool Roof	Warehouse	New	N_WR_Cool	0.07	0.56	0.12	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Assembly	Existing	E_AS_Dedic	0.78	0.89	0.89	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	College and University	Existing	E_CU_Dedic	0.72	0.74	0.98	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Grocery	Existing	E_GR_Dedic	0.47	0.89	0.53	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Healthcare	Existing	E_HC_Dedic	1.69	0.89	1.91	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Hospitals	Existing	E_HS_Dedic	1.61	0.89	1.82	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Institutional	Existing	E_IN_Dedica	0.43	0.89	0.49	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Lodging/Hospitality	Existing	E_LG_Dedic	1.06	0.74	1.44	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Miscellaneous	Existing	E_MS_Dedic	0.44	0.89	0.49	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Offices	Existing	E_OF_Dedic	0.87	0.89	0.98	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Restaurants	Existing	E_RS_Dedic	1.34	0.89	1.51	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Retail	Existing	E_RT_Dedic	1.03	0.89	1.16	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Schools K-12	Existing	E_SC_Dedic	0.90	0.89	1.01	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Warehouse	Existing	E_WR_Dedic	0.20	0.89	0.23	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Assembly	New	N_AS_Dedic	0.78	0.89	0.89	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	College and University	New	N_CU_Dedic	0.72	0.74	0.98	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Grocery	New	N_GR_Dedic	0.47	0.89	0.53	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Healthcare	New	N_HC_Dedic	1.69	0.89	1.91	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Hospitals	New	N_HS_Dedic	1.61	0.89	1.82	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Institutional	New	N_IN_Dedica	0.43	0.89	0.49	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Lodging/Hospitality	New	N_LG_Dedic	1.06	0.74	1.44	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Miscellaneous	New	N_MS_Dedic	0.44	0.89	0.49	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Offices	New	N_OF_Dedic	0.87	0.89	0.98	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Restaurants	New	N_RS_Dedic	1.34	0.89	1.51	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Retail	New	N_RT_Dedic	1.03	0.89	1.16	0	0	0	Fail RIM
Commercial	Dedicated Outdoor Air System on VRF unit	Schools K-12	New	N_SC_Dedic	0.90	0.89	1.01	0	0	0	Fail RIM

Commercial	Hotel Card Energy Control Systems	College and University	Existing	E_CU_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Grocery	Existing	E_GR_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Healthcare	Existing	E_HC_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Hospitals	Existing	E_HS_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Institutional	Existing	E_IN_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Lodging/Hospitality	Existing	E_LG_Hotel	0.74	0.31	2.39	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Miscellaneous	Existing	E_MS_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Offices	Existing	E_OF_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Restaurants	Existing	E_RS_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Retail	Existing	E_RT_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Schools K-12	Existing	E_SC_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Warehouse	Existing	E_WR_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Assembly	New	N_AS_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	College and University	New	N_CU_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Grocery	New	N_GR_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Healthcare	New	N_HC_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Hospitals	New	N_HS_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Institutional	New	N_IN_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Lodging/Hospitality	New	N_LG_Hotel	0.74	0.31	2.39	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Miscellaneous	New	N_MS_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Offices	New	N_OF_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Restaurants	New	N_RS_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Retail	New	N_RT_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Schools K-12	New	N_SC_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Hotel Card Energy Control Systems	Warehouse	New	N_WR_Hotel	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	HVAC tune-up	College and University	Existing	E_CU_HVAC	0.92	0.66	1.40	0	0	0	Fail TRC
Commercial	HVAC tune-up	Grocery	Existing	E_GR_HVAC	0.67	0.95	0.70	0	0	0	Fail TRC
Commercial	HVAC tune-up	Healthcare	Existing	E_HC_HVAC	2.62	0.95	2.75	0	0	0	Fail 2-year Threshold
Commercial	HVAC tune-up	Hospitals	Existing	E_HS_HVAC	1.71	0.66	2.60	0	0	0	Fail 2-year Threshold
Commercial	HVAC tune-up	Institutional	Existing	E_IN_HVAC	0.65	0.95	0.68	0	0	0	Fail TRC
Commercial	HVAC tune-up	Miscellaneous	Existing	E_MS_HVAC	0.59	0.84	0.71	0	0	0	Fail TRC
Commercial	HVAC tune-up	Warehouse	Existing	E_WR_HVAC	0.29	0.95	0.31	0	0	0	Fail TRC
Commercial	HVAC tune-up	College and University	New	N_CU_HVAC	0.92	0.66	1.40	0	0	0	Fail TRC
Commercial	HVAC tune-up	Grocery	New	N_GR_HVAC	0.67	0.95	0.70	0	0	0	Fail TRC
Commercial	HVAC tune-up	Healthcare	New	N_HC_HVAC	2.62	0.95	2.75	0	0	0	Fail 2-year Threshold
Commercial	HVAC tune-up	Hospitals	New	N_HS_HVAC	1.71	0.66	2.60	0	0	0	Fail 2-year Threshold
Commercial	HVAC tune-up	Institutional	New	N_IN_HVAC	0.65	0.95	0.68	0	0	0	Fail TRC
Commercial	HVAC tune-up	Miscellaneous	New	N_MS_HVAC	0.59	0.84	0.71	0	0	0	Fail TRC
Commercial	HVAC tune-up	Warehouse	New	N_WR_HVAC	0.29	0.95	0.31	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Assembly	Existing	E_AS_HVAC	0.79	0.84	0.95	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	College and University	Existing	E_CU_HVAC	0.88	0.84	1.05	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Grocery	Existing	E_GR_HVAC	0.44	0.84	0.52	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Institutional	Existing	E_IN_HVAC	0.43	0.84	0.51	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Miscellaneous	Existing	E_MS_HVAC	0.44	0.84	0.53	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Offices	Existing	E_OF_HVAC	0.89	0.84	1.07	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Schools K-12	Existing	E_SC_HVAC	0.87	0.84	1.05	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Warehouse	Existing	E_WR_HVAC	0.19	0.84	0.23	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Assembly	New	N_AS_HVAC	0.79	0.84	0.95	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	College and University	New	N_CU_HVAC	0.88	0.84	1.05	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Grocery	New	N_GR_HVAC	0.44	0.84	0.52	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Institutional	New	N_IN_HVAC	0.43	0.84	0.51	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Miscellaneous	New	N_MS_HVAC	0.44	0.84	0.53	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Offices	New	N_OF_HVAC	0.89	0.84	1.07	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Schools K-12	New	N_SC_HVAC	0.87	0.84	1.05	0	0	0	Fail TRC
Commercial	HVAC tune-up_RTU	Warehouse	New	N_WR_HVAC	0.19	0.84	0.23	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Assembly	Existing	E_AS_Infiltra	0.16	1.44	0.11	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	College and University	Existing	E_CU_Infiltra	0.08	1.44	0.05	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Grocery	Existing	E_GR_Infiltra	0.54	1.44	0.37	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Healthcare	Existing	E_HC_Infiltra	0.15	1.44	0.10	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Hospitals	Existing	E_HS_Infiltra	0.08	1.44	0.05	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Institutional	Existing	E_IN_Infiltra	0.48	1.44	0.34	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Lodging/Hospitality	Existing	E_LG_Infiltra	0.36	1.44	0.25	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Miscellaneous	Existing	E_MS_Infiltra	0.10	1.44	0.07	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Offices	Existing	E_OF_Infiltra	0.70	1.44	0.49	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Restaurants	Existing	E_RS_Infiltra	0.52	1.44	0.36	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Retail	Existing	E_RT_Infiltra	0.23	1.44	0.16	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Schools K-12	Existing	E_SC_Infiltra	0.05	1.44	0.04	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Warehouse	Existing	E_WR_Infiltr	0.14	1.44	0.10	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Assembly	New	N_AS_Infiltra	0.16	1.44	0.11	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	College and University	New	N_CU_Infiltra	0.08	1.44	0.05	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Grocery	New	N_GR_Infiltra	0.53	1.44	0.37	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Healthcare	New	N_HC_Infiltra	0.15	1.44	0.10	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Hospitals	New	N_HS_Infiltra	0.08	1.44	0.05	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Institutional	New	N_IN_Infiltra	0.48	1.44	0.33	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Lodging/Hospitality	New	N_LG_Infiltra	0.36	1.44	0.25	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Miscellaneous	New	N_MS_Infiltra	0.10	1.44	0.07	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Offices	New	N_OF_Infiltra	0.69	1.44	0.48	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Restaurants	New	N_RS_Infiltra	0.51	1.44	0.36	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Retail	New	N_RT_Infiltra	0.22	1.44	0.16	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Schools K-12	New	N_SC_Infiltra	0.05	1.44	0.04	0	0	0	Fail TRC
Commercial	Infiltration Reduction - Air Sealing	Warehouse	New	N_WR_Infiltr	0.14	1.44	0.10	0	0	0	Fail TRC
Commercial	Low U-Value Windows	Assembly	New	N_AS_Low U	0.19	1.12	0.17	0	0	0	Fail TRC
Commercial	Low U-Value Windows	College and University	New	N_CU_Low U	0.19	1.12	0.17	0	0	0	Fail TRC
Commercial	Low U-Value Windows	Grocery	New	N_GR_Low U	0.19	1.12	0.17	0	0	0	Fail TRC
Commercial	Low U-Value Windows	Healthcare	New	N_HC_Low U	0.19	1.12	0.17	0	0	0	Fail TRC
Commercial	Low U-Value Windows	Hospitals	New	N_HS_Low U	0.19	1.12	0.17	0	0	0	Fail TRC
Commercial	Low U-Value Windows	Institutional	New	N_IN_Low U	0.19	1.12	0.17	0	0	0	Fail TRC
Commercial	Low U-Value Windows	Lodging/Hospitality	New	N_LG_Low U	0.22	1.27	0.17	0	0	0	Fail TRC
Commercial	Low U-Value Windows	Miscellaneous	New	N_MS_Low U	0.18	1.06	0.17	0	0	0	Fail TRC
Commercial	Low U-Value Windows	Offices	New	N_OF_Low U	0.19	1.12	0.17	0	0	0	Fail TRC
Commercial	Low U-Value Windows	Restaurants	New	N_RS_Low U	0.19	1.12	0.17	0	0	0	Fail TRC
Commercial	Low U-Value Windows	Retail	New	N_RT_Low U	0.19	1.12	0.17	0	0	0	Fail TRC
Commercial	Low U-Value Windows	Schools K-12	New	N_SC_Low U	0.19	1.12	0.17	0	0	0	Fail TRC
Commercial	Low U-Value Windows	Warehouse	New	N_WR_Low	0.18	1.06	0.17	0	0	0	Fail TRC
Commercial	Program

Commercial	Dedicated Outdoor Air System on VRF unit	Warehouse	New	N_WR_Dedic	0.20	0.89	0.23	0	0	0	Fail RIM
Commercial	Destratification Fans	Assembly	Existing	E_AS_Destra	0.06	0.62	0.10	0	0	0	Fail RIM
Commercial	Destratification Fans	College and University	Existing	E_CU_Destra	0.12	0.62	0.19	0	0	0	Fail RIM
Commercial	Destratification Fans	Grocery	Existing	E_GR_Destra	0.04	0.62	0.07	0	0	0	Fail RIM
Commercial	Destratification Fans	Healthcare	Existing	E_HC_Destra	0.11	0.62	0.17	0	0	0	Fail RIM
Commercial	Destratification Fans	Hospitals	Existing	E_HS_Destra	0.21	0.62	0.34	0	0	0	Fail RIM
Commercial	Destratification Fans	Institutional	Existing	E_IN_Destra	0.02	0.62	0.04	0	0	0	Fail RIM
Commercial	Destratification Fans	Lodging/Hospitality	Existing	E_LG_Destra	0.03	0.62	0.06	0	0	0	Fail RIM
Commercial	Destratification Fans	Miscellaneous	Existing	E_MS_Destra	0.05	0.62	0.09	0	0	0	Fail RIM
Commercial	Destratification Fans	Offices	Existing	E_OF_Destra	0.01	0.62	0.02	0	0	0	Fail RIM
Commercial	Destratification Fans	Restaurants	Existing	E_RS_Destra	0.09	0.62	0.15	0	0	0	Fail RIM
Commercial	Destratification Fans	Retail	Existing	E_RT_Destra	0.11	0.62	0.18	0	0	0	Fail RIM
Commercial	Destratification Fans	Schools K-12	Existing	E_SC_Destra	0.35	0.62	0.57	0	0	0	Fail RIM
Commercial	Destratification Fans	Warehouse	Existing	E_WR_Destr	0.04	0.62	0.06	0	0	0	Fail RIM
Commercial	Destratification Fans	Assembly	New	N_AS_Destra	0.06	0.62	0.10	0	0	0	Fail RIM
Commercial	Destratification Fans	College and University	New	N_CU_Destra	0.12	0.62	0.19	0	0	0	Fail RIM
Commercial	Destratification Fans	Grocery	New	N_GR_Destra	0.04	0.62	0.07	0	0	0	Fail RIM
Commercial	Destratification Fans	Healthcare	New	N_HC_Destra	0.11	0.62	0.17	0	0	0	Fail RIM
Commercial	Destratification Fans	Hospitals	New	N_HS_Destra	0.21	0.62	0.34	0	0	0	Fail RIM
Commercial	Destratification Fans	Institutional	New	N_IN_Destra	0.02	0.62	0.04	0	0	0	Fail RIM
Commercial	Destratification Fans	Lodging/Hospitality	New	N_LG_Destra	0.03	0.62	0.06	0	0	0	Fail RIM
Commercial	Destratification Fans	Miscellaneous	New	N_MS_Destra	0.05	0.62	0.09	0	0	0	Fail RIM
Commercial	Destratification Fans	Offices	New	N_OF_Destra	0.01	0.62	0.02	0	0	0	Fail RIM
Commercial	Destratification Fans	Restaurants	New	N_RS_Destra	0.09	0.62	0.15	0	0	0	Fail RIM
Commercial	Destratification Fans	Retail	New	N_RT_Destra	0.11	0.62	0.18	0	0	0	Fail RIM
Commercial	Destratification Fans	Schools K-12	New	N_SC_Destra	0.35	0.62	0.57	0	0	0	Fail RIM
Commercial	Destratification Fans	Warehouse	New	N_WR_Destr	0.04	0.62	0.06	0	0	0	Fail RIM
Commercial	Duct Insulation	Assembly	Existing	E_AS_Duct I	0.08	1.42	0.06	0	0	0	Fail PCT
Commercial	Duct Insulation	College and University	Existing	E_CU_Duct I	0.13	1.42	0.09	0	0	0	Fail PCT
Commercial	Duct Insulation	Grocery	Existing	E_GR_Duct I	0.82	1.42	0.58	0	0	0	Fail PCT
Commercial	Duct Insulation	Healthcare	Existing	E_HC_Duct I	0.34	1.42	0.24	0	0	0	Fail PCT
Commercial	Duct Insulation	Hospitals	Existing	E_HS_Duct I	0.34	1.42	0.24	0	0	0	Fail PCT
Commercial	Duct Insulation	Institutional	Existing	E_IN_Duct I	0.38	1.42	0.27	0	0	0	Fail PCT
Commercial	Duct Insulation	Lodging/Hospitality	Existing	E_LG_Duct I	0.19	1.42	0.13	0	0	0	Fail PCT
Commercial	Duct Insulation	Miscellaneous	Existing	E_MS_Duct I	0.26	1.42	0.18	0	0	0	Fail PCT
Commercial	Duct Insulation	Offices	Existing	E_OF_Duct I	0.35	1.42	0.24	0	0	0	Fail PCT
Commercial	Duct Insulation	Restaurants	Existing	E_RS_Duct I	0.79	1.42	0.56	0	0	0	Fail PCT
Commercial	Duct Insulation	Retail	Existing	E_RT_Duct I	0.15	1.42	0.11	0	0	0	Fail PCT
Commercial	Duct Insulation	Schools K-12	Existing	E_SC_Duct I	0.13	1.42	0.09	0	0	0	Fail PCT
Commercial	Duct Insulation	Warehouse	Existing	E_WR_Duct	0.04	1.42	0.03	0	0	0	Fail PCT
Commercial	Duct Insulation	Assembly	New	N_AS_Duct I	0.08	1.42	0.06	0	0	0	Fail PCT
Commercial	Duct Insulation	College and University	New	N_CU_Duct I	0.13	1.42	0.09	0	0	0	Fail PCT
Commercial	Duct Insulation	Grocery	New	N_GR_Duct I	0.82	1.42	0.58	0	0	0	Fail PCT
Commercial	Duct Insulation	Healthcare	New	N_HC_Duct I	0.34	1.42	0.24	0	0	0	Fail PCT
Commercial	Duct Insulation	Hospitals	New	N_HS_Duct I	0.34	1.42	0.24	0	0	0	Fail PCT
Commercial	Duct Insulation	Institutional	New	N_IN_Duct I	0.38	1.42	0.27	0	0	0	Fail PCT
Commercial	Duct Insulation	Lodging/Hospitality	New	N_LG_Duct I	0.19	1.42	0.13	0	0	0	Fail PCT
Commercial	Duct Insulation	Miscellaneous	New	N_MS_Duct I	0.26	1.42	0.18	0	0	0	Fail PCT
Commercial	Duct Insulation	Offices	New	N_OF_Duct I	0.35	1.42	0.24	0	0	0	Fail PCT
Commercial	Duct Insulation	Restaurants	New	N_RS_Duct I	0.79	1.42	0.56	0	0	0	Fail PCT
Commercial	Duct Insulation	Retail	New	N_RT_Duct I	0.15	1.42	0.11	0	0	0	Fail PCT
Commercial	Duct Insulation	Schools K-12	New	N_SC_Duct I	0.13	1.42	0.09	0	0	0	Fail PCT
Commercial	Duct Insulation	Warehouse	New	N_WR_Duct	0.04	1.42	0.03	0	0	0	Fail PCT
Commercial	Duct Sealing Repair	Grocery	Existing	E_GR_Duct S	48.67	1.64	29.68	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Healthcare	Existing	E_HC_Duct S	19.89	1.64	12.13	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Hospitals	Existing	E_HS_Duct S	19.89	1.64	12.13	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Institutional	Existing	E_IN_Duct Sa	22.43	1.64	13.68	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Lodging/Hospitality	Existing	E_LG_Duct S	11.23	1.64	6.85	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Miscellaneous	Existing	E_MS_Duct S	15.28	1.64	9.32	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Offices	Existing	E_OF_Duct S	20.53	1.64	12.52	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Restaurants	Existing	E_RS_Duct S	47.04	1.64	28.69	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Retail	Existing	E_RT_Duct S	48.67	1.64	29.68	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Schools K-12	Existing	E_SC_Duct S	19.89	1.64	12.13	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Warehouse	New	N_GR_Duct S	48.67	1.64	29.68	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Grocery	New	N_HC_Duct S	19.89	1.64	12.13	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Healthcare	New	N_HS_Duct S	19.89	1.64	12.13	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Hospitals	New	N_IN_Duct Sa	22.43	1.64	13.68	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Institutional	New	N_LG_Duct S	11.23	1.64	6.85	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Lodging/Hospitality	New	N_MS_Duct S	15.28	1.64	9.32	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Miscellaneous	New	N_OF_Duct S	20.53	1.64	12.52	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Offices	New	N_RS_Duct S	47.04	1.64	28.69	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Restaurants	New	N_RT_Duct S	48.67	1.64	29.68	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Retail	New	N_SC_Duct S	19.89	1.64	12.13	0	0	0	Fail 2-year Threshold
Commercial	Duct Sealing Repair	Schools K-12	New	N_WR_Duct S	48.67	1.64	29.68	0	0	0	Fail 2-year Threshold
Commercial	ECM Motors on Furnaces	Assembly	Existing	E_AS_ECM	0.58	0.26	2.19	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	College and University	Existing	E_CU_ECM	1.22	0.56	2.19	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Grocery	Existing	E_GR_ECM	1.82	0.48	3.76	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Healthcare	Existing	E_HC_ECM	0.90	0.26	3.43	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Hospitals	Existing	E_HS_ECM	2.18	0.56	3.90	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Institutional	Existing	E_IN_ECM	0.50	0.26	1.91	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Lodging/Hospitality	Existing	E_LG_ECM	1.12	0.48	2.31	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Miscellaneous	Existing	E_MS_ECM	0.32	0.26	1.21	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Offices	Existing	E_OF_ECM	0.34	0.26	1.28	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Restaurants	Existing	E_RS_ECM	3.90	0.48	8.07	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Retail	Existing	E_RT_ECM	2.45	0.48	5.06	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Schools K-12	Existing	E_SC_ECM	1.23	0.26	4.66	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Warehouse	Existing	E_WR_ECM	0.32	0.26	1.21	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Assembly	New	N_AS_ECM	0.58	0.26	2.19	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	College and University	New	N_CU_ECM	1.22	0.56	2.19	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Grocery	New	N_GR_ECM	1.82	0.48	3.76	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Healthcare	New	N_HC_ECM	0.90	0.26	3.43	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Hospitals	New	N_HS_ECM	2.18	0.56	3.90	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Institutional	New	N_IN_ECM	0.50	0.26	1.91	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Lodging/Hospitality	New	N_LG_ECM	1.12	0.48	2.31	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Miscellaneous	New	N_MS_ECM	0.32	0.26	1.21	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Offices	New	N_OF_ECM	0.34	0.26	1.28	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Restaurants	New	N_RS_ECM	3.90	0.48	8.07	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Retail	New	N_RT_ECM	2.45	0.48	5.06	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Schools K-12	New	N_SC_ECM	1.23	0.26	4.66	0	0	0	Fail RIM
Commercial	ECM Motors on Furnaces	Warehouse	New	N_WR_ECM	0.32	0.26	1.21	0	0	0	Fail RIM
Commercial	Energy Recovery Ventilation System (ERV)	Assembly	Existing	E_AS_Energ	0.29	4.05	0.07	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	College and University	Existing	E_CU_Energ	0.24	4.05	0.06	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Grocery	Existing	E_GR_Energ	1.54	4.05	0.38	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Healthcare	Existing	E_HC_Energ	0.63	4.05	0.16	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Hospitals	Existing	E_HS_Energ	0.63	4.05	0.16	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Institutional	Existing	E_IN_Energ	0.71	4.05	0.18	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Lodging/Hospitality	Existing	E_LG_Energ	0.36	4.05	0.09	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Miscellaneous	Existing	E_MS_Energ	0.48	4.05	0.12	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Offices	Existing	E_OF_Energ	0.40	4.05	0.10	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Restaurants	Existing	E_RS_Energ	1.63	4.05	0.40	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Retail	Existing	E_RT_Energ	0.36	4.05	0.09	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Schools K-12	Existing	E_SC_Energ	0.24	4.05	0.06	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Warehouse	Existing	E_WR_Energ	0.08	4.05	0.02	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Assembly	New	N_AS_Energ	0.29	4.05	0.07	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	College and University	New	N_CU_Energ	0.24	4.05	0.06	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Grocery	New	N_GR_Energ	1.54	4.05	0.38	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Healthcare	New	N_HC_Energ	0.63	4.05	0.16	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Hospitals	New	N_HS_Energ	0.63	4.05	0.16	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Institutional	New	N_IN_Energ	0.71	4.05	0.18	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Lodging/Hospitality	New	N_LG_Energ	0.36	4.05	0.09	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Miscellaneous	New	N_MS_Energ	0.48	4.05	0.12	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Offices	New	N_OF_Energ	0.40	4.05	0.10	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Restaurants	New	N_RS_Energ	1.63	4.05	0.40	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Retail	New	N_RT_Energ	0.36	4.05	0.09	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Schools K-12	New	N_SC_Energ	0.24	4.05	0.06	0	0	0	Fail PCT
Commercial	Energy Recovery Ventilation System (ERV)	Warehouse	New	N_WR_Energ	0.08	4.05	0.02	0	0	0	Fail PCT
Commercial	Facility Commissioning	Assembly	Existing	E_AS_Facili	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Facility Commissioning	College and University	Existing	E_CU_Facili	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Facility Commissioning	Grocery	Existing	E_GR_Facili	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Facility Commissioning	Healthcare	Existing	E_HC_Facili	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Facility Commissioning	Hospitals	Existing	E_HS_Facili	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Facility Commissioning	Institutional	Existing	E_IN_Facilit	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Facility Commissioning	Lodging/Hospitality	Existing	E_LG_Facili	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Facility Commissioning	Miscellaneous	Existing	E_MS_Facili	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Facility Commissioning	Offices	Existing	E_OF_Facili	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Facility Commissioning	Restaurants	Existing	E_RS_Facili	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Facility Commissioning	Retail	Existing	E_RT_Facili	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Facility Commissioning	Schools K-12	Existing	E_SC_Facili	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Facility Commissioning	Warehouse	Existing	E_WR_Facili	0.00	0.00	0.00	0	0	0	Fail RIM

Commercial	Programmable Thermostat	Institutional	New	N_IN_Progra	0.74	0.30	2.42	0	0	0	Fail TRC
Commercial	Programmable Thermostat	Miscellaneous	New	N_MS_Progr	0.52	0.30	1.70	0	0	0	Fail TRC
Commercial	Programmable Thermostat	Offices	New	N_OF_Progra	0.69	0.30	2.26	0	0	0	Fail TRC
Commercial	Programmable Thermostat	Retail	New	N_RT_Progra	0.92	0.99	0.93	0	0	0	Fail TRC
Commercial	Programmable Thermostat	Schools K-12	New	N_SC_Progra	0.25	0.30	0.83	0	0	0	Fail TRC
Commercial	Programmable Thermostat	Warehouse	New	N_WR_Progr	0.08	0.30	0.27	0	0	0	Fail TRC
Commercial	Roof Insulation	Assembly	Existing	E_AS_Roof	0.65	1.22	0.53	0	0	0	Fail TRC
Commercial	Roof Insulation	College and University	Existing	E_CU_Roof	0.64	1.21	0.53	0	0	0	Fail TRC
Commercial	Roof Insulation	Grocery	Existing	E_GR_Roof	0.66	1.25	0.53	0	0	0	Fail TRC
Commercial	Roof Insulation	Healthcare	Existing	E_HC_Roof	0.65	1.22	0.53	0	0	0	Fail TRC
Commercial	Roof Insulation	Hospitals	Existing	E_HS_Roof	0.64	1.21	0.53	0	0	0	Fail TRC
Commercial	Roof Insulation	Institutional	Existing	E_IN_Roof	0.65	1.22	0.53	0	0	0	Fail TRC
Commercial	Roof Insulation	Lodging/Hospitality	Existing	E_LG_Roof	0.64	1.21	0.53	0	0	0	Fail TRC
Commercial	Roof Insulation	Miscellaneous	Existing	E_MS_Roof	0.65	1.22	0.53	0	0	0	Fail TRC
Commercial	Roof Insulation	Offices	Existing	E_OF_Roof	0.65	1.22	0.53	0	0	0	Fail TRC
Commercial	Roof Insulation	Restaurants	Existing	E_RS_Roof	0.66	1.25	0.53	0	0	0	Fail TRC
Commercial	Roof Insulation	Retail	Existing	E_RT_Roof	0.66	1.25	0.53	0	0	0	Fail TRC
Commercial	Roof Insulation	Schools K-12	Existing	E_SC_Roof	0.65	1.22	0.53	0	0	0	Fail TRC
Commercial	Roof Insulation	Warehouse	Existing	E_WR_Roof	0.38	0.71	0.53	0	0	0	Fail TRC
Commercial	Roof Insulation	Assembly	New	N_AS_Roof	0.32	1.22	0.26	0	0	0	Fail TRC
Commercial	Roof Insulation	College and University	New	N_CU_Roof	0.32	1.21	0.26	0	0	0	Fail TRC
Commercial	Roof Insulation	Grocery	New	N_GR_Roof	0.33	1.25	0.26	0	0	0	Fail TRC
Commercial	Roof Insulation	Healthcare	New	N_HC_Roof	0.32	1.22	0.26	0	0	0	Fail TRC
Commercial	Roof Insulation	Hospitals	New	N_HS_Roof	0.32	1.21	0.26	0	0	0	Fail TRC
Commercial	Roof Insulation	Institutional	New	N_IN_Roof	0.32	1.22	0.26	0	0	0	Fail TRC
Commercial	Roof Insulation	Lodging/Hospitality	New	N_LG_Roof	0.32	1.21	0.26	0	0	0	Fail TRC
Commercial	Roof Insulation	Miscellaneous	New	N_MS_Roof	0.32	1.22	0.26	0	0	0	Fail TRC
Commercial	Roof Insulation	Offices	New	N_OF_Roof	0.32	1.22	0.26	0	0	0	Fail TRC
Commercial	Roof Insulation	Restaurants	New	N_RS_Roof	0.33	1.25	0.26	0	0	0	Fail TRC
Commercial	Roof Insulation	Retail	New	N_RT_Roof	0.33	1.25	0.26	0	0	0	Fail TRC
Commercial	Roof Insulation	Schools K-12	New	N_SC_Roof	0.32	1.22	0.26	0	0	0	Fail TRC
Commercial	Roof Insulation	Warehouse	New	N_WR_Roof	0.19	0.71	0.26	0	0	0	Fail TRC
Commercial	Smart Thermostat	Assembly	Existing	E_AS_Smart	0.29	0.30	0.94	0	0	0	Fail TRC
Commercial	Smart Thermostat	College and University	Existing	E_CU_Smart	0.65	0.44	1.47	0	0	0	Fail TRC
Commercial	Smart Thermostat	Grocery	Existing	E_GR_Smart	8.94	0.99	9.05	0	0	0	Fail 2-year Threshold
Commercial	Smart Thermostat	Miscellaneous	Existing	E_MS_Smart	0.92	0.30	3.01	0	0	0	Fail TRC
Commercial	Smart Thermostat	Restaurants	Existing	E_RS_Smart	7.45	0.99	7.54	0	0	0	Fail 2-year Threshold
Commercial	Smart Thermostat	Schools K-12	Existing	E_SC_Smart	0.45	0.30	1.47	0	0	0	Fail TRC
Commercial	Smart Thermostat	Warehouse	Existing	E_WR_Smart	0.14	0.30	0.47	0	0	0	Fail TRC
Commercial	Smart Thermostat	Assembly	New	N_AS_Smart	0.29	0.30	0.94	0	0	0	Fail TRC
Commercial	Smart Thermostat	College and University	New	N_CU_Smart	0.65	0.44	1.47	0	0	0	Fail TRC
Commercial	Smart Thermostat	Grocery	New	N_GR_Smart	8.94	0.99	9.05	0	0	0	Fail 2-year Threshold
Commercial	Smart Thermostat	Miscellaneous	New	N_MS_Smart	0.92	0.30	3.01	0	0	0	Fail TRC
Commercial	Smart Thermostat	Restaurants	New	N_RS_Smart	7.45	0.99	7.54	0	0	0	Fail 2-year Threshold
Commercial	Smart Thermostat	Schools K-12	New	N_SC_Smart	0.45	0.30	1.47	0	0	0	Fail TRC
Commercial	Smart Thermostat	Warehouse	New	N_WR_Smart	0.14	0.30	0.47	0	0	0	Fail TRC
Commercial	Wall Insulation	Assembly	New	N_AS_Wall I	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Wall Insulation	College and University	New	N_CU_Wall	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Wall Insulation	Grocery	New	N_GR_Wall	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Wall Insulation	Healthcare	New	N_HC_Wall	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Wall Insulation	Hospitals	New	N_HS_Wall	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Wall Insulation	Institutional	New	N_IN_Wall	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Wall Insulation	Lodging/Hospitality	New	N_LG_Wall	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Wall Insulation	Miscellaneous	New	N_MS_Wall	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Wall Insulation	Offices	New	N_OF_Wall	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Wall Insulation	Restaurants	New	N_RS_Wall	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Wall Insulation	Retail	New	N_RT_Wall	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Wall Insulation	Schools K-12	New	N_SC_Wall	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Wall Insulation	Warehouse	New	N_WR_Wall	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Assembly	Existing	E_AS_Ware	0.21	0.70	0.30	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	College and University	Existing	E_CU_Ware	0.10	0.70	0.15	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Grocery	Existing	E_GR_Ware	0.72	0.70	1.02	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Healthcare	Existing	E_HC_Ware	0.20	0.70	0.28	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Hospitals	Existing	E_HS_Ware	0.10	0.70	0.15	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Institutional	Existing	E_IN_Ware	0.64	0.70	0.91	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Lodging/Hospitality	Existing	E_LG_Ware	0.48	0.70	0.69	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Miscellaneous	Existing	E_MS_Ware	0.13	0.70	0.18	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Offices	Existing	E_OF_Ware	0.93	0.70	1.33	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Restaurants	Existing	E_RS_Ware	0.69	0.70	0.99	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Retail	Existing	E_RT_Ware	0.30	0.70	0.43	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Schools K-12	Existing	E_SC_Ware	0.07	0.70	0.10	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Warehouse	Existing	E_WR_Ware	0.19	0.70	0.27	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Assembly	New	N_AS_Ware	0.21	0.70	0.29	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	College and University	New	N_CU_Ware	0.10	0.70	0.14	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Grocery	New	N_GR_Ware	0.70	0.70	1.00	0	0	0	Fail TRC
Commercial	Warehouse Loading Dock Seals	Healthcare	New	N_HC_Ware	0.20

Commercial	Facility Commissioning	Assembly	New	N_AS_Facili	0.15	0.67	0.23	0	0	0	Fail RIM
Commercial	Facility Commissioning	College and University	New	N_CU_Facili	0.21	0.61	0.35	0	0	0	Fail RIM
Commercial	Facility Commissioning	Grocery	New	N_GR_Facili	1.50	0.67	2.25	0	0	0	Fail RIM
Commercial	Facility Commissioning	Healthcare	New	N_HC_Facili	0.61	0.67	0.92	0	0	0	Fail RIM
Commercial	Facility Commissioning	Hospitals	New	N_HS_Facili	0.56	0.61	0.92	0	0	0	Fail RIM
Commercial	Facility Commissioning	Institutional	New	N_IN_Facili	0.69	0.67	1.04	0	0	0	Fail RIM
Commercial	Facility Commissioning	Lodging/Hospitality	New	N_LG_Facili	0.35	0.67	0.52	0	0	0	Fail RIM
Commercial	Facility Commissioning	Miscellaneous	New	N_MS_Facili	0.47	0.67	0.71	0	0	0	Fail RIM
Commercial	Facility Commissioning	Offices	New	N_OF_Facili	0.63	0.67	0.95	0	0	0	Fail RIM
Commercial	Facility Commissioning	Restaurants	New	N_RS_Facili	1.45	0.67	2.18	0	0	0	Fail RIM
Commercial	Facility Commissioning	Retail	New	N_RT_Facili	0.28	0.67	0.42	0	0	0	Fail RIM
Commercial	Facility Commissioning	Schools K-12	New	N_SC_Facili	0.23	0.67	0.35	0	0	0	Fail RIM
Commercial	Facility Commissioning	Warehouse	New	N_WR_Facili	0.07	0.67	0.11	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Assembly	Existing	E_AS_Facili	1.03	0.73	1.41	0	0	0	Fail RIM
Commercial	Facility Energy Management System	College and University	Existing	E_CU_Facili	1.28	0.60	2.14	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Grocery	Existing	E_GR_Facili	11.62	0.84	13.88	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Healthcare	Existing	E_HC_Facili	4.14	0.73	5.67	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Hospitals	Existing	E_HS_Facili	3.41	0.60	5.67	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Institutional	Existing	E_IN_Facili	4.67	0.73	6.40	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Lodging/Hospitality	Existing	E_LG_Facili	2.68	0.84	3.20	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Miscellaneous	Existing	E_MS_Facili	3.18	0.73	4.36	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Offices	Existing	E_OF_Facili	4.27	0.73	5.85	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Restaurants	Existing	E_RS_Facili	11.23	0.84	13.42	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Retail	Existing	E_RT_Facili	2.18	0.84	2.60	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Schools K-12	Existing	E_SC_Facili	1.56	0.73	2.14	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Warehouse	Existing	E_WR_Facili	0.50	0.73	0.69	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Assembly	New	N_AS_Facili	1.03	0.73	1.41	0	0	0	Fail RIM
Commercial	Facility Energy Management System	College and University	New	N_CU_Facili	1.28	0.60	2.14	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Grocery	New	N_GR_Facili	11.62	0.84	13.88	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Healthcare	New	N_HC_Facili	4.14	0.73	5.67	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Hospitals	New	N_HS_Facili	3.41	0.60	5.67	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Institutional	New	N_IN_Facili	4.67	0.73	6.40	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Lodging/Hospitality	New	N_LG_Facili	2.68	0.84	3.20	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Miscellaneous	New	N_MS_Facili	3.18	0.73	4.36	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Offices	New	N_OF_Facili	4.27	0.73	5.85	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Restaurants	New	N_RS_Facili	11.23	0.84	13.42	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Retail	New	N_RT_Facili	2.18	0.84	2.60	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Schools K-12	New	N_SC_Facili	1.56	0.73	2.14	0	0	0	Fail RIM
Commercial	Facility Energy Management System	Warehouse	New	N_WR_Facili	0.50	0.73	0.69	0	0	0	Fail RIM
Commercial	Floor Insulation	Assembly	Existing	E_AS_Floor	0.08	1.22	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	College and University	Existing	E_CU_Floor	0.08	1.21	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Grocery	Existing	E_GR_Floor	0.08	1.25	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Healthcare	Existing	E_HC_Floor	0.08	1.22	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Hospitals	Existing	E_HS_Floor	0.08	1.21	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Institutional	Existing	E_IN_Floor	0.08	1.22	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Lodging/Hospitality	Existing	E_LG_Floor	0.08	1.21	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Miscellaneous	Existing	E_MS_Floor	0.08	1.22	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Offices	Existing	E_OF_Floor	0.08	1.22	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Restaurants	Existing	E_RS_Floor	0.08	1.25	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Retail	Existing	E_RT_Floor	0.08	1.25	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Schools K-12	Existing	E_SC_Floor	0.08	1.22	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Warehouse	Existing	E_WR_Floor	0.05	0.71	0.07	0	0	0	Fail RIM
Commercial	Floor Insulation	Assembly	New	N_AS_Floor	0.08	1.22	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	College and University	New	N_CU_Floor	0.08	1.21	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Grocery	New	N_GR_Floor	0.08	1.25	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Healthcare	New	N_HC_Floor	0.08	1.22	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Hospitals	New	N_HS_Floor	0.08	1.21	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Institutional	New	N_IN_Floor	0.08	1.22	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Lodging/Hospitality	New	N_LG_Floor	0.08	1.21	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Miscellaneous	New	N_MS_Floor	0.08	1.22	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Offices	New	N_OF_Floor	0.08	1.22	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Restaurants	New	N_RS_Floor	0.08	1.25	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Retail	New	N_RT_Floor	0.08	1.25	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Schools K-12	New	N_SC_Floor	0.08	1.22	0.07	0	0	0	Fail PCT
Commercial	Floor Insulation	Warehouse	New	N_WR_Floor	0.05	0.71	0.07	0	0	0	Fail RIM
Commercial	Green Roof	Assembly	Existing	E_AS_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	College and University	Existing	E_CU_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Grocery	Existing	E_GR_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Healthcare	Existing	E_HC_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Hospitals	Existing	E_HS_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Institutional	Existing	E_IN_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Lodging/Hospitality	Existing	E_LG_Green	0.02	1.47	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Miscellaneous	Existing	E_MS_Green	0.01	0.56	0.01	0	0	0	Fail RIM
Commercial	Green Roof	Offices	Existing	E_OF_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Restaurants	Existing	E_RS_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Retail	Existing	E_RT_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Schools K-12	Existing	E_SC_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Warehouse	Existing	E_WR_Green	0.01	0.56	0.01	0	0	0	Fail RIM
Commercial	Green Roof	Assembly	New	N_AS_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	College and University	New	N_CU_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Grocery	New	N_GR_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Healthcare	New	N_HC_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Hospitals	New	N_HS_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Institutional	New	N_IN_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Lodging/Hospitality	New	N_LG_Green	0.02	1.47	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Miscellaneous	New	N_MS_Green	0.01	0.56	0.01	0	0	0	Fail RIM
Commercial	Green Roof	Offices	New	N_OF_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Restaurants	New	N_RS_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Retail	New	N_RT_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Schools K-12	New	N_SC_Green	0.01	1.18	0.01	0	0	0	Fail PCT
Commercial	Green Roof	Warehouse	New	N_WR_Green	0.01	0.56	0.01	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Assembly	Existing	E_AS_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	College and University	Existing	E_CU_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Grocery	Existing	E_GR_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Healthcare	Existing	E_HC_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Hospitals	Existing	E_HS_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Institutional	Existing	E_IN_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Lodging/Hospitality	Existing	E_LG_Hotel	0.74	0.31	2.39	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Miscellaneous	Existing	E_MS_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Offices	Existing	E_OF_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Restaurants	Existing	E_RS_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Retail	Existing	E_RT_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Schools K-12	Existing	E_SC_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Warehouse	Existing	E_WR_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Assembly	New	N_AS_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	College and University	New	N_CU_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Grocery	New	N_GR_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Healthcare	New	N_HC_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Hospitals	New	N_HS_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Institutional	New	N_IN_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Lodging/Hospitality	New	N_LG_Hotel	0.74	0.31	2.39	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Miscellaneous	New	N_MS_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Offices	New	N_OF_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Restaurants	New	N_RS_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Retail	New	N_RT_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Schools K-12	New	N_SC_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Hotel Card Energy Control Systems	Warehouse	New	N_WR_Hotel	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	HVAC tune-up	Assembly	Existing	E_AS_HVAC	1.20	0.95	1.26	0	0	0	Fail RIM
Commercial	HVAC tune-up	College and University	Existing	E_CU_HVAC	0.92	0.66	1.40	0	0	0	Fail RIM
Commercial	HVAC tune-up	Grocery	Existing	E_GR_HVAC	0.67	0.95	0.70	0	0	0	Fail RIM
Commercial	HVAC tune-up	Healthcare	Existing	E_HC_HVAC	2.62	0.95	2.75	0	0	0	Fail RIM
Commercial	HVAC tune-up	Hospitals	Existing	E_HS_HVAC	1.71	0.66	2.60	0	0	0	Fail RIM
Commercial	HVAC tune-up	Institutional	Existing	E_IN_HVAC	0.65	0.95	0.68	0	0	0	Fail RIM
Commercial	HVAC tune-up	Lodging/Hospitality	Existing	E_LG_HVAC	1.99	0.95	2.09	0	0	0	Fail RIM
Commercial	HVAC tune-up	Miscellaneous	Existing	E_MS_HVAC	0.59	0.84	0.71	0	0	0	Fail RIM
Commercial	HVAC tune-up	Offices	Existing	E_OF_HVAC	1.19	0.84	1.42	0	0	0	Fail RIM
Commercial	HVAC tune-up	Restaurants	Existing	E_RS_HVAC	1.95	0.95	2.05	0	0	0	Fail RIM
Commercial	HVAC tune-up	Retail	Existing	E_RT_HVAC	1.53	0.95	1.60	0	0	0	Fail RIM
Commercial	HVAC tune-up	Schools K-12	Existing	E_SC_HVAC	1.33	0.95	1.39	0	0	0	Fail RIM
Commercial	HVAC tune-up	Warehouse	Existing	E_WR_HVAC	0.29	0.95	0.31	0	0	0	Fail RIM
Commercial	HVAC tune-up	Assembly	New	N_AS_HVAC	1.20	0.95	1.26	0	0	0	Fail RIM
Commercial	HVAC tune-up	College and University	New	N_CU_HVAC	0.92	0.66	1.40	0	0	0	Fail RIM
Commercial	HVAC tune-up	Grocery	New	N_GR_HVAC	0.67	0.95	0.70	0	0	0	Fail RIM
Commercial	HVAC tune-up	Healthcare	New	N_HC_HVAC	2.62	0.95	2.75	0	0	0	Fail RIM
Commercial	HVAC tune-up	Hospitals	New	N_HS_HVAC	1.71	0.66	2.60	0	0	0	Fail RIM
Commercial	HVAC tune-up	Institutional	New	N_IN_HVAC	0.65	0.95	0.68	0	0	0	Fail RIM
Commercial	HVAC tune-up	Lodging/Hospitality	New	N_LG_HVAC	1.99	0.95	2.09	0	0	0	Fail RIM
Commercial	HVAC tune-up	Miscellaneous	New	N_MS_HVAC	0.59	0.84	0.71	0	0	0	Fail RIM
Commercial	HVAC tune-up	Offices	New	N_OF_HVAC	1.19	0.84	1.42	0	0	0	Fail RIM
Commercial	HVAC tune-up	Restaurants	New	N_RS_HVAC	1.95	0.95	2.05	0	0	0	Fail RIM
Commercial	HVAC tune-up	Retail	New	N_RT_HVAC	1.53	0.95	1.60	0	0	0	Fail RIM
Commercial	HVAC tune-up	Schools K-12	New	N_SC_HVAC	1.33	0.95	1.39	0	0	0	Fail RIM
Commercial	HVAC tune-up	Warehouse	New	N_WR_HVAC	0.29	0.95	0.31	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Assembly	Existing	E_AS_HVAC	0.79	0.84	0.95	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	College and University	Existing	E_CU_HVAC	0.88	0.84	1.05	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Grocery	Existing	E_GR_HVAC	0.44	0.84	0.52	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Healthcare	Existing	E_HC_HVAC	1.72	0.84	2.06	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Hospitals	Existing	E_HS_HVAC	1.63	0.84	1.95	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Institutional	Existing	E_IN_HVAC	0.43	0.84	0.51	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Lodging/Hospitality	Existing	E_LG_HVAC	1.31	0.84	1.56	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Miscellaneous	Existing	E_MS_HVAC	0.44	0.84	0.53	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Offices	Existing	E_OF_HVAC	0.89	0.84	1.07	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Restaurants	Existing	E_RS_HVAC	1.28	0.84	1.54	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Retail	Existing	E_RT_HVAC	1.01	0.84	1.20	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Schools K-12	Existing	E_SC_HVAC	0.87	0.84	1.05	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Warehouse	Existing	E_WR_HVAC	0.19	0.84	0.23	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Assembly	New	N_AS_HVAC	0.79	0.84	0.95	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	College and University	New	N_CU_HVAC	0.88	0.84	1.05	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Grocery	New	N_GR_HVAC	0.44	0.84	0.52	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Healthcare	New	N_HC_HVAC	1.72	0.84	2.06	0	0	0	Fail RIM
Commercial	Wateside Economizer	Warehouse	New	N_WR_Wate	0.01	1.19	0.01	0	0	0	Fail TRC
Commercial	Window Sun Protection	Assembly	Existing	E_AS_Windo	0.22	0.97	0.23	0	0	0	Fail TRC
Commercial	Window Sun Protection	College and University	Existing	E_CU_Windo	0.22	0.97	0.23	0	0	0	Fail TRC
Commercial	Window Sun Protection	Grocery	Existing	E_GR_Windo	0.22	0.97	0.23	0	0	0	Fail TRC
Commercial	Window Sun Protection	Healthcare	Existing	E_HC_Windo	0.22	0.97	0.23	0	0	0	Fail TRC
Commercial	Window Sun Protection	Hospitals	Existing	E_HS_Windo	0.22	0.97	0.23	0	0	0	Fail TRC
Commercial	Window Sun Protection	Institutional	Existing	E_IN_Windo	0.22	0.97	0.23	0	0	0	Fail TRC
Commercial	Window Sun Protection	Lodging/Hospitality	Existing	E_LG_Windo	0.24	1.08	0.23	0	0	0	Fail TRC
Commercial	Window Sun Protection	Miscellaneous	Existing	E_MS_Windo	0.28	1.22	0.23	0	0	0	Fail TRC
Commercial	Window Sun Protection	Offices	Existing	E_OF_Windo	0.22	0.97	0.23	0	0	0	Fail TRC
Commercial	Window Sun Protection	Restaurants	Existing	E_RS_Windo	0.22	0.97	0.23	0	0	0	Fail TRC
Commercial	Window Sun Protection	Retail	Existing	E_RT_Windo	0.22	0.97	0.23	0	0	0	Fail TRC
Commercial	Window Sun Protection	Schools K-12	Existing	E_SC_Windo	0.22	0.97	0.23	0	0	0	Fail TRC
Commercial	Window Sun Protection	Warehouse	Existing	E_WR_Windo	0.28	1.22	0.23	0	0	0	Fail TRC
Commercial	Window Sun Protection	Assembly	New	N_AS_Windo	0.13	0.97	0.14	0	0	0	Fail TRC
Commercial	Window Sun Protection	College and University	New	N_CU_Windo	0.13	0.97	0.14	0	0	0	Fail TRC
Commercial	Window Sun Protection	Grocery	New	N_GR_Windo	0.13	0.97	0.14	0	0	0	Fail TRC
Commercial	Window Sun Protection	Healthcare	New	N_HC_Windo	0.13	0.97	0.14	0	0	0	Fail TRC
Commercial	Window Sun Protection	Hospitals	New	N_HS_Windo	0.13	0.97	0.14	0	0	0	Fail TRC
Commercial	Window Sun Protection	Institutional	New	N_IN_Windo	0.13	0.97	0.14	0	0	0	Fail TRC
Commercial	Window Sun Protection	Lodging/Hospitality	New	N_LG_Windo	0.15	1.08	0.14	0	0	0	Fail TRC
Commercial	Window Sun Protection	Miscellaneous	New	N_MS_Windo	0.17	1.22	0.14	0	0	0	Fail TRC
Commercial	Window Sun Protection	Offices	New	N_OF_Windo	0.13	0.97	0.14	0	0	0	Fail TRC
Commercial	Window Sun Protection	Restaurants	New	N_RS_Windo	0.13	0.97	0.14	0	0	0	Fail TRC
Commercial	Window Sun Protection	Retail	New	N_RT_Windo	0.13	0.97	0.14	0	0	0	Fail TRC
Commercial	Window Sun Protection	Schools K-12	New	N_SC_Windo	0.13	0.97	0.14	0	0	0	Fail TRC
Commercial	Window Sun Protection	Warehouse	New	N_WR_Windo	0.17	1.22	0.14	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Assembly	Existing	E_AS_Bi-Lev	0.21	0.27	0.77	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	College and University	Existing	E_CU_Bi-Lev	0.33	0.27	1.19	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Grocery	Existing	E_GR_Bi-Lev	0.43	0.29	1.49	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Healthcare	Existing	E_HC_Bi-Lev	0.37	0.27	1.35	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Hospitals	Existing	E_HS_Bi-Lev	0.50	0.27	1.83	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Institutional	Existing	E_IN_Bi-Lev	0.24	0.27	0.89	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Lodging/Hospitality	Existing	E_LG_Bi-Lev	0.29	0.29	1.01	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Miscellaneous	Existing	E_MS_Bi-Lev	0.33	0.27	1.19	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Offices	Existing	E_OF_Bi-Lev	0.24	0.27	0.88	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Restaurants	Existing	E_RS_Bi-Lev	0.26	0.29	0.90	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Retail	Existing	E_RT_Bi-Lev	0.39	0.29	1.34	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Schools K-12	Existing	E_SC_Bi-Lev	0.18	0.27	0.64	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Warehouse	Existing	E_WR_Bi-Lev	0.28	0.27	1.03	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Assembly	New	N_AS_Bi-Lev	0.21	0.27	0.77	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	College and University	New	N_CU_Bi-Lev	0.33	0.27	1.19	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Grocery	New	N_GR_Bi-Lev	0.43	0.29	1.49	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Healthcare	New	N_HC_Bi-Lev	0.37	0.27	1.35	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Hospitals	New	N_HS_Bi-Lev	0.50	0.27	1.83	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Institutional	New	N_IN_Bi-Lev	0.24	0.27	0.89	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Lodging/Hospitality	New	N_LG_Bi-Lev	0.29	0.29	1.01	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Miscellaneous	New	N_MS_Bi-Lev	0.33	0.27	1.19	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Offices	New	N_OF_Bi-Lev	0.24	0.27	0.88	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Restaurants	New	N_RS_Bi-Lev	0.26	0.29	0.90	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Retail	New	N_RT_Bi-Lev	0.39	0.29	1.34	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Schools K-12	New	N_SC_Bi-Lev	0.18	0.27	0.64	0	0	0	Fail TRC
Commercial	Bi-Level Lighting Control (Interior)	Warehouse	New	N_WR_Bi-Lev	0.28	0.27	1.03	0	0	0	Fail TRC
Commercial	Interior Lighting Controls	Assembly	Existing	E_AS_Interio	0.45	0.27	1.67	0	0	0	Fail TRC
Commercial	Interior Lighting Controls	College and University	Existing	E_CU_Interio	0.69	0.27	2.56	0	0	0	Fail TRC
Commercial	Interior Lighting Controls	Grocery	Existing	E_GR_Interio	0.87	0.27	3.21	0	0	0	Fail TRC
Commercial	Interior Lighting Controls	Healthcare	Existing	E_H

Commercial	HVAC tune-up_RTU	Hospitals	New	N_HS_HVAC	1.63	0.84	1.95	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Institutional	New	N_IN_HVAC	0.43	0.84	0.51	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Lodging/Hospitality	New	N_LG_HVAC	1.31	0.84	1.56	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Miscellaneous	New	N_MS_HVAC	0.44	0.84	0.53	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Offices	New	N_OF_HVAC	0.89	0.84	1.07	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Restaurants	New	N_RS_HVAC	1.28	0.84	1.54	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Retail	New	N_RT_HVAC	1.01	0.84	1.20	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Schools K-12	New	N_SC_HVAC	0.87	0.84	1.05	0	0	0	Fail RIM
Commercial	HVAC tune-up_RTU	Warehouse	New	N_WR_HVAC	0.19	0.84	0.23	0	0	0	Fail RIM
Commercial	Infiltration Reduction - Air Sealing	Assembly	Existing	E_AS_Infiltra	0.16	1.44	0.11	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	College and University	Existing	E_CU_Infiltra	0.08	1.44	0.05	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Grocery	Existing	E_GR_Infiltra	0.54	1.44	0.37	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Healthcare	Existing	E_HC_Infiltra	0.15	1.44	0.10	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Hospitals	Existing	E_HS_Infiltra	0.08	1.44	0.05	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Institutional	Existing	E_IN_Infiltra	0.48	1.44	0.34	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Lodging/Hospitality	Existing	E_LG_Infiltra	0.36	1.44	0.25	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Miscellaneous	Existing	E_MS_Infiltra	0.10	1.44	0.07	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Offices	Existing	E_OF_Infiltra	0.70	1.44	0.49	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Restaurants	Existing	E_RS_Infiltra	0.52	1.44	0.36	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Retail	Existing	E_RT_Infiltra	0.23	1.44	0.16	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Schools K-12	Existing	E_SC_Infiltra	0.05	1.44	0.04	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Warehouse	Existing	E_WR_Infiltr	0.14	1.44	0.10	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Assembly	New	N_AS_Infiltr	0.16	1.44	0.11	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	College and University	New	N_CU_Infiltr	0.08	1.44	0.05	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Grocery	New	N_GR_Infiltr	0.53	1.44	0.37	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Healthcare	New	N_HC_Infiltr	0.15	1.44	0.10	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Hospitals	New	N_HS_Infiltr	0.08	1.44	0.05	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Institutional	New	N_IN_Infiltra	0.48	1.44	0.33	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Lodging/Hospitality	New	N_LG_Infiltr	0.36	1.44	0.25	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Miscellaneous	New	N_MS_Infiltr	0.10	1.44	0.07	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Offices	New	N_OF_Infiltr	0.69	1.44	0.48	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Restaurants	New	N_RS_Infiltr	0.51	1.44	0.36	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Retail	New	N_RT_Infiltr	0.22	1.44	0.16	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Schools K-12	New	N_SC_Infiltr	0.05	1.44	0.04	0	0	0	Fail PCT
Commercial	Infiltration Reduction - Air Sealing	Warehouse	New	N_WR_Infiltr	0.14	1.44	0.10	0	0	0	Fail PCT
Commercial	Low U-Value Windows	Assembly	New	N_AS_Low U	0.19	1.12	0.17	0	0	0	Fail PCT
Commercial	Low U-Value Windows	College and University	New	N_CU_Low U	0.19	1.12	0.17	0	0	0	Fail PCT
Commercial	Low U-Value Windows	Grocery	New	N_GR_Low U	0.19	1.12	0.17	0	0	0	Fail PCT
Commercial	Low U-Value Windows	Healthcare	New	N_HC_Low U	0.19	1.12	0.17	0	0	0	Fail PCT
Commercial	Low U-Value Windows	Hospitals	New	N_HS_Low U	0.19	1.12	0.17	0	0	0	Fail PCT
Commercial	Low U-Value Windows	Institutional	New	N_IN_Low U	0.19	1.12	0.17	0	0	0	Fail PCT
Commercial	Low U-Value Windows	Lodging/Hospitality	New	N_LG_Low U	0.22	1.27	0.17	0	0	0	Fail PCT
Commercial	Low U-Value Windows	Miscellaneous	New	N_MS_Low U	0.18	1.06	0.17	0	0	0	Fail PCT
Commercial	Low U-Value Windows	Offices	New	N_OF_Low U	0.19	1.12	0.17	0	0	0	Fail PCT
Commercial	Low U-Value Windows	Restaurants	New	N_RS_Low U	0.19	1.12	0.17	0	0	0	Fail PCT
Commercial	Low U-Value Windows	Retail	New	N_RT_Low U	0.19	1.12	0.17	0	0	0	Fail PCT
Commercial	Low U-Value Windows	Schools K-12	New	N_SC_Low U	0.19	1.12	0.17	0	0	0	Fail PCT
Commercial	Low U-Value Windows	Warehouse	New	N_WR_Low	0.18	1.06	0.17	0	0	0	Fail PCT
Commercial	Programmable Thermostat	Assembly	Existing	E_AS_Progra	0.16	0.30	0.53	0	0	0	Fail RIM
Commercial	Programmable Thermostat	College and University	Existing	E_CU_Progra	0.37	0.44	0.83	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Grocery	Existing	E_GR_Progra	5.04	0.99	5.10	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Healthcare	Existing	E_HC_Progra	0.64	0.30	2.09	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Hospitals	Existing	E_HS_Progra	0.97	0.44	2.21	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Institutional	Existing	E_IN_Progra	0.74	0.30	2.42	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Miscellaneous	Existing	E_MS_Progra	0.52	0.30	1.70	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Offices	Existing	E_OF_Progra	0.69	0.30	2.26	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Restaurants	Existing	E_RS_Progra	4.20	0.99	4.25	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Retail	Existing	E_RT_Progra	0.92	0.99	0.93	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Schools K-12	Existing	E_SC_Progra	0.25	0.30	0.83	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Warehouse	Existing	E_WR_Progr	0.08	0.30	0.27	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Assembly	New	N_AS_Progra	0.16	0.30	0.53	0	0	0	Fail RIM
Commercial	Programmable Thermostat	College and University	New	N_CU_Progra	0.37	0.44	0.83	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Grocery	New	N_GR_Progra	5.04	0.99	5.10	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Healthcare	New	N_HC_Progra	0.64	0.30	2.09	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Hospitals	New	N_HS_Progra	0.97	0.44	2.21	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Institutional	New	N_IN_Progra	0.74	0.30	2.42	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Miscellaneous	New	N_MS_Progra	0.52	0.30	1.70	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Offices	New	N_OF_Progra	0.69	0.30	2.26	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Restaurants	New	N_RS_Progra	4.20	0.99	4.25	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Retail	New	N_RT_Progra	0.92	0.99	0.93	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Schools K-12	New	N_SC_Progra	0.25	0.30	0.83	0	0	0	Fail RIM
Commercial	Programmable Thermostat	Warehouse	New	N_WR_Progr	0.08	0.30	0.27	0	0	0	Fail RIM
Commercial	Roof Insulation	Assembly	Existing	E_AS_Roof I	0.65	1.22	0.53	0	0	0	Fail PCT
Commercial	Roof Insulation	College and University	Existing	E_CU_Roof I	0.64	1.21	0.53	0	0	0	Fail PCT
Commercial	Roof Insulation	Grocery	Existing	E_GR_Roof I	0.66	1.25	0.53	0	0	0	Fail PCT
Commercial	Roof Insulation	Healthcare	Existing	E_HC_Roof I	0.65	1.22	0.53	0	0	0	Fail PCT
Commercial	Roof Insulation	Hospitals	Existing	E_HS_Roof I	0.64	1.21	0.53	0	0	0	Fail PCT
Commercial	Roof Insulation	Institutional	Existing	E_IN_Roof I	0.65	1.22	0.53	0	0	0	Fail PCT
Commercial	Roof Insulation	Lodging/Hospitality	Existing	E_LG_Roof I	0.64	1.21	0.53	0	0	0	Fail PCT
Commercial	Roof Insulation	Miscellaneous	Existing	E_MS_Roof I	0.65	1.22	0.53	0	0	0	Fail PCT
Commercial	Roof Insulation	Offices	Existing	E_OF_Roof I	0.65	1.22	0.53	0	0	0	Fail PCT
Commercial	Roof Insulation	Restaurants	Existing	E_RS_Roof I	0.66	1.25	0.53	0	0	0	Fail PCT
Commercial	Roof Insulation	Retail	Existing	E_RT_Roof I	0.66	1.25	0.53	0	0	0	Fail PCT
Commercial	Roof Insulation	Schools K-12	Existing	E_SC_Roof I	0.65	1.22	0.53	0	0	0	Fail PCT
Commercial	Roof Insulation	Warehouse	Existing	E_WR_Roof	0.38	0.71	0.53	0	0	0	Fail RIM
Commercial	Roof Insulation	Assembly	New	N_AS_Roof I	0.32	1.22	0.26	0	0	0	Fail PCT
Commercial	Roof Insulation	College and University	New	N_CU_Roof I	0.32	1.21	0.26	0	0	0	Fail PCT
Commercial	Roof Insulation	Grocery	New	N_GR_Roof I	0.33	1.25	0.26	0	0	0	Fail PCT
Commercial	Roof Insulation	Healthcare	New	N_HC_Roof I	0.32	1.22	0.26	0	0	0	Fail PCT
Commercial	Roof Insulation	Hospitals	New	N_HS_Roof I	0.32	1.21	0.26	0	0	0	Fail PCT
Commercial	Roof Insulation	Institutional	New	N_IN_Roof I	0.32	1.22	0.26	0	0	0	Fail PCT
Commercial	Roof Insulation	Lodging/Hospitality	New	N_LG_Roof I	0.32	1.21	0.26	0	0	0	Fail PCT
Commercial	Roof Insulation	Miscellaneous	New	N_MS_Roof	0.32	1.22	0.26	0	0	0	Fail PCT
Commercial	Roof Insulation	Offices	New	N_OF_Roof I	0.32	1.22	0.26	0	0	0	Fail PCT
Commercial	Roof Insulation	Restaurants	New	N_RS_Roof I	0.33	1.25	0.26	0	0	0	Fail PCT
Commercial	Roof Insulation	Retail	New	N_RT_Roof I	0.33	1.25	0.26	0	0	0	Fail PCT
Commercial	Roof Insulation	Schools K-12	New	N_SC_Roof I	0.32	1.22	0.26	0	0	0	Fail PCT
Commercial	Roof Insulation	Warehouse	New	N_WR_Roof	0.19	0.71	0.26	0	0	0	Fail RIM
Commercial	Smart Thermostat	Assembly	Existing	E_AS_Smart	0.29	0.30	0.94	0	0	0	Fail RIM
Commercial	Smart Thermostat	College and University	Existing	E_CU_Smart	0.65	0.44	1.47	0	0	0	Fail RIM
Commercial	Smart Thermostat	Grocery	Existing	E_GR_Smart	8.94	0.99	9.05	0	0	0	Fail RIM
Commercial	Smart Thermostat	Healthcare	Existing	E_HC_Smart	1.13	0.30	3.72	0	0	0	Fail RIM
Commercial	Smart Thermostat	Hospitals	Existing	E_HS_Smart	1.73	0.44	3.92	0	0	0	Fail RIM
Commercial	Smart Thermostat	Institutional	Existing	E_IN_Smart	1.31	0.30	4.30	0	0	0	Fail RIM
Commercial	Smart Thermostat	Miscellaneous	Existing	E_MS_Smart	0.92	0.30	3.01	0	0	0	Fail RIM
Commercial	Smart Thermostat	Offices	Existing	E_OF_Smart	1.22	0.30	4.00	0	0	0	Fail RIM
Commercial	Smart Thermostat	Restaurants	Existing	E_RS_Smart	7.45	0.99	7.54	0	0	0	Fail RIM
Commercial	Smart Thermostat	Retail	Existing	E_RT_Smart	1.63	0.99	1.65	0	0	0	Fail RIM
Commercial	Smart Thermostat	Schools K-12	Existing	E_SC_Smart	0.45	0.30	1.47	0	0	0	Fail RIM
Commercial	Smart Thermostat	Warehouse	Existing	E_WR_Smart	0.14	0.30	0.47	0	0	0	Fail RIM
Commercial	Smart Thermostat	Assembly	New	N_AS_Smart	0.29	0.30	0.94	0	0	0	Fail RIM
Commercial	Smart Thermostat	College and University	New	N_CU_Smart	0.65	0.44	1.47	0	0	0	Fail RIM
Commercial	Smart Thermostat	Grocery	New	N_GR_Smart	8.94	0.99	9.05	0	0	0	Fail RIM
Commercial	Smart Thermostat	Healthcare	New	N_HC_Smart	1.13	0.30	3.72	0	0	0	Fail RIM
Commercial	Smart Thermostat	Hospitals	New	N_HS_Smart	1.73	0.44	3.92	0	0	0	Fail RIM
Commercial	Smart Thermostat	Institutional	New	N_IN_Smart	1.31	0.30	4.30	0	0	0	Fail RIM
Commercial	Smart Thermostat	Miscellaneous	New	N_MS_Smart	0.92	0.30	3.01	0	0	0	Fail RIM
Commercial	Smart Thermostat	Offices	New	N_OF_Smart	1.22	0.30	4.00	0	0	0	Fail RIM
Commercial	Smart Thermostat	Restaurants	New	N_RS_Smart	7.45	0.99	7.54	0	0	0	Fail RIM
Commercial	Smart Thermostat	Retail	New	N_RT_Smart	1.63	0.99	1.65	0	0	0	Fail RIM
Commercial	Smart Thermostat	Schools K-12	New	N_SC_Smart	0.45	0.30	1.47	0	0	0	Fail RIM
Commercial	Smart Thermostat	Warehouse	New	N_WR_Smart	0.14	0.30	0.47	0	0	0	Fail RIM
Commercial	Wall Insulation	Warehouse	Existing	E_WR_Wall	1.99	0.71	2.81	0	0	0	Fail RIM
Commercial	Wall Insulation	Assembly	New	N_AS_Wall I	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Wall Insulation	College and University	New	N_CU_Wall I	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Wall Insulation	Grocery	New	N_GR_Wall I	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Wall Insulation	Healthcare	New	N_HC_Wall I	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Wall Insulation	Hospitals	New	N_HS_Wall I	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Wall Insulation	Institutional	New	N_IN_Wall In	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Wall Insulation	Lodging/Hospitality	New	N_LG_Wall I	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Wall Insulation	Miscellaneous	New	N_MS_Wall	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Wall Insulation	Offices	New	N_OF_Wall I	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Wall Insulation	Restaurants	New	N_RS_Wall I	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Wall Insulation	Retail	New	N_RT_Wall I	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Wall Insulation	Schools K-12	New	N_SC_Wall I	0.00	0.00	0.00	0	0	0	Fail RIM

Commercial	Network PC Power Management	Healthcare	Existing	E_HC_Netwo	0.83	0.46	1.78	0	0	0	Fail TRC
Commercial	Network PC Power Management	Hospitals	Existing	E_HS_Netwo	0.80	0.44	1.81	0	0	0	Fail TRC
Commercial	Network PC Power Management	Institutional	Existing	E_IN_Netwo	0.82	0.46	1.78	0	0	0	Fail TRC
Commercial	Network PC Power Management	Lodging/Hospitality	Existing	E_LG_Netwo	0.83	0.46	1.78	0	0	0	Fail TRC
Commercial	Network PC Power Management	Miscellaneous	Existing	E_MS_Netwo	0.84	0.46	1.81	0	0	0	Fail TRC
Commercial	Network PC Power Management	Offices	Existing	E_OF_Netwo	0.83	0.46	1.78	0	0	0	Fail TRC
Commercial	Network PC Power Management	Restaurants	Existing	E_RS_Netwo	0.83	0.46	1.78	0	0	0	Fail TRC
Commercial	Network PC Power Management	Retail	Existing	E_RT_Netwo	0.81	0.46	1.73	0	0	0	Fail TRC
Commercial	Network PC Power Management	Schools K-12	Existing	E_SC_Netwo	0.83	0.46	1.79	0	0	0	Fail TRC
Commercial	Network PC Power Management	Warehouse	Existing	E_WR_Netwo	0.66	0.46	1.43	0	0	0	Fail TRC
Commercial	Network PC Power Management	Assembly	New	N_AS_Netwo	0.82	0.46	1.76	0	0	0	Fail TRC
Commercial	Network PC Power Management	College and University	New	N_CU_Netwo	0.80	0.44	1.79	0	0	0	Fail TRC
Commercial	Network PC Power Management	Grocery	New	N_GR_Netwo	0.82	0.46	1.76	0	0	0	Fail TRC
Commercial	Network PC Power Management	Healthcare	New	N_HC_Netwo	0.83	0.46	1.78	0	0	0	Fail TRC
Commercial	Network PC Power Management	Hospitals	New	N_HS_Netwo	0.80	0.44	1.81	0	0	0	Fail TRC
Commercial	Network PC Power Management	Institutional	New	N_IN_Netwo	0.82	0.46	1.76	0	0	0	Fail TRC
Commercial	Network PC Power Management	Lodging/Hospitality	New	N_LG_Netwo	0.83	0.46	1.78	0	0	0	Fail TRC
Commercial	Network PC Power Management	Miscellaneous	New	N_MS_Netwo	0.84	0.46	1.81	0	0	0	Fail TRC
Commercial	Network PC Power Management	Offices	New	N_OF_Netwo	0.83	0.46	1.78	0	0	0	Fail TRC
Commercial	Network PC Power Management	Restaurants	New	N_RS_Netwo	0.83	0.46	1.78	0	0	0	Fail TRC
Commercial	Network PC Power Management	Retail	New	N_RT_Netwo	0.81	0.46	1.75	0	0	0	Fail TRC
Commercial	Network PC Power Management	Schools K-12	New	N_SC_Netwo	0.83	0.46	1.79	0	0	0	Fail TRC
Commercial	Network PC Power Management	Warehouse	New	N_WR_Netwo	0.66	0.46	1.43	0	0	0	Fail TRC
Commercial	Smart Strip Plug Outlet	Assembly	Existing	E_AS_Smart	0.89	0.46	1.93	0	0	0	Fail TRC
Commercial	Smart Strip Plug Outlet	College and University	Existing	E_CU_Smart	1.17	0.46	2.54	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Grocery	Existing	E_GR_Smart	1.14	0.46	2.46	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Healthcare	Existing	E_HC_Smart	1.60	0.46	3.46	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Hospitals	Existing	E_HS_Smart	1.75	0.46	3.79	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Institutional	Existing	E_IN_Smart	1.46	0.46	3.16	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Lodging/Hospitality	Existing	E_LG_Smart	1.31	0.46	2.84	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Miscellaneous	Existing	E_MS_Smart	1.78	0.46	3.85	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Offices	Existing	E_OF_Smart	1.11	0.46	2.40	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Restaurants	Existing	E_RS_Smart	1.07	0.46	2.31	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Retail	Existing	E_RT_Smart	0.48	0.46	1.05	0	0	0	Fail TRC
Commercial	Smart Strip Plug Outlet	Schools K-12	Existing	E_SC_Smart	1.61	0.46	3.48	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Warehouse	Existing	E_WR_Smart	0.13	0.46	0.28	0	0	0	Fail TRC
Commercial	Smart Strip Plug Outlet	Assembly	New	N_AS_Smart	0.89	0.46	1.93	0	0	0	Fail TRC
Commercial	Smart Strip Plug Outlet	College and University	New	N_CU_Smart	1.17	0.46	2.54	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Grocery	New	N_GR_Smart	1.14	0.46	2.46	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Healthcare	New	N_HC_Smart	1.60	0.46	3.46	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Hospitals	New	N_HS_Smart	1.75	0.46	3.79	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Institutional	New	N_IN_Smart	1.46	0.46	3.16	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Lodging/Hospitality	New	N_LG_Smart	1.31	0.46	2.84	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Miscellaneous	New	N_MS_Smart	1.78	0.46	3.85	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Offices	New	N_OF_Smart	1.11	0.46	2.40	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Restaurants	New	N_RS_Smart	1.07	0.46	2.31	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Retail	New	N_RT_Smart	0.48	0.46	1.05	0	0	0	Fail TRC
Commercial	Smart Strip Plug Outlet	Schools K-12	New	N_SC_Smart	1.61	0.46	3.48	0	0	0	Fail 2-year Threshold
Commercial	Smart Strip Plug Outlet	Warehouse	New	N_WR_Smart	0.13	0.46	0.28	0	0	0	Fail TRC
Commercial	Anti-Sweat Controls	Assembly	Existing	E_AS_Anti-S	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	College and University	Existing	E_CU_Anti-S	1.82	0.47	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Grocery	Existing	E_GR_Anti-S	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Healthcare	Existing	E_HC_Anti-S	1.82	0.47	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Hospitals	Existing	E_HS_Anti-S	1.82	0.47	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Institutional	Existing	E_IN_Anti-S	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Lodging/Hospitality	Existing	E_LG_Anti-S	1.82	0.47	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Miscellaneous	Existing	E_MS_Anti-S	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Offices	Existing	E_OF_Anti-S	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Restaurants	Existing	E_RS_Anti-S	1.82	0.47	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Retail	Existing	E_RT_Anti-S	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Schools K-12	Existing	E_SC_Anti-S	1.82	0.47	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Warehouse	Existing	E_WR_Anti-	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Assembly	New	N_AS_Anti-S	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	College and University	New	N_CU_Anti-S	1.82	0.47	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Grocery	New	N_GR_Anti-S	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Healthcare	New	N_HC_Anti-S	1.82	0.47	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Hospitals	New	N_HS_Anti-S	1.82	0.47	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Institutional	New	N_IN_Anti-S	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Lodging/Hospitality	New	N_LG_Anti-S	1.82	0.47	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Miscellaneous	New	N_MS_Anti-S	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Offices	New	N_OF_Anti-S	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Restaurants	New	N_RS_Anti-S	1.82	0.47	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Retail	New	N_RT_Anti-S	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Schools K-12	New	N_SC_Anti-S	1.82	0.47	3.87	0	0	0	Fail 2-year Threshold
Commercial	Anti-Sweat Controls	Warehouse	New	N_WR_Anti-	1.49	0.39	3.87	0	0	0	Fail 2-year Threshold
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Assembly	Existing	E_AS_Autom	0.08	0.49	0.16	0	0	0	Fail TRC
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	College and University	Existing	E_CU_Autom	0.

Commercial	Wall Insulation	Warehouse	New	N_WR_Wall	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Assembly	Existing	E_AS_Ware	0.21	0.70	0.30	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	College and University	Existing	E_CU_Ware	0.10	0.70	0.15	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Grocery	Existing	E_GR_Ware	0.72	0.70	1.02	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Healthcare	Existing	E_HC_Ware	0.20	0.70	0.28	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Hospitals	Existing	E_HS_Ware	0.10	0.70	0.15	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Institutional	Existing	E_IN_Ware	0.64	0.70	0.91	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Lodging/Hospitality	Existing	E_LG_Ware	0.48	0.70	0.69	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Miscellaneous	Existing	E_MS_Ware	0.13	0.70	0.18	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Offices	Existing	E_OF_Ware	0.93	0.70	1.33	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Restaurants	Existing	E_RS_Ware	0.69	0.70	0.99	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Retail	Existing	E_RT_Ware	0.30	0.70	0.43	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Schools K-12	Existing	E_SC_Ware	0.07	0.70	0.10	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Warehouse	Existing	E_WR_Ware	0.19	0.70	0.27	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Assembly	New	N_AS_Ware	0.21	0.70	0.29	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	College and University	New	N_CU_Ware	0.10	0.70	0.14	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Grocery	New	N_GR_Ware	0.72	0.70	1.00	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Healthcare	New	N_HC_Ware	0.20	0.70	0.28	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Hospitals	New	N_HS_Ware	0.10	0.70	0.14	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Institutional	New	N_IN_Ware	0.63	0.70	0.90	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Lodging/Hospitality	New	N_LG_Ware	0.48	0.70	0.68	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Miscellaneous	New	N_MS_Ware	0.13	0.70	0.18	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Offices	New	N_OF_Ware	0.92	0.70	1.30	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Restaurants	New	N_RS_Ware	0.68	0.70	0.97	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Retail	New	N_RT_Ware	0.30	0.70	0.42	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Schools K-12	New	N_SC_Ware	0.07	0.70	0.10	0	0	0	Fail RIM
Commercial	Warehouse Loading Dock Seals	Warehouse	New	N_WR_Ware	0.19	0.70	0.27	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Assembly	Existing	E_AS_Water	0.04	0.43	0.08	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	College and University	Existing	E_CU_Water	0.07	0.52	0.13	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Grocery	Existing	E_GR_Water	0.36	0.43	0.83	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Healthcare	Existing	E_HC_Water	0.18	0.52	0.34	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Hospitals	Existing	E_HS_Water	0.18	0.52	0.34	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Institutional	Existing	E_IN_Water	0.17	0.43	0.38	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Lodging/Hospitality	Existing	E_LG_Water	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Miscellaneous	Existing	E_MS_Water	1.06	0.43	2.45	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Offices	Existing	E_OF_Water	0.15	0.43	0.35	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Restaurants	Existing	E_RS_Water	0.42	0.52	0.80	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Retail	Existing	E_RT_Water	0.07	0.43	0.16	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Schools K-12	Existing	E_SC_Water	0.07	0.52	0.13	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Warehouse	Existing	E_WR_Water	0.02	0.43	0.04	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Assembly	New	N_AS_Water	0.04	0.43	0.08	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	College and University	New	N_CU_Water	0.07	0.52	0.13	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Grocery	New	N_GR_Water	0.36	0.43	0.83	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Healthcare	New	N_HC_Water	0.18	0.52	0.34	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Hospitals	New	N_HS_Water	0.18	0.52	0.34	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Institutional	New	N_IN_Water	0.17	0.43	0.38	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Lodging/Hospitality	New	N_LG_Water	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Miscellaneous	New	N_MS_Water	1.06	0.43	2.45	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Offices	New	N_OF_Water	0.15	0.43	0.35	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Restaurants	New	N_RS_Water	0.42	0.52	0.80	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Retail	New	N_RT_Water	0.07	0.43	0.16	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Schools K-12	New	N_SC_Water	0.07	0.52	0.13	0	0	0	Fail RIM
Commercial	Water Cooled Refrigeration Heat Recovery	Warehouse	New	N_WR_Water	0.02	0.43	0.04	0	0	0	Fail RIM
Commercial	Waterside Economizer	Assembly	Existing	E_AS_Water	0.06	1.19	0.05	0	0	0	Fail PCT
Commercial	Waterside Economizer	College and University	Existing	E_CU_Water	0.06	1.19	0.05	0	0	0	Fail PCT
Commercial	Waterside Economizer	Grocery	Existing	E_GR_Water	0.03	1.19	0.03	0	0	0	Fail PCT
Commercial	Waterside Economizer	Healthcare	Existing	E_HC_Water	0.12	1.19	0.10	0	0	0	Fail PCT
Commercial	Waterside Economizer	Hospitals	Existing	E_HS_Water	0.11	1.19	0.10	0	0	0	Fail PCT
Commercial	Waterside Economizer	Institutional	Existing	E_IN_Water	0.03	1.19	0.03	0	0	0	Fail PCT
Commercial	Waterside Economizer	Lodging/Hospitality	Existing	E_LG_Water	0.09	1.19	0.08	0	0	0	Fail PCT
Commercial	Waterside Economizer	Miscellaneous	Existing	E_MS_Water	0.03	1.19	0.03	0	0	0	Fail PCT
Commercial	Waterside Economizer	Offices	Existing	E_OF_Water	0.06	1.19	0.05	0	0	0	Fail PCT
Commercial	Waterside Economizer	Restaurants	Existing	E_RS_Water	0.09	1.19	0.08	0	0	0	Fail PCT
Commercial	Waterside Economizer	Retail	Existing	E_RT_Water	0.07	1.19	0.06	0	0	0	Fail PCT
Commercial	Waterside Economizer	Schools K-12	Existing	E_SC_Water	0.06	1.19	0.05	0	0	0	Fail PCT
Commercial	Waterside Economizer	Warehouse	Existing	E_WR_Water	0.01	1.19	0.01	0	0	0	Fail PCT
Commercial	Waterside Economizer	Assembly	New	N_AS_Water	0.06	1.19	0.05	0	0	0	Fail PCT
Commercial	Waterside Economizer	College and University	New	N_CU_Water	0.06	1.19	0.05	0	0	0	Fail PCT
Commercial	Waterside Economizer	Grocery	New	N_GR_Water	0.03	1.19	0.03	0	0	0	Fail PCT
Commercial	Waterside Economizer	Healthcare	New	N_HC_Water	0.12	1.19	0.10	0	0	0	Fail PCT
Commercial	Waterside Economizer	Hospitals	New	N_HS_Water	0.11	1.19	0.10	0	0	0	Fail PCT
Commercial	Waterside Economizer	Institutional	New	N_IN_Water	0.03	1.19	0.03	0	0	0	Fail PCT
Commercial	Waterside Economizer	Lodging/Hospitality	New	N_LG_Water	0.09	1.19	0.08	0	0	0	Fail PCT
Commercial	Waterside Economizer	Miscellaneous	New	N_MS_Water	0.03	1.19	0.03	0	0	0	Fail PCT
Commercial	Waterside Economizer	Offices	New	N_OF_Water	0.06	1.19	0.05	0	0	0	Fail PCT
Commercial	Waterside Economizer	Restaurants	New	N_RS_Water	0.09	1.19	0.08	0	0	0	Fail PCT
Commercial	Waterside Economizer	Retail	New	N_RT_Water	0.07	1.19	0.06	0	0	0	Fail PCT
Commercial	Waterside Economizer	Schools K-12	New	N_SC_Water	0.06	1.19	0.05	0	0	0	Fail PCT
Commercial	Waterside Economizer	Warehouse	New	N_WR_Water	0.01	1.19	0.01	0	0	0	Fail PCT
Commercial	Window Sun Protection	Assembly	Existing	E_AS_Windo	0.22	0.97	0.23	0	0	0	Fail RIM
Commercial	Window Sun Protection	College and University	Existing	E_CU_Windo	0.22	0.97	0.23	0	0	0	Fail RIM
Commercial	Window Sun Protection	Grocery	Existing	E_GR_Windo	0.22	0.97	0.23	0	0	0	Fail RIM
Commercial	Window Sun Protection	Healthcare	Existing	E_HC_Windo	0.22	0.97	0.23	0	0	0	Fail RIM
Commercial	Window Sun Protection	Hospitals	Existing	E_HS_Windo	0.22	0.97	0.23	0	0	0	Fail RIM
Commercial	Window Sun Protection	Institutional	Existing	E_IN_Windo	0.22	0.97	0.23	0	0	0	Fail RIM
Commercial	Window Sun Protection	Lodging/Hospitality	Existing	E_LG_Windo	0.24	1.08	0.23	0	0	0	Fail PCT
Commercial	Window Sun Protection	Miscellaneous	Existing	E_MS_Windo	0.28	1.22	0.23	0	0	0	Fail PCT
Commercial	Window Sun Protection	Offices	Existing	E_OF_Windo	0.22	0.97	0.23	0	0	0	Fail RIM
Commercial	Window Sun Protection	Restaurants	Existing	E_RS_Windo	0.22	0.97	0.23	0	0	0	Fail RIM
Commercial	Window Sun Protection	Retail	Existing	E_RT_Windo	0.22	0.97	0.23	0	0	0	Fail RIM
Commercial	Window Sun Protection	Schools K-12	Existing	E_SC_Windo	0.22	0.97	0.23	0	0	0	Fail RIM
Commercial	Window Sun Protection	Warehouse	Existing	E_WR_Windo	0.28	1.22	0.23	0	0	0	Fail PCT
Commercial	Window Sun Protection	Assembly	New	N_AS_Windo	0.13	0.97	0.14	0	0	0	Fail RIM
Commercial	Window Sun Protection	College and University	New	N_CU_Windo	0.13	0.97	0.14	0	0	0	Fail RIM
Commercial	Window Sun Protection	Grocery	New	N_GR_Windo	0.13	0.97	0.14	0	0	0	Fail RIM
Commercial	Window Sun Protection	Healthcare	New	N_HC_Windo	0.13	0.97	0.14	0	0	0	Fail RIM
Commercial	Window Sun Protection	Hospitals	New	N_HS_Windo	0.13	0.97	0.14	0	0	0	Fail RIM
Commercial	Window Sun Protection	Institutional	New	N_IN_Windo	0.13	0.97	0.14	0	0	0	Fail RIM
Commercial	Window Sun Protection	Lodging/Hospitality	New	N_LG_Windo	0.15	1.08	0.14	0	0	0	Fail PCT
Commercial	Window Sun Protection	Miscellaneous	New	N_MS_Windo	0.17	1.22	0.14	0	0	0	Fail PCT
Commercial	Window Sun Protection	Offices	New	N_OF_Windo	0.13	0.97	0.14	0	0	0	Fail RIM
Commercial	Window Sun Protection	Restaurants	New	N_RS_Windo	0.13	0.97	0.14	0	0	0	Fail RIM
Commercial	Window Sun Protection	Retail	New	N_RT_Windo	0.13	0.97	0.14	0	0	0	Fail RIM
Commercial	Window Sun Protection	Schools K-12	New	N_SC_Windo	0.13	0.97	0.14	0	0	0	Fail RIM
Commercial	Window Sun Protection	Warehouse	New	N_WR_Windo	0.17	1.22	0.14	0	0	0	Fail PCT
Commercial	Bi-Level Lighting Control (Interior)	Assembly	Existing	E_AS_Bi-Lev	0.21	0.27	0.77	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	College and University	Existing	E_CU_Bi-Lev	0.33	0.27	1.19	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Grocery	Existing	E_GR_Bi-Lev	0.43	0.29	1.49	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Healthcare	Existing	E_HC_Bi-Lev	0.37	0.27	1.35	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Hospitals	Existing	E_HS_Bi-Lev	0.50	0.27	1.83	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Institutional	Existing	E_IN_Bi-Lev	0.24	0.27	0.89	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Lodging/Hospitality	Existing	E_LG_Bi-Lev	0.29	0.29	1.01	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Miscellaneous	Existing	E_MS_Bi-Lev	0.33	0.27	1.19	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Offices	Existing	E_OF_Bi-Lev	0.24	0.27	0.88	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Restaurants	Existing	E_RS_Bi-Lev	0.26	0.29	0.90	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Retail	Existing	E_RT_Bi-Lev	0.39	0.29	1.34	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Schools K-12	Existing	E_SC_Bi-Lev	0.18	0.27	0.64	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Warehouse	Existing	E_WR_Bi-Lev	0.28	0.27	1.03	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Assembly	New	N_AS_Bi-Lev	0.21	0.27	0.77	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	College and University	New	N_CU_Bi-Lev	0.33	0.27	1.19	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Grocery	New	N_GR_Bi-Lev	0.43	0.29	1.49	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Healthcare	New	N_HC_Bi-Lev	0.37	0.27	1.35	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Hospitals	New	N_HS_Bi-Lev	0.50	0.27	1.83	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Institutional	New	N_IN_Bi-Lev	0.24	0.27	0.89	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Lodging/Hospitality	New	N_LG_Bi-Lev	0.29	0.29	1.01	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Miscellaneous	New	N_MS_Bi-Lev	0.33	0.27	1.19	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Offices	New	N_OF_Bi-Lev	0.24	0.27	0.88	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Restaurants	New	N_RS_Bi-Lev	0.26	0.29	0.90	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Retail	New	N_RT_Bi-Lev	0.39	0.29	1.34	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Schools K-12	New	N_SC_Bi-Lev	0.18	0.27	0.64	0	0	0	Fail RIM
Commercial	Bi-Level Lighting Control (Interior)	Warehouse	New	N_WR_Bi-Lev	0.28	0.27	1.03	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Assembly	Existing	E_AS_Interio	0.45	0.27	1.67	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	College and University	Existing	E_CU_Interio	0.69	0.27	2.56	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Grocery	Existing	E_GR_Interio	0.87	0.27	3.21	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Healthcare	Existing	E_HC_Interio	0.79	0.27	2.92	0	0	0	Fail RIM

Commercial	Floating Head Pressure Controls	Offices	Existing	E_OF_Floati	5.53	0.61	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Restaurants	Existing	E_RS_Floati	5.12	0.56	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Retail	Existing	E_RT_Floati	5.53	0.61	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Schools K-12	Existing	E_SC_Floati	5.12	0.56	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Warehouse	Existing	E_WR_Float	5.53	0.61	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Assembly	New	N_AS_Floati	5.53	0.61	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	College and University	New	N_CU_Floati	5.12	0.56	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Grocery	New	N_GR_Floati	5.53	0.61	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Healthcare	New	N_HC_Floati	5.12	0.56	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Hospitals	New	N_HS_Floati	5.12	0.56	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Institutional	New	N_IN_Floati	5.53	0.61	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Lodging/Hospitality	New	N_LG_Floati	5.12	0.56	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Miscellaneous	New	N_MS_Floati	5.53	0.61	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Offices	New	N_OF_Floati	5.53	0.61	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Restaurants	New	N_RS_Floati	5.12	0.56	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Retail	New	N_RT_Floati	5.53	0.61	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Schools K-12	New	N_SC_Floati	5.12	0.56	9.10	0	0	0	Fail 2-year Threshold
Commercial	Floating Head Pressure Controls	Warehouse	New	N_WR_Float	5.53	0.61	9.10	0	0	0	Fail 2-year Threshold
Commercial	Freezer-Cooler Replacement Gaskets	Assembly	Existing	E_AS_Freeze	0.26	0.46	0.56	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	College and University	Existing	E_CU_Freeze	0.24	0.44	0.56	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Grocery	Existing	E_GR_Freeze	0.26	0.46	0.56	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Healthcare	Existing	E_HC_Freeze	0.24	0.44	0.56	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Hospitals	Existing	E_HS_Freeze	0.24	0.44	0.56	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Institutional	Existing	E_IN_Freeze	0.26	0.46	0.56	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Lodging/Hospitality	Existing	E_LG_Freeze	0.24	0.44	0.56	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Miscellaneous	Existing	E_MS_Freeze	0.26	0.46	0.56	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Offices	Existing	E_OF_Freeze	0.26	0.46	0.56	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Restaurants	Existing	E_RS_Freeze	0.24	0.44	0.56	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Retail	Existing	E_RT_Freeze	0.26	0.46	0.56	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Schools K-12	Existing	E_SC_Freeze	0.24	0.44	0.56	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Warehouse	Existing	E_WR_Freeze	0.26	0.46	0.56	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Assembly	New	N_AS_Freeze	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	College and University	New	N_CU_Freeze	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Grocery	New	N_GR_Freeze	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Healthcare	New	N_HC_Freeze	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Hospitals	New	N_HS_Freeze	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Institutional	New	N_IN_Freeze	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Lodging/Hospitality	New	N_LG_Freeze	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Miscellaneous	New	N_MS_Freeze	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Offices	New	N_OF_Freeze	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Restaurants	New	N_RS_Freeze	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Retail	New	N_RT_Freeze	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Schools K-12	New	N_SC_Freeze	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	Freezer-Cooler Replacement Gaskets	Warehouse	New	N_WR_Freez	0.00	0.00	0.00	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Assembly	Existing	E_AS_High E	0.36	0.59	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	College and University	Existing	E_CU_High E	0.33	0.55	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Grocery	Existing	E_GR_High E	0.36	0.59	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Healthcare	Existing	E_HC_High E	0.33	0.55	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Hospitals	Existing	E_HS_High E	0.33	0.55	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Institutional	Existing	E_IN_High E	0.36	0.59	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Lodging/Hospitality	Existing	E_LG_High E	0.33	0.55	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Miscellaneous	Existing	E_MS_High E	0.36	0.59	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Offices	Existing	E_OF_High E	0.36	0.59	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Restaurants	Existing	E_RS_High E	0.33	0.55	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Retail	Existing	E_RT_High E	0.36	0.59	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Schools K-12	Existing	E_SC_High E	0.33	0.55	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Warehouse	Existing	E_WR_High	0.36	0.59	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Assembly	New	N_AS_High E	0.36	0.59	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	College and University	New	N_CU_High	0.33	0.55	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Grocery	New	N_GR_High E	0.36	0.59	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Healthcare	New	N_HC_High E	0.33	0.55	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Hospitals	New	N_HS_High E	0.33	0.55	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Institutional	New	N_IN_High E	0.36	0.59	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Lodging/Hospitality	New	N_LG_High E	0.33	0.55	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Miscellaneous	New	N_MS_High E	0.36	0.59	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Offices	New	N_OF_High E	0.36	0.59	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Restaurants	New	N_RS_High E	0.33	0.55	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Retail	New	N_RT_High E	0.36	0.59	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrigeration Compressor	Schools K-12	New	N_SC_High E	0.33	0.55	0.60	0	0	0	Fail TRC
Commercial	High Efficiency Refrige

Commercial	Interior Lighting Controls	Hospitals	Existing	E_HS_Interio	1.07	0.27	3.94	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Institutional	Existing	E_IN_Interio	0.52	0.27	1.91	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Lodging/Hospitality	Existing	E_LG_Interio	0.59	0.27	2.18	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Miscellaneous	Existing	E_MS_Interio	0.69	0.27	2.56	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Offices	Existing	E_OF_Interio	0.51	0.27	1.89	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Restaurants	Existing	E_RS_Interio	0.53	0.27	1.95	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Retail	Existing	E_RT_Interio	0.78	0.27	2.89	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Schools K-12	Existing	E_SC_Interio	0.37	0.27	1.38	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Warehouse	Existing	E_WR_Interi	0.60	0.27	2.22	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Assembly	New	N_AS_Interio	0.45	0.27	1.67	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	College and University	New	N_CU_Interi	0.69	0.27	2.56	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Grocery	New	N_GR_Interio	0.87	0.27	3.21	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Healthcare	New	N_HC_Interio	0.79	0.27	2.92	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Hospitals	New	N_HS_Interio	1.07	0.27	3.94	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Institutional	New	N_IN_Interio	0.52	0.27	1.91	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Lodging/Hospitality	New	N_LG_Interio	0.59	0.27	2.18	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Miscellaneous	New	N_MS_Interi	0.69	0.27	2.56	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Offices	New	N_OF_Interio	0.51	0.27	1.89	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Restaurants	New	N_RS_Interio	0.53	0.27	1.95	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Retail	New	N_RT_Interio	0.78	0.27	2.89	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Schools K-12	New	N_SC_Interio	0.37	0.27	1.38	0	0	0	Fail RIM
Commercial	Interior Lighting Controls	Warehouse	New	N_WR_Interi	0.60	0.27	2.22	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Assembly	Existing	E_AS_Efficie	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	College and University	Existing	E_CU_Efficie	0.10	0.51	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Grocery	Existing	E_GR_Efficie	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Healthcare	Existing	E_HC_Efficie	0.10	0.51	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Hospitals	Existing	E_HS_Efficie	0.10	0.51	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Institutional	Existing	E_IN_Efficie	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Lodging/Hospitality	Existing	E_LG_Efficie	0.10	0.51	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Miscellaneous	Existing	E_MS_Efficie	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Offices	Existing	E_OF_Efficie	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Restaurants	Existing	E_RS_Efficie	0.10	0.51	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Retail	Existing	E_RT_Efficie	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Schools K-12	Existing	E_SC_Efficie	0.10	0.51	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Warehouse	Existing	E_WR_Effici	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Assembly	New	N_AS_Efficie	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	College and University	New	N_CU_Effici	0.10	0.51	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Grocery	New	N_GR_Efficie	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Healthcare	New	N_HC_Effici	0.10	0.51	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Hospitals	New	N_HS_Efficie	0.10	0.51	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Institutional	New	N_IN_Efficie	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Lodging/Hospitality	New	N_LG_Efficie	0.10	0.51	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Miscellaneous	New	N_MS_Effici	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Offices	New	N_OF_Efficie	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Restaurants	New	N_RS_Efficie	0.10	0.51	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Retail	New	N_RT_Efficie	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Schools K-12	New	N_SC_Efficie	0.10	0.51	0.19	0	0	0	Fail RIM
Commercial	Efficient Motor Belts	Warehouse	New	N_WR_Effici	0.10	0.52	0.19	0	0	0	Fail RIM
Commercial	Engine Block Timer	Assembly	Existing	E_AS_Engin	0.36	0.26	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	College and University	Existing	E_CU_Engin	0.60	0.43	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Grocery	Existing	E_GR_Engin	0.36	0.26	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Healthcare	Existing	E_HC_Engin	0.36	0.26	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Hospitals	Existing	E_HS_Engin	0.60	0.43	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Institutional	Existing	E_IN_Engin	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Lodging/Hospitality	Existing	E_LG_Engin	0.36	0.26	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Miscellaneous	Existing	E_MS_Engin	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Offices	Existing	E_OF_Engin	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Restaurants	Existing	E_RS_Engin	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Retail	Existing	E_RT_Engin	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Schools K-12	Existing	E_SC_Engin	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Warehouse	Existing	E_WR_Engi	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Assembly	New	N_AS_Engin	0.36	0.26	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	College and University	New	N_CU_Engin	0.60	0.43	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Grocery	New	N_GR_Engin	0.36	0.26	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Healthcare	New	N_HC_Engin	0.36	0.26	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Hospitals	New	N_HS_Engin	0.60	0.43	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Institutional	New	N_IN_Engin	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Lodging/Hospitality	New	N_LG_Engin	0.36	0.26	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Miscellaneous	New	N_MS_Engin	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Offices	New	N_OF_Engin	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Restaurants	New	N_RS_Engin	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Retail	New	N_RT_Engin	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Schools K-12	New	N_SC_Engin	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Engine Block Timer	Warehouse	New	N_WR_Engi	0.45	0.32	1.40	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Assembly	Existing	E_AS_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	College and University	Existing	E_CU_Regen	0.11	0.55	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Grocery	Existing	E_GR_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Healthcare	Existing	E_HC_Regen	0.11	0.55	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Hospitals	Existing	E_HS_Regen	0.11	0.55	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Institutional	Existing	E_IN_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Lodging/Hospitality	Existing	E_LG_Regen	0.11	0.55	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Miscellaneous	Existing	E_MS_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Offices	Existing	E_OF_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Restaurants	Existing	E_RS_Regen	0.11	0.55	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Retail	Existing	E_RT_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Schools K-12	Existing	E_SC_Regen	0.11	0.55	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Warehouse	Existing	E_WR_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Assembly	New	N_AS_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	College and University	New	N_CU_Regen	0.11	0.55	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Grocery	New	N_GR_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Healthcare	New	N_HC_Regen	0.11	0.55	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Hospitals	New	N_HS_Regen	0.11	0.55	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Institutional	New	N_IN_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Lodging/Hospitality	New	N_LG_Regen	0.11	0.55	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Miscellaneous	New	N_MS_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Offices	New	N_OF_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Restaurants	New	N_RS_Regen	0.11	0.55	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Retail	New	N_RT_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Schools K-12	New	N_SC_Regen	0.11	0.55	0.20	0	0	0	Fail RIM
Commercial	Regenerative Drive Elevator Motor	Warehouse	New	N_WR_Regen	0.11	0.57	0.20	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Assembly	Existing	E_AS_VSD C	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	College and University	Existing	E_CU_VSD C	2.06	0.56	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Grocery	Existing	E_GR_VSD C	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Healthcare	Existing	E_HC_VSD C	2.06	0.56	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Hospitals	Existing	E_HS_VSD C	2.06	0.56	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Institutional	Existing	E_IN_VSD C	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Lodging/Hospitality	Existing	E_LG_VSD C	2.06	0.56	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Miscellaneous	Existing	E_MS_VSD C	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Offices	Existing	E_OF_VSD C	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Restaurants	Existing	E_RS_VSD C	2.06	0.56	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Retail	Existing	E_RT_VSD C	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Schools K-12	Existing	E_SC_VSD C	2.06	0.56	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Warehouse	Existing	E_WR_VSD C	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Assembly	New	N_AS_VSD C	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	College and University	New	N_CU_VSD C	2.06	0.56	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Grocery	New	N_GR_VSD C	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Healthcare	New	N_HC_VSD C	2.06	0.56	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Hospitals	New	N_HS_VSD C	2.06	0.56	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Institutional	New	N_IN_VSD C	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Lodging/Hospitality	New	N_LG_VSD C	2.06	0.56	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Miscellaneous	New	N_MS_VSD C	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Offices	New	N_OF_VSD C	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Restaurants	New	N_RS_VSD C	2.06	0.56	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Retail	New	N_RT_VSD C	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Schools K-12	New	N_SC_VSD C	2.06	0.56	3.66	0	0	0	Fail RIM
Commercial	VSD Controlled Compressor	Warehouse	New	N_WR_VSD	2.22	0.61	3.66	0	0	0	Fail RIM
Commercial	Network PC Power Management	Assembly	Existing	E_AS_Netwo	0.82	0.46	1.78	0	0	0	Fail RIM
Commercial	Network PC Power Management	College and University	Existing	E_CU_Netwo	0.80	0.44	1.79	0	0	0	Fail RIM
Commercial	Network PC Power Management	Grocery	Existing	E_GR_Netwo	0.82	0.46	1.76	0	0	0	Fail RIM
Commercial	Network PC Power Management	Healthcare	Existing	E_HC_Netwo	0.83	0.46	1.78	0	0	0	Fail RIM
Commercial	Network PC Power Management	Hospitals	Existing	E_HS_Netwo	0.80	0.44	1.81	0	0	0	Fail RIM
Commercial	Network PC Power Management	Institutional	Existing	E_IN_Netwo	0.82	0.46	1.76	0	0	0	Fail RIM
Commercial	Network PC Power Management	Lodging/Hospitality	Existing	E_LG_Netwo	0.83	0.46	1.78	0	0	0	Fail RIM
Commercial	Network PC Power Management	Miscellaneous	Existing	E_MS_Netwo	0.84	0.46	1.81	0	0	0	Fail RIM
Commercial	Network PC Power Management	Offices	Existing	E_OF_Netwo	0.83	0.46	1.78	0	0	0	Fail RIM
Commercial	Network PC Power Management	Restaurants	Existing	E_RS_Netwo	0.83	0.46	1.78	0	0	0	Fail RIM
Commercial	Network PC Power Management	Retail	Existing	E_RT_Netwo	0.81	0.46	1.75	0	0	0	Fail RIM
Commercial	Network PC Power Management	Schools K-12	Existing	E_SC_Netwo	0.83	0.46	1.79	0	0	0	Fail RIM
Commercial	Network PC Power Management	Warehouse	Existing	E_WR_Netw	0.66	0.46	1.43	0	0	0	Fail RIM
Commercial	Network PC Power Management	Assembly	New	N_AS_Netwo	0.82	0.46	1.76	0	0	0	Fail RIM
Commercial	Network PC Power Management	College and University	New	N_CU_Netwo	0.80	0.44	1.79	0	0	0	Fail RIM
Commercial	Network PC Power Management	Grocery	New	N_GR_Netwo	0.82	0.46	1.76	0	0	0	Fail RIM
Commercial	Network PC Power Management	Healthcare	New	N_HC_Netwo	0.83	0.46	1.78	0	0	0	Fail RIM
Commercial	Network PC Power Management	Hospitals	New	N_HS_Netwo	0.80	0.44	1.81	0	0	0	Fail RIM
Commercial	Network PC Power Management	Institutional	New	N_IN_Netwo	0.82	0.46	1.76	0	0	0	Fail RIM
Commercial	Network PC Power Management	Lodging/Hospitality	New	N_LG_Netwo	0.83	0.46	1.78	0	0	0	Fail RIM
Commercial	Network PC Power Management	Miscellaneous	New	N_MS_Netwo	0.84	0.46	1.81	0	0	0	Fail RIM
Commercial	Network PC Power Management	Offices	New	N_OF_Netwo	0.83	0.46	1.78	0	0	0	Fail RIM
Commercial	Network PC Power Management	Restaurants	New	N_RS_Netwo	0.83	0.46	1.78	0	0	0	Fail RIM
Commercial	Network PC Power Management	Retail	New	N_RT_Netwo	0.81	0.46	1.75	0	0	0	Fail RIM
Commercial	Network PC Power Management	Schools K-12	New	N_SC_Netwo	0.83	0.46	1.79	0	0	0	Fail RIM
Commercial	Network PC Power Management	Warehouse	New	N_WR_Netw	0.66	0.46	1.43	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Assembly	Existing	E_AS_Smart	0.09	0.46	1.93	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	College and University	Existing	E_CU_Smart	1.17	0.46	2.54	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Grocery	Existing	E_GR_Smart	1.14	0.46	2.46	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Healthcare	Existing	E_HC_Smart	1.60	0.46	3.46	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Hospitals	Existing	E_HS_Smart	1.75	0.46	3.79	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Institutional	Existing	E_IN_Smart	1.46	0.46	3.16	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Lodging/Hospitality	Existing	E_LG_Smart	1.31	0.46	2.84	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Miscellaneous	Existing	E_MS_Smart	1.78	0.46	3.85	0	0	0	Fail RIM

Commercial	Refrigerated Display Case Lighting Controls	Assembly	New	N_AS_Refrig	0.07	0.48	0.14	0	0	0	Fail TRC
Commercial	Refrigerated Display Case Lighting Controls	College and University	New	N_CU_Refrig	0.07	0.48	0.14	0	0	0	Fail TRC
Commercial	Refrigerated Display Case Lighting Controls	Grocery	New	N_GR_Refrig	0.07	0.48	0.14	0	0	0	Fail TRC
Commercial	Refrigerated Display Case Lighting Controls	Healthcare	New	N_HC_Refrig	0.07	0.48	0.14	0	0	0	Fail TRC
Commercial	Refrigerated Display Case Lighting Controls	Hospitals	New	N_HS_Refrig	0.07	0.48	0.14	0	0	0	Fail TRC
Commercial	Refrigerated Display Case Lighting Controls	Institutional	New	N_IN_Refrig	0.07	0.48	0.14	0	0	0	Fail TRC
Commercial	Refrigerated Display Case Lighting Controls	Lodging/Hospitality	New	N_LG_Refrig	0.07	0.48	0.14	0	0	0	Fail TRC
Commercial	Refrigerated Display Case Lighting Controls	Miscellaneous	New	N_MS_Refrig	0.07	0.48	0.14	0	0	0	Fail TRC
Commercial	Refrigerated Display Case Lighting Controls	Offices	New	N_OF_Refrig	0.07	0.48	0.14	0	0	0	Fail TRC
Commercial	Refrigerated Display Case Lighting Controls	Restaurants	New	N_RS_Refrig	0.07	0.48	0.14	0	0	0	Fail TRC
Commercial	Refrigerated Display Case Lighting Controls	Retail	New	N_RT_Refrig	0.07	0.48	0.14	0	0	0	Fail TRC
Commercial	Refrigerated Display Case Lighting Controls	Schools K-12	New	N_SC_Refrig	0.07	0.48	0.14	0	0	0	Fail TRC
Commercial	Refrigerated Display Case Lighting Controls	Warehouse	New	N_WR_Refri	0.07	0.48	0.14	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Assembly	Existing	E_AS_Strip C	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	College and University	Existing	E_CU_Strip C	0.29	0.44	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Grocery	Existing	E_GR_Strip C	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Healthcare	Existing	E_HC_Strip C	0.29	0.44	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Hospitals	Existing	E_HS_Strip C	0.29	0.44	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Institutional	Existing	E_IN_Strip C	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Lodging/Hospitality	Existing	E_LG_Strip C	0.29	0.44	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Miscellaneous	Existing	E_MS_Strip C	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Offices	Existing	E_OF_Strip C	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Restaurants	Existing	E_RS_Strip C	0.29	0.44	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Retail	Existing	E_RT_Strip C	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Schools K-12	Existing	E_SC_Strip C	0.29	0.44	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Warehouse	Existing	E_WR_Strip	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Assembly	New	N_AS_Strip C	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	College and University	New	N_CU_Strip C	0.29	0.44	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Grocery	New	N_GR_Strip C	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Healthcare	New	N_HC_Strip C	0.29	0.44	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Hospitals	New	N_HS_Strip C	0.29	0.44	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Institutional	New	N_IN_Strip C	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Lodging/Hospitality	New	N_LG_Strip C	0.29	0.44	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Miscellaneous	New	N_MS_Strip C	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Offices	New	N_OF_Strip C	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Restaurants	New	N_RS_Strip C	0.29	0.44	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Retail	New	N_RT_Strip C	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Schools K-12	New	N_SC_Strip C	0.29	0.44	0.68	0	0	0	Fail TRC
Commercial	Strip Curtains for Walk-ins	Warehouse	New	N_WR_Strip	0.31	0.46	0.68	0	0	0	Fail TRC
Commercial	CO Sensors for Parking Garage Exhaust	Assembly	Existing	E_AS_CO Se	3.42	0.38	9.09	0	0	0	Fail 2-year Threshold
Commercial	CO Sensors for Parking Garage Exhaust	College and University	Existing	E_CU_CO Se	3.42	0.38	9.09	0	0	0	Fail 2-year Threshold
Commercial	CO Sensors for Parking Garage Exhaust	Grocery	Existing	E_GR_CO Se	3.42	0.38	9.09	0	0	0	Fail 2-year Threshold
Commercial	CO Sensors for Parking Garage Exhaust	Healthcare	Existing	E_HC_CO Se	3.42	0.38	9.09	0	0	0	Fail 2-year Threshold
Commercial	CO Sensors for Parking Garage Exhaust	Hospitals	Existing	E_HS_CO Se	3.42	0.38	9.09	0	0	0	Fail 2-year Threshold
Commercial	CO Sensors for Parking Garage Exhaust	Institutional	Existing	E_IN_CO Se	3.42	0.38	9.09	0	0	0	Fail 2-year Threshold
Commercial	CO Sensors for Parking Garage Exhaust	Lodging/Hospitality	Existing	E_LG_CO Se	3.42	0.38	9.09	0	0	0	Fail 2-year Threshold
Commercial	CO Sensors for Parking Garage Exhaust	Miscellaneous	Existing	E_MS_CO Se	3.42	0.38	9.09	0	0	0	Fail 2-year Threshold
Commercial	CO Sensors for Parking Garage Exhaust	Offices	Existing	E_OF_CO Se	3.42	0.38	9.09	0	0	0	Fail 2-year Threshold
Commercial	CO Sensors for Parking Garage Exhaust	Restaurants	Existing	E_RS_CO Se	3.42	0.38	9.09	0	0	0	Fail 2-year Threshold
Commercial	CO Sensors for Parking Garage Exhaust	Retail	Existing	E_RT_CO Se	3.42	0.38	9.09	0

Commercial	Smart Strip Plug Outlet	Offices	Existing	E_OF_Smart	1.11	0.46	2.40	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Restaurants	Existing	E_RS_Smart	1.07	0.46	2.31	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Retail	Existing	E_RT_Smart	0.48	0.46	1.05	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Schools K-12	Existing	E_SC_Smart	1.61	0.46	3.48	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Warehouse	Existing	E_WR_Smart	0.13	0.46	0.28	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Assembly	New	N_AS_Smart	0.89	0.46	1.93	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	College and University	New	N_CU_Smart	1.17	0.46	2.54	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Grocery	New	N_GR_Smart	1.14	0.46	2.46	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Healthcare	New	N_HC_Smart	1.60	0.46	3.46	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Hospitals	New	N_HS_Smart	1.75	0.46	3.79	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Institutional	New	N_IN_Smart	1.46	0.46	3.16	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Lodging/Hospitality	New	N_LG_Smart	1.31	0.46	2.84	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Miscellaneous	New	N_MS_Smart	1.78	0.46	3.85	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Offices	New	N_OF_Smart	1.11	0.46	2.40	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Restaurants	New	N_RS_Smart	1.07	0.46	2.31	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Retail	New	N_RT_Smart	0.48	0.46	1.05	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Schools K-12	New	N_SC_Smart	1.61	0.46	3.48	0	0	0	Fail RIM
Commercial	Smart Strip Plug Outlet	Warehouse	New	N_WR_Smart	0.13	0.46	0.28	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Assembly	Existing	E_AS_Anti-S	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	College and University	Existing	E_CU_Anti-S	1.82	0.47	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Grocery	Existing	E_GR_Anti-S	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Healthcare	Existing	E_HC_Anti-S	1.82	0.47	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Hospitals	Existing	E_HS_Anti-S	1.82	0.47	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Institutional	Existing	E_IN_Anti-S	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Lodging/Hospitality	Existing	E_LG_Anti-S	1.82	0.47	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Miscellaneous	Existing	E_MS_Anti-S	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Offices	Existing	E_OF_Anti-S	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Restaurants	Existing	E_RS_Anti-S	1.82	0.47	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Retail	Existing	E_RT_Anti-S	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Schools K-12	Existing	E_SC_Anti-S	1.82	0.47	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Warehouse	Existing	E_WR_Anti-	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Assembly	New	N_AS_Anti-S	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	College and University	New	N_CU_Anti-S	1.82	0.47	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Grocery	New	N_GR_Anti-S	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Healthcare	New	N_HC_Anti-S	1.82	0.47	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Hospitals	New	N_HS_Anti-S	1.82	0.47	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Institutional	New	N_IN_Anti-S	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Lodging/Hospitality	New	N_LG_Anti-S	1.82	0.47	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Miscellaneous	New	N_MS_Anti-S	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Offices	New	N_OF_Anti-S	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Restaurants	New	N_RS_Anti-S	1.82	0.47	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Retail	New	N_RT_Anti-S	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Schools K-12	New	N_SC_Anti-S	1.82	0.47	3.87	0	0	0	Fail RIM
Commercial	Anti-Sweat Controls	Warehouse	New	N_WR_Anti-	1.49	0.39	3.87	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Assembly	Existing	E_AS_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	College and University	Existing	E_CU_Autom	0.08	0.47	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Grocery	Existing	E_GR_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Healthcare	Existing	E_HC_Autom	0.08	0.47	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Hospitals	Existing	E_HS_Autom	0.08	0.47	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Institutional	Existing	E_IN_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Lodging/Hospitality	Existing	E_LG_Autom	0.08	0.47	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Miscellaneous	Existing	E_MS_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Offices	Existing	E_OF_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Restaurants	Existing	E_RS_Autom	0.08	0.47	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Retail	Existing	E_RT_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Schools K-12	Existing	E_SC_Autom	0.08	0.47	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Warehouse	Existing	E_WR_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Assembly	New	N_AS_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	College and University	New	N_CU_Autom	0.08	0.47	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Grocery	New	N_GR_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Healthcare	New	N_HC_Autom	0.08	0.47	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Hospitals	New	N_HS_Autom	0.08	0.47	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Institutional	New	N_IN_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Lodging/Hospitality	New	N_LG_Autom	0.08	0.47	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Miscellaneous	New	N_MS_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Offices	New	N_OF_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Restaurants	New	N_RS_Autom	0.08	0.47	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Retail	New	N_RT_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Schools K-12	New	N_SC_Autom	0.08	0.47	0.16	0	0	0	Fail RIM
Commercial	Automatic Door Closer for Walk-in Coolers and Freezers	Warehouse	New	N_WR_Autom	0.08	0.49	0.16	0	0	0	Fail RIM
Commercial	Demand Defrost	Assembly	Existing	E_AS_Demar	0.25	0.53	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	College and University	Existing	E_CU_Demar	0.24	0.51	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Grocery	Existing	E_GR_Demar	0.25	0.53	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Healthcare	Existing	E_HC_Demar	0.24	0.51	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Hospitals	Existing	E_HS_Demar	0.24	0.51	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Institutional	Existing	E_IN_Demar	0.25	0.53	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Lodging/Hospitality	Existing	E_LG_Demar	0.24	0.51	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Miscellaneous	Existing	E_MS_Demar	0.25	0.53	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Offices	Existing	E_OF_Demar	0.25	0.53	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Restaurants	Existing	E_RS_Demar	0.24	0.51	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Retail	Existing	E_RT_Demar	0.25	0.53	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Schools K-12	Existing	E_SC_Demar	0.24	0.51	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Warehouse	Existing	E_WR_Dema	0.25	0.53	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Assembly	New	N_AS_Demar	0.25	0.53	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	College and University	New	N_CU_Demar	0.24	0.51	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Grocery	New	N_GR_Demar	0.25	0.53	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Healthcare	New	N_HC_Demar	0.24	0.51	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Hospitals	New	N_HS_Demar	0.24	0.51	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Institutional	New	N_IN_Demar	0.25	0.53	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Lodging/Hospitality	New	N_LG_Demar	0.24	0.51	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Miscellaneous	New	N_MS_Demar	0.25	0.53	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Offices	New	N_OF_Demar	0.25	0.53	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Restaurants	New	N_RS_Demar	0.24	0.51	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Retail	New	N_RT_Demar	0.25	0.53	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Schools K-12	New	N_SC_Demar	0.24	0.51	0.47	0	0	0	Fail RIM
Commercial	Demand Defrost	Warehouse	New	N_WR_Dema	0.25	0.53	0.47	0	0	0	Fail RIM

Industrial	Compressed Air Equipment	Chemicals and Plastics		CP_Compres	4.71	0.57	8.21	0	0	0	Fail 2-year Threshold
Industrial	Process Other Systems Optimization	Construction		CS_Process C	5.80	0.45	12.92	0	0	0	Fail 2-year Threshold
Industrial	Plant Energy Management	Construction		CS_Plant Ene	20.00	0.54	36.96	0	0	0	Fail 2-year Threshold
Industrial	Process Heat System Optimization	Construction		CS_Process H	0.27	0.45	0.59	0	0	0	Fail TRC
Industrial	Process Heat Improved Controls	Construction		CS_Process H	0.67	0.58	1.15	0	0	0	Fail TRC
Industrial	Process Refrig System Optimization	Construction		CS_Process R	1.68	0.45	3.74	0	0	0	Fail 2-year Threshold
Industrial	Process Refrig Controls	Construction		CS_Process R	9.68	0.58	16.70	0	0	0	Fail 2-year Threshold
Industrial	Pump System Optimization	Construction		CS_Pump Sys	6.18	0.52	11.88	0	0	0	Fail 2-year Threshold
Industrial	Pump Improved Controls	Construction		CS_Pump Imp	9.95	0.57	17.36	0	0	0	Fail 2-year Threshold
Industrial	Motor Optimization	Construction		CS_Motor Op	0.90	0.52	1.73	0	0	0	Fail TRC
Industrial	Motor Improved Controls	Construction		CS_Motor Im	6.12	0.57	10.68	0	0	0	Fail 2-year Threshold
Industrial	Pump Equipment Upgrade	Construction		CS_Pump Eq	4.77	0.57	8.32	0	0	0	Fail 2-year Threshold
Industrial	Motor Equipment Upgrades	Construction		CS_Motor Eq	2.46	0.52	4.73	0	0	0	Fail 2-year Threshold
Industrial	Fan System Optimization	Construction		CS_Fan Syste	11.62	0.52	22.33	0	0	0	Fail 2-year Threshold
Industrial	Fan Improved Controls	Construction		CS_Fan Impr	19.05	0.57	33.23	0	0	0	Fail 2-year Threshold
Industrial	Fan Equipment Upgrades	Construction		CS_Fan Equi	3.48	0.57	6.07	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls	Construction		CS_Lighting(	3.01	0.53	5.64	0	0	0	Fail 2-year Threshold
Industrial	HVAC Improved Controls	Construction		CS_HVAC Im	12.93	0.59	21.93	0	0	0	Fail 2-year Threshold
Industrial	Building Envelope Improvements	Construction		CS_Building	4.52	0.59	7.67	0	0	0	Fail 2-year Threshold
Industrial	HVAC Equipment Upgrades	Construction		CS_HVAC Eq	5.60	0.61	9.24	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls - Exterior	Construction		CS_Lighting(	1.57	0.28	5.64	0	0	0	Fail 2-year Threshold
Industrial	Efficient Lighting - Exterior	Construction		CS_Efficient	2.65	0.29	9.16	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air System Optimization	Construction		CS_Compres	7.60	0.52	14.61	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air Controls	Construction		CS_Compres	9.98	0.56	17.83	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air Equipment	Construction		CS_Compres	6.13	0.57	10.70	0	0	0	Fail 2-year Threshold
Industrial	Process Other Systems Optimization	Electrical and Electronic Equip.		EE_Process C	1.58	0.45	3.53	0	0	0	Fail 2-year Threshold
Industrial	Plant Energy Management	Electrical and Electronic Equip.		EE_Plant Ene	20.04	0.54	36.96	0	0	0	Fail 2-year Threshold
Industrial	Process Heat System Optimization	Electrical and Electronic Equip.		EE_Process H	1.94	0.45	4.29	0	0	0	Fail 2-year Threshold
Industrial	Process Heat Improved Controls	Electrical and Electronic Equip.		EE_Process H	0.72	0.58	1.23	0	0	0	Fail TRC
Industrial	Process Refrig System Optimization	Electrical and Electronic Equip.		EE_Process R	26.43	0.45	58.84	0	0	0	Fail 2-year Threshold
Industrial	Process Refrig Controls	Electrical and Electronic Equip.		EE_Process R	0.73	0.58	1.26	0	0	0	Fail TRC
Industrial	Process Refrig Equipment Upgrade	Electrical and Electronic Equip.		EE_Process R	4.60	0.53	8.74	0	0	0	Fail 2-year Threshold
Industrial	Pump Improved Controls	Electrical and Electronic Equip.		EE_Pump Im	9.95	0.57	17.36	0	0	0	Fail 2-year Threshold
Industrial	Motor Optimization	Electrical and Electronic Equip.		EE_Motor Op	5.78	0.52	11.11	0	0	0	Fail 2-year Threshold
Industrial	Motor Improved Controls	Electrical and Electronic Equip.		EE_Motor Im	9.95	0.57	17.36	0	0	0	Fail 2-year Threshold
Industrial	Motor Equipment Upgrades	Electrical and Electronic Equip.		EE_Motor Eq	2.50	0.52	4.80	0	0	0	Fail 2-year Threshold
Industrial	Fan Improved Controls	Electrical and Electronic Equip.		EE_Fan Impr	25.81	0.57	45.01	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls	Electrical and Electronic Equip.		EE_Lighting(	2.92	0.53	5.46	0	0	0	Fail 2-year Threshold
Industrial	HVAC Recommissioning	Electrical and Electronic Equip.		EE_HVAC R	11.73	0.53	21.95	0	0	0	Fail 2-year Threshold
Industrial	HVAC Improved Controls	Electrical and Electronic Equip.		EE_HVAC Im	4.80	0.59	8.14	0	0	0	Fail 2-year Threshold
Industrial	Building Envelope Improvements	Electrical and Electronic Equip.		EE_Building	3.75	0.59	6.37	0	0	0	Fail 2-year Threshold
Industrial	HVAC Equipment Upgrades	Electrical and Electronic Equip.		EE_HVAC Eq	6.18	0.61	10.19	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls - Exterior	Electrical and Electronic Equip.		EE_Lighting(	1.52	0.28	5.46	0	0	0	Fail 2-year Threshold
Industrial	Efficient Lighting - Exterior	Electrical and Electronic Equip.		EE_Efficient	2.65	0.29	9.16	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air System Optimization	Electrical and Electronic Equip.		EE_Compres	8.53	0.52	16.35	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air Controls	Electrical and Electronic Equip.		EE_Compres	18.00	0.56	32.15	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air Equipment	Electrical and Electronic Equip.		EE_Compres	16.61	0.57	28.97	0	0	0	Fail 2-year Threshold
Industrial	Process Other Systems Optimization	Lumber/Furniture/Pulp/Paper		LP_Process C	1.61	0.45	3.59	0	0	0	Fail 2-year Threshold
Industrial	Plant Energy Management	Lumber/Furniture/Pulp/Paper		LP_Plant Ene	3.83	0.54	7.09	0	0	0	Fail 2-year Threshold
Industrial	Process Other Equipment Upgrades	Lumber/Furniture/Pulp/Paper		LP_Process C	4.74	0.53	9.01	0	0	0	Fail 2-year Threshold
Industrial	Process Heat System Optimization	Lumber/Furniture/Pulp/Paper		LP_Process H	0.29	0.45	0.64	0	0	0	Fail TRC
Industrial	Process Heat Improved Controls	Lumber/Furniture/Pulp/Paper		LP_Process H	0.72	0.58	1.23	0	0	0	Fail TRC
Industrial	Process Refrig Controls	Lumber/Furniture/Pulp/Paper		LP_Process R	0.73	0.58	1.26	0	0	0	Fail TRC
Industrial	Pump Improved Controls	Lumber/Furniture/Pulp/Paper		LP_Pump Im	9.95	0.57	17.36	0	0	0	Fail 2-year Threshold
Industrial	Motor Optimization	Lumber/Furniture/Pulp/Paper		LP_Motor Op	5.23	0.52	10.01	0	0	0	Fail 2-year Threshold
Industrial	Motor Improved Controls	Lumber/Furniture/Pulp/Paper		LP_Motor Im	12.90	0.57	22.50	0	0	0	Fail 2-year Threshold
Industrial	Motor Equipment Upgrades	Lumber/Furniture/Pulp/Paper		LP_Motor Eq	6.25	0.52	12.02	0	0	0	Fail 2-year Threshold
Industrial	Fan System Optimization	Lumber/Furniture/Pulp/Paper		LP_Fan Syste	11.70	0.52	22.49	0	0	0	Fail 2-year Threshold
Industrial	Fan Improved Controls	Lumber/Furniture/Pulp/Paper		LP_Fan Impr	25.81	0.57	45.01	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls	Lumber/Furniture/Pulp/Paper		LP_Lighting(	2.42	0.53	4.52	0	0	0	Fail 2-year Threshold
Industrial	HVAC Improved Controls	Lumber/Furniture/Pulp/Paper		LP_HVAC Im	37.99	0.59	64.43	0	0	0	Fail 2-year Threshold
Industrial	HVAC Equipment Upgrades	Lumber/Furniture/Pulp/Paper		LP_HVAC Eq	6.18	0.61	10.19	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls - Exterior	Lumber/Furniture/Pulp/Paper		LP_Lighting(	1.25	0.28	4.52	0	0	0	Fail 2-year Threshold
Industrial	Efficient Lighting - Exterior	Lumber/Furniture/Pulp/Paper		LP_Efficient	2.65	0.29	9.16	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air System Optimization	Lumber/Furniture/Pulp/Paper		LP_Compres	8.36	0.52	16.07	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air Controls	Lumber/Furniture/Pulp/Paper		LP_Compres	16.20	0.56	28.93	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air Equipment	Lumber/Furniture/Pulp/Paper		LP_Compres	4.36	0.57	7.61	0	0	0	Fail 2-year Threshold
Industrial	Process Other Systems Optimization	Metal Products and Machinery		MM_Process	1.07	0.45	2.38	0	0	0	Fail 2-year Threshold
Industrial	Plant Energy Management	Metal Products and Machinery		MM_Plant En	4.90	0.54	9.06	0	0	0	Fail 2-year Threshold
Industrial	Process Heat System Optimization	Metal Products and Machinery		MM_Process	0.43	0.45	0.94	0	0	0	Fail TRC
Industrial	Process Heat Improved Controls	Metal Products and Machinery		MM_Process	0.71	0.58	1.23	0	0	0	Fail TRC
Industrial	Process Heat Equipment Upgrade	Metal Products and Machinery		MM_Process	4.06	0.53	7.71	0	0	0	Fail 2-year Threshold
Industrial	Process Refrig System Optimization	Metal Products and Machinery		MM_Process	34.13	0.45	75.97	0	0	0	Fail 2-year Threshold
Industrial	Pump System Optimization	Metal Products and Machinery		MM_Pump S	14.05	0.52	27.00	0	0	0	Fail 2-year Threshold
Industrial	Pump Improved Controls	Metal Products and Machinery		MM_Pump Im	9.95	0.57	17.36	0	0	0	Fail 2-year Threshold
Industrial	Motor Optimization	Metal Products and Machinery		MM_Motor O	5.06	0.52	9.72	0	0	0	Fail 2-year Threshold
Industrial	Motor Improved Controls	Metal Products and Machinery		MM_Motor I	14.00	0.57	24.43	0	0	0	Fail 2-year Threshold
Industrial	Pump Equipment Upgrade	Metal Products and Machinery		MM_Pump E	4.32	0.57	7.54	0	0	0	Fail 2-year Threshold
Industrial	Motor Equipment Upgrades	Metal Products and Machinery		MM_Motor E	2.24	0.52	4.30	0	0	0	Fail 2-year Threshold
Industrial	Fan System Optimization	Metal Products and Machinery		MM_Fan Syst	19.91	0.52	38.25	0	0	0	Fail 2-year Threshold
Industrial	Fan Improved Controls	Metal Products and Machinery		MM_Fan Imp	25.81	0.57	45.01	0	0	0	Fail 2-year Threshold
Industrial	Fan Equipment Upgrades	Metal Products and Machinery		MM_Fan Equ	4.32	0.57	7.54	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls	Metal Products and Machinery		MM_Lighting	2.65	0.53	4.95	0	0	0	Fail 2-year Threshold
Industrial	HVAC Recommissioning	Metal Products and Machinery		MM_HVAC R	0.36	0.53	0.68	0	0	0	Fail TRC
Industrial	HVAC Improved Controls	Metal Products and Machinery		MM_HVAC	11.14	0.59	18.90	0	0	0	Fail 2-year Threshold
Industrial	Building Envelope Improvements	Metal Products and Machinery		MM_Building	5.06	0.59	8.59	0	0	0	Fail 2-year Threshold
Industrial	HVAC Equipment Upgrades	Metal Products and Machinery		MM_HVAC E	5.18	0.61	8.53	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls - Exterior	Metal Products and Machinery		MM_Lighting	1.38	0.28	4.95	0	0	0	Fail 2-year Threshold
Industrial	Efficient Lighting - Exterior	Metal Products and Machinery		MM_Efficien	2.65	0.29	9.16	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air System Optimization	Metal Products and Machinery		MM_Compre	8.62	0.52	16.56	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air Controls	Metal Products and Machinery		MM_Compre	10.97	0.56	19.60	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air Equipment	Metal Products and Machinery		MM_Compre	6.43	0.57	11.22	0	0	0	Fail 2-year Threshold
Industrial	Process Other Systems Optimization	Miscellaneous Manufacturing		MS_Process C	8.19	0.45	18.24	0	0	0	Fail 2-year Threshold
Industrial	Plant Energy Management	Miscellaneous Manufacturing		MS_Plant En	20.05	0.54	36.96	0	0	0	Fail 2-year Threshold
Industrial	Process Heat System Optimization	Miscellaneous Manufacturing		MS_Process H	0.53	0.43	1.17	0	0	0	Fail TRC
Industrial	Process Heat Improved Controls	Miscellaneous Manufacturing		MS_Process H	0.72	0.58	1.23	0	0	0	Fail TRC

Commercial	Floating Head Pressure Controls	Assembly	Existing	E_AS_Floati	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	College and University	Existing	E_CU_Floati	5.12	0.56	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Grocery	Existing	E_GR_Floati	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Healthcare	Existing	E_HC_Floati	5.12	0.56	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Hospitals	Existing	E_HS_Floati	5.12	0.56	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Institutional	Existing	E_IN_Floati	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Lodging/Hospitality	Existing	E_LG_Floati	5.12	0.56	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Miscellaneous	Existing	E_MS_Floati	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Offices	Existing	E_OF_Floati	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Restaurants	Existing	E_RS_Floati	5.12	0.56	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Retail	Existing	E_RT_Floati	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Schools K-12	Existing	E_SC_Floati	5.12	0.56	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Warehouse	Existing	E_WR_Float	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Assembly	New	N_AS_Float	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	College and University	New	N_CU_Float	5.12	0.56	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Grocery	New	N_GR_Float	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Healthcare	New	N_HC_Float	5.12	0.56	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Hospitals	New	N_HS_Float	5.12	0.56	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Institutional	New	N_IN_Float	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Lodging/Hospitality	New	N_LG_Float	5.12	0.56	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Miscellaneous	New	N_MS_Float	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Offices	New	N_OF_Float	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Restaurants	New	N_RS_Float	5.12	0.56	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Retail	New	N_RT_Float	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Schools K-12	New	N_SC_Float	5.12	0.56	9.10	0	0	0	Fail RIM
Commercial	Floating Head Pressure Controls	Warehouse	New	N_WR_Float	5.53	0.61	9.10	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Assembly	Existing	E_AS_Freeze	0.26	0.46	0.56	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	College and University	Existing	E_CU_Freeze	0.24	0.44	0.56	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Grocery	Existing	E_GR_Freeze	0.26	0.46	0.56	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Healthcare	Existing	E_HC_Freeze	0.24	0.44	0.56	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Hospitals	Existing	E_HS_Freeze	0.24	0.44	0.56	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Institutional	Existing	E_IN_Freeze	0.26	0.46	0.56	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Lodging/Hospitality	Existing	E_LG_Freeze	0.24	0.44	0.56	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Miscellaneous	Existing	E_MS_Freeze	0.26	0.46	0.56	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Offices	Existing	E_OF_Freeze	0.26	0.46	0.56	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Restaurants	Existing	E_RS_Freeze	0.24	0.44	0.56	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Retail	Existing	E_RT_Freeze	0.26	0.46	0.56	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Schools K-12	Existing	E_SC_Freeze	0.24	0.44	0.56	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Warehouse	Existing	E_WR_Freez	0.26	0.46	0.56	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Assembly	New	N_AS_Freeze	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	College and University	New	N_CU_Freeze	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Grocery	New	N_GR_Freeze	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Healthcare	New	N_HC_Freeze	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Hospitals	New	N_HS_Freeze	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Institutional	New	N_IN_Freeze	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Lodging/Hospitality	New	N_LG_Freeze	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Miscellaneous	New	N_MS_Freeze	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Offices	New	N_OF_Freeze	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Restaurants	New	N_RS_Freeze	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Retail	New	N_RT_Freeze	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Schools K-12	New	N_SC_Freeze	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Freezer-Cooler Replacement Gaskets	Warehouse	New	N_WR_Freez	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Assembly	Existing	E_AS_High E	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	College and University	Existing	E_CU_High E	0.33	0.55	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Grocery	Existing	E_GR_High E	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Healthcare	Existing	E_HC_High E	0.33	0.55	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Hospitals	Existing	E_HS_High E	0.33	0.55	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Institutional	Existing	E_IN_High E	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Lodging/Hospitality	Existing	E_LG_High E	0.33	0.55	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Miscellaneous	Existing	E_MS_High E	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Offices	Existing	E_OF_High E	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Restaurants	Existing	E_RS_High E	0.33	0.55	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Retail	Existing	E_RT_High E	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Schools K-12	Existing	E_SC_High E	0.33	0.55	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Warehouse	Existing	E_WR_High	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Assembly	New	N_AS_High E	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	College and University	New	N_CU_High E	0.33	0.55	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Grocery	New	N_GR_High E	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Healthcare	New	N_HC_High E	0.33	0.55	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Hospitals	New	N_HS_High E	0.33	0.55	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Institutional	New	N_IN_High E	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Lodging/Hospitality	New	N_LG_High E	0.33	0.55	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Miscellaneous	New	N_MS_High E	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Offices	New	N_OF_High E	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Restaurants	New	N_RS_High E	0.33	0.55	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Retail	New	N_RT_High E	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Schools K-12	New	N_SC_High E	0.33	0.55	0.60	0	0	0	Fail RIM
Commercial	High Efficiency Refrigeration Compressor	Warehouse	New	N_WR_High	0.36	0.59	0.60	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Assembly	Existing	E_AS_High R	0.24	0.57	0.41	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	College and University	Existing	E_CU_High R	0.22	0.54	0.41	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Grocery	Existing	E_GR_High R	0.24	0.57	0.41	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Healthcare	Existing	E_HC_High R	0.22	0.54	0.41	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Hospitals	Existing	E_HS_High R	0.22	0.54	0.41	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Institutional	Existing	E_IN_High R	0.24	0.57	0.41	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Lodging/Hospitality	Existing	E_LG_High R	0.22	0.54	0.41	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Miscellaneous	Existing	E_MS_High R	0.24	0.57	0.41	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Offices	Existing	E_OF_High R	0.24	0.57	0.41	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Restaurants	Existing	E_RS_High R	0.22	0.54	0.41	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Retail	Existing	E_RT_High R	0.24	0.57	0.41	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Schools K-12	Existing	E_SC_High R	0.22	0.54	0.41	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Warehouse	Existing	E_WR_High	0.24	0.57	0.41	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Assembly	New	N_AS_High R	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	College and University	New	N_CU_High R	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Grocery	New	N_GR_High R	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Healthcare	New	N_HC_High R	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Hospitals	New	N_HS_High R	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Institutional	New	N_IN_High R	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Lodging/Hospitality	New	N_LG_High R	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Miscellaneous	New	N_MS_High R	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Offices	New	N_OF_High R	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Restaurants	New	N_RS_High R	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Retail	New	N_RT_High R	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Schools K-12	New	N_SC_High R	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	High R-Value Glass Doors	Warehouse	New	N_WR_High	0.00	0.00	0.00	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Assembly	Existing	E_AS_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	College and University	Existing	E_CU_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Grocery	Existing	E_GR_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Healthcare	Existing	E_HC_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Hospitals	Existing	E_HS_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Institutional	Existing	E_IN_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Lodging/Hospitality	Existing	E_LG_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Miscellaneous	Existing	E_MS_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Offices	Existing	E_OF_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Restaurants	Existing	E_RS_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Retail	Existing	E_RT_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Schools K-12	Existing	E_SC_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Warehouse	Existing	E_WR_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Assembly	New	N_AS_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	College and University	New	N_CU_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Grocery	New	N_GR_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Healthcare	New	N_HC_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Hospitals	New	N_HS_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Institutional	New	N_IN_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Lodging/Hospitality	New	N_LG_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Miscellaneous	New	N_MS_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Offices	New	N_OF_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Restaurants	New	N_RS_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Retail	New	N_RT_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Schools K-12	New	N_SC_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	Night Covers for Display Cases	Warehouse	New	N_WR_Night	0.03	0.47	0.06	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Assembly	Existing	E_AS_PSC to	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	College and University	Existing	E_CU_PSC to	1.77	0.56	3.15	0	0	0	Fail RIM

Industrial	Process Refrig System Optimization	Miscellaneous Manufacturing		MS_Process R	0.60	0.45	1.33	0	0	0	Fail TRC
Industrial	Process Refrig Controls	Miscellaneous Manufacturing		MS_Process R	0.73	0.58	1.26	0	0	0	Fail TRC
Industrial	Pump System Optimization	Miscellaneous Manufacturing		MS_Pump Sy	2.92	0.52	5.61	0	0	0	Fail 2-year Threshold
Industrial	Pump Improved Controls	Miscellaneous Manufacturing		MS_Pump Im	9.95	0.57	17.36	0	0	0	Fail 2-year Threshold
Industrial	Motor Optimization	Miscellaneous Manufacturing		MS_Motor O	0.66	0.52	1.27	0	0	0	Fail TRC
Industrial	Motor Improved Controls	Miscellaneous Manufacturing		MS_Motor Im	9.95	0.57	17.36	0	0	0	Fail 2-year Threshold
Industrial	Pump Equipment Upgrade	Miscellaneous Manufacturing		MS_Pump Eq	4.77	0.57	8.32	0	0	0	Fail 2-year Threshold
Industrial	Fan Improved Controls	Miscellaneous Manufacturing		MS_Fan Impr	25.81	0.57	45.01	0	0	0	Fail 2-year Threshold
Industrial	Fan Equipment Upgrades	Miscellaneous Manufacturing		MS_Fan Equi	3.48	0.57	6.07	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls	Miscellaneous Manufacturing		MS_Lighting	3.74	0.53	6.98	0	0	0	Fail 2-year Threshold
Industrial	HVAC Improved Controls	Miscellaneous Manufacturing		MS_HVAC Im	104.66	0.59	177.51	0	0	0	Fail 2-year Threshold
Industrial	Building Envelope Improvements	Miscellaneous Manufacturing		MS_Building	6.54	0.59	11.09	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls - Exterior	Miscellaneous Manufacturing		MS_Lighting	1.94	0.28	6.98	0	0	0	Fail 2-year Threshold
Industrial	Efficient Lighting - Exterior	Miscellaneous Manufacturing		MS_Efficient	2.65	0.29	9.16	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air System Optimization	Miscellaneous Manufacturing		MS_Compres	5.55	0.52	10.67	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air Controls	Miscellaneous Manufacturing		MS_Compres	84.97	0.56	151.77	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air Equipment	Miscellaneous Manufacturing		MS_Compres	44.04	0.57	76.83	0	0	0	Fail 2-year Threshold
Industrial	Process Other Systems Optimization	Primary Resources Industries		PR_Process O	0.99	0.45	2.19	0	0	0	Fail TRC
Industrial	Plant Energy Management	Primary Resources Industries		PR_Plant Ene	20.06	0.54	36.96	0	0	0	Fail 2-year Threshold
Industrial	Process Heat System Optimization	Primary Resources Industries		PR_Process H	0.47	0.45	1.05	0	0	0	Fail TRC
Industrial	Process Heat Improved Controls	Primary Resources Industries		PR_Process H	0.72	0.58	1.23	0	0	0	Fail TRC
Industrial	Process Refrig System Optimization	Primary Resources Industries		PR_Process R	34.13	0.45	75.97	0	0	0	Fail 2-year Threshold
Industrial	Process Refrig Controls	Primary Resources Industries		PR_Process R	0.73	0.58	1.26	0	0	0	Fail TRC
Industrial	Process Refrig Equipment Upgrade	Primary Resources Industries		PR_Process R	2.82	0.53	5.36	0	0	0	Fail 2-year Threshold
Industrial	Pump System Optimization	Primary Resources Industries		PR_Pump Sy	48.99	0.52	94.13	0	0	0	Fail 2-year Threshold
Industrial	Pump Improved Controls	Primary Resources Industries		PR_Pump Im	9.95	0.57	17.36	0	0	0	Fail 2-year Threshold
Industrial	Motor Optimization	Primary Resources Industries		PR_Motor Op	6.67	0.52	12.82	0	0	0	Fail 2-year Threshold
Industrial	Motor Improved Controls	Primary Resources Industries		PR_Motor Im	9.95	0.57	17.36	0	0	0	Fail 2-year Threshold
Industrial	Pump Equipment Upgrade	Primary Resources Industries		PR_Pump Eq	5.71	0.57	9.96	0	0	0	Fail 2-year Threshold
Industrial	Motor Equipment Upgrades	Primary Resources Industries		PR_Motor Eq	2.38	0.52	4.56	0	0	0	Fail 2-year Threshold
Industrial	Fan System Optimization	Primary Resources Industries		PR_Fan Syste	126.06	0.52	242.22	0	0	0	Fail 2-year Threshold
Industrial	Fan Improved Controls	Primary Resources Industries		PR_Fan Impr	25.81	0.57	45.01	0	0	0	Fail 2-year Threshold
Industrial	Fan Equipment Upgrades	Primary Resources Industries		PR_Fan Equi	5.71	0.57	9.96	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls	Primary Resources Industries		PR_Lighting	2.87	0.53	5.36	0	0	0	Fail 2-year Threshold
Industrial	HVAC Improved Controls	Primary Resources Industries		PR_HVAC Im	20.96	0.59	35.54	0	0	0	Fail 2-year Threshold
Industrial	Building Envelope Improvements	Primary Resources Industries		PR_Building	5.02	0.59	8.52	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls - Exterior	Primary Resources Industries		PR_Lighting	1.49	0.28	5.36	0	0	0	Fail 2-year Threshold
Industrial	Efficient Lighting - Exterior	Primary Resources Industries		PR_Efficient	2.65	0.29	9.16	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air System Optimization	Primary Resources Industries		PR_Compres	8.97	0.52	17.24	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air Controls	Primary Resources Industries		PR_Compres	12.13	0.56	21.66	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air Equipment	Primary Resources Industries		PR_Compres	5.25	0.57	9.16	0	0	0	Fail 2-year Threshold
Industrial	Process Other Systems Optimization	Stone/Clay/Glass/Concrete		ST_Process O	8.19	0.45	18.24	0	0	0	Fail 2-year Threshold
Industrial	Plant Energy Management	Stone/Clay/Glass/Concrete		ST_Plant Ene	19.99	0.54	36.96	0	0	0	Fail 2-year Threshold
Industrial	Process Heat System Optimization	Stone/Clay/Glass/Concrete		ST_Process H	0.25	0.45	0.56	0	0	0	Fail TRC
Industrial	Process Heat Improved Controls	Stone/Clay/Glass/Concrete		ST_Process H	0.72	0.58	1.23	0	0	0	Fail TRC
Industrial	Process Refrig Controls	Stone/Clay/Glass/Concrete		ST_Process R	0.73	0.58	1.26	0	0	0	Fail TRC
Industrial	Pump System Optimization	Stone/Clay/Glass/Concrete		ST_Pump Sys	0.00	0.00	0.00	0	0	0	Fail TRC
Industrial	Pump Improved Controls	Stone/Clay/Glass/Concrete		ST_Pump Im	9.95	0.57	17.36	0	0	0	Fail 2-year Threshold
Industrial	Motor Optimization	Stone/Clay/Glass/Concrete		ST_Motor Op	6.28	0.52	12.07	0	0	0	Fail 2-year Threshold
Industrial	Motor Improved Controls	Stone/Clay/Glass/Concrete		ST_Motor Im	9.95	0.57	17.36	0	0	0	Fail 2-year Threshold
Industrial	Pump Equipment Upgrade	Stone/Clay/Glass/Concrete		ST_Pump Eq	3.48	0.57	6.07	0	0	0	Fail 2-year Threshold
Industrial	Motor Equipment Upgrades	Stone/Clay/Glass/Concrete		ST_Motor Eq	6.70	0.52	12.88	0	0	0	Fail 2-year Threshold
Industrial	Fan Improved Controls	Stone/Clay/Glass/Concrete		ST_Fan Impr	25.81	0.57	45.01	0	0	0	Fail 2-year Threshold
Industrial	Fan Equipment Upgrades	Stone/Clay/Glass/Concrete		ST_Fan Equi	3.48	0.57	6.07	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls	Stone/Clay/Glass/Concrete		ST_Lighting	2.81	0.53	5.26	0	0	0	Fail 2-year Threshold
Industrial	HVAC Improved Controls	Stone/Clay/Glass/Concrete		ST_HVAC Im	16.03	0.59	27.20	0	0	0	Fail 2-year Threshold
Industrial	Building Envelope Improvements	Stone/Clay/Glass/Concrete		ST_Building	4.22	0.59	7.15	0	0	0	Fail 2-year Threshold
Industrial	HVAC Equipment Upgrades	Stone/Clay/Glass/Concrete		ST_HVAC Eq	6.18	0.61	10.19	0	0	0	Fail 2-year Threshold
Industrial	Lighting Controls - Exterior	Stone/Clay/Glass/Concrete		ST_Lighting	1.46	0.28	5.26	0	0	0	Fail 2-year Threshold
Industrial	Efficient Lighting - Exterior	Stone/Clay/Glass/Concrete		ST_Efficient	2.65	0.29	9.16	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air System Optimization	Stone/Clay/Glass/Concrete		ST_Compres	6.66	0.52	12.81	0	0	0	Fail 2-year Threshold
Industrial	Compressed Air Controls	Stone/Clay/Glass/Concrete		ST_Compres	10.34	0.56	18.46	0	0	0	Fail 2-year Threshold
Industrial	Process Other Systems Optimization	Textiles and Leather		TX_Process O	3.48	0.45	7.74	0	0	0	Fail 2-year Threshold
Industrial	Process Heat System Optimization	Textiles and Leather		TX_Process H	0.08	0.45	0.17	0	0	0	Fail TRC
Industrial	Process Heat Equipment Upgrade	Textiles and Leather		TX_Process H	11.10	0.53	21.11	0	0	0	Fail 2-year Threshold
Industrial	Process Refrig Controls	Textiles and Leather		TX_Process R	0.73	0.58	1.26	0	0	0	Fail TRC
Industrial	Process Refrig Equipment Upgrade	Textiles and Leather		TX_Process R	2.52	0.53	4.79	0	0	0	Fail 2-year Threshold
Industrial	Pump Improved Controls	Textiles and Leather		TX_Pump Im	9.95	0.57	17.36	0	0	0	Fail 2-year Threshold
Industrial	Motor Improved Controls	Textiles and Leather		TX_Motor Im	9.95	0.57	17.36	0	0	0	Fail 2-year Threshold
Industrial	Pump Equipment Upgrade	Textiles and Leather		TX_Pump Eq	4.96	0.57	8.66	0	0	0	Fail 2-year Threshold
Industrial	Motor Equipment Upgrades	Textiles and Leather		TX_Motor Eq	2.92	0.52	5.60	0	0	0	Fail 2

Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Grocery	Existing	E_GR_PSC to	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Healthcare	Existing	E_HC_PSC to	1.77	0.56	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Hospitals	Existing	E_HS_PSC to	1.77	0.56	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Institutional	Existing	E_IN_PSC to	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Lodging/Hospitality	Existing	E_LG_PSC to	1.77	0.56	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Miscellaneous	Existing	E_MS_PSC to	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Offices	Existing	E_OF_PSC to	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Restaurants	Existing	E_RS_PSC to	1.77	0.56	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Retail	Existing	E_RT_PSC to	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Schools K-12	Existing	E_SC_PSC to	1.77	0.56	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Warehouse	Existing	E_WR_PSC t	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Assembly	New	N_AS_PSC to	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	College and University	New	N_CU_PSC to	1.77	0.56	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Grocery	New	N_GR_PSC to	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Healthcare	New	N_HC_PSC to	1.77	0.56	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Hospitals	New	N_HS_PSC to	1.77	0.56	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Institutional	New	N_IN_PSC to	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Lodging/Hospitality	New	N_LG_PSC to	1.77	0.56	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Miscellaneous	New	N_MS_PSC to	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Offices	New	N_OF_PSC to	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Restaurants	New	N_RS_PSC to	1.77	0.56	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Retail	New	N_RT_PSC to	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Schools K-12	New	N_SC_PSC to	1.77	0.56	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Warehouse	New	N_WR_PSC t	1.84	0.58	3.15	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Assembly	Existing	E_AS_PSC to	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	College and University	Existing	E_CU_PSC to	1.15	0.56	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Grocery	Existing	E_GR_PSC to	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Healthcare	Existing	E_HC_PSC to	1.15	0.56	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Hospitals	Existing	E_HS_PSC to	1.15	0.56	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Institutional	Existing	E_IN_PSC to	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Lodging/Hospitality	Existing	E_LG_PSC to	1.15	0.56	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Miscellaneous	Existing	E_MS_PSC to	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Offices	Existing	E_OF_PSC to	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Restaurants	Existing	E_RS_PSC to	1.15	0.56	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Retail	Existing	E_RT_PSC to	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Schools K-12	Existing	E_SC_PSC to	1.15	0.56	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Warehouse	Existing	E_WR_PSC t	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Assembly	New	N_AS_PSC to	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	College and University	New	N_CU_PSC to	1.15	0.56	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Grocery	New	N_GR_PSC to	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Healthcare	New	N_HC_PSC to	1.15	0.56	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Hospitals	New	N_HS_PSC to	1.15	0.56	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Institutional	New	N_IN_PSC to	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Lodging/Hospitality	New	N_LG_PSC to	1.15	0.56	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Miscellaneous	New	N_MS_PSC to	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Offices	New	N_OF_PSC to	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Restaurants	New	N_RS_PSC to	1.15	0.56	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Retail	New	N_RT_PSC to	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Schools K-12	New	N_SC_PSC to	1.15	0.56	2.05	0	0	0	Fail RIM
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Warehouse	New	N_WR_PSC t	1.19	0.58	2.05	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Assembly	Existing	E_AS_Refrig	0.18	0.48	0.38	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	College and University	Existing	E_CU_Refrig	0.18	0.48	0.38	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Grocery	Existing	E_GR_Refrig	0.18	0.48	0.38	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Healthcare	Existing	E_HC_Refrig	0.18	0.48	0.38	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Hospitals	Existing	E_HS_Refrig	0.18	0.48	0.38	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Institutional	Existing	E_IN_Refrig	0.18	0.48	0.38	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Lodging/Hospitality	Existing	E_LG_Refrig	0.18	0.48	0.38	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Miscellaneous	Existing	E_MS_Refrig	0.18	0.48	0.38	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Offices	Existing	E_OF_Refrig	0.18	0.48	0.38	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Restaurants	Existing	E_RS_Refrig	0.18	0.48	0.38	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Retail	Existing	E_RT_Refrig	0.18	0.48	0.38	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Schools K-12	Existing	E_SC_Refrig	0.18	0.48	0.38	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Warehouse	Existing	E_WR_Refrig	0.18	0.48	0.38	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Assembly	New	N_AS_Refrig	0.07	0.48	0.14	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	College and University	New	N_CU_Refrig	0.07	0.48	0.14	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Grocery	New	N_GR_Refrig	0.07	0.48	0.14	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Healthcare	New	N_HC_Refrig	0.07	0.48	0.14	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Hospitals	New	N_HS_Refrig	0.07	0.48	0.14	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Institutional	New	N_IN_Refrig	0.07	0.48	0.14	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Lodging/Hospitality	New	N_LG_Refrig	0.07	0.48	0.14	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Miscellaneous	New	N_MS_Refrig	0.07	0.48	0.14	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Offices	New	N_OF_Refrig	0.07	0.48	0.14	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Restaurants	New	N_RS_Refrig	0.07	0.48	0.14	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Retail	New	N_RT_Refrig	0.07	0.48	0.14	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Schools K-12	New	N_SC_Refrig	0.07	0.48	0.14	0	0	0	Fail RIM
Commercial	Refrigerated Display Case Lighting Controls	Warehouse	New	N_WR_Refrig	0.07	0.48	0.14	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Assembly	Existing	E_AS_Strip C	0.31	0.46	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	College and University	Existing	E_CU_Strip C	0.29	0.44	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Grocery	Existing	E_GR_Strip C	0.31	0.46	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Healthcare	Existing	E_HC_Strip C	0.29	0.44	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Hospitals	Existing	E_HS_Strip C	0.29	0.44	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Institutional	Existing	E_IN_Strip C	0.31	0.46	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Lodging/Hospitality	Existing	E_LG_Strip C	0.29	0.44	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Miscellaneous	Existing	E_MS_Strip C	0.31	0.46	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Offices	Existing	E_OF_Strip C	0.31	0.46	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Restaurants	Existing	E_RS_Strip C	0.29	0.44	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Retail	Existing	E_RT_Strip C	0.31	0.46	0.68	0	0	0	Fail RIM

Commercial	Solar Voltaic (17.1w/sf2)	Assembly	New	AS_Solar Vo	0.83	0.64	1.29	0	0	0	Fail TRC
Commercial	Solar Voltaic (17.1w/sf2)	College and University	New	CU_Solar Vo	0.83	0.64	1.29	0	0	0	Fail TRC
Commercial	Solar Voltaic (17.1w/sf2)	Grocery	New	GR_Solar Vo	0.83	0.64	1.29	0	0	0	Fail TRC
Commercial	Solar Voltaic (17.1w/sf2)	Healthcare	New	HC_Solar Vo	0.83	0.64	1.29	0	0	0	Fail TRC
Commercial	Solar Voltaic (17.1w/sf2)	Hospitals	New	HS_Solar Vo	0.83	0.64	1.29	0	0	0	Fail TRC
Commercial	Solar Voltaic (17.1w/sf2)	Institutional	New	IN_Solar Vol	0.83	0.64	1.29	0	0	0	Fail TRC
Commercial	Solar Voltaic (17.1w/sf2)	Lodging/Hospitality	New	LG_Solar Vo	0.83	0.64	1.29	0	0	0	Fail TRC
Commercial	Solar Voltaic (17.1w/sf2)	Miscellaneous	New	MS_Solar Vo	0.83	0.64	1.29	0	0	0	Fail TRC
Commercial	Solar Voltaic (17.1w/sf2)	Offices	New	OF_Solar Vol	0.83	0.64	1.29	0	0	0	Fail TRC
Commercial	Solar Voltaic (17.1w/sf2)	Restaurants	New	RS_Solar Vol	0.83	0.64	1.29	0	0	0	Fail TRC
Commercial	Solar Voltaic (17.1w/sf2)	Retail	New	RT_Solar Vol	0.83	0.64	1.29	0	0	0	Fail TRC
Commercial	Solar Voltaic (17.1w/sf2)	Schools K-12	New	SC_Solar Vol	0.83	0.64	1.29	0	0	0	Fail TRC
Commercial	Solar Voltaic (17.1w/sf2)	Warehouse	New	WR_Solar Vo	0.83	0.64	1.29	0	0	0	Fail TRC
Commercial	Storage with other DSM (EE and DR) - Seg 1 - 15 MWh		New	Storage with	0.04	0.00	0.00	0	0	0	Fail TRC
Commercial	Storage with other DSM (EE and DR) - Seg 2 - 25 MWh		New	Storage with	0.02	0.00	0.00	0	0	0	Fail TRC
Commercial	Storage with other DSM (EE and DR) - Seg 3 - 50 MWh		New	Storage with	0.02	0.00	0.00	0	0	0	Fail TRC
Commercial	Storage with other DSM (EE and DR) - Seg 4 51+ MWh		New	Storage with	0.02	0.00	0.00	0	0	0	Fail TRC
Nonresidential	5500 kW Steam Turbine-Biomass		New	5500 kW Ste	0.44	0.58	0.76	0	0	0	Fail TRC
Nonresidential	3500 kW Steam Turbine-Biomass		New	3500 kW Ste	0.41	0.58	0.71	0	0	0	Fail TRC
Nonresidential	3500 kW Gas Turbine		New	3500 kW Gas	0.33	0.61	0.54	0	0	0	Fail TRC
Nonresidential	3000 kW Gas Turbine		New	3000 kW Gas	0.32	0.61	0.53	0	0	0	Fail TRC
Nonresidential	2500 kW Gas Turbine		New	2500 kW Gas	0.32	0.61	0.52	0	0	0	Fail TRC
Nonresidential	4500 kW Reciprocating Engine		New	4500 kW Rec	0.61	0.92	0.66	0	0	0	Fail TRC
Nonresidential	1500 kW Steam Turbine-Biomass		New	1500 kW Ste	0.45	0.58	0.77	0	0	0	Fail TRC
Nonresidential	3000 kW Reciprocating Engine		New	3000 kW Rec	0.60	0.92	0.65	0	0	0	Fail TRC
Nonresidential	1125 kW Fuel Cell		New	1125 kW Fuel	0.35	0.56	0.62	0	0	0	Fail TRC
Nonresidential	800 kW Fuel Cell-Biogas		New	800 kW Fuel	0.31	0.56	0.55	0	0	0	Fail TRC
Nonresidential	1250 kW Reciprocating Engine		New	1250 kW Rec	0.54	0.92	0.58	0	0	0	Fail TRC
Nonresidential	1250 kW Reciprocating Engine-Biogas		New	1250 kW Rec	0.52	0.92	0.56	0	0	0	Fail TRC
Nonresidential	500 kW Fuel Cell		New	500 kW Fuel	0.27	0.56	0.48	0	0	0	Fail TRC
Nonresidential	350 kW Reciprocating Engine		New	350 kW Recip	0.47	0.92	0.50	0	0	0	Fail TRC
Nonresidential	175 kW Fuel Cell		New	175 kW Fuel	0.15	0.56	0.27	0	0	0	Fail TRC
Nonresidential	200 kW Micro Turbine		New	200 kW Micr	0.21	0.69	0.31	0	0	0	Fail TRC
Nonresidential	150 kW Reciprocating Engine		New	150 kW Recip	0.44	0.92	0.48	0	0	0	Fail TRC
Nonresidential	100 kW Micro Turbine		New	100 kW Micr	0.23	0.69	0.30	0	0	0	Fail TRC
Nonresidential	100 kW Micro Turbine- Biogas		New	100 kW Micr	0.20	0.69	0.29	0	0	0	Fail TRC
Nonresidential	50 kW Micro Turbine		New	50 kW Micro	0.20	0.69	0.29	0	0	0	Fail TRC

Commercial	Strip Curtains for Walk-ins	Schools K-12	Existing	E_SC_Strip C	0.29	0.44	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Warehouse	Existing	E_WR_Strip	0.31	0.46	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Assembly	New	N_AS_Strip C	0.31	0.46	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	College and University	New	N_CU_Strip	0.29	0.44	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Grocery	New	N_GR_Strip	0.31	0.46	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Healthcare	New	N_HC_Strip	0.29	0.44	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Hospitals	New	N_HS_Strip C	0.29	0.44	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Institutional	New	N_IN_Strip C	0.31	0.46	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Lodging/Hospitality	New	N_LG_Strip	0.29	0.44	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Miscellaneous	New	N_MS_Strip	0.31	0.46	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Offices	New	N_OF_Strip C	0.31	0.46	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Restaurants	New	N_RS_Strip C	0.29	0.44	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Retail	New	N_RT_Strip C	0.31	0.46	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Schools K-12	New	N_SC_Strip C	0.29	0.44	0.68	0	0	0	Fail RIM
Commercial	Strip Curtains for Walk-ins	Warehouse	New	N_WR_Strip	0.31	0.46	0.68	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Assembly	Existing	E_AS_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	College and University	Existing	E_CU_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Grocery	Existing	E_GR_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Healthcare	Existing	E_HC_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Hospitals	Existing	E_HS_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Institutional	Existing	E_IN_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Lodging/Hospitality	Existing	E_LG_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Miscellaneous	Existing	E_MS_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Offices	Existing	E_OF_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Restaurants	Existing	E_RS_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Retail	Existing	E_RT_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Schools K-12	Existing	E_SC_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Warehouse	Existing	E_WR_CO S	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Assembly	New	N_AS_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	College and University	New	N_CU_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Grocery	New	N_GR_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Healthcare	New	N_HC_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Hospitals	New	N_HS_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Institutional	New	N_IN_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Lodging/Hospitality	New	N_LG_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Miscellaneous	New	N_MS_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Offices	New	N_OF_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Restaurants	New	N_RS_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Retail	New	N_RT_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Schools K-12	New	N_SC_CO Se	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	CO Sensors for Parking Garage Exhaust	Warehouse	New	N_WR_CO S	3.42	0.38	9.09	0	0	0	Fail RIM
Commercial	Demand Controlled Ventilation	College and University	Existing	E_CU_Dema	6.14	1.25	4.90	0	0	0	Fail 2-year Threshold
Commercial	Demand Controlled Ventilation	Healthcare	Existing	E_HC_Dema	5.99	1.25	4.77	0	0	0	Fail 2-year Threshold
Commercial	Demand Controlled Ventilation	Hospitals	Existing	E_HS_Dema	8.91	1.25	7.10	0	0	0	Fail 2-year Threshold
Commercial	Demand Controlled Ventilation	Institutional	Existing	E_IN_Dema	6.14	1.25	4.89	0	0	0	Fail 2-year Threshold
Commercial	Demand Controlled Ventilation	Schools K-12	Existing	E_SC_Dema	6.32	1.25	5.04	0	0	0	Fail 2-year Threshold
Commercial	Demand Controlled Ventilation	College and University	New	N_CU_Dema	6.14	1.25	4.90	0	0	0	Fail 2-year Threshold
Commercial	Demand Controlled Ventilation	Healthcare	New	N_HC_Dema	5.99	1.25	4.77	0	0	0	Fail 2-year Threshold
Commercial	Demand Controlled Ventilation	Hospitals	New	N_HS_Dema	8.91	1.25	7.10	0	0	0	Fail 2-year Threshold
Commercial	Demand Controlled Ventilation	Institutional	New	N_IN_Dema	6.14	1.25	4.89	0	0	0	Fail 2-year Threshold
Commercial	Demand Controlled Ventilation	Schools K-12	New	N_SC_Dema	6.32	1.25	5.04	0	0	0	Fail 2-year Threshold
Commercial	VAV System	Assembly	Existing	E_AS_VAV S	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	College and University	Existing	E_CU_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Grocery	Existing	E_GR_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Healthcare	Existing	E_HC_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Hospitals	Existing	E_HS_VAV S	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Institutional	Existing	E_IN_VAV S	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Lodging/Hospitality	Existing	E_LG_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Miscellaneous	Existing	E_MS_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Offices	Existing	E_OF_VAV S	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Restaurants	Existing	E_RS_VAV S	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Retail	Existing	E_RT_VAV S	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Schools K-12	Existing	E_SC_VAV S	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Warehouse	Existing	E_WR_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Assembly	New	N_AS_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	College and University	New	N_CU_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Grocery	New	N_GR_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Healthcare	New	N_HC_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Hospitals	New	N_HS_VAV S	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Institutional	New	N_IN_VAV S	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Lodging/Hospitality	New	N_LG_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Miscellaneous	New	N_MS_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Offices	New	N_OF_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Restaurants	New	N_RS_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Retail	New	N_RT_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Schools K-12	New	N_SC_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	VAV System	Warehouse	New	N_WR_VAV	8.28	0.76	10.91	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Assembly	Existing	E_AS_Retro-	1.32	0.93	1.42	0	0	0	Fail RIM
Commercial	Retro-Commissioning	College and University	Existing	E_CU_Retro-	1.82	0.85	2.15	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Grocery	Existing	E_GR_Retro-	14.41	1.03	13.97	0	0	0	Fail 2-year Threshold
Commercial	Retro-Commissioning	Healthcare	Existing	E_HC_Retro-	5.30	0.93	5.71	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Hospitals	Existing	E_HS_Retro-	4.84	0.85	5.71	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Institutional	Existing	E_IN_Retro-	5.97	0.93	6.44	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Lodging/Hospitality	Existing	E_LG_Retro-	3.32	1.03	3.22	0	0	0	Fail 2-year Threshold
Commercial	Retro-Commissioning	Miscellaneous	Existing	E_MS_Retro-	4.08	0.93	4.40	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Offices	Existing	E_OF_Retro-	5.47	0.93	5.89	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Restaurants	Existing	E_RS_Retro-	13.92	1.03	13.50	0	0	0	Fail 2-year Threshold
Commercial	Retro-Commissioning	Retail	Existing	E_RT_Retro-	2.70	1.03	2.62	0	0	0	Fail 2-year Threshold
Commercial	Retro-Commissioning	Schools K-12	Existing	E_SC_Retro-	1.99	0.93	2.15	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Warehouse	Existing	E_WR_Retro-	0.64	0.93	0.69	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Assembly	New	N_AS_Retro-	1.32	0.93	1.42	0	0	0	Fail RIM
Commercial	Retro-Commissioning	College and University	New	N_CU_Retro-	1.82	0.85	2.15	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Grocery	New	N_GR_Retro-	14.41	1.03	13.97	0	0	0	Fail 2-year Threshold
Commercial	Retro-Commissioning	Healthcare	New	N_HC_Retro-	5.30	0.93	5.71	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Hospitals	New	N_HS_Retro-	4.84	0.85	5.71	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Institutional	New	N_IN_Retro-4	5.97	0.93	6.44	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Lodging/Hospitality	New	N_LG_Retro-	3.32	1.03	3.22	0	0	0	Fail 2-year Threshold
Commercial	Retro-Commissioning	Miscellaneous	New	N_MS_Retro-	4.08	0.93	4.40	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Offices	New	N_OF_Retro-	5.47	0.93	5.89	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Restaurants	New	N_RS_Retro-	13.92	1.03	13.50	0	0	0	Fail 2-year Threshold
Commercial	Retro-Commissioning	Retail	New	N_RT_Retro-	2.70	1.03	2.62	0	0	0	Fail 2-year Threshold
Commercial	Retro-Commissioning	Schools K-12	New	N_SC_Retro-	1.99	0.93	2.15	0	0	0	Fail RIM
Commercial	Retro-Commissioning	Warehouse	New	N_WR_Retro	0.64	0.93	0.69	0	0	0	Fail RIM
Industrial	Process Other Systems Optimization	Agriculture and Assembly		AA_Process	8.19	0.45	18.24	0	0	0	Fail RIM
Industrial	Plant Energy Management	Agriculture and Assembly		AA_Plant Ene	3.85	0.54	7.09	0	0	0	Fail RIM
Industrial	Process Heat System Optimization	Agriculture and Assembly		AA_Process	0.05	0.45	0.10	0	0	0	Fail RIM
Industrial	Process Heat Improved Controls	Agriculture and Assembly		AA_Process	0.72	0.58	1.23	0	0	0	Fail RIM
Industrial	Process Refrig System Optimization	Agriculture and Assembly		AA_Process	0.91	0.45	2.02	0	0	0	Fail RIM
Industrial	Process Refrig Controls	Agriculture and Assembly		AA_Process	1.45	0.58	2.50	0	0	0	Fail RIM
Industrial	Process Refrig Equipment Upgrade	Agriculture and Assembly		AA_Process	2.26	0.53	4.29	0	0	0	Fail RIM
Industrial	Pump System Optimization	Agriculture and Assembly		AA_Pump Sy	7.41	0.52	14.23	0	0	0	Fail RIM
Industrial	Pump Improved Controls	Agriculture and Assembly		AA_Pump Im	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Motor Optimization	Agriculture and Assembly		AA_Motor Op	3.19	0.52	6.14	0	0	0	Fail RIM
Industrial	Motor Improved Controls	Agriculture and Assembly		AA_Motor In	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Pump Equipment Upgrade	Agriculture and Assembly		AA_Pump Eq	2.14	0.57	3.73	0	0	0	Fail RIM
Industrial	Motor Equipment Upgrades	Agriculture and Assembly		AA_Motor Eq	2.59	0.52	4.98	0	0	0	Fail RIM
Industrial	Fan Improved Controls	Agriculture and Assembly		AA_Fan Impr	25.81	0.57	45.01	0	0	0	Fail RIM
Industrial	Fan Equipment Upgrades	Agriculture and Assembly		AA_Fan Equ	2.94	0.57	5.12	0	0	0	Fail RIM
Industrial	Lighting Controls	Agriculture and Assembly		AA_Lighting	3.34	0.53	6.24	0	0	0	Fail RIM

Industrial	Efficient Lighting - Other Interior Lighting	Agriculture and Assembly		AA_Efficient	1.54	0.58	2.63	0	0	0	Fail RIM
Industrial	Efficient Lighting - High Bay	Agriculture and Assembly		AA_Efficient	2.84	0.58	4.86	0	0	0	Fail RIM
Industrial	HVAC Recommissioning	Agriculture and Assembly		AA_HVAC R	5.22	0.53	9.77	0	0	0	Fail RIM
Industrial	HVAC Improved Controls	Agriculture and Assembly		AA_HVAC Ir	73.89	0.59	125.33	0	0	0	Fail RIM
Industrial	Building Envelope Improvements	Agriculture and Assembly		AA_Building	4.05	0.59	6.87	0	0	0	Fail RIM
Industrial	HVAC Equipment Upgrades	Agriculture and Assembly		AA_HVAC E	6.18	0.61	10.19	0	0	0	Fail RIM
Industrial	Lighting Controls - Exterior	Agriculture and Assembly		AA_Lighting	1.73	0.28	6.24	0	0	0	Fail RIM
Industrial	Efficient Lighting - Exterior	Agriculture and Assembly		AA_Efficient	2.65	0.29	9.16	0	0	0	Fail RIM
Industrial	Compressed Air System Optimization	Agriculture and Assembly		AA_Compres	8.27	0.52	15.89	0	0	0	Fail RIM
Industrial	Compressed Air Controls	Agriculture and Assembly		AA_Compres	2.25	0.56	4.02	0	0	0	Fail RIM
Industrial	Compressed Air Equipment	Agriculture and Assembly		AA_Compres	2.76	0.57	4.81	0	0	0	Fail RIM
Industrial	Process Other Systems Optimization	Chemicals and Plastics		CP_Process C	8.19	0.45	18.24	0	0	0	Fail RIM
Industrial	Plant Energy Management	Chemicals and Plastics		CP_Plant Ene	19.98	0.54	36.96	0	0	0	Fail RIM
Industrial	Process Heat System Optimization	Chemicals and Plastics		CP_Process H	0.22	0.45	0.49	0	0	0	Fail RIM
Industrial	Process Heat Improved Controls	Chemicals and Plastics		CP_Process H	1.05	0.58	1.81	0	0	0	Fail RIM
Industrial	Process Heat Equipment Upgrade	Chemicals and Plastics		CP_Process H	1.79	0.53	3.40	0	0	0	Fail RIM
Industrial	Process Refrig System Optimization	Chemicals and Plastics		CP_Process R	9.09	0.45	20.24	0	0	0	Fail RIM
Industrial	Process Refrig Controls	Chemicals and Plastics		CP_Process R	2.02	0.58	3.48	0	0	0	Fail RIM
Industrial	Process Refrig Equipment Upgrade	Chemicals and Plastics		CP_Process R	2.49	0.53	4.73	0	0	0	Fail RIM
Industrial	Pump System Optimization	Chemicals and Plastics		CP_Pump Sys	4.24	0.52	8.16	0	0	0	Fail RIM
Industrial	Pump Improved Controls	Chemicals and Plastics		CP_Pump Imp	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Motor Optimization	Chemicals and Plastics		CP_Motor Op	4.40	0.52	8.45	0	0	0	Fail RIM
Industrial	Motor Improved Controls	Chemicals and Plastics		CP_Motor Im	5.99	0.57	10.45	0	0	0	Fail RIM
Industrial	Pump Equipment Upgrade	Chemicals and Plastics		CP_Pump Eq	2.80	0.57	4.88	0	0	0	Fail RIM
Industrial	Motor Equipment Upgrades	Chemicals and Plastics		CP_Motor Eq	1.91	0.52	3.68	0	0	0	Fail RIM
Industrial	Fan System Optimization	Chemicals and Plastics		CP_Fan Syste	5.00	0.52	9.61	0	0	0	Fail RIM
Industrial	Fan Improved Controls	Chemicals and Plastics		CP_Fan Impr	25.81	0.57	45.01	0	0	0	Fail RIM
Industrial	Fan Equipment Upgrades	Chemicals and Plastics		CP_Fan Equi	2.80	0.57	4.88	0	0	0	Fail RIM
Industrial	Lighting Controls	Chemicals and Plastics		CP_Lighting	2.98	0.53	5.57	0	0	0	Fail RIM
Industrial	Efficient Lighting - Other Interior Lighting	Chemicals and Plastics		CP_Efficient	1.54	0.58	2.63	0	0	0	Fail RIM
Industrial	Efficient Lighting - High Bay	Chemicals and Plastics		CP_Efficient	2.84	0.58	4.86	0	0	0	Fail RIM
Industrial	HVAC Improved Controls	Chemicals and Plastics		CP_HVAC In	37.71	0.59	63.97	0	0	0	Fail RIM
Industrial	Building Envelope Improvements	Chemicals and Plastics		CP_Building	5.84	0.59	9.91	0	0	0	Fail RIM
Industrial	HVAC Equipment Upgrades	Chemicals and Plastics		CP_HVAC Eq	8.08	0.61	13.33	0	0	0	Fail RIM
Industrial	Lighting Controls - Exterior	Chemicals and Plastics		CP_Lighting	1.55	0.28	5.57	0	0	0	Fail RIM
Industrial	Efficient Lighting - Exterior	Chemicals and Plastics		CP_Efficient	2.65	0.29	9.16	0	0	0	Fail RIM
Industrial	Compressed Air System Optimization	Chemicals and Plastics		CP_Compres	7.74	0.52	14.87	0	0	0	Fail RIM
Industrial	Compressed Air Controls	Chemicals and Plastics		CP_Compres	3.03	0.56	5.42	0	0	0	Fail RIM
Industrial	Compressed Air Equipment	Chemicals and Plastics		CP_Compres	4.71	0.57	8.21	0	0	0	Fail RIM
Industrial	Process Other Systems Optimization	Construction		CS_Process C	5.80	0.45	12.92	0	0	0	Fail RIM
Industrial	Plant Energy Management	Construction		CS_Plant Ene	20.00	0.54	36.96	0	0	0	Fail RIM
Industrial	Process Heat System Optimization	Construction		CS_Process H	0.27	0.45	0.59	0	0	0	Fail RIM
Industrial	Process Heat Improved Controls	Construction		CS_Process H	0.67	0.58	1.15	0	0	0	Fail RIM
Industrial	Process Refrig System Optimization	Construction		CS_Process R	1.68	0.45	3.74	0	0	0	Fail RIM
Industrial	Process Refrig Controls	Construction		CS_Process R	9.68	0.58	16.70	0	0	0	Fail RIM
Industrial	Process Refrig Equipment Upgrade	Construction		CS_Process R	2.01	0.53	3.81	0	0	0	Fail RIM
Industrial	Pump System Optimization	Construction		CS_Pump Sys	6.18	0.52	11.88	0	0	0	Fail RIM
Industrial	Pump Improved Controls	Construction		CS_Pump Imp	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Motor Optimization	Construction		CS_Motor Op	0.90	0.52	1.73	0	0	0	Fail RIM
Industrial	Motor Improved Controls	Construction		CS_Motor Im	6.12	0.57	10.68	0	0	0	Fail RIM
Industrial	Pump Equipment Upgrade	Construction		CS_Pump Eq	4.77	0.57	8.32	0	0	0	Fail RIM
Industrial	Motor Equipment Upgrades	Construction		CS_Motor Eq	2.46	0.52	4.73	0	0	0	Fail RIM
Industrial	Fan System Optimization	Construction		CS_Fan Syste	11.62	0.52	22.33	0	0	0	Fail RIM
Industrial	Fan Improved Controls	Construction		CS_Fan Impr	19.05	0.57	33.23	0	0	0	Fail RIM
Industrial	Fan Equipment Upgrades	Construction		CS_Fan Equi	3.48	0.57	6.07	0	0	0	Fail RIM
Industrial	Lighting Controls	Construction		CS_Lighting	3.01	0.53	5.64	0	0	0	Fail RIM
Industrial	Efficient Lighting - Other Interior Lighting	Construction		CS_Efficient	1.54	0.58	2.63	0	0	0	Fail RIM
Industrial	Efficient Lighting - High Bay	Construction		CS_Efficient	2.84	0.58	4.86	0	0	0	Fail RIM
Industrial	HVAC Recommissioning	Construction		CS_HVAC R	1.82	0.53	3.41	0	0	0	Fail RIM
Industrial	HVAC Improved Controls	Construction		CS_HVAC In	12.93	0.59	21.93	0	0	0	Fail RIM
Industrial	Building Envelope Improvements	Construction		CS_Building	4.52	0.59	7.67	0	0	0	Fail RIM
Industrial	HVAC Equipment Upgrades	Construction		CS_HVAC Eq	5.60	0.61	9.24	0	0	0	Fail RIM
Industrial	Lighting Controls - Exterior	Construction		CS_Lighting	1.57	0.28	5.64	0	0	0	Fail RIM
Industrial	Efficient Lighting - Exterior	Construction		CS_Efficient	2.65	0.29	9.16	0	0	0	Fail RIM
Industrial	Compressed Air System Optimization	Construction		CS_Compres	7.60	0.52	14.61	0	0	0	Fail RIM
Industrial	Compressed Air Controls	Construction		CS_Compres	9.98	0.56	17.83	0	0	0	Fail RIM
Industrial	Compressed Air Equipment	Construction		CS_Compres	6.13	0.57	10.70	0	0	0	Fail RIM
Industrial	Process Other Systems Optimization	Electrical and Electronic Equip.		EE_Process C	1.58	0.45	3.53	0	0	0	Fail RIM
Industrial	Plant Energy Management	Electrical and Electronic Equip.		EE_Plant Ene	20.04	0.54	36.96	0	0	0	Fail RIM
Industrial	Process Heat System Optimization	Electrical and Electronic Equip.		EE_Process H	1.94	0.45	4.29	0	0	0	Fail RIM
Industrial	Process Heat Improved Controls	Electrical and Electronic Equip.		EE_Process H	0.72	0.58	1.23	0	0	0	Fail RIM
Industrial	Process Refrig System Optimization	Electrical and Electronic Equip.		EE_Process R	26.43	0.45	58.84	0	0	0	Fail RIM
Industrial	Process Refrig Controls	Electrical and Electronic Equip.		EE_Process R	0.73	0.58	1.26	0	0	0	Fail RIM
Industrial	Process Refrig Equipment Upgrade	Electrical and Electronic Equip.		EE_Process R	4.60	0.53	8.74	0	0	0	Fail RIM
Industrial	Pump Improved Controls	Electrical and Electronic Equip.		EE_Pump Imp	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Motor Optimization	Electrical and Electronic Equip.		EE_Motor Op	5.78	0.52	11.11	0	0	0	Fail RIM
Industrial	Motor Improved Controls	Electrical and Electronic Equip.		EE_Motor Im	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Motor Equipment Upgrades	Electrical and Electronic Equip.		EE_Motor Eq	2.50	0.52	4.80	0	0	0	Fail RIM
Industrial	Fan Improved Controls	Electrical and Electronic Equip.		EE_Fan Impr	25.81	0.57	45.01	0	0	0	Fail RIM
Industrial	Lighting Controls	Electrical and Electronic Equip.		EE_Lighting	2.92	0.53	5.46	0	0	0	Fail RIM
Industrial	Efficient Lighting - Other Interior Lighting	Electrical and Electronic Equip.		EE_Efficient	1.54	0.58	2.63	0	0	0	Fail RIM
Industrial	Efficient Lighting - High Bay	Electrical and Electronic Equip.		EE_Efficient	2.84	0.58	4.86	0	0	0	Fail RIM
Industrial	HVAC Recommissioning	Electrical and Electronic Equip.		EE_HVAC R	11.73	0.53	21.95	0	0	0	Fail RIM
Industrial	HVAC Improved Controls	Electrical and Electronic Equip.		EE_HVAC In	4.80	0.59	8.14	0	0	0	Fail RIM
Industrial	Building Envelope Improvements	Electrical and Electronic Equip.		EE_Building	3.75	0.59	6.37	0	0	0	Fail RIM
Industrial	HVAC Equipment Upgrades	Electrical and Electronic Equip.		EE_HVAC Eq	6.18	0.61	10.19	0	0	0	Fail RIM
Industrial	Lighting Controls - Exterior	Electrical and Electronic Equip.		EE_Lighting	1.52	0.28	5.46	0	0	0	Fail RIM
Industrial	Efficient Lighting - Exterior	Electrical and Electronic Equip.		EE_Efficient	2.65	0.29	9.16	0	0	0	Fail RIM
Industrial	Compressed Air System Optimization	Electrical and Electronic Equip.		EE_Compres	8.51	0.52	16.35	0	0	0	Fail RIM
Industrial	Compressed Air Controls	Electrical and Electronic Equip.		EE_Compres	18.00	0.56	32.15	0	0	0	Fail RIM
Industrial	Compressed Air Equipment	Electrical and Electronic Equip.		EE_Compres	16.61	0.57	28.97	0	0	0	Fail RIM
Industrial	Process Other Systems Optimization	Lumber/Furniture/Pulp/Paper		LP_Process C	1.61	0.45	3.59	0	0	0	Fail RIM
Industrial	Plant Energy Management	Lumber/Furniture/Pulp/Paper		LP_Plant Ene	3.83	0.54	7.09	0	0	0	Fail RIM
Industrial	Process Other Equipment Upgrades	Lumber/Furniture/Pulp/Paper		LP_Process C	4.74	0.53	9.01	0	0	0	Fail RIM
Industrial	Process Heat System Optimization	Lumber/Furniture/Pulp/Paper		LP_Process H	0.29	0.45	0.64	0	0	0	Fail RIM
Industrial	Process Heat Improved Controls	Lumber/Furniture/Pulp/Paper		LP_Process H	0.72	0.58	1.23	0	0	0	Fail RIM
Industrial	Process Refrig Controls	Lumber/Furniture/Pulp/Paper		LP_Process R	0.73	0.58	1.26	0	0	0	Fail RIM
Industrial	Process Refrig Equipment Upgrade	Lumber/Furniture/Pulp/Paper		LP_Process R	1.73	0.53	3.29	0	0	0	Fail RIM
Industrial	Pump System Optimization	Lumber/Furniture/Pulp/Paper		LP_Pump Sys	1.62	0.52	3.12	0	0	0	Fail RIM
Industrial	Pump Improved Controls	Lumber/Furniture/Pulp/Paper		LP_Pump Imp	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Motor Optimization	Lumber/Furniture/Pulp/Paper		LP_Motor Op	5.21	0.52	10.01	0	0	0	Fail RIM
Industrial	Motor Improved Controls	Lumber/Furniture/Pulp/Paper		LP_Motor Im	12.90	0.57	22.50	0	0	0	Fail RIM
Industrial	Pump Equipment Upgrade	Lumber/Furniture/Pulp/Paper		LP_Pump Eq	2.01	0.57	3.50	0	0	0	Fail RIM
Industrial	Motor Equipment Upgrades	Lumber/Furniture/Pulp/Paper		LP_Motor Eq	6.25	0.52	12.02	0	0	0	Fail RIM
Industrial	Fan System Optimization	Lumber/Furniture/Pulp/Paper		LP_Fan Syste	11.70	0.52	22.49	0	0	0	Fail RIM
Industrial	Fan Improved Controls	Lumber/Furniture/Pulp/Paper		LP_Fan Impr	25.81	0.57	45.01	0	0	0	Fail RIM
Industrial	Fan Equipment Upgrades	Lumber/Furniture/Pulp/Paper		LP_Fan Equi	2.74	0.57	4.78	0	0	0	Fail RIM
Industrial	Lighting Controls	Lumber/Furniture/Pulp/Paper		LP_Lighting	2.42	0.53	4.52	0	0	0	Fail RIM

Industrial	Efficient Lighting - Other Interior Lighting	Lumber/Furniture/Pulp/Paper		LP_Efficient I	1.54	0.58	2.63	0	0	0	Fail RIM
Industrial	Efficient Lighting - High Bay	Lumber/Furniture/Pulp/Paper		LP_Efficient I	2.84	0.58	4.86	0	0	0	Fail RIM
Industrial	HVAC Improved Controls	Lumber/Furniture/Pulp/Paper		LP_HVAC Im	37.99	0.59	64.43	0	0	0	Fail RIM
Industrial	HVAC Equipment Upgrades	Lumber/Furniture/Pulp/Paper		LP_HVAC Eq	6.18	0.61	10.19	0	0	0	Fail RIM
Industrial	Lighting Controls - Exterior	Lumber/Furniture/Pulp/Paper		LP_Lighting C	1.25	0.28	4.52	0	0	0	Fail RIM
Industrial	Efficient Lighting - Exterior	Lumber/Furniture/Pulp/Paper		LP_Efficient I	2.65	0.29	9.16	0	0	0	Fail RIM
Industrial	Compressed Air System Optimization	Lumber/Furniture/Pulp/Paper		LP_Compress	8.36	0.52	16.07	0	0	0	Fail RIM
Industrial	Compressed Air Controls	Lumber/Furniture/Pulp/Paper		LP_Compress	16.20	0.56	28.93	0	0	0	Fail RIM
Industrial	Compressed Air Equipment	Lumber/Furniture/Pulp/Paper		LP_Compress	4.36	0.57	7.61	0	0	0	Fail RIM
Industrial	Process Other Systems Optimization	Metal Products and Machinery		MM_Process	1.07	0.45	2.38	0	0	0	Fail RIM
Industrial	Plant Energy Management	Metal Products and Machinery		MM_Plant En	4.90	0.54	9.06	0	0	0	Fail RIM
Industrial	Process Heat System Optimization	Metal Products and Machinery		MM_Process	0.43	0.45	0.94	0	0	0	Fail RIM
Industrial	Process Heat Improved Controls	Metal Products and Machinery		MM_Process	0.71	0.58	1.23	0	0	0	Fail RIM
Industrial	Process Heat Equipment Upgrade	Metal Products and Machinery		MM_Process	4.06	0.53	7.71	0	0	0	Fail RIM
Industrial	Process Refrig System Optimization	Metal Products and Machinery		MM_Process	34.13	0.45	75.97	0	0	0	Fail RIM
Industrial	Process Refrig Controls	Metal Products and Machinery		MM_Process	1.08	0.58	1.86	0	0	0	Fail RIM
Industrial	Process Refrig Equipment Upgrade	Metal Products and Machinery		MM_Process	2.12	0.53	4.03	0	0	0	Fail RIM
Industrial	Pump System Optimization	Metal Products and Machinery		MM_Pump S	14.05	0.52	27.00	0	0	0	Fail RIM
Industrial	Pump Improved Controls	Metal Products and Machinery		MM_Pump Im	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Motor Optimization	Metal Products and Machinery		MM_Motor O	5.06	0.52	9.72	0	0	0	Fail RIM
Industrial	Motor Improved Controls	Metal Products and Machinery		MM_Motor Im	14.00	0.57	24.43	0	0	0	Fail RIM
Industrial	Pump Equipment Upgrade	Metal Products and Machinery		MM_Pump E	4.32	0.57	7.54	0	0	0	Fail RIM
Industrial	Motor Equipment Upgrades	Metal Products and Machinery		MM_Motor E	2.24	0.52	4.30	0	0	0	Fail RIM
Industrial	Fan System Optimization	Metal Products and Machinery		MM_Fan Sys	19.91	0.52	38.25	0	0	0	Fail RIM
Industrial	Fan Improved Controls	Metal Products and Machinery		MM_Fan Imp	25.81	0.57	45.01	0	0	0	Fail RIM
Industrial	Fan Equipment Upgrades	Metal Products and Machinery		MM_Fan Equ	4.32	0.57	7.54	0	0	0	Fail RIM
Industrial	Lighting Controls	Metal Products and Machinery		MM_Lighting	2.65	0.53	4.95	0	0	0	Fail RIM
Industrial	Efficient Lighting - Other Interior Lighting	Metal Products and Machinery		MM_Efficient	1.54	0.58	2.63	0	0	0	Fail RIM
Industrial	Efficient Lighting - High Bay	Metal Products and Machinery		MM_Efficient	2.84	0.58	4.86	0	0	0	Fail RIM
Industrial	HVAC Recommissioning	Metal Products and Machinery		MM_HVAC I	0.36	0.53	0.68	0	0	0	Fail RIM
Industrial	HVAC Improved Controls	Metal Products and Machinery		MM_HVAC I	11.14	0.59	18.90	0	0	0	Fail RIM
Industrial	Building Envelope Improvements	Metal Products and Machinery		MM_Building	5.06	0.59	8.59	0	0	0	Fail RIM
Industrial	HVAC Equipment Upgrades	Metal Products and Machinery		MM_HVAC E	5.18	0.61	8.53	0	0	0	Fail RIM
Industrial	Lighting Controls - Exterior	Metal Products and Machinery		MM_Lighting	1.38	0.28	4.95	0	0	0	Fail RIM
Industrial	Efficient Lighting - Exterior	Metal Products and Machinery		MM_Efficient	2.65	0.29	9.16	0	0	0	Fail RIM
Industrial	Compressed Air System Optimization	Metal Products and Machinery		MM_Compre	8.62	0.52	16.56	0	0	0	Fail RIM
Industrial	Compressed Air Controls	Metal Products and Machinery		MM_Compre	10.97	0.56	19.60	0	0	0	Fail RIM
Industrial	Compressed Air Equipment	Metal Products and Machinery		MM_Compre	6.43	0.57	11.22	0	0	0	Fail RIM
Industrial	Process Other Systems Optimization	Miscellaneous Manufacturing		MS_Process O	8.19	0.45	18.24	0	0	0	Fail RIM
Industrial	Plant Energy Management	Miscellaneous Manufacturing		MS_Plant En	20.05	0.54	36.96	0	0	0	Fail RIM
Industrial	Process Heat System Optimization	Miscellaneous Manufacturing		MS_Process H	0.53	0.45	1.17	0	0	0	Fail RIM
Industrial	Process Heat Improved Controls	Miscellaneous Manufacturing		MS_Process H	0.72	0.58	1.23	0	0	0	Fail RIM
Industrial	Process Refrig System Optimization	Miscellaneous Manufacturing		MS_Process R	0.60	0.45	1.33	0	0	0	Fail RIM
Industrial	Process Refrig Controls	Miscellaneous Manufacturing		MS_Process R	0.73	0.58	1.26	0	0	0	Fail RIM
Industrial	Process Refrig Equipment Upgrade	Miscellaneous Manufacturing		MS_Process R	1.75	0.53	3.33	0	0	0	Fail RIM
Industrial	Pump System Optimization	Miscellaneous Manufacturing		MS_Pump Sy	2.92	0.52	5.61	0	0	0	Fail RIM
Industrial	Pump Improved Controls	Miscellaneous Manufacturing		MS_Pump Im	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Motor Optimization	Miscellaneous Manufacturing		MS_Motor Op	0.66	0.52	1.27	0	0	0	Fail RIM
Industrial	Motor Improved Controls	Miscellaneous Manufacturing		MS_Motor Im	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Pump Equipment Upgrade	Miscellaneous Manufacturing		MS_Pump Eq	4.77	0.57	8.32	0	0	0	Fail RIM
Industrial	Motor Equipment Upgrades	Miscellaneous Manufacturing		MS_Motor Eq	1.89	0.52	3.62	0	0	0	Fail RIM
Industrial	Fan Improved Controls	Miscellaneous Manufacturing		MS_Fan Impr	25.81	0.57	45.01	0	0	0	Fail RIM
Industrial	Fan Equipment Upgrades	Miscellaneous Manufacturing		MS_Fan Equ	3.48	0.57	6.07	0	0	0	Fail RIM
Industrial	Lighting Controls	Miscellaneous Manufacturing		MS_Lighting	3.74	0.53	6.98	0	0	0	Fail RIM
Industrial	Efficient Lighting - Other Interior Lighting	Miscellaneous Manufacturing		MS_Efficient	1.54	0.58	2.63	0	0	0	Fail RIM
Industrial	Efficient Lighting - High Bay	Miscellaneous Manufacturing		MS_Efficient	2.84	0.58	4.86	0	0	0	Fail RIM
Industrial	HVAC Improved Controls	Miscellaneous Manufacturing		MS_HVAC Ii	104.66	0.59	177.51	0	0	0	Fail RIM
Industrial	Building Envelope Improvements	Miscellaneous Manufacturing		MS_Building	6.54	0.59	11.09	0	0	0	Fail RIM
Industrial	HVAC Equipment Upgrades	Miscellaneous Manufacturing		MS_HVAC E	2.37	0.61	3.90	0	0	0	Fail RIM
Industrial	Lighting Controls - Exterior	Miscellaneous Manufacturing		MS_Lighting	1.94	0.28	6.98	0	0	0	Fail RIM
Industrial	Efficient Lighting - Exterior	Miscellaneous Manufacturing		MS_Efficient	2.65	0.29	9.16	0	0	0	Fail RIM
Industrial	Compressed Air System Optimization	Miscellaneous Manufacturing		MS_Compres	5.55	0.52	10.67	0	0	0	Fail RIM
Industrial	Compressed Air Controls	Miscellaneous Manufacturing		MS_Compres	84.97	0.56	151.77	0	0	0	Fail RIM
Industrial	Compressed Air Equipment	Miscellaneous Manufacturing		MS_Compres	44.04	0.57	76.83	0	0	0	Fail RIM
Industrial	Process Other Systems Optimization	Primary Resources Industries		PR_Process O	0.99	0.45	2.19	0	0	0	Fail RIM
Industrial	Plant Energy Management	Primary Resources Industries		PR_Plant Ene	20.06	0.54	36.96	0	0	0	Fail RIM
Industrial	Process Heat System Optimization	Primary Resources Industries		PR_Process H	0.47	0.45	1.05	0	0	0	Fail RIM
Industrial	Process Heat Improved Controls	Primary Resources Industries		PR_Process H	0.72	0.58	1.23	0	0	0	Fail RIM
Industrial	Process Refrig System Optimization	Primary Resources Industries		PR_Process R	34.13	0.45	75.97	0	0	0	Fail RIM
Industrial	Process Refrig Controls	Primary Resources Industries		PR_Process R	0.73	0.58	1.26	0	0	0	Fail RIM
Industrial	Process Refrig Equipment Upgrade	Primary Resources Industries		PR_Process R	2.82	0.53	5.36	0	0	0	Fail RIM
Industrial	Pump System Optimization	Primary Resources Industries		PR_Pump Sys	48.99	0.52	94.13	0	0	0	Fail RIM
Industrial	Pump Improved Controls	Primary Resources Industries		PR_Pump Imp	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Motor Optimization	Primary Resources Industries		PR_Motor Op	6.67	0.52	12.82	0	0	0	Fail RIM
Industrial	Motor Improved Controls	Primary Resources Industries		PR_Motor Im	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Pump Equipment Upgrade	Primary Resources Industries		PR_Pump Eq	5.71	0.57	9.96	0	0	0	Fail RIM
Industrial	Motor Equipment Upgrades	Primary Resources Industries		PR_Motor Eq	2.38	0.52	4.56	0	0	0	Fail RIM
Industrial	Fan System Optimization	Primary Resources Industries		PR_Fan Syste	126.06	0.52	242.22	0	0	0	Fail RIM
Industrial	Fan Improved Controls	Primary Resources Industries		PR_Fan Impr	25.81	0.57	45.01	0	0	0	Fail RIM
Industrial	Fan Equipment Upgrades	Primary Resources Industries		PR_Fan Equip	5.71	0.57	9.96	0	0	0	Fail RIM
Industrial	Lighting Controls	Primary Resources Industries		PR_Lighting	2.87	0.53	5.36	0	0	0	Fail RIM

Industrial	Efficient Lighting - Other Interior Lighting	Primary Resources Industries		PR_Efficient	1.54	0.58	2.63	0	0	0	Fail RIM
Industrial	Efficient Lighting - High Bay	Primary Resources Industries		PR_Efficient	2.84	0.58	4.86	0	0	0	Fail RIM
Industrial	HVAC Improved Controls	Primary Resources Industries		PR_HVAC In	20.96	0.59	35.54	0	0	0	Fail RIM
Industrial	Building Envelope Improvements	Primary Resources Industries		PR_Building	5.02	0.59	8.52	0	0	0	Fail RIM
Industrial	HVAC Equipment Upgrades	Primary Resources Industries		PR_HVAC Eq	3.21	0.61	5.29	0	0	0	Fail RIM
Industrial	Lighting Controls - Exterior	Primary Resources Industries		PR_Lighting C	1.49	0.28	5.36	0	0	0	Fail RIM
Industrial	Efficient Lighting - Exterior	Primary Resources Industries		PR_Efficient	2.65	0.29	9.16	0	0	0	Fail RIM
Industrial	Compressed Air System Optimization	Primary Resources Industries		PR_Compress	8.97	0.52	17.24	0	0	0	Fail RIM
Industrial	Compressed Air Controls	Primary Resources Industries		PR_Compress	12.13	0.56	21.66	0	0	0	Fail RIM
Industrial	Compressed Air Equipment	Primary Resources Industries		PR_Compress	5.25	0.57	9.16	0	0	0	Fail RIM
Industrial	Process Other Systems Optimization	Stone/Clay/Glass/Concrete		ST_Process O	8.19	0.45	18.24	0	0	0	Fail RIM
Industrial	Plant Energy Management	Stone/Clay/Glass/Concrete		ST_Plant Ene	19.99	0.54	36.96	0	0	0	Fail RIM
Industrial	Process Heat System Optimization	Stone/Clay/Glass/Concrete		ST_Process H	0.25	0.45	0.56	0	0	0	Fail RIM
Industrial	Process Heat Improved Controls	Stone/Clay/Glass/Concrete		ST_Process H	0.72	0.58	1.23	0	0	0	Fail RIM
Industrial	Process Heat Equipment Upgrade	Stone/Clay/Glass/Concrete		ST_Process H	1.79	0.53	3.40	0	0	0	Fail RIM
Industrial	Process Refrig Controls	Stone/Clay/Glass/Concrete		ST_Process R	0.73	0.58	1.26	0	0	0	Fail RIM
Industrial	Process Refrig Equipment Upgrade	Stone/Clay/Glass/Concrete		ST_Process R	1.61	0.53	3.06	0	0	0	Fail RIM
Industrial	Pump System Optimization	Stone/Clay/Glass/Concrete		ST_Pump Sys	0.00	0.00	0.00	0	0	0	Fail RIM
Industrial	Pump Improved Controls	Stone/Clay/Glass/Concrete		ST_Pump Imp	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Motor Optimization	Stone/Clay/Glass/Concrete		ST_Motor Op	6.28	0.52	12.07	0	0	0	Fail RIM
Industrial	Motor Improved Controls	Stone/Clay/Glass/Concrete		ST_Motor Im	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Pump Equipment Upgrade	Stone/Clay/Glass/Concrete		ST_Pump Equ	3.48	0.57	6.07	0	0	0	Fail RIM
Industrial	Motor Equipment Upgrades	Stone/Clay/Glass/Concrete		ST_Motor Eq	6.70	0.52	12.88	0	0	0	Fail RIM
Industrial	Fan Improved Controls	Stone/Clay/Glass/Concrete		ST_Fan Impro	25.81	0.57	45.01	0	0	0	Fail RIM
Industrial	Fan Equipment Upgrades	Stone/Clay/Glass/Concrete		ST_Fan Equip	3.48	0.57	6.07	0	0	0	Fail RIM
Industrial	Lighting Controls	Stone/Clay/Glass/Concrete		ST_Lighting C	2.81	0.53	5.26	0	0	0	Fail RIM
Industrial	Efficient Lighting - Other Interior Lighting	Stone/Clay/Glass/Concrete		ST_Efficient	1.54	0.58	2.63	0	0	0	Fail RIM
Industrial	Efficient Lighting - High Bay	Stone/Clay/Glass/Concrete		ST_Efficient	2.84	0.58	4.86	0	0	0	Fail RIM
Industrial	HVAC Improved Controls	Stone/Clay/Glass/Concrete		ST_HVAC In	16.03	0.59	27.20	0	0	0	Fail RIM
Industrial	Building Envelope Improvements	Stone/Clay/Glass/Concrete		ST_Building	4.22	0.59	7.15	0	0	0	Fail RIM
Industrial	HVAC Equipment Upgrades	Stone/Clay/Glass/Concrete		ST_HVAC Eq	6.18	0.61	10.19	0	0	0	Fail RIM
Industrial	Lighting Controls - Exterior	Stone/Clay/Glass/Concrete		ST_Lighting C	1.46	0.28	5.26	0	0	0	Fail RIM
Industrial	Efficient Lighting - Exterior	Stone/Clay/Glass/Concrete		ST_Efficient	2.65	0.29	9.16	0	0	0	Fail RIM
Industrial	Compressed Air System Optimization	Stone/Clay/Glass/Concrete		ST_Compress	6.66	0.52	12.81	0	0	0	Fail RIM
Industrial	Compressed Air Controls	Stone/Clay/Glass/Concrete		ST_Compress	10.34	0.56	18.46	0	0	0	Fail RIM
Industrial	Compressed Air Equipment	Stone/Clay/Glass/Concrete		ST_Compress	2.87	0.57	5.00	0	0	0	Fail RIM
Industrial	Process Other Systems Optimization	Textiles and Leather		TX_Process O	3.48	0.45	7.74	0	0	0	Fail RIM
Industrial	Process Heat System Optimization	Textiles and Leather		TX_Process H	0.08	0.45	0.17	0	0	0	Fail RIM
Industrial	Process Heat Equipment Upgrade	Textiles and Leather		TX_Process H	11.10	0.53	21.11	0	0	0	Fail RIM
Industrial	Process Refrig Controls	Textiles and Leather		TX_Process R	0.73	0.58	1.26	0	0	0	Fail RIM
Industrial	Process Refrig Equipment Upgrade	Textiles and Leather		TX_Process R	2.52	0.53	4.79	0	0	0	Fail RIM
Industrial	Pump Improved Controls	Textiles and Leather		TX_Pump Imp	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Motor Optimization	Textiles and Leather		TX_Motor Op	1.34	0.52	2.57	0	0	0	Fail RIM
Industrial	Motor Improved Controls	Textiles and Leather		TX_Motor Im	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Pump Equipment Upgrade	Textiles and Leather		TX_Pump Equ	4.96	0.57	8.66	0	0	0	Fail RIM
Industrial	Motor Equipment Upgrades	Textiles and Leather		TX_Motor Eq	2.92	0.52	5.60	0	0	0	Fail RIM
Industrial	Fan Improved Controls	Textiles and Leather		TX_Fan Impro	25.81	0.57	45.01	0	0	0	Fail RIM
Industrial	Fan Equipment Upgrades	Textiles and Leather		TX_Fan Equip	4.96	0.57	8.66	0	0	0	Fail RIM
Industrial	Lighting Controls	Textiles and Leather		TX_Lighting C	3.29	0.53	6.14	0	0	0	Fail RIM
Industrial	Efficient Lighting - Other Interior Lighting	Textiles and Leather		TX_Efficient	1.54	0.58	2.63	0	0	0	Fail RIM
Industrial	Efficient Lighting - High Bay	Textiles and Leather		TX_Efficient	2.84	0.58	4.86	0	0	0	Fail RIM
Industrial	HVAC Recommissioning	Textiles and Leather		TX_HVAC R	7.10	0.53	13.28	0	0	0	Fail RIM
Industrial	HVAC Improved Controls	Textiles and Leather		TX_HVAC In	199.40	0.59	338.20	0	0	0	Fail RIM
Industrial	Building Envelope Improvements	Textiles and Leather		TX_Building	2.32	0.59	3.93	0	0	0	Fail RIM
Industrial	HVAC Equipment Upgrades	Textiles and Leather		TX_HVAC Eq	6.02	0.61	9.93	0	0	0	Fail RIM
Industrial	Lighting Controls - Exterior	Textiles and Leather		TX_Lighting C	1.71	0.28	6.14	0	0	0	Fail RIM
Industrial	Efficient Lighting - Exterior	Textiles and Leather		TX_Efficient	2.65	0.29	9.16	0	0	0	Fail RIM
Industrial	Compressed Air System Optimization	Textiles and Leather		TX_Compress	8.21	0.52	15.78	0	0	0	Fail RIM
Industrial	Compressed Air Controls	Textiles and Leather		TX_Compress	10.06	0.56	17.97	0	0	0	Fail RIM
Industrial	Compressed Air Equipment	Textiles and Leather		TX_Compress	5.04	0.57	8.80	0	0	0	Fail RIM
Industrial	Process Other Systems Optimization	Transportation Equipment		TR_Process O	8.19	0.45	18.24	0	0	0	Fail RIM
Industrial	Plant Energy Management	Transportation Equipment		TR_Plant Ene	20.06	0.54	36.96	0	0	0	Fail RIM
Industrial	Process Heat System Optimization	Transportation Equipment		TR_Process H	0.89	0.45	1.96	0	0	0	Fail RIM
Industrial	Process Heat Improved Controls	Transportation Equipment		TR_Process H	0.72	0.58	1.23	0	0	0	Fail RIM
Industrial	Process Refrig Controls	Transportation Equipment		TR_Process R	0.73	0.58	1.26	0	0	0	Fail RIM
Industrial	Process Refrig Equipment Upgrade	Transportation Equipment		TR_Process R	3.39	0.53	6.44	0	0	0	Fail RIM
Industrial	Pump System Optimization	Transportation Equipment		TR_Pump Sys	5.24	0.52	10.07	0	0	0	Fail RIM
Industrial	Pump Improved Controls	Transportation Equipment		TR_Pump Imp	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Motor Optimization	Transportation Equipment		TR_Motor Op	4.90	0.52	9.41	0	0	0	Fail RIM
Industrial	Motor Improved Controls	Transportation Equipment		TR_Motor Im	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Pump Equipment Upgrade	Transportation Equipment		TR_Pump Equ	2.50	0.57	4.36	0	0	0	Fail RIM
Industrial	Motor Equipment Upgrades	Transportation Equipment		TR_Motor Eq	13.05	0.52	25.07	0	0	0	Fail RIM
Industrial	Fan System Optimization	Transportation Equipment		TR_Fan Syste	11.70	0.52	22.49	0	0	0	Fail RIM
Industrial	Fan Improved Controls	Transportation Equipment		TR_Fan Impro	64.40	0.57	112.34	0	0	0	Fail RIM
Industrial	Fan Equipment Upgrades	Transportation Equipment		TR_Fan Equip	2.50	0.57	4.36	0	0	0	Fail RIM
Industrial	Lighting Controls	Transportation Equipment		TR_Lighting C	3.21	0.53	6.00	0	0	0	Fail RIM
Industrial	Efficient Lighting - Other Interior Lighting	Transportation Equipment		TR_Efficient	1.54	0.58	2.63	0	0	0	Fail RIM
Industrial	Efficient Lighting - High Bay	Transportation Equipment		TR_Efficient	2.84	0.58	4.86	0	0	0	Fail RIM
Industrial	HVAC Recommissioning	Transportation Equipment		TR_HVAC R	1.81	0.53	3.39	0	0	0	Fail RIM
Industrial	HVAC Improved Controls	Transportation Equipment		TR_HVAC In	43.37	0.59	73.56	0	0	0	Fail RIM
Industrial	Building Envelope Improvements	Transportation Equipment		TR_Building	4.82	0.59	8.17	0	0	0	Fail RIM
Industrial	HVAC Equipment Upgrades	Transportation Equipment		TR_HVAC Eq	6.18	0.61	10.19	0	0	0	Fail RIM
Industrial	Lighting Controls - Exterior	Transportation Equipment		TR_Lighting C	1.67	0.28	6.00	0	0	0	Fail RIM
Industrial	Efficient Lighting - Exterior	Transportation Equipment		TR_Efficient	2.65	0.29	9.16	0	0	0	Fail RIM
Industrial	Compressed Air System Optimization	Transportation Equipment		TR_Compress	6.72	0.52	12.91	0	0	0	Fail RIM
Industrial	Compressed Air Controls	Transportation Equipment		TR_Compress	8.11	0.56	14.49	0	0	0	Fail RIM
Industrial	Compressed Air Equipment	Transportation Equipment		TR_Compress	7.33	0.57	12.78	0	0	0	Fail RIM
Industrial	Process Other Systems Optimization	Water and Wastewater		WW_Process	5.80	0.45	12.92	0	0	0	Fail RIM
Industrial	Plant Energy Management	Water and Wastewater		WW_Plant En	20.01	0.54	36.96	0	0	0	Fail RIM
Industrial	Process Heat System Optimization	Water and Wastewater		WW_Process	0.27	0.45	0.59	0	0	0	Fail RIM
Industrial	Process Heat Improved Controls	Water and Wastewater		WW_Process	0.67	0.58	1.15	0	0	0	Fail RIM
Industrial	Process Refrig System Optimization	Water and Wastewater		WW_Process	1.68	0.45	3.74	0	0	0	Fail RIM
Industrial	Process Refrig Controls	Water and Wastewater		WW_Process	9.68	0.58	16.70	0	0	0	Fail RIM
Industrial	Process Refrig Equipment Upgrade	Water and Wastewater		WW_Process	2.01	0.53	3.81	0	0	0	Fail RIM
Industrial	Pump System Optimization	Water and Wastewater		WW_Pump Sy	6.18	0.52	11.88	0	0	0	Fail RIM
Industrial	Pump Improved Controls	Water and Wastewater		WW_Pump Im	9.95	0.57	17.36	0	0	0	Fail RIM
Industrial	Motor Optimization	Water and Wastewater		WW_Motor O	0.90	0.52	1.73	0	0	0	Fail RIM
Industrial	Motor Improved Controls	Water and Wastewater		WW_Motor Im	6.12	0.57	10.68	0	0	0	Fail RIM
Industrial	Pump Equipment Upgrade	Water and Wastewater		WW_Pump Eq	4.77	0.57	8.32	0	0	0	Fail RIM

Industrial	Motor Equipment Upgrades	Water and Wastewater		WW_Motor E	2.46	0.52	4.73	0	0	0	Fail RIM
Industrial	Fan System Optimization	Water and Wastewater		WW_Fan Sys	11.62	0.52	22.33	0	0	0	Fail RIM
Industrial	Fan Improved Controls	Water and Wastewater		WW_Fan Imp	19.05	0.57	33.23	0	0	0	Fail RIM
Industrial	Fan Equipment Upgrades	Water and Wastewater		WW_Fan Equ	3.48	0.57	6.07	0	0	0	Fail RIM
Industrial	Lighting Controls	Water and Wastewater		WW_Lighting	3.01	0.53	5.64	0	0	0	Fail RIM
Industrial	Efficient Lighting - Other Interior Lighting	Water and Wastewater		WW_Efficien	1.54	0.58	2.63	0	0	0	Fail RIM
Industrial	Efficient Lighting - High Bay	Water and Wastewater		WW_Efficien	2.84	0.58	4.86	0	0	0	Fail RIM
Industrial	HVAC Recommissioning	Water and Wastewater		WW_HVAC C	1.82	0.53	3.41	0	0	0	Fail RIM
Industrial	HVAC Improved Controls	Water and Wastewater		WW_HVAC C	12.93	0.59	21.93	0	0	0	Fail RIM
Industrial	Building Envelope Improvements	Water and Wastewater		WW_Building	4.52	0.59	7.67	0	0	0	Fail RIM
Industrial	HVAC Equipment Upgrades	Water and Wastewater		WW_HVAC C	5.60	0.61	9.24	0	0	0	Fail RIM
Industrial	Lighting Controls - Exterior	Water and Wastewater		WW_Lighting	1.57	0.28	5.64	0	0	0	Fail RIM
Industrial	Efficient Lighting - Exterior	Water and Wastewater		WW_Efficien	2.65	0.29	9.16	0	0	0	Fail RIM
Industrial	Compressed Air System Optimization	Water and Wastewater		WW_Compre	7.60	0.52	14.61	0	0	0	Fail RIM
Industrial	Compressed Air Controls	Water and Wastewater		WW_Compre	9.98	0.56	17.83	0	0	0	Fail RIM
Industrial	Compressed Air Equipment	Water and Wastewater		WW_Compre	6.13	0.57	10.70	0	0	0	Fail RIM
Residential	PV System	Single Family	New	SF_Solar Vol	0.49	0.51	0.97	0	0	0	Fail RIM
Residential	PV System	Multi-Family	New	MF_Solar Vo	0.49	0.51	0.97	0	0	0	Fail RIM
Residential	Battery Storage from PV System	Single Family	New	SF_Solar Plu	0.14	0.38	0.37	0	0	0	Fail RIM
Residential	Battery Storage from PV System	Multi-Family	New	MF_Solar Plu	0.10	1.57	0.06	0	0	0	Fail PCT
Commercial	Solar Voltaic (17.1w/sf2)	Assembly	New	AS_Solar Vol	0.83	0.64	1.29	0	0	0	Fail RIM
Commercial	Solar Voltaic (17.1w/sf2)	College and University	New	CU_Solar Vo	0.83	0.64	1.29	0	0	0	Fail RIM
Commercial	Solar Voltaic (17.1w/sf2)	Grocery	New	GR_Solar Vo	0.83	0.64	1.29	0	0	0	Fail RIM
Commercial	Solar Voltaic (17.1w/sf2)	Healthcare	New	HC_Solar Vo	0.83	0.64	1.29	0	0	0	Fail RIM
Commercial	Solar Voltaic (17.1w/sf2)	Hospitals	New	HS_Solar Vo	0.83	0.64	1.29	0	0	0	Fail RIM
Commercial	Solar Voltaic (17.1w/sf2)	Institutional	New	IN_Solar Vol	0.83	0.64	1.29	0	0	0	Fail RIM
Commercial	Solar Voltaic (17.1w/sf2)	Lodging/Hospitality	New	LG_Solar Vol	0.83	0.64	1.29	0	0	0	Fail RIM
Commercial	Solar Voltaic (17.1w/sf2)	Miscellaneous	New	MS_Solar Vo	0.83	0.64	1.29	0	0	0	Fail RIM
Commercial	Solar Voltaic (17.1w/sf2)	Offices	New	OF_Solar Vo	0.83	0.64	1.29	0	0	0	Fail RIM
Commercial	Solar Voltaic (17.1w/sf2)	Restaurants	New	RS_Solar Vol	0.83	0.64	1.29	0	0	0	Fail RIM
Commercial	Solar Voltaic (17.1w/sf2)	Retail	New	RT_Solar Vo	0.83	0.64	1.29	0	0	0	Fail RIM
Commercial	Solar Voltaic (17.1w/sf2)	Schools K-12	New	SC_Solar Vo	0.83	0.64	1.29	0	0	0	Fail RIM
Commercial	Solar Voltaic (17.1w/sf2)	Warehouse	New	WR_Solar Vo	0.83	0.64	1.29	0	0	0	Fail RIM
Commercial	Storage with other DSM (EE and DR) - Seg 1 - 15 MWh		New	Storage with	0.04	0.00	0.00	0	0	0	Fail RIM
Commercial	Storage with other DSM (EE and DR) - Seg 2 - 25 MWh		New	Storage with	0.02	0.00	0.00	0	0	0	Fail RIM
Commercial	Storage with other DSM (EE and DR) - Seg 3 - 50 MWh		New	Storage with	0.02	0.00	0.00	0	0	0	Fail RIM
Commercial	Storage with other DSM (EE and DR) - Seg 4 51+ MWh		New	Storage with	0.02	0.00	0.00	0	0	0	Fail RIM
Nonresidential	5500 kW Steam Turbine-Biomass		New	5500 kW Ste	0.44	0.58	0.76	0	0	0	Fail RIM
Nonresidential	3500 kW Steam Turbine-Biomass		New	3500 kW Ste	0.41	0.58	0.71	0	0	0	Fail RIM
Nonresidential	3500 kW Gas Turbine		New	3500 kW Gas	0.33	0.61	0.54	0	0	0	Fail RIM
Nonresidential	3000 kW Gas Turbine		New	3000 kW Gas	0.32	0.61	0.53	0	0	0	Fail RIM
Nonresidential	2500 kW Gas Turbine		New	2500 kW Gas	0.32	0.61	0.52	0	0	0	Fail RIM
Nonresidential	4500 kW Reciprocating Engine		New	4500 kW Rec	0.61	0.92	0.66	0	0	0	Fail RIM
Nonresidential	1500 kW Steam Turbine-Biomass		New	1500 kW Ste	0.45	0.58	0.77	0	0	0	Fail RIM
Nonresidential	3000 kW Reciprocating Engine		New	3000 kW Rec	0.60	0.92	0.65	0	0	0	Fail RIM
Nonresidential	1125 kW Fuel Cell		New	1125 kW Fue	0.35	0.56	0.62	0	0	0	Fail RIM
Nonresidential	800 kW Fuel Cell-Biogas		New	800 kW Fuel	0.31	0.56	0.55	0	0	0	Fail RIM
Nonresidential	1250 kW Reciprocating Engine		New	1250 kW Rec	0.54	0.92	0.58	0	0	0	Fail RIM
Nonresidential	1250 kW Reciprocating Engine-Biogas		New	1250 kW Rec	0.52	0.92	0.56	0	0	0	Fail RIM
Nonresidential	500 kW Fuel Cell		New	500 kW Fuel	0.27	0.56	0.48	0	0	0	Fail RIM
Nonresidential	350 kW Reciprocating Engine		New	350 kW Recip	0.47	0.92	0.50	0	0	0	Fail RIM
Nonresidential	175 kW Fuel Cell		New	175 kW Fuel	0.15	0.56	0.27	0	0	0	Fail RIM
Nonresidential	200 kW Micro Turbine		New	200 kW Micr	0.21	0.69	0.31	0	0	0	Fail RIM
Nonresidential	150 kW Reciprocating Engine		New	150 kW Recip	0.44	0.92	0.48	0	0	0	Fail RIM
Nonresidential	100 kW Micro Turbine		New	100 kW Micr	0.21	0.69	0.30	0	0	0	Fail RIM
Nonresidential	100 kW Micro Turbine- Biogas		New	100 kW Micr	0.20	0.69	0.29	0	0	0	Fail RIM
Nonresidential	50 kW Micro Turbine		New	50 kW Micro	0.20	0.69	0.29	0	0	0	Fail RIM

Achievable Potential - RIM

Passing Measures Results
[Economic Potential or Achievable Potential] – [TRC or RIM]

Customer Class	Measure Name	Segment	Vintage	*Measure Name	TRC	RIM	PCT	Summer (MW)	Winter (MW)	Energy (GWh)
Residential	Ceiling Insulation(R12 to R38)	Single Family	New	N_SF_Ceiling	2.19	1.00	2.24	0.00	0.00	0.00
Residential	Home Energy Management System	Single Family	New	N_SF_Home	1.71	1.00	1.75	0.02	0.04	0.11
Residential	Ceiling Insulation(R12 to R38)	Single Family	Existing	E_SF_Ceiling	2.19	1.00	2.24	1.92	0.88	2.93
Residential	Home Energy Management System	Single Family	Existing	E_SF_Home	1.71	1.00	1.76	0.63	0.28	0.81
Residential	Energy Star Windows	Single Family	Existing	E_SF_Energy	3.36	1.02	3.46	3.89	1.70	7.85
Residential	Duct Repair	Single Family	Existing	E_SF_Duct R	3.19	1.00	3.56	6.25	2.75	9.96
Residential	Air Sealing-Infiltration Control	Single Family	Existing	E_SF_Air Se	1.24	1.00	1.25	5.78	2.53	9.15
Residential	Ceiling Insulation(R12 to R38)	Multi-Family	New	N_MF_Ceilin	1.65	1.00	1.67	0.00	0.00	0.00
Residential	Ceiling Insulation(R12 to R38)	Multi-Family	Existing	E_MF_Ceilin	1.65	1.00	1.67	0.57	0.26	0.89
Residential	15 SEER Air Source Heat Pump	Single Family	Turnover	T_SF_15 SE	1.44	1.00	1.46	4.61	8.57	10.71
Residential	14 SEER ASHP from base electric resistance heating	Single Family	Turnover	T_SF_14 SE	3.18	1.00	3.40	0.00	7.84	12.11
Residential	15 SEER Air Source Heat Pump	Single Family	New	N_SF_15 SE	1.44	1.00	1.46	1.08	2.00	2.50
Residential	14 SEER ASHP from base electric resistance heating	Single Family	New	N_SF_14 SE	3.18	1.00	3.40	0.00	1.83	2.83
Residential	Ceiling Insulation(R12 to R38)	Manufactured Home	New	N_MH_Ceilin	1.55	1.00	1.57	0.00	0.00	0.00
Residential	Ceiling Insulation(R12 to R38)	Manufactured Home	Existing	E_MH_Ceilin	1.55	1.00	1.57	0.21	0.19	0.41
Residential	Ceiling Insulation(R19 to R38)	Single Family	New	N_SF_Ceilin	1.31	1.00	1.32	0.00	0.00	0.00
Residential	Ceiling Insulation(R19 to R38)	Single Family	Existing	E_SF_Ceilin	1.31	1.00	1.32	0.38	0.17	0.57
Residential	16 SEER Central AC	Single Family	Turnover	T_SF_16 SE	1.46	1.00	1.48	2.90	0.00	5.68
Residential	15 SEER Central AC	Single Family	Turnover	T_SF_15 SE	1.52	1.00	1.55	0.00	0.00	0.00
Residential	16 SEER Central AC	Single Family	New	N_SF_16 SE	1.46	1.00	1.48	0.66	0.00	1.12
Residential	15 SEER Central AC	Single Family	New	N_SF_15 SE	1.52	1.00	1.55	0.00	0.00	0.00
Residential	Ceiling Insulation(R2 to R38)	Single Family	New	N_SF_Ceiling	6.32	1.19	5.97	0.00	0.00	0.00
Residential	Ceiling Insulation(R2 to R38)	Single Family	Existing	E_SF_Ceiling	6.32	1.19	5.97	0.30	0.13	0.43
Residential	Home Energy Management System	Multi-Family	New	N_MF_Home	1.25	1.00	1.27	0.09	0.02	0.07
Residential	Home Energy Management System	Multi-Family	Existing	E_MF_Home	1.25	1.00	1.27	0.70	0.12	0.55
Residential	Energy Star Windows	Multi-Family	Existing	E_MF_Energy	3.36	1.02	3.46	1.99	0.35	3.89
Residential	Duct Repair	Multi-Family	Existing	E_MF_Duct	2.17	1.00	2.28	9.21	1.64	10.32
Residential	Air Sealing-Infiltration Control	Multi-Family	Existing	E_MF_Air Se	1.35	1.00	1.37	4.83	0.86	5.41
Residential	Ceiling Insulation(R2 to R38)	Multi-Family	New	N_MF_Ceilin	4.76	1.12	4.60	0.00	0.00	0.00
Residential	Ceiling Insulation(R2 to R38)	Multi-Family	Existing	E_MF_Ceilin	4.76	1.12	4.60	0.95	0.38	1.46
Residential	14 SEER ASHP from base electric resistance heating	Multi-Family	Turnover	T_MF_14 SE	2.93	1.00	3.11	0.00	0.62	0.96
Residential	14 SEER ASHP from base electric resistance heating	Multi-Family	New	N_MF_14 SE	2.93	1.00	3.11	0.00	0.15	0.23
Residential	Ceiling Insulation(R2 to R38)	Manufactured Home	New	N_MH_Ceilin	4.66	1.12	4.52	0.00	0.00	0.00
Residential	Ceiling Insulation(R2 to R38)	Manufactured Home	Existing	E_MH_Ceilin	4.66	1.12	4.52	0.44	0.28	0.73
Residential	Home Energy Management System	Manufactured Home	New	N_MH_Hom	1.88	1.00	1.95	0.15	0.03	0.11
Residential	Home Energy Management System	Manufactured Home	Existing	E_MH_Home	1.88	1.00	1.95	1.12	0.21	0.84
Residential	Energy Star Windows	Manufactured Home	Existing	E_MH_Energ	3.36	1.02	3.46	0.90	0.17	1.77
Residential	Duct Repair	Manufactured Home	Existing	E_MH_Duct	3.13	1.00	3.43	6.58	1.25	6.96
Residential	Air Sealing-Infiltration Control	Manufactured Home	Existing	E_MH_Air Se	1.88	1.00	1.95	3.38	0.64	3.58
Residential	Spray Foam Insulation(Base R2)	Single Family	New	N_SF_Spray	1.48	1.00	1.50	0.00	0.00	0.00
Residential	Spray Foam Insulation(Base R2)	Single Family	Existing	E_SF_Spray	1.48	1.00	1.50	5.48	2.39	8.76
Residential	14 SEER ASHP from base electric resistance heating	Manufactured Home	Turnover	T_MH_14 SE	2.04	1.00	2.11	0.00	0.30	0.46
Residential	14 SEER ASHP from base electric resistance heating	Manufactured Home	New	N_MH_14 SE	2.04	1.00	2.11	0.00	0.07	0.11
Residential	Wall Insulation	Single Family	Existing	E_SF_Wall I	1.31	1.00	1.32	0.69	0.32	0.73
Residential	Wall Insulation	Manufactured Home	Existing	E_MH_Wall	1.51	1.00	1.53	0.16	0.08	0.13
Commercial	Thermal Energy Storage	Assembly	New	N_AS_Therm	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Duct Sealing Repair	Assembly	New	N_AS_Duct	4.47	1.41	3.50	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	Assembly	New	N_AS_Ceilin	4.14	1.08	4.24	0.00	0.00	0.00
Commercial	Wall Insulation	Assembly	Existing	E_AS_Wall I	3.16	1.02	3.34	0.06	0.00	0.00
Commercial	Thermal Energy Storage	Assembly	Existing	E_AS_Therm	2.48	2.92	9999.00	1.78	0.52	-0.28
Commercial	Low U-Value Windows	Assembly	Existing	E_AS_Low U	1.41	1.03	1.43	0.05	0.00	0.13
Commercial	Duct Sealing Repair	Assembly	Existing	E_AS_Duct S	4.47	1.41	3.50	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	Assembly	Existing	E_AS_Ceilin	4.21	1.08	4.31	0.00	0.00	0.00
Commercial	Demand Controlled Ventilation	Assembly	New	N_AS_Dema	2.75	1.07	2.87	0.01	0.05	0.09
Commercial	Demand Controlled Ventilation	Assembly	Existing	E_AS_Dema	2.75	1.07	2.87	0.07	0.40	0.68
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Assembly	Turnover	T_AS_High I	1.43	1.03	1.45	0.03	0.00	0.07
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Assembly	Turnover	T_AS_High I	2.40	1.03	2.49	0.05	0.00	0.13
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Assembly	New	N_AS_High I	1.43	1.03	1.45	0.01	0.00	0.02
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Assembly	New	N_AS_High I	2.40	1.03	2.49	0.02	0.00	0.04
Commercial	Thermal Energy Storage	College and University	New	N_CU_Therm	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Duct Sealing Repair	College and University	New	N_CU_Duct	6.45	1.56	4.79	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	College and University	New	N_CU_Ceilin	4.11	1.07	4.24	0.00	0.00	0.00
Commercial	Wall Insulation	College and University	Existing	E_CU_Wall I	3.06	1.02	3.22	0.00	0.00	0.00
Commercial	Thermal Energy Storage	College and University	Existing	E_CU_Therm	2.48	2.92	9999.00	0.04	0.01	-0.01
Commercial	Low U-Value Windows	College and University	Existing	E_CU_Low U	1.41	1.03	1.43	0.00	0.00	0.03
Commercial	Duct Sealing Repair	College and University	Existing	E_CU_Duct S	6.45	1.56	4.79	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	College and University	Existing	E_CU_Ceilin	4.18	1.08	4.31	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	College and University	Turnover	T_CU_High I	1.58	1.03	1.61	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	College and University	Turnover	T_CU_High I	2.65	1.03	2.76	0.00	0.00	0.01
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	College and University	New	N_CU_High I	1.58	1.03	1.61	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	College and University	New	N_CU_High I	2.65	1.03	2.76	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Grocery	New	N_GR_Therm	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	Grocery	New	N_GR_Ceilin	4.24	1.11	4.24	0.00	0.00	0.00
Commercial	Wall Insulation	Grocery	Existing	E_GR_Wall I	3.20	1.02	3.38	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Grocery	Existing	E_GR_Therm	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Low U-Value Windows	Grocery	Existing	E_GR_Low U	1.41	1.03	1.43	0.04	0.00	0.11
Commercial	Ceiling Insulation(R2 to R38)	Grocery	Existing	E_GR_Ceilin	4.32	1.11	4.31	0.00	0.00	0.00
Commercial	High Efficiency PTHP	Grocery	Turnover	T_GR_High I	4.42	1.21	4.12	0.00	0.00	0.00
Commercial	High Efficiency PTAC	Grocery	Turnover	T_GR_High I	4.32	1.22	3.99	0.00	0.00	0.00
Commercial	High Efficiency PTHP	Grocery	New	N_GR_High I	4.42	1.21	4.12	0.00	0.00	0.00
Commercial	High Efficiency PTAC	Grocery	New	N_GR_High I	4.32	1.22	3.99	0.00	0.00	0.00
Commercial	Demand Controlled Ventilation	Grocery	New	N_GR_Dema	1.33	1.04	1.35	0.01	0.04	0.07
Commercial	Demand Controlled Ventilation	Grocery	Existing	E_GR_Dema	1.33	1.04	1.35	0.05	0.31	0.53
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Grocery	Turnover	T_GR_High I	1.36	1.03	1.37	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Grocery	New	N_GR_High I	1.36	1.03	1.37	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Healthcare	New	N_HC_Therm	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	Healthcare	New	N_HC_Ceilin	4.14	1.08	4.24	0.00	0.00	0.00
Commercial	Wall Insulation	Healthcare	Existing	E_HC_Wall I	3.04	1.02	3.19	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Healthcare	Existing	E_HC_Therm	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Low U-Value Windows	Healthcare	Existing	E_HC_Low U	1.41	1.03	1.43	0.06	0.00	0.16
Commercial	Ceiling Insulation(R2 to R38)	Healthcare	Existing	E_HC_Ceilin	4.21	1.08	4.31	0.04	0.01	2.19
Commercial	High Efficiency DX 135k- less than 240k BTU	Healthcare	Turnover	T_HC_High	1.44	1.03	1.46	0.46	0.00	1.12
Commercial	High Efficiency DX 135k- less than 240k BTU	Healthcare	New	N_HC_High	1.44	1.03	1.46	0.11	0.00	0.27
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Healthcare	Turnover	T_HC_High	2.99	1.03	3.15	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Healthcare	Turnover	T_HC_High	4.89	1.09	5.10	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Healthcare	New	N_HC_High	2.99	1.03	3.15	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Healthcare	New	N_HC_High	4.89	1.09	5.10	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Hospitals	New	N_HS_Therm	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	Hospitals	New	N_HS_Ceilin	4.11	1.07	4.24	0.00	0.00	0.00
Commercial	Wall Insulation	Hospitals	Existing	E_HS_Wall I	3.10	1.02	3.27	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Hospitals	Existing	E_HS_Therm	2.48	2.92	9999.00	2.92	0.85	-0.46
Commercial	Low U-Value Windows	Hospitals	Existing	E_HS_Low U	1.41	1.03	1.43	0.05	0.00	0.14
Commercial	Ceiling Insulation(R2 to R38)	Hospitals	Existing	E_HS_Ceilin	4.18	1.08	4.31	0.00	0.00	0.00
Commercial	High Efficiency DX 135k- less than 240k BTU	Hospitals	Turnover	T_HS_High	1.37	1.03	1.39	0.17	0.00	0.42
Commercial	High Efficiency DX 135k- less than 240k BTU	Hospitals	New	N_HS_High	1.37	1.03	1.39	0.04	0.00	0.10
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Hospitals	Turnover	T_HS_High I	2.85	1.03	2.98	0.07	0.00	0.19
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Hospitals	Turnover	T_HS_High I	4.66	1.08	4.89	0.12	0.00	0.32
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Hospitals	New	N_HS_High	2.85	1.03	2.98	0.02	0.00	0.06
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Hospitals	New	N_HS_High	4.66	1.08	4.89	0.04	0.00	0.11
Commercial	Thermal Energy Storage	Institutional	New	N_IN_Therm	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	Institutional	New	N_IN_Ceilin	4.14	1.08	4.24	0.00	0.00	0.00
Commercial	Wall Insulation	Institutional	Existing	E_IN_Wall I	3.08	1.02	3.24	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Institutional	Existing	E_IN_Therm	2.48	2.92	9999.00	0.73	0.21	-0.12
Commercial	Low U-Value Windows	Institutional	Existing	E_IN_Low U	1.41	1.03	1.43	0.03	0.00	0.07
Commercial	Ceiling Insulation(R2 to R38)	Institutional	Existing	E_IN_Ceilin	4.21	1.08	4.31	0.00	0.00	0.00
Commercial	High Efficiency PTHP	Institutional	Turnover	T_IN_High I	4.26	1.20	3.99	0.00	0.00	0.00
Commercial	High Efficiency PTAC	Institutional	Turnover	T_IN_High I	4.23	1.21	3.92	0.00	0.00	0.01
Commercial	High Efficiency PTHP	Institutional	New	N_IN_High I	4.26	1.20	3.99	0.00	0.00	0.00
Commercial	High Efficiency PTAC	Institutional	New	N_IN_High I	4.23	1.21	3.92	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Institutional	Turnover	T_IN_High I	1.33	1.03	1.34	0.03	0.00	0.07
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Institutional	New	N_IN_High I	1.33	1.03	1.34	0.01	0.00	0.02
Commercial	Thermal Energy Storage	Lodging/Hospitality	New	N_LG_Therm	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Smart Thermostat	Lodging/Hospitality	New	N_LG_Smart	11.17	4.50	2.73	-0.02	0.09	0.69
Commercial	Programmable Thermostat	Lodging/Hospitality	New	N_LG_Progr	6.56	3.51	1.98	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	Lodging/Hospitality	New	N_LG_Ceilin	4.11	1.07	4.24	0.00	0.00	0.00

Achievable Potential - RIM

Failing Measures Results
[Economic Potential or Achievable Potential] – [TRC or RIM]

Customer Class	Measure Name	Segment	Vintage	*Measure Name	TRC	RIM	PCT	Summer (MW)	Winter (MW)	Energy (GWh)	Reason For Failure
Commercial	Efficient Battery Charger	Assembly	Turnover	T_AS_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	College and University	Turnover	T_CU_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Grocery	Turnover	T_GR_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Healthcare	Turnover	T_HC_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Hospitals	Turnover	T_HS_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Institutional	Turnover	T_IN_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Lodging/Hospitality	Turnover	T_LG_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Miscellaneous	Turnover	T_MS_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Offices	Turnover	T_OF_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Restaurants	Turnover	T_RS_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Retail	Turnover	T_RT_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Schools K-12	Turnover	T_SC_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Warehouse	Turnover	T_WR_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Assembly	New	N_AS_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	College and University	New	N_CU_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Grocery	New	N_GR_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Healthcare	New	N_HC_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Hospitals	New	N_HS_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Institutional	New	N_IN_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Lodging/Hospitality	New	N_LG_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Miscellaneous	New	N_MS_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Offices	New	N_OF_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Restaurants	New	N_RS_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Retail	New	N_RT_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Schools K-12	New	N_SC_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Commercial	Efficient Battery Charger	Warehouse	New	N_WR_Effic	1.47	0.96	1.59	0	0	0	Fail RIM
Residential	Room AC control	Multi Family	New		0.55	0.55	N/A	0	0	0	Fail RIM
Residential	Smart thermostats - Utility Installation	Single Family	New		1.08	0.70	N/A	0	0	0	Fail RIM
Residential	Smart thermostats - Utility Installation	Multi Family	New		0.56	0.51	N/A	0	0	0	Fail RIM
Residential	Smart thermostats - Utility Installation	Mobile Home/Other	New		1.06	0.70	N/A	0	0	0	Fail RIM
Residential	CPP + Tech	Single Family	New		1.43	0.97	N/A	0	0	0	Fail RIM
Residential	CPP + Tech	Multi Family	New		0.97	0.90	N/A	0	0	0	Fail RIM
Residential	CPP + Tech	Mobile Home/Other	New		1.42	0.97	N/A	0	0	0	Fail RIM
Small C&I	CPP + Tech	0-15,000 kWh	New		0.40	0.80	N/A	0	0	0	Fail RIM
Small C&I	CPP + Tech	15,001-25,000 kWh	New		0.81	0.80	N/A	0	0	0	Fail RIM
Small C&I	CPP + Tech	25,001-50,000 kWh	New		1.04	0.69	N/A	0	0	0	Fail RIM
Small C&I	CPP + Tech	50,001 kWh +	New		2.66	0.96	N/A	0	0	0	Fail RIM
Small C&I	Smart thermostats - Utility Installation	0-15,000 kWh	New		0.40	0.81	N/A	0	0	0	Fail RIM
Small C&I	Smart thermostats - Utility Installation	15,001-25,000 kWh	New		0.83	0.81	N/A	0	0	0	Fail RIM
Small C&I	Smart thermostats - Utility Installation	25,001-50,000 kWh	New		1.07	0.70	N/A	0	0	0	Fail RIM
Small C&I	Smart thermostats - Utility Installation	50,001 kWh +	New		2.83	0.99	N/A	0	0	0	Fail RIM

Achievable Potential - TRC

Passing Measures Results
[Economic Potential or Achievable Potential] – [TRC or RIM]

Customer Class	Measure Name	Segment	Vintage	*Measure Name	TRC	RIM	PCT	Summer (MW)	Winter (MW)	Energy (GWh)
Residential	High Efficiency Induction Cooktop	Single Family	Turnover	T_SF_High I	1.78	0.67	2.85	1.51	0.25	3.67
Residential	High Efficiency Induction Cooktop	Multi-Family	Turnover	T_MF_High	1.78	0.67	2.85	0.05	0.00	1.13
Residential	High Efficiency Induction Cooktop	Manufactured Home	Turnover	T_MH_High	1.78	0.67	2.85	0.12	0.02	0.30
Residential	High Efficiency Induction Cooktop	Single Family	New	N_SF_High I	1.78	0.67	2.85	0.32	0.05	0.77
Residential	High Efficiency Induction Cooktop	Multi-Family	New	N_MF_High	1.78	0.67	2.85	0.10	0.02	0.24
Residential	High Efficiency Induction Cooktop	Manufactured Home	New	N_MH_High	1.78	0.67	2.85	0.03	0.00	0.06
Residential	14 SEER ASHP from base electric resistance heating	Single Family	Turnover	T_SF_14 SE	3.18	0.99	3.45	0.00	8.03	12.40
Residential	14 SEER ASHP from base electric resistance heating	Multi-Family	Turnover	T_MF_14 SE	2.93	0.96	3.24	0.00	0.66	1.02
Residential	14 SEER ASHP from base electric resistance heating	Manufactured Home	Turnover	T_MH_14 SE	2.04	0.84	2.52	0.00	0.36	0.55
Residential	14 SEER ASHP from base electric resistance heating	Single Family	New	N_SF_14 SE	3.18	0.99	3.45	0.00	1.88	2.89
Residential	14 SEER ASHP from base electric resistance heating	Multi-Family	New	N_MF_14 SE	2.93	0.96	3.24	0.00	0.15	0.24
Residential	14 SEER ASHP from base electric resistance heating	Manufactured Home	New	N_MH_14 SE	2.04	0.84	2.52	0.00	0.08	0.13
Residential	15 SEER Air Source Heat Pump	Single Family	Turnover	T_SF_15 SE	1.44	0.73	2.02	5.88	10.58	13.61
Residential	15 SEER Air Source Heat Pump	Single Family	New	N_SF_15 SE	1.44	0.73	2.02	1.37	2.47	3.17
Residential	15 SEER Central AC	Single Family	Turnover	T_SF_15 SE	1.52	0.71	2.21	0.49	0.00	4.08
Residential	15 SEER Central AC	Single Family	New	N_SF_15 SE	1.52	0.71	2.21	0.43	0.00	0.84
Residential	16 SEER Central AC	Single Family	Turnover	T_SF_16 SE	1.46	0.69	2.16	0.00	0.00	0.00
Residential	16 SEER Central AC	Single Family	New	N_SF_16 SE	1.46	0.69	2.16	0.00	0.00	0.00
Residential	LED - 9W Flood	Single Family	Turnover	T_SF_LED	1.15	0.34	3.78	2.46	2.58	27.94
Residential	LED - 9W Flood	Multi-Family	Turnover	T_MF_LED	1.15	0.34	3.78	1.12	1.18	12.77
Residential	LED - 9W Flood	Manufactured Home	Turnover	T_MH_LED	1.15	0.34	3.78	0.32	0.34	3.63
Residential	LED - 9W Flood	Single Family	New	N_SF_LED	1.15	0.34	3.78	0.36	0.38	4.14
Residential	LED - 9W Flood	Multi-Family	New	N_MF_LED	1.15	0.34	3.78	0.17	0.17	1.89
Residential	LED - 9W Flood	Manufactured Home	New	N_MH_LED	1.15	0.34	3.78	0.05	0.05	0.54
Residential	LED Specialty Lamps-SW Chandelier	Single Family	Turnover	T_SF_LED S	1.21	0.35	3.95	0.07	0.07	0.80
Residential	LED Specialty Lamps-SW Chandelier	Multi-Family	Turnover	T_MF_LED	1.21	0.35	3.95	0.03	0.03	0.37
Residential	LED Specialty Lamps-SW Chandelier	Manufactured Home	Turnover	T_MH_LED	1.21	0.35	3.95	0.01	0.01	0.11
Residential	LED Specialty Lamps-SW Chandelier	Single Family	New	N_SF_LED S	1.21	0.35	3.95	0.01	0.01	0.13
Residential	LED Specialty Lamps-SW Chandelier	Multi-Family	New	N_MF_LED	1.21	0.35	3.95	0.01	0.01	0.07
Residential	LED Specialty Lamps-SW Chandelier	Manufactured Home	New	N_MH_LED	1.21	0.35	3.95	0.00	0.00	0.02
Residential	Two Speed Pool Pump	Single Family	Turnover	T_SF_Two S	1.22	0.41	3.29	1.35	1.52	9.01
Residential	Two Speed Pool Pump	Multi-Family	Turnover	T_MF_Two	1.22	0.41	3.29	0.00	0.00	0.00
Residential	Two Speed Pool Pump	Manufactured Home	Turnover	T_MH_Two	1.22	0.41	3.29	0.00	0.00	0.00
Residential	Two Speed Pool Pump	Single Family	New	N_SF_Two S	1.22	0.41	3.29	0.23	0.26	1.57
Residential	Two Speed Pool Pump	Multi-Family	New	N_MF_Two	1.22	0.41	3.29	0.00	0.00	0.00
Residential	Two Speed Pool Pump	Manufactured Home	New	N_MH_Two	1.22	0.41	3.29	0.00	0.00	0.00
Residential	Variable Speed Pool Pump	Single Family	Turnover	T_SF_Variab	1.22	0.41	3.29	0.00	0.00	0.00
Residential	Variable Speed Pool Pump	Multi-Family	Turnover	T_MF_Varia	1.22	0.41	3.29	0.00	0.00	0.00
Residential	Variable Speed Pool Pump	Manufactured Home	Turnover	T_MH_Varia	1.22	0.41	3.29	0.00	0.00	0.00
Residential

Commercial	Wall Insulation	Lodging/Hospitality	Existing	E_LG_Wall I	3.06	1.02	3.22	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Lodging/Hospitality	Existing	E_LG_Ther	2.48	2.92	9999.00	0.58	0.17	-0.09
Commercial	Smart Thermostat	Lodging/Hospitality	Existing	E_LG_Smart	11.17	4.56	2.73	-0.17	0.72	5.66
Commercial	Programmable Thermostat	Lodging/Hospitality	Existing	E_LG_Progr	6.56	3.51	1.98	0.00	0.00	0.00
Commercial	Low U-Value Windows	Lodging/Hospitality	Existing	E_LG_Low U	1.60	1.02	1.63	0.14	0.00	0.33
Commercial	Ceiling Insulation(R2 to R38)	Lodging/Hospitality	Existing	E_LG_Ceilin	4.18	1.08	4.31	0.00	0.00	0.00
Commercial	Demand Controlled Ventilation	Lodging/Hospitality	New	N_LG_Dema	4.20	1.24	4.05	0.07	0.40	0.68
Commercial	Demand Controlled Ventilation	Lodging/Hospitality	Existing	E_LG_Dema	4.20	1.24	4.05	0.50	2.81	4.75
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Lodging/Hospitality	Turnover	T_LG_High I	2.31	1.03	2.39	0.01	0.00	0.03
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Lodging/Hospitality	Turnover	T_LG_High I	3.82	1.03	4.11	0.02	0.00	0.06
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Lodging/Hospitality	New	N_LG_High	2.31	1.03	2.39	0.00	0.00	0.01
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Lodging/Hospitality	New	N_LG_High	3.82	1.03	4.11	0.01	0.00	0.02
Commercial	Thermal Energy Storage	Miscellaneous	New	N_MS_Ther	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	Miscellaneous	New	N_MS_Ceilin	4.14	1.08	4.24	0.00	0.00	0.00
Commercial	Wall Insulation	Miscellaneous	Existing	E_MS_Wall I	3.12	1.02	3.29	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Miscellaneous	Existing	E_MS_Ther	2.48	2.92	9999.00	1.22	0.35	-0.19
Commercial	Low U-Value Windows	Miscellaneous	Existing	E_MS_Low U	1.33	1.03	1.35	0.09	0.00	0.28
Commercial	Ceiling Insulation(R2 to R38)	Miscellaneous	Existing	E_MS_Ceilin	4.21	1.08	4.31	0.00	0.00	0.00
Commercial	High Efficiency PTHP	Miscellaneous	Turnover	T_MS_High	4.35	1.21	4.07	0.02	0.00	0.04
Commercial	High Efficiency PTAC	Miscellaneous	Turnover	T_MS_High	3.80	1.06	4.02	0.00	0.00	0.00
Commercial	High Efficiency PTHP	Miscellaneous	New	N_MS_High	4.35	1.21	4.07	0.01	0.00	0.01
Commercial	High Efficiency PTAC	Miscellaneous	New	N_MS_High	3.80	1.06	4.02	0.00	0.00	0.00
Commercial	Demand Controlled Ventilation	Miscellaneous	New	N_MS_Dem	3.87	1.21	3.77	0.01	0.03	0.05
Commercial	Demand Controlled Ventilation	Miscellaneous	Existing	E_MS_Dema	3.87	1.21	3.77	0.04	0.20	0.35
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Miscellaneous	Turnover	T_MS_High	1.38	1.03	1.39	0.03	0.00	0.07
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Miscellaneous	New	N_MS_High	1.38	1.03	1.39	0.01	0.00	0.02
Commercial	Thermal Energy Storage	Offices	New	N_OF_Ther	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	Offices	New	N_OF_Ceilin	4.14	1.08	4.24	0.00	0.00	0.00
Commercial	Wall Insulation	Offices	Existing	E_OF_Wall I	3.12	1.02	3.29	0.01	0.00	0.54
Commercial	Thermal Energy Storage	Offices	Existing	E_OF_Ther	2.48	2.92	9999.00	1.99	0.58	-0.32
Commercial	Low U-Value Windows	Offices	Existing	E_OF_Low U	1.41	1.03	1.43	0.09	0.00	0.27
Commercial	Ceiling Insulation(R2 to R38)	Offices	Existing	E_OF_Ceilin	4.21	1.08	4.31	0.03	0.08	1.55
Commercial	Demand Controlled Ventilation	Offices	New	N_OF_Dema	4.02	1.22	3.90	0.08	0.47	0.79
Commercial	Demand Controlled Ventilation	Offices	Existing	E_OF_Dema	4.02	1.22	3.90	0.77	4.34	7.41
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Offices	Turnover	T_OF_High I	1.60	1.03	1.63	0.05	0.00	0.13
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Offices	Turnover	T_OF_High I	2.68	1.03	2.80	0.09	0.00	0.24
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Offices	New	N_OF_High	1.60	1.03	1.63	0.02	0.00	0.04
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Offices	New	N_OF_High	2.68	1.03	2.80	0.03	0.00	0.08
Commercial	Thermal Energy Storage	Restaurants	New	N_RS_Ther	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	Restaurants	New	N_RS_Ceilin	4.24	1.11	4.24	0.00	0.00	0.00
Commercial	Wall Insulation	Restaurants	Existing	E_RS_Wall I	3.25	1.03	3.42	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Restaurants	Existing	E_RS_Ther	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Low U-Value Windows	Restaurants	Existing	E_RS_Low U	1.41	1.03	1.43	0.12	0.00	0.36
Commercial	Ceiling Insulation(R2 to R38)	Restaurants	Existing	E_RS_Ceilin	4.32	1.11	4.31	0.00	0.00	0.00
Commercial	Demand Controlled Ventilation	Restaurants	New	N_RS_Dema	1.43	1.04	1.45	0.02	0.10	0.17
Commercial	Demand Controlled Ventilation	Restaurants	Existing	E_RS_Dema	1.43	1.04	1.45	0.12	0.70	1.19
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Restaurants	Turnover	T_RS_High I	2.27	1.03	2.35	0.00	0.00	0.01
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Restaurants	Turnover	T_RS_High I	3.75	1.03	4.03	0.01	0.00	0.02
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Restaurants	New	N_RS_High	2.27	1.03	2.35	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Restaurants	New	N_RS_High	3.75	1.03	4.03	0.00	0.00	0.01
Commercial	Thermal Energy Storage	Retail	New	N_RT_Ther	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Duct Sealing Repair	Retail	New	N_RT_Duct	7.63	1.62	5.62	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	Retail	New	N_RT_Ceilin	4.24	1.11	4.24	0.00	0.00	0.00
Commercial	Wall Insulation	Retail	Existing	E_RT_Wall I	3.20	1.02	3.38	0.07	0.00	0.36
Commercial	Thermal Energy Storage	Retail	Existing	E_RT_Ther	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Low U-Value Windows	Retail	Existing	E_RT_Low U	1.41	1.03	1.43	0.10	0.00	0.27
Commercial	Duct Sealing Repair	Retail	Existing	E_RT_Duct	7.63	1.62	5.62	1.57	0.14	8.15
Commercial	Ceiling Insulation(R2 to R38)	Retail	Existing	E_RT_Ceilin	4.32	1.11	4.31	0.00	0.00	0.00
Commercial	Demand Controlled Ventilation	Retail	New	N_RT_Dema	2.98	1.11	3.05	0.12	0.68	1.16
Commercial	Demand Controlled Ventilation	Retail	Existing	E_RT_Dema	2.98	1.11	3.05	0.85	4.80	8.18
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Retail	Turnover	T_RT_High I	1.80	1.03	1.84	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Retail	Turnover	T_RT_High I	3.00	1.03	3.16	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Retail	New	N_RT_High	1.80	1.03	1.84	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Retail	New	N_RT_High	3.00	1.03	3.16	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Schools K-12	New	N_SC_Ther	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Duct Sealing Repair	Schools K-12	New	N_SC_Duct	6.45	1.56	4.79	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	Schools K-12	New	N_SC_Ceilin	4.14	1.08	4.24	0.00	0.00	0.00
Commercial	Wall Insulation	Schools K-12	Existing	E_SC_Wall I	3.21	1.02	3.39	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Schools K-12	Existing	E_SC_Ther	2.48	2.92	9999.00	0.48	0.14	-0.08
Commercial	Low U-Value Windows	Schools K-12	Existing	E_SC_Low U	1.41	1.03	1.43	0.02	0.00	0.05
Commercial	Duct Sealing Repair	Schools K-12	Existing	E_SC_Duct	6.45	1.56	4.79	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R38)	Schools K-12	Existing	E_SC_Ceilin	4.21	1.08	4.31	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Schools K-12	Turnover	T_SC_High I	1.58	1.03	1.60	0.01	0.00	0.04
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Schools K-12	Turnover	T_SC_High I	2.63	1.03	2.75	0.02	0.00	0.06
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Schools K-12	New	N_SC_High	1.58	1.03	1.60	0.00	0.00	0.01
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Schools K-12	New	N_SC_High	2.63	1.03	2.75	0.01	0.00	0.02
Commercial	Thermal Energy Storage	Warehouse	New	N_WR_Ther	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Duct Sealing Repair	Warehouse	New	N_WR_Duct	2.29	1.09	2.22	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Warehouse	Existing	E_WR_Ther	2.48	2.92	9999.00	0.00	0.00	0.00
Commercial	Low U-Value Windows	Warehouse	Existing	E_WR_Low	1.33	1.03	1.35	0.01	0.00	0.03
Commercial	Duct Sealing Repair	Warehouse	Existing	E_WR_Duct	2.29	1.09	2.22	0.00	0.00	0.00
Commercial	High Efficiency PTHP	Warehouse	Turnover	T_WR_High	2.06	1.03	2.12	0.00	0.00	0.00
Commercial	High Efficiency PTAC	Warehouse	Turnover	T_WR_High	2.02	1.03	2.08	0.00	0.00	0.00
Commercial	High Efficiency PTHP	Warehouse	New	N_WR_High	2.06	1.03	2.12	0.00	0.00	0.00
Commercial	High Efficiency PTAC	Warehouse	New	N_WR_High	2.02	1.03	2.08	0.00	0.00	0.00
Commercial	Demand Controlled Ventilation	Warehouse	New	N_WR_Dem	1.20	1.04	1.21	0.01	0.05	0.08
Commercial	Demand Controlled Ventilation	Warehouse	Existing	E_WR_Dem	1.20	1.04	1.21	0.06	0.35	0.59
Residential	Central air conditioner - Load Shed	Single Family	Existing		1.90	1.90	N/A	0.00	0.00	0.00
Residential	Central air conditioner - Load Shed	Multi Family	Existing		1.00	1.00	N/A	18.34	0.00	0.00
Residential	Central air conditioner - Load Shed	Mobile Home/Other	Existing		1.87	1.87	N/A	7.22	0.00	0.00
Residential	Central Heating - Load Shed	Single Family	Existing		2.17	2.17	N/A	0.00	0.00	0.00
Residential	Central Heating - Load Shed	Multi Family	Existing		1.25	1.25	N/A	0.00	23.34	0.00
Residential	Central Heating - Load Shed	Mobile Home/Other	Existing		2.09	2.09	N/A	0.00	8.04	0.00
Residential	Central air conditioner - 50% cycling	Single Family	Existing		1.00	1.00	N/A	0.00	0.00	0.00
Residential	Central air conditioner - 50% cycling	Multi Family	Existing		1.00	1.00	N/A	0.00	0.00	0.00
Residential	Central air conditioner - 50% cycling	Mobile Home/Other	Existing		1.00	1.00	N/A	0.00	0.00	0.00
Residential	Central Heating - 50% cycling	Single Family	Existing		1.05	1.05	N/A	0.00	0.00	0.00

Commercial	Energy Star Hot Food Holding Cabinet	Institutional	New	N_IN_Energ	1.18	0.48	2.57	0.00	0.00	0.00
Commercial	Energy Star Hot Food Holding Cabinet	Lodging/Hospitality	New	N_LG_Energ	1.18	0.48	2.57	0.02	0.01	0.09
Commercial	Energy Star Hot Food Holding Cabinet	Miscellaneous	New	N_MS_Energ	1.18	0.48	2.57	0.00	0.00	0.00
Commercial	Energy Star Hot Food Holding Cabinet	Offices	New	N_OF_Energ	1.18	0.48	2.57	0.00	0.00	0.00
Commercial	Energy Star Hot Food Holding Cabinet	Restaurants	New	N_RS_Energ	1.18	0.48	2.57	0.08	0.04	0.48
Commercial	Energy Star Hot Food Holding Cabinet	Retail	New	N_RT_Energ	1.18	0.48	2.57	0.00	0.00	0.00
Commercial	Energy Star Hot Food Holding Cabinet	Schools K-12	New	N_SC_Energ	1.18	0.48	2.57	0.00	0.00	0.00
Commercial	Energy Star Hot Food Holding Cabinet	Warehouse	New	N_WR_Energ	1.18	0.48	2.57	0.00	0.00	0.00
Commercial	Heat Pump Water Heater	Assembly	Turnover	T_AS_Heat I	1.81	0.54	3.81	0.01	0.00	0.03
Commercial	Heat Pump Water Heater	Assembly	New	N_AS_Heat	1.81	0.54	3.81	0.00	0.00	0.00
Commercial	Solar Water Heater	Hospitals	Turnover	T_HS_Solar	1.00	0.35	3.02	0.00	0.00	0.02
Commercial	Solar Water Heater	Institutional	Turnover	T_IN_Solar V	1.17	0.37	3.40	0.03	0.00	0.39
Commercial	Solar Water Heater	Lodging/Hospitality	Turnover	T_LG_Solar	1.17	0.37	3.40	0.02	0.00	0.30
Commercial	Solar Water Heater	Miscellaneous	Turnover	T_MS_Solar	1.11	0.36	3.25	0.00	0.00	0.01
Commercial	Solar Water Heater	Offices	Turnover	T_OF_Solar	1.03	0.35	3.08	0.01	0.00	0.13
Commercial	Solar Water Heater	Hospitals	New	N_HS_Solar	1.00	0.35	3.02	0.00	0.00	0.00
Commercial	Solar Water Heater	Institutional	New	N_IN_Solar	1.17	0.37	3.40	0.00	0.00	0.05
Commercial	Solar Water Heater	Lodging/Hospitality	New	N_LG_Solar	1.17	0.37	3.40	0.00	0.00	0.04
Commercial	Solar Water Heater	Miscellaneous	New	N_MS_Solar	1.11	0.36	3.25	0.00	0.00	0.00
Commercial	Solar Water Heater	Offices	New	N_OF_Solar	1.03	0.35	3.08	0.00	0.00	0.02
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Assembly	Turnover	T_AS_High I	2.05	0.68	3.14	0.08	0.00	0.29
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	College and University	Turnover	T_CU_High I	2.26	0.71	3.37	0.00	0.00	0.02
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Grocery	Turnover	T_GR_High I	1.17	0.55	2.18	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Healthcare	Turnover	T_HC_High	4.14	0.82	5.65	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Hospitals	Turnover	T_HS_High I	3.95	0.82	5.41	0.17	0.01	0.62
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Institutional	Turnover	T_IN_High I	1.14	0.54	2.15	0.05	0.00	0.19
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Lodging/Hospitality	Turnover	T_LG_High I	3.25	0.78	4.53	0.03	0.00	0.11
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Miscellaneous	Turnover	T_MS_High	1.18	0.55	2.19	0.05	0.00	0.19
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Offices	Turnover	T_OF_High I	2.29	0.71	3.41	0.14	0.01	0.52
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Restaurants	Turnover	T_RS_High I	3.19	0.78	4.46	0.01	0.00	0.03
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Retail	Turnover	T_RT_High I	2.56	0.73	3.71	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Schools K-12	Turnover	T_SC_High I	2.25	0.71	3.36	0.04	0.00	0.14
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Assembly	New	N_AS_High	2.05	0.68	3.14	0.03	0.00	0.10
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	College and University	New	N_CU_High	2.26	0.71	3.37	0.00	0.00	0.01
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Grocery	New	N_GR_High	1.17	0.55	2.18	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Healthcare	New	N_HC_High	4.14	0.82	5.65	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Hospitals	New	N_HS_High	3.95	0.82	5.41	0.06	0.00	0.20
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Institutional	New	N_IN_High I	1.14	0.54	2.15	0.00	0.00	0.02
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Lodging/Hospitality	New	N_LG_High	3.25	0.78	4.53	0.01	0.00	0.04
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Miscellaneous	New	N_MS_High	1.18	0.55	2.19	0.00	0.00	0.02
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Offices	New	N_OF_High	2.29	0.71	3.41	0.05	0.00	0.17
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Restaurants	New	N_RS_High	3.19	0.78	4.46	0.00	0.00	0.01
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Retail	New	N_RT_High	2.56	0.73	3.71	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Air Cooled, 50 tons)	Schools K-12	New	N_SC_High	2.25	0.71	3.36	0.01	0.00	0.05
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Assembly	Turnover	T_AS_High I	2.40	0.87	2.89	0.06	0.00	0.15
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	College and University	Turnover	T_CU_High I	2.65	0.96	3.09	0.06	0.00	0.01
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Grocery	Turnover	T_GR_High I	1.36	0.68	2.04	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Healthcare	Turnover	T_HC_High	4.89	1.06	5.10	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Hospitals	Turnover	T_HS_High I	4.66	1.05	4.89	0.12	0.00	0.32
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Institutional	Turnover	T_IN_High I	1.33	0.67	2.02	0.04	0.00	0.10
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Lodging/Hospitality	Turnover	T_LG_High I	3.82	1.00	4.11	0.02	0.00	0.06
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Miscellaneous	Turnover	T_MS_High	1.38	0.68	2.05	0.04	0.00	0.09
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Offices	Turnover	T_OF_High I	2.68	0.90	3.12	0.10	0.00	0.27
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Restaurants	Turnover	T_RS_High I	3.75	0.99	4.06	0.01	0.00	0.02
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Retail	Turnover	T_RT_High I	3.00	0.93	3.39	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Schools K-12	Turnover	T_SC_High I	2.63	0.89	3.08	0.03	0.00	0.07
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Assembly	New	N_AS_High	2.40	0.87	2.89	0.02	0.00	0.05
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	College and University	New	N_CU_High	2.65	0.96	3.09	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Grocery	New	N_GR_High	1.36	0.68	2.04	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Healthcare	New	N_HC_High	4.89	1.06	5.10	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Hospitals	New	N_HS_High	4.66	1.05	4.89	0.04	0.00	0.11
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Institutional	New	N_IN_High I	1.33	0.67	2.02	0.01	0.00	0.02
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Lodging/Hospitality	New	N_LG_High	3.82	1.00	4.11	0.01	0.00	0.02
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Miscellaneous	New	N_MS_High	1.38	0.68	2.05	0.01	0.00	0.02
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Offices	New	N_OF_High	2.68	0.90	3.12	0.03	0.00	0.09
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Restaurants	New	N_RS_High	3.75	0.99	4.06	0.00	0.00	0.01
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Retail	New	N_RT_High	3.00	0.93	3.39	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-centrifugal, 200 tons)	Schools K-12	New	N_SC_High	2.63	0.89	3.08	0.01	0.00	0.02
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Assembly	Turnover	T_AS_High I	1.43	0.70	2.10	0.04	0.00	0.09
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	College and University	Turnover	T_CU_High I	1.58	0.73	2.22	0.00	0.00	0.01
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Healthcare	Turnover	T_HC_High	2.99	0.93	3.39	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Hospitals	Turnover	T_HS_High I	2.85	0.92	3.26	0.08	0.00	0.21
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Lodging/Hospitality	Turnover	T_LG_High I	2.31	0.85	2.81	0.01	0.00	0.04
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Offices	Turnover	T_OF_High I	1.60	0.73	2.23	0.06	0.00	0.17
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Restaurants	Turnover	T_RS_High I	2.27	0.85	2.78	0.00	0.00	0.01
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Retail	Turnover	T_RT_High I	1.80	0.77	2.39	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Schools K-12	Turnover	T_SC_High I	1.58	0.73	2.21	0.02	0.00	0.05
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Assembly	New	N_AS_High	1.43	0.70	2.10	0.00	0.00	0.01
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	College and University	New	N_CU_High	1.58	0.73	2.22	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Healthcare	New	N_HC_High	2.99	0.93	3.39	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Hospitals	New	N_HS_High	2.85	0.92	3.26	0.03	0.00	0.07
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Lodging/Hospitality	New	N_LG_High	2.31	0.85	2.81	0.00	0.00	0.01
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Offices	New	N_OF_High	1.60	0.73	2.23	0.01	0.00	0.02
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Restaurants	New	N_RS_High	2.27	0.85	2.78	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Retail	New	N_RT_High	1.80	0.77	2.39	0.00	0.00	0.00
Commercial	High Efficiency Chiller (Water cooled-positive displacement, 100 tons)	Schools K-12	New	N_SC_High	1.58	0.73	2.21	0.00	0.00	0.01
Commercial	High Efficiency DX 135k- less than 240k BTU	Healthcare	Turnover	T_HC_High	1.44	0.71	2.07	0.59	0.00	1.43
Commercial	High Efficiency DX 135k- less than 240k BTU	Hospitals	Turnover	T_HS_High I	1.37	0.70	2.01	0.23	0.00	0.55
Commercial	High Efficiency DX 135k- less than 240k BTU	Healthcare	New	N_HC_High	1.44	0.71	2.07	0.02	0.00	0.06
Commercial	High Efficiency DX 135k- less than 240k BTU	Hospitals	New	N_HS_High	1.37	0.70	2.01	0.01	0.00	0.02
Commercial	High Efficiency PTAC	Grocery	Turnover	T_GR_High I	4.32	1.18	3.99	0.00	0.00	0.00
Commercial	High Efficiency PTAC	Institutional	Turnover	T_IN_High I	4.23	1.18	3.92	0.00	0.00	0.00
Commercial	High Efficiency PTAC	Miscellaneous	Turnover	T_MS_High	3.80	1.03	4.02	0.00	0.00	0.00
Commercial	High Efficiency PTAC	Warehouse	Turnover	T_WR_High	2.02	0.96	2.31	0.00	0.00	0.00
Commercial	High Efficiency PTAC	Grocery	New	N_GR_High	4.32	1.18	3.99	0.00	0.00	0.00
Commercial	High Efficiency PTAC	Institutional	New	N_IN_High I	4.23	1.18	3.92	0.00	0.00	0.00
Commercial	High Efficiency PTAC	Miscellaneous	New	N_MS_High	3.80	1.03	4.02	0.00	0.00	0.00

Residential	Central Heating - 50% cycling	Multi Family	Existing		1.00	1.00	N/A	0.00	0.00	0.00	
Residential	Central Heating - 50% cycling	Mobile Home/Other	Existing		1.04	1.04	N/A	0.00	0.00	0.00	
Residential	Water heater switches	Single Family	Existing		1.00	1.00	N/A	0.00	0.00	0.00	
Residential	Water heater switches	Multi Family	Existing		1.00	1.00	N/A	0.00	0.00	0.00	
Residential	Water heater switches	Mobile Home/Other	Existing		1.00	1.00	N/A	0.00	0.00	0.00	
Residential	Pool pump switches	Single Family	Existing		1.00	1.00	N/A	11.69	7.54	0.00	
Residential	Pool pump switches	Multi Family	Existing		1.00	1.00	N/A	0.00	0.00	0.00	
Residential	Pool pump switches	Mobile Home/Other	Existing		1.00	1.00	N/A	0.00	0.00	0.00	
Residential	Room AC control	Single Family	New		1.00	1.00	N/A	0.92	1.05	0.00	
Residential	Room AC control	Mobile Home/Other	New		1.00	1.00	N/A	3.62	3.97	0.00	
Residential	Smart thermostats - BYOT	Single Family	New		1.10	1.10	N/A	0.00	0.00	0.00	
Residential	Smart thermostats - BYOT	Multi Family	New		1.00	1.00	N/A	0.00	0.00	0.00	
Residential	Smart thermostats - BYOT	Mobile Home/Other	New		1.11	1.11	N/A	0.00	0.00	0.00	
Small C&I	Central air conditioner - Load Shed	0-15,000 kWh	New		1.00	1.00	N/A	1.13	0.00	0.00	
Small C&I	Central air conditioner - Load Shed	15,001-25,000 kWh	New		1.00	1.00	N/A	0.63	0.00	0.00	
Small C&I	Central air conditioner - Load Shed	25,001-50,000 kWh	New		1.00	1.00	N/A	0.30	0.00	0.00	
Small C&I	Central air conditioner - Load Shed	50,001 kWh +	New		1.00	1.00	N/A	1.29	0.00	0.00	
Small C&I	Central Heating - Load Shed	0-15,000 kWh	New		1.00	1.00	N/A	0.00	6.06	0.00	
Small C&I	Central Heating - Load Shed	15,001-25,000 kWh	New		1.00	1.00	N/A	0.00	1.26	0.00	
Small C&I	Central Heating - Load Shed	25,001-50,000 kWh	New		1.00	1.00	N/A	0.00	0.60	0.00	
Small C&I	Central Heating - Load Shed	50,001 kWh +	New		1.00	1.00	N/A	0.00	0.29	0.00	
Small C&I	Central air conditioner - 50% cycling	0-15,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00	
Small C&I	Central air conditioner - 50% cycling	15,001-25,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00	
Small C&I	Central air conditioner - 50% cycling	25,001-50,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00	
Small C&I	Central air conditioner - 50% cycling	50,001 kWh +	New		1.00	1.00	N/A	0.00	0.00	0.00	
Small C&I	Central Heating - 50% cycling	0-15,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00	
Small C&I	Central Heating - 50% cycling	15,001-25,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00	
Small C&I	Central Heating - 50% cycling	25,001-50,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00	
Small C&I	Central Heating - 50% cycling	50,001 kWh +	New		1.00	1.00	N/A	0.00	0.00	0.00	
Small C&I	Smart thermostats - BYOT	0-15,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00	
Small C&I	Smart thermostats - BYOT	15,001-25,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00	
Small C&I	Smart thermostats - BYOT	25,001-50,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00	
Small C&I	Smart thermostats - BYOT	50,001 kWh +	New		1.00	1.00	N/A	0.00	0.00	0.00	
Large C&I	Auto DR	0-50 kW	New		2.13	2.13	N/A	29.40	24.72	0.00	
Large C&I	Auto DR	51-300 kW	New		2.13	2.13	N/A	41.54	31.97	0.00	
Large C&I	Auto DR	301-500 kW	New		2.13	2.13	N/A	44.44	35.76	0.00	
Large C&I	Auto DR	501 kW +	Existing		2.15	2.15	N/A	0.00	0.00	0.00	
Large C&I	CPP	0-50 kW	New		1.13	1.13	N/A	0.00	0.00	0.00	
Large C&I	CPP	51-300 kW	New		1.30	1.30	N/A	0.00	0.00	0.00	
Large C&I	CPP	301-500 kW	New		1.00	1.00	N/A	0.00	0.00	0.00	
Large C&I	CPP	501 kW +	New		1.40	1.40	N/A	0.00	0.00	0.00	
Large C&I	Firm Service Level	0-50 kW	New		2.35	2.35	N/A	0.00	0.00	0.00	
Large C&I	Firm Service Level	51-300 kW	New		2.35	2.35	N/A	0.00	0.00	0.00	
Large C&I	Firm Service Level	301-500 kW	New		2.35	2.35	N/A	0.00	0.00	0.00	
Large C&I	Firm Service Level	501 kW +	Existing		2.37	2.37	N/A	0.00	0.00	0.00	
Large C&I	Guaranteed Load Drop	0-50 kW	New		2.35	2.35	N/A	0.00	0.00	0.00	
Large C&I	Guaranteed Load Drop	51-300 kW	New		2.35	2.35	N/A	0.00	0.00	0.00	
Large C&I	Guaranteed Load Drop	301-500 kW	New		2.35	2.35	N/A	0.00	0.00	0.00	
Large C&I	Guaranteed Load Drop	501 kW +	Existing		2.37	2.37	N/A	0.00	0.00	0.00	

Commercial	High Efficiency PTAC	Warehouse	New	N_WR_High	2.02	0.90	2.31	0.00	0.00	0.00	
Commercial	High Efficiency PTHP	Grocery	Turnover	T_GR_High	4.42	1.18	4.12	0.00	0.00	0.01	
Commercial	High Efficiency PTHP	Institutional	Turnover	T_IN_High	4.26	1.16	3.99	0.00	0.00	0.01	
Commercial	High Efficiency PTHP	Miscellaneous	Turnover	T_MS_High	4.35	1.17	4.07	0.02	0.00	0.04	
Commercial	High Efficiency PTHP	Warehouse	Turnover	T_WR_High	2.06	0.90	2.36	0.00	0.00	0.01	
Commercial	High Efficiency PTHP	Grocery	New	N_GR_High	4.42	1.18	4.12	0.00	0.00	0.00	
Commercial	High Efficiency PTHP	Institutional	New	N_IN_High	4.26	1.16	3.99	0.00	0.00	0.00	
Commercial	High Efficiency PTHP	Miscellaneous	New	N_MS_High	4.35	1.17	4.07	0.01	0.00	0.01	
Commercial	High Efficiency PTHP	Warehouse	New	N_WR_High	2.06	0.90	2.36	0.00	0.00	0.00	
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Healthcare	Turnover	T_HC_Varia	1.62	0.64	2.62	0.03	0.00	0.10	
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Hospitals	Turnover	T_HS_Varia	1.55	0.63	2.55	0.00	0.00	0.02	
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Lodging/Hospitality	Turnover	T_LG_Varia	1.03	0.48	2.23	0.00	0.02	0.12	
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Restaurants	Turnover	T_RS_Varia	1.32	0.59	2.31	0.00	0.03	0.12	
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Retail	Turnover	T_RT_Varia	1.03	0.52	2.00	0.00	0.03	0.10	
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Healthcare	New	N_HC_Varia	1.62	0.64	2.62	0.01	0.00	0.02	
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Hospitals	New	N_HS_Varia	1.55	0.63	2.55	0.00	0.00	0.01	
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Lodging/Hospitality	New	N_LG_Varia	1.03	0.48	2.23	0.00	0.00	0.03	
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Restaurants	New	N_RS_Varia	1.32	0.59	2.31	0.00	0.01	0.03	
Commercial	Variable Refrigerant Flow (VRF) HVAC Systems	Retail	New	N_RT_Varia	1.03	0.52	2.00	0.00	0.01	0.03	
Commercial	High Bay Fluorescent (T5)	Schools K-12	Turnover	T_SC_High	3.02	0.64	5.38	0.00	0.00	0.00	
Commercial	High Bay Fluorescent (T5)	Schools K-12	New	N_SC_High	3.02	0.64	5.38	0.00	0.00	0.00	
Commercial	High Bay LED	Assembly	Turnover	T_AS_High	2.55	0.62	4.59	0.06	0.06	0.31	
Commercial	High Bay LED	Institutional	Turnover	T_IN_High	2.87	0.64	5.12	0.00	0.00	0.00	
Commercial	High Bay LED	Lodging/Hospitality	Turnover	T_LG_High	3.19	0.65	5.69	0.00	0.00	0.00	
Commercial	High Bay LED	Offices	Turnover	T_OF_High	2.83	0.63	5.06	0.00	0.00	0.00	
Commercial	High Bay LED	Restaurants	Turnover	T_RS_High	2.91	0.64	5.19	0.00	0.00	0.00	
Commercial	High Bay LED	Schools K-12	Turnover	T_SC_High	2.16	0.59	3.97	0.00	0.00	0.00	
Commercial	High Bay LED	Warehouse	Turnover	T_WR_High	3.24	0.65	5.78	0.23	0.23	1.25	
Commercial	High Bay LED	Assembly	New	N_AS_High	2.55	0.62	4.59	0.00	0.00	0.00	
Commercial	High Bay LED	Institutional	New	N_IN_High	2.87	0.64	5.12	0.00	0.00	0.00	
Commercial	High Bay LED	Lodging/Hospitality	New	N_LG_High	3.19	0.65	5.69	0.00	0.00	0.00	
Commercial	High Bay LED	Offices	New	N_OF_High	2.83	0.63	5.06	0.00	0.00	0.00	
Commercial	High Bay LED	Restaurants	New	N_RS_High	2.91	0.64	5.19	0.00	0.00	0.00	
Commercial	High Bay LED	Schools K-12	New	N_SC_High	2.16	0.59	3.97	0.00	0.00	0.00	
Commercial	High Bay LED	Warehouse	New	N_WR_High	3.24	0.65	5.78	0.00	0.00	0.00	
Commercial	Premium T8 - Fixture Replacement	Grocery	Turnover	T_GR_Premi	1.10	0.50	2.35	0.02	0.00	0.06	
Commercial	Premium T8 - Fixture Replacement	Healthcare	Turnover	T_HC_Premi	1.01	0.48	2.22	0.01	0.00	0.05	
Commercial	Premium T8 - Fixture Replacement	Retail	Turnover	T_RT_Premi	1.00	0.48	2.21	0.00	0.00	0.00	
Commercial	Premium T8 - Fixture Replacement	Grocery	New	N_GR_Premi	1.10	0.50	2.35	0.00	0.00	0.00	
Commercial	Premium T8 - Fixture Replacement	Healthcare	New	N_HC_Premi	1.01	0.48	2.22	0.00	0.00	0.00	
Commercial	Premium T8 - Fixture Replacement	Retail	New	N_RT_Premi	1.00	0.48	2.21	0.00	0.00	0.00	
Commercial	Efficient Battery Charger	Assembly	Turnover	T_AS_Effici	1.47	0.75	2.07	0.27	0.00	0.50	
Commercial	Efficient Battery Charger	College and University	Turnover	T_CU_Effici	1.47	0.75	2.07	0.00	0.00	0.00	
Commercial	Efficient Battery Charger	Grocery	Turnover	T_GR_Effici	1.47	0.75	2.07	0.37	0.00	0.68	
Commercial	Efficient Battery Charger	Healthcare	Turnover	T_HC_Effici	1.47	0.75	2.07	0.38	0.00	0.68	
Commercial	Efficient Battery Charger	Hospitals	Turnover	T_HS_Effici	1.47	0.75	2.07	0.49	0.00	0.89	
Commercial	Efficient Battery Charger	Institutional	Turnover	T_IN_Effici	1.47	0.75	2.07	0.38	0.00	0.70	
Commercial	Efficient Battery Charger	Lodging/Hospitality	Turnover	T_LG_Effici	1.47	0.75	2.07	0.87	0.00	1.59	
Commercial	Efficient Battery Charger	Miscellaneous	Turnover	T_MS_Effici	1.47	0.75	2.07	0.00	0.00	0.00	
Commercial	Efficient Battery Charger	Offices	Turnover	T_OF_Effici	1.47	0.75	2.07	2.22	0.00	4.05	
Commercial	Efficient Battery Charger	Restaurants	Turnover	T_RS_Effici	1.47	0.75	2.07	0.00	0.00	0.00	
Commercial	Efficient Battery Charger	Retail	Turnover	T_RT_Effici	1.47	0.75	2.07	1.21	0.00	2.21	
Commercial	Efficient Battery Charger	Schools K-12	Turnover	T_SC_Effici	1.47	0.75	2.07	0.00	0.00	0.00	
Commercial	Efficient Battery Charger	Warehouse	Turnover	T_WR_Effici	1.47	0.75	2.07	0.41	0.00	0.75	
Commercial	Efficient Battery Charger	Assembly	New	N_AS_Effici	1.47	0.75	2.07	0.03	0.00	0.06	
Commercial	Efficient Battery Charger	College and University	New	N_CU_Effici	1.47	0.75	2.07	0.00	0.00	0.00	
Commercial	Efficient Battery Charger	Grocery	New	N_GR_Effici	1.47	0.75	2.07	0.04	0.00	0.08	
Commercial	Efficient Battery Charger	Healthcare	New	N_HC_Effici	1.47	0.75	2.07	0.04	0.00	0.08	
Commercial	Efficient Battery Charger	Hospitals	New	N_HS_Effici	1.47	0.75	2.07	0.06	0.00	0.10	
Commercial	Efficient Battery Charger	Institutional	New	N_IN_Effici	1.47	0.75	2.07	0.04	0.00	0.08	
Commercial	Efficient Battery Charger	Lodging/Hospitality	New	N_LG_Effici	1.47	0.75	2.07	0.10	0.00	0.18	
Commercial	Efficient Battery Charger	Miscellaneous	New	N_MS_Effici	1.47	0.75	2.07	0.00	0.00	0.00	
Commercial	Efficient Battery Charger	Offices	New	N_OF_Effici	1.47	0.75	2.07	0.25	0.00	0.46	
Commercial	Efficient Battery Charger	Restaurants	New	N_RS_Effici	1.47	0.75	2.07	0.00	0.00	0.00	
Commercial	Efficient Battery Charger	Retail	New	N_RT_Effici	1.47	0.75	2.07	0.14	0.00	0.25	
Commercial	Efficient Battery Charger	Schools K-12	New	N_SC_Effici	1.47	0.75	2.07	0.00	0.00	0.00	
Commercial	Efficient Battery Charger	Warehouse	New	N_WR_Effici	1.47	0.75	2.07	0.05	0.00	0.08	
Commercial	Variable Speed Pool Pump	Assembly	Turnover	T_AS_Varia	1.48	0.57	2.79	0.00	0.00	0.01	
Commercial	Variable Speed Pool Pump	College and University	Turnover	T_CU_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Grocery	Turnover	T_GR_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Healthcare	Turnover	T_HC_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Hospitals	Turnover	T_HS_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Institutional	Turnover	T_IN_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Lodging/Hospitality	Turnover	T_LG_Varia	1.48	0.57	2.79	0.16	0.03	0.69	
Commercial	Variable Speed Pool Pump	Miscellaneous	Turnover	T_MS_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Offices	Turnover	T_OF_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Restaurants	Turnover	T_RS_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Retail	Turnover	T_RT_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Schools K-12	Turnover	T_SC_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Assembly	New	N_AS_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	College and University	New	N_CU_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Grocery	New	N_GR_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Healthcare	New	N_HC_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Hospitals	New	N_HS_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Institutional	New	N_IN_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Lodging/Hospitality	New	N_LG_Varia	1.48	0.57	2.79	0.02	0.00	0.08	
Commercial	Variable Speed Pool Pump	Miscellaneous	New	N_MS_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Offices	New	N_OF_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Restaurants	New	N_RS_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Retail	New	N_RT_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Variable Speed Pool Pump	Schools K-12	New	N_SC_Varia	1.48	0.57	2.79	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Assembly	Turnover	T_AS_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	College and University	Turnover	T_CU_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Grocery	Turnover	T_GR_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Healthcare	Turnover	T_HC_Energ	1.16	0.41	3.08	0.00	0.00	0.01	
Commercial	Energy Star Uninterruptable Power Supply	Hospitals	Turnover	T_HS_Energ	1.16	0.41	3.08	0.00	0.00	0.02	
Commercial	Energy Star Uninterruptable Power Supply	Institutional	Turnover	T_IN_Energ	1.16	0.41	3.08	0.00	0.00	0.01	
Commercial	Energy Star Uninterruptable Power Supply	Lodging/Hospitality	Turnover	T_LG_Energ	1.16	0.41	3.08	0.01	0.01	0.11	
Commercial	Energy Star Uninterruptable Power Supply	Miscellaneous	Turnover	T_MS_Energ	1.16	0.41	3.08	0.00	0.00	0.01	
Commercial	Energy Star Uninterruptable Power Supply	Offices	Turnover	T_OF_Energ	1.16	0.41	3.08	0.01	0.01	0.07	
Commercial	Energy Star Uninterruptable Power Supply	Restaurants	Turnover	T_RS_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Retail	Turnover	T_RT_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Schools K-12	Turnover	T_SC_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Warehouse	Turnover	T_WR_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Assembly	New	N_AS_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	College and University	New	N_CU_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Grocery	New	N_GR_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Healthcare	New	N_HC_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Hospitals	New	N_HS_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Institutional	New	N_IN_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Lodging/Hospitality	New	N_LG_Energ	1.16	0.41	3.08	0.00	0.00	0.02	
Commercial	Energy Star Uninterruptable Power Supply	Miscellaneous	New	N_MS_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Offices	New	N_OF_Energ	1.16	0.41	3.08	0.00	0.00	0.01	
Commercial	Energy Star Uninterruptable Power Supply	Restaurants	New	N_RS_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Retail	New	N_RT_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Schools K-12	New	N_SC_Energ	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Uninterruptable Power Supply	Warehouse	New	N_WR_Ener	1.16	0.41	3.08	0.00	0.00	0.00	
Commercial	Energy Star Commercial Solid Door Refrigerator	Assembly	Turnover	T_AS_Energ	2.31	0.55	4.81	0.00	0.00	0.00	
Commercial	Energy Star Commercial Solid Door Refrigerator	College and University	Turnover	T_CU_Energ	2.16	0.52	4.81	0.00	0.00	0.00	
Commercial	Energy Star Commercial Solid Door Refrigerator	Grocery	Turnover	T_GR_Energ	2.31	0.55	4.81	0.09	0.04	0.60	
Commercial	Energy Star Commercial Solid Door Refrigerator	Healthcare	Turnover	T_HC_Energ	2.16	0.52	4.81	0.00	0.00	0.00	
Commercial	Energy Star Commercial Solid Door Refrigerator	Hospitals	Turnover	T_HS_Energ	2.16	0.52	4.81	0.00	0.00	0.00	
Commercial	Energy Star Commercial Solid Door Refrigerator	Institutional	Turnover	T_IN_Energ	2.31	0.55	4.81	0.00	0.00	0.00	
Commercial	Energy Star Commercial Solid Door Refrigerator	Lodging/Hospitality	Turnover	T_LG_Energ	2.16	0.52	4.81	0.00	0.00	0.00	
Commercial	Energy Star Commercial Solid Door Refrigerator	Miscellaneous	Turnover	T_MS_Energ	2.31	0.55	4.81	0.00	0.00	0.00	

Commercial	Energy Star Commercial Solid Door Refrigerator	Offices	Turnover	T_OF_Energ	2.31	0.55	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Restaurants	Turnover	T_RS_Energ	2.16	0.52	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Retail	Turnover	T_RT_Energ	2.31	0.55	4.81	0.00	0.00	0.03
Commercial	Energy Star Commercial Solid Door Refrigerator	Schools K-12	Turnover	T_SC_Energ	2.16	0.52	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Warehouse	Turnover	T_WR_Energ	2.31	0.55	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Assembly	New	N_AS_Energ	2.31	0.55	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	College and University	New	N_CU_Energ	2.16	0.52	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Grocery	New	N_GR_Energ	2.31	0.55	4.81	0.02	0.01	0.10
Commercial	Energy Star Commercial Solid Door Refrigerator	Healthcare	New	N_HC_Energ	2.16	0.52	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Hospitals	New	N_HS_Energ	2.16	0.52	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Institutional	New	N_IN_Energ	2.31	0.55	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Lodging/Hospitality	New	N_LG_Energ	2.16	0.52	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Miscellaneous	New	N_MS_Energ	2.31	0.55	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Offices	New	N_OF_Energ	2.31	0.55	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Restaurants	New	N_RS_Energ	2.16	0.52	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Retail	New	N_RT_Energ	2.31	0.55	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Schools K-12	New	N_SC_Energ	2.16	0.52	4.81	0.00	0.00	0.00
Commercial	Energy Star Commercial Solid Door Refrigerator	Warehouse	New	N_WR_Energ	2.31	0.55	4.81	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Assembly	Existing	E_AS_Ceiling	4.21	1.06	4.33	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	College and University	Existing	E_CU_Ceiling	4.18	1.05	4.33	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Grocery	Existing	E_GR_Ceiling	4.32	1.08	4.33	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Healthcare	Existing	E_HC_Ceiling	4.21	1.06	4.33	0.04	0.01	2.19
Commercial	Ceiling Insulation(R2 to R30)	Hospitals	Existing	E_HS_Ceiling	4.18	1.05	4.33	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Institutional	Existing	E_IN_Ceiling	4.21	1.06	4.33	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Lodging/Hospitality	Existing	E_LG_Ceiling	4.18	1.05	4.33	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Miscellaneous	Existing	E_MS_Ceiling	4.21	1.06	4.33	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Offices	Existing	E_OF_Ceiling	4.21	1.06	4.33	0.03	0.00	1.55
Commercial	Ceiling Insulation(R2 to R30)	Restaurants	Existing	E_RS_Ceiling	4.32	1.08	4.33	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Retail	Existing	E_RT_Ceiling	4.32	1.08	4.33	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Schools K-12	Existing	E_SC_Ceiling	4.23	1.06	4.33	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Warehouse	Existing	E_WR_Ceiling	1.86	0.57	3.44	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Assembly	New	N_AS_Ceiling	4.14	1.05	4.24	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	College and University	New	N_CU_Ceiling	4.11	1.05	4.24	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Grocery	New	N_GR_Ceiling	4.24	1.08	4.24	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Healthcare	New	N_HC_Ceiling	4.14	1.05	4.24	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Hospitals	New	N_HS_Ceiling	4.11	1.05	4.24	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Institutional	New	N_IN_Ceiling	4.14	1.05	4.24	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Lodging/Hospitality	New	N_LG_Ceiling	4.11	1.05	4.24	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Miscellaneous	New	N_MS_Ceiling	4.14	1.05	4.24	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Offices	New	N_OF_Ceiling	4.14	1.05	4.24	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Restaurants	New	N_RS_Ceiling	4.24	1.08	4.24	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Retail	New	N_RT_Ceiling	4.24	1.08	4.24	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Schools K-12	New	N_SC_Ceiling	4.14	1.05	4.24	0.00	0.00	0.00
Commercial	Ceiling Insulation(R2 to R30)	Warehouse	New	N_WR_Ceiling	1.86	0.57	3.44	0.00	0.00	0.00
Commercial	Chilled Water System - Variable Speed Drives	Assembly	Existing	E_AS_Chiller	2.05	0.49	4.80	0.29	0.01	2.68
Commercial	Chilled Water System - Variable Speed Drives	College and University	Existing	E_CU_Chiller	2.05	0.49	4.80	0.00	0.00	0.01
Commercial	Chilled Water System - Variable Speed Drives	Grocery	Existing	E_GR_Chiller	2.05	0.49	4.80	0.00	0.00	0.00
Commercial	Chilled Water System - Variable Speed Drives	Healthcare	Existing	E_HC_Chiller	2.05	0.49	4.80	0.00	0.00	0.00
Commercial	Chilled Water System - Variable Speed Drives	Hospitals	Existing	E_HS_Chiller	2.05	0.49	4.80	0.24	0.01	2.23
Commercial	Chilled Water System - Variable Speed Drives	Institutional	Existing	E_IN_Chiller	2.05	0.49	4.80	0.18	0.01	1.66
Commercial	Chilled Water System - Variable Speed Drives	Lodging/Hospitality	Existing	E_LG_Chiller	2.05	0.49	4.80	0.14	0.01	1.32
Commercial	Chilled Water System - Variable Speed Drives	Miscellaneous	Existing	E_MS_Chiller	2.05	0.49	4.80	0.20	0.01	1.87
Commercial	Chilled Water System - Variable Speed Drives	Offices	Existing	E_OF_Chiller	2.05	0.49	4.80	0.49	0.02	4.49
Commercial	Chilled Water System - Variable Speed Drives	Restaurants	Existing	E_RS_Chiller	2.05	0.49	4.80	0.03	0.00	0.31
Commercial	Chilled Water System - Variable Speed Drives	Retail	Existing	E_RT_Chiller	2.05	0.49	4.80	0.00	0.00	0.00
Commercial	Chilled Water System - Variable Speed Drives	Schools K-12	Existing	E_SC_Chiller	2.05	0.49	4.80	0.09	0.00	0.84
Commercial	Chilled Water System - Variable Speed Drives	Warehouse	Existing	E_WR_Chiller	2.05	0.49	4.80	0.00	0.00	0.00
Commercial	Chilled Water System - Variable Speed Drives	Assembly	New	N_AS_Chiller	2.05	0.49	4.80	0.05	0.00	0.46
Commercial	Chilled Water System - Variable Speed Drives	College and University	New	N_CU_Chiller	2.05	0.49	4.80	0.00	0.00	0.00
Commercial	Chilled Water System - Variable Speed Drives	Grocery	New	N_GR_Chiller	2.05	0.49	4.80	0.00	0.00	0.00
Commercial	Chilled Water System - Variable Speed Drives	Healthcare	New	N_HC_Chiller	2.05	0.49	4.80	0.00	0.00	0.00
Commercial	Chilled Water System - Variable Speed Drives	Hospitals	New	N_HS_Chiller	2.05	0.49	4.80	0.03	0.00	0.23
Commercial	Chilled Water System - Variable Speed Drives	Institutional	New	N_IN_Chiller	2.05	0.49	4.80	0.04	0.00	0.39
Commercial	Chilled Water System - Variable Speed Drives	Lodging/Hospitality	New	N_LG_Chiller	2.05	0.49	4.80	0.02	0.00	0.16
Commercial	Chilled Water System - Variable Speed Drives	Miscellaneous	New	N_MS_Chiller	2.05	0.49	4.80	0.05	0.00	0.44
Commercial	Chilled Water System - Variable Speed Drives	Offices	New	N_OF_Chiller	2.05	0.49	4.80	0.08	0.00	0.76
Commercial	Chilled Water System - Variable Speed Drives	Restaurants	New	N_RS_Chiller	2.05	0.49	4.80	0.00	0.00	0.04
Commercial	Chilled Water System - Variable Speed Drives	Retail	New	N_RT_Chiller	2.05	0.49	4.80	0.00	0.00	0.00
Commercial	Chilled Water System - Variable Speed Drives	Schools K-12	New	N_SC_Chiller	2.05	0.49	4.80	0.02	0.00	0.15
Commercial	Chilled Water System - Variable Speed Drives	Warehouse	New	N_WR_Chiller	2.05	0.49	4.80	0.00	0.00	0.00
Commercial	Dedicated Outdoor Air System on VRF unit	Healthcare	Existing	E_HC_Dedic	1.58	0.64	2.58	0.02	0.00	0.07
Commercial	Dedicated Outdoor Air System on VRF unit	Hospitals	Existing	E_HS_Dedic	1.51	0.63	2.51	0.00	0.00	0.01
Commercial	Dedicated Outdoor Air System on VRF unit	Lodging/Hospitality	Existing	E_LG_Dedic	1.01	0.47	2.20	0.00	0.01	0.06
Commercial	Dedicated Outdoor Air System on VRF unit	Restaurants	Existing	E_RS_Dedic	1.27	0.58	2.25	0.00	0.02	0.07
Commercial	Dedicated Outdoor Air System on VRF unit	Healthcare	New	N_HC_Dedic	1.58	0.64	2.58	0.00	0.00	0.01
Commercial	Dedicated Outdoor Air System on VRF unit	Hospitals	New	N_HS_Dedic	1.51	0.63	2.51	0.00	0.00	0.00
Commercial	Dedicated Outdoor Air System on VRF unit	Lodging/Hospitality	New	N_LG_Dedic	1.01	0.47	2.20	0.00	0.00	0.01
Commercial	Dedicated Outdoor Air System on VRF unit	Restaurants	New	N_RS_Dedic	1.27	0.58	2.25	0.00	0.00	0.01
Commercial	Duct Sealing Repair	Assembly	Existing	E_AS_Duct_S	4.47	1.37	3.50	0.00	0.00	0.00
Commercial	Duct Sealing Repair	College and University	Existing	E_CU_Duct_	6.45	1.51	4.79	0.00	0.00	0.00
Commercial	Duct Sealing Repair	Retail	Existing	E_RT_Duct_S	7.63	1.57	5.62	1.57	0.14	8.15
Commercial	Duct Sealing Repair	Schools K-12	Existing	E_SC_Duct_S	6.45	1.51	4.79	0.00	0.00	0.00
Commercial	Duct Sealing Repair	Warehouse	Existing	E_WR_Duct	2.29	1.06	2.22	0.00	0.00	0.00
Commercial	Duct Sealing Repair	Assembly	New	N_AS_Duct_	4.47	1.37	3.50	0.00	0.00	0.00
Commercial	Duct Sealing Repair	College and University	New	N_CU_Duct	6.45	1.51	4.79	0.00	0.00	0.00
Commercial	Duct Sealing Repair	Retail	New	N_RT_Duct_	7.63	1.57	5.62	0.00	0.00	0.00
Commercial	Duct Sealing Repair	Schools K-12	New	N_SC_Duct_	6.45	1.51	4.79	0.00	0.00	0.00
Commercial	Duct Sealing Repair	Warehouse	New	N_WR_Duct	2.29	1.06	2.22	0.00	0.00	0.00
Commercial	ECM Motors on Furnaces	College and University	Existing	E_CU_ECM	1.13	0.42	2.82	0.00	0.00	0.00
Commercial	ECM Motors on Furnaces	Grocery	Existing	E_GR_ECM	1.61	0.43	4.13	0.00	0.00	0.00
Commercial	ECM Motors on Furnaces	Hospitals	Existing	E_HS_ECM	1.92	0.50	4.24	0.00	0.00	0.00
Commercial	ECM Motors on Furnaces	Lodging/Hospitality	Existing	E_LG_ECM	1.03	0.37	2.92	0.00	0.00	0.00
Commercial	ECM Motors on Furnaces	Retail	Existing	E_RT_ECM	2.08	0.46	5.20	0.00	0.00	0.00
Commercial	ECM Motors on Furnaces	Schools K-12	Existing	E_SC_ECM	1.05	0.24	4.87	0.00	0.00	0.00
Commercial	ECM Motors on Furnaces	College and University	New	N_CU_ECM	1.13	0.42	2.82	0.00	0.00	0.00
Commercial	ECM Motors on Furnaces	Grocery	New	N_GR_ECM	1.61	0.43	4.13	0.00	0.00	0.00
Commercial	ECM Motors on Furnaces	Hospitals	New	N_HS_ECM	1.92	0.50	4.24	0.00	0.00	0.00
Commercial	ECM Motors on Furnaces	Lodging/Hospitality	New	N_LG_ECM	1.03	0.37	2.92	0.00	0.00	0.00
Commercial	ECM Motors on Furnaces	Retail	New	N_RT_ECM	2.08	0.46	5.20	0.00	0.00	0.00
Commercial	ECM Motors on Furnaces	Schools K-12	New	N_SC_ECM	1.05	0.24	4.87	0.00	0.00	0.00
Commercial	Facility Commissioning	Grocery	New	N_GR_Facil	1.35	0.53	2.72	0.01	0.00	0.35
Commercial	Facility Commissioning	Restaurants	New	N_RS_Facil	1.31	0.53	2.66	0.25	0.00	1.29
Commercial	Facility Energy Management System	College and University	Existing	E_CU_Facil	1.19	0.45	2.77	0.00	0.00	0.01
Commercial	Facility Energy Management System	Healthcare	Existing	E_HC_Facil	3.45	0.70	5.71	0.02	0.00	0.08
Commercial	Facility Energy Management System	Hospitals	Existing	E_HS_Facil	2.84	0.58	5.71	0.15	0.05	1.00
Commercial	Facility Energy Management System	Lodging/Hospitality	Existing	E_LG_Facil	2.41	0.71	3.66	0.05	0.01	0.18
Commercial	Facility Energy Management System	Miscellaneous	Existing	E_MS_Facil	2.76	0.67	4.62	0.71	0.05	3.42
Commercial	Facility Energy Management System	Offices	Existing	E_OF_Facil	3.54	0.70	5.86	0.31	0.02	1.52
Commercial	Facility Energy Management System	Retail	Existing	E_RT_Facil	2.00	0.67	3.16	0.91	0.27	3.53
Commercial	Facility Energy Management System	Schools K-12	Existing	E_SC_Facil	1.45	0.55	2.77	0.01	0.00	0.04
Commercial	Facility Energy Management System	College and University	New	N_CU_Facil	1.19	0.45	2.77	0.00	0.00	0.01
Commercial	Facility Energy Management System	Healthcare	New	N_HC_Facil	3.45	0.70	5.71	0.02	0.00	0.08
Commercial	Facility Energy Management System	Hospitals	New	N_HS_Facil	2.84	0.58	5.71	0.01	0.00	0.10
Commercial	Facility Energy Management System	Lodging/Hospitality	New	N_LG_Facil	2.41	0.71	3.66	0.03	0.01	0.13
Commercial	Facility Energy Management System	Miscellaneous	New	N_MS_Facil	2.76	0.67	4.62	0.09	0.01	0.41
Commercial	Facility Energy Management System	Offices	New	N_OF_Facil	3.54	0.70	5.86	0.03	0.00	0.12
Commercial	Facility Energy Management System	Retail	New	N_RT_Facil	2.00	0.67	3.16	0.11	0.03	0.43
Commercial	Facility Energy Management System	Schools K-12	New	N_SC_Facil	1.45	0.55	2.77	0.01	0.00	0.03

Commercial	HVAC tune-up	Assembly	Existing	E_AS_HVAC	1.08	0.66	1.70	0.00	0.00	0.00
Commercial	HVAC tune-up	Lodging/Hospitality	Existing	E_LG_HVAC	1.67	0.85	2.16	0.00	0.00	0.00
Commercial	HVAC tune-up	Offices	Existing	E_OF_HVAC	1.05	0.62	1.79	0.01	0.00	0.01
Commercial	HVAC tune-up	Restaurants	Existing	E_RS_HVAC	1.64	0.84	2.14	0.00	0.00	0.00
Commercial	HVAC tune-up	Retail	Existing	E_RT_HVAC	1.33	0.75	1.89	0.00	0.00	0.00
Commercial	HVAC tune-up	Schools K-12	Existing	E_SC_HVAC	1.18	0.70	1.77	0.00	0.00	0.00
Commercial	HVAC tune-up	Assembly	New	N_AS_HVAC	1.08	0.66	1.70	0.00	0.00	0.00
Commercial	HVAC tune-up	Lodging/Hospitality	New	N_LG_HVAC	1.67	0.85	2.16	0.00	0.00	0.00
Commercial	HVAC tune-up	Offices	New	N_OF_HVAC	1.05	0.62	1.79	0.00	0.00	0.01
Commercial	HVAC tune-up	Restaurants	New	N_RS_HVAC	1.64	0.84	2.14	0.00	0.00	0.00
Commercial	HVAC tune-up	Retail	New	N_RT_HVAC	1.33	0.75	1.89	0.00	0.00	0.00
Commercial	HVAC tune-up	Schools K-12	New	N_SC_HVAC	1.18	0.70	1.77	0.00	0.00	0.00
Commercial	HVAC tune-up_RTU	Healthcare	Existing	E_HC_HVAC	1.45	0.74	2.15	0.65	0.00	1.64
Commercial	HVAC tune-up_RTU	Hospitals	Existing	E_HS_HVAC	1.38	0.72	2.09	0.25	0.00	0.64
Commercial	HVAC tune-up_RTU	Lodging/Hospitality	Existing	E_LG_HVAC	1.14	0.65	1.87	0.36	0.00	0.90
Commercial	HVAC tune-up_RTU	Restaurants	Existing	E_RS_HVAC	1.12	0.64	1.85	1.16	0.00	2.92
Commercial	HVAC tune-up_RTU	Healthcare	New	N_HC_HVAC	1.45	0.74	2.15	0.16	0.00	0.39
Commercial	HVAC tune-up_RTU	Hospitals	New	N_HS_HVAC	1.38	0.72	2.09	0.06	0.00	0.15
Commercial	HVAC tune-up_RTU	Lodging/Hospitality	New	N_LG_HVAC	1.14	0.65	1.87	0.08	0.00	0.21
Commercial	HVAC tune-up_RTU	Restaurants	New	N_RS_HVAC	1.12	0.64	1.85	0.27	0.00	0.68
Commercial	Low U-Value Windows	Assembly	Existing	E_AS_Low U	1.41	0.68	2.13	0.06	0.00	0.17
Commercial	Low U-Value Windows	College and University	Existing	E_CU_Low U	1.41	0.68	2.13	0.00	0.00	0.01
Commercial	Low U-Value Windows	Grocery	Existing	E_GR_Low U	1.41	0.68	2.13	0.05	0.00	0.13
Commercial	Low U-Value Windows	Healthcare	Existing	E_HC_Low U	1.41	0.68	2.13	0.08	0.00	0.21
Commercial	Low U-Value Windows	Hospitals	Existing	E_HS_Low U	1.41	0.68	2.13	0.07	0.00	0.19
Commercial	Low U-Value Windows	Institutional	Existing	E_IN_Low U	1.41	0.68	2.13	0.04	0.00	0.10
Commercial	Low U-Value Windows	Lodging/Hospitality	Existing	E_LG_Low U	1.60	0.77	2.13	0.17	0.00	0.40
Commercial	Low U-Value Windows	Miscellaneous	Existing	E_MS_Low U	1.33	0.64	2.13	0.13	0.00	0.39
Commercial	Low U-Value Windows	Offices	Existing	E_OF_Low U	1.41	0.68	2.13	0.12	0.00	0.36
Commercial	Low U-Value Windows	Restaurants	Existing	E_RS_Low U	1.41	0.68	2.13	0.17	0.00	0.48
Commercial	Low U-Value Windows	Retail	Existing	E_RT_Low U	1.41	0.68	2.13	0.13	0.00	0.38
Commercial	Low U-Value Windows	Schools K-12	Existing	E_SC_Low U	1.41	0.68	2.13	0.02	0.00	0.07
Commercial	Low U-Value Windows	Warehouse	Existing	E_WR_Low	1.33	0.64	2.13	0.01	0.00	0.04
Commercial	Programmable Thermostat	Lodging/Hospitality	Existing	E_LG_Progr	6.56	3.41	1.98	0.00	0.00	0.00
Commercial	Programmable Thermostat	Restaurants	Existing	E_RS_Progr	3.52	0.93	4.32	0.68	0.00	1.98
Commercial	Programmable Thermostat	Lodging/Hospitality	New	N_LG_Progr	6.56	3.41	1.98	0.00	0.00	0.00
Commercial	Programmable Thermostat	Restaurants	New	N_RS_Progr	3.52	0.93	4.32	0.08	0.00	0.24
Commercial	Smart Thermostat	Hospitals	Existing	E_HS_Smart	1.47	0.41	4.06	0.26	0.00	3.14
Commercial	Smart Thermostat	Institutional	Existing	E_IN_Smart	1.09	0.29	4.35	0.02	0.00	1.62
Commercial	Smart Thermostat	Lodging/Hospitality	Existing	E_LG_Smart	11.17	4.34	2.73	-0.17	0.72	5.60
Commercial	Smart Thermostat	Offices	Existing	E_OF_Smart	1.03	0.28	4.13	0.09	-0.11	8.53
Commercial	Smart Thermostat	Retail	Existing	E_RT_Smart	1.53	0.69	2.29	2.86	0.00	7.92
Commercial	Smart Thermostat	Hospitals	New	N_HS_Smart	1.47	0.41	4.06	0.03	0.00	0.39
Commercial	Smart Thermostat	Institutional	New	N_IN_Smart	1.09	0.29	4.35	0.00	0.00	0.20
Commercial	Smart Thermostat	Lodging/Hospitality	New	N_LG_Smart	11.17	4.34	2.73	-0.02	0.09	0.69
Commercial	Smart Thermostat	Offices	New	N_OF_Smart	1.03	0.28	4.13	0.01	-0.01	1.04
Commercial	Smart Thermostat	Retail	New	N_RT_Smart	1.53	0.69	2.29	0.35	0.00	0.97
Commercial	Thermal Energy Storage	Assembly	Existing	E_AS_Ther	2.48	2.94	9999.00	1.78	0.52	-0.28
Commercial	Thermal Energy Storage	College and University	Existing	E_CU_Ther	2.48	2.94	9999.00	0.04	0.01	-0.01
Commercial	Thermal Energy Storage	Grocery	Existing	E_GR_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Healthcare	Existing	E_HC_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Hospitals	Existing	E_HS_Ther	2.48	2.94	9999.00	2.92	0.85	-0.46
Commercial	Thermal Energy Storage	Institutional	Existing	E_IN_Ther	2.48	2.94	9999.00	0.73	0.21	-0.12
Commercial	Thermal Energy Storage	Lodging/Hospitality	Existing	E_LG_Ther	2.48	2.94	9999.00	0.58	0.17	-0.09
Commercial	Thermal Energy Storage	Miscellaneous	Existing	E_MS_Ther	2.48	2.94	9999.00	1.22	0.35	-0.19
Commercial	Thermal Energy Storage	Offices	Existing	E_OF_Ther	2.48	2.94	9999.00	1.99	0.58	-0.32
Commercial	Thermal Energy Storage	Restaurants	Existing	E_RS_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Retail	Existing	E_RT_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Schools K-12	Existing	E_SC_Ther	2.48	2.94	9999.00	0.48	0.14	-0.08
Commercial	Thermal Energy Storage	Warehouse	Existing	E_WR_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Assembly	New	N_AS_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	College and University	New	N_CU_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Grocery	New	N_GR_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Healthcare	New	N_HC_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Hospitals	New	N_HS_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Institutional	New	N_IN_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Lodging/Hospitality	New	N_LG_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Miscellaneous	New	N_MS_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Offices	New	N_OF_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Restaurants	New	N_RS_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Retail	New	N_RT_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Schools K-12	New	N_SC_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Thermal Energy Storage	Warehouse	New	N_WR_Ther	2.48	2.94	9999.00	0.00	0.00	0.00
Commercial	Wall Insulation	Assembly	Existing	E_AS_Wall I	3.16	0.98	3.42	0.00	0.00	0.00
Commercial	Wall Insulation	College and University	Existing	E_CU_Wall I	3.06	0.96	3.35	0.00	0.00	0.00
Commercial	Wall Insulation	Grocery	Existing	E_GR_Wall I	3.20	1.00	3.39	0.00	0.00	0.00
Commercial	Wall Insulation	Healthcare	Existing	E_HC_Wall I	3.04	0.96	3.32	0.00	0.00	0.08
Commercial	Wall Insulation	Hospitals	Existing	E_HS_Wall I	3.10	0.97	3.39	0.00	0.00	0.00
Commercial	Wall Insulation	Institutional	Existing	E_IN_Wall I	3.08	0.97	3.35	0.00	0.00	0.00
Commercial	Wall Insulation	Lodging/Hospitality	Existing	E_LG_Wall I	3.06	0.96	3.35	0.00	0.00	0.00
Commercial	Wall Insulation	Miscellaneous	Existing	E_MS_Wall I	3.12	0.97	3.39	0.00	0.00	0.00
Commercial	Wall Insulation	Offices	Existing	E_OF_Wall I	3.12	0.97	3.39	0.01	0.00	0.56
Commercial	Wall Insulation	Restaurants	Existing	E_RS_Wall I	3.25	1.00	3.42	0.00	0.00	0.00
Commercial	Wall Insulation	Retail	Existing	E_RT_Wall I	3.20	1.00	3.39	0.07	0.00	0.36
Commercial	Wall Insulation	Schools K-12	Existing	E_SC_Wall I	3.21	0.98	3.46	0.00	0.00	0.00
Commercial	Wall Insulation	Warehouse	Existing	E_WR_Wall	1.85	0.57	3.42	0.00	0.00	0.00
Commercial	VSD Controlled Compressor	Assembly	Existing	E_AS_VSD I	1.97	0.53	4.04	0.04	0.02	0.20
Commercial	VSD Controlled Compressor	College and University	Existing	E_CU_VSD I	1.82	0.49	4.04	0.03	0.01	0.08
Commercial	VSD Controlled Compressor	Grocery	Existing	E_GR_VSD I	1.97	0.53	4.04	0.25	0.12	1.67
Commercial	VSD Controlled Compressor	Healthcare	Existing	E_HC_VSD I	1.82	0.49	4.04	0.07	0.06	0.53
Commercial	VSD Controlled Compressor	Hospitals	Existing	E_HS_VSD I	1.82	0.49	4.04	0.07	0.06	0.52
Commercial	VSD Controlled Compressor	Institutional	Existing	E_IN_VSD I	1.97	0.53	4.04	0.06	0.03	0.41
Commercial	VSD Controlled Compressor	Lodging/Hospitality	Existing	E_LG_VSD I	1.82	0.49	4.04	0.16	0.13	1.23
Commercial	VSD Controlled Compressor	Miscellaneous	Existing	E_MS_VSD	1.97	0.53	4.04	2.63	1.23	17.45
Commercial	VSD Controlled Compressor	Offices	Existing	E_OF_VSD I	1.97	0.53	4.04	0.36	0.17	2.36
Commercial	VSD Controlled Compressor	Restaurants	Existing	E_RS_VSD I	1.82	0.49	4.04	0.09	0.07	0.67
Commercial	VSD Controlled Compressor	Retail	Existing	E_RT_VSD I	1.97	0.53	4.04	0.26	0.12	1.72
Commercial	VSD Controlled Compressor	Schools K-12	Existing	E_SC_VSD I	1.82	0.49	4.04	0.02	0.02	0.16
Commercial	VSD Controlled Compressor	Warehouse	Existing	E_WR_VSD	1.97	0.53	4.04	0.09	0.04	0.58
Commercial	VSD Controlled Compressor	Assembly	New	N_AS_VSD I	1.97	0.53	4.04	0.03	0.02	0.22
Commercial	VSD Controlled Compressor	College and University	New	N_CU_VSD	1.82	0.49	4.04	0.01	0.01	0.06
Commercial	VSD Controlled Compressor	Grocery	New	N_GR_VSD	1.97	0.53	4.04	0.04	0.02	0.25
Commercial	VSD Controlled Compressor	Healthcare	New	N_HC_VSD	1.82	0.49	4.04	0.05	0.04	0.40
Commercial	VSD Controlled Compressor	Hospitals	New	N_HS_VSD	1.82	0.49	4.04	0.05	0.04	0.39
Commercial	VSD Controlled Compressor	Institutional	New	N_IN_VSD I	1.97	0.53	4.04	0.05	0.02	0.31
Commercial	VSD Controlled Compressor	Lodging/Hospitality	New	N_LG_VSD I	1.82	0.49	4.04	0.12	0.10	0.93
Commercial	VSD Controlled Compressor	Miscellaneous	New	N_MS_VSD	1.97	0.53	4.04	0.40	0.18	2.62
Commercial	VSD Controlled Compressor	Offices	New	N_OF_VSD I	1.97	0.53	4.04	0.27	0.13	1.77
Commercial	VSD Controlled Compressor	Restaurants	New	N_RS_VSD I	1.82	0.49	4.04	0.07	0.05	0.50
Commercial	VSD Controlled Compressor	Retail	New	N_RT_VSD	1.97	0.53	4.04	0.19	0.09	1.29
Commercial	VSD Controlled Compressor	Schools K-12	New	N_SC_VSD I	1.82	0.49	4.04	0.02	0.01	0.12
Commercial	VSD Controlled Compressor	Warehouse	New	N_WR_VSD	1.97	0.53	4.04	0.07	0.03	0.44
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Assembly	Existing	E_AS_PSC n	1.65	0.49	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	College and University	Existing	E_CU_PSC n	1.60	0.48	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Grocery	Existing	E_GR_PSC n	1.65	0.49	3.62	1.05	0.10	7.54
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Healthcare	Existing	E_HC_PSC n	1.60	0.48	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Hospitals	Existing	E_HS_PSC n	1.60	0.48	3.62	0.01	0.00	0.04
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Institutional	Existing	E_IN_PSC n	1.65	0.49	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Lodging/Hospitality	Existing	E_LG_PSC n	1.60	0.48	3.62	0.03	0.02	0.20
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Miscellaneous	Existing	E_MS_PSC n	1.65	0.49	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Offices	Existing	E_OF_PSC n	1.65	0.49	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Restaurants	Existing	E_RS_PSC n	1.60	0.48	3.62	0.27	0.22	2.06
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Retail	Existing	E_RT_PSC n	1.65	0.49	3.62	0.04	0.00	0.32
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Schools K-12	Existing	E_SC_PSC n	1.60	0.48	3.62	0.00	0.00	0.01
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Warehouse	Existing	E_WR_PSC	1.65	0.49	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Assembly	New	N_AS_PSC n	1.65	0.49	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	College and University	New	N_CU_PSC	1.60	0.48	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Grocery	New	N_GR_PSC n	1.65	0.49	3.62	0.59	0.05	4.22
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Healthcare	New	N_HC_PSC	1.60	0.48	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Hospitals	New	N_HS_PSC n	1.60	0.48	3.62	0.00	0.00	0.02
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Institutional	New	N_IN_PSC n	1.65	0.49	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Lodging/Hospitality	New	N_LG_PSC n	1.60	0.48	3.62	0.01	0.01	0.11
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Miscellaneous	New	N_MS_PSC n	1.65	0.49	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Offices	New	N_OF_PSC n	1.65	0.49	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Restaurants	New	N_RS_PSC n	1.60	0.48	3.62	0.15	0.13	1.16
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Retail	New	N_RT_PSC n	1.65	0.49	3.62	0.02	0.00	0.18
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Schools K-12	New	N_SC_PSC n	1.60	0.48	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Reach-In)	Warehouse	New	N_WR_PSC	1.65	0.49	3.62	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Assembly	Existing	E_AS_PSC n	1.11	0.43	2.70	0.00	0.00	0.01
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	College and University	Existing	E_CU_PSC n	1.07	0.42	2.70	0.00	0.00	0.00

Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Grocery	Existing	E_GR_PSC_	1.11	0.43	2.70	0.40	0.04	2.89
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Healthcare	Existing	E_HC_PSC_	1.07	0.42	2.70	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Hospitals	Existing	E_HS_PSC_	1.07	0.42	2.70	0.01	0.01	0.05
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Institutional	Existing	E_IN_PSC_	1.11	0.43	2.70	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Lodging/Hospitality	Existing	E_LG_PSC_	1.07	0.42	2.70	0.02	0.02	0.17
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Miscellaneous	Existing	E_MS_PSC_	1.11	0.43	2.70	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Offices	Existing	E_OF_PSC_	1.11	0.43	2.70	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Restaurants	Existing	E_RS_PSC_	1.07	0.42	2.70	0.27	0.23	2.11
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Retail	Existing	E_RT_PSC_	1.11	0.43	2.70	0.02	0.00	0.17
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Schools K-12	Existing	E_SC_PSC_	1.07	0.42	2.70	0.00	0.00	0.01
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Warehouse	Existing	E_WR_PSC	1.11	0.43	2.70	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Assembly	New	N_AS_PSC_	1.11	0.43	2.70	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	College and University	New	N_CU_PSC_	1.07	0.42	2.70	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Grocery	New	N_GR_PSC_	1.11	0.43	2.70	0.23	0.02	1.62
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Healthcare	New	N_HC_PSC_	1.07	0.42	2.70	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Hospitals	New	N_HS_PSC_	1.07	0.42	2.70	0.00	0.00	0.03
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Institutional	New	N_IN_PSC_	1.11	0.43	2.70	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Lodging/Hospitality	New	N_LG_PSC_	1.07	0.42	2.70	0.01	0.01	0.09
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Miscellaneous	New	N_MS_PSC_	1.11	0.43	2.70	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Offices	New	N_OF_PSC_	1.11	0.43	2.70	0.00	0.00	0.00
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Restaurants	New	N_RS_PSC_	1.07	0.42	2.70	0.15	0.13	1.18
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Retail	New	N_RT_PSC_	1.11	0.43	2.70	0.01	0.00	0.09
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Schools K-12	New	N_SC_PSC_	1.07	0.42	2.70	0.00	0.00	0.01
Commercial	PSC to ECM Evaporator Fan Motor (Walk-In, Refrigerator)	Warehouse	New	N_WR_PSC	1.11	0.43	2.70	0.00	0.00	0.00
Commercial	Demand Controlled Ventilation	Assembly	Existing	E_AS_Dema	2.75	1.03	2.87	0.07	0.40	0.68
Commercial	Demand Controlled Ventilation	Grocery	Existing	E_GR_Dema	1.33	0.74	1.85	0.07	0.38	0.65
Commercial	Demand Controlled Ventilation	Lodging/Hospitality	Existing	E_LG_Dema	4.20	1.18	4.05	0.58	2.81	4.79
Commercial	Demand Controlled Ventilation	Miscellaneous	Existing	E_MS_Dema	3.87	1.15	3.77	0.04	0.20	0.35
Commercial	Demand Controlled Ventilation	Offices	Existing	E_OF_Dema	4.62	1.17	3.90	0.77	4.34	7.41
Commercial	Demand Controlled Ventilation	Restaurants	Existing	E_RS_Dema	1.43	0.76	1.92	0.15	0.84	1.44
Commercial	Demand Controlled Ventilation	Retail	Existing	E_RT_Dema	2.98	1.06	3.05	0.85	4.80	8.18
Commercial	Demand Controlled Ventilation	Warehouse	Existing	E_WR_Dem	1.20	0.69	1.76	0.08	0.44	0.75
Commercial	Demand Controlled Ventilation	Assembly	New	N_AS_Dema	2.75	1.03	2.87	0.01	0.05	0.09
Commercial	Demand Controlled Ventilation	Grocery	New	N_GR_Dema	1.33	0.74	1.85	0.01	0.05	0.09
Commercial	Demand Controlled Ventilation	Lodging/Hospitality	New	N_LG_Dema	4.20	1.18	4.05	0.07	0.40	0.68
Commercial	Demand Controlled Ventilation	Miscellaneous	New	N_MS_Dema	3.87	1.15	3.77	0.01	0.03	0.05
Commercial	Demand Controlled Ventilation	Offices	New	N_OF_Dema	4.62	1.17	3.90	0.08	0.47	0.79
Commercial	Demand Controlled Ventilation	Restaurants	New	N_RS_Dema	1.43	0.76	1.92	0.02	0.12	0.20
Commercial	Demand Controlled Ventilation	Retail	New	N_RT_Dema	2.98	1.06	3.05	0.12	0.68	1.16
Commercial	Demand Controlled Ventilation	Warehouse	New	N_WR_Dem	1.20	0.69	1.76	0.01	0.06	0.11
Commercial	Retro-Commissioning	Assembly	Existing	E_AS_Retro	1.16	0.69	1.79	0.52	0.67	3.41
Commercial	Retro-Commissioning	College and University	Existing	E_CU_Retro	1.52	0.76	2.20	0.13	0.00	0.33
Commercial	Retro-Commissioning	Schools K-12	Existing	E_SC_Retro	1.66	0.83	2.20	0.15	0.31	0.96
Commercial	Retro-Commissioning	Assembly	New	N_AS_Retro	1.16	0.69	1.79	0.00	0.00	0.00
Commercial	Retro-Commissioning	College and University	New	N_CU_Retro	1.52	0.76	2.20	0.00	0.00	0.00
Commercial	Retro-Commissioning	Schools K-12	New	N_SC_Retro	1.66	0.83	2.20	0.00	0.00	0.00
Industrial	Process Refrig.Controls	Agriculture and Assembly		AA_Process	1.33	0.46	3.07	0.00	0.00	0.02
Industrial	Pump Equipment Upgrade	Agriculture and Assembly		AA_Pump Eq	1.89	0.51	4.10	0.03	0.03	0.19
Industrial	Fan Equipment Upgrades	Agriculture and Assembly		AA_Fan Equ	2.48	0.54	5.25	0.02	0.02	0.12
Industrial	Efficient Lighting - Other Interior Lighting	Agriculture and Assembly		AA_Efficien	1.40	0.47	3.16	0.19	0.18	1.31
Industrial	Efficient Lighting - High Bay	Agriculture and Assembly		AA_Efficien	2.40	0.55	4.99	0.46	0.45	3.24
Industrial	Compressed Air Controls	Agriculture and Assembly		AA_Compre	1.94	0.51	4.26	0.11	0.11	0.81
Industrial	Compressed Air Equipment	Agriculture and Assembly		AA_Compre	2.35	0.53	4.99	0.05	0.04	0.34
Industrial	Process Heat Equipment Upgrade	Chemicals and Plastics		CP_Process	1.53	0.48	3.59	0.04	0.04	0.32
Industrial	Process Refrig.Controls	Chemicals and Plastics		CP_Process	1.79	0.50	3.89	0.02	0.02	0.18
Industrial	Pump Equipment Upgrade	Chemicals and Plastics		CP_Pump Eq	2.39	0.54	5.06	0.06	0.06	0.43
Industrial	Motor Equipment Upgrades	Chemicals and Plastics		CP_Motor Eq	1.62	0.48	3.80	0.02	0.02	0.17
Industrial	Fan Equipment Upgrades	Chemicals and Plastics		CP_Fan Equ	2.38	0.54	5.05	0.01	0.01	0.06
Industrial	Efficient Lighting - Other Interior Lighting	Chemicals and Plastics		CP_Efficient	1.40	0.47	3.16	0.48	0.47	3.37
Industrial	Efficient Lighting - High Bay	Chemicals and Plastics		CP_Efficient	2.40	0.55	4.99	0.15	0.14	1.04
Industrial	Process Refrig.Equipment Upgrade	Construction		CS_Process	1.68	0.49	3.91	0.00	0.00	0.03
Industrial	Efficient Lighting - Other Interior Lighting	Construction		CS_Efficient	1.40	0.47	3.16	0.06	0.06	0.42
Industrial	Efficient Lighting - High Bay	Construction		CS_Efficient	2.40	0.55	4.99	0.03	0.03	0.24
Industrial	HVAC Recommissioning	Construction		CS_HVAC R	1.56	0.48	3.60	0.03	0.03	0.18
Industrial	Efficient Lighting - Other Interior Lighting	Electrical and Electronic Equip.		EE_Efficient	1.40	0.47	3.16	0.15	0.15	1.05
Industrial	Efficient Lighting - High Bay	Electrical and Electronic Equip.		EE_Efficient	2.40	0.55	4.99	0.05	0.05	0.33
Industrial	Process Refrig.Equipment Upgrade	Lumber/Furniture/Pulp/Paper		LP_Process	1.49	0.47	3.51	0.00	0.00	0.01
Industrial	Pump System Optimization	Lumber/Furniture/Pulp/Paper		LP_Pump Sy	1.40	0.46	3.37	0.24	0.23	1.77
Industrial	Pump Equipment Upgrade	Lumber/Furniture/Pulp/Paper		LP_Pump Eq	1.79	0.50	3.91	0.05	0.05	0.40
Industrial	Fan Equipment Upgrades	Lumber/Furniture/Pulp/Paper		LP_Fan Equ	2.34	0.53	4.97	0.03	0.03	0.24
Industrial	Efficient Lighting - Other Interior Lighting	Lumber/Furniture/Pulp/Paper		LP_Efficient	1.40	0.47	3.16	0.16	0.16	1.12
Industrial	Efficient Lighting - High Bay	Lumber/Furniture/Pulp/Paper		LP_Efficient	2.40	0.55	4.99	0.09	0.09	0.61
Industrial	Process Refrig.Controls	Metal Products and Machinery		MM_Process	1.01	0.41	2.55	0.00	0.00	0.01
Industrial	Process Refrig.Equipment Upgrade	Metal Products and Machinery		MM_Process	1.76	0.50	4.07	0.00	0.00	0.01
Industrial	Efficient Lighting - Other Interior Lighting	Metal Products and Machinery		MM_Efficien	1.40	0.47	3.16	0.11	0.11	0.76
Industrial	Efficient Lighting - High Bay	Metal Products and Machinery		MM_Efficien	2.40	0.55	4.99	0.10	0.09	0.68
Industrial	Process Refrig.Equipment Upgrade	Miscellaneous Manufacturing		MS_Process	1.50	0.47	3.54	0.00	0.00	0.01
Industrial	Motor Equipment Upgrades	Miscellaneous Manufacturing		MS_Motor E	1.60	0.48	3.76	0.00	0.00	0.02
Industrial	Efficient Lighting - Other Interior Lighting	Miscellaneous Manufacturing		MS_Efficien	1.40	0.47	3.16	0.13	0.13	0.93
Industrial	Efficient Lighting - High Bay	Miscellaneous Manufacturing		MS_Efficien	2.40	0.55	4.99	0.12	0.11	0.82
Industrial	HVAC Equipment Upgrades	Miscellaneous Manufacturing		MS_HVAC E	2.11	0.53	4.32	0.12	0.12	0.84
Industrial	Efficient Lighting - Other Interior Lighting	Primary Resources Industries		PR_Efficient	1.40	0.47	3.16	0.14	0.14	0.98
Industrial	Efficient Lighting - High Bay	Primary Resources Industries		PR_Efficient	2.40	0.55	4.99	0.16	0.16	1.16
Industrial	HVAC Equipment Upgrades	Primary Resources Industries		PR_HVAC E	2.76	0.57	5.51	0.01	0.01	0.04
Industrial	Process Heat Equipment Upgrade	Stone/Clay/Glass/Concrete		ST_Process	1.53	0.48	3.59	0.13	0.13	0.98
Industrial	Process Refrig.Equipment Upgrade	Stone/Clay/Glass/Concrete		ST_Process	1.40	0.46	3.33	0.00	0.00	0.01
Industrial	Efficient Lighting - Other Interior Lighting	Stone/Clay/Glass/Concrete		ST_Efficient	1.40	0.47	3.16	0.08	0.08	0.55
Industrial	Efficient Lighting - High Bay	Stone/Clay/Glass/Concrete		ST_Efficient	2.40	0.55	4.99	0.04	0.04	0.29
Industrial	Compressed Air Equipment	Stone/Clay/Glass/Concrete		ST_Compres	2.43	0.54	5.15	0.01	0.01	0.04
Industrial	Motor Optimization	Textiles and Leather		TX_Motor O	1.19	0.43	2.96	0.01	0.01	0.07
Industrial	Efficient Lighting - Other Interior Lighting	Textiles and Leather		TX_Efficient	1.40	0.47	3.16	0.01	0.01	0.04
Industrial	Efficient Lighting - High Bay	Textiles and Leather		TX_Efficient	2.40	0.55	4.99	0.00	0.00	0.01
Industrial	Building Envelope Improvements	Textiles and Leather		TX_Building	2.03	0.53	4.27	0.00	0.00	0.00
Industrial	Pump Equipment Upgrade	Transportation Equipment		TR_Pump Eq	2.17	0.52	4.62	0.00	0.00	0.03
Industrial	Fan Equipment Upgrades	Transportation Equipment		TR_Fan Equ	2.17	0.52	4.62	0.00	0.00	0.02
Industrial	Efficient Lighting - Other Interior Lighting	Transportation Equipment		TR_Efficient	1.40	0.47	3.16	0.15	0.14	1.03
Industrial	Efficient Lighting - High Bay	Transportation Equipment		TR_Efficient	2.40	0.55	4.99	0.04	0.04	0.29
Industrial	HVAC Recommissioning	Transportation Equipment		TR_HVAC R	1.55	0.48	3.58	0.05	0.05	0.32
Industrial	Process Refrig.Equipment Upgrade	Water and Wastewater		WW_Process	1.68	0.49	3.91	0.00	0.00	0.00
Industrial	Efficient Lighting - Other Interior Lighting	Water and Wastewater		WW_Efficien	1.40	0.47	3.16	0.00	0.00	0.01
Industrial	Efficient Lighting - High Bay	Water and Wastewater		WW_Efficien	2.40	0.55	4.99	0.00	0.00	0.00
Industrial	HVAC Recommissioning	Water and Wastewater		WW_HVAC	1.56	0.48	3.60	0.00	0.00	0.00
Residential	Central air conditioner - Load Shed	Single Family	Existing		1.90	1.90	N/A	0.00	0.00	0.00
Residential	Central air conditioner - Load Shed	Multi Family	Existing		1.00	1.00	N/A	18.34	0.00	0.00
Residential	Central air conditioner - Load Shed	Mobile Home/Other	Existing		1.87	1.87	N/A	7.23	0.00	0.00
Residential	Central Heating - Load Shed	Single Family	Existing		2.17	2.17	N/A	0.00	0.00	0.00

Residential	Central Heating - Load Shed	Multi Family	Existing		1.25	1.25	N/A	0.00	23.34	0.00
Residential	Central Heating - Load Shed	Mobile Home/Other	Existing		2.09	2.09	N/A	0.00	8.04	0.00
Residential	Central air conditioner - 50% cycling	Single Family	Existing		1.00	1.00	N/A	0.00	0.00	0.00
Residential	Central air conditioner - 50% cycling	Multi Family	Existing		1.00	1.00	N/A	0.00	0.00	0.00
Residential	Central air conditioner - 50% cycling	Mobile Home/Other	Existing		1.00	1.00	N/A	0.00	0.00	0.00
Residential	Central Heating - 50% cycling	Single Family	Existing		1.05	1.05	N/A	0.00	0.00	0.00
Residential	Central Heating - 50% cycling	Multi Family	Existing		1.00	1.00	N/A	0.00	0.00	0.00
Residential	Central Heating - 50% cycling	Mobile Home/Other	Existing		1.04	1.04	N/A	0.00	0.00	0.00
Residential	Water heater switches	Single Family	Existing		1.00	1.00	N/A	0.00	0.00	0.00
Residential	Water heater switches	Multi Family	Existing		1.00	1.00	N/A	0.00	0.00	0.00
Residential	Water heater switches	Mobile Home/Other	Existing		1.00	1.00	N/A	0.00	0.00	0.00
Residential	Pool pump switches	Single Family	Existing		1.00	1.00	N/A	11.69	7.54	0.00
Residential	Pool pump switches	Multi Family	Existing		1.00	1.00	N/A	0.00	0.00	0.00
Residential	Pool pump switches	Mobile Home/Other	Existing		1.00	1.00	N/A	0.00	0.00	0.00
Residential	Room AC control	Single Family	New		1.00	1.00	N/A	0.92	1.05	0.00
Residential	Room AC control	Mobile Home/Other	New		1.00	1.00	N/A	3.62	3.97	0.00
Residential	Smart thermostats - Utility Installation	Single Family	New		1.08	0.70	N/A	0.00	0.00	0.00
Residential	Smart thermostats - Utility Installation	Mobile Home/Other	New		1.06	0.70	N/A	0.00	0.00	0.00
Residential	Smart thermostats - BYOT	Single Family	New		1.10	1.10	N/A	0.00	0.00	0.00
Residential	Smart thermostats - BYOT	Multi Family	New		1.00	1.00	N/A	0.00	0.00	0.00
Residential	Smart thermostats - BYOT	Mobile Home/Other	New		1.11	1.11	N/A	0.00	0.00	0.00
Residential	CPP + Tech	Single Family	New		1.43	0.97	N/A	0	0	0
Residential	CPP + Tech	Mobile Home/Other	New		1.42	0.97	N/A	0	0	0
Small C&I	Central air conditioner - Load Shed	0-15,000 kWh	New		1.00	1.00	N/A	1.13	0.00	0.00
Small C&I	Central air conditioner - Load Shed	15,001-25,000 kWh	New		1.00	1.00	N/A	0.63	0.00	0.00
Small C&I	Central air conditioner - Load Shed	25,001-50,000 kWh	New		1.00	1.00	N/A	0.30	0.00	0.00
Small C&I	Central air conditioner - Load Shed	50,001 kWh +	New		1.00	1.00	N/A	1.29	0.00	0.00
Small C&I	Central Heating - Load Shed	0-15,000 kWh	New		1.00	1.00	N/A	0.00	6.06	0.00
Small C&I	Central Heating - Load Shed	15,001-25,000 kWh	New		1.00	1.00	N/A	0.00	1.26	0.00
Small C&I	Central Heating - Load Shed	25,001-50,000 kWh	New		1.00	1.00	N/A	0.00	0.66	0.00
Small C&I	Central Heating - Load Shed	50,001 kWh +	New		1.00	1.00	N/A	0.00	0.29	0.00
Small C&I	Central air conditioner - 50% cycling	0-15,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00
Small C&I	Central air conditioner - 50% cycling	15,001-25,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00
Small C&I	Central air conditioner - 50% cycling	25,001-50,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00
Small C&I	Central air conditioner - 50% cycling	50,001 kWh +	New		1.00	1.00	N/A	0.00	0.00	0.00
Small C&I	Central Heating - 50% cycling	0-15,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00
Small C&I	Central Heating - 50% cycling	15,001-25,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00
Small C&I	Central Heating - 50% cycling	25,001-50,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00
Small C&I	Central Heating - 50% cycling	50,001 kWh +	New		1.00	1.00	N/A	0.00	0.00	0.00
Small C&I	Smart thermostats - Utility Installation	25,001-50,000 kWh	New		1.07	0.70	N/A	0.00	0.00	0.00
Small C&I	Smart thermostats - Utility Installation	50,001 kWh +	New		2.83	0.99	N/A	0.00	0.00	0.00
Small C&I	Smart thermostats - BYOT	0-15,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00
Small C&I	Smart thermostats - BYOT	15,001-25,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00
Small C&I	Smart thermostats - BYOT	25,001-50,000 kWh	New		1.00	1.00	N/A	0.00	0.00	0.00
Small C&I	Smart thermostats - BYOT	50,001 kWh +	New		1.00	1.00	N/A	0.00	0.00	0.00
Small C&I	CPP + Tech	25,001-50,000 kWh	New		1.04	0.69	N/A	0.00	0.00	0.00
Small C&I	CPP + Tech	50,001 kWh +	New		2.66	0.96	N/A	0.00	0.00	0.00
Large C&I	Auto DR	0-50 kW	New		2.13	2.13	N/A	29.40	24.72	0.00
Large C&I	Auto DR	51-300 kW	New		2.13	2.13	N/A	41.54	31.97	0.00
Large C&I	Auto DR	301-500 kW	New		2.13	2.13	N/A	44.44	35.76	0.00
Large C&I	Auto DR	501 kW +	Existing		2.15	2.15	N/A	0.00	0.00	0.00
Large C&I	CPP	0-50 kW	New		1.15	1.15	N/A	0.00	0.00	0.00
Large C&I	CPP	51-300 kW	New		1.30	1.30	N/A	0.00	0.00	0.00
Large C&I	CPP	301-500 kW	New		1.00	1.00	N/A	0.00	0.00	0.00
Large C&I	CPP	501 kW +	New		1.40	1.40	N/A	0.00	0.00	0.00
Large C&I	Firm Service Level	0-50 kW	New		2.35	2.35	N/A	0.00	0.00	0.00
Large C&I	Firm Service Level	51-300 kW	New		2.35	2.35	N/A	0.00	0.00	0.00
Large C&I	Firm Service Level	301-500 kW	New		2.35	2.35	N/A	0.00	0.00	0.00
Large C&I	Firm Service Level	501 kW +	Existing		2.37	2.37	N/A	0.00	0.00	0.00
Large C&I	Guaranteed Load Drop	0-50 kW	New		2.35	2.35	N/A	0.00	0.00	0.00
Large C&I	Guaranteed Load Drop	51-300 kW	New		2.35	2.35	N/A	0.00	0.00	0.00
Large C&I	Guaranteed Load Drop	301-500 kW	New		2.35	2.35	N/A	0.00	0.00	0.00
Large C&I	Guaranteed Load Drop	501 kW +	Existing		2.37	2.37	N/A	0.00	0.00	0.00