ORIGINAL

State of Florida



Hublic Service Commission -M-E-M-O-R-A-N-D-U-M

DATE: August 13, 2003

TO:

Blanca S. Bayó, Commission Clerk and Administrative Services Director

FROM: Division of Auditing and Safety (Ruehl) (Ruehl) (RE: Docket No. 030623-EI - Complaints by Southeastern Utility Services, Inc., on Behalf of

Various Customers, against Florida Power & Light Company concerning Thermal

Demand Meter Error

Please place the following in the above docket file.

Re-test of 1V Demand Meter #52093 tested by Florida Power and Light as requested by George Brown, Southeastern Utility Services, Inc. and witnessed by Commission Engineers.

JR:dr

Attachment

cc:

Without Attachments

Tim Devlin Joe Jenkins Roland Floyd Bill McNulty Cochran Keating **Edward Mills**

Dan Hoppe

COMMISSION CLERK ADMINISTRATIVE SERVICES

03:11 MA E1 3UA E0

DOCUMENT ALMOCR - DATE U7462 AUG 148

FPSC-COMMISSION CLERK

State of Florida



Public Service Commission

-M-E-M-O-R-A-N-D-U-M-

DATE: August 11, 2003

TO: Jim Ruehl, Supvr., Electric Safety, Tallahassee

FROM: Clinton Williams, Engineer III, Miami

RE: Meter Tests

I witnessed the re-test of demand meter #IV52093 at FPL's Miami Test Center on August 5, 2003. The test was done at the request of Mr. George Brown and was done at a higher load level that the earlier test. The result showed a KWD error of +5.78%. Two test forms for this meter are enclosed.



Stop: 08/21/2002 15:37.26

Board: 2529

Tester: JDT

FLORIDA POWER & LIGHT

EQUIPMENT SUMMARY REPORT

SERIAL NO: L023402791

SENIAL NO. 6023402731									
Identification -		Faceplate -							
Serial No 023402791	1	Mfr L	_	Aep Code	СН				
Company No 52093	' ! !	Mfr Type. TN	MT	Form	6 S				
		Company Symbol: 1V		Volts	277				
Amr No·		Type Code: 04			. 2.5				
Batch No		M&S Code. LE			: 003.600				
Barcode.	[Reg Ratio	: 055 05/09				
ccounting	L	Status/Location —							
Purchase Date: 00/00/0000				Current	Previous				
Retire Code:		Shop Status: C	PPID: 00						
Retire By		Bin:							
Retire Date: 00/00/0000		Address: 100 RIVERFRONT, HOLIDAY INN							
Information Test Location: K	Std	Mode: Watts		Creep: <u>No</u>					
Test Reason: PSC		ection: Forward	Hiç	h Pot: Yes	_				
Seal Status: 53	Test S	ervice: Single Phase	Element Ba	lance: Yes					
As Found————		As Left							
S A B	С	s	S A B	С					
FL: 100.33 100.45			0.33 100.45						
PF: 100.15			0.15						
LL: <u>100.20</u>		LL: 100.20							
WA: <u>100.26</u>		WA: 100							
Reading: 5616 KYZ		Reading:	5621 Reps Pa	ss Fail ⁻ 1	0				
Start: 08/21/2002 15.26:38	\$tart: 08/	/21/2002 15:26.38							

Witnessed by Elister Williams, PSC Engines 8-5-03

Stop: 08/21/2002 15:37:26
Tester: JDT Board 2529



FLORIDA POWER & LIGHT

EQUIPMENT SUMMARY REPORT

SERIAL NO: L023402791

				····		
Information	Std Mada	\Matte	Cross No.	7		
Test Location S		Watts	Creep. No			
Test Reason. RTM	Test Direction		High Pot: Yes			
Seal Status	Test Service	Single Phase	Element Balance. Yes			
As Found———	As L	.eft]		
S A B	С	S	A В С			
FL <u>99.80</u>	1 1	FL: 100.17				
PF. 99.89		PF· 100 24	-			
LL <u>99 42</u>		LL: 100 00				
WA [.] 99.77		WA: <u>100.17</u>				
Reading 0000 KYZ.		Reading: 0005	Reps Pass Fail ⁻ 2	ı		
Start: 06/21/1994 12:45:00		Start: 01/01/19	00 12.45:00			
Stop 06/21/1994 12:56.00		Stop: 01/01/1900 12·56 00				
Tester. RAR Board [.] 07		Tester: RAR	Board. <u>07</u>			
- Variboard	D					
	Demand—					
Register Test /	_ As Found	d	As Left			
	Pass	s/Fail.	Pass/Fail:			
Start: 06/21/1994 00:00:00	Demand Demand:			0		
Stop: 06/21/1994 00:00:00	Rea	ading				
Tester: Board: 02						
rester Board. 02						
~Variboard ~~~~	_ ⊢Demand					
Register Test / 7.0	-As Found	d	As Left			
L	Pass	s/Fail·	Pass/Fail:			
Start: 08/05/2003 09:30 08		nand 5.78	1 !			
Stop: 08/05/2003 10:34 37						
	Rea	adıng 05628	Reading: 056	34		
Tester. BEF Board 4		·				
General Comment						
K₽₩ ACC +6.0 %						
KWD						

Witnessed by Eliston Williams, PSC Engineer B-5-03