


ORIGINAL

# Appendix B


DOCUMENT NUMBER-DATE

04611 MAY 26 8

FPSC-COMMISSION CLERK




This healthy pole fell during the storm. It is burdened with a 2" telephone bundle, a 3" CATV bundle and a three cable telecommunication carrier bundle.




Communication and CATV cable at eye level after a storm passed through and blew the pole over.




Three bundled cables attached within one foot of space on the pole (against FPL standards). Additionally there are multiple cables coming off the pole at the Sam's club sign (almost mid picture) and tossed together about thirty feet to the right of the pole. All the cables inter-twine at midspan, causing a very large cross-section sail for the wind to catch.



Cable transfer of large cable and multiple attachments not completely transferred and hanging in the wind, preventing the old pole from being removed.



This bundle contains six cables and a messenger cable. Two of the cables are more than one inch in diameter. The bundle reaches a diameter of five inches and more where splices exist.



Very sloppily constructed CATV bundle with many cables attached along with a telephone bundle