

Row Labels	January	February	Grand Total
20059241	7,333.98	3,385.65	10,719.63
FL BASE-POLE REPLACE-CLOSED LOT	7,333.98	3,385.65	10,719.63
LPOLCM	13,714.63	388,722.29	402,436.92
FL Reactive Pole Replacments	13,714.63	388,722.29	402,436.92
LPOLRPL	179,749.28	64,100.68	243,849.96
FL Pole Replacements	179,749.28	64,100.68	243,849.96
MX1164436	173.04		173.04
12505 STARKEY ROAD (2 Poles / 2 ban	173.04		173.04
MX2398542		48.03	48.03
POLE REPLACEMENT - NON-INSPECTION B		48.03	48.03
Grand Total	200,970.93	456,256.65	657,227.58

Row Labels	January	February	Grand Total
20065326	275.68	0.00	275.68
CIR POLE REPL	275.68	0.00	275.68
LPOLIR	760,644.95	1,120,958.04	1,881,602.99
FL Pole Replace Insp Based	760,644.95	1,120,958.04	1,881,602.99
MX3283548	1,070.75		1,070.75
DELAND 5X POLE PROJECT - WO 7	1,070.75		1,070.75
Grand Total	761,991.38	1,120,958.04	1,882,949.42

Row Labels	January	February	Grand Total
MX2039119	639.69	10,244.35	10,884.04
SO_POLE_REPL_PINE_W0392	639.69	10,244.35	10,884.04
MX2039074	15.57	13,440.65	13,456.22
SO_POLE_REPL_PINE_W0392	15.57	13,440.65	13,456.22
MX2326874	751.55	11,944.67	12,696.22
SUB OPT - DEFECTIVE POLE REPLACEMEN	751.55	11,944.67	12,696.22
MX2969240	6,632.66	1,945.32	8,577.98
SO_POLE REPLACEMENT_X104_51ST ST_PA	6,632.66	1,945.32	8,577.98
MX2329106	2,547.35	304.37	2,851.72
SO_POLE REPLACEMENT_X104_51ST ST_PA	2,547.35	304.37	2,851.72
MX2780102	1,624.04	8,402.78	10,026.82
SO_POLE REPLACEMENT_X103_51ST ST_PA	1,624.04	8,402.78	10,026.82
MX2780254	1,544.65	21,195.06	22,739.71
SO_POLE REPLACEMENT_X103_51ST ST_PA	1,544.65	21,195.06	22,739.71
MX2969299	8,141.00	1,978.64	10,119.64
SO_POLE REPLACEMENT_X104_51ST ST_PA	8,141.00	1,978.64	10,119.64
MX2969346	6,453.23	647.60	7,100.83
SO_POLE REPLACEMENT_X104_51ST ST_PA	6,453.23	647.60	7,100.83
MX3049552	7,819.68	1,655.25	9,474.93
SO_POLE REPLACEMENT_X105_51ST ST_PA	7,819.68	1,655.25	9,474.93
MX2386121	1,215.60	1,765.79	2,981.39
SO_POLE_REPL_DEL_W0804	1,215.60	1,765.79	2,981.39
MX2386172	14,417.37		14,417.37
SO_POLE_REPL_DEL_W0804	14,417.37		14,417.37
MX2014903	6,966.31		6,966.31
SO_POLE_REPL_DEL_W0804	6,966.31		6,966.31
MX2386054	1,621.24		1,621.24
SO_POLE_REPL_DEL_W0804	1,621.24		1,621.24
MX2038843		-98.16	-98.16
SO_POLE_REPL_PINE_W0395		-98.16	-98.16
MX2038892		-224.16	-224.16
SO_POLE_REPL_PINE_W0395		-224.16	-224.16
MX2038948		-55.42	-55.42
SO_POLE_REPL_PINE_W0395		-55.42	-55.42
MX2329320		5,606.09	5,606.09
SO_POLE REPLACEMENT_104_51ST ST_PAR		5,606.09	5,606.09
MX2328929		285.13	285.13
SO_POLE REPLACEMENT_X103_51ST ST_PA		285.13	285.13
MX2329517		3,029.39	3,029.39
SO_POLE REPLACEMENT_X105_51ST ST_PA		3,029.39	3,029.39
MX2329574		580.04	580.04
SO_POLE REPLACEMENT_X105_51ST ST_PA		580.04	580.04
MX2329798		650.18	650.18
SO_POLE REPLACEMENT_X106_51ST ST_PA		650.18	650.18
MX2329859		9,064.92	9,064.92
SO_POLE REPLACEMENT_X106_51ST ST_PA		9,064.92	9,064.92

MX2329948	7,325.15	7,325.15
SO_POLE REPLACEMENT_X107_51ST ST_PA	7,325.15	7,325.15
MX2330017	3,456.96	3,456.96
SO_POLE REPLACEMENT_X107_51ST ST_PA	3,456.96	3,456.96
MX2746823	309.67	309.67
SO_POLE REPLACEMENT_X107_51ST ST_PA	309.67	309.67
MX2969434	7,942.07	7,942.07
SO_POLE REPLACEMENT_X104_51ST ST_PA	7,942.07	7,942.07
MX2969554	20,428.75	20,428.75
SO_POLE REPLACEMENT_X104_51ST ST_PA	20,428.75	20,428.75
MX2969609	4,746.40	4,746.40
SO_POLE REPLACEMENT_X104_51ST ST_PA	4,746.40	4,746.40
MX3047567	10,284.39	10,284.39
SO_POLE REPLACEMENT_X103_51ST ST_PA	10,284.39	10,284.39
MX2780246	8,965.66	8,965.66
SO_POLE_REPL_PTRW_C203_Parent	8,965.66	8,965.66
Grand Total	60,389.94	155,821.54 216,211.48

Row Labels	February	Grand Total
LSPPPLFD	13,472.24	13,472.24
DEF SPP Pole Replace FH	13,472.24	13,472.24
Grand Total	13,472.24	13,472.24

Row Labels	February	Grand Total
LSPPPLHD	5,540.77	5,540.77
DEF SPP Pole Replace LH	5,540.77	5,540.77
Grand Total	5,540.77	5,540.77