

ORIGINAL

LAW OFFICES  
ROSE, SUNDBSTROM & BENTLEY, LLP  
2548 BLAIRSTONE PINES DRIVE  
TALLAHASSEE, FLORIDA 32301

FREDERICK L. ASCHAUER, JR.  
CHRIS H. BENTLEY, P.A.  
ROBERT C. BRANNAN  
DAVID F. CHESTER  
F. MARSHALL DETERDING  
JOHN R. JENKINS, P.A.  
STEVEN T. MINDLIN, P.A.  
CHASITY H. O'STEEN  
DAREN L. SHIPPY  
WILLIAM E. SUNDBSTROM, P.A.  
DIANE D. TREMOR, P.A.  
JOHN L. WHARTON  
ROBERT M. C. ROSE, OF COUNSEL  
WAYNE L. SCHIEFELBEIN, OF COUNSEL

(850) 877-6555  
FAX (850) 656-4029  
www.rsbatorneys.com

REPLY TO CENTRAL FLORIDA OFFICE

January 16, 2006

CENTRAL FLORIDA OFFICE  
SANLANDO CENTER  
2180 W. STATE ROAD 434, SUITE 2118  
LONGWOOD, FLORIDA 32779  
(407) 830-6331  
FAX (407) 830-8522

MARTIN S. FRIEDMAN, P.A.  
VALERIE L. LORD  
BRIAN J. STREET

Ms. Blanca Bayo  
Commission Clerk and Administrative Services Director  
Florida Public Service Commission  
2540 Shumard Oak Boulevard  
Tallahassee, FL 32399

Re: Docket No. 050902-WS; Application of Gold Coast Utility Corp. for Authority to Transfer Assets and Certificate Nos. 590-W and 508-S of Lake Haven Utility Associates, Ltd., d/b/a Lake Wales Utility Company in Polk County  
Our File No.: 40057.03


Dear Ms. Bayo:

In response to the Commission Staff's December 28, 2005 correspondence regarding the above-referenced docket, enclosed is a copy of Laniger Enterprises of America, Inc.'s response to the Florida Department of Environmental Protection's Sanitary Survey of its public water system. As you will note, none of the non-compliance issues were substantial enough for the DEP to issue a notice of violation.

With regard to the Laniger Enterprises wastewater treatment plant, that utility currently has an application pending before the DEP for a renewal of its operating permit, which is being addressed through a proceeding before the Division of Administrative Hearings. Should the Staff have any further questions regarding this matter, please do not hesitate to have them give me a call.

- CMP \_\_\_\_\_
- COM \_\_\_\_\_
- CTR \_\_\_\_\_
- ECR \_\_\_\_\_
- GCL \_\_\_\_\_
- OFC \_\_\_\_\_
- RCA \_\_\_\_\_
- SCR \_\_\_\_\_
- SGA \_\_\_\_\_
- SEC \_\_\_\_\_
- OTH \_\_\_\_\_

MSF/tlc  
Enclosure  
cc: Mr. Keith Burge (w/o enclosure)  
Mr. Richard Redemann (w/enclosure)

Very truly yours,  
  
MARTIN S. FRIEDMAN  
For the Firm

RECEIVED CENTER  
06 JAN 19 10 08 AM

RECEIVED FPSC  
06 JAN 19 AM 9:02  
COMMISSION CLERK

JAN 11 2006

## Laniger Enterprises of America, Inc.

2340 NE Dixie Hwy  
Jensen Beach, FL 34957

January 6, 2006

Florida Department of Environmental Protection  
Port St. Lucie Branch Office  
1801 SE Hillmoor Drive, Suite C-204  
Port St. Lucie, FL 34952

Re: Response to your letter dated December 23, 2005

Dear Sir or Madam:

This letter is in response to the above mentioned letter. The first three deficiencies that you referenced that were also noted on a non - compliance letter dated 12/3/2002 were addressed back in 2002, but since you decided to schedule an inspection 1 week after hurricane Wilma blew through, the fence was again blown down. I will attempt to address each deficiency as notated in your letter.

- 1.) As I stated above the fence had blown down again during hurricane Wilma, but it is now repaired and the whole facility is secured.
- 2.) There are currently 2 high service pumps in operation, and the third pump was sent out to be repaired. Since the last inspection the third high service pump has been installed and is currently working. I would like to add that there has always been two working high service pumps, which are more than able to provide sufficient capacity.
- 3.) There is a Generator log book in the water plant building and it has been there since the December 3, 2002 letter. It has all the entries in it and it is up to date. I do not know why the operator or the inspector could not find it.
- 4.) The rain cap on top of the ground storage tank was repaired and it is now being painted and it is in the process of being installed. It should be back on by the time of your follow up inspection on Wednesday, December 11, 2006 at 11:00 am
- 5.) The disinfection monitoring plan has been done and is on file at the utility office. We were told that it did not have to be filed with the FDEP as long as it was completed and available upon request. However, I am enclosing it with this letter.
- 6.) This sampling was done on time and submitted to the Department. I have called the Port St. Lucie office and they were going to check their files. However, I will enclose a copy of the results along with this letter.

DOCUMENT NUMBER-DATE

00489 JAN 19 06

FPSC-COMMISSION CLERK

7.) I have contacted your office and scheduled a follow up visit to address the location of the second well as well as to confirm that the chlorine alarm and dialer are functional.

If you should have any questions or concerns regarding the above please contact me in writing at the above address. Thank you for your cooperation in this matter.

Sincerely,

Reginald J. Burge  
Laniger Enterprises of America, Inc.

cc. Mr. Martin S. Friedman, Rose, Sundstrom & Bentley