

VOTE SHEET

October 26, 2010

Docket No. 090505-EI – Review of replacement fuel costs associated with the February 26, 2008 outage on Florida Power & Light Company's electrical system. (Deferred from the October 12, 2010 Commission Conference, revised recommendation filed.)

Issue 1: Should the Commission reconsider its decision to credit FPL with 27 hours of time associated with the repair of the rod position indication system at Turkey Point Unit 3?

Recommendation: No. The Commission considered and evaluated all the record evidence in reaching its conclusion that the incremental time associated with the repair of the rod position indication system was 27 hours and not 126 hours. Because the Commission did not overlook or fail to consider the evidence in the record, FPL's motion for reconsideration should be denied.

DEFERRED

COMMISSIONERS ASSIGNED: All Commissioners

COMMISSIONERS' SIGNATURES

MAJORITY

DISSENTING

Four horizontal lines for majority signatures.

Four horizontal lines for dissenting signatures.

REMARKS/DISSENTING COMMENTS: Deferred to the November 9, 2010 Commission Conference

DOCUMENT NUMBER DATE

8910 OCT 26 0

Vote Sheet

October 26, 2010

Docket No. 090505-EI – Review of replacement fuel costs associated with the February 26, 2008 outage on Florida Power & Light's electrical system. (Deferred from the October 12, 2010 Commission Conference, revised recommendation filed.)

(Continued from previous page)

Issue 2: Should the Commission reconsider its decision to require Florida Power & Light Company to refund the full 107 hours of outage at Turkey Point Unit 4, without giving credit for the time required to replace and test a malfunctioning relay in at the reverse power protection system?

Recommendation: No. The Commission did not overlook or fail to consider Order No. 23232, issued July 20, 1990, in Docket No. 090001-EI (Order No. 23232), in requiring a refund for the full outage time at Turkey Point Unit 4. The repair for the relay was not a planned outage. In Order No. 23232, a portion of the outage coincided with a planned outage.

DEFERRED

Issue 3: Should the Commission make any corrections to the refund amount established in Order No. PSC-10-0381-FOF-EI?

Recommendation: No. The Commission did not overlook or fail to consider the factual and legal issues raised by FPL in reaching the Commission's decision to require a refund of \$13,854,054 to ratepayers as a result of the February 26, 2008 outage.

DEFERRED

Issue 4: Should this docket be closed?

Recommendation: Yes. Upon expiration of the time for appeal, if no appeal has been taken, this docket should be closed.

DEFERRED