

State of Florida



## Public Service Commission

CAPITAL CIRCLE OFFICE CENTER • 2540 SHUMARD OAK BOULEVARD  
TALLAHASSEE, FLORIDA 32399-0850

**-M-E-M-O-R-A-N-D-U-M-**

---

**DATE:** July 9, 2015  
**TO:** Carlotta S. Stauffer, Commission Clerk, Office of Commission Clerk  
**FROM:** Clayton Lewis, US Engineering Specialist, Division of Engineering *CKL*  
**RE:** Docket No. 140219-WU- Application for staff-assisted rate case in Polk County by Alturas Utilities, L.L.C.

---

Please file the attached in the above mentioned Docket File.

Thank you.

## **Terri Jones**

---

**From:** Clayton Lewis  
**Sent:** Thursday, July 09, 2015 8:32 AM  
**To:** Terri Jones  
**Subject:** Docket No. 140219 - Alturas

Good Morning,

Please add the message below to the docket file.

Thank you

-----Original Message-----

**From:** L SZABO [<mailto:l.szabo@rogers.com>]  
**Sent:** Thursday, July 09, 2015 7:22 AM  
**To:** Clayton Lewis  
**Cc:** [WileyPratt@netscape.net](mailto:WileyPratt@netscape.net)  
**Subject:** answers to your question

Good Morning Mr. Lewis,

I am forwarding Wiley Pratt reply to your questions.

I will call you later on today or latest by tomorrow before noon as I am still waiting for more input from contractors.

Leslie Szabo

Mr. Lewis,

Here is the information you requested:

1. January 2014: Replaced Roto-Tube on stenner chlorine pump.
2. April 2014: Replaced Roto-Tube on stenner chlorine pump.

\*The above two issues were due to calcium build-up inside injector/pipe creating back pressure causing a hole to form on roto-tube.

3. May 2014: Lighting strike at WTP knock out motor on stenner chlorine pump-changed out motor.
- 4 June 2014: Discharge tube on chlorine line had a hole-changed out tubing.

If you need anything email back or call (863) 651-0259.

Thank You'  
Wiley Pratt