CORRESPONDENCE 10/11/2017 DOCUMENT NO. 08598-2017

Review of Electric Utility Hurricane Preparedness and Restoration Actions

Docket No: 20170215-EU

Name: Bruce Hill

Electric Utility Provider: FPL

Zip Code: 33419 Category: Other

Comments: The biggest problem that. I can see is the lackluster efforts to keep the power lines clear of tree limbs. In my neighborhood hood alone I could show you at least 100 locations where trees are in direct contact with the highest power lines. We've had several power blips since the storm and I'm amazed that we don't loose power every day because of this situation. Some how with have to hold the power company and the property owner responsible for keeping the power lines clear on a continual basis.

Thank you