

North Peninsula Utilities Corp.

P.O. Box 2803
Ormond Beach, FL 32175
386-677-7607 phone
developershw@gmail.com

Takira T. Thompson
Engineering Specialist
Division of Engineering
Florida Public Service Commission
Tallahassee FL 32311

RE: 8Th Request to SARC

Ms. Thompson,

1. a. Overflows outside utility property have been few. They are caused by electrical power failures, mechanical problems or storms/hurricanes. Improvements/upgrades to the electrical system (including surge protectors) have been made over the last year. Upgrades to the warning RTU and to electrical/mechanical equipment are continuing this year.
- b. NPUC will continue to upgrade the perimeter fencing and, in the future, install a fence around the plant itself to help visually and provide some additional sound abatement.
- c. NPUC has been and is in compliance with all Volusia County ordinances regarding plant noise. NPUC has additionally installed sound deadening fences, where needed, to help with this issue.
- d. Plant odor is generally caused by mechanical equipment problems. Operators (Wetherell) have/will make necessary adjustments as quickly as possible to moderate any odors.

R. Hillman
NPUC