



CenturyLink™

Monica Echevarria Garcia

100 CenturyLink Drive

Monroe, LA 71203

(813) 316-7766

monica.echevarriagarcia@lumen.com

May 23, 2024

VIA ELECTRONIC FILING

Mr. Adam Teitzman, Clerk
Office of the Commission Clerk
Florida Public Service Commission
2540 Shumard Oak Boulevard
Tallahassee, FL 32399-0850

RE: **Docket No. 20240000-OT (Undocketed Filings for 2024)**
Lumen's Annual Pole Report, Subsection (6) of Rule 25-18.020, F.A.C.

Dear Mr. Teitzman:

In accordance with Rule 25-18.020(6), F.A.C, Pole Safety, Inspection, Maintenance, and Vegetation Management, attached please find the Annual Report for poles as defined in Section 366.02(06), F.S. owned by CenturyLink of Florida, Inc. ("Lumen").

Should you have any questions concerning this filing, please feel free to contact me.

Sincerely,

/s/ Monica Echevarria Garcia

Monica Echevarria Garcia

MEG/bardm

Enclosure

2024 Annual Pole Report of Inspections for Lumen Owned Poles in Florida

Lumen Pole Data for the prior calendar year.

1. The number of poles owned in whole or in part by the communications services provider at the beginning and at the end of the calendar year:
 - a. As of June 1, 2023: **34,767**
 - b. As of May 31, 2024: **34,767**
2. The number of poles that were scheduled for inspection: **4,346**
3. The number of poles actually inspected: **4,346**
4. The number of poles that failed inspection: **160**
5. The number of poles strength tested: **1,753**
 - a. Methods used to ensure compliance with the NESC strength requirements:
Bore and Sound, Sound Only
6. The number of poles that failed strength testing: **146**
7. The number of poles repaired: **138**
 - a. Summary of the repairs: **Osmose C Truss installed on 134 poles; Osmose C Truss - Tall installed on 1 pole; Osmose Double C Truss installed on 3 poles**
8. The number of poles replaced: **80**
 - a. Reason for Replacement: **Poles were replaced due to extensive shell and heartwood rot, leaning, decayed and split tops.**
9. The total miles of vegetation management conducted: **approximately 235 miles**

Lumen Pole Data for the upcoming calendar year.

1. The number of poles to be inspected: **4887**
2. The total miles for which vegetation management will be conducted:
approximately 231 miles