STEEL.

HECTOR

DAVIS

October 30, 1996

Charles A. Guyton 904,222,3423

961302-EI

By Hand Delivery

Blanca S. Bayó, Director Records and Reporting Florida Public Service Commission 4075 Esplanade Way, Room 110 Tallahassee, Florida 32399-0850

> Re: Petition of Florida Power & Light Company to Further Extend its BuildSmart™ Pilot Program

Dear Ms. Bayó:

ACK ____

AFA

APP

Enclosed for filing on behalf of Florida Power & Light Company are the original and fifteen (15) copies of Petition of Florida Power & Light Company to Further Extend its BuildSmartTM Pilot Program. Also enclosed is an additional copy of the Petition, which I request you stamp as filed and returned to our runner.

If you or your Staff have any questions regarding this filing, please contact me at 222-2300

-	
CAG/ld	
cc Jack Shreve, E	sq.
encs RECEIVED &	FILE
TAI/17308-17-49	
FPSC-BUREA	U OF RECORDS
Mami 305 577 7000 	West Fair each 561 650 7200 561 655 1509 Fax

Very truly yours,

Charles A. Guyton Attorney for Florida Power &

Light Company

Key West 305 292 7272 305 292 7271 Fax DOCUMENT NUMBER-DATE

Caracas 4655 2 3 OCT 30 %

FPSC-RECORDS/REPORTING

BEFORE THE FLORIDA PUBLIC SERVICE COMMISSION

In Re: Petition of Florida Power &)	Docket No. 96 130 2
Light Company to Further Extend Its)	
BuildSmart TM Pilot Program)	Filed: October 30, 1996

PETITION OF FLORIDA POWER & LIGHT COMPANY TO FURTHER EXTEND ITS BUILDSMART™ PILOT PROGRAM

Florida Power & Light Company ("FPL"), pursuant to Section 366.82(2), Florida Statutes (1995), hereby petitions the Florida Public Service Commission ("Commission") to extend FPL's BuildSmartTM Pilot Program until final Commission action on FPL's Amended Petition For Approval Of BuildSmartTM Program and allow FPL to recover reasonable and prudent expenditures for the BuildSmartTM Pilot Program through FPL's Energy Conservation Cost Recovery ("ECCR") Clause. The grounds for this petition are:

- FPL is an investor-owned electric utility regulated by the Commission pursuant to Chapter 366, Florida Statutes. FPL is subject to the Florida Energy Efficiency and Conservation Act ("FEECA"), Section 366.80-.85, 403.519, Florida Statutes (1995), and its ECCR Clause is subject to the Commission's jurisdiction. FPL is substantially affected thereby.
- FPL's address is 9250 West Flagler Street, Miami, FL 33174. Correspondence, notices, orders and other documents concerning this Petition should be sent to:

Charles A. Guyton Steel Hector & Davis LLP Suite 601 215 S. Monroe Street Tallahassee, FL 32301 William G. Walker, III Vice President, Regulatory Affairs Florida Power & Light Company 9250 West Flagler Street Miami, FL 33174

I 1523 OCT 30 %

- 3. In March 1993 the Commission approved the New Home Construction Research Project as part of FPL's Conservation Plan. Order No. PSC-93-0339-FOF-EG. The New Home Construction Research Project was a two year research project designed to investigate, quantify and determine the cost-effectiveness of the conservation opportunities available in the residential, detached, single-family, home construction market.
- A significant part of the New Home Construction Research Project was the creation and offering of a BuildSmart™ Pilot Program that has been used to evaluate the impact of education, inspections, and certification on new home construction energy-efficiency. In the BuildSmart™ Pilot Program, FPL has educated builders and customers about energy-efficiency building practices and their benefits, performed new home inspections to verify installations, rated the homes for their energy efficiency, and provided certificates for qualifying new homes (homes that exceed Energy Efficiency Code requirements by more than 10%-Bronze Certificates, 20%-Silver Certificate, and 30%-Gold Certificates). The Residential New Construction BuildSmart™ Program Standards, previously provided to the Commission as part of a quarterly report, more fully explain the BuildSmart™ Pilot Program and are attached as Appendix A.
- 5. FPL has been offering the BuildSmart™ Pilot Program in Southwest Florida (Charlotte, Lee, Glades, Hendry and Collier counties). The pilot program has been well-received by builders and customers. As of September 30, 1996, ninety-five (95) builders have participated and five hundred and thirty-eight (538) homes have been certified (see Appendix B for a list of participating builders and home certification history).

- 6. FPL completed its New Home Construction Research Project and filed a final report with the Commission on June 1, 1995. The final report found that BuildSmart™ had proven preliminarily to be cost-effective.
- Prior to filing its final report, FPL petitioned the Commission to extend FPL's BuildSmartTM Pilot Program through December 31, 1995. FPL requested that its BuildSmartTM activities in Southwest Florida be continued until a system-wide program could be established. The primary justification for the continued offering of BuildSmartTM in Southwest Florida was program continuity. BuildSmartTM had been well-received where it is offered, and there was significant momentum in those markets. Suspension of the BuildSmartTM efforts until a new program could be rolled-out would have forfeited that momentum and adversely affected customer and building contractor acceptance. Therefore, FPL sought Commission approval to continue the BuildSmartTM Pilot Program until FPL could seek and was granted approval of a system-wide BuildSmartTM Program. By Order No. 95-0611-FOF-EG, the Commission granted FPL's request to extend the BuildSmartTM Pilot Program through December 31, 1995.
- FPL filed a petition seeking Commission approval of a permanent BuildSmart™
 Program on December 7, 1995. That petition was assigned Docket No. 951536-EG.
- 9. At the same time that FPL filed for approval of the permanent BuildSmart™ Program, FPL sought a further extension of the BuildSmart™ Pilot Program until final Commission action in Docket No. 951536-EG. In Order No. PSC-96-0116-FOF-EG, the Commission granted a second extension of the BuildSmart™ Pilot Program through March 30, 1996.
- 10. In February 1996 FPL filed a request for a third extension for the BuildSmart Pilot Program, since the schedule for the Permanent BuildSmart Program had been extended beyond

March 30, 1996. Once again FPL sought Commission approval of the extension of the BuildSmart Pilot Program until final Commission action in Docket No. 951536-EG. By Order No.PSC-96-0404-FOF-EG, the Commission granted a third extension of the BuildSmart Pilot Program through December 31, 1996.

- 11. In July 1996 FPL amended its petition for approval of the permanent BuildSmart™

 Program in Docket No. 951536-EG. FPL does not anticipate Commission proposed agency action on the permanent BuildSmart™ Program until some time in late 1996. A protest of such a proposed agency action order would extend final action on the BuildSmart™ Program well into 1997. Therefore, FPL is filing this Petition to seek a further extension of its BuildSmart™ Pilot Program in Southwest Florida until the Commission takes final action on FPL's petition in Docket No. 951536-EG. FPL is prepared to continue submitting quarterly reports during this extension period.
- 12. FPL seeks to recover the costs associated with the extension of its BuildSmart™ Pilot Program after December 31, 1996 until the Commission takes final action in Docket No. 951536-EG. FPL estimates that the cost of extending its BuildSmart™ activities in Southwest Florida through December 31, 1997 would be \$80,000. These expenditures are in excess of the \$6,750,000 of costs originally estimated for FPL's New Home Construction Research Project and the additional amounts authorized in the three prior extensions of the BuildSmart™ Pilot Program.
- 13. FPL believes that its BuildSmart™ Pilot Program in Southwest Florida should continue until a system-wide program can be established. The primary justification for the continued offering of BuildSmart™ in Southwest Florida is program continuity. BuildSmart™ has been well-received where it is offered, and there is significant momentum in those markets. Suspension of the BuildSmart™ efforts until a new program can be rolled-out would forfeit that

momentum and adversely affect customer and building contractor acceptance. Therefore, FPL is seeking Commission approval to continue the BuildSmartTM Pilot Program until FPL can seek and is granted approval of a system-wide BuildSmartTM Program.

14. The continued offering of BuildSmart™ will help achieve the goals of FEECA and Commission Rule 25-17.001, Florida Administrative Code. BuildSmart™ has been shown to be cost-effective to both participating and nonparticipating customers. BuildSmart™ has also been demonstrated to be monitorable and to yield measurable results. Therefore, it satisfies the Commission's criteria for approval and cost recovery.

WHEREFORE, FPL respectfully petitions the Commission (1) to extend the BuildSmartTM

Pilot Program in Southwest Florida until the Commission takes final action in Docket No. 951536
EG, FPL's petition for approval of a permanent BuildSmartTM Program for system-wide implementation, and (2) allow FPL to recover through its ECCR clause reasonable and prudent expenditures for the extended BuildSmartTM Pilot Program activities.

Respectfully submitted,

STEEL HECTOR & DAVIS LLP 215 S. Monroe St., Suite 601 Tallahassee, FL 32301-1804

Attorneys for Florida Power & Light Company

By: Karles A Hugers
Charles A. Guyton

CERTIFICATE OF SERVICE

I HEREBY CERTIFY that a true and correct copy of the Petition Of Florida Power & Light Company To Extend Its BuildSmart™ Pilot Program was mailed this 30th day of October, 1996 to the following:

Jack Shreve, Esquire John Roger Howe, Esquire. Office of Public Counsel 111 West Madison Street Room 812 Tallahassee, Florida 32399

Charles A. Guston

APPENDIX A RESIDENTIAL NEW CONSTRUCTION . BUILDSMART^{IM} PROGRAM STANDARDS



Residential New Construction BuildSmart Program Standards

CONTENTS

		Page
Program Objective		1
Utility's Requirements for Program Participation by Builders		1
Details on How BuildSmart Homes will be Submitted by Builders		2
FPL Inspection Process		2
Technical Specifications		3
Exhibits:		
A. BuildSmart Notification Form		4
B. Energy Performance Index (EPI)		5
C. HVAC Manual J Load Calculations	7	6
D. BuildSmart Certificate		7
E. FPL BuildSmart Residential Offices		8
F FPI BuildSmart Service Territory		0

Program Objective

The objective of the BuildSmart Program is to encourage energy conservation through the building of energy efficient residential new construction. The purpose of these standards is to instruct builders in the FPL BuildSmart process.

Utility's Requirements for Program Participation by Builders

- Each participating builder must enter into a BuildSmart Program Contract with FPL covering the time period and territory served by the participating builder. The contract must be signed by the general building contractor.
- Builders must comply with all national, state and local codes and ordinances.
- The BuildSmart Program applies only to residential single-family detached dwellings.
- Dwellings must be serviced by FPL and located within the BuildSmart service territory (see Exhibit F).
- All eligible BuildSmart homes must be completed on or after January 1, 1994.
- The dwelling must have whole house cooling which may be supplied by a central cooling system or by a combination of individual room units.
- Builders shall provide the following data for each home to be certified in the program:
 - BuildSmart Notification Form {See Exhibit A}
 - Energy Performance Index (EPI) {See Exhibit B}
 - HVAC Manual J Load Calculations (See Exhibit C)
 - Floor and Elevation Plans
- The builder shall correct any deficiency with the inspection as identified by FPL prior to BuildSmart certification of the home.
- FPL reserves the right to verify each installation for which a BuildSmart Notification Form has been submitted.
- FPL will be the final judge of whether the requirements of the BuildSmart Program have been met.
- FPL reserves the right to modify or terminate these program standards and procedures for this program at any time with ten (10) days written notice to the participating FPL BuildSmart builders.

Details on How BuildSmart homes Will Be Processed by Builders

- Builder will submit to FPL for each home:
 - BuildSmart Notification Form,
 - Energy Performance Index(EPI),
 - HVAC Manual J Load Calculations, and
 - Floor and Elevation Plans.
- 2. Builder will notify FPL to perform Mid-point Inspection.
 - Prior to drywall,
 - After air conditioning duct work is installed, and
 - Prior to ceiling insulation if possible.
- Builder will notify FPL to perform Final Inspection immediately prior to certificate
 of occupancy. Once homes have passed the Final Inspection, builders will be
 awarded the appropriate BuildSmart Certificate and Medallion.

FPL Inspection Process

Initial FPL Inspection:

- Review EPI Calculation
- Review Manual J Load Calculation
- Review Floor and Elevation Plans

Mid-point FPL Inspection:

- Duct Air Tightness Testing
- Air, Moisture and Thermal Barriers
- Glass, Floor and Wall Area and Orientation
- Framing and Overhang

Final FPL Inspection:

- Infiltration Practice
- Mechanical Equipment Verification Heating System Cooling System Hot Water System
- HVAC Credits
- Hot Water Credits
- EPI Verification
- Manual J Verification

Technical Specifications of Eligibility

- Builder will comply with all national, state and local codes pertaining to residential new construction.
- Houses submitted as BuildSmart will achieve an EPI of 90 or below and will fall under three levels:

BuildSmart Level	Description
Bronze	90-81 EPI
Silver	80-71 EPI
Gold	70 or below EPI

 HVAC Manual J load calculations will comply with all national, state and local codes pertaining to the installation and operation of HVAC equipment.

Exhibit A

BuildSmart Notification Form

BuildSmarfTM Notification Form Program Specialist

	pany Name	Phone number:	ax number:
	ng Address: street		zip
		Contact person:	
Hou	se Information;		
Street	address	Subdivision:	City:
		Customer name:	
n Cu	stom Home D Model Home Mode	el home name	
Gold	Silver	Bronze EPI	
۵	Initial notification date	ections as Easy as 1-2-3	
۵	Initial notification date EPI form attached, Faxed		ched)
۵	Initial notification date EPI form attached, Faxed	or Mailed	ched)
٥	Initial notification date EPI form attached, Faxed HVAC Manual J Load cal	or Mailed culation - ACCA 7th edition (attached)	ched)
	Initial notification date □ EPI form attached, Faxed □ HVAC Manual J Load cal □ Floor & Elevation Plans (a)	or Mailed culation - ACCA 7th edition (attached)	ched)
	Initial notification date EPI form attached, Faxed HVAC Manual J Load cal Floor & Elevation Plans (a) Midpoint notification of	or Mailed culation - ACCA 7th edition (attached)	ched)
	Initial notification date EPI form attached, Faxed HVAC Manual J Load cal Floor & Elevation Plans (a) Midpoint notification of	or Mailed culation - ACCA 7th edition (attacked)	ched)

Exhibit B

Energy Performance Index (EPI)

Single family detached or Multifamily attached if Multifamily—No. of units covered by this submission if Multifamily, is this a worst case (yes / no) Conditioned floor area (sq. ft.) Predominant eave overhang (ft.) Glass area and type: a. Clear glass b. Tint, film or solar screen Ploor type and Insulation: a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value) Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 4. Log (Insulation R-value) Ceiling type area and insulation: a. Under attic (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler (Insulation + Location) Cooling system	
New construction or addition Single family detached or Multifamily attached If Multifamily—No. of units covered by this submission If Multifamily, is this a worst case (yes / no) Conditioned floor area (sq. ft.) Predominant eave overhang (ft.) Porch overhang length (ft.) Glass area and type: a. Clear glass b. Tint, film or solar screen Floor type and insulation: a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value + sq. ft.) c. Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 5. Steel (Insulation R-value) 4. Log (Insulation R-value) 4. Log (Insulation R-value) 4. Log (Insulation R-value) 4. Log (Insulation R-value) 5. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler (Insulation + Location) cooling system	Please Print 1. 2. 3. 4. 5. 6. 7. 5. 6. 7. 5. 5. 6. 7. 5. 6. 5. 6. 5. 6. 5. 6. 5. 6. 5. 6. 5. 6. 5. 6. 5. 6. 5. 6. 5. 6. 5. 6. 5. 6. 5. 6. 5. 6. 6
b. Tint, film or solar screen Floor type and Insulation: a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value + sq. ft.) c. Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) 5. Steel (Insulation R-value) 6. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler (Insulation + Location) Cooling system	1. 2. 3. 4. 5. 6. 7. Single Pane Double Pane 8a. sq. ft. sq. ft. 6b. sq. ft. sq. ft. 9c. Rs 1 sq. ft. 9c. Rs 1 sq. ft. 10a-1 Rs 1 sq. ft. 10a-2 Rs 1 sq. ft. 10a-4 Rs 1 sq. ft. 10b-2 Rs
Single family detached or Multifamily attached if Multifamily.—No. of units covered by this submission if Multifamily, is this a worst case (yes / no) Conditioned floor area (sq. ft.) Predominant eave overhang (ft.) Glass area and type: a. Clear glass b. Tint, film or solar screen Floor type and Insulation: a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value + sq. ft.) c. Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 5. Adjacent: 1. Concrete (Insulation R-value) 4. Log (Insulation R-value) 4. Log (Insulation R-value) 6. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler (Insulation + Location) cooling system	3
## Multifamily—No. of units covered by this submission ## Multifamily, is this a worst case (yes / no) Conditioned floor area (sq. ft.) Predominant eave overhang (ft.) Predominant eave overhang (ft.) Porch overhang length (ft.) Glass area and type: a. Clear glass b. Tint, film or solar screen Floor type and Insulation: a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steet (Insulation R-value) 4. Log (Insulation R-value) b. Adjacent: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 6. Siegle assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler (Insulation + Location) Cooling system	3
If Multifamily, is this a worst case (yes / no) Conditioned floor area (sq. ft.) Predominant eave overhang (ft.) Porch overhang length (ft.) Glass area and type: a. Clear glass b. Tint, film or solar screen Floor type and insulation: a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value + sq. ft.) c. Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) b. Adjacent: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 5. Steel (Insulation R-value) 4. Log (Insulation R-value) 6. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler (Insulation + Location) Cooling system	4
Conditioned floor area (sq. ft.) Predominant eave overhang (ft.) Porch overhang length (ft.) Glass area and type: a. Clear glass b. Tint, film or solar screen Floor type and insulation: a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value + sq. ft.) c. Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) 4. Log (Insulation R-value) 5. Single assembly (Insulation R-value) 6. Single assembly (Insulation R-value) 8. Air Handler (Insulation + Location) 8. Air Handler (Insulation + Location) 8. Cooling system	5
Predominant eave overhang (it.) Porch overhang length (it.) Glass area and type: a. Clear glass b. Tint, film or solar screen Floor type and insulation: a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value + sq. ft.) c. Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 5. Adjacent: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 5. Steel (Insulation R-value) 6. Log (Insulation R-value) 7. Log (Insulation R-value) 8. Log (Insulation R-value) 9. Single assembly (Insulation R-value) 8. Single assembly (Insulation R-value) 8. Air Handler (Insulation + Location) 8. Air Handler (Insulation + Location) 8. Cooling system	6
Porch overhang length (ft.) Glass area and type: a. Clear glass b. Tint, film or solar screen Floor type and Insulation: a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value + sq. ft.) c. Concrete, raised (R-value) Net Watt type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 5. Adjacent: 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 6. Adjacent: 6. Concrete (Insulation R-value) 7. Steel (Insulation R-value) 8. Log (Insulation R-value) 9. Log (Insulation R-value) 9. Single assembly (Insulation R-value) 1. Single assembly (Insulation R-value) 1. Air Handler (Insulation + Location) 1. Cooling system 1. Clear of the system of the	7. Single Pane Double Pane 8a. sq. ft. sq. ft. sq. ft. 8b. sq. ft. sq. ft. 9a. R=
Glass area and type: a. Clear glass b. Tint, film or solar screen Floor type and Insulation: a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value + sq. ft.) c. Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 5. Adjacent: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 5. Steel (Insulation R-value) 6. Log (Insulation R-value) 7. Log (Insulation R-value) 8. Log (Insulation R-value) 9. Single assembly (Insulation R-value) 8. Single assembly (Insulation R-value) 8. Air Handler (Insulation + Location) 8. Air Handler (Insulation + Location) 8. Cooling system	Single Pane Double Pane 8asq. ftsq. ft. 8bsq. ftsq. ft. 9a. R=l. ft. 9b. R=sq. ft. 9c. R=sq. ft. 10a-1 R=sq. ft. 10a-2 R=sq. ft. 10a-3 R=sq. ft. 10a-4 R=sq. ft. 10b-1 R=sq. ft. 10b-1 R=sq. ft. 10b-2 R=sq. ft.
a. Clear glass b. Tint, film or solar screen Floor type and insulation: a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value) c. Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) b. Adjacent: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) 6. Log (Insulation R-value) 7. Log (Insulation R-value) 8. Log (Insulation R-value) 9. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler (Insulation + Location) Cooling system	8a
b. Tint, film or solar screen Floor type and insulation: a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value) c. Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) 4. Log (Insulation R-value) 5. Steel (Insulation R-value) 6. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler (Insulation + Location) cooling system	8bsq. ftsq. ft
Floor type and Insulation: a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value + sq. ft.) c. Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) b. Adjacent: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 5. Steef (Insulation R-value) 4. Log (Insulation R-value) 5. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler (Insulation + Location) Cooling system	9a. Rs
a. Slab on grade (R-value + perimeter) b. Wood, raised (R-value + sq. ft.) c. Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 5. Adjacent: 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) 6. Adjacent: 6. Wood frame (Insulation R-value) 7. Steel (Insulation R-value) 8. Log (Insulation R-value) 9. Log (Insulation R-value) 9. Single assembly (Insulation R-value) Air distribution systems 9. Ducts (Insulation + Location) 10. Air Handler (Insulation + Location) 10. Cooling system	90. R=
b. Wood, raised (R-value + sq. ft.) c. Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steet (Insulation R-value) 4. Log (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steet (Insulation R-value) 4. Log (Insulation R-value) 5. Steet (Insulation R-value) 6. Single assembly (Insulation R-value) Alr distribution systems a. Ducts (Insulation + Location) b. Air Handler (Insulation + Location) cooling system	90. R=
c. Concrete, raised (R-value) Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 4. Log (Insulation R-value) b. Adjacent: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steet (Insulation R-value) 4. Log (Insulation R-value) 5. Log (Insulation R-value) Ceiling type area and Insulation: a. Under stic (Insulation R-value) b. Single assembly (Insulation R-value) Alr distribution systems a. Ducts (Insulation + Location)	9c. Rm
Net Wall type area and insulation: a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) 5. Wood frame (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) 5. Single assembly (Insulation R-value) 6. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler (Insulation + Location) Cooling system	10a-1 Ra
a. Exterior: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) 5. Adjacent: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) 5. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler (Insulation + Location) Cooling system	10a-2 Ra sq.ft. 10a-3 Ra sq.ft. 10a-4 Ra sq.ft. 10b-1 Ra sq.ft. 10b-2 Ra sq.ft.
2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) b. Adjacent: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) 6. Log (Insulation R-value) 5. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler (Insulation + Location) Cooling system	10a-2 Ra sq.ft. 10a-3 Ra sq.ft. 10a-4 Ra sq.ft. 10b-1 Ra sq.ft. 10b-2 Ra sq.ft.
3. Steel (Insulation R-value) 4. Log (Insulation R-value) 5. Adjacent: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) 5. Log (Insulation R-value) 6. Single assembly (Insulation R-value) 7. Air distribution systems 7. Ducts (Insulation + Location) 7. Location 7. Location 8. Air Handler (Insulation + Location) 8. Cooling system	10a-3 Rm sq. ft. 10a-4 Rs sq. ft. 10b-1 Rs sq. ft. 10b-2 Rs sq. ft.
4. Log (Insulation R-value) b. Adjacent: 1. Concrete (Insulation R-value) 2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) Ceiling type area and Insulation: a. Under attic (Insulation R-value) b. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler(Insulation + Location) Cooling system	10a-4 Rs sq. ft. 10b-1 Rs sq. ft. 10b-2 Rs sq. ft.
2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) Ceiling type area and insulation: a. Under attic (Insulation R-value) b. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler(Insulation + Location) Cooling system	100-1 Resq.ft 100-2 Resq.ft
2. Wood frame (Insulation R-value) 3. Steel (Insulation R-value) 4. Log (Insulation R-value) Ceiling type area and insulation: a. Under attic (Insulation R-value) b. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler(Insulation + Location) Cooling system	10b-2 Re
3. Steel (Insulation R-value) 4. Log (Insulation R-value) Ceiling type area and insulation: a. Under attic (Insulation R-value) b. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler(Insulation + Location) Cooling system	10b-2 Re
4. Log (Insulation R-value) Ceiling type area and insulation: a. Under attic (Insulation R-value) b. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler(Insulation + Location) Cooling system	
Ceiling type area and Insulation: a. Under attic (Insulation R-value) b. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler(Insulation + Location) Cooling system	10b-3 R= sq. ft.
a. Under attic (Insulation R-value) b. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler(Insulation + Location) Cooling system	10b-4 R=sq. ft
b. Single assembly (Insulation R-value) Air distribution systems a. Ducts (Insulation + Location) b. Air Handler(Insulation + Location) Cooling system	
Air distribution systems a. Ducts (Insulation + Location) b. Air Handler(Insulation + Location) Cooling system	11a. Resq. ft
a. Ducts (Insulation + Location) b. Air Handler(Insulation + Location) Cooling system	11b. Resq.ft
b. Air Handler(Insulation + Location) Cooling system	
Cooling system	12a. Re sentant:
	12b. Rs
	13. Type:
	SEER/EER/COP:
leating system:	14. Type:
Types: heat pump, elec. strip, nat. gas, L.P. gas, room or PTAC, none)	HSPF/COP/AFUE:
fot water system:	15. Type:
Types: elec., natural gas, solar, L.P. gas, none)	EF:
lot Water Credits:	
a. Heat Recovery (HR)	16a.
b. Dedicated Heat Pump(DHP)	16a.
filtration practice: 1, 2 or 3	17.
VAC Credits (Type in Letter designation: CF-Celling Fan, CV-Cross went,	18.
HF-Whole house fan, RB-Atic radiant berrier, MZ-Multizone)	A STATE OF THE STA
PI (must not exceed 100 points)	19
a. Total As-Built points	19a.
b. Total Base points	19b.
y confly that the phone and apsolfications consend by the calculation are in complexes with the Review Swap Code.	of plans and specifications specimel by the collectation indicates completenes with the Energy Corts. Enters completelies is conspicted. It is helding will be improved

Exhibit C

HVAC Manual J load calculation

Load Calculations For Residential Air Conditioning Based On ACCA Manual J 7th Edition

	The state of the s	FFL Job No.	
CityLot			
Prepared By	He lewesters	Telephone (),	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		sign Conditions Summer	
Outside db Winter Design Ten	*F Inside db 70 nperature Difference		ference+*F
	He	ating Summary	
Design Heating Los (Total Heat Loss fo	d Requirements = r Entire House)		Btuh
	Co	oling Summary	
Total Latent Gain +	at =	Btuh	

BALANCE POINT CALCULATION FOR HEAT PUMP




Exhibit D

BuildSmart Certificate



FPL's program for energy-efficient home construction



THIS CERTIFIES THAT THE HOME AT

IS APPROVED BY FLORIDA POWER & LIGHT COMPANY AS A BUILDSMART GOLD HOME. THIS HOME EXCEEDS THE STATE OF FLORIDA'S MINIMUM ENERGY CODE REQUIREMENTS. BENEFITTING THE HOMEOWNER AND ALL FLORIDIANS THROUGH LOWER ENERGY USE AND CONSERVATION OF NATURAL RESOURCES

Builder Representative Date

FPL BuildSmart Representative

Dat

Exhibit E

FPL BuildSmart Residential Offices

Charlotte County: 272 E. Virginia Ave. Punta Gorda, FL 33951 (813)637-5570

Lee/Hendry/Glades Counties: 1926 Victoria Ave. Ft. Myers, FL 33902 (813)332-9102

Collier/Lee Counties: 955 10 Ave N Naples, FL 33940 (813)434-1295

Exhibit F

FPL BuildSmart Service Territory



APPENDIX B BUILDSMART™ PARTICIPATING BUILDER LISTING AND HOME CERTIFICATION HISTORY

Builder/Company Name	Address	Phone #		vice	
			CHA	COL	LEE
3N Group, Inc.	2900 14th Street N., Suite #10 Naples, FL 33940	(941) 261-2220	X	X	Х
A. Lynn Titus General Contractor	4710 West Blvd. Naples, FL 33940	(941) 649-1274		X	X
Anthony Fiore Construction, Inc.	168 W Dearborn St Englewood, FL. 34223	(941) 474-2421	X	Ē	
Architectual Builders of Southwest Florida, Inc.	4739 Riverside Drive Estero, FL. 33928	(941) 495-8998		X	X
Bay Builders of Bonita Springs, Inc.	P.O. Box 1103 Bonita Springs, FL. 33959	(941) 947-2555		X	X
Borelli Construction Corporation	P.O. Box 8211 Naples, FL 33941	(941) 263-7900		X	X
Boardwalk Properties	2541 Englewood Rd Englewood,FL 34223	(941) 475-1168	X		
C.N.A. Home Development, Inc.	4357 SE Highway 31 Arcadia, FL 33821	(941) 993-9791	X		
Britannia Construction, Inc.	P.O. Box 2402 Port Charlotte, FL. 33949	(941) 743-4356	X		
Cali & Associates	P.O. Box 7213 Naples, FL. 33941	(941) 455-3478		X	
Celico Custom Builders	1312 Market Circle, #2 Port Charlotte, FL. 33953	(941) 255-1340	X		
Cherokee Development Corp.	3867 Midshore Drive Naples, FL 33999	(941) 598-3222		X	
Combs Homes, Inc.	10 Sportsman Terrace Rotonda West, FL 33947	(941) 697-6854	X		
Construction Professionals of Southwest Florida, Inc.	7380 Stonegate Dr. Naples, FL. 33942	(941) 591-0617		X	X
Coral Harbor Enterprises, Inc	1601 W Marion Ave Punta Gorda, FL. 33950	(941) 639-2132	X		
Daniel Wayne Hornes, Inc.	P.O. Box 08370 Ft. Myers, FL. 33908	(941) 466-3955			X
D. B. Temple Homes, Inc.	2253 Cameron Ln. Sarasota, FL. 34231	(941) 924-1666	X		
DeAngelis Custom Builders, Inc.	P.O. Box 8036 Naples, FL. 33941	(941) 643-5549		X	X
Deer Run Associates, "Deer Lake"	6900-27 Daniels Parkway Suite 131 Ft. Myers, FL. 33912	(941) 768-6166			X
DeFlavis Construction	2265 Golden Gate Blvd. Naples, FL. 33964	(941) 352-7117		X	X
Distictive Homes of Southwest Florida, Inc.	P. O. Box 7668 Naples, FL. 33941	(941) 643-5739		X	X
Don Ewy Construction	8005 Vera Cruz Way Naples, FL. 33942	(941) 591-3958		X	X
Empire Builders	6000 Taylor Road, Suite One Naples, FL. 33942	(941) 566-3204		X	X

Builder/Company Name	Address	Phone #	Sen	vice	Area
			CHA	COL	LEE
Fero Construction Inc.	18320 Paulson Drive #B Port Charlotte, FL. 33954	(941) 743-3376	X		
Five Star General Contracting, Inc.	1203 West Marion Avenue Punta Gorda, FL. 33950	(941) 637-7848	X		
Frank Adkins Builder, Inc.	12376 Eagle Court Estero, FL. 33928	(941) 992-4555		Х	X
Frank Kirby Building Contractor	670 13th Street NW Naples, FL. 33964	(941) 455-4372		Х	
George Tuman Construction, Inc.	P.O. Box 380605 Murdock, FL 33938	(941) 627-8011	X		
Gordon R Derrington	2030 Padre Island Dr Punta Gorda, FL. 33950	(941) 637-3977	X		
Gulf Coast Homes of Lee County, Inc.	11934 Fairway Lakes Drive, Suite 1 Fort Myers, FL. 33913	(941) 561-2400			X
Gulfshore Construction, Inc.	4055 Tamiami Trall #5 Port Charlotte, FL 33952	(941) 625-1233	X		
Hallmark Custom Builders, Inc.	P.O. Box 7676 North Port, FL 34287	(941) 625-9796	X		
HandCrafted Homes, Inc.	11920 Fairway Lakes Drive, Suite 2 Fort Myers, FL. 33913	(941) 561-2255		X	X
Holiday Builders, Inc.	1517 SE 16th Place Cape Coral, FL 33990	(941) 772-700			X
Holiday Builders, Inc.	675 Tamiami Tr # 6 Port Charlotte, FL 33953	(941) 764-1584	X		X
Inter Building Marketing	505 5th Avenue S, Suite E	(941) 434-6648		X	
Willkomm & Willkomm	Naples, FL. 33940		-		
Imperial Homes of Naples, Inc.	868 99th Avenue North Naples, FL. 33963	(941) 597-1316		X	X
J L Cooper Inc. Builders	P.O. Box 7712 North Port, FL. 34287	(941) 426-0671	X		
John F. Soave, Inc.	2403 Trade Center Way, #4 Naples, FL. 33942	(941) 591-1116		Х	X
Kalavitis Construction, Inc.	1154 8th Avenue North Naples, FL. 33940	(941) 262-8375		X	
Leo L. Willette Construction	4837 Tarpon Avenue Bonita Springs, FL. 33923	(941) 992-4485	_	X	X
Malle Homes, Inc.	2200 Blackwood Drive Venice, FL. 34293	(941) 497-1197	X		
Marvin Development Corp.	954 Country Club Blvd. Cape Coral, FL. 33990	(941) 574-4566 (941) 352-1634	X	Х	X
Masada Homes, Inc.	929 Tamiami Tr #A Port Charlotte, FL 33953	(941) 625-9065	X		
Masterbuilders Construction	909-A Tamiami Trail Port Charlotte, FL. 33953	(941) 629-4065	X		
McCandless Homes, Inc.	21202 Olean Blvd, #C4 Port Charlotte, FL. 33952	(941) 629-0292	X		

Builder/Company Name	Address	Phone #	Sen	vice i	Area
			CHA	COL	LEE
Meridian Construction & Development	4460-2 Camino Real Way Ft. Myers, FL. 33912	(941) 936-3005			X
Metropolitan Building Concepts, Inc.	P.O. Box 37 Cape Coral, FL. 33910	(941) 945-1170			X
Monk Custom Homes, Inc.	2381 21st Street SW Naples, FL. 33964	(941) 455-1260		х	
Monopoly Builders, Inc.	1924 SE 13th St Cape Coral, FL 33990	(941) 772-2743			X
Moonlake Development	5026 Eclipse Ct. Naples, FL 33942	(941) 643-2227		Х	X
NCD , Inc.	1601 Jackson St. #202 Ft. Myers, FL 33901	(941) 334-0999	M.	X	X
Novello Building Co, Inc.	6893 Mill Run Circle Naples, FL. 33942	(941) 566-3067		X	Х
Oakhurst Homes	P.O. Box 1016 Murdock, FL. 33938-1016	(941) 743-8212	X		
Oakwood Builders	P.O. Box 1603 Naples, FL. 33939	(941) 643-7918		X	
Panther Homes, Inc.	12131 Summergate Cir #204 Ft. Myers, FL. 33913	(941) 561-2909			X
Paradise Homes of Naples, Inc.	10681 Regent Circle Naples, FL. 33942	(941) 566-3815		Х	
Paragon General Contracting, Inc.	5007 Tamiami Trail E. Naples, FL. 33962	(941) 793-7900		X	
Pax Quality Construction	5835 Sunnyside Lane Ft. Myers, FL. 33919	(941) 433-4899		X	X
Prestige Homes	109 E Olympia Ave Punta Gorda, FL 33950	(941) 637-9387	X		
Rainbow Homes	1490 Alamander Avenue Englewood, FL. 34223	(941) 474-5901	X		
RCE Contractors, Inc.	3884 Progress Avenue Naples, FL. 33964	(941) 643-5758		Х	X
Rich Larkin Construction, Inc.	3469 1st Avenue St. James City, FL 33956	(941) 283-4871		Х	
Richardson Homes, Inc	16501 Arbor Ridge Drive Ft. Myers, FL. 33908	(941) 466-1218			X
Royal Palm Custom Homes	4750 N. Tamiami Trail #1 Naples, FL. 33940	(941) 435-0550		X	X
Ryan Construction Co.	789 Wedge Drive Naples, FL. 33940	(941) 649-5704		X	Х
Sheene Construction, Inc.	P.O. Box 1685 Punt Gorda, FL 33951-1685	(941) 637-8070	X		
Signature Homes of Murdock, Inc.	P.O. Box 668 Murdock, FL. 33938	(941) 625-5577	х		
Snell Construction	9853 Tamiami Trail N., Suite 201 Naples, FL. 33963	(941) 591-3407		X	X

Builder/Company Name	Address	Phone #	Sen	vice	Area
	Marcon Carlo meneral a		CHA	COL	TLEE
Snider Custom Homes, Inc.	269 Rosemary Street Port Charlotte, FL 33948	(941) 637-1976	X		
Stephen Smith Builder, Inc.	187 10th Avenue S. Naples, FL. 33940	(941) 262-0079		X	
Southwest Construction of Florida, Inc.	525 E Olympia Ave #1 Punt Gorda, FL 33950	(941) 575-2800	X		
Sugar Spring Building Contractors, Inc.	12231 Oak Brook Court Ft. Myers, FL. 33908	(941) 466-5508			X
Sun Country Homes	P.O. Box 2706	(941) 627-4457	X		
of Charlotte County, Inc.	Port Charlotte, FL 33949-2706	W			
Sunrise Construction	2041 Golden Gate Blvd. Naples, FL. 33964	(941) 455-1112		X	
Sunwest Homes	9853 N. Tamiami Trail Naples, FL 33963	(941) 566-8158		X	
Taylor Contractors	315 E. Olympia Avenue Punta Gorda, FL. 33950	(941) 637-6400	X		
Tharpe Construction, Inc.	8695 College Pkwy #318 Ft. Myers, FL 33919	(941) 433-3123			X
The Anchor Group, Inc.	15630 McGregor Blvd. #102 Fort Myers, FL. 33908	(941) 433-1881	X	Х	Х
The Michaels Group	12220-45 Town Lake Dr Ft. Myers, FL 33913	(941) 561-1212		X	X
Thomas Galt, Inc.	2700 Evans Ave #3 Fort Myers, FL. 33901	(941) 337-1339			X
Tim Towles Custom Homes	2825 Tamiami Trail #B4 Punta Gorda, FL. 33950	(941) 575-1515	X		
Titan Real Estate Enterprises, Inc.	P.O. Box 8725 Naples, FL. 33941	(941) 435-0301		Х	X
Tracey Construction, Inc.	P.O. Box 1097 Cape Coral, FL. 33910	(941) 574-4900		Х	X
US Home	10891 Six Mile Cypress Ft. Myers, FL. 33912	(941) 278-1199			X
US Home	10100-B Vailwood Naples, FL. 33999	(941) 591-2098		X	
Vision Builders of Southwest Florida, Inc.	2219 Cape Coral Pkwy. Cape Coral, FL. 33904	(941) 542-7372			X
Walker Brothers Construction, Inc.	2171 Oaks Blvd. Naples, FL. 33999	(941) 597-8288		х	X
Warren Hope Builder, Inc.	3861 S. McCall Road Englewood, FL. 34224	(941) 474-1532	X		
Wedgewood Homes, Inc.	1242 Market Circle Port Charlotte, FL 33953	(941) 629-8527	X		
West Coast Builders	1009 Presque Isle Blvd. Port Charlotte, FL. 33954	(941) 629-3999	X		X
Wheat Homes	775 Tamiami Trail Port Charlotte, FL. 33953	(941) 255-3070	X		

Builder/Company Name	Address	Phone #	Service Area		
			CHA	COL	LEE
William Fruecht, Inc. Custom Homes	5415 Jaegar Rd., Unit A Naples, FL. 33942	(941) 594-1100		X	
Woodhaven Construction	416 Mahon Drive Venice, FL 34285	(941) 488-9191	X		
Yorktowne Homes, Inc.	1720 El Jobean Road #108 Port Charlotte, FL 33948	(941) 627-5020	Х		

BuildSmart Program Participation 1994-1996 Cumulative Efficiency Level

