

ORIGINAL

Kay Flynn

CMP _____
COM _____
CTR _____
ECR _____
GCL _____
OPC _____
RCA _____
SCR _____
SGA _____
SEC 1

From: Kay Flynn
Sent: Monday, December 18, 2006 10:45 AM
To: Hong Wang; Blanca Bayo; Rose Thompson
Subject: FW: Oral Modification Request to Item 7 on December 19, 2006 Agenda

No change is needed to the vote sheets or minutes.

I am printing this for the docket file.

Kay

From: Mary Bane
Sent: Monday, December 18, 2006 10:44 AM
To: Mary Bane; Lisa Bennett
Cc: Mary Anne Helton; Michael Cooke; Connie Kummer; John Plescow; Betty Ashby; Chuck Hill; Diane Lee; Edward Mills; Roberta Bass; Cayce Hinton; Manuel Arisso; William C. Garner; Jeremy Susac; Kay Flynn; Hong Wang
Subject: RE: Oral Modification Request to Item 7 on December 19, 2006 Agenda

OTH BB, LF, HW, RT

Approved.

From: Mary Bane
Sent: Monday, December 18, 2006 10:44 AM
To: Lisa Bennett
Cc: Mary Anne Helton; Michael Cooke; Connie Kummer; John Plescow; Betty Ashby; Chuck Hill; Diane Lee; Edward Mills; Roberta Bass; Cayce Hinton; Manuel Arisso; William C. Garner; Jeremy Susac; Kay Flynn; Hong Wang
Subject: RE: Oral Modification Request to Item 7 on December 19, 2006 Agenda

From: Lisa Bennett
Sent: Monday, December 18, 2006 9:35 AM
To: Mary Bane
Cc: Mary Anne Helton; Michael Cooke; Connie Kummer; John Plescow; Betty Ashby; Chuck Hill; Diane Lee; Edward Mills
Subject: Oral Modification Request to Item 7 on December 19, 2006 Agenda

Staff is requesting that we be permitted to make a modification to Item 7 on tomorrow's agenda. Item 7 is Docket No. 060488-EI, Complaint No. 665167E of Streamline Hotel. The change would appear on lines 1, 2 and 3 of the first full paragraph on page 6 of the recommendation. The purpose of the change is to clarify the conclusion and make it consistent with the recommendation. The change, in legislative format, would read as follows:

Conclusion

Based on the analysis above, staff recommends that the Commission find that the point of delivery for the Streamline Hotel ~~begin~~ is at the weatherhead, owned by the property owner. The customer's responsibility begins at the weatherhead and continues through wires connected to the current transformers from the weatherhead. The utility is responsible for the actual current transformers and any wiring connecting them to the meter. The customer's responsibility resumes where the wires exit the current transformers to connect to the load center. Staff recommends that the Commission find that FPL has not violated any tariff or commission rule as it relates to the complaint filed by customer Eric Doyle as owner of Streamline Hotel.

DOCUMENT NUMBER DATE

11515 DEC 18 8

*Please let me know if you have any questions or concerns regarding this modification.

Lisa Bennett
Office of the General Counsel
850-413-6230