CORRESPONDENCE 10/17/2017 DOCUMENT NO. 08862-201

Review of Electric Utility Hurricane Preparedness and Restoration Actions

Docket No : 20170215-EU

Name: David Coley

Electric Utility Provider: FPL

Zip Code: 34237

Category: Power restoration time

Comments: I am not dissatisfied with the amount of time it took to restore power, which was 5 days. I am very dissapointed with the lack of underground utilities in my heavily treed neighborhood. The overhead grid is dated - it is the same grid put in place in the 1950s! It is extremely vulnerable to limb fall from even minor storm events. Property values dictate that we need the same consideration as new subdivisions, that FPL begin retrofitting our neighborhoods for underground service.