

FILED 5/31/2024 DOCUMENT NO. 04430-2024 FPSC - COMMISSION CLERK

1919 McKinney Avenue, Dallas, TX 75201 Frontier.com

May 31, 2024

VIA E-FILING

Adam J. Teitzman Commission Clerk Florida Public Service Commission 2540 Shumard Oak Blvd Tallahassee, FL 32399

Re: 25-18.020 Pole Safety, Inspection, Maintenance, and Vegetation Management.

Dear Mr. Teitzman,

Pursuant to the Commission's rules, 25-18.020 of the Florida Administrative Code, Frontier Florida, LLC and Frontier Communications of the South, LLC ("Frontier") is providing this 2024 annual report.

To ensure the safety of its Florida operating facilities, during 2023, Frontier replaced 201 poles due to damage or safety issues. To further refine its facilities program, 2024 Frontier engaged a third-party contractor, Osmose Utilities Services, Inc., to oversee inspections of all Frontier utility poles in the state of Florida over the next two years.

Under the contractor agreement, Osmose will inspect 11,250 poles each year with a minimum of 2,813 poles inspected each quarter.

Frontier's program coordinator will work closely with Osmose to identify inspection locations, monitor inspection status and perform routine quality inspections. Osmose will perform inspections of Frontier's communication facilities in accordance with industry standards and identify National Electrical Safety Code (NESC) violations as appropriate. More specifically, this includes documenting visual and physical measurements, identifying primary and secondary power attachments, conducting Intrusive Inspections, placing FRONTIER ownership tags not otherwise identified, fixing minor infractions (pole tag kit, guy guards, visibility strips, ground moldings), removal of foreign attachments (ex: yard sale and lost pet signs) and inspecting for hazardous vegetative conditions.

For documentation purposes, Osmose will photograph each pole, verify the pole GPS coordinates, and submit inspection records in Frontier's facilities tracking systems.

Frontier's vegetation management program leverages Osmose conducted inspections, the vendor pole transfer process and Frontier conducted inspections. During 2023, Frontier vendors assessed vegetation for hazardous conditions in conjunction with 4,270 pole transfers. Vegetation was cleared from pole areas where appropriate. Additionally, Frontier operations conducted vegetation management inspections along 26 miles of designated Hillsborough County, Pasco County and Polk County locations.



The following identifies the pole inspection results as of May 25, 2024.

2024	Results
i. Number of poles with public utility electrical facilities the CSP owned in whole or in part at the beginning and end of the calendar year	94,209 total poles
	23,291 with power
ii. Number of poles that were scheduled for inspection	10,181
iii.The number of poles that were actually inspected	1,504 as of 5/25/2024
	623 with power
iv. The number of poles that failed inspection	626
	315 with power
v. The number of poles strength tested and the methods used to ensure compliance with NESC strength requirements	623 with power
	(resi-drill)
vi. The number of poles that failed strength testing	315 with power
vii. The number of poles repaired and a summary of the repairs	559
	270 with power
viii. The number of poles replaced and the reason for replacement	67
	45 with power
	45 failed strength testing; 22 damage or safety issues (pending replacement)
ix. The total miles of vegetation management performed	2023 Vendor inspected vegetation in conjunction with 4, 270 pole transfers. Additionally, Frontier inspected 26 miles for vegetation impact.
2025	
i. The number of poles to be inspected;	12,099
ii. The total miles of vegetation management to be conducted	Osmose will incorporate vegetation management as part of 12,099 pole inspections.



Should you have any questions regarding this submission, please do not hesitate to contact me at judy.geise@ftr.com or (214) 724-7719.

Respectfully submitted,

July Geise

Manager, Regulatory (214) 724-7719 judy.geise@ftr.com