



DEPARTMENT OF ENVIRONMENTAL PROTECTION
C e n t r a l D i s t r i c t

Drinking Water Program

MALFUNCTION OR **INCIDENT REPORT**

407/893-3318 OR 3988; 894-7555, EXT. 2243

FAX: 407/893-4418; E-FAX: 407.897.4189

Date: 5/20/15

Time: 13:25

Received By: Jason Seyfert

Reported By: Scott Gosnell

Business Name: Sanlando Utilities Corporation

Name of Plant/System: Wekiva Hunt Club

PWS ID Number: 3591121

Address: 144 Ledbury Dr. Longwood, FL. 32779

System Phone: 407-869-1919

County: Seminole

Owner: Sanlando Utilities Corporation

Contact Person: Scott Gosnell

Phone #: 407-682-5651

Failure

Planned Outage

Date: 5/20/15

Time: 10:00

Expected to be (or was) back in service:

Date: 5/20/15

Time: 11:45

Location of Trouble (address): 301 Sweetwater Cove Blvd. Longwood, FL. 32779

Statement of Trouble (check as many as necessary to explain incident):

- Water main breaks Pressure greater than 20-psi pressure drop below 20 psi. Outage (no water to customers) Service line break tie in (no pressure drop) valve repair, replace or shut off
 Treatment Facilities Pumping Facilities Storage Facilities Well failure Plant equip. break down
 Planned main clearance (explain below)
 Other: 6" water main cracked.

Was integrity of water system maintained Yes No If yes, explain: Valves Isolated.

Number of Customers Affected: 37 Connections Individuals

Corrective Action:

Prior to placing back into service, was line/ Equipment:

Flushed: Yes No

Superchlorinated/Disinfected Yes No

Bacteriologicals Requested? Yes No

Sample Location: One upstream and one downstream.

Was heavily chlorinated water released to environment Yes No; to distribution Yes No

Explain:

Was a Precautionary Boil Water Notice Issued per DOH Guidelines dated 8/26/1999: Yes No

If a **Precautionary Boil Water Notice** was issued, please attach or submit together with this report.

Bacteriological reports (2 days) as well as a rescission notice must follow.

Valve #	Size	Num. of valves closed	Location of Valve

Remarks:



DEPARTMENT OF ENVIRONMENTAL PROTECTION
C e n t r a l D i s t r i c t

Drinking Water Program

MALFUNCTION OR **INCIDENT REPORT**

407/893-3318 OR 3988; 894-7555, EXT. 2243

FAX: 407/893-4418; E-FAX: 407.897.4189

Date: 8/1/16

Time: 0745

Received By: Brad Whidden

Reported By: Scott Gosnell

Business Name: Utilities Inc. of Florida

Name of Plant/System: Sanlando - Wekiva Hunt Club PWS ID Number: 3591121

Address: 144 Ledbury Dr. Longwood, FL. 32779

System Phone: 407-869-1919

County: Seminole

Owner: Utilities Inc. of Florida

Contact Person: Scott Gosnell

Phone #: 407-682-5651

Failure

Planned Outage

Date: 7/29/16

Time: 2000

Expected to be (or was) back in service:

Date: 7/29/16

Time: 2230

Location of Trouble (address): 351 Red Mulberry Longwood, FL. 32779

Statement of Trouble (check as many as necessary to explain incident):

- Water main breaks Pressure greater than 20-psi pressure drop below 20 psi Outage (no water to customers) Service line break tie in (no pressure drop) valve repair, replace or shut off
 Treatment Facilities Pumping Facilities Storage Facilities Well failure Plant equip. break down
 Planned main clearance (explain below)
 Other: 6" water main break.

Was integrity of water system maintained Yes No If yes, explain: Valves Isolated.

Number of Customers Affected: 35 Connections Individuals

Corrective Action:

Prior to placing back into service, was line/ Equipment:

Flushed: Yes No

Superchlorinated/Disinfected Yes No

Bacteriologicals Requested? Yes No

Sample Location: 351 Red Mulberry, 213&227 E.Hornbeam

Was heavily chlorinated water released to environment Yes No; to distribution Yes No

Explain:

Was a Precautionary Boil Water Notice Issued per DOH Guidelines dated 8/26/1999: Yes No

If a Precautionary Boil Water Notice was issued, please attach or submit together with this report.

Bacteriological reports (2 days) as well as a rescission notice must follow.

Valve #	Size	Num. of valves closed	Location of Valve

Remarks:

Rev.



DEPARTMENT OF ENVIRONMENTAL PROTECTION
C e n t r a l D i s t r i c t

Drinking Water Program

MALFUNCTION OR **INCIDENT REPORT**

407/893-3318 OR 3988; 894-7555, EXT. 2243

FAX: 407/893-4418; E-FAX: 407.897.4189

Date: 2/12/16 Time: 0900 Received By: Brad Whidden
 Reported By: Scott Gosnell Business Name: Sanlando Utilities Corporation
 Name of Plant/System: Wekiva Hunt Club PWS ID Number: 3591121
 Address: 144 Ledbury Dr. Longwood, FL. 32779
 System Phone: 407-869-1919
 County: Seminole
 Owner: Sanlando Utilities Corporation

Contact Person: Scott Gosnell Phone #: 407-682-5651

Failure Planned Outage Date: 2/11/16 Time: 1530

Expected to be (or was) back in service: Date: 2/11/16 Time: 1830

Location of Trouble (address): 503 Birdsong Ct. Longwood, FL. 32779

Statement of Trouble (check as many as necessary to explain incident):

- Water main breaks Pressure greater than 20-psi pressure drop below 20 psi. Outage (no water to customers)
- Service line break tie in (no pressure drop) valve repair, replace or shut off
- Treatment Facilities Pumping Facilities Storage Facilities Well failure Plant equip. break down
- Planned main clearance (explain below)
- Other: 6" water main break.

Was integrity of water system maintained Yes No If yes, explain: Valves Isolated.

Number of Customers Affected: 40 Connections Individuals

Corrective Action:

Prior to placing back into service, was line/ Equipment:

Flushed: Yes No

Superchlorinated/Disinfected Yes No

Bacteriologicals Requested? Yes No

Sample Location: 503&545 Birdsong and 442 Timber Ridge

Was heavily chlorinated water released to environment Yes No; to distribution Yes No

Explain:

Was a Precautionary Boil Water Notice Issued per DOH Guidelines dated 8/26/1999: Yes No

If a Precautionary Boil Water Notice was issued, please attach or submit together with this report.

Bacteriological reports (2 days) as well as a rescission notice must follow.

Valve #	Size	Num. of valves closed	Location of Valve

Remarks:

Rev.