

Oily's Auto Repair

5669 5th Ave.
 Stock Island, FL 33040-0000
 Shop Phone: (305) 849-0164

Email: Oilysautorepair@yahoo.com
 Web Address: Oilysautorepair.com

Estimate

20435

Estimate Ref #20,435
 Date Printed: 12/20/2016
 Printed Time: 12:51 pm
 Reg.#MV52775
 ASE CERTIFIED

Hat/Ref:

OILY'S AUTO REPAIR -- THANKS FOR YOUR BUSINESS!

Time Promised:

KWRU

6630 Front Street
 Key West, FL 33040

Home: (305) 522-0052 Work: (305) 295-3301

Cell:

Email: chriskw@bellsouth.net

2004 CHEVROLET COLORADO L4 2.8L 2770CC 169CID FI GAS N 8

VIN: 1GCCS198X48205780

License: L452UV

Unit #:

Mileage In: 97,713

Mileage Out: 97,713

DOM: 6/04

Date Written: 12/19/2016

Written By:

Save Old Parts: No

Job #4

Labor 1

TIE ROD END / STEERING

Work Requested - TIE ROD END - Replace - Outer
 Tie Rod - Both Sides - Does Not Include: Adjust
 Toe-In.

66.50

Part

Labor 1

Tie Rod End

2.00

49.97

99.94

Work Requested - ADJUST TOE

50.00

Parts: \$524.08

Labor: \$524.57

Sublet: \$0.00

Misc: \$0.00

Hazmat:* \$12.50

Supplies:* \$8.75

Tax Total: \$80.25

Total: \$1,150.15

Less Paid: 0.00

Balance Due: \$1,150.15

Oily's Auto Repair

5669 5th Ave.

Stock Island, FL 33040-0000

Shop Phone: (305) 849-0164

Email: Oilysautorepair@yahoo.com

Web Address: Oilysautorepair.com

Estimate

20435

Estimate Ref #20,435

Date Printed: 12/20/2016

Printed Time: 12:51 pm

Reg.#MV52775

ASE CERTIFIED

Hat/Ref:

OILY'S AUTO REPAIR - THANKS FOR YOUR BUSINESS!

Time Promised:

KWRU

6630 Front Street

Key West, FL 33040

Home: (305) 522-0052 Work: (305) 295-3301

Cell:

Email: chriskw@bellsouth.net

2004 CHEVROLET COLORADO L4 2.8L 2770CC 169CID FI GAS N 8

VIN: 1GCCS198X48205760

License: L452UV

Unit #:

Mileage In: 97,713

Mileage Out: 97,713

DOM: 6/04

Date Written: 12/19/2016

Written By:

Save Old Parts: No

Vehicle Service 1

Labor 1

Part MOTOR OIL

Part

Note/Title

RECOMMENDATIONS / NOTES

Tires

VEHICLE SERVICE

Work Requested - Oil Change with Filter, Top up

Fluids, Tire Pressures and Rotation if Needed,

Check Lights, Belts and Hoses. Washer Fluid

Motor Oil

Oil Filter

5.00

3.25

18.57

1.00

3.95

16.25

3.95

Job #1

Labor 1

Part BC1

STALLING / LOW RPM

Work Requested - STALLING / LOW RPM

Clean Throttle Body and Clean Induction System

PartsCleaner

1.00

5.00

95.00

5.00

FRONT BRAKE SERVICE

Labor 1

Part

Part

FRONT BRAKES

Work Requested - FRONT BRAKES

Front Brake Pads

Brake Rotor/Disc

1.00

64.95

95.00

2.00

46.05

64.95

92.10

Oily's Auto Repair

5869 5th Ave.
 Stock Island, FL 33040-0000
 Shop Phone: (305) 849-0164

Email: Oilyautorepair@yahoo.com
 Web Address: Oilyautorepair.com

Estimate

20435

Estimate Ref #20,435
 Date Printed: 12/20/2016
 Printed Time: 12:51 pm
 Reg.#MV52775
 ASE CERTIFIED

Hat/Ref:

OILY'S AUTO REPAIR - THANKS FOR YOUR BUSINESS!

Time Promised:

KWRU 2004 CHEVROLET COLORADO L4 2.8L 2770CC 169CID FI GAS N 8
 6630 Front Street VIN: 1GCCS198X48205760 Date Written: 12/19/2016
 Key West, FL 33040 License: L452UV Mileage In: 97,713 Written By:
 Home: (305) 522-0052 Work: (305) 295-3301 Unit #: Mileage Out: 97,713 Save Old Parts: No
 Cell: Email: chriskw@bellsouth.net DOM: 5/04

Part	BC1	Parts Cleaner	1.00	2.59	2.59
Part	DOT	Brake Fluid	1.00	5.00	5.00

Job #2 **TUNE-UP**

Labor	1	SPARK PLUG / IGNITION COIL			
		Work Requested - SPARK PLUG			142.50
Part		#3 Ignition Coil			
Part		Spark Plug	4.00	7.95	31.80
Part		Ignition Coil	1.00	71.95	71.95

Job #3 **DRIVE BELT TENSIONER**

Labor	1	IDLER PULLEY			
		Work Requested - DRIVE BELT TENSIONER			57.00
		IDLER PULLEY			
		SERPENTINE BELT			
Part		Serpentine Belt Tensioner	1.00	59.95	59.95
Part		Idler Pulley	1.00	28.96	28.96
Part		Serpentine Belt	1.00	41.64	41.64