CKL TIS

State of Florida



Public Service Commission

CAPITAL CIRCLE OFFICE CENTER • 2540 SHUMARD OAK BOULEVARD TALLAHASSEE, FLORIDA 32399-0850

-M-E-M-O-R-A-N-D-U-M-

DATE:

October 26, 2018

TO:

Carlotta S. Stauffer, Commission Clerk, Office of Commission Clerk

FROM:

Clayton Lewis, Engineering Specialist, Division of Engineering

RE:

Docket No. 20180021-WU- Application for staff-assisted rate case in Highlands

County by Country Walk Utilities, Inc.

Please file the attached, "October 25, 2018, DEP letter of compliance," in the above mentioned docket file.

Thank you.

CL/jp

Attachment

Joann Parsons

From:

Clayton Lewis

Sent:

Friday, October 26, 2018 10:27 AM

To:

Joann Parsons

Subject: Attachments: FW: DEP Letter - Country Walk - Return to Compliance

FDEP Return to Compliance Letter 10-25-2018.pdf

Please file this message and attachment in Docket No. 20180021 Country Walk Utilities, Inc..

"October 25, 2018 DEP Letter of Compliance"

Thank you.

From: Troy Rendell [mailto:trendell@uswatercorp.net]

Sent: Thursday, October 25, 2018 12:42 PM **To:** Luis Salvador; Doug Wright; Clayton Lewis

Subject: DEP Letter - Country Walk - Return to Compliance

Please find attached the FDEP return to compliance letter concerning Country Walk dated October 25, 2018.

Thank you.

Troy Rendell U.S. Water Services Corporation

U.S. Water

4939 Cross Bayou Boulevard New Port Richey, FL 34652 (Office) 727-848-8292 x245 (Fax) 727-848-7701

(E-Mail) <u>trendell@uswatercorp.net</u>



FLORIDA DEPARTMENT OF Environmental Protection

South District Post Office Box 2549 Fort Myers, Florida 33902-2549 SouthDistrict@FloridaDEP.gov Rick Scott Governor Carlos Lopez-Cantera Lt. Governor Noah Valenstein Secretary

October 25, 2018

Sharon Purviance U.S. Water Services Corporation 4939 Cross Bayou Blvd. New Port Richey, FL 34652 Spurviance@uswatercorp.net

Re:

Return to Compliance Letter

Country Walk

PSW ID No.: 6284114 Highlands County – PW

Dear Ms. Purviance:

Department personnel conducted a Compliance Inspection of the above-referenced facility on September 12, 2018. Based on the information provided during the inspection, the facility was determined to be in compliance. A copy of the inspection report is attached for your records.

The Department appreciates your efforts to maintain this facility in compliance with state and federal rules. Should you have any questions or comments, please contact Andrew Price at (239) 344-5621, or via e-mail at: Andrew.Price@FloridaDEP.gov.

Sincerely,

Jennifer Carpenter Assistant Director

South District Office

Florida Department of Environmental Protection

Tennifer L. Cayester

Enclosure: Inspection Report

cc:

Gary Deremer gderemer@uswatercorp.net

Troy Rendell trendell@uswatercorp.net

Cc	mp	oliance Inspection Form						Page 1		
Z	Dat	Pate of Inspection: September 12, 2018								
VIIIO	Water System: Country Walk System Type: Community System PWS #: 6284114									
RMA	System Address: 29 Lakeside Trail, Lake Placid, FL 33852									
(FO	Owner Name: Gary Deremer									
MI	Owner Address: 4939 Cross Bayou Blvd., New Port Richey, FL 34652									
STE	Owner Phone: <u>727-848-8292</u>				Owner Cell:					
SY	Owner Fax:				Owner Email: gderemer@uswatercorp.net					
BASIC INSPECTION AND SYSTEM INFORMATION	Prin	nary Contact Name: Sharon Purvianc	e							
	Prin	Primary Contact Address: 4939 Cross Bayou Blvd., New Port Richey, FL 34652								
	Primary Contact Phone: 727-848-8292				Primary Contact Cell: 727-919-1548					
	Prin	nary Contact Fax:	Fax:			Primary Contact Email: spurviance@uswatercorp.net				
	Орє	perator Required? ⊠Yes □ No (if "No", Operator Section Not Applicable)								
BAS		erator Name: Sharon Purviance	Operator Phone: <u>727-919-1548</u>			Operator Email: spurviance@uswatercorp.n			ercorp.net	
TREATMENT SOURCE – WELL INFORMATION	Well Number		AAO4478			z	Flushing of Dead End	s Compliant?	Y	
	Well Artesian?		N		7	DISTRIBUTION	Valve Maintenance C	ompliant?	Y	
	Setback Compliant?		Y			RIBL	Distribution Map (C/35	0 / 150)	Y	
	Well Head Sealed? (Pad/Conduit/Openings)		Y			IST	Distribution CL Samp ≥3300: 1 grab per day serving water or 5	oles Compliant?	Y	
	Well Casing 12" Above Grade? (2002)		Y				< 3300: 1 grab per day serving water or 2			
	Casing Vent Compliant? (2003)		Y	,			Records Properly Reta		Y	
	Check Valve Compliant?		Y				Preventative Maintena		Y	
	Tap Compitant. (smooth 12 mgh pre-check)		Y		-		Flow Meter Accuracy		Y	
	6' x 6' x 4" Well Apron? (2002)		Y		-	- E	Bacteriological Samp		Y	
	_	w Measureable?	<u>Y</u>		-	EMI	Chemical Sampling?		Y	
		ell Security Measure Compliant?	Y			IAG	Chemical Sampling? (Plan/Sampling) Process Performance Records? Cross Connection Control Plan? (C)		NA V	
	Auxiliary Power? (C/350/ 150)		NA			MAN			Y	
	CL Storage Compliant (no organics/sun)		Y				Any Cross Connections Observed?		N	
	Loss of Chlorine Alarm Compliant?		NA				Pb and Cu Sampling Plan? (C, NTNC)		Y	
	CL Testing Following S.O.P.		Y				Auxiliary Power Maintenance? (c)		NA NA	
	Plant Security Measures Compliant?		Y				Emergency Response Plan? (C/350/150		NA Y	
	9	CL Solution NSF Approved? Solution Vat Compliant? (covered)	Y			- S	O & M Log Compliant? Operator Visits Compliant MORs Submittal Compliant?		Y	
	HY		Y			- IRA			Y	
	Safety: (Gloves/ Apron/ Eyewash/ Etc.) Spare Chlorination Compliant?		NA NA			OPE	Noks submittal Compilant:			
						00	E-ilita 4 I A	10 U V VN		
		Loss of Chlorine Alarm Compliant?	NA NA				Facility 4–Log Approved? Yes No			
	GAS	CL Room Complaint? (Separate/ Vented)	NA NA				4-Log Approval In Compliance? ☐ Yes ☐ No			
	ľ	Scale Compliant?			1000	FOLLOW -UP TO LAST INSPECTION				
		Auto Switchover Provided?	NA			Total Control	Last Inspection Fully Compliant? ⊠ Yes □		∃No	
		Safety: (SCBA/ Gloves/ Ammonia/ Panic HW)		NA		CI	FIELD SAMPLING	RESULTS		
	AL					Fr	ee Chlorine	Total Chlorine		
	ION						PLANT	DISTRIBU	TION	
	ADDITIONAL						nples were not taken	Samples were no		
	₹ I					during the time of this inspection		during the time of this inspection		
	Tank Number Hydropneumatic					ins	pection			
GE	Ins	spections Compliant? (annual /5 yr)	2014							
STORAGE	Overflow / Vents Compliant?		NA							
STC	Pre	essure Relief Valve Provided? (Hydro)	Y							
	Se	curity Measures Compliant?	Y	Y C. S.	In	Inspector Used FDEP Test Kit #				


None

REMARKS AND RECOMMENDATIONS

The Department meet with US Water and Florida Rural Water Association to conduct a compliance inspection of the water treatment plant. At the time of the inspection, the Department did not observe any items of concern. The facility has been in violation for Disinfection By-Products in the past. However, with the installation of new treatment and subsequent sampling, the facility has resolved the MCL violation and has been put on annual sampling for Disinfection By-Products.

The facility at the time of the inspection is in compliance with all primary and secondary water quality standards as per Rule 62-550, Florida Administrative Code.

PHOTOS



andrew I Price

Inspectors Signature:

Title: Environmental Specialist II Date: September 20, 2018

Review Signature: /

Title: Environmental Manager Date: October 22, 2018